

NC School District/830 Scotland County/High School

Scotland High

Draft

Campus Assessment Report

March 7, 2017



Table of Contents

Campus Executive Summary	11
Campus Dashboard Summary	14
Campus Condition Summary	15
<u>1967 Football Pressbox</u>	17
Executive Summary	17
Dashboard Summary	18
Condition Summary	19
Photo Album	20
Condition Detail	21
System Listing	22
System Notes	23
Renewal Schedule	27
Forecasted Sustainment Requirement	29
Deficiency Summary By System	30
Deficiency Summary By Priority	31
Deficiency By Priority Investment	32
Deficiency Summary By Category	33
Deficiency Details By Priority	34
<u>1967 Gym Building</u>	35
Executive Summary	35
Dashboard Summary	36
Condition Summary	37
Photo Album	38
Condition Detail	39
System Listing	40
System Notes	42
Renewal Schedule	53
Forecasted Sustainment Requirement	56
Deficiency Summary By System	57

Campus Assessment Report

Deficiency Summary By Priority	58
Deficiency By Priority Investment	59
Deficiency Summary By Category	60
Deficiency Details By Priority	61
<u>1967 Restroom Building</u>	65
Executive Summary	65
Dashboard Summary	66
Condition Summary	67
Photo Album	68
Condition Detail	69
System Listing	70
System Notes	71
Renewal Schedule	76
Forecasted Sustainment Requirement	78
Deficiency Summary By System	79
Deficiency Summary By Priority	80
Deficiency By Priority Investment	81
Deficiency Summary By Category	82
Deficiency Details By Priority	83
<u>1967 Storage Building</u>	84
Executive Summary	84
Dashboard Summary	85
Condition Summary	86
Photo Album	87
Condition Detail	88
System Listing	89
System Notes	90
Renewal Schedule	96
Forecasted Sustainment Requirement	98
Deficiency Summary By System	99
Deficiency Summary By Priority	100

Campus Assessment Report

Deficiency By Priority Investment	101
Deficiency Summary By Category	102
Deficiency Details By Priority	103
<u>1967, 1977 Main Building</u>	105
Executive Summary	105
Dashboard Summary	106
Condition Summary	107
Photo Album	108
Condition Detail	109
System Listing	110
System Notes	112
Renewal Schedule	126
Forecasted Sustainment Requirement	129
Deficiency Summary By System	130
Deficiency Summary By Priority	131
Deficiency By Priority Investment	132
Deficiency Summary By Category	133
Deficiency Details By Priority	134
<u>1977 Baseball Pressbox</u>	142
Executive Summary	142
Dashboard Summary	143
Condition Summary	144
Photo Album	145
Condition Detail	146
System Listing	147
System Notes	148
Renewal Schedule	151
Forecasted Sustainment Requirement	153
Deficiency Summary By System	154
Deficiency Summary By Priority	155
Deficiency By Priority Investment	156

Campus Assessment Report

Deficiency Summary By Category	157
Deficiency Details By Priority	158
<u>1977 Technology Building</u>	159
Executive Summary	159
Dashboard Summary	160
Condition Summary	161
Photo Album	162
Condition Detail	163
System Listing	164
System Notes	165
Renewal Schedule	173
Forecasted Sustainment Requirement	175
Deficiency Summary By System	176
Deficiency Summary By Priority	177
Deficiency By Priority Investment	178
Deficiency Summary By Category	179
Deficiency Details By Priority	180
<u>1979 Fieldhouse</u>	181
Executive Summary	181
Dashboard Summary	182
Condition Summary	183
Photo Album	184
Condition Detail	185
System Listing	186
System Notes	187
Renewal Schedule	195
Forecasted Sustainment Requirement	197
Deficiency Summary By System	198
Deficiency Summary By Priority	199
Deficiency By Priority Investment	200
Deficiency Summary By Category	201

Campus Assessment Report

Deficiency Details By Priority	202
<u>1991 Addition</u>	203
Executive Summary	203
Dashboard Summary	204
Condition Summary	205
Photo Album	206
Condition Detail	207
System Listing	208
System Notes	210
Renewal Schedule	219
Forecasted Sustainment Requirement	221
Deficiency Summary By System	222
Deficiency Summary By Priority	223
Deficiency By Priority Investment	224
Deficiency Summary By Category	225
Deficiency Details By Priority	226
<u>1999 Visitor Concession Stand</u>	227
Executive Summary	227
Dashboard Summary	228
Condition Summary	229
Photo Album	230
Condition Detail	231
System Listing	232
System Notes	233
Renewal Schedule	240
Forecasted Sustainment Requirement	242
Deficiency Summary By System	243
Deficiency Summary By Priority	244
Deficiency By Priority Investment	245
Deficiency Summary By Category	246
Deficiency Details By Priority	247

Campus Assessment Report

<u>2005 Weight Room</u>	248
Executive Summary	248
Dashboard Summary	249
Condition Summary	250
Photo Album	251
Condition Detail	252
System Listing	253
System Notes	254
Renewal Schedule	261
Forecasted Sustainment Requirement	263
Deficiency Summary By System	264
Deficiency Summary By Priority	265
Deficiency By Priority Investment	266
Deficiency Summary By Category	267
Deficiency Details By Priority	268
<u>2008 Storage Building</u>	269
Executive Summary	269
Dashboard Summary	270
Condition Summary	271
Photo Album	272
Condition Detail	273
System Listing	274
System Notes	275
Renewal Schedule	278
Forecasted Sustainment Requirement	279
Deficiency Summary By System	280
Deficiency Summary By Priority	281
Deficiency By Priority Investment	282
Deficiency Summary By Category	283
Deficiency Details By Priority	284
<u>2009 Soccer Storage Building</u>	285

Campus Assessment Report

Executive Summary	285
Dashboard Summary	286
Condition Summary	287
Photo Album	288
Condition Detail	289
System Listing	290
System Notes	291
Renewal Schedule	297
Forecasted Sustainment Requirement	299
Deficiency Summary By System	300
Deficiency Summary By Priority	301
Deficiency By Priority Investment	302
Deficiency Summary By Category	303
Deficiency Details By Priority	304
<u>2009 Softball Pressbox</u>	305
Executive Summary	305
Dashboard Summary	306
Condition Summary	307
Photo Album	308
Condition Detail	309
System Listing	310
System Notes	311
Renewal Schedule	315
Forecasted Sustainment Requirement	317
Deficiency Summary By System	318
Deficiency Summary By Priority	319
Deficiency By Priority Investment	320
Deficiency Summary By Category	321
Deficiency Details By Priority	322
<u>2012 Concession Building</u>	323
Executive Summary	323

Campus Assessment Report

Dashboard Summary	324
Condition Summary	325
Photo Album	326
Condition Detail	327
System Listing	328
System Notes	329
Renewal Schedule	335
Forecasted Sustainment Requirement	337
Deficiency Summary By System	338
Deficiency Summary By Priority	339
Deficiency By Priority Investment	340
Deficiency Summary By Category	341
Deficiency Details By Priority	342
<u>2015 Baseball Pressbox</u>	343
Executive Summary	343
Dashboard Summary	344
Condition Summary	345
Photo Album	346
Condition Detail	347
System Listing	348
System Notes	349
Renewal Schedule	353
Forecasted Sustainment Requirement	355
Deficiency Summary By System	356
Deficiency Summary By Priority	357
Deficiency By Priority Investment	358
Deficiency Summary By Category	359
Deficiency Details By Priority	360
<u>2015 Laundromat Building</u>	361
Executive Summary	361
Dashboard Summary	362

Campus Assessment Report

Condition Summary	363
Photo Album	364
Condition Detail	365
System Listing	366
System Notes	367
Renewal Schedule	375
Forecasted Sustainment Requirement	377
Deficiency Summary By System	378
Deficiency Summary By Priority	379
Deficiency By Priority Investment	380
Deficiency Summary By Category	381
Deficiency Details By Priority	382
Site	383
Executive Summary	383
Dashboard Summary	384
Condition Summary	385
Photo Album	386
Condition Detail	387
System Listing	388
System Notes	389
Renewal Schedule	395
Forecasted Sustainment Requirement	396
Deficiency Summary By System	397
Deficiency Summary By Priority	398
Deficiency By Priority Investment	399
Deficiency Summary By Category	400
Deficiency Details By Priority	401

Campus Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	285,240
Year Built:	1967
Last Renovation:	
Replacement Value:	\$67,064,418
Repair Cost:	\$13,538,819.91
Total FCI:	20.19 %
Total RSLI:	34.80 %
FCA Score:	79.81



Description:

GENERAL:

Scotland High School is located at 100 West Church Street in Laurinburg, North Carolina. The 2 story, 178,900 square foot building was originally constructed in 1967. There have been 4 additions or no major renovations. In 1967 a gym building was constructed, in 1977 a technology building was constructed, in 1991 an addition was constructed which houses a gymnasium, and in 2015 a new laundromat building was constructed. In addition to the main building, the campus contains ancillary buildings; storage, pressbox, concession/restrooms, and fieldhouse.

This report contains condition and adequacy data collected during the 2016 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for the site and building elements.

A. SUBSTRUCTURE

Campus Assessment Report - Scotland High

The building rests on footings and foundation walls and is assumed to have standard cast-in-place concrete foundations. The building does not have a basement.

B. SUPERSTRUCTURE

Floor construction is metal pan deck with lightweight fill. Roof construction is metal pan deck with lightweight fill. The exterior envelope is composed of walls of brick veneer over CMU. Exterior windows are aluminum frame with fixed panes. Exterior doors are hollow metal steel mostly with glazing. Roofing is typically low slope built-up and pitched standing metal roof. Roof openings include roof hatches with fixed ladder access. Most building entrances appear to comply with ADA requirements.

C. INTERIORS

Interior partitions are typically CMU and drywall. Interior doors are generally hollow core wood with wood frames and mostly without glazing. Interior fittings include the following items: white boards, graphics and identifying devices, lockers, toilet accessories, storage shelving, handrails, and fabricated toilet partitions. Stair construction includes steel risers and concrete treads with terrazzo and epoxy finishes. The interior wall finishes are typically painted CMU and painted drywall. Floor finishes in common areas are typically terrazzo. Floor finishes in assignable spaces is typically vinyl composition tile, carpet, ceramic tiles, quarry tiles, and wood. Ceiling finishes in common areas are typically suspended acoustical tile. Ceiling finishes in assignable areas are typically painted drywall.

CONVEYING:

The building does include conveying equipment. Conveying equipment includes 1 geared traction elevators, and no wheelchair lifts.

D. SERVICES

PLUMBING: Plumbing fixtures are typically low-flow water fixtures with manual control valves. Domestic water distribution is combination of copper and galvanized steel with gas hot water heating. Sanitary waste system is cast iron. Rain water drainage system is internal with roof drains. Other plumbing systems is supplied by natural gas.

HVAC:

Heating is provided by 3 gas fired boilers. Cooling is supplied by water cooled chillers and cooling towers. The heating/cooling distribution system is a ductwork system utilizing air handling units. Fresh air is supplied by air handling units. Ceiling mounted exhaust fans are installed in bathrooms and other required areas. Controls and instrumentation are digital and are centrally controlled by an energy management system. This building has a remote Building Automation System.

FIRE PROTECTION:

The building does not have a fire sprinkler system. The building does not have additional fire suppression systems. Standpipes are not included within fire stairs. Fire extinguishers and cabinets are distributed near fire exits and corridors.

ELECTRICAL:

The main electrical service is fed from a pad mounted transformer to the main switchboard/distribution panel located in the building. Lighting is lay-in type, fluorescent light fixtures. Branch circuit wiring is typically copper serving electrical switches and receptacles. Emergency and life safety egress lighting systems are installed and exit signs are present at exit doors and near stairways and are typically illuminated.

COMMUNICATIONS AND SECURITY:

The fire alarm system consists of audible/visual strobe annunciators in all common spaces. The system is activated by manual pull stations and smoke detectors and the system is centrally monitored. The telephone and data systems are segregated and include dedicated equipment closets. This building does have a local area network (LAN). The building includes an internal security system that is actuated by the following items: contacts, infrared, optical or a combination of all devices. The building has controlled entry doors access provided by camera access at the main door; entry doors are secured with magnetic door locks. The security system has CCTV cameras and is centrally monitored; this building has a public address and paging system combined with the telephone system.

OTHER ELECTRICAL SYSTEMS:

This building does have a separately derived emergency power system. There is 1 natural gas emergency generator.

E. EQUIPMENT & FURNISHINGS:





This building includes the following items and equipment: fixed food service, library equipment, athletic equipment, theater and stage, audio-visual, laboratory, vehicle equipment, fixed casework, and multiple seating furnishings.

G. SITE

Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, play areas, and fencing. Site mechanical and electrical features include water, sewer, natural gas, and site lighting.

Campus Dashboard Summary

Gross Area:	285,240	Last Renovation:	
Year Built:	1967	Replacement Value:	\$67,064,418
Repair Cost:	\$13,538,820	RSLI%:	34.80 %
FCI:	20.19 %		



Campus Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	61.69 %	0.00 %	\$0.00
A20 - Basement Construction	53.27 %	0.00 %	\$0.00
B10 - Superstructure	53.75 %	0.00 %	\$0.00
B20 - Exterior Enclosure	32.60 %	9.09 %	\$625,716.37
B30 - Roofing	41.43 %	21.64 %	\$383,296.00
C10 - Interior Construction	31.11 %	3.99 %	\$106,013.00
C20 - Stairs	50.21 %	0.00 %	\$0.00
C30 - Interior Finishes	53.73 %	3.41 %	\$243,309.54
D10 - Conveying	0.00 %	110.00 %	\$192,854.00
D20 - Plumbing	14.65 %	44.07 %	\$1,737,656.00
D30 - HVAC	18.63 %	61.75 %	\$5,949,353.00
D40 - Fire Protection	1.53 %	97.39 %	\$1,085,129.00
D50 - Electrical	51.01 %	0.43 %	\$33,049.94
E10 - Equipment	51.93 %	23.82 %	\$1,054,794.00
E20 - Furnishings	4.43 %	92.54 %	\$1,216,116.00
G20 - Site Improvements	23.13 %	12.42 %	\$911,533.06
G30 - Site Mechanical Utilities	8.21 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	13.07 %	0.00 %	\$0.00
Totals:	34.80 %	20.19 %	\$13,538,819.91

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance
1967 Football Pressbox	320	2.25	\$0.00	\$0.00	\$1,260.00	\$0.00	\$0.00
1967 Gym Building	43,100	35.19	\$0.00	\$0.00	\$3,028,551.00	\$0.00	\$0.00
1967 Restroom Building	450	8.14	\$0.00	\$0.00	\$4,717.00	\$0.00	\$0.00
1967 Storage Building	460	11.71	\$0.00	\$0.00	\$10,808.00	\$0.00	\$0.00
1967, 1977 Main Building	178,900	25.90	\$26,400.00	\$0.00	\$9,018,066.68	\$0.00	\$0.00
1977 Baseball Pressbox	430	15.43	\$0.00	\$0.00	\$10,631.84	\$0.00	\$0.00
1977 Technology Building	14,000	2.74	\$0.00	\$0.00	\$64,372.00	\$0.00	\$0.00
1979 Fieldhouse	6,000	2.55	\$0.00	\$0.00	\$37,843.00	\$0.00	\$0.00
1991 Addition	28,500	7.16	\$0.00	\$0.00	\$380,219.00	\$0.00	\$0.00
1999 Visitor Concession Stand	1,200	18.21	\$0.00	\$0.00	\$32,155.00	\$0.00	\$0.00
2005 Weight Room	5,700	0.77	\$0.00	\$0.00	\$10,546.80	\$0.00	\$0.00
2008 Storage Building	1,620	0.85	\$1,716.53	\$0.00	\$0.00	\$0.00	\$0.00
2009 Soccer Storage Building	435	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2009 Softball Pressbox	490	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2012 Concession Building	1,400	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2015 Baseball Pressbox	235	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
2015 Laundromat Building	2,000	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
Site	285,240	7.94	\$12,696.06	\$0.00	\$898,837.00	\$0.00	\$0.00
Total:		20.19	\$40,812.59	\$0.00	\$13,498,007.32	\$0.00	\$0.00

Deficiencies By Priority



Budget Estimate Total: \$13,538,819.91

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	320
Year Built:	1967
Last Renovation:	
Replacement Value:	\$56,112
Repair Cost:	\$1,260.00
Total FCI:	2.25 %
Total RSLI:	34.90 %
FCA Score:	97.75







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	320
Year Built:	1967	Last Renovation:	
Repair Cost:	\$1,260	Replacement Value:	\$56,112
FCI:	2.25 %	RSLI%:	34.90 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	50.00 %	0.00 %	\$0.00
B10 - Superstructure	50.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	32.97 %	0.00 %	\$0.00
B30 - Roofing	16.00 %	0.00 %	\$0.00
C30 - Interior Finishes	22.37 %	0.00 %	\$0.00
D50 - Electrical	9.69 %	24.74 %	\$1,260.00
Totals:	34.90 %	2.25 %	\$1,260.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). North Elevation - Jan 10, 2017



2). East Elevation - Jan 10, 2017



3). West Elevation - Jan 10, 2017



4). Northeast Elevation - Jan 10, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	320	100	1967	2067		50.00 %	0.00 %	50			\$6,442
A1030	Slab on Grade	\$19.75	S.F.	320	100	1967	2067		50.00 %	0.00 %	50			\$6,320
B1010	Floor Construction	\$11.44	S.F.	320	100	1967	2067		50.00 %	0.00 %	50			\$3,661
B1020	Roof Construction	\$16.26	S.F.	320	100	1967	2067		50.00 %	0.00 %	50			\$5,203
B2010	Exterior Walls	\$29.79	S.F.	320	100	1967	2067		50.00 %	0.00 %	50			\$9,533
B2020	Exterior Windows	\$17.17	S.F.	320	30	1967	1997	2021	13.33 %	0.00 %	4			\$5,494
B2030	Exterior Doors	\$8.66	S.F.	320	30	1967	1997	2021	13.33 %	0.00 %	4			\$2,771
B3010105	Built-Up	\$8.95	S.F.	320	25	1967	1992	2021	16.00 %	0.00 %	4			\$2,864
B3020	Roof Openings	\$0.29	S.F.	320	25	1967	1992	2021	16.00 %	0.00 %	4			\$93
C3010	Wall Finishes	\$5.11	S.F.	320	10	1967	1977	2021	40.00 %	0.00 %	4			\$1,635
C3020	Floor Finishes	\$12.37	S.F.	320	20	1967	1987	2021	20.00 %	0.00 %	4			\$3,958
C3030	Ceiling Finishes	\$9.52	S.F.	320	25	1967	1992	2021	16.00 %	0.00 %	4			\$3,046
D5010	Electrical Service/Distribution	\$3.09	S.F.	320	40	1967	2007	2021	10.00 %	0.00 %	4			\$989
D5020	Branch Wiring	\$9.24	S.F.	320	30	1967	1997	2021	13.33 %	0.00 %	4			\$2,957
D5020	Lighting	\$3.58	S.F.	320	30	1967	1997		0.00 %	109.95 %	-20		\$1,260.00	\$1,146
Total									34.90 %	2.25 %			\$1,260.00	\$56,112

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1967 Football Pressbox

System: B3010105 - Built-Up




Note:

System: B3020 - Roof Openings



Note:


System: C3010 - Wall Finishes



Note:


Campus Assessment Report - 1967 Football Pressbox

System: C3020 - Floor Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

System: D5010 - Electrical Service/Distribution



Note:

Campus Assessment Report - 1967 Football Pressbox

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Campus Assessment Report - 1967 Football Pressbox


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$1,260	\$0	\$0	\$0	\$30,377	\$0	\$0	\$0	\$0	\$0	\$0	\$31,637
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$6,803	\$0	\$0	\$0	\$0	\$0	\$0	\$6,803
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$3,431	\$0	\$0	\$0	\$0	\$0	\$0	\$3,431
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010105 - Built-Up	\$0	\$0	\$0	\$0	\$4,448	\$0	\$0	\$0	\$0	\$0	\$0	\$4,448
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$115	\$0	\$0	\$0	\$0	\$0	\$0	\$115
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$2,025	\$0	\$0	\$0	\$0	\$0	\$0	\$2,025
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$4,900	\$0	\$0	\$0	\$0	\$0	\$0	\$4,900
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$3,772	\$0	\$0	\$0	\$0	\$0	\$0	\$3,772
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$1,225	\$0	\$0	\$0	\$0	\$0	\$0	\$1,225
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$3,660	\$0	\$0	\$0	\$0	\$0	\$0	\$3,660
D5020 - Lighting	\$1,260	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,260

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$1,260.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
D5020	Lighting	\$0.00	\$0.00	\$1,260.00	\$0.00	\$0.00	\$1,260.00
	Total:	\$0.00	\$0.00	\$1,260.00	\$0.00	\$0.00	\$1,260.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: D5020 - Lighting



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 320.00
Unit of Measure: S.F.
Estimate: \$1,260.00
Assessor Name: Eduardo Lopez
Date Created: 01/10/2017

Notes: The lighting system is beyond its service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	43,100
Year Built:	1967
Last Renovation:	
Replacement Value:	\$8,607,011
Repair Cost:	\$3,028,551.00
Total FCI:	35.19 %
Total RSLI:	32.15 %
FCA Score:	64.81







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	43,100
Year Built:	1967	Last Renovation:	
Repair Cost:	\$3,028,551	Replacement Value:	\$8,607,011
FCI:	35.19 %	RSLI%:	32.15 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	50.00 %	0.00 %	\$0.00
A20 - Basement Construction	50.00 %	0.00 %	\$0.00
B10 - Superstructure	50.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	20.19 %	62.68 %	\$605,900.00
B30 - Roofing	42.93 %	0.00 %	\$0.00
C10 - Interior Construction	25.38 %	0.00 %	\$0.00
C30 - Interior Finishes	55.48 %	0.00 %	\$0.00
D20 - Plumbing	13.33 %	0.00 %	\$0.00
D30 - HVAC	9.56 %	87.33 %	\$1,988,375.00
D40 - Fire Protection	0.00 %	110.00 %	\$198,174.00
D50 - Electrical	51.08 %	0.00 %	\$0.00
E10 - Equipment	72.62 %	0.00 %	\$0.00
E20 - Furnishings	0.00 %	110.00 %	\$236,102.00
Totals:	32.15 %	35.19 %	\$3,028,551.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). North Elevation - Feb 14, 2017



2). West Elevation - Feb 14, 2017



3). Southwest Elevation - Feb 14, 2017



4). Northeast Elevation - Feb 14, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.



Campus Assessment Report - 1967 Gym Building

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$2.18	S.F.	43,100	100	1967	2067		50.00 %	0.00 %	50			\$93,958
A1030	Slab on Grade	\$4.08	S.F.	43,100	100	1967	2067		50.00 %	0.00 %	50			\$175,848
A2010	Basement Excavation	\$0.83	S.F.	43,100	100	1967	2067		50.00 %	0.00 %	50			\$35,773
A2020	Basement Walls	\$5.74	S.F.	43,100	100	1967	2067		50.00 %	0.00 %	50			\$247,394
B1020	Roof Construction	\$7.60	S.F.	43,100	100	1967	2067		50.00 %	0.00 %	50			\$327,560
B2010	Exterior Walls	\$8.84	S.F.	43,100	100	1967	2067		50.00 %	0.00 %	50			\$381,004
B2020	Exterior Windows	\$12.78	S.F.	43,100	30	1967	1997		0.00 %	110.00 %	-20		\$605,900.00	\$550,818
B2030	Exterior Doors	\$0.81	S.F.	43,100	30	1967	1997	2021	13.33 %	0.00 %	4			\$34,911
B3010120	Single Ply Membrane	\$6.98	S.F.	28,005	20	2010	2030		65.00 %	0.00 %	13			\$195,475
B3010130	Preformed Metal Roofing	\$9.66	S.F.	15,095	30	1967	1997	2021	13.33 %	0.00 %	4			\$145,818
C1010	Partitions	\$4.70	S.F.	43,100	75	1967	2042		33.33 %	0.00 %	25			\$202,570
C1020	Interior Doors	\$2.44	S.F.	43,100	30	1967	1997	2021	13.33 %	0.00 %	4			\$105,164
C1030	Fittings	\$1.48	S.F.	43,100	20	1967	1987	2021	20.00 %	0.00 %	4			\$63,788
C3010	Wall Finishes	\$2.56	S.F.	43,100	10	1967	1977	2021	40.00 %	0.00 %	4			\$110,336
C3020	Floor Finishes	\$10.94	S.F.	43,100	20	1967	1987	2021	20.00 %	0.00 %	4			\$471,514
C3030	Ceiling Finishes	\$10.56	S.F.	43,100	25	2016	2041		96.00 %	0.00 %	24			\$455,136
D2010	Plumbing Fixtures	\$8.83	S.F.	43,100	30	1967	1997	2021	13.33 %	0.00 %	4			\$380,573
D2020	Domestic Water Distribution	\$1.64	S.F.	43,100	30	1967	1997	2021	13.33 %	0.00 %	4			\$70,684
D2030	Sanitary Waste	\$2.59	S.F.	43,100	30	1967	1997	2021	13.33 %	0.00 %	4			\$111,629
D2040	Rain Water Drainage	\$0.63	S.F.	43,100	30	1967	1997	2021	13.33 %	0.00 %	4			\$27,153
D3020	Heat Generating Systems	\$6.93	S.F.	43,100	30	1967	1997		0.00 %	110.00 %	-20		\$328,551.00	\$298,683
D3030	Cooling Generating Systems	\$7.18	S.F.	43,100	25	2007	2032		60.00 %	0.00 %	15			\$309,458
D3040	Distribution Systems	\$8.37	S.F.	43,100	30	1967	1997		0.00 %	110.00 %	-20		\$396,822.00	\$360,747
D3050	Terminal & Package Units	\$26.64	S.F.	43,100	15	1967	1982		0.00 %	110.00 %	-35		\$1,263,002.00	\$1,148,184
D3060	Controls & Instrumentation	\$2.65	S.F.	43,100	20	1967	1987	2021	20.00 %	0.00 %	4			\$114,215
D3090	Other HVAC Systems/Equip	\$1.06	S.F.	43,100	20	1967	1987	2021	20.00 %	0.00 %	4			\$45,686
D4010	Sprinklers	\$3.63	S.F.	43,100	30	1967	1997		0.00 %	110.00 %	-20		\$172,098.00	\$156,453
D4020	Standpipes	\$0.55	S.F.	43,100	30	1967	1997		0.00 %	110.00 %	-20		\$26,076.00	\$23,705
D5010	Electrical Service/Distribution	\$1.60	S.F.	43,100	40	1967	2007	2021	10.00 %	0.00 %	4			\$68,960
D5020	Branch Wiring	\$4.55	S.F.	43,100	30	1967	1997	2021	13.33 %	0.00 %	4			\$196,105
D5020	Lighting	\$10.64	S.F.	43,100	30	2016	2046		96.67 %	0.00 %	29			\$458,584
D5030810	Security & Detection Systems	\$1.97	S.F.	43,100	15	1967	1982	2021	26.67 %	0.00 %	4			\$84,907
D5030910	Fire Alarm Systems	\$3.56	S.F.	43,100	15	1967	1982	2021	26.67 %	0.00 %	4			\$153,436
D5030920	Data Communication	\$4.61	S.F.	43,100	15	1967	1982	2021	26.67 %	0.00 %	4			\$198,691
E1010	Commercial Equipment	\$0.59	S.F.	43,100	20	1967	1987	2021	20.00 %	0.00 %	4			\$25,429
E1020	Institutional Equipment	\$13.04	S.F.	43,100	20	2012	2032		75.00 %	0.00 %	15			\$562,024
E2010	Fixed Furnishings	\$4.98	S.F.	43,100	20	1967	1987		0.00 %	110.00 %	-30		\$236,102.00	\$214,638
Total									32.15 %	35.19 %			\$3,028,551.00	\$8,607,011

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1020 - Roof Construction



Note:

System: B2010 - Exterior Walls



Note:



System: B2020 - Exterior Windows



Note: The exterior windows are beyond their service life and should be replaced.

Campus Assessment Report - 1967 Gym Building

System: B2030 - Exterior Doors



Note:

System: B3010120 - Single Ply Membrane



Note:



System: B3010130 - Preformed Metal Roofing



Note:



Campus Assessment Report - 1967 Gym Building

System: C1010 - Partitions




Note:

System: C1020 - Interior Doors



Note:


System: C1030 - Fittings



Note:

Campus Assessment Report - 1967 Gym Building

System: C3010 - Wall Finishes




Note:

System: C3020 - Floor Finishes



Note:


System: C3030 - Ceiling Finishes



Note:

Campus Assessment Report - 1967 Gym Building

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

Campus Assessment Report - 1967 Gym Building

System: D2040 - Rain Water Drainage



Note:

System: D3020 - Heat Generating Systems



Note: The heat generating systems are beyond their service life and should be replaced.


System: D3030 - Cooling Generating Systems



Note:

Campus Assessment Report - 1967 Gym Building

System: D3040 - Distribution Systems



Note: The distribution system is beyond its service life and should be replaced.

System: D3050 - Terminal & Package Units



Note: The terminal and package units are beyond their service life and should be replaced.

System: D3060 - Controls & Instrumentation



Note:

Campus Assessment Report - 1967 Gym Building

System: D3090 - Other HVAC Systems/Equip



Note:

System: D4010 - Sprinklers

This system contains no images

Note: The building does not have a fire protection system and it should be installed.

System: D4020 - Standpipes

This system contains no images

Note: The building does not have a fire protection system and it should be installed.

System: D5010 - Electrical Service/Distribution



Note:



System: D5020 - Branch Wiring



Note:

Campus Assessment Report - 1967 Gym Building

System: D5020 - Lighting




Note:

System: D5030810 - Security & Detection Systems



Note:


System: D5030910 - Fire Alarm Systems



Note:

Campus Assessment Report - 1967 Gym Building

System: D5030920 - Data Communication






Note:

System: E1010 - Commercial Equipment



Note:


System: E1020 - Institutional Equipment



Note:

Campus Assessment Report - 1967 Gym Building

System: E2010 - Fixed Furnishings



Note: The fixed furnishings are beyond their service life and should be replaced.

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$3,028,551	\$0	\$0	\$0	\$3,028,438	\$0	\$0	\$0	\$0	\$0	\$0	\$6,056,989
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$605,900	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$605,900
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$43,222	\$0	\$0	\$0	\$0	\$0	\$0	\$43,222
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$226,484	\$0	\$0	\$0	\$0	\$0	\$0	\$226,484
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$130,199	\$0	\$0	\$0	\$0	\$0	\$0	\$130,199
C1030 - Fittings	\$0	\$0	\$0	\$0	\$78,974	\$0	\$0	\$0	\$0	\$0	\$0	\$78,974
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$136,603	\$0	\$0	\$0	\$0	\$0	\$0	\$136,603


Campus Assessment Report - 1967 Gym Building

C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$583,762	\$0	\$0	\$0	\$0	\$0	\$0	\$583,762
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$471,172	\$0	\$0	\$0	\$0	\$0	\$0	\$471,172
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$87,511	\$0	\$0	\$0	\$0	\$0	\$0	\$87,511
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$138,203	\$0	\$0	\$0	\$0	\$0	\$0	\$138,203
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$33,617	\$0	\$0	\$0	\$0	\$0	\$0	\$33,617
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$328,551	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$328,551
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$396,822	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$396,822
D3050 - Terminal & Package Units	\$1,263,002	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,263,002
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$141,406	\$0	\$0	\$0	\$0	\$0	\$0	\$141,406
D3090 - Other HVAC Systems/Equip	\$0	\$0	\$0	\$0	\$56,562	\$0	\$0	\$0	\$0	\$0	\$0	\$56,562
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$172,098	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$172,098
D4020 - Standpipes	\$26,076	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$26,076
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$85,377	\$0	\$0	\$0	\$0	\$0	\$0	\$85,377
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$242,790	\$0	\$0	\$0	\$0	\$0	\$0	\$242,790
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$105,120	\$0	\$0	\$0	\$0	\$0	\$0	\$105,120
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$189,963	\$0	\$0	\$0	\$0	\$0	\$0	\$189,963
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$245,991	\$0	\$0	\$0	\$0	\$0	\$0	\$245,991
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1010 - Commercial Equipment	\$0	\$0	\$0	\$0	\$31,483	\$0	\$0	\$0	\$0	\$0	\$0	\$31,483
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$236,102	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$236,102

** Indicates non-renewable system*


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$3,028,551.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$3,028,551.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2020	Exterior Windows	\$0.00	\$0.00	\$605,900.00	\$0.00	\$0.00	\$605,900.00
D3020	Heat Generating Systems	\$0.00	\$0.00	\$328,551.00	\$0.00	\$0.00	\$328,551.00
D3040	Distribution Systems	\$0.00	\$0.00	\$396,822.00	\$0.00	\$0.00	\$396,822.00
D3050	Terminal & Package Units	\$0.00	\$0.00	\$1,263,002.00	\$0.00	\$0.00	\$1,263,002.00
D4010	Sprinklers	\$0.00	\$0.00	\$172,098.00	\$0.00	\$0.00	\$172,098.00
D4020	Standpipes	\$0.00	\$0.00	\$26,076.00	\$0.00	\$0.00	\$26,076.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$236,102.00	\$0.00	\$0.00	\$236,102.00
	Total:	\$0.00	\$0.00	\$3,028,551.00	\$0.00	\$0.00	\$3,028,551.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B2020 - Exterior Windows



Location: Exterior Walls
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 43,100.00
Unit of Measure: S.F.
Estimate: \$605,900.00
Assessor Name: Eduardo Lopez
Date Created: 02/13/2017

Notes: The exterior windows are beyond their service life and should be replaced.

System: D3020 - Heat Generating Systems



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 43,100.00
Unit of Measure: S.F.
Estimate: \$328,551.00
Assessor Name: Eduardo Lopez
Date Created: 02/13/2017

Notes: The heat generating systems are beyond their service life and should be replaced.

System: D3040 - Distribution Systems



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 43,100.00
Unit of Measure: S.F.
Estimate: \$396,822.00
Assessor Name: Eduardo Lopez
Date Created: 02/13/2017

Notes: The distribution system is beyond its service life and should be replaced.

System: D3050 - Terminal & Package Units



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 43,100.00
Unit of Measure: S.F.
Estimate: \$1,263,002.00
Assessor Name: Eduardo Lopez
Date Created: 02/13/2017

Notes: The terminal and package units are beyond their service life and should be replaced.

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout Building
Distress: Missing
Category: Building Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 43,100.00
Unit of Measure: S.F.
Estimate: \$172,098.00
Assessor Name: Eduardo Lopez
Date Created: 02/13/2017

Notes: The building does not have a fire protection system and it should be installed.


System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout Building
Distress: Missing
Category: Building Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 43,100.00
Unit of Measure: S.F.
Estimate: \$26,076.00
Assessor Name: Eduardo Lopez
Date Created: 02/13/2017

Notes: The building does not have a fire protection system and it should be installed.

System: E2010 - Fixed Furnishings



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 43,100.00
Unit of Measure: S.F.
Estimate: \$236,102.00
Assessor Name: Eduardo Lopez
Date Created: 02/13/2017

Notes: The fixed furnishings are beyond their service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	450
Year Built:	1967
Last Renovation:	
Replacement Value:	\$57,919
Repair Cost:	\$4,717.00
Total FCI:	8.14 %
Total RSLI:	28.76 %
FCA Score:	91.86







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	450
Year Built:	1967	Last Renovation:	
Repair Cost:	\$4,717	Replacement Value:	\$57,919
FCI:	8.14 %	RSLI%:	28.76 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	50.00 %	0.00 %	\$0.00
B10 - Superstructure	50.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	48.24 %	0.00 %	\$0.00
B30 - Roofing	20.00 %	0.00 %	\$0.00
C10 - Interior Construction	27.33 %	0.00 %	\$0.00
C30 - Interior Finishes	18.61 %	35.26 %	\$4,717.00
D20 - Plumbing	13.33 %	0.00 %	\$0.00
D30 - HVAC	26.67 %	0.00 %	\$0.00
D50 - Electrical	12.22 %	0.00 %	\$0.00
Totals:	28.76 %	8.14 %	\$4,717.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). East Elevation - Jan 10, 2017



2). South Elevation - Jan 10, 2017



3). West Elevation - Jan 10, 2017



4). North Elevation - Jan 10, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

Campus Assessment Report - 1967 Restroom Building

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$6.93	S.F.	450	100	1967	2067		50.00 %	0.00 %	50			\$3,119
A1030	Slab on Grade	\$7.37	S.F.	450	100	1967	2067		50.00 %	0.00 %	50			\$3,317
B1020	Roof Construction	\$5.98	S.F.	450	100	1967	2067		50.00 %	0.00 %	50			\$2,691
B2010	Exterior Walls	\$18.04	S.F.	450	100	1967	2067		50.00 %	0.00 %	50			\$8,118
B2030	Exterior Doors	\$0.91	S.F.	450	30	1967	1997	2021	13.33 %	0.00 %	4			\$410
B3010140	Asphalt Shingles	\$4.32	S.F.	450	20	1967	1987	2021	20.00 %	0.00 %	4			\$1,944
C1010	Partitions	\$10.34	S.F.	450	75	1967	2042		33.33 %	0.00 %	25			\$4,653
C1030	Fittings	\$8.47	S.F.	450	20	1967	1987	2021	20.00 %	0.00 %	4			\$3,812
C3010	Wall Finishes	\$7.46	S.F.	450	10	1967	1977	2021	40.00 %	0.00 %	4			\$3,357
C3020	Floor Finishes	\$12.74	S.F.	450	20	1967	1987	2021	20.00 %	0.00 %	4			\$5,733
C3030	Ceiling Finishes	\$9.53	S.F.	450	25	1967	1992		0.00 %	109.98 %	-25		\$4,717.00	\$4,289
D2010	Plumbing Fixtures	\$9.98	S.F.	450	30	1967	1997	2021	13.33 %	0.00 %	4			\$4,491
D2020	Domestic Water Distribution	\$0.84	S.F.	450	30	1967	1997	2021	13.33 %	0.00 %	4			\$378
D2030	Sanitary Waste	\$5.94	S.F.	450	30	1967	1997	2021	13.33 %	0.00 %	4			\$2,673
D3050	Terminal & Package Units	\$10.63	S.F.	450	15	1967	1982	2021	26.67 %	0.00 %	4			\$4,784
D5010	Electrical Service/Distribution	\$3.09	S.F.	450	40	1967	2007	2021	10.00 %	0.00 %	4			\$1,391
D5020	Branch Wiring	\$2.55	S.F.	450	30	1967	1997	2021	13.33 %	0.00 %	4			\$1,148
D5020	Lighting	\$3.58	S.F.	450	30	1967	1997	2021	13.33 %	0.00 %	4			\$1,611
Total									28.76 %	8.14 %			\$4,717.00	\$57,919

System Notes


The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2030 - Exterior Doors



Note:



System: B3010140 - Asphalt Shingles



Note:




Campus Assessment Report - 1967 Restroom Building

System: C1010 - Partitions






Note:

System: C1030 - Fittings



Note:




System: C3010 - Wall Finishes



Note:

Campus Assessment Report - 1967 Restroom Building

System: C3020 - Floor Finishes




Note:

System: C3030 - Ceiling Finishes



Note: The ceiling finishes are beyond their service life and should be replaced.



System: D2010 - Plumbing Fixtures



Note:



Campus Assessment Report - 1967 Restroom Building

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

System: D3050 - Terminal & Package Units



Note:

Campus Assessment Report - 1967 Restroom Building

System: D5010 - Electrical Service/Distribution




Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$4,717	\$0	\$0	\$0	\$40,070	\$0	\$0	\$0	\$0	\$0	\$0	\$44,787
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$506	\$0	\$0	\$0	\$0	\$0	\$0	\$506
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$3,194	\$0	\$0	\$0	\$0	\$0	\$0	\$3,194
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$4,719	\$0	\$0	\$0	\$0	\$0	\$0	\$4,719
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$4,157	\$0	\$0	\$0	\$0	\$0	\$0	\$4,157
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$7,097	\$0	\$0	\$0	\$0	\$0	\$0	\$7,097
C3030 - Ceiling Finishes	\$4,717	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,717
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$5,560	\$0	\$0	\$0	\$0	\$0	\$0	\$5,560
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$468	\$0	\$0	\$0	\$0	\$0	\$0	\$468


Campus Assessment Report - 1967 Restroom Building

D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$3,309	\$0	\$0	\$0	\$0	\$0	\$0	\$3,309
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$5,922	\$0	\$0	\$0	\$0	\$0	\$0	\$5,922
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$1,722	\$0	\$0	\$0	\$0	\$0	\$0	\$1,722
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$1,420	\$0	\$0	\$0	\$0	\$0	\$0	\$1,420
D5020 - Lighting	\$0	\$0	\$0	\$0	\$1,994	\$0	\$0	\$0	\$0	\$0	\$0	\$1,994

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$4,717.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
C3030	Ceiling Finishes	\$0.00	\$0.00	\$4,717.00	\$0.00	\$0.00	\$4,717.00
	Total:	\$0.00	\$0.00	\$4,717.00	\$0.00	\$0.00	\$4,717.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: C3030 - Ceiling Finishes



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 450.00
Unit of Measure: S.F.
Estimate: \$4,717.00
Assessor Name: Eduardo Lopez
Date Created: 01/10/2017

Notes: The ceiling finishes are beyond their service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	460
Year Built:	1967
Last Renovation:	
Replacement Value:	\$92,322
Repair Cost:	\$10,808.00
Total FCI:	11.71 %
Total RSLI:	29.90 %
FCA Score:	88.29







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	460
Year Built:	1967	Last Renovation:	
Repair Cost:	\$10,808	Replacement Value:	\$92,322
FCI:	11.71 %	RSLI%:	29.90 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	50.00 %	0.00 %	\$0.00
B10 - Superstructure	50.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	37.65 %	0.00 %	\$0.00
B30 - Roofing	20.00 %	0.00 %	\$0.00
C10 - Interior Construction	29.82 %	0.00 %	\$0.00
C30 - Interior Finishes	16.03 %	12.58 %	\$2,586.00
D20 - Plumbing	13.33 %	0.00 %	\$0.00
D50 - Electrical	0.00 %	109.99 %	\$8,222.00
E20 - Furnishings	20.00 %	0.00 %	\$0.00
Totals:	29.90 %	11.71 %	\$10,808.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). South Elevation - Jan 10, 2017



2). West Elevation - Jan 10, 2017



3). North Elevation - Jan 10, 2017



4). East Elevation - Jan 10, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

Campus Assessment Report - 1967 Storage Building

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	460	100	1967	2067		50.00 %	0.00 %	50			\$9,260
A1030	Slab on Grade	\$19.75	S.F.	460	100	1967	2067		50.00 %	0.00 %	50			\$9,085
B1020	Roof Construction	\$16.26	S.F.	460	100	1967	2067		50.00 %	0.00 %	50			\$7,480
B2010	Exterior Walls	\$29.79	S.F.	460	100	1967	2067		50.00 %	0.00 %	50			\$13,703
B2020	Exterior Windows	\$6.47	S.F.	460	30	1967	1997	2021	13.33 %	0.00 %	4			\$2,976
B2030	Exterior Doors	\$8.66	S.F.	460	30	1967	1997	2021	13.33 %	0.00 %	4			\$3,984
B3010140	Asphalt Shingles	\$4.32	S.F.	460	20	1967	1987	2021	20.00 %	0.00 %	4			\$1,987
C1010	Partitions	\$10.34	S.F.	460	75	1967	2042		33.33 %	0.00 %	25			\$4,756
C1020	Interior Doors	\$2.20	S.F.	460	30	1967	1997	2021	13.33 %	0.00 %	4			\$1,012
C3010	Wall Finishes	\$5.11	S.F.	460	10	1967	1977		0.00 %	110.00 %	-40		\$2,586.00	\$2,351
C3020	Floor Finishes	\$20.82	S.F.	460	20	1967	1987	2021	20.00 %	0.00 %	4			\$9,577
C3030	Ceiling Finishes	\$18.76	S.F.	460	25	1967	1992	2021	16.00 %	0.00 %	4			\$8,630
D2010	Plumbing Fixtures	\$9.98	S.F.	460	30	1967	1997	2021	13.33 %	0.00 %	4			\$4,591
D2020	Domestic Water Distribution	\$0.84	S.F.	460	30	1967	1997	2021	13.33 %	0.00 %	4			\$386
D2030	Sanitary Waste	\$5.94	S.F.	460	30	1967	1997	2021	13.33 %	0.00 %	4			\$2,732
D5010	Electrical Service/Distribution	\$3.09	S.F.	460	40	1967	2007		0.00 %	110.06 %	-10		\$1,564.00	\$1,421
D5020	Branch Wiring	\$3.58	S.F.	460	30	1967	1997		0.00 %	109.96 %	-20		\$1,811.00	\$1,647
D5020	Lighting	\$9.58	S.F.	460	30	1967	1997		0.00 %	109.98 %	-20		\$4,847.00	\$4,407
E2010	Fixed Furnishings	\$5.08	S.F.	460	20	1967	1987	2021	20.00 %	0.00 %	4			\$2,337
Total									29.90 %	11.71 %			\$10,808.00	\$92,322

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls




Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1967 Storage Building

System: B3010140 - Asphalt Shingles



Note:

System: C1010 - Partitions



Note:


System: C1020 - Interior Doors



Note:

Campus Assessment Report - 1967 Storage Building

System: C3010 - Wall Finishes



Note: The wall finishes are beyond their service life and should be replaced.

System: C3020 - Floor Finishes



Note:


System: C3030 - Ceiling Finishes



Note:

Campus Assessment Report - 1967 Storage Building

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:


Campus Assessment Report - 1967 Storage Building

System: D5010 - Electrical Service/Distribution




Note: The electrical service distribution is beyond its service life and should be replaced.

System: D5020 - Branch Wiring



Note: The branch wiring is beyond its service life and should be replaced.


System: D5020 - Lighting



Note: The lighting system is beyond its service life and should be replaced.

Campus Assessment Report - 1967 Storage Building

System: E20 - Furnishings



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$10,808	\$0	\$0	\$0	\$48,114	\$0	\$0	\$0	\$0	\$0	\$3,475	\$62,398
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$3,685	\$0	\$0	\$0	\$0	\$0	\$0	\$3,685
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$4,932	\$0	\$0	\$0	\$0	\$0	\$0	\$4,932
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$3,265	\$0	\$0	\$0	\$0	\$0	\$0	\$3,265
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$1,253	\$0	\$0	\$0	\$0	\$0	\$0	\$1,253
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$2,586	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,475	\$6,061
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$11,857	\$0	\$0	\$0	\$0	\$0	\$0	\$11,857
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$10,684	\$0	\$0	\$0	\$0	\$0	\$0	\$10,684
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$5,684	\$0	\$0	\$0	\$0	\$0	\$0	\$5,684


Campus Assessment Report - 1967 Storage Building

D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$478	\$0	\$0	\$0	\$0	\$0	\$0	\$478
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$3,383	\$0	\$0	\$0	\$0	\$0	\$0	\$3,383
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$1,564	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,564
D5020 - Branch Wiring	\$1,811	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,811
D5020 - Lighting	\$4,847	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,847
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$2,893	\$0	\$0	\$0	\$0	\$0	\$0	\$2,893

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$10,808.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$10,808.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
C3010	Wall Finishes	\$0.00	\$0.00	\$2,586.00	\$0.00	\$0.00	\$2,586.00
D5010	Electrical Service/Distribution	\$0.00	\$0.00	\$1,564.00	\$0.00	\$0.00	\$1,564.00
D5020	Branch Wiring	\$0.00	\$0.00	\$1,811.00	\$0.00	\$0.00	\$1,811.00
D5020	Lighting	\$0.00	\$0.00	\$4,847.00	\$0.00	\$0.00	\$4,847.00
	Total:	\$0.00	\$0.00	\$10,808.00	\$0.00	\$0.00	\$10,808.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: C3010 - Wall Finishes



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 460.00
Unit of Measure: S.F.
Estimate: \$2,586.00
Assessor Name: Terence Davis
Date Created: 01/10/2017

Notes: The wall finishes are beyond its service life and should be replaced.

System: D5010 - Electrical Service/Distribution



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 460.00
Unit of Measure: S.F.
Estimate: \$1,564.00
Assessor Name: Terence Davis
Date Created: 01/10/2017

Notes: The electrical service distribution is beyond its service life and should be replaced.

System: D5020 - Branch Wiring



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 460.00
Unit of Measure: S.F.
Estimate: \$1,811.00
Assessor Name: Terence Davis
Date Created: 01/10/2017

Notes: The branch wiring is beyond its service life and should be replaced.

System: D5020 - Lighting



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 460.00
Unit of Measure: S.F.
Estimate: \$4,847.00
Assessor Name: Terence Davis
Date Created: 01/10/2017

Notes: The lighting system is beyond its service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	178,900
Year Built:	1967
Last Renovation:	
Replacement Value:	\$34,920,145
Repair Cost:	\$9,044,466.68
Total FCI:	25.90 %
Total RSLI:	36.78 %
FCA Score:	74.10







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	178,900
Year Built:	1967	Last Renovation:	
Repair Cost:	\$9,044,467	Replacement Value:	\$34,920,145
FCI:	25.90 %	RSLI%:	36.78 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	50.00 %	0.00 %	\$0.00
A20 - Basement Construction	50.00 %	0.00 %	\$0.00
B10 - Superstructure	50.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	27.78 %	0.33 %	\$13,200.00
B30 - Roofing	52.99 %	4.25 %	\$41,326.00
C10 - Interior Construction	25.38 %	1.57 %	\$24,189.00
C20 - Stairs	50.00 %	0.00 %	\$0.00
C30 - Interior Finishes	55.48 %	4.85 %	\$208,642.74
D10 - Conveying	0.00 %	110.00 %	\$192,854.00
D20 - Plumbing	11.11 %	70.18 %	\$1,737,656.00
D30 - HVAC	16.32 %	71.28 %	\$3,945,640.00
D40 - Fire Protection	0.00 %	110.00 %	\$822,583.00
D50 - Electrical	51.05 %	0.48 %	\$23,567.94
E10 - Equipment	52.12 %	31.05 %	\$1,054,794.00
E20 - Furnishings	0.00 %	110.00 %	\$980,014.00
Totals:	36.78 %	25.90 %	\$9,044,466.68

Photo Album

The photo album consists of the various cardinal directions of the building..

1). South Elevation - Jan 11, 2017



2). Southwest Elevation - Jan 11, 2017



3). East Elevation - Jan 11, 2017



4). North Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$2.18	S.F.	178,900	100	1967	2067		50.00 %	0.00 %	50			\$390,002
A1030	Slab on Grade	\$4.08	S.F.	178,900	100	1967	2067		50.00 %	0.00 %	50			\$729,912
A2010	Basement Excavation	\$0.83	S.F.	178,900	100	1967	2067		50.00 %	0.00 %	50			\$148,487
A2020	Basement Walls	\$5.74	S.F.	178,900	100	1967	2067		50.00 %	0.00 %	50			\$1,026,886
B1010	Floor Construction	\$11.42	S.F.	178,900	100	1967	2067		50.00 %	0.00 %	50			\$2,043,038
B1020	Roof Construction	\$7.60	S.F.	178,900	100	1967	2067		50.00 %	0.00 %	50			\$1,359,640
B2010	Exterior Walls	\$8.84	S.F.	178,900	100	1967	2067		50.00 %	0.83 %	50		\$13,200.00	\$1,581,476
B2020	Exterior Windows	\$12.78	S.F.	178,900	30	1967	1997	2021	13.33 %	0.00 %	4			\$2,286,342
B2030	Exterior Doors	\$0.81	S.F.	178,900	30	1967	1997	2021	13.33 %	0.00 %	4			\$144,909
B3010120	Single Ply Membrane	\$6.98	S.F.	108,270	20	2010	2030		65.00 %	0.00 %	13			\$755,725
B3010130	Preformed Metal Roofing	\$9.66	S.F.	18,508	30	1977	2007	2021	13.33 %	0.00 %	4			\$178,787
B3020	Roof Openings	\$0.21	S.F.	178,900	25	1967	1992		0.00 %	110.00 %	-25		\$41,326.00	\$37,569
C1010	Partitions	\$4.70	S.F.	178,900	75	1967	2042		33.33 %	1.57 %	25		\$13,200.00	\$840,830
C1020	Interior Doors	\$2.44	S.F.	178,900	30	1967	1997	2021	13.33 %	0.00 %	4			\$436,516
C1030	Fittings	\$1.48	S.F.	178,900	20	1967	1987	2021	20.00 %	4.15 %	4		\$10,989.00	\$264,772
C2010	Stair Construction	\$1.29	S.F.	178,900	100	1967	2067		50.00 %	0.00 %	50			\$230,781
C3010	Wall Finishes	\$2.56	S.F.	178,900	10	1967	1977	2021	40.00 %	0.00 %	4			\$457,984
C3020	Floor Finishes	\$10.94	S.F.	178,900	20	1967	1987	2021	20.00 %	8.09 %	4		\$158,238.80	\$1,957,166
C3030	Ceiling Finishes	\$10.56	S.F.	178,900	25	2016	2041		96.00 %	2.67 %	24		\$50,403.94	\$1,889,184
D1010	Elevators and Lifts	\$0.98	S.F.	178,900	30	1967	1997		0.00 %	110.00 %	-20		\$192,854.00	\$175,322
D2010	Plumbing Fixtures	\$8.83	S.F.	178,900	30	1967	1997		0.00 %	110.00 %	-20		\$1,737,656.00	\$1,579,687
D2020	Domestic Water Distribution	\$1.64	S.F.	178,900	30	2007	2037		66.67 %	0.00 %	20			\$293,396
D2030	Sanitary Waste	\$2.59	S.F.	178,900	30	1967	1997	2021	13.33 %	0.00 %	4			\$463,351
D2040	Rain Water Drainage	\$0.63	S.F.	178,900	30	1967	1997	2021	13.33 %	0.00 %	4			\$112,707
D2090	Other Plumbing Systems -Nat Gas	\$0.15	S.F.	178,900	40	1967	2007	2021	10.00 %	0.00 %	4			\$26,835
D3020	Heat Generating Systems	\$6.93	S.F.	178,900	30	1967	1997		0.00 %	110.00 %	-20		\$1,363,755.00	\$1,239,777
D3030	Cooling Generating Systems	\$7.18	S.F.	178,900	25	2007	2032		60.00 %	0.00 %	15			\$1,284,502
D3040	Distribution Systems	\$8.37	S.F.	178,900	30	1967	1997		0.00 %	110.00 %	-20		\$1,647,132.00	\$1,497,393
D3050	Terminal & Package Units	\$4.75	S.F.	178,900	15	1967	1982		0.00 %	110.00 %	-35		\$934,753.00	\$849,775
D3060	Controls & Instrumentation	\$2.65	S.F.	178,900	20	1967	1987	2021	20.00 %	0.00 %	4			\$474,085
D3090	Other HVAC Systems/Equip	\$1.06	S.F.	178,900	20	1967	1987	2021	20.00 %	0.00 %	4			\$189,634
D4010	Sprinklers	\$3.63	S.F.	178,900	30	1967	1997		0.00 %	110.00 %	-20		\$714,348.00	\$649,407
D4020	Standpipes	\$0.55	S.F.	178,900	30	1967	1997		0.00 %	110.00 %	-20		\$108,235.00	\$98,395
D5010	Electrical Service/Distribution	\$1.60	S.F.	178,900	40	1967	2007	2021	10.00 %	0.00 %	4			\$286,240


Campus Assessment Report - 1967, 1977 Main Building

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
D5020	Branch Wiring	\$4.55	S.F.	178,900	30	1967	1997	2021	13.33 %	0.00 %	4			\$813,995
D5020	Lighting	\$10.64	S.F.	178,900	30	2016	2046		96.67 %	1.24 %	29		\$23,567.94	\$1,903,496
D5030810	Security & Detection Systems	\$1.97	S.F.	178,900	15	1967	1982	2021	26.67 %	0.00 %	4			\$352,433
D5030910	Fire Alarm Systems	\$3.56	S.F.	178,900	15	1967	1982	2021	26.67 %	0.00 %	4			\$636,884
D5030920	Data Communication	\$4.61	S.F.	178,900	15	1967	1982	2021	26.67 %	0.00 %	4			\$824,729
D5090	Other Electrical Systems	\$0.67	S.F.	178,900	20	2007	2027		50.00 %	0.00 %	10			\$119,863
E1010	Commercial Equipment	\$0.59	S.F.	178,900	20	1967	1987	2021	20.00 %	0.00 %	4			\$105,551
E1020	Institutional Equipment	\$13.04	S.F.	178,900	20	2012	2032		75.00 %	0.00 %	15			\$2,332,856
E1090	Other Equipment	\$5.36	S.F.	178,900	20	1967	1987		0.00 %	110.00 %	-30		\$1,054,794.00	\$958,904
E2010	Fixed Furnishings	\$4.98	S.F.	178,900	20	1967	1987		0.00 %	110.00 %	-30		\$980,014.00	\$890,922
Total									36.78 %	25.90 %			\$9,044,466.68	\$34,920,145

System Notes



The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1010 - Floor Construction



Note:

System: B1020 - Roof Construction



Note:

System: B2010 - Exterior Walls



Note:

Campus Assessment Report - 1967, 1977 Main Building

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

System: B3010120 - Single Ply Membrane



Note:

Campus Assessment Report - 1967, 1977 Main Building

System: B3010130 - Preformed Metal Roofing





Note:

System: B3020 - Roof Openings



Note: The roof openings are beyond their service life and should be replaced.


System: C1010 - Partitions



Note:


Campus Assessment Report - 1967, 1977 Main Building

System: C1020 - Interior Doors



Note:


System: C1030 - Fittings



Note:




Campus Assessment Report - 1967, 1977 Main Building

System: C2010 - Stair Construction



Note:


System: C3010 - Wall Finishes



Note:



Campus Assessment Report - 1967, 1977 Main Building

System: C3020 - Floor Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

Campus Assessment Report - 1967, 1977 Main Building

System: D1010 - Elevators and Lifts



Note:

System: D2010 - Plumbing Fixtures



Note: The plumbing fixtures are beyond their service life and should be replaced.

System: D2020 - Domestic Water Distribution



Note:

Campus Assessment Report - 1967, 1977 Main Building

System: D2030 - Sanitary Waste



Note:

System: D2040 - Rain Water Drainage



Note:

System: D2090 - Other Plumbing Systems -Nat Gas



Note:

Campus Assessment Report - 1967, 1977 Main Building

System: D3020 - Heat Generating Systems



Note: The heat generating systems are beyond their service life and should be replaced.

System: D3030 - Cooling Generating Systems



Note:

System: D3040 - Distribution Systems



Note: The distribution system is beyond its service life and should be replaced.

Campus Assessment Report - 1967, 1977 Main Building

System: D3050 - Terminal & Package Units



Note: The terminal and package units are beyond their service life and should be replaced.

System: D3060 - Controls & Instrumentation



Note:

System: D3090 - Other HVAC Systems/Equip



Note:

System: D4010 - Sprinklers

This system contains no images

Note: The building does not have a fire protection system and it should be installed.

System: D4020 - Standpipes

This system contains no images

Note: The building does not have a fire protection system and it should be installed.

Campus Assessment Report - 1967, 1977 Main Building

System: D5010 - Electrical Service/Distribution



Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Campus Assessment Report - 1967, 1977 Main Building

System: D5030810 - Security & Detection Systems



Note:

System: D5030910 - Fire Alarm Systems



Note:

System: D5030920 - Data Communication



Note:

Campus Assessment Report - 1967, 1977 Main Building

System: D5090 - Other Electrical Systems






Note:

System: E1010 - Commercial Equipment



Note: The commercial equipment is beyond its service life and should be replaced.

System: E1020 - Institutional Equipment



Note:

Campus Assessment Report - 1967, 1977 Main Building

System: E1090 - Other Equipment



Note: The kitchen equipment is beyond its service life and should be replaced.

System: E2010 - Fixed Furnishings



Note: The fixed furnishings are beyond their service life and should be replaced.

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$9,044,467	\$0	\$0	\$0	\$12,452,937	\$0	\$0	\$0	\$0	\$0	\$177,194	\$21,674,597
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$13,200	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$13,200
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$2,830,628	\$0	\$0	\$0	\$0	\$0	\$0	\$2,830,628
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$179,406	\$0	\$0	\$0	\$0	\$0	\$0	\$179,406
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$277,692	\$0	\$0	\$0	\$0	\$0	\$0	\$277,692
B3020 - Roof Openings	\$41,326	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$41,326
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$13,200	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$13,200
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$540,433	\$0	\$0	\$0	\$0	\$0	\$0	\$540,433
C1030 - Fittings	\$10,989	\$0	\$0	\$0	\$327,803	\$0	\$0	\$0	\$0	\$0	\$0	\$338,792

Campus Assessment Report - 1967, 1977 Main Building

C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$567,011	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$567,011
C3020 - Floor Finishes	\$158,239	\$0	\$0	\$0	\$2,423,089	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,581,328
C3030 - Ceiling Finishes	\$50,404	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$50,404
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D10 - Conveying	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D1010 - Elevators and Lifts	\$192,854	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$192,854
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$1,737,656	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,737,656
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$573,656	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$573,656
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$139,538	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$139,538
D2090 - Other Plumbing Systems -Nat Gas	\$0	\$0	\$0	\$0	\$33,224	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$33,224
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$1,363,755	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,363,755
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$1,647,132	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,647,132
D3050 - Terminal & Package Units	\$934,753	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$934,753
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$586,946	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$586,946
D3090 - Other HVAC Systems/Equip	\$0	\$0	\$0	\$0	\$234,778	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$234,778
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$714,348	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$714,348
D4020 - Standpipes	\$108,235	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$108,235
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$354,382	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$354,382
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$1,007,775	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,007,775
D5020 - Lighting	\$23,568	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$23,568
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$436,333	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$436,333
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$788,500	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$788,500
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$1,021,064	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,021,064


Campus Assessment Report - 1967, 1977 Main Building

D5090 - Other Electrical Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$177,194	\$177,194
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1010 - Commercial Equipment	\$0	\$0	\$0	\$0	\$130,678	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$130,678
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1090 - Other Equipment	\$1,054,794	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,054,794
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$980,014	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$980,014

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$9,044,466.68

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$9,044,466.68


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2010	Exterior Walls	\$13,200.00	\$0.00	\$0.00	\$0.00	\$0.00	\$13,200.00
B3020	Roof Openings	\$0.00	\$0.00	\$41,326.00	\$0.00	\$0.00	\$41,326.00
C1010	Partitions	\$13,200.00	\$0.00	\$0.00	\$0.00	\$0.00	\$13,200.00
C1030	Fittings	\$0.00	\$0.00	\$10,989.00	\$0.00	\$0.00	\$10,989.00
C3020	Floor Finishes	\$0.00	\$0.00	\$158,238.80	\$0.00	\$0.00	\$158,238.80
C3030	Ceiling Finishes	\$0.00	\$0.00	\$50,403.94	\$0.00	\$0.00	\$50,403.94
D1010	Elevators and Lifts	\$0.00	\$0.00	\$192,854.00	\$0.00	\$0.00	\$192,854.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$1,737,656.00	\$0.00	\$0.00	\$1,737,656.00
D3020	Heat Generating Systems	\$0.00	\$0.00	\$1,363,755.00	\$0.00	\$0.00	\$1,363,755.00
D3040	Distribution Systems	\$0.00	\$0.00	\$1,647,132.00	\$0.00	\$0.00	\$1,647,132.00
D3050	Terminal & Package Units	\$0.00	\$0.00	\$934,753.00	\$0.00	\$0.00	\$934,753.00
D4010	Sprinklers	\$0.00	\$0.00	\$714,348.00	\$0.00	\$0.00	\$714,348.00
D4020	Standpipes	\$0.00	\$0.00	\$108,235.00	\$0.00	\$0.00	\$108,235.00
D5020	Lighting	\$0.00	\$0.00	\$23,567.94	\$0.00	\$0.00	\$23,567.94
E1090	Other Equipment	\$0.00	\$0.00	\$1,054,794.00	\$0.00	\$0.00	\$1,054,794.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$980,014.00	\$0.00	\$0.00	\$980,014.00
	Total:	\$26,400.00	\$0.00	\$9,018,066.68	\$0.00	\$0.00	\$9,044,466.68

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$9,044,466.68

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Currently Critical (Immediate):

System: B2010 - Exterior Walls



Location: Exterior Walls
Distress: Damaged
Category: Safety / Building Code Compliance
Priority: 1 - Currently Critical (Immediate)
Correction: Engineering Study-2016-11-15 17:41:59
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$13,200.00
Assessor Name: Terence Davis
Date Created: 01/06/2017

Notes: There are visible cracks on the exterior walls and it should be studied by a professional engineer.

System: C1010 - Partitions



Location: Media Center
Distress: Failing
Category: Safety / Building Code Compliance
Priority: 1 - Currently Critical (Immediate)
Correction: Engineering Study
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$13,200.00
Assessor Name: Terence Davis
Date Created: 01/06/2017

Notes: There are visible cracks on the partition wall and should be studied by a professional engineer.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B3020 - Roof Openings



Location: Roof
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$41,326.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The roof openings are beyond their service life and should be replaced by OSHA complaint access.

System: C1030 - Fittings



Location: Throughout Building
Distress: Inadequate
Category: Building Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Replace signage and toilet partitions
Qty: 150.00
Unit of Measure: Ea.
Estimate: \$10,989.00
Assessor Name: Terence Davis
Date Created: 02/14/2017

Notes: The signage is not ADA compliant and should be replaced.

System: C3020 - Floor Finishes



Location: Throughout building
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Replace carpet
Qty: 1,851.11
Unit of Measure: S.Y.
Estimate: \$158,238.80
Assessor Name: Terence Davis
Date Created: 01/06/2017

Notes: The carpet is beyond its service life and should be replaced.

System: C3030 - Ceiling Finishes



Location: Throughout building
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Acoustic tile repairs - (2% of ceilings)
Qty: 47.20
Unit of Measure: C.S.F.
Estimate: \$50,403.94
Assessor Name: Terence Davis
Date Created: 01/06/2017

Notes: The acoustical ceiling tiles are beyond their service life and should be replaced.

System: D1010 - Elevators and Lifts



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$192,854.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The elevators and lifts are beyond their service life and should be replaced.

System: D2010 - Plumbing Fixtures



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$1,737,656.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The plumbing fixtures are beyond their service life and should be replaced.

System: D3020 - Heat Generating Systems



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$1,363,755.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The heat generating systems are beyond their service life and should be replaced.


System: D3040 - Distribution Systems



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$1,647,132.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The distribution system is beyond its service life and should be replaced.

System: D3050 - Terminal & Package Units



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$934,753.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The terminal and package units are beyond their service life and should be replaced.

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$714,348.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The building does not have a fire protection system and it should be installed.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$108,235.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The building does not have a fire protection system and it should be installed.

System: D5020 - Lighting



Location: Throughout building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Replace fluorescent fixture, lay-in, recess mtd, 2' x 4', two 40 W
Qty: 75.00
Unit of Measure: Ea.
Estimate: \$23,567.94
Assessor Name: Terence Davis
Date Created: 01/06/2017

Notes: The lighting fixtures are beyond their service life and should be replaced.

System: E1090 - Other Equipment



Location: Cafeteria and Home Economics Classrooms
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$1,054,794.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The kitchen equipment is beyond its service life and should be replaced.

System: E2010 - Fixed Furnishings



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 178,900.00
Unit of Measure: S.F.
Estimate: \$980,014.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The fixed furnishings are beyond their service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	430
Year Built:	1977
Last Renovation:	
Replacement Value:	\$68,887
Repair Cost:	\$10,631.84
Total FCI:	15.43 %
Total RSLI:	31.65 %
FCA Score:	84.57







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	430
Year Built:	1977	Last Renovation:	
Repair Cost:	\$10,632	Replacement Value:	\$68,887
FCI:	15.43 %	RSLI%:	31.65 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	60.00 %	0.00 %	\$0.00
B10 - Superstructure	60.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	8.33 %	20.49 %	\$4,899.84
B30 - Roofing	0.00 %	137.99 %	\$5,732.00
C20 - Stairs	60.00 %	0.00 %	\$0.00
C30 - Interior Finishes	40.00 %	0.00 %	\$0.00
D50 - Electrical	12.84 %	0.00 %	\$0.00
Totals:	31.65 %	15.43 %	\$10,631.84

Photo Album

The photo album consists of the various cardinal directions of the building..

1). North Elevation - Jan 11, 2017



2). West Elevation - Jan 11, 2017



3). South Elevation - Jan 11, 2017



4). East Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	430	100	1977	2077		60.00 %	0.00 %	60			\$8,656
A1030	Slab on Grade	\$19.75	S.F.	430	100	1977	2077		60.00 %	0.00 %	60			\$8,493
B1010	Floor Construction	\$11.44	S.F.	430	100	1977	2077		60.00 %	0.00 %	60			\$4,919
B1020	Roof Construction	\$16.26	S.F.	430	100	1977	2077		60.00 %	0.00 %	60			\$6,992
B2010	Exterior Walls	\$29.79	S.F.	430	100	1977	2077	2021	4.00 %	38.25 %	4		\$4,899.84	\$12,810
B2020	Exterior Windows	\$17.17	S.F.	430	30	1977	2007	2021	13.33 %	0.00 %	4			\$7,383
B2030	Exterior Doors	\$8.66	S.F.	430	30	1977	2007	2021	13.33 %	0.00 %	4			\$3,724
B3010130	Preformed Metal Roofing	\$9.66	S.F.	430	30	1977	2007		0.00 %	137.99 %	-10		\$5,732.00	\$4,154
C2010	Stair Construction	\$1.32	S.F.	430	100	1977	2077		60.00 %	0.00 %	60			\$568
C3010	Wall Finishes	\$5.11	S.F.	430	10	1977	1987	2021	40.00 %	0.00 %	4			\$2,197
D5010	Electrical Service/Distribution	\$3.09	S.F.	430	40	1977	2017	2021	10.00 %	0.00 %	4			\$1,329
D5020	Branch Wiring	\$9.24	S.F.	430	30	1977	2007	2021	13.33 %	0.00 %	4			\$3,973
D5020	Lighting	\$8.58	S.F.	430	30	1977	2007	2021	13.33 %	0.00 %	4			\$3,689
Total									31.65 %	15.43 %			\$10,631.84	\$68,887

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1977 Baseball Pressbox

System: B3010130 - Preformed Metal Roofing



Note:

System: C2010 - Stair Construction



Note:

System: C3010 - Wall Finishes



Note:


Campus Assessment Report - 1977 Baseball Pressbox

System: D5010 - Electrical Service/Distribution




Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Campus Assessment Report - 1977 Baseball Pressbox


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$10,632	\$0	\$0	\$0	\$27,603	\$0	\$0	\$0	\$0	\$0	\$0	\$38,235
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$4,900	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,900
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$9,140	\$0	\$0	\$0	\$0	\$0	\$0	\$9,140
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$4,610	\$0	\$0	\$0	\$0	\$0	\$0	\$4,610
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$5,732	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$5,732
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$2,720	\$0	\$0	\$0	\$0	\$0	\$0	\$2,720
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$1,645	\$0	\$0	\$0	\$0	\$0	\$0	\$1,645
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$4,920	\$0	\$0	\$0	\$0	\$0	\$0	\$4,920
D5020 - Lighting	\$0	\$0	\$0	\$0	\$4,567	\$0	\$0	\$0	\$0	\$0	\$0	\$4,567

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$10,631.84

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$10,631.84


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2010	Exterior Walls	\$0.00	\$0.00	\$4,899.84	\$0.00	\$0.00	\$4,899.84
B3010130	Preformed Metal Roofing	\$0.00	\$0.00	\$5,732.00	\$0.00	\$0.00	\$5,732.00
	Total:	\$0.00	\$0.00	\$10,631.84	\$0.00	\$0.00	\$10,631.84

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$10,631.84

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B2010 - Exterior Walls



Location: Exterior Walls
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Refinish aluminum siding, 2nd floor
Qty: 12.80
Unit of Measure: C.S.F.
Estimate: \$4,899.84
Assessor Name: Eduardo Lopez
Date Created: 01/11/2017

Notes: The exterior wall finish is in poor condition and should be replaced.

System: B3010130 - Preformed Metal Roofing



Location: Roof
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 430.00
Unit of Measure: S.F.
Estimate: \$5,732.00
Assessor Name: Eduardo Lopez
Date Created: 01/11/2017

Notes: The roof is beyond its service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	14,000
Year Built:	1977
Last Renovation:	
Replacement Value:	\$2,353,260
Repair Cost:	\$64,372.00
Total FCI:	2.74 %
Total RSLI:	38.36 %
FCA Score:	97.26







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	14,000
Year Built:	1977	Last Renovation:	
Repair Cost:	\$64,372	Replacement Value:	\$2,353,260
FCI:	2.74 %	RSLI%:	38.36 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	60.00 %	0.00 %	\$0.00
A20 - Basement Construction	60.00 %	0.00 %	\$0.00
B10 - Superstructure	60.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	31.73 %	0.00 %	\$0.00
B30 - Roofing	13.33 %	0.00 %	\$0.00
C10 - Interior Construction	32.65 %	0.00 %	\$0.00
C30 - Interior Finishes	55.48 %	0.00 %	\$0.00
D20 - Plumbing	20.03 %	0.00 %	\$0.00
D30 - HVAC	29.15 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	110.00 %	\$64,372.00
D50 - Electrical	51.08 %	0.00 %	\$0.00
Totals:	38.36 %	2.74 %	\$64,372.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). West Elevation - Feb 13, 2017



2). Northwest Elevation - Feb 13, 2017



3). North Elevation - Feb 13, 2017



4). East Elevation - Feb 13, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

Campus Assessment Report - 1977 Technology Building

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$2.18	S.F.	14,000	100	1977	2077		60.00 %	0.00 %	60			\$30,520
A1030	Slab on Grade	\$4.08	S.F.	14,000	100	1977	2077		60.00 %	0.00 %	60			\$57,120
A2010	Basement Excavation	\$0.83	S.F.	14,000	100	1977	2077		60.00 %	0.00 %	60			\$11,620
A2020	Basement Walls	\$5.74	S.F.	14,000	100	1977	2077		60.00 %	0.00 %	60			\$80,360
B1020	Roof Construction	\$7.60	S.F.	14,000	100	1977	2077		60.00 %	0.00 %	60			\$106,400
B2010	Exterior Walls	\$8.84	S.F.	14,000	100	1977	2077		60.00 %	0.00 %	60			\$123,760
B2020	Exterior Windows	\$12.78	S.F.	14,000	30	1977	2007	2021	13.33 %	0.00 %	4			\$178,920
B2030	Exterior Doors	\$0.81	S.F.	14,000	30	1977	2007	2021	13.33 %	0.00 %	4			\$11,340
B3010130	Preformed Metal Roofing	\$9.66	S.F.	14,000	30	1977	2007	2021	13.33 %	0.00 %	4			\$135,240
C1010	Partitions	\$4.70	S.F.	14,000	75	1977	2052		46.67 %	0.00 %	35			\$65,800
C1020	Interior Doors	\$2.44	S.F.	14,000	30	1977	2007	2021	13.33 %	0.00 %	4			\$34,160
C1030	Fittings	\$1.48	S.F.	14,000	20	1977	1997	2021	20.00 %	0.00 %	4			\$20,720
C3010	Wall Finishes	\$2.56	S.F.	14,000	10	1977	1987	2021	40.00 %	0.00 %	4			\$35,840
C3020	Floor Finishes	\$10.94	S.F.	14,000	20	1977	1997	2021	20.00 %	0.00 %	4			\$153,160
C3030	Ceiling Finishes	\$10.56	S.F.	14,000	25	2016	2041		96.00 %	0.00 %	24			\$147,840
D2010	Plumbing Fixtures	\$8.83	S.F.	14,000	30	1977	2007	2021	13.33 %	0.00 %	4			\$123,620
D2020	Domestic Water Distribution	\$1.64	S.F.	14,000	30	2007	2037		66.67 %	0.00 %	20			\$22,960
D2030	Sanitary Waste	\$2.59	S.F.	14,000	30	1977	2007	2021	13.33 %	0.00 %	4			\$36,260
D3040	Distribution Systems	\$8.37	S.F.	14,000	30	2000	2030		43.33 %	0.00 %	13			\$117,180
D3050	Terminal & Package Units	\$26.64	S.F.	14,000	15	2000	2015	2021	26.67 %	0.00 %	4			\$372,960
D3060	Controls & Instrumentation	\$2.65	S.F.	14,000	20	2000	2020		15.00 %	0.00 %	3			\$37,100
D3090	Other HVAC Systems/Equip	\$1.06	S.F.	14,000	20	2000	2020		15.00 %	0.00 %	3			\$14,840
D4010	Sprinklers	\$3.63	S.F.	14,000	30	1977	2007		0.00 %	110.00 %	-10		\$55,902.00	\$50,820
D4020	Standpipes	\$0.55	S.F.	14,000	30	1977	2007		0.00 %	110.00 %	-10		\$8,470.00	\$7,700
D5010	Electrical Service/Distribution	\$1.60	S.F.	14,000	40	1977	2017	2021	10.00 %	0.00 %	4			\$22,400
D5020	Branch Wiring	\$4.55	S.F.	14,000	30	1977	2007	2021	13.33 %	0.00 %	4			\$63,700
D5020	Lighting	\$10.64	S.F.	14,000	30	2016	2046		96.67 %	0.00 %	29			\$148,960
D5030810	Security & Detection Systems	\$1.97	S.F.	14,000	15	1977	1992	2021	26.67 %	0.00 %	4			\$27,580
D5030910	Fire Alarm Systems	\$3.56	S.F.	14,000	15	1977	1992	2021	26.67 %	0.00 %	4			\$49,840
D5030920	Data Communication	\$4.61	S.F.	14,000	15	1977	1992	2021	26.67 %	0.00 %	4			\$64,540
Total									38.36 %	2.74 %			\$64,372.00	\$2,353,260

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1020 - Roof Construction



Note:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

Campus Assessment Report - 1977 Technology Building

System: B2030 - Exterior Doors




Note:

System: B3010130 - Preformed Metal Roofing



Note:


System: C1010 - Partitions



Note:


Campus Assessment Report - 1977 Technology Building

System: C1020 - Interior Doors




Note:

System: C1030 - Fittings



Note:


System: C3010 - Wall Finishes



Note:


Campus Assessment Report - 1977 Technology Building

System: C3020 - Floor Finishes





Note:

System: C3030 - Ceiling Finishes



Note:


System: D2010 - Plumbing Fixtures



Note:



Campus Assessment Report - 1977 Technology Building

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

System: D3040 - Distribution Systems



Note:

Campus Assessment Report - 1977 Technology Building

System: D3050 - Terminal & Package Units



Note:

System: D3060 - Controls & Instrumentation



Note:

System: D3090 - Other HVAC Systems/Equip



Note:

System: D4010 - Sprinklers

This system contains no images

Note: The building does not have a fire protection system and it should be installed.


System: D4020 - Standpipes

This system contains no images

Note: The building does not have a fire protection system and it should be installed.


Campus Assessment Report - 1977 Technology Building

System: D5010 - Electrical Service/Distribution





Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Campus Assessment Report - 1977 Technology Building

System: D5030810 - Security & Detection Systems




Note:

System: D5030910 - Fire Alarm Systems



Note:

System: D5030920 - Data Communication



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$64,372	\$0	\$0	\$62,432	\$1,689,586	\$0	\$0	\$0	\$0	\$0	\$0	\$1,816,390
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$221,514	\$0	\$0	\$0	\$0	\$0	\$0	\$221,514
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$14,040	\$0	\$0	\$0	\$0	\$0	\$0	\$14,040
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$210,055	\$0	\$0	\$0	\$0	\$0	\$0	\$210,055
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$42,292	\$0	\$0	\$0	\$0	\$0	\$0	\$42,292
C1030 - Fittings	\$0	\$0	\$0	\$0	\$25,653	\$0	\$0	\$0	\$0	\$0	\$0	\$25,653
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$44,372	\$0	\$0	\$0	\$0	\$0	\$0	\$44,372
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$189,621	\$0	\$0	\$0	\$0	\$0	\$0	\$189,621


Campus Assessment Report - 1977 Technology Building

C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$153,049	\$0	\$0	\$0	\$0	\$0	\$0	\$153,049
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$44,892	\$0	\$0	\$0	\$0	\$0	\$0	\$44,892
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$461,747	\$0	\$0	\$0	\$0	\$0	\$0	\$461,747
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$44,594	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$44,594
D3090 - Other HVAC Systems/Equip	\$0	\$0	\$0	\$17,838	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$17,838
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$55,902	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$55,902
D4020 - Standpipes	\$8,470	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$8,470
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$27,733	\$0	\$0	\$0	\$0	\$0	\$0	\$27,733
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$78,864	\$0	\$0	\$0	\$0	\$0	\$0	\$78,864
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$34,146	\$0	\$0	\$0	\$0	\$0	\$0	\$34,146
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$61,705	\$0	\$0	\$0	\$0	\$0	\$0	\$61,705
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$79,904	\$0	\$0	\$0	\$0	\$0	\$0	\$79,904

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$64,372.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
D4010	Sprinklers	\$0.00	\$0.00	\$55,902.00	\$0.00	\$0.00	\$55,902.00
D4020	Standpipes	\$0.00	\$0.00	\$8,470.00	\$0.00	\$0.00	\$8,470.00
	Total:	\$0.00	\$0.00	\$64,372.00	\$0.00	\$0.00	\$64,372.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout Building
Distress: Missing
Category: Building Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 14,000.00
Unit of Measure: S.F.
Estimate: \$55,902.00
Assessor Name: Eduardo Lopez
Date Created: 02/13/2017

Notes: The building does not have a fire protection system and it should be installed.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout Building
Distress: Missing
Category: Building Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 14,000.00
Unit of Measure: S.F.
Estimate: \$8,470.00
Assessor Name: Eduardo Lopez
Date Created: 02/13/2017

Notes: The building does not have a fire protection system and it should be installed.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	6,000
Year Built:	1979
Last Renovation:	
Replacement Value:	\$1,482,480
Repair Cost:	\$37,843.00
Total FCI:	2.55 %
Total RSLI:	34.22 %
FCA Score:	97.45







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	6,000
Year Built:	1979	Last Renovation:	
Repair Cost:	\$37,843	Replacement Value:	\$1,482,480
FCI:	2.55 %	RSLI%:	34.22 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	62.00 %	0.00 %	\$0.00
B10 - Superstructure	62.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	39.40 %	0.00 %	\$0.00
B30 - Roofing	0.00 %	146.00 %	\$37,843.00
C10 - Interior Construction	33.74 %	0.00 %	\$0.00
C30 - Interior Finishes	20.61 %	0.00 %	\$0.00
D20 - Plumbing	13.33 %	0.00 %	\$0.00
D30 - HVAC	23.00 %	0.00 %	\$0.00
D50 - Electrical	13.53 %	0.00 %	\$0.00
E10 - Equipment	20.00 %	0.00 %	\$0.00
Totals:	34.22 %	2.55 %	\$37,843.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). East Elevation - Jan 11, 2017



2). North Elevation - Jan 11, 2017



3). West Elevation - Jan 11, 2017



4). South Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	6,000	100	1979	2079		62.00 %	0.00 %	62			\$120,780
A1030	Slab on Grade	\$19.75	S.F.	6,000	100	1979	2079		62.00 %	0.00 %	62			\$118,500
B1020	Roof Construction	\$16.26	S.F.	6,000	100	1979	2079		62.00 %	0.00 %	62			\$97,560
B2010	Exterior Walls	\$29.79	S.F.	6,000	100	1979	2079		62.00 %	0.00 %	62			\$178,740
B2020	Exterior Windows	\$17.17	S.F.	6,000	30	1979	2009	2021	13.33 %	0.00 %	4			\$103,020
B2030	Exterior Doors	\$8.66	S.F.	6,000	30	1979	2009	2021	13.33 %	0.00 %	4			\$51,960
B3010140	Asphalt Shingles	\$4.32	S.F.	6,000	20	1979	1999		0.00 %	146.00 %	-18		\$37,843.00	\$25,920
C1010	Partitions	\$10.34	S.F.	6,000	75	1979	2054		49.33 %	0.00 %	37			\$62,040
C1020	Interior Doors	\$2.20	S.F.	6,000	30	1979	2009	2021	13.33 %	0.00 %	4			\$13,200
C1030	Fittings	\$8.47	S.F.	6,000	20	1979	1999	2021	20.00 %	0.00 %	4			\$50,820
C3010	Wall Finishes	\$5.11	S.F.	6,000	10	1979	1989	2021	40.00 %	0.00 %	4			\$30,660
C3020	Floor Finishes	\$20.82	S.F.	6,000	20	1979	1999	2021	20.00 %	0.00 %	4			\$124,920
C3030	Ceiling Finishes	\$18.76	S.F.	6,000	25	1979	2004	2021	16.00 %	0.00 %	4			\$112,560
D2010	Plumbing Fixtures	\$9.98	S.F.	6,000	30	1979	2009	2021	13.33 %	0.00 %	4			\$59,880
D2020	Domestic Water Distribution	\$0.84	S.F.	6,000	30	1979	2009	2021	13.33 %	0.00 %	4			\$5,040
D2030	Sanitary Waste	\$5.94	S.F.	6,000	30	1979	2009	2021	13.33 %	0.00 %	4			\$35,640
D3040	Distribution Systems	\$5.35	S.F.	6,000	30	1979	2009	2021	13.33 %	0.00 %	4			\$32,100
D3050	Terminal & Package Units	\$16.96	S.F.	6,000	15	1979	1994	2021	26.67 %	0.00 %	4			\$101,760
D3060	Controls & Instrumentation	\$3.48	S.F.	6,000	20	1979	1999	2021	20.00 %	0.00 %	4			\$20,880
D5010	Electrical Service/Distribution	\$3.09	S.F.	6,000	40	1979	2019		5.00 %	0.00 %	2			\$18,540
D5020	Branch Wiring	\$3.58	S.F.	6,000	30	1979	2009	2021	13.33 %	0.00 %	4			\$21,480
D5020	Lighting	\$9.58	S.F.	6,000	30	1979	2009	2021	13.33 %	0.00 %	4			\$57,480
D5030810	Security & Detection Systems	\$1.00	Ea.	6,000	15	1979	1994	2021	26.67 %	0.00 %	4			\$6,000
D5030910	Fire Alarm Systems	\$1.21	S.F.	6,000	15	1979	1994	2021	26.67 %	0.00 %	4			\$7,260
E1010	Commercial Equipment	\$3.30	S.F.	6,000	20	1979	1999	2021	20.00 %	0.00 %	4			\$19,800
E1020	Institutional Equipment	\$0.99	S.F.	6,000	20	1979	1999	2021	20.00 %	0.00 %	4			\$5,940
Total									34.22 %	2.55 %			\$37,843.00	\$1,482,480

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:




Campus Assessment Report - 1979 Fieldhouse

System: B3010140 - Asphalt Shingles



Note:

System: C1010 - Partitions



Note:


System: C1020 - Interior Doors



Note:


Campus Assessment Report - 1979 Fieldhouse

System: C1030 - Fittings



Note:

System: C3010 - Wall Finishes



Note:




System: C3020 - Floor Finishes



Note:

Campus Assessment Report - 1979 Fieldhouse

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:


Campus Assessment Report - 1979 Fieldhouse

System: D2030 - Sanitary Waste



Note:

System: D3040 - Distribution Systems



Note:

System: D3050 - Terminal & Package Units



Note:

Campus Assessment Report - 1979 Fieldhouse

System: D3060 - Controls & Instrumentation




Note:

System: D5010 - Electrical Service/Distribution



Note:


System: D5020 - Branch Wiring



Note:


Campus Assessment Report - 1979 Fieldhouse

System: D5020 - Lighting



Note:

System: D5030810 - Security & Detection Systems



Note:

System: D5030910 - Fire Alarm Systems



Note:



Campus Assessment Report - 1979 Fieldhouse

System: E1010 - Commercial Equipment



Note:

System: E1020 - Institutional Equipment



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$37,843	\$0	\$21,636	\$0	\$1,065,227	\$0	\$0	\$0	\$0	\$0	\$0	\$1,124,706
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$127,545	\$0	\$0	\$0	\$0	\$0	\$0	\$127,545
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$64,330	\$0	\$0	\$0	\$0	\$0	\$0	\$64,330
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$37,843	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$37,843
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$16,342	\$0	\$0	\$0	\$0	\$0	\$0	\$16,342
C1030 - Fittings	\$0	\$0	\$0	\$0	\$62,918	\$0	\$0	\$0	\$0	\$0	\$0	\$62,918
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$37,959	\$0	\$0	\$0	\$0	\$0	\$0	\$37,959
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$154,658	\$0	\$0	\$0	\$0	\$0	\$0	\$154,658
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$139,356	\$0	\$0	\$0	\$0	\$0	\$0	\$139,356
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1979 Fieldhouse

D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$74,135	\$0	\$0	\$0	\$0	\$0	\$0	\$74,135
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$6,240	\$0	\$0	\$0	\$0	\$0	\$0	\$6,240
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$44,124	\$0	\$0	\$0	\$0	\$0	\$0	\$44,124
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$39,742	\$0	\$0	\$0	\$0	\$0	\$0	\$39,742
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$125,985	\$0	\$0	\$0	\$0	\$0	\$0	\$125,985
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$25,851	\$0	\$0	\$0	\$0	\$0	\$0	\$25,851
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$21,636	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$21,636
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$26,594	\$0	\$0	\$0	\$0	\$0	\$0	\$26,594
D5020 - Lighting	\$0	\$0	\$0	\$0	\$71,164	\$0	\$0	\$0	\$0	\$0	\$0	\$71,164
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$7,428	\$0	\$0	\$0	\$0	\$0	\$0	\$7,428
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$8,988	\$0	\$0	\$0	\$0	\$0	\$0	\$8,988
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1010 - Commercial Equipment	\$0	\$0	\$0	\$0	\$24,514	\$0	\$0	\$0	\$0	\$0	\$0	\$24,514
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$7,354	\$0	\$0	\$0	\$0	\$0	\$0	\$7,354

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$37,843.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B3010140	Asphalt Shingles	\$0.00	\$0.00	\$37,843.00	\$0.00	\$0.00	\$37,843.00
	Total:	\$0.00	\$0.00	\$37,843.00	\$0.00	\$0.00	\$37,843.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B3010140 - Asphalt Shingles



Location: Roof
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 6,000.00
Unit of Measure: S.F.
Estimate: \$37,843.00
Assessor Name: Eduardo Lopez
Date Created: 01/11/2017

Notes: The roof is beyond its service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	28,500
Year Built:	1991
Last Renovation:	
Replacement Value:	\$5,307,555
Repair Cost:	\$380,219.00
Total FCI:	7.16 %
Total RSLI:	41.97 %
FCA Score:	92.84







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	28,500
Year Built:	1991	Last Renovation:	
Repair Cost:	\$380,219	Replacement Value:	\$5,307,555
FCI:	7.16 %	RSLI%:	41.97 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	74.00 %	0.00 %	\$0.00
A20 - Basement Construction	74.00 %	0.00 %	\$0.00
B10 - Superstructure	74.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	37.27 %	0.00 %	\$0.00
B30 - Roofing	0.00 %	150.00 %	\$298,395.00
C10 - Interior Construction	39.07 %	31.14 %	\$81,824.00
C30 - Interior Finishes	55.46 %	0.00 %	\$0.00
D20 - Plumbing	13.58 %	0.00 %	\$0.00
D30 - HVAC	43.05 %	0.00 %	\$0.00
D40 - Fire Protection	13.33 %	0.00 %	\$0.00
D50 - Electrical	52.56 %	0.00 %	\$0.00
E10 - Equipment	20.00 %	0.00 %	\$0.00
E20 - Furnishings	20.00 %	0.00 %	\$0.00
Totals:	41.97 %	7.16 %	\$380,219.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). Southwest Elevation - Jan 11, 2017



2). South Elevation - Jan 11, 2017



3). East Elevation - Jan 11, 2017



4). West Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

Campus Assessment Report - 1991 Addition

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$2.32	S.F.	28,500	100	1991	2091		74.00 %	0.00 %	74			\$66,120
A1030	Slab on Grade	\$4.36	S.F.	28,500	100	1991	2091		74.00 %	0.00 %	74			\$124,260
A2010	Basement Excavation	\$0.88	S.F.	28,500	100	1991	2091		74.00 %	0.00 %	74			\$25,080
A2020	Basement Walls	\$6.15	S.F.	28,500	100	1991	2091		74.00 %	0.00 %	74			\$175,275
B1020	Roof Construction	\$8.14	S.F.	28,500	100	1991	2091		74.00 %	0.00 %	74			\$231,990
B2010	Exterior Walls	\$9.48	S.F.	28,500	100	1991	2091		74.00 %	0.00 %	74			\$270,180
B2020	Exterior Windows	\$13.69	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$390,165
B2030	Exterior Doors	\$0.86	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$24,510
B3010120	Single Ply Membrane	\$6.98	S.F.	28,500	20	1991	2011		0.00 %	150.00 %	-6		\$298,395.00	\$198,930
C1010	Partitions	\$5.03	S.F.	28,500	75	1991	2066		65.33 %	0.00 %	49			\$143,355
C1020	Interior Doors	\$2.61	S.F.	28,500	30	1991	2021	2016	0.00 %	110.00 %	-1		\$81,824.00	\$74,385
C1030	Fittings	\$1.58	S.F.	28,500	20	1991	2011	2021	20.00 %	0.00 %	4			\$45,030
C3010	Wall Finishes	\$2.75	S.F.	28,500	10	1991	2001	2021	40.00 %	0.00 %	4			\$78,375
C3020	Floor Finishes	\$11.72	S.F.	28,500	20	1991	2011	2021	20.00 %	0.00 %	4			\$334,020
C3030	Ceiling Finishes	\$11.30	S.F.	28,500	25	2016	2041		96.00 %	0.00 %	24			\$322,050
D2010	Plumbing Fixtures	\$9.46	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$269,610
D2020	Domestic Water Distribution	\$1.76	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$50,160
D2030	Sanitary Waste	\$2.77	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$78,945
D2090	Other Plumbing Systems -Nat Gas	\$0.16	S.F.	28,500	40	1991	2031		35.00 %	0.00 %	14			\$4,560
D3020	Heat Generating Systems	\$7.42	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$211,470
D3030	Cooling Generating Systems	\$7.68	S.F.	28,500	25	2012	2037		80.00 %	0.00 %	20			\$218,880
D3040	Distribution Systems	\$8.96	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$255,360
D3050	Terminal & Package Units	\$4.75	S.F.	28,500	15	2012	2027		66.67 %	0.00 %	10			\$135,375
D3060	Controls & Instrumentation	\$2.84	S.F.	28,500	20	2012	2032		75.00 %	0.00 %	15			\$80,940
D4010	Sprinklers	\$3.89	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$110,865
D4020	Standpipes	\$0.59	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$16,815
D5010	Electrical Service/Distribution	\$1.70	S.F.	28,500	40	1991	2031		35.00 %	0.00 %	14			\$48,450
D5020	Branch Wiring	\$4.87	S.F.	28,500	30	1991	2021		13.33 %	0.00 %	4			\$138,795
D5020	Lighting	\$11.38	S.F.	28,500	30	2016	2046		96.67 %	0.00 %	29			\$324,330
D5030810	Security & Detection Systems	\$2.10	S.F.	28,500	15	1991	2006	2021	26.67 %	0.00 %	4			\$59,850
D5030910	Fire Alarm Systems	\$3.83	S.F.	28,500	15	1991	2006	2021	26.67 %	0.00 %	4			\$109,155
D5030920	Data Communication	\$4.92	S.F.	28,500	15	1991	2006	2021	26.67 %	0.00 %	4			\$140,220
E1020	Institutional Equipment	\$13.97	S.F.	28,500	20	1991	2011	2021	20.00 %	0.00 %	4			\$398,145
E2010	Fixed Furnishings	\$5.33	S.F.	28,500	20	1991	2011	2021	20.00 %	0.00 %	4			\$151,905
Total									41.97 %	7.16 %			\$380,219.00	\$5,307,555

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1991 Addition

System: B3010120 - Single Ply Membrane




Note: The roof is beyond its service life and should be replaced.

System: C1010 - Partitions



Note:


System: C1020 - Interior Doors



Note: The doors are in poor condition and should be replaced.

Campus Assessment Report - 1991 Addition

System: C1030 - Fittings



Note:

System: C3010 - Wall Finishes



Note:



System: C3020 - Floor Finishes



Note:


Campus Assessment Report - 1991 Addition

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:

Campus Assessment Report - 1991 Addition

System: D2030 - Sanitary Waste



Note:

System: D2090 - Other Plumbing Systems -Nat Gas



Note:

System: D3020 - Heat Generating Systems



Note:

Campus Assessment Report - 1991 Addition

System: D3030 - Cooling Generating Systems



Note:

System: D3040 - Distribution Systems



Note:

System: D3050 - Terminal & Package Units



Note:

Campus Assessment Report - 1991 Addition

System: D3060 - Controls & Instrumentation



Note:

System: D4010 - Sprinklers

This system contains no images

Note: The building does not have a fire protection system and it should be installed.

System: D4020 - Standpipes

This system contains no images

Note: The building does not have a fire protection system and it should be installed.

System: D5010 - Electrical Service/Distribution



Note:

System: D5020 - Branch Wiring



Note:

Campus Assessment Report - 1991 Addition

System: D5020 - Lighting




Note:

System: D5030810 - Security & Detection Systems



Note:

System: D5030910 - Fire Alarm Systems



Note:

Campus Assessment Report - 1991 Addition

System: D5030920 - Data Communication



Note:

System: E1020 - Institutional Equipment



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$380,219	\$0	\$0	\$0	\$3,545,059	\$0	\$0	\$0	\$0	\$0	\$200,127	\$4,125,405
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$483,048	\$0	\$0	\$0	\$0	\$0	\$0	\$483,048
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$30,345	\$0	\$0	\$0	\$0	\$0	\$0	\$30,345
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$298,395	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$298,395
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$81,824	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$81,824
C1030 - Fittings	\$0	\$0	\$0	\$0	\$55,750	\$0	\$0	\$0	\$0	\$0	\$0	\$55,750
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$97,033	\$0	\$0	\$0	\$0	\$0	\$0	\$97,033
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$413,537	\$0	\$0	\$0	\$0	\$0	\$0	\$413,537


Campus Assessment Report - 1991 Addition

C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$333,793	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$333,793
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$62,101	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$62,101
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$97,739	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$97,739
D2090 - Other Plumbing Systems -Nat Gas	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$261,812	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$261,812
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$316,151	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$316,151
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$200,127	\$0	\$200,127
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$0	\$0	\$0	\$0	\$137,258	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$137,258
D4020 - Standpipes	\$0	\$0	\$0	\$0	\$20,819	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$20,819
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$171,837	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$171,837
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$74,098	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$74,098
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$135,141	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$135,141
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$173,601	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$173,601
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$492,928	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$492,928
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$188,068	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$188,068

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$380,219.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$380,219.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B3010120	Single Ply Membrane	\$0.00	\$0.00	\$298,395.00	\$0.00	\$0.00	\$298,395.00
C1020	Interior Doors	\$0.00	\$0.00	\$81,824.00	\$0.00	\$0.00	\$81,824.00
	Total:	\$0.00	\$0.00	\$380,219.00	\$0.00	\$0.00	\$380,219.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):


System: B3010120 - Single Ply Membrane



Location: Roof
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 28,500.00
Unit of Measure: S.F.
Estimate: \$298,395.00
Assessor Name: Terence Davis
Date Created: 01/05/2017

Notes: The roof is beyond its service life and should be replaced.

System: C1020 - Interior Doors



Location: Throughout Building
Distress: Damaged
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 28,500.00
Unit of Measure: S.F.
Estimate: \$81,824.00
Assessor Name: Terence Davis
Date Created: 01/06/2017

Notes: The doors are in poor condition and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	1,200
Year Built:	1999
Last Renovation:	
Replacement Value:	\$176,604
Repair Cost:	\$32,155.00
Total FCI:	18.21 %
Total RSLI:	42.57 %
FCA Score:	81.79







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	1,200
Year Built:	1999	Last Renovation:	
Repair Cost:	\$32,155	Replacement Value:	\$176,604
FCI:	18.21 %	RSLI%:	42.57 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	82.00 %	0.00 %	\$0.00
B10 - Superstructure	82.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	69.81 %	0.00 %	\$0.00
B30 - Roofing	10.00 %	0.00 %	\$0.00
C10 - Interior Construction	45.62 %	0.00 %	\$0.00
C30 - Interior Finishes	19.01 %	47.14 %	\$16,817.00
D20 - Plumbing	40.00 %	0.00 %	\$0.00
D30 - HVAC	12.61 %	75.32 %	\$15,338.00
D50 - Electrical	42.90 %	0.00 %	\$0.00
E20 - Furnishings	10.00 %	0.00 %	\$0.00
Totals:	42.57 %	18.21 %	\$32,155.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). South Elevation - Jan 11, 2017



2). East Elevation - Jan 11, 2017



3). Northeast Elevation - Jan 11, 2017



4). West Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$6.93	S.F.	1,200	100	1999	2099		82.00 %	0.00 %	82			\$8,316
A1030	Slab on Grade	\$7.37	S.F.	1,200	100	1999	2099		82.00 %	0.00 %	82			\$8,844
B1020	Roof Construction	\$5.98	S.F.	1,200	100	1999	2099		82.00 %	0.00 %	82			\$7,176
B2010	Exterior Walls	\$18.04	S.F.	1,200	100	1999	2099		82.00 %	0.00 %	82			\$21,648
B2020	Exterior Windows	\$6.47	S.F.	1,200	30	1999	2029		40.00 %	0.00 %	12			\$7,764
B2030	Exterior Doors	\$0.91	S.F.	1,200	30	1999	2029		40.00 %	0.00 %	12			\$1,092
B3010140	Asphalt Shingles	\$4.32	S.F.	1,200	20	1999	2019		10.00 %	0.00 %	2			\$5,184
C1010	Partitions	\$10.34	S.F.	1,200	75	1999	2074		76.00 %	0.00 %	57			\$12,408
C1020	Interior Doors	\$2.20	S.F.	1,200	30	1999	2029		40.00 %	0.00 %	12			\$2,640
C1030	Fittings	\$8.47	S.F.	1,200	20	1999	2019		10.00 %	0.00 %	2			\$10,164
C3010	Wall Finishes	\$7.46	S.F.	1,200	10	1999	2009	2021	40.00 %	0.00 %	4			\$8,952
C3020	Floor Finishes	\$12.74	S.F.	1,200	20	1999	2019	2016	0.00 %	110.00 %	-1		\$16,817.00	\$15,288
C3030	Ceiling Finishes	\$9.53	S.F.	1,200	25	1999	2024		28.00 %	0.00 %	7			\$11,436
D2010	Plumbing Fixtures	\$9.98	S.F.	1,200	30	1999	2029		40.00 %	0.00 %	12			\$11,976
D2020	Domestic Water Distribution	\$0.84	S.F.	1,200	30	1999	2029		40.00 %	0.00 %	12			\$1,008
D2030	Sanitary Waste	\$5.94	S.F.	1,200	30	1999	2029		40.00 %	0.00 %	12			\$7,128
D3040	Distribution Systems	\$5.35	S.F.	1,200	30	1999	2029		40.00 %	0.00 %	12			\$6,420
D3050	Terminal & Package Units	\$11.62	S.F.	1,200	15	1999	2014		0.00 %	110.00 %	-3		\$15,338.00	\$13,944
D5010	Electrical Service/Distribution	\$1.47	S.F.	1,200	40	1999	2039		55.00 %	0.00 %	22			\$1,764
D5020	Branch Wiring	\$2.55	S.F.	1,200	30	1999	2029		40.00 %	0.00 %	12			\$3,060
D5020	Lighting	\$3.58	S.F.	1,200	30	1999	2029		40.00 %	0.00 %	12			\$4,296
E2010	Fixed Furnishings	\$5.08	S.F.	1,200	20	1999	2019		10.00 %	0.00 %	2			\$6,096
Total									42.57 %	18.21 %			\$32,155.00	\$176,604

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:



Campus Assessment Report - 1999 Visitor Concession Stand

System: B3010140 - Asphalt Shingles



Note:

System: C1010 - Partitions



Note:

System: C1020 - Interior Doors



Note:


Campus Assessment Report - 1999 Visitor Concession Stand

System: C1030 - Fittings



Note:

System: C3010 - Wall Finishes



Note:


System: C3020 - Floor Finishes



Note:



Campus Assessment Report - 1999 Visitor Concession Stand

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:

Campus Assessment Report - 1999 Visitor Concession Stand

System: D2030 - Sanitary Waste



Note:

System: D3040 - Distribution Systems



Note:

System: D3050 - Terminal & Package Units



Note:


Campus Assessment Report - 1999 Visitor Concession Stand

System: D5010 - Electrical Service/Distribution




Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Campus Assessment Report - 1999 Visitor Concession Stand

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$32,155	\$0	\$27,005	\$0	\$11,083	\$0	\$0	\$15,472	\$0	\$0	\$0	\$85,715
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$8,030	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$8,030
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$11,861	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$11,861
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$11,083	\$0	\$0	\$0	\$0	\$0	\$0	\$11,083
C3020 - Floor Finishes	\$16,817	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$16,817
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$15,472	\$0	\$0	\$0	\$15,472
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1999 Visitor Concession Stand

D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$15,338	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$15,338
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$7,114	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$7,114

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$32,155.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$32,155.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
C3020	Floor Finishes	\$0.00	\$0.00	\$16,817.00	\$0.00	\$0.00	\$16,817.00
D3050	Terminal & Package Units	\$0.00	\$0.00	\$15,338.00	\$0.00	\$0.00	\$15,338.00
	Total:	\$0.00	\$0.00	\$32,155.00	\$0.00	\$0.00	\$32,155.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: C3020 - Floor Finishes



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 1,200.00
Unit of Measure: S.F.
Estimate: \$16,817.00
Assessor Name: Eduardo Lopez
Date Created: 01/11/2017

Notes: The floor finishes are beyond their service life and should be replaced.

System: D3050 - Terminal & Package Units



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 1,200.00
Unit of Measure: S.F.
Estimate: \$15,338.00
Assessor Name: Eduardo Lopez
Date Created: 01/11/2017

Notes: The terminal and package units are beyond their service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	5,700
Year Built:	2005
Last Renovation:	
Replacement Value:	\$1,370,337
Repair Cost:	\$10,546.80
Total FCI:	0.77 %
Total RSLI:	63.05 %
FCA Score:	99.23







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	5,700
Year Built:	2005	Last Renovation:	
Repair Cost:	\$10,547	Replacement Value:	\$1,370,337
FCI:	0.77 %	RSLI%:	63.05 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	88.00 %	0.00 %	\$0.00
B10 - Superstructure	88.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	81.69 %	0.00 %	\$0.00
B30 - Roofing	60.00 %	0.00 %	\$0.00
C10 - Interior Construction	63.75 %	0.00 %	\$0.00
C30 - Interior Finishes	45.04 %	4.14 %	\$10,546.80
D20 - Plumbing	60.00 %	0.00 %	\$0.00
D30 - HVAC	31.00 %	0.00 %	\$0.00
D50 - Electrical	49.82 %	0.00 %	\$0.00
E20 - Furnishings	40.00 %	0.00 %	\$0.00
Totals:	63.05 %	0.77 %	\$10,546.80

Photo Album

The photo album consists of the various cardinal directions of the building..

1). East Elevation - Jan 11, 2017



2). North Elevation - Jan 11, 2017



3). West Elevation - Jan 11, 2017



4). South Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	5,700	100	2005	2105		88.00 %	0.00 %	88			\$114,741
A1030	Slab on Grade	\$19.75	S.F.	5,700	100	2005	2105		88.00 %	0.00 %	88			\$112,575
B1020	Roof Construction	\$16.26	S.F.	5,700	100	2005	2105		88.00 %	0.00 %	88			\$92,682
B2010	Exterior Walls	\$29.79	S.F.	5,700	100	2005	2105		88.00 %	0.00 %	88			\$169,803
B2030	Exterior Doors	\$8.66	S.F.	5,700	30	2005	2035		60.00 %	0.00 %	18			\$49,362
B3010130	Preformed Metal Roofing	\$9.66	S.F.	5,700	30	2005	2035		60.00 %	0.00 %	18			\$55,062
C1010	Partitions	\$10.34	S.F.	5,700	75	2005	2080		84.00 %	0.00 %	63			\$58,938
C1020	Interior Doors	\$2.20	S.F.	5,700	30	2005	2035		60.00 %	0.00 %	18			\$12,540
C1030	Fittings	\$8.47	S.F.	5,700	20	2005	2025		40.00 %	0.00 %	8			\$48,279
C3010	Wall Finishes	\$5.11	S.F.	5,700	10	2005	2015	2021	40.00 %	0.00 %	4			\$29,127
C3020	Floor Finishes	\$20.82	S.F.	5,700	20	2005	2025		40.00 %	8.89 %	8		\$10,546.80	\$118,674
C3030	Ceiling Finishes	\$18.76	S.F.	5,700	25	2005	2030		52.00 %	0.00 %	13			\$106,932
D2010	Plumbing Fixtures	\$9.98	S.F.	5,700	30	2005	2035		60.00 %	0.00 %	18			\$56,886
D2020	Domestic Water Distribution	\$0.84	S.F.	5,700	30	2005	2035		60.00 %	0.00 %	18			\$4,788
D2030	Sanitary Waste	\$5.94	S.F.	5,700	30	2005	2035		60.00 %	0.00 %	18			\$33,858
D3040	Distribution Systems	\$5.35	S.F.	5,700	30	2005	2035		60.00 %	0.00 %	18			\$30,495
D3050	Terminal & Package Units	\$16.96	S.F.	5,700	15	2005	2020		20.00 %	0.00 %	3			\$96,672
D3060	Controls & Instrumentation	\$3.48	S.F.	5,700	20	2005	2025		40.00 %	0.00 %	8			\$19,836
D5010	Electrical Service/Distribution	\$3.09	S.F.	5,700	40	2005	2045		70.00 %	0.00 %	28			\$17,613
D5020	Branch Wiring	\$3.58	S.F.	5,700	30	2005	2035		60.00 %	0.00 %	18			\$20,406
D5020	Lighting	\$9.58	S.F.	5,700	30	2005	2035		60.00 %	0.00 %	18			\$54,606
D5030910	Security & Detection Systems	\$1.97	S.F.	5,700	15	2005	2020		20.00 %	0.00 %	3			\$11,229
D5030920	Data Communication	\$4.61	S.F.	5,700	15	2005	2020		20.00 %	0.00 %	3			\$26,277
E2010	Fixed Furnishings	\$5.08	S.F.	5,700	20	2005	2025		40.00 %	0.00 %	8			\$28,956
Total									63.05 %	0.77 %			\$10,546.80	\$1,370,337

System Notes


The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2030 - Exterior Doors



Note:


System: B3010130 - Preformed Metal Roofing



Note:

Campus Assessment Report - 2005 Weight Room

System: C1010 - Partitions



Note:

System: C1020 - Interior Doors



Note:



System: C1030 - Fittings



Note:

Campus Assessment Report - 2005 Weight Room

System: C3010 - Wall Finishes




Note:

System: C3020 - Floor Finishes



Note: The epoxy in the boys restroom is in poor condition and should be replaced.




System: C3030 - Ceiling Finishes



Note: The acoustical ceiling tiles are beyond their service life and should be replaced.


Campus Assessment Report - 2005 Weight Room

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

Campus Assessment Report - 2005 Weight Room

System: D3040 - Distribution Systems



Note:

System: D3050 - Terminal & Package Units



Note:

System: D3060 - Controls & Instrumentation



Note:

Campus Assessment Report - 2005 Weight Room

System: D5010 - Electrical Service/Distribution





Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Campus Assessment Report - 2005 Weight Room

System: D5030910 - Security & Detection Systems



Note:

System: D5030920 - Data Communication



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$10,547	\$0	\$0	\$161,282	\$36,061	\$0	\$0	\$0	\$300,630	\$0	\$0	\$508,520
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$67,274	\$0	\$0	\$67,274
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$36,061	\$0	\$0	\$0	\$0	\$0	\$0	\$36,061
C3020 - Floor Finishes	\$10,547	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$165,365	\$0	\$0	\$175,912
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 2005 Weight Room

D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$116,199	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$116,199
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$27,641	\$0	\$0	\$27,641
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Security & Detection Systems	\$0	\$0	\$0	\$13,497	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$13,497
D5030920 - Data Communication	\$0	\$0	\$0	\$31,585	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$31,585
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$40,349	\$0	\$0	\$40,349

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$10,546.80


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
C3020	Floor Finishes	\$0.00	\$0.00	\$10,546.80	\$0.00	\$0.00	\$10,546.80
	Total:	\$0.00	\$0.00	\$10,546.80	\$0.00	\$0.00	\$10,546.80

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: C3020 - Floor Finishes



Location: Mens Restroom
Distress: Damaged
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Replace epoxy flooring
Qty: 5.00
Unit of Measure: C.S.F.
Estimate: \$10,546.80
Assessor Name: Eduardo Lopez
Date Created: 01/11/2017

Notes: The epoxy flooring in the restroom area is in poor condition and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	1,620
Year Built:	2008
Last Renovation:	
Replacement Value:	\$201,869
Repair Cost:	\$1,716.53
Total FCI:	0.85 %
Total RSLI:	84.58 %
FCA Score:	99.15







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	1,620
Year Built:	2008	Last Renovation:	
Repair Cost:	\$1,717	Replacement Value:	\$201,869
FCI:	0.85 %	RSLI%:	84.58 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	91.00 %	0.00 %	\$0.00
B10 - Superstructure	91.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	86.27 %	2.76 %	\$1,716.53
B30 - Roofing	55.00 %	0.00 %	\$0.00
C10 - Interior Construction	76.18 %	0.00 %	\$0.00
D50 - Electrical	70.00 %	0.00 %	\$0.00
Totals:	84.58 %	0.85 %	\$1,716.53

Photo Album

The photo album consists of the various cardinal directions of the building..

1). East Elevation - Jan 11, 2017



2). Northeast Elevation - Jan 11, 2017



3). West Elevation - Jan 11, 2017



4). South Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	1,620	100	2008	2108		91.00 %	0.00 %	91			\$32,611
A1030	Slab on Grade	\$19.75	S.F.	1,620	100	2008	2108		91.00 %	0.00 %	91			\$31,995
B1020	Roof Construction	\$16.26	S.F.	1,620	100	2008	2108		91.00 %	0.00 %	91			\$26,341
B2010	Exterior Walls	\$29.79	S.F.	1,620	100	2008	2108		91.00 %	3.56 %	91		\$1,716.53	\$48,260
B2030	Exterior Doors	\$8.66	S.F.	1,620	30	2008	2038		70.00 %	0.00 %	21			\$14,029
B3010140	Asphalt Shingles	\$4.32	S.F.	1,620	20	2008	2028		55.00 %	0.00 %	11			\$6,998
C1010	Partitions	\$10.34	S.F.	1,620	40	2008	2048		77.50 %	0.00 %	31			\$16,751
C1020	Interior Doors	\$2.20	S.F.	1,620	30	2008	2038		70.00 %	0.00 %	21			\$3,564
D5020	Branch Wiring	\$3.58	S.F.	1,620	30	2008	2038		70.00 %	0.00 %	21			\$5,800
D5020	Lighting	\$9.58	S.F.	1,620	30	2008	2038		70.00 %	0.00 %	21			\$15,520
Total									84.58 %	0.85 %			\$1,716.53	\$201,869

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1020 - Roof Construction



Note:

System: B2010 - Exterior Walls



Note:

System: B2030 - Exterior Doors



Note:



Campus Assessment Report - 2008 Storage Building

System: B3010140 - Asphalt Shingles



Note:

System: C1010 - Partitions



Note:

System: C1020 - Interior Doors



Note:

Campus Assessment Report - 2008 Storage Building

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$1,717	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,717
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$1,717	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,717
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

** Indicates non-renewable system*


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$1,716.53


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2010	Exterior Walls	\$1,716.53	\$0.00	\$0.00	\$0.00	\$0.00	\$1,716.53
	Total:	\$1,716.53	\$0.00	\$0.00	\$0.00	\$0.00	\$1,716.53

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$1,716.53

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Currently Critical (Immediate):

System: B2010 - Exterior Walls



Location: Exterior Walls
Distress: Damaged
Category: Deferred Maintenance / Building Code Compliance
Priority: 1 - Currently Critical (Immediate)
Correction: Replace hardboard panels, 1st floor
Qty: 2.00
Unit of Measure: C.S.F.
Estimate: \$1,716.53
Assessor Name: Eduardo Lopez
Date Created: 01/12/2017

Notes: The exterior siding is falling off and it is in poor condition and it should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	435
Year Built:	2009
Last Renovation:	
Replacement Value:	\$96,169
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	75.92 %
FCA Score:	100.00



Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.


Dashboard Summary

Function:	HS -High School	Gross Area:	435
Year Built:	2009	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$96,169
FCI:	0.00 %	RSLI%:	75.92 %

No data found for this asset

No data found for this asset

No data found for this asset



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	92.00 %	0.00 %	\$0.00
B10 - Superstructure	92.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	85.71 %	0.00 %	\$0.00
B30 - Roofing	60.00 %	0.00 %	\$0.00
C10 - Interior Construction	76.13 %	0.00 %	\$0.00
C30 - Interior Finishes	58.78 %	0.00 %	\$0.00
D20 - Plumbing	73.33 %	0.00 %	\$0.00
D30 - HVAC	49.96 %	0.00 %	\$0.00
D50 - Electrical	74.60 %	0.00 %	\$0.00
E20 - Furnishings	60.00 %	0.00 %	\$0.00
Totals:	75.92 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). South Elevation - Jan 12, 2017



2). East Elevation - Jan 12, 2017



3). North Elevation - Jan 12, 2017



4). West Elevation - Jan 12, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

Campus Assessment Report - 2009 Soccer Storage Building

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	435	100	2009	2109		92.00 %	0.00 %	92			\$8,757
A1030	Slab on Grade	\$19.75	S.F.	435	100	2009	2109		92.00 %	0.00 %	92			\$8,591
B1020	Roof Construction	\$16.26	S.F.	435	100	2009	2109		92.00 %	0.00 %	92			\$7,073
B2010	Exterior Walls	\$29.79	S.F.	435	100	2009	2109		92.00 %	0.00 %	92			\$12,959
B2020	Exterior Windows	\$6.47	S.F.	435	30	2009	2039		73.33 %	0.00 %	22			\$2,814
B2030	Exterior Doors	\$8.66	S.F.	435	30	2009	2039		73.33 %	0.00 %	22			\$3,767
B3010140	Asphalt Shingles	\$4.32	S.F.	435	20	2009	2029		60.00 %	0.00 %	12			\$1,879
C1010	Partitions	\$10.34	S.F.	435	75	2009	2084		89.33 %	0.00 %	67			\$4,498
C1030	Fittings	\$8.47	S.F.	435	20	2009	2029		60.00 %	0.00 %	12			\$3,684
C3010	Wall Finishes	\$5.11	S.F.	435	10	2009	2019		20.00 %	0.00 %	2			\$2,223
C3020	Floor Finishes	\$20.82	S.F.	435	20	2009	2029		60.00 %	0.00 %	12			\$9,057
C3030	Ceiling Finishes	\$18.76	S.F.	435	25	2009	2034		68.00 %	0.00 %	17			\$8,161
D2010	Plumbing Fixtures	\$9.98	S.F.	435	30	2009	2039		73.33 %	0.00 %	22			\$4,341
D2020	Domestic Water Distribution	\$0.84	S.F.	435	30	2009	2039		73.33 %	0.00 %	22			\$365
D2030	Sanitary Waste	\$5.94	S.F.	435	30	2009	2039		73.33 %	0.00 %	22			\$2,584
D3050	Terminal & Package Units	\$10.63	S.F.	435	15	2009	2024		46.67 %	0.00 %	7			\$4,624
D3060	Controls & Instrumentation	\$3.48	S.F.	435	20	2009	2029		60.00 %	0.00 %	12			\$1,514
D5010	Electrical Service/Distribution	\$3.09	S.F.	435	40	2009	2049		80.00 %	0.00 %	32			\$1,344
D5020	Branch Wiring	\$3.58	S.F.	435	30	2009	2039		73.33 %	0.00 %	22			\$1,557
D5020	Lighting	\$9.58	S.F.	435	30	2009	2039		73.33 %	0.00 %	22			\$4,167
E2010	Fixed Furnishings	\$5.08	S.F.	435	20	2009	2029		60.00 %	0.00 %	12			\$2,210
Total									75.92 %					\$96,169

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:


Campus Assessment Report - 2009 Soccer Storage Building

System: B3010140 - Asphalt Shingles



Note:

System: C1010 - Partitions



Note:



System: C1030 - Fittings



Note:

Campus Assessment Report - 2009 Soccer Storage Building

System: C3010 - Wall Finishes



Note:

System: C3020 - Floor Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

Campus Assessment Report - 2009 Soccer Storage Building

System: D2010 - Plumbing Fixtures




Note:

System: D2020 - Domestic Water Distribution



Note:



System: D2030 - Sanitary Waste



Note:

Campus Assessment Report - 2009 Soccer Storage Building

System: D3050 - Terminal & Package Units



Note:

System: D3060 - Controls & Instrumentation



Note:

System: D5010 - Electrical Service/Distribution



Note:

Campus Assessment Report - 2009 Soccer Storage Building

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$2,594	\$0	\$0	\$0	\$0	\$6,255	\$0	\$0	\$0	\$8,849
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$2,594	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,594
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 2009 Soccer Storage Building

D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$6,255	\$0	\$0	\$0	\$6,255
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	490
Year Built:	2009
Last Renovation:	
Replacement Value:	\$85,775
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	80.99 %
FCA Score:	100.00



Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary


Function:	HS -High School	Gross Area:	490
Year Built:	2009	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$85,775
FCI:	0.00 %	RSLI%:	80.99 %

No data found for this asset

No data found for this asset

No data found for this asset

10 Year Investment Forecast



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	92.00 %	0.00 %	\$0.00
B10 - Superstructure	92.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	83.33 %	0.00 %	\$0.00
B30 - Roofing	60.00 %	0.00 %	\$0.00
C20 - Stairs	92.00 %	0.00 %	\$0.00
C30 - Interior Finishes	51.23 %	0.00 %	\$0.00
D50 - Electrical	74.32 %	0.00 %	\$0.00
E20 - Furnishings	60.00 %	0.00 %	\$0.00
Totals:	80.99 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). South Elevation - Jan 12, 2017



2). West Elevation - Jan 12, 2017



3). North Elevation - Jan 12, 2017



4). East Elevation - Jan 12, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	490	100	2009	2109		92.00 %	0.00 %	92			\$9,864
A1030	Slab on Grade	\$19.75	S.F.	490	100	2009	2109		92.00 %	0.00 %	92			\$9,678
B1010	Floor Construction	\$11.44	S.F.	490	100	2009	2109		92.00 %	0.00 %	92			\$5,606
B1020	Roof Construction	\$16.26	S.F.	490	100	2009	2109		92.00 %	0.00 %	92			\$7,967
B2010	Exterior Walls	\$29.79	S.F.	490	100	2009	2109		92.00 %	0.00 %	92			\$14,597
B2020	Exterior Windows	\$17.17	S.F.	490	30	2009	2039		73.33 %	0.00 %	22			\$8,413
B2030	Exterior Doors	\$8.66	S.F.	490	30	2009	2039		73.33 %	0.00 %	22			\$4,243
B3010140	Asphalt Shingles	\$4.32	S.F.	490	20	2009	2029		60.00 %	0.00 %	12			\$2,117
C2010	Stair Construction	\$1.32	S.F.	490	100	2009	2109		92.00 %	0.00 %	92			\$647
C3010	Wall Finishes	\$5.11	S.F.	490	10	2009	2019		20.00 %	0.00 %	2			\$2,504
C3030	Ceiling Finishes	\$9.52	S.F.	490	25	2009	2034		68.00 %	0.00 %	17			\$4,665
D5010	Electrical Service/Distribution	\$3.09	S.F.	490	40	2009	2049		80.00 %	0.00 %	32			\$1,514
D5020	Branch Wiring	\$9.24	S.F.	490	30	2009	2039		73.33 %	0.00 %	22			\$4,528
D5020	Lighting	\$8.58	S.F.	490	30	2009	2039		73.33 %	0.00 %	22			\$4,204
E2010	Fixed Furnishings	\$10.67	S.F.	490	20	2009	2029		60.00 %	0.00 %	12			\$5,228
Total									80.99 %					\$85,775

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1010 - Floor Construction



Note:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

Campus Assessment Report - 2009 Softball Pressbox

System: B2030 - Exterior Doors





Note:

System: B3010140 - Asphalt Shingles



Note:



System: C2010 - Stair Construction



Note:

Campus Assessment Report - 2009 Softball Pressbox

System: C3010 - Wall Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

System: D5010 - Electrical Service/Distribution



Note:

Campus Assessment Report - 2009 Softball Pressbox

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%


Campus Assessment Report - 2009 Softball Pressbox

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$2,922	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,922
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$2,922	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,922
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	1,400
Year Built:	2012
Last Renovation:	
Replacement Value:	\$238,070
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	87.22 %
FCA Score:	100.00



Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.


Dashboard Summary

Function:	HS -High School	Gross Area:	1,400
Year Built:	2012	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$238,070
FCI:	0.00 %	RSLI%:	87.22 %

No data found for this asset

No data found for this asset

No data found for this asset



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	95.00 %	0.00 %	\$0.00
B10 - Superstructure	95.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	89.68 %	0.00 %	\$0.00
B30 - Roofing	75.00 %	0.00 %	\$0.00
C10 - Interior Construction	91.58 %	0.00 %	\$0.00
C30 - Interior Finishes	73.58 %	0.00 %	\$0.00
D20 - Plumbing	83.33 %	0.00 %	\$0.00
D30 - HVAC	81.96 %	0.00 %	\$0.00
D50 - Electrical	81.51 %	0.00 %	\$0.00
Totals:	87.22 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). North Elevation - Jan 12, 2017



2). East Elevation - Jan 12, 2017



3). Southeast Elevation - Jan 12, 2017



4). West Elevation - Jan 12, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	1,400	100	2012	2112		95.00 %	0.00 %	95			\$28,182
A1030	Slab on Grade	\$19.75	S.F.	1,400	100	2012	2112		95.00 %	0.00 %	95			\$27,650
B1020	Roof Construction	\$16.26	S.F.	1,400	100	2012	2112		95.00 %	0.00 %	95			\$22,764
B2010	Exterior Walls	\$18.04	S.F.	1,400	100	2012	2112		95.00 %	0.00 %	95			\$25,256
B2020	Exterior Windows	\$6.47	S.F.	1,400	30	2012	2042		83.33 %	0.00 %	25			\$9,058
B2030	Exterior Doors	\$8.66	S.F.	1,400	30	2012	2042		83.33 %	0.00 %	25			\$12,124
B3010140	Asphalt Shingles	\$4.32	S.F.	1,400	20	2012	2032		75.00 %	0.00 %	15			\$6,048
C1010	Partitions	\$10.34	S.F.	1,400	75	2012	2087		93.33 %	0.00 %	70			\$14,476
C1020	Interior Doors	\$2.20	S.F.	1,400	30	2012	2042		83.33 %	0.00 %	25			\$3,080
C3010	Wall Finishes	\$5.11	S.F.	1,400	10	2012	2022		50.00 %	0.00 %	5			\$7,154
C3030	Ceiling Finishes	\$18.76	S.F.	1,400	25	2012	2037		80.00 %	0.00 %	20			\$26,264
D2010	Plumbing Fixtures	\$9.98	S.F.	1,400	30	2012	2042		83.33 %	0.00 %	25			\$13,972
D2020	Domestic Water Distribution	\$0.84	S.F.	1,400	30	2012	2042		83.33 %	0.00 %	25			\$1,176
D2030	Sanitary Waste	\$5.94	S.F.	1,400	30	2012	2042		83.33 %	0.00 %	25			\$8,316
D3040	Distribution Systems	\$5.35	S.F.	1,400	30	2012	2042		83.33 %	0.00 %	25			\$7,490
D3090	Other HVAC Systems/Equip	\$1.06	S.F.	1,400	20	2012	2032		75.00 %	0.00 %	15			\$1,484
D5010	Electrical Service/Distribution	\$1.47	S.F.	1,400	40	2012	2052		87.50 %	0.00 %	35			\$2,058
D5020	Branch Wiring	\$3.58	S.F.	1,400	30	2012	2042		83.33 %	0.00 %	25			\$5,012
D5020	Lighting	\$9.58	S.F.	1,400	30	2012	2042		83.33 %	0.00 %	25			\$13,412
D5030810	Security & Detection Systems	\$1.00	Ea.	1,400	15	2012	2027		66.67 %	0.00 %	10			\$1,400
D5030910	Fire Alarm Systems	\$1.21	S.F.	1,400	15	2012	2027		66.67 %	0.00 %	10			\$1,694
Total									87.22 %					\$238,070

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:



Campus Assessment Report - 2012 Concession Building

System: B3010140 - Asphalt Shingles



Note:

System: C1010 - Partitions



Note:




System: C1020 - Interior Doors



Note:


Campus Assessment Report - 2012 Concession Building

System: C3010 - Wall Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

Campus Assessment Report - 2012 Concession Building

System: D2020 - Domestic Water Distribution




Note:

System: D2030 - Sanitary Waste



Note:

System: D3040 - Distribution Systems



Note:

Campus Assessment Report - 2012 Concession Building

System: D3090 - Other HVAC Systems/Equip



Note:

System: D5010 - Electrical Service/Distribution



Note:

System: D5020 - Branch Wiring



Note:

Campus Assessment Report - 2012 Concession Building

System: D5020 - Lighting



Note:

System: D5030810 - Security & Detection Systems



Note:

System: D5030910 - Fire Alarm Systems



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$0	\$0	\$0	\$9,122	\$0	\$0	\$0	\$0	\$4,573	\$13,696
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$9,122	\$0	\$0	\$0	\$0	\$0	\$9,122
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 2012 Concession Building

D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3090 - Other HVAC Systems/Equip	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,070	\$2,070
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,504	\$2,504

* Indicates non-renewable system

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	235
Year Built:	2015
Last Renovation:	
Replacement Value:	\$41,535
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	95.20 %
FCA Score:	100.00



Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary


Function:	HS -High School	Gross Area:	235
Year Built:	2015	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$41,535
FCI:	0.00 %	RSLI%:	95.20 %

No data found for this asset

No data found for this asset

No data found for this asset

10 Year Investment Forecast



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	98.00 %	0.00 %	\$0.00
B10 - Superstructure	98.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	95.83 %	0.00 %	\$0.00
B30 - Roofing	90.00 %	0.00 %	\$0.00
C20 - Stairs	98.00 %	0.00 %	\$0.00
C30 - Interior Finishes	88.81 %	0.00 %	\$0.00
D50 - Electrical	93.58 %	0.00 %	\$0.00
Totals:	95.20 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). Northeast Elevation - Jan 12, 2017



2). Southeast Elevation - Jan 12, 2017



3). Southwest Elevation - Jan 12, 2017



4). Northwest Elevation - Jan 12, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	235	100	2015	2115		98.00 %	0.00 %	98			\$4,731
A1030	Slab on Grade	\$19.75	S.F.	235	100	2015	2115		98.00 %	0.00 %	98			\$4,641
B1010	Floor Construction	\$11.44	S.F.	235	100	2015	2115		98.00 %	0.00 %	98			\$2,688
B1020	Roof Construction	\$16.26	S.F.	235	100	2015	2115		98.00 %	0.00 %	98			\$3,821
B2010	Exterior Walls	\$29.79	S.F.	235	100	2015	2115		98.00 %	0.00 %	98			\$7,001
B2020	Exterior Windows	\$17.17	S.F.	235	30	2015	2045		93.33 %	0.00 %	28			\$4,035
B2030	Exterior Doors	\$8.66	S.F.	235	30	2015	2045		93.33 %	0.00 %	28			\$2,035
B3010140	Asphalt Shingles	\$4.32	S.F.	235	20	2015	2035		90.00 %	0.00 %	18			\$1,015
C2010	Stair Construction	\$1.32	S.F.	235	100	2015	2115		98.00 %	0.00 %	98			\$310
C3010	Wall Finishes	\$5.11	S.F.	235	10	2015	2025		80.00 %	0.00 %	8			\$1,201
C3020	Floor Finishes	\$12.37	S.F.	235	20	2015	2035		90.00 %	0.00 %	18			\$2,907
C3030	Ceiling Finishes	\$9.52	S.F.	235	25	2015	2040		92.00 %	0.00 %	23			\$2,237
D5010	Electrical Service/Distribution	\$3.09	S.F.	235	40	2015	2055		95.00 %	0.00 %	38			\$726
D5020	Branch Wiring	\$9.24	S.F.	235	30	2015	2045		93.33 %	0.00 %	28			\$2,171
D5020	Lighting	\$8.58	S.F.	235	30	2015	2045		93.33 %	0.00 %	28			\$2,016
Total									95.20 %					\$41,535

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls




Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:


Campus Assessment Report - 2015 Baseball Pressbox

System: B3010140 - Asphalt Shingles




Note:

System: C2010 - Stair Construction



Note:

System: C3010 - Wall Finishes



Note:

Campus Assessment Report - 2015 Baseball Pressbox

System: C3020 - Floor Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

System: D5010 - Electrical Service/Distribution



Note:

Campus Assessment Report - 2015 Baseball Pressbox

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Campus Assessment Report - 2015 Baseball Pressbox


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,673	\$0	\$0	\$1,673
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C20 - Stairs	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C2010 - Stair Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,673	\$0	\$0	\$1,673
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	2,000
Year Built:	2015
Last Renovation:	
Replacement Value:	\$427,460
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	93.99 %
FCA Score:	100.00



Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.


Dashboard Summary

Function:	HS -High School	Gross Area:	2,000
Year Built:	2015	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$427,460
FCI:	0.00 %	RSLI%:	93.99 %

No data found for this asset

No data found for this asset

No data found for this asset



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	98.00 %	0.00 %	\$0.00
B10 - Superstructure	98.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	96.69 %	0.00 %	\$0.00
B30 - Roofing	90.00 %	0.00 %	\$0.00
C10 - Interior Construction	96.57 %	0.00 %	\$0.00
C30 - Interior Finishes	89.43 %	0.00 %	\$0.00
D20 - Plumbing	93.33 %	0.00 %	\$0.00
D30 - HVAC	89.38 %	0.00 %	\$0.00
D50 - Electrical	90.52 %	0.00 %	\$0.00
E10 - Equipment	90.00 %	0.00 %	\$0.00
E20 - Furnishings	90.00 %	0.00 %	\$0.00
Totals:	93.99 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). Southeast Elevation - Jan 13, 2017



2). Northeast Elevation - Jan 13, 2017



3). North Elevation - Jan 13, 2017



4). Southwest Elevation - Jan 13, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	2,000	100	2015	2115		98.00 %	0.00 %	98			\$40,260
A1030	Slab on Grade	\$19.75	S.F.	2,000	100	2015	2115		98.00 %	0.00 %	98			\$39,500
B1020	Roof Construction	\$16.26	S.F.	2,000	100	2015	2115		98.00 %	0.00 %	98			\$32,520
B2010	Exterior Walls	\$29.79	S.F.	2,000	100	2015	2115		98.00 %	0.00 %	98			\$59,580
B2020	Exterior Windows	\$6.93	S.F.	2,000	30	2015	2045		93.33 %	0.00 %	28			\$13,860
B2030	Exterior Doors	\$4.70	S.F.	2,000	30	2015	2045		93.33 %	0.00 %	28			\$9,400
B3010140	Asphalt Shingles	\$4.32	S.F.	2,000	20	2015	2035		90.00 %	0.00 %	18			\$8,640
C1010	Partitions	\$11.01	S.F.	2,000	75	2015	2090		97.33 %	0.00 %	73			\$22,020
C1020	Interior Doors	\$2.59	S.F.	2,000	30	2015	2045		93.33 %	0.00 %	28			\$5,180
C3010	Wall Finishes	\$5.11	S.F.	2,000	10	2015	2025		80.00 %	0.00 %	8			\$10,220
C3030	Ceiling Finishes	\$18.76	S.F.	2,000	25	2015	2040		92.00 %	0.00 %	23			\$37,520
D2010	Plumbing Fixtures	\$11.71	S.F.	2,000	30	2015	2045		93.33 %	0.00 %	28			\$23,420
D2020	Domestic Water Distribution	\$0.99	S.F.	2,000	30	2015	2045		93.33 %	0.00 %	28			\$1,980
D2030	Sanitary Waste	\$1.57	S.F.	2,000	30	2015	2045		93.33 %	0.00 %	28			\$3,140
D3040	Distribution Systems	\$6.26	S.F.	2,000	30	2015	2045		93.33 %	0.00 %	28			\$12,520
D3050	Terminal & Package Units	\$9.57	S.F.	2,000	15	2015	2030		86.67 %	0.00 %	13			\$19,140
D3060	Controls & Instrumentation	\$1.98	S.F.	2,000	20	2015	2035		90.00 %	0.00 %	18			\$3,960
D5010	Electrical Service/Distribution	\$1.73	S.F.	2,000	40	2015	2055		95.00 %	0.00 %	38			\$3,460
D5020	Branch Wiring	\$3.58	S.F.	2,000	30	2015	2045		93.33 %	0.00 %	28			\$7,160
D5020	Lighting	\$9.58	S.F.	2,000	30	2015	2045		93.33 %	0.00 %	28			\$19,160
D5030310	Data Communications	\$4.61	S.F.	2,000	15	2015	2030		86.67 %	0.00 %	13			\$9,220
D5030810	Security & Detection Systems	\$3.46	Ea.	2,000	15	2015	2030		86.67 %	0.00 %	13			\$6,920
D5030910	Fire Alarm	\$3.56	S.F.	2,000	15	2015	2030		86.67 %	0.00 %	13			\$7,120
E1010	Commercial Equipment	\$9.83	S.F.	2,000	20	2015	2035		90.00 %	0.00 %	18			\$19,660
E2010	Fixed Furnishings	\$5.95	S.F.	2,000	20	2015	2035		90.00 %	0.00 %	18			\$11,900
Total									93.99 %					\$427,460

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls




Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:




Campus Assessment Report - 2015 Laundromat Building

System: B3010140 - Asphalt Shingles






Note:

System: C1010 - Partitions



Note:




System: C1020 - Interior Doors



Note:



Campus Assessment Report - 2015 Laundromat Building

System: C3010 - Wall Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:


Campus Assessment Report - 2015 Laundromat Building

System: D2020 - Domestic Water Distribution





Note:

System: D2030 - Sanitary Waste



Note:

System: D3040 - Distribution Systems



Note:

Campus Assessment Report - 2015 Laundromat Building

System: D3050 - Terminal & Package Units



Note:

System: D3060 - Controls & Instrumentation



Note:


System: D5010 - Electrical Service/Distribution



Note:




Campus Assessment Report - 2015 Laundromat Building

System: D5020 - Branch Wiring




Note:

System: D5020 - Lighting



Note:


System: D5030310 - Data Communications



Note:



Campus Assessment Report - 2015 Laundromat Building

System: D5030810 - Security & Detection Systems



Note:

System: D5030910 - Fire Alarm



Note:

System: E1010 - Commercial Equipment



Note:

Campus Assessment Report - 2015 Laundromat Building

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$14,241	\$0	\$0	\$14,241
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$14,241	\$0	\$0	\$14,241
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 2015 Laundromat Building

D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030310 - Data Communications	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Fire Alarm	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1010 - Commercial Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	285,240
Year Built:	1967
Last Renovation:	
Replacement Value:	\$11,480,908
Repair Cost:	\$911,533.06
Total FCI:	7.94 %
Total RSLI:	18.34 %
FCA Score:	92.06







Description:

The narrative for this site is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	285,240
Year Built:	1967	Last Renovation:	
Repair Cost:	\$911,533	Replacement Value:	\$11,480,908
FCI:	7.94 %	RSLI%:	18.34 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	23.13 %	12.42 %	\$911,533.06
G30 - Site Mechanical Utilities	8.21 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	13.07 %	0.00 %	\$0.00
Totals:	18.34 %	7.94 %	\$911,533.06

Photo Album

The photo album consists of the various cardinal directions of the building..

- 1). Aerial Image of Scotland High School -
Dec 30, 2016



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$3.76	S.F.	285,240	25	1967	1992	2021	16.00 %	1.60 %	4		\$17,160.00	\$1,072,502
G2020	Parking Lots	\$1.61	S.F.	285,240	25	1967	1992		0.00 %	110.00 %	-25		\$505,160.00	\$459,236
G2030	Pedestrian Paving	\$1.98	S.F.	285,240	30	1967	1997	2021	13.33 %	2.25 %	4		\$12,696.06	\$564,775
G2040105	Fence & Guardrails	\$1.20	S.F.	285,240	30	1967	1997		0.00 %	110.00 %	-20		\$376,517.00	\$342,288
G2040950	Baseball Field	\$5.78	S.F.	285,240	20	1967	1987	2021	20.00 %	0.00 %	4			\$1,648,687
G2040950	Covered Walkways	\$0.81	S.F.	285,240	25	1967	1992	2021	16.00 %	0.00 %	4			\$231,044
G2040950	Football Field	\$3.38	S.F.	285,240	20	2009	2029		60.00 %	0.00 %	12			\$964,111
G2040950	Playing Field	\$1.50	S.F.	285,240	20	1967	1987	2021	20.00 %	0.00 %	4			\$427,860
G2040950	Softball Field	\$2.01	S.F.	285,240	20	1967	1987	2021	20.00 %	0.00 %	4			\$573,332
G2040950	Track	\$1.78	S.F.	285,240	20	2009	2029		60.00 %	0.00 %	12			\$507,727
G2050	Landscaping	\$1.91	S.F.	285,240	15	1967	1982		0.00 %	0.00 %	-35			\$544,808
G3010	Water Supply	\$2.42	S.F.	285,240	50	1967	2017	2021	8.00 %	0.00 %	4			\$690,281
G3020	Sanitary Sewer	\$1.52	S.F.	285,240	50	1967	2017	2021	8.00 %	0.00 %	4			\$433,565
G3030	Storm Sewer	\$4.67	S.F.	285,240	50	1967	2017	2021	8.00 %	0.00 %	4			\$1,332,071
G3060	Fuel Distribution	\$1.03	S.F.	285,240	40	1967	2007	2021	10.00 %	0.00 %	4			\$293,797
G4010	Electrical Distribution	\$2.44	S.F.	285,240	50	1967	2017	2021	8.00 %	0.00 %	4			\$695,986
G4020	Site Lighting	\$1.57	S.F.	285,240	30	1967	1997	2021	13.33 %	0.00 %	4			\$447,827
G4030	Site Communications & Security	\$0.88	S.F.	285,240	15	1967	1982	2021	26.67 %	0.00 %	4			\$251,011
Total									18.34 %	7.94 %			\$911,533.06	\$11,480,908

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: G2010 - Roadways



Note:

System: G2020 - Parking Lots



Note: The parking lot is beyond its service life and should be resealed, restriped and recoated.

System: G2030 - Pedestrian Paving



Note:

Campus Assessment Report - Site

System: G2040105 - Fence & Guardrails



Note: The fences and guardrail are rusted and beyond their service life and should be replaced.

System: G2040950 - Baseball Field



Note:

System: G2040950 - Covered Walkways



Note:

Campus Assessment Report - Site

System: G2040950 - Football Field



Note:

System: G2040950 - Playing Field



Note:

System: G2040950 - Softball Field



Note:

Campus Assessment Report - Site

System: G2040950 - Track



Note:

System: G2050 - Landscaping



Note: The landscaping is beyond its service life and should be replaced.

System: G3010 - Water Supply



Note:

Campus Assessment Report - Site

System: G3020 - Sanitary Sewer



Note:

System: G3030 - Storm Sewer



Note:

System: G3060 - Fuel Distribution



Note:

Campus Assessment Report - Site

System: G4010 - Electrical Distribution



Note:

System: G4020 - Site Lighting



Note:

System: G4030 - Site Communications & Security



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$911,533	\$0	\$0	\$0	\$10,724,988	\$0	\$0	\$0	\$0	\$0	\$0	\$11,636,521
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$17,160	\$0	\$0	\$0	\$1,327,822	\$0	\$0	\$0	\$0	\$0	\$0	\$1,344,982
G2020 - Parking Lots	\$505,160	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$505,160
G2030 - Pedestrian Paving	\$12,696	\$0	\$0	\$0	\$699,226	\$0	\$0	\$0	\$0	\$0	\$0	\$711,922
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040105 - Fence & Guardrails	\$376,517	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$376,517
G2040950 - Baseball Field	\$0	\$0	\$0	\$0	\$2,041,173	\$0	\$0	\$0	\$0	\$0	\$0	\$2,041,173
G2040950 - Covered Walkways	\$0	\$0	\$0	\$0	\$286,047	\$0	\$0	\$0	\$0	\$0	\$0	\$286,047
G2040950 - Football Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040950 - Playing Field	\$0	\$0	\$0	\$0	\$529,716	\$0	\$0	\$0	\$0	\$0	\$0	\$529,716
G2040950 - Softball Field	\$0	\$0	\$0	\$0	\$709,820	\$0	\$0	\$0	\$0	\$0	\$0	\$709,820
G2040950 - Track	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* G2050 - Landscaping	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$0	\$0	\$0	\$0	\$854,609	\$0	\$0	\$0	\$0	\$0	\$0	\$854,609
G3020 - Sanitary Sewer	\$0	\$0	\$0	\$0	\$536,779	\$0	\$0	\$0	\$0	\$0	\$0	\$536,779
G3030 - Storm Sewer	\$0	\$0	\$0	\$0	\$1,649,183	\$0	\$0	\$0	\$0	\$0	\$0	\$1,649,183
G3060 - Fuel Distribution	\$0	\$0	\$0	\$0	\$363,739	\$0	\$0	\$0	\$0	\$0	\$0	\$363,739
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$0	\$0	\$0	\$0	\$861,672	\$0	\$0	\$0	\$0	\$0	\$0	\$861,672
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$554,436	\$0	\$0	\$0	\$0	\$0	\$0	\$554,436
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$310,766	\$0	\$0	\$0	\$0	\$0	\$0	\$310,766

** Indicates non-renewable system*


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$911,533.06

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$911,533.06


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
G2010	Roadways	\$0.00	\$0.00	\$17,160.00	\$0.00	\$0.00	\$17,160.00
G2020	Parking Lots	\$0.00	\$0.00	\$505,160.00	\$0.00	\$0.00	\$505,160.00
G2030	Pedestrian Paving	\$12,696.06	\$0.00	\$0.00	\$0.00	\$0.00	\$12,696.06
G2040105	Fence & Guardrails	\$0.00	\$0.00	\$376,517.00	\$0.00	\$0.00	\$376,517.00
	Total:	\$12,696.06	\$0.00	\$898,837.00	\$0.00	\$0.00	\$911,533.06

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Currently Critical (Immediate):

System: G2030 - Pedestrian Paving



Location: Site
Distress: Failing
Category: Life Safety Code Compliance
Priority: 1 - Currently Critical (Immediate)
Correction: Remove and replace concrete sidewalk, 4' wide
Qty: 250.00
Unit of Measure: L.F.
Estimate: \$12,696.06
Assessor Name: Somnath Das
Date Created: 01/09/2017

Notes: The pedestrian paving is undulating and has become a tripping hazard, the pedestrian paving should be replaced.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: G2010 - Roadways



Location: Site
Distress: Failing
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Resurface the roadway
Qty: 100.00
Unit of Measure: L.F.
Estimate: \$17,160.00
Assessor Name: Somnath Das
Date Created: 01/09/2017

Notes: The roadways have cracks and it should be resealed and recoated.

System: G2020 - Parking Lots



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 285,240.00
Unit of Measure: S.F.
Estimate: \$505,160.00
Assessor Name: Somnath Das
Date Created: 12/30/2016

Notes: The parking lot is beyond its service life and should be resealed, restriped and recoated.

System: G2040105 - Fence & Guardrails



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 285,240.00
Unit of Measure: S.F.
Estimate: \$376,517.00
Assessor Name: Somnath Das
Date Created: 12/30/2016

Notes: The fences and guardrail are rusted and beyond their service life and should be replaced.

NC School District/830 Scotland County/High School

Shaw Academy

Draft

Campus Assessment Report

March 7, 2017



Table of Contents

Campus Executive Summary	6
Campus Dashboard Summary	9
Campus Condition Summary	10
<u>1951 Main/Cafeteria</u>	12
Executive Summary	12
Dashboard Summary	13
Condition Summary	14
Photo Album	15
Condition Detail	16
System Listing	17
System Notes	19
Renewal Schedule	28
Forecasted Sustainment Requirement	30
Deficiency Summary By System	31
Deficiency Summary By Priority	32
Deficiency By Priority Investment	33
Deficiency Summary By Category	34
Deficiency Details By Priority	35
<u>1956 Gym</u>	42
Executive Summary	42
Dashboard Summary	43
Condition Summary	44
Photo Album	45
Condition Detail	46
System Listing	47
System Notes	48
Renewal Schedule	57
Forecasted Sustainment Requirement	59
Deficiency Summary By System	60

Campus Assessment Report

Deficiency Summary By Priority	61
Deficiency By Priority Investment	62
Deficiency Summary By Category	63
Deficiency Details By Priority	64
<u>1957 Classrooms-Annex</u>	73
Executive Summary	73
Dashboard Summary	74
Condition Summary	75
Photo Album	76
Condition Detail	77
System Listing	78
System Notes	79
Renewal Schedule	86
Forecasted Sustainment Requirement	88
Deficiency Summary By System	89
Deficiency Summary By Priority	90
Deficiency By Priority Investment	91
Deficiency Summary By Category	92
Deficiency Details By Priority	93
<u>1966 Shop-Storage</u>	99
Executive Summary	99
Dashboard Summary	100
Condition Summary	101
Photo Album	102
Condition Detail	103
System Listing	104
System Notes	105
Renewal Schedule	108
Forecasted Sustainment Requirement	109
Deficiency Summary By System	110
Deficiency Summary By Priority	111

Campus Assessment Report

Deficiency By Priority Investment	112
Deficiency Summary By Category	113
Deficiency Details By Priority	114
<u>1982 Media Center</u>	116
Executive Summary	116
Dashboard Summary	117
Condition Summary	118
Photo Album	119
Condition Detail	120
System Listing	121
System Notes	122
Renewal Schedule	131
Forecasted Sustainment Requirement	133
Deficiency Summary By System	134
Deficiency Summary By Priority	135
Deficiency By Priority Investment	136
Deficiency Summary By Category	137
Deficiency Details By Priority	138
<u>Site</u>	142
Executive Summary	142
Dashboard Summary	143
Condition Summary	144
Photo Album	145
Condition Detail	146
System Listing	147
System Notes	148
Renewal Schedule	153
Forecasted Sustainment Requirement	154
Deficiency Summary By System	155
Deficiency Summary By Priority	156
Deficiency By Priority Investment	157

Campus Assessment Report

Deficiency Summary By Category	158
Deficiency Details By Priority	159

Campus Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	54,896
Year Built:	1951
Last Renovation:	
Replacement Value:	\$11,524,432
Repair Cost:	\$4,434,601.00
Total FCI:	38.48 %
Total RSLI:	23.98 %
FCA Score:	61.52



Description:

GENERAL:

Shaw Academy is located at 18700 Old Wire Rd in Laurinburg, North Carolina. The 1 story, 54,896 square foot building was originally constructed in 1951 There have been 4 additions. In addition to the main building, the campus contains a 1956 gym, a 1957 classroom annex, a 1966 shop/storage building, and a 1982 media center.

This report contains condition and adequacy data collected during the 2017 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for the site and building elements.

A. SUBSTRUCTURE

The building rests on slab-on grade and is assumed to have standard cast-in-place concrete foundations. The main building does not have a basement .

B. SUPERSTRUCTURE

Floor construction is concrete. Roof construction is steel. The exterior envelope is composed of walls of brick veneer over CMU. Exterior windows are aluminum frame with operable panes. Exterior doors are hollow metal steel mostly with glazing. Roofing is typically low slope standing seam metal. There are no roof openings. Most building entrances appear to comply with ADA requirements.

C. INTERIORS

Interior partitions are typically CMU. Interior doors are generally solid core wood with hollow steel frames and mostly with glazing. Interior fittings include the following items: white boards, graphics and identifying devices, toilet accessories, storage shelving, handrails, fabricated toilet partitions. The interior wall finishes are typically painted CMU. Floor finishes in common areas are typically vinyl composition tile. Floor finishes in assignable spaces is typically vinyl composition tile. Ceiling finishes in common areas are typically suspended acoustical tile. Ceiling finishes in assignable areas are typically suspended acoustical tile.

CONVEYING:

The building does not include conveying equipment. Conveying equipment includes no hydraulic elevators, and no wheelchair lifts.

D. SERVICES

PLUMBING:

Plumbing fixtures are typically non-low-flow water fixtures with manual control valves. Domestic water distribution is combination of copper and galvanized steel with electric hot water heating. Sanitary waste system is cast iron and plastic. Rain water drainage system is external with gutters..

HVAC:

Heating is provided by 2 gas fired boilers. Cooling is supplied by multiple air cooled chillers. The heating/cooling distribution system is a radiant system utilizing air handling units. Fresh air is supplied by infiltration. Ceiling mounted exhaust fans are installed in bathrooms and other required areas. Controls and instrumentation are digital and are not centrally controlled by an energy management system. This building does not have a locally controlled Building Automation System.

FIRE PROTECTION:

The building does not have a fire sprinkler system. The building does not have additional fire suppression system in the kitchen. Standpipes are not included within fire stairs. Fire extinguishers and cabinets are distributed near fire exits and corridors.

ELECTRICAL:

The main electrical service is fed from a pad mounted transformer to the main switchboard/distribution panel located in the building. Lighting is lay-in, recessed and surface type, fluorescent and LED light fixtures. Branch circuit wiring is typically copper serving electrical switches and receptacles. Emergency and life safety egress lighting systems are installed and exit signs are present at exit doors and near stairways and are typically illuminated.

COMMUNICATIONS AND SECURITY:

The fire alarm system consists of audible/visual strobe annunciators in common spaces, balconies and interior corridors. The system is activated by manual pull stations and smoke detectors and the system is centrally monitored. The telephone and data systems are segregated and include dedicated equipment closets. This building does have a local area network (LAN). The building includes an internal security system that is actuated by the following items: contacts, infrared, optical or a combination of all devices. The building has controlled entry doors access provided by key and locks; entry doors are secured with lock sets. The security system has CCTV cameras and is not centrally monitored; this building has a public address and paging system separate from the telephone system.

OTHER ELECTRICAL SYSTEMS:

This building does not have a separately derived emergency power system.

E. EQUIPMENT & FURNISHINGS:

This building includes the following items and equipment: fixed food service, library equipment, athletic equipment, theater and stage, audio-visual, fixed casework, window treatment, floor grilles and mats, and multiple seating furnishings.

G.

SITE

Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, play areas, and fencing. Site mechanical and electrical features include water, sewer, propane, and site lighting.

Campus Assessment Report - Shaw Academy

Attributes:

General Attributes:





Condition Assessor: Matt Mahaffey Assessment Date:
Suitability Assessor:

School Information:

HS Attendance Area:		LEA School No.:	
No. of Mobile Units:	0	No. of Bldgs.:	1
SF of Mobile Units:		Status:	
School Grades:	7-12	Site Acreage:	15.9

Campus Dashboard Summary

Gross Area:	54,896	Last Renovation:	
Year Built:	1951	Replacement Value:	\$11,524,432
Repair Cost:	\$4,434,601	RSLI%:	23.98 %
FCI:	38.48 %		



Campus Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	41.67 %	0.00 %	\$0.00
A20 - Basement Construction	39.00 %	0.00 %	\$0.00
B10 - Superstructure	39.55 %	0.00 %	\$0.00
B20 - Exterior Enclosure	22.84 %	49.46 %	\$608,179.00
B30 - Roofing	49.10 %	18.12 %	\$92,069.00
C10 - Interior Construction	10.67 %	44.97 %	\$491,459.00
C30 - Interior Finishes	11.85 %	50.79 %	\$775,589.00
D20 - Plumbing	0.20 %	108.39 %	\$702,197.00
D30 - HVAC	45.54 %	8.10 %	\$75,533.00
D40 - Fire Protection	0.00 %	110.00 %	\$260,046.00
D50 - Electrical	32.15 %	35.62 %	\$497,338.00
E10 - Equipment	21.17 %	34.15 %	\$27,664.00
E20 - Furnishings	1.46 %	99.30 %	\$223,981.00
G20 - Site Improvements	3.12 %	63.56 %	\$591,779.00
G30 - Site Mechanical Utilities	30.00 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	24.74 %	34.70 %	\$88,767.00
Totals:	23.98 %	38.48 %	\$4,434,601.00

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance
1951 Main/Cafeteria	28,806	36.65	\$0.00	\$0.00	\$1,788,391.00	\$167,622.00	\$0.00
1956 Gym	8,688	44.81	\$0.00	\$7,262.00	\$649,708.00	\$47,688.00	\$0.00
1957 Classrooms-Annex	6,120	44.62	\$0.00	\$65,570.00	\$388,368.00	\$33,592.00	\$0.00
1966 Shop-Storage	7,520	28.94	\$0.00	\$0.00	\$352,719.00	\$0.00	\$0.00
1982 Media Center	3,762	38.39	\$0.00	\$0.00	\$232,485.00	\$20,650.00	\$0.00
Site	54,896	41.39	\$0.00	\$0.00	\$680,546.00	\$0.00	\$0.00
Total:		38.48	\$0.00	\$72,832.00	\$4,092,217.00	\$269,552.00	\$0.00

Deficiencies By Priority



- 1 - Currently Critical (Immediate)
- 2 - Potentially Critical (Year 1) - \$72,832.00
- 3 - Necessary/Not Yet Critical (Years 2-5) - \$4,092,217.00
- 4 - Recommended (Years 6-10) - \$269,552.00
- 5 - Codes or Standards Compliance

Budget Estimate Total: \$4,434,601.00

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	28,806
Year Built:	1951
Last Renovation:	
Replacement Value:	\$5,336,600
Repair Cost:	\$1,956,013.00
Total FCI:	36.65 %
Total RSLI:	26.14 %
FCA Score:	63.35







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	28,806
Year Built:	1951	Last Renovation:	
Repair Cost:	\$1,956,013	Replacement Value:	\$5,336,600
FCI:	36.65 %	RSLI%:	26.14 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	34.00 %	0.00 %	\$0.00
B10 - Superstructure	34.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	16.14 %	57.80 %	\$330,491.00
B30 - Roofing	73.33 %	0.00 %	\$0.00
C10 - Interior Construction	7.81 %	46.44 %	\$308,627.00
C30 - Interior Finishes	15.55 %	49.79 %	\$360,594.00
D20 - Plumbing	0.00 %	110.00 %	\$443,612.00
D30 - HVAC	49.16 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	110.00 %	\$158,116.00
D50 - Electrical	38.35 %	19.56 %	\$160,334.00
E10 - Equipment	25.91 %	15.00 %	\$9,506.00
E20 - Furnishings	0.00 %	110.00 %	\$184,733.00
Totals:	26.14 %	36.65 %	\$1,956,013.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). North Elevation - Jan 11, 2017



2). East Elevation - Jan 11, 2017



3). South Elevation - Jan 11, 2017



4). West Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

Campus Assessment Report - 1951 Main/Cafeteria

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.79	S.F.	28,806	100	1951	2051		34.00 %	0.00 %	34			\$137,981
A1030	Slab on Grade	\$8.43	S.F.	28,806	100	1951	2051		34.00 %	0.00 %	34			\$242,835
B1010	Floor Construction	\$1.64	S.F.	28,806	100	1951	2051		34.00 %	0.00 %	34			\$47,242
B1020	Roof Construction	\$15.76	S.F.	28,806	100	1951	2051		34.00 %	0.00 %	34			\$453,983
B2010	Exterior Walls	\$9.42	S.F.	28,806	100	1951	2051		34.00 %	0.00 %	34			\$271,353
B2020	Exterior Windows	\$9.39	S.F.	28,806	30	1982	2012		0.00 %	110.00 %	-5		\$297,537.00	\$270,488
B2030	Exterior Doors	\$1.04	S.F.	28,806	30	1951	1981		0.00 %	110.00 %	-36		\$32,954.00	\$29,958
B3010130	Preformed Metal Roofing	\$9.66	S.F.	28,806	30	2009	2039		73.33 %	0.00 %	22			\$278,266
C1010	Partitions	\$10.80	S.F.	28,806	75	1951	2026		12.00 %	0.00 %	9			\$311,105
C1020	Interior Doors	\$2.53	S.F.	28,806	20	1982	2002	2021	20.00 %	0.00 %	4			\$72,879
C1030	Fittings	\$9.74	S.F.	28,806	20	1951	1971		0.00 %	110.00 %	-46		\$308,627.00	\$280,570
C3010	Wall Finishes	\$2.79	S.F.	28,806	10	2010	2020		30.00 %	0.00 %	3			\$80,369
C3020	Floor Finishes	\$11.38	S.F.	28,806	20	1982	2002		0.00 %	110.00 %	-15		\$360,594.00	\$327,812
C3030	Ceiling Finishes	\$10.97	S.F.	28,806	25	1999	2024		28.00 %	0.00 %	7			\$316,002
D2010	Plumbing Fixtures	\$11.48	S.F.	28,806	30	1982	2012		0.00 %	110.00 %	-5		\$363,762.00	\$330,693
D2020	Domestic Water Distribution	\$0.98	S.F.	28,806	30	1951	1981		0.00 %	110.00 %	-36		\$31,053.00	\$28,230
D2030	Sanitary Waste	\$1.54	S.F.	28,806	30	1951	1981		0.00 %	110.00 %	-36		\$48,797.00	\$44,361
D3020	Heat Generating Systems	\$5.08	S.F.	28,806	30	2000	2030		43.33 %	0.00 %	13			\$146,334
D3040	Distribution Systems	\$6.14	S.F.	28,806	30	2000	2030		43.33 %	0.00 %	13			\$176,869
D3050	Terminal & Package Units	\$8.29	S.F.	28,806	15	2010	2025		53.33 %	0.00 %	8			\$238,802
D3060	Controls & Instrumentation	\$1.94	S.F.	28,806	20	2010	2030		65.00 %	0.00 %	13			\$55,884
D4010	Sprinklers	\$4.32	S.F.	28,806	30			2017	0.00 %	110.00 %	0		\$136,886.00	\$124,442
D4020	Standpipes	\$0.67	S.F.	28,806	30			2017	0.00 %	110.00 %	0		\$21,230.00	\$19,300
D5010	Electrical Service/Distribution	\$1.69	S.F.	28,806	40	1982	2022		12.50 %	0.00 %	5			\$48,682
D5020	Branch Wiring	\$5.06	S.F.	28,806	30	1951	1981		0.00 %	110.00 %	-36		\$160,334.00	\$145,758
D5020	Lighting	\$11.92	S.F.	28,806	30	1999	2029		40.00 %	0.00 %	12			\$343,368
D5030810	Security & Detection Systems	\$1.87	S.F.	28,806	15	2012	2027		66.67 %	0.00 %	10			\$53,867
D5030910	Fire Alarm Systems	\$3.39	S.F.	28,806	15	2012	2027		66.67 %	0.00 %	10			\$97,652
D5030920	Data Communication	\$4.40	S.F.	28,806	15	2010	2025		53.33 %	0.00 %	8			\$126,746
D5090	Other Electrical Systems	\$0.12	S.F.	28,806	20	2010	2030		65.00 %	0.00 %	13			\$3,457
E1020	Institutional Equipment	\$0.30	S.F.	28,806	20	1982	2002		0.00 %	110.00 %	-15		\$9,506.00	\$8,642
E1090	Other Equipment	\$1.90	S.F.	28,806	20	2003	2023		30.00 %	0.00 %	6			\$54,731
E2010	Fixed Furnishings	\$5.83	S.F.	28,806	20	1982	2002		0.00 %	110.00 %	-15		\$184,733.00	\$167,939
Total									26.14 %	36.65 %			\$1,956,013.00	\$5,336,600

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:


Campus Assessment Report - 1951 Main/Cafeteria

System: B3010130 - Preformed Metal Roofing




Note:

System: C1010 - Partitions



Note:


System: C1020 - Interior Doors



Note:



Campus Assessment Report - 1951 Main/Cafeteria

System: C1030 - Fittings





Note:

System: C3010 - Wall Finishes



Note:


System: C3020 - Floor Finishes



Note:

Campus Assessment Report - 1951 Main/Cafeteria

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:


System: D2020 - Domestic Water Distribution



Note:

Campus Assessment Report - 1951 Main/Cafeteria

System: D2030 - Sanitary Waste



Note:

System: D3020 - Heat Generating Systems



Note:

System: D3040 - Distribution Systems



Note:

Campus Assessment Report - 1951 Main/Cafeteria

System: D3050 - Terminal & Package Units



Note:

System: D3060 - Controls & Instrumentation



Note:


System: D5010 - Electrical Service/Distribution



Note:


Campus Assessment Report - 1951 Main/Cafeteria

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

System: D5030810 - Security & Detection Systems



Note:

Campus Assessment Report - 1951 Main/Cafeteria

System: D5030910 - Fire Alarm Systems



Note:

System: D5030920 - Data Communication



Note:

System: D5090 - Other Electrical Systems



Note:

Campus Assessment Report - 1951 Main/Cafeteria

System: E1020 - Institutional Equipment



Note:

System: E1090 - Other Equipment



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$1,956,013	\$0	\$0	\$96,604	\$90,229	\$62,079	\$71,888	\$427,507	\$509,372	\$0	\$223,993	\$3,437,684
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$297,537	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$297,537
B2030 - Exterior Doors	\$32,954	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$32,954
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$90,229	\$0	\$0	\$0	\$0	\$0	\$0	\$90,229
C1030 - Fittings	\$308,627	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$308,627
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$96,604	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$96,604
C3020 - Floor Finishes	\$360,594	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$360,594
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$427,507	\$0	\$0	\$0	\$427,507
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1951 Main/Cafeteria

D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$363,762	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$363,762
D2020 - Domestic Water Distribution	\$31,053	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$31,053
D2030 - Sanitary Waste	\$48,797	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$48,797
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$332,758	\$0	\$0	\$0	\$332,758
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$136,886	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$136,886
D4020 - Standpipes	\$21,230	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$21,230
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$62,079	\$0	\$0	\$0	\$0	\$0	\$0	\$62,079
D5020 - Branch Wiring	\$160,334	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$160,334
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$79,632	\$79,632
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$144,361	\$144,361
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$176,614	\$0	\$0	\$0	\$176,614
D5090 - Other Electrical Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$9,506	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$9,506
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$71,888	\$0	\$0	\$0	\$0	\$0	\$71,888
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$184,733	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$184,733

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$1,956,013.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$1,956,013.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2020	Exterior Windows	\$0.00	\$0.00	\$297,537.00	\$0.00	\$0.00	\$297,537.00
B2030	Exterior Doors	\$0.00	\$0.00	\$32,954.00	\$0.00	\$0.00	\$32,954.00
C1030	Fittings	\$0.00	\$0.00	\$308,627.00	\$0.00	\$0.00	\$308,627.00
C3020	Floor Finishes	\$0.00	\$0.00	\$360,594.00	\$0.00	\$0.00	\$360,594.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$363,762.00	\$0.00	\$0.00	\$363,762.00
D2020	Domestic Water Distribution	\$0.00	\$0.00	\$31,053.00	\$0.00	\$0.00	\$31,053.00
D2030	Sanitary Waste	\$0.00	\$0.00	\$48,797.00	\$0.00	\$0.00	\$48,797.00
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$136,886.00	\$0.00	\$136,886.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$21,230.00	\$0.00	\$21,230.00
D5020	Branch Wiring	\$0.00	\$0.00	\$160,334.00	\$0.00	\$0.00	\$160,334.00
E1020	Institutional Equipment	\$0.00	\$0.00	\$0.00	\$9,506.00	\$0.00	\$9,506.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$184,733.00	\$0.00	\$0.00	\$184,733.00
	Total:	\$0.00	\$0.00	\$1,788,391.00	\$167,622.00	\$0.00	\$1,956,013.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$1,956,013.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B2020 - Exterior Windows



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 28,806.00
Unit of Measure: S.F.
Estimate: \$297,537.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: The aluminum frame, operable, single pane windows are aged, rusted, not energy efficient, and should be replaced.

System: B2030 - Exterior Doors



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 28,806.00
Unit of Measure: S.F.
Estimate: \$32,954.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: The original exterior doors are aged, rusted, and should be replaced.

System: C1030 - Fittings



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Accessibility Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 28,806.00
Unit of Measure: S.F.
Estimate: \$308,627.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: The fittings throughout the building are aged, in marginal condition, and should be replaced.
Room signage is missing or non-ADA compliant.

System: C3020 - Floor Finishes



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 28,806.00
Unit of Measure: S.F.
Estimate: \$360,594.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: The VCT flooring is aged, cracked, worn, and should be replaced.
The carpet is also aged, stained, frayed, and should be replace.

System: D2010 - Plumbing Fixtures



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 28,806.00
Unit of Measure: S.F.
Estimate: \$363,762.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: Plumbing fixtures are in operational conditions. However, they are aged and should be replaced with a low-flow water fixtures.

System: D2020 - Domestic Water Distribution



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 28,806.00
Unit of Measure: S.F.
Estimate: \$31,053.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: The domestic water distribution system is aged and should be replaced.

System: D2030 - Sanitary Waste



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 28,806.00
Unit of Measure: S.F.
Estimate: \$48,797.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: The sanitary waste system is aged, has reported periodic failures, and should be replaced.

System: D5020 - Branch Wiring



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 28,806.00
Unit of Measure: S.F.
Estimate: \$160,334.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: The original branch wiring system is operating, but is aged, in poor condition, and should be replaced.

System: E2010 - Fixed Furnishings



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 28,806.00
Unit of Measure: S.F.
Estimate: \$184,733.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: The fixed furnishings are aged, in marginal condition, and should be replaced.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 28,806.00
Unit of Measure: S.F.
Estimate: \$136,886.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 28,806.00
Unit of Measure: S.F.
Estimate: \$21,230.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

System: E1020 - Institutional Equipment



Location: Stage
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 28,806.00
Unit of Measure: S.F.
Estimate: \$9,506.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: Theater equipment is aged and damaged and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	8,688
Year Built:	1956
Last Renovation:	
Replacement Value:	\$1,572,645
Repair Cost:	\$704,658.00
Total FCI:	44.81 %
Total RSLI:	21.85 %
FCA Score:	55.19







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	8,688
Year Built:	1956	Last Renovation:	
Repair Cost:	\$704,658	Replacement Value:	\$1,572,645
FCI:	44.81 %	RSLI%:	21.85 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	39.00 %	0.00 %	\$0.00
A20 - Basement Construction	39.00 %	0.00 %	\$0.00
B10 - Superstructure	39.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	18.51 %	57.80 %	\$99,677.00
B30 - Roofing	0.00 %	148.98 %	\$92,069.00
C10 - Interior Construction	8.74 %	58.50 %	\$117,262.00
C30 - Interior Finishes	4.53 %	60.21 %	\$131,501.00
D20 - Plumbing	0.00 %	110.00 %	\$133,795.00
D30 - HVAC	43.01 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	110.00 %	\$47,688.00
D50 - Electrical	34.73 %	30.87 %	\$64,508.00
E10 - Equipment	0.00 %	110.00 %	\$18,158.00
Totals:	21.85 %	44.81 %	\$704,658.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). West Elevation - Jan 11, 2017



2). South Elevation - Jan 11, 2017



3). East Elevation - Jan 11, 2017



4). North Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.79	S.F.	8,688	100	1956	2056		39.00 %	0.00 %	39			\$41,616
A1030	Slab on Grade	\$8.43	S.F.	8,688	100	1956	2056		39.00 %	0.00 %	39			\$73,240
A2010	Basement Excavation	\$1.90	S.F.	8,688	100	1956	2056		39.00 %	0.00 %	39			\$16,507
A2020	Basement Walls	\$13.07	S.F.	8,688	100	1956	2056		39.00 %	0.00 %	39			\$113,552
B1010	Floor Construction	\$1.64	S.F.	8,688	100	1956	2056		39.00 %	0.00 %	39			\$14,248
B1020	Roof Construction	\$15.76	S.F.	8,688	100	1956	2056		39.00 %	0.00 %	39			\$136,923
B2010	Exterior Walls	\$9.42	S.F.	8,688	100	1956	2056		39.00 %	0.00 %	39			\$81,841
B2020	Exterior Windows	\$9.39	S.F.	8,688	30	1956	1986		0.00 %	110.00 %	-31		\$89,738.00	\$81,580
B2030	Exterior Doors	\$1.04	S.F.	8,688	30	1982	2012		0.00 %	109.99 %	-5		\$9,939.00	\$9,036
B3010105	Built-Up	\$8.95	S.F.	588	25	1982	2007		0.00 %	137.98 %	-10		\$7,262.00	\$5,263
B3010120	Single Ply Membrane	\$6.98	S.F.	8,100	20	1982	2002		0.00 %	150.00 %	-15		\$84,807.00	\$56,538
C1010	Partitions	\$10.80	S.F.	8,688	75	1956	2031		18.67 %	0.00 %	14			\$93,830
C1020	Interior Doors	\$2.53	S.F.	8,688	20	1956	1976		0.00 %	110.00 %	-41		\$24,179.00	\$21,981
C1030	Fittings	\$9.74	S.F.	8,688	20	1956	1976		0.00 %	110.00 %	-41		\$93,083.00	\$84,621
C3010	Wall Finishes	\$2.79	S.F.	8,688	10	1999	2009		0.00 %	110.00 %	-8		\$26,663.00	\$24,240
C3020	Floor Finishes	\$11.38	S.F.	8,688	20	1999	2019		10.00 %	0.00 %	2			\$98,869
C3030	Ceiling Finishes	\$10.97	S.F.	8,688	25	1982	2007		0.00 %	110.00 %	-10		\$104,838.00	\$95,307
D2010	Plumbing Fixtures	\$11.48	S.F.	8,688	30	1956	1986		0.00 %	110.00 %	-31		\$109,712.00	\$99,738
D2020	Domestic Water Distribution	\$0.98	S.F.	8,688	30	1956	1986		0.00 %	110.01 %	-31		\$9,366.00	\$8,514
D2030	Sanitary Waste	\$1.54	S.F.	8,688	30	1956	1986		0.00 %	109.99 %	-31		\$14,717.00	\$13,380
D3020	Heat Generating Systems	\$5.08	S.F.	8,688	30	2000	2030		43.33 %	0.00 %	13			\$44,135
D3050	Terminal & Package Units	\$8.29	S.F.	8,688	15	2008	2023		40.00 %	0.00 %	6			\$72,024
D3060	Controls & Instrumentation	\$1.94	S.F.	8,688	20	2008	2028		55.00 %	0.00 %	11			\$16,855
D4010	Sprinklers	\$4.32	S.F.	8,688	30			2017	0.00 %	110.00 %	0		\$41,285.00	\$37,532
D4020	Standpipes	\$0.67	S.F.	8,688	30			2017	0.00 %	110.00 %	0		\$6,403.00	\$5,821
D5010	Electrical Service/Distribution	\$1.69	S.F.	8,688	40	1956	1996		0.00 %	110.00 %	-21		\$16,151.00	\$14,683
D5020	Branch Wiring	\$5.06	S.F.	8,688	30	1956	1986		0.00 %	110.00 %	-31		\$48,357.00	\$43,961
D5020	Lighting	\$11.92	S.F.	8,688	30	1999	2029		40.00 %	0.00 %	12			\$103,561
D5030810	Security & Detection Systems	\$1.87	S.F.	8,688	15	2012	2027		66.67 %	0.00 %	10			\$16,247
D5030910	Fire Alarm Systems	\$3.39	S.F.	8,688	15	2012	2027		66.67 %	0.00 %	10			\$29,452
D5090	Other Electrical Systems	\$0.12	S.F.	8,688	20	2010	2030		65.00 %	0.00 %	13			\$1,043
E1090	Other Equipment	\$1.90	S.F.	8,688	20	1956	1976		0.00 %	110.00 %	-41		\$18,158.00	\$16,507
Total									21.85 %	44.81 %			\$704,658.00	\$1,572,645

System Notes


The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: A2020 - Basement Walls



Note:

System: B1010 - Floor Construction



Note:

System: B1020 - Roof Construction



Note:


Campus Assessment Report - 1956 Gym

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1956 Gym

System: B3010105 - Built-Up




Note:

System: C1010 - Partitions



Note:

System: C1020 - Interior Doors



Note:

Campus Assessment Report - 1956 Gym

System: C1030 - Fittings



Note:

System: C3010 - Wall Finishes



Note:

System: C3020 - Floor Finishes



Note:

Campus Assessment Report - 1956 Gym

System: C3030 - Ceiling Finishes




Note:

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:


Campus Assessment Report - 1956 Gym

System: D2030 - Sanitary Waste



Note:

System: D3020 - Heat Generating Systems



Note:

System: D3050 - Terminal & Package Units



Note:

Campus Assessment Report - 1956 Gym

System: D3060 - Controls & Instrumentation



Note:

System: D5010 - Electrical Service/Distribution



Note:

System: D5020 - Branch Wiring



Note:

Campus Assessment Report - 1956 Gym

System: D5020 - Lighting



Note:

System: D5030810 - Security & Detection Systems



Note:

System: D5030910 - Fire Alarm Systems



Note:

Campus Assessment Report - 1956 Gym

System: D5090 - Other Electrical Systems



Note:

System: E1090 - Other Equipment



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$704,658	\$0	\$115,379	\$0	\$0	\$0	\$94,600	\$0	\$0	\$0	\$103,390	\$1,018,027
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$89,738	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$89,738
B2030 - Exterior Doors	\$9,939	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$9,939
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010105 - Built-Up	\$7,262	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$7,262
B3010120 - Single Ply Membrane	\$84,807	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$84,807
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$24,179	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$24,179
C1030 - Fittings	\$93,083	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$93,083
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1956 Gym

C3010 - Wall Finishes	\$26,663	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$35,833	\$62,496
C3020 - Floor Finishes	\$0	\$0	\$115,379	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$115,379
C3030 - Ceiling Finishes	\$104,838	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$104,838
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$109,712	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$109,712
D2020 - Domestic Water Distribution	\$9,366	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$9,366
D2030 - Sanitary Waste	\$14,717	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$14,717
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$94,600	\$0	\$0	\$0	\$0	\$0	\$94,600
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$41,285	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$41,285
D4020 - Standpipes	\$6,403	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$6,403
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$16,151	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$16,151
D5020 - Branch Wiring	\$48,357	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$48,357
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$24,017	\$24,017
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$43,540	\$43,540
D5090 - Other Electrical Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1090 - Other Equipment	\$18,158	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$18,158

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$704,658.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$704,658.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2020	Exterior Windows	\$0.00	\$0.00	\$89,738.00	\$0.00	\$0.00	\$89,738.00
B2030	Exterior Doors	\$0.00	\$0.00	\$9,939.00	\$0.00	\$0.00	\$9,939.00
B3010105	Built-Up	\$0.00	\$7,262.00	\$0.00	\$0.00	\$0.00	\$7,262.00
B3010120	Single Ply Membrane	\$0.00	\$0.00	\$84,807.00	\$0.00	\$0.00	\$84,807.00
C1020	Interior Doors	\$0.00	\$0.00	\$24,179.00	\$0.00	\$0.00	\$24,179.00
C1030	Fittings	\$0.00	\$0.00	\$93,083.00	\$0.00	\$0.00	\$93,083.00
C3010	Wall Finishes	\$0.00	\$0.00	\$26,663.00	\$0.00	\$0.00	\$26,663.00
C3030	Ceiling Finishes	\$0.00	\$0.00	\$104,838.00	\$0.00	\$0.00	\$104,838.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$109,712.00	\$0.00	\$0.00	\$109,712.00
D2020	Domestic Water Distribution	\$0.00	\$0.00	\$9,366.00	\$0.00	\$0.00	\$9,366.00
D2030	Sanitary Waste	\$0.00	\$0.00	\$14,717.00	\$0.00	\$0.00	\$14,717.00
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$41,285.00	\$0.00	\$41,285.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$6,403.00	\$0.00	\$6,403.00
D5010	Electrical Service/Distribution	\$0.00	\$0.00	\$16,151.00	\$0.00	\$0.00	\$16,151.00
D5020	Branch Wiring	\$0.00	\$0.00	\$48,357.00	\$0.00	\$0.00	\$48,357.00
E1090	Other Equipment	\$0.00	\$0.00	\$18,158.00	\$0.00	\$0.00	\$18,158.00
	Total:	\$0.00	\$7,262.00	\$649,708.00	\$47,688.00	\$0.00	\$704,658.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$704,658.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 2 - Potentially Critical (Year 1):

System: B3010105 - Built-Up



Location: Entry foyer
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 2 - Potentially Critical (Year 1)
Correction: Renew System
Qty: 588.00
Unit of Measure: S.F.
Estimate: \$7,262.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: Built-up roof covering is in deteriorating conditions with signs of cracks, bubbling, patches and reported water leaks through parapets and other areas.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B2020 - Exterior Windows



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 8,688.00
Unit of Measure: S.F.
Estimate: \$89,738.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: The aluminum frame, operable, single pane windows are aged, rusted, not energy efficient, and should be replaced.

System: B2030 - Exterior Doors



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 8,688.00
Unit of Measure: S.F.
Estimate: \$9,939.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: The original exterior doors are aged, rusted, and should be replaced.


System: B3010120 - Single Ply Membrane

This deficiency has no image.

Location: Gym
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 8,100.00
Unit of Measure: S.F.
Estimate: \$84,807.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: *No photo available due to roof accessibility*
The EPDM adhered and ballasted roof coverings are aging, showing signs of failure and should be replaced.

System: C1020 - Interior Doors



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Accessibility Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 8,688.00
Unit of Measure: S.F.
Estimate: \$24,179.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: The interior doors are aged, failing, most hardware is not ADA or code compliant and should be replaced.

System: C1030 - Fittings



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Accessibility Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 8,688.00
Unit of Measure: S.F.
Estimate: \$93,083.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: The fittings throughout the building are aged, in marginal condition, handrails and room signage are ADA non-compliance and system should be replaced.

System: C3010 - Wall Finishes



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 8,688.00
Unit of Measure: S.F.
Estimate: \$26,663.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: The wall finishes are aged, scuffed, fading, stained, and should be replaced.

System: C3030 - Ceiling Finishes



Location: Gym
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 8,688.00
Unit of Measure: S.F.
Estimate: \$104,838.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: The original ceiling finishes are aged, failing and should be replaced.

System: D2010 - Plumbing Fixtures



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 8,688.00
Unit of Measure: S.F.
Estimate: \$109,712.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: Plumbing fixtures are in operational conditions. However, they are aged, not ADA compliant and should be replaced with a low-flow water fixtures.


System: D2020 - Domestic Water Distribution



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 8,688.00
Unit of Measure: S.F.
Estimate: \$9,366.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: The domestic water distribution system is aged and should be replaced.

System: D2030 - Sanitary Waste



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 8,688.00
Unit of Measure: S.F.
Estimate: \$14,717.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: The sanitary waste system is aged, has reported periodic failures, and should be replaced.


System: D5010 - Electrical Service/Distribution



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 8,688.00
Unit of Measure: S.F.
Estimate: \$16,151.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: The original electrical distribution system is operating properly due to an aggressive maintenance program but is aged, in marginal condition, and should be replaced.

System: D5020 - Branch Wiring



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 8,688.00
Unit of Measure: S.F.
Estimate: \$48,357.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: The original branch wiring system is operating, but is aged, in poor condition, and should be replaced.

System: E1090 - Other Equipment



Location: Gym
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 8,688.00
Unit of Measure: S.F.
Estimate: \$18,158.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: The athletic equipment is aged, in marginal condition, and should be replaced.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 8,688.00
Unit of Measure: S.F.
Estimate: \$41,285.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 8,688.00
Unit of Measure: S.F.
Estimate: \$6,403.00
Assessor Name: Terence Davis
Date Created: 12/23/2016

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	6,120
Year Built:	1957
Last Renovation:	
Replacement Value:	\$1,092,728
Repair Cost:	\$487,530.00
Total FCI:	44.62 %
Total RSLI:	21.22 %
FCA Score:	55.38







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	6,120
Year Built:	1957	Last Renovation:	
Repair Cost:	\$487,530	Replacement Value:	\$1,092,728
FCI:	44.62 %	RSLI%:	21.22 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	40.00 %	0.00 %	\$0.00
B10 - Superstructure	40.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	19.68 %	52.03 %	\$63,213.00
B30 - Roofing	40.00 %	0.00 %	\$0.00
C10 - Interior Construction	11.56 %	46.44 %	\$65,570.00
C30 - Interior Finishes	16.74 %	12.21 %	\$18,782.00
D20 - Plumbing	0.00 %	110.00 %	\$77,283.00
D30 - HVAC	23.46 %	57.54 %	\$75,533.00
D40 - Fire Protection	0.00 %	110.00 %	\$33,592.00
D50 - Electrical	22.52 %	70.59 %	\$114,309.00
E20 - Furnishings	0.00 %	110.00 %	\$39,248.00
Totals:	21.22 %	44.62 %	\$487,530.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). East Elevation - Jan 11, 2017



2). North Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.79	S.F.	6,120	100	1957	2057		40.00 %	0.00 %	40			\$29,315
A1030	Slab on Grade	\$8.43	S.F.	6,120	100	1957	2057		40.00 %	0.00 %	40			\$51,592
B1010	Floor Construction	\$1.64	S.F.	6,120	100	1957	2057		40.00 %	0.00 %	40			\$10,037
B1020	Roof Construction	\$15.76	S.F.	6,120	100	1957	2057		40.00 %	0.00 %	40			\$96,451
B2010	Exterior Walls	\$9.42	S.F.	6,120	100	1957	2057		40.00 %	0.00 %	40			\$57,650
B2020	Exterior Windows	\$9.39	S.F.	6,120	30	1957	1987		0.00 %	110.00 %	-30		\$63,213.00	\$57,467
B2030	Exterior Doors	\$1.04	S.F.	6,120	30	1982	2012	2021	13.33 %	0.00 %	4			\$6,365
B3010130	Preformed Metal Roofing	\$9.66	S.F.	6,120	30	1999	2029		40.00 %	0.00 %	12			\$59,119
C1010	Partitions	\$10.80	S.F.	6,120	75	1957	2032		20.00 %	0.00 %	15			\$66,096
C1020	Interior Doors	\$2.53	S.F.	6,120	20	1982	2002	2021	20.00 %	0.00 %	4			\$15,484
C1030	Fittings	\$9.74	S.F.	6,120	20	1957	1977		0.00 %	110.00 %	-40		\$65,570.00	\$59,609
C3010	Wall Finishes	\$2.79	S.F.	6,120	10	1999	2009		0.00 %	110.00 %	-8		\$18,782.00	\$17,075
C3020	Floor Finishes	\$11.38	S.F.	6,120	20	1999	2019		10.00 %	0.00 %	2			\$69,646
C3030	Ceiling Finishes	\$10.97	S.F.	6,120	25	1999	2024		28.00 %	0.00 %	7			\$67,136
D2010	Plumbing Fixtures	\$11.48	S.F.	6,120	30	1957	1987		0.00 %	110.00 %	-30		\$77,283.00	\$70,258
D3020	Heat Generating Systems	\$5.08	S.F.	6,120	30	1983	2013		0.00 %	110.00 %	-4		\$34,199.00	\$31,090
D3040	Distribution Systems	\$6.14	S.F.	6,120	30	1983	2013		0.00 %	110.00 %	-4		\$41,334.00	\$37,577
D3050	Terminal & Package Units	\$8.29	S.F.	6,120	15	2009	2024		46.67 %	0.00 %	7			\$50,735
D3060	Controls & Instrumentation	\$1.94	S.F.	6,120	20	2009	2029		60.00 %	0.00 %	12			\$11,873
D4010	Sprinklers	\$4.32	S.F.	6,120	30			2017	0.00 %	110.00 %	0		\$29,082.00	\$26,438
D4020	Standpipes	\$0.67	S.F.	6,120	30			2017	0.00 %	110.00 %	0		\$4,510.00	\$4,100
D5010	Electrical Service/Distribution	\$1.69	S.F.	6,120	40	2009	2049		80.00 %	0.00 %	32			\$10,343
D5020	Branch Wiring	\$5.06	S.F.	6,120	30	1957	1987		0.00 %	110.00 %	-30		\$34,064.00	\$30,967
D5020	Lighting	\$11.92	S.F.	6,120	30	1982	2012		0.00 %	110.00 %	-5		\$80,245.00	\$72,950
D5030910	Fire Alarm Systems	\$3.39	S.F.	6,120	15	2012	2027		66.67 %	0.00 %	10			\$20,747
D5030920	Data Communication	\$4.40	S.F.	6,120	15	2010	2025		53.33 %	0.00 %	8			\$26,928
E2010	Fixed Furnishings	\$5.83	S.F.	6,120	20	1957	1977		0.00 %	110.00 %	-40		\$39,248.00	\$35,680
Total									21.22 %	44.62 %			\$487,530.00	\$1,092,728

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls




Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1957 Classrooms-Annex

System: B3010130 - Preformed Metal Roofing



Note:

System: C1010 - Partitions



Note:

System: C1020 - Interior Doors



Note:

Campus Assessment Report - 1957 Classrooms-Annex

System: C1030 - Fittings



Note:

System: C3010 - Wall Finishes



Note:

System: C3020 - Floor Finishes



Note:

Campus Assessment Report - 1957 Classrooms-Annex

System: C3030 - Ceiling Finishes





Note:

System: D2010 - Plumbing Fixtures



Note:

System: D3020 - Heat Generating Systems



Note:

Campus Assessment Report - 1957 Classrooms-Annex

System: D3040 - Distribution Systems



Note:

System: D3050 - Terminal & Package Units



Note:

System: D3060 - Controls & Instrumentation



Note:

Campus Assessment Report - 1957 Classrooms-Annex

System: D5010 - Electrical Service/Distribution



Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Campus Assessment Report - 1957 Classrooms-Annex

System: D5030910 - Fire Alarm Systems



Note:

System: D5030920 - Data Communication



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$487,530	\$0	\$81,276	\$0	\$27,049	\$0	\$0	\$159,463	\$37,523	\$0	\$55,911	\$848,752
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$63,213	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$63,213
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$7,880	\$0	\$0	\$0	\$0	\$0	\$0	\$7,880
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$19,170	\$0	\$0	\$0	\$0	\$0	\$0	\$19,170
C1030 - Fittings	\$65,570	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$65,570
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$18,782	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$25,241	\$44,023
C3020 - Floor Finishes	\$0	\$0	\$81,276	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$81,276
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$90,826	\$0	\$0	\$0	\$90,826
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1957 Classrooms-Annex

D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$77,283	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$77,283
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$34,199	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$34,199
D3040 - Distribution Systems	\$41,334	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$41,334
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$68,637	\$0	\$0	\$0	\$68,637
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$29,082	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$29,082
D4020 - Standpipes	\$4,510	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,510
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$34,064	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$34,064
D5020 - Lighting	\$80,245	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$80,245
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$30,670	\$30,670
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$37,523	\$0	\$0	\$37,523
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$39,248	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$39,248

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$487,530.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$487,530.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2020	Exterior Windows	\$0.00	\$0.00	\$63,213.00	\$0.00	\$0.00	\$63,213.00
C1030	Fittings	\$0.00	\$65,570.00	\$0.00	\$0.00	\$0.00	\$65,570.00
C3010	Wall Finishes	\$0.00	\$0.00	\$18,782.00	\$0.00	\$0.00	\$18,782.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$77,283.00	\$0.00	\$0.00	\$77,283.00
D3020	Heat Generating Systems	\$0.00	\$0.00	\$34,199.00	\$0.00	\$0.00	\$34,199.00
D3040	Distribution Systems	\$0.00	\$0.00	\$41,334.00	\$0.00	\$0.00	\$41,334.00
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$29,082.00	\$0.00	\$29,082.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$4,510.00	\$0.00	\$4,510.00
D5020	Branch Wiring	\$0.00	\$0.00	\$34,064.00	\$0.00	\$0.00	\$34,064.00
D5020	Lighting	\$0.00	\$0.00	\$80,245.00	\$0.00	\$0.00	\$80,245.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$39,248.00	\$0.00	\$0.00	\$39,248.00
	Total:	\$0.00	\$65,570.00	\$388,368.00	\$33,592.00	\$0.00	\$487,530.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$487,530.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 2 - Potentially Critical (Year 1):

System: C1030 - Fittings



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Accessibility Code Compliance
Priority: 2 - Potentially Critical (Year 1)
Correction: Renew System
Qty: 6,120.00
Unit of Measure: S.F.
Estimate: \$65,570.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The fittings throughout the building are aged, in marginal condition, handrails and room signage are ADA non-compliance and system should be replaced.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B2020 - Exterior Windows



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 6,120.00
Unit of Measure: S.F.
Estimate: \$63,213.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The aluminum frame, operable, single pane windows are aged, rusted, not energy efficient, and should be replaced.

System: C3010 - Wall Finishes



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 6,120.00
Unit of Measure: S.F.
Estimate: \$18,782.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The wall paint is damaged, fading, stained, and should be re-painted.

System: D2010 - Plumbing Fixtures



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Accessibility Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 6,120.00
Unit of Measure: S.F.
Estimate: \$77,283.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: Plumbing fixtures are in operational conditions. However, they are aged, not ADA compliant and should be replaced with a low-flow water fixtures.

System: D3020 - Heat Generating Systems



Location: Boiler Rm
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 6,120.00
Unit of Measure: S.F.
Estimate: \$34,199.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The gas-fired boilers are operating poorly, aging, inefficient, becoming logistically unsupportable, and should be replaced with energy efficient models.

System: D3040 - Distribution Systems



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 6,120.00
Unit of Measure: S.F.
Estimate: \$41,334.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The radiator units are aged, becoming logistically unsupportable, and should be replaced.

System: D5020 - Branch Wiring



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 6,120.00
Unit of Measure: S.F.
Estimate: \$34,064.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The original branch wiring system is operating, but is aged, in poor condition, and should be replaced.

System: D5020 - Lighting



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 6,120.00
Unit of Measure: S.F.
Estimate: \$80,245.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The lighting system is operating, but is aged, in poor condition, and should be replaced.

System: E2010 - Fixed Furnishings



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 6,120.00
Unit of Measure: S.F.
Estimate: \$39,248.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The fixed furnishings are aged, in marginal condition, and should be replaced.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 6,120.00
Unit of Measure: S.F.
Estimate: \$29,082.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 6,120.00
Unit of Measure: S.F.
Estimate: \$4,510.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	7,520
Year Built:	1966
Last Renovation:	
Replacement Value:	\$1,218,992
Repair Cost:	\$352,719.00
Total FCI:	28.94 %
Total RSLI:	28.91 %
FCA Score:	71.06







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	7,520
Year Built:	1966	Last Renovation:	
Repair Cost:	\$352,719	Replacement Value:	\$1,218,992
FCI:	28.94 %	RSLI%:	28.91 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	49.00 %	0.00 %	\$0.00
B10 - Superstructure	49.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	37.96 %	24.78 %	\$71,636.00
B30 - Roofing	10.00 %	0.00 %	\$0.00
C30 - Interior Finishes	8.47 %	51.25 %	\$172,223.00
D50 - Electrical	0.00 %	110.00 %	\$108,860.00
Totals:	28.91 %	28.94 %	\$352,719.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). South Elevation - Jan 11, 2017



2). West Elevation - Jan 11, 2017



3). North Elevation - Jan 11, 2017



4). East Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing


The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$20.13	S.F.	7,520	100	1966	2066		49.00 %	0.00 %	49			\$151,378
A1030	Slab on Grade	\$19.75	S.F.	7,520	100	1966	2066		49.00 %	0.00 %	49			\$148,520
B1020	Roof Construction	\$16.26	S.F.	7,520	100	1966	2066		49.00 %	0.00 %	49			\$122,275
B2010	Exterior Walls	\$29.79	S.F.	7,520	100	1966	2066		49.00 %	0.00 %	49			\$224,021
B2030	Exterior Doors	\$8.66	S.F.	7,520	30	1966	1996		0.00 %	110.00 %	-21		\$71,636.00	\$65,123
B3010130	Preformed Metal Roofing	\$9.66	S.F.	7,520	30	1966	1996	2020	10.00 %	0.00 %	3			\$72,643
C3010	Wall Finishes	\$5.11	S.F.	7,520	10	1966	1976	2020	30.00 %	0.00 %	3			\$38,427
C3020	Floor Finishes	\$20.82	S.F.	7,520	20	1966	1986		0.00 %	110.00 %	-31		\$172,223.00	\$156,566
C3030	Ceiling Finishes	\$18.76	S.F.	7,520	25	1966	1991	2020	12.00 %	0.00 %	3			\$141,075
D5020	Branch Wiring	\$3.58	S.F.	7,520	40	1966	2006		0.00 %	110.00 %	-11		\$29,614.00	\$26,922
D5020	Lighting	\$9.58	S.F.	7,520	30	1966	1996		0.00 %	110.00 %	-21		\$79,246.00	\$72,042
Total									28.91 %	28.94 %			\$352,719.00	\$1,218,992

System Notes


The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1020 - Roof Construction



Note:

System: B2010 - Exterior Walls



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1966 Shop-Storage

System: B3010130 - Preformed Metal Roofing




Note:

System: C3010 - Wall Finishes



Note:


System: C3020 - Floor Finishes



Note:

Campus Assessment Report - 1966 Shop-Storage

System: C3030 - Ceiling Finishes




Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$352,719	\$0	\$0	\$325,306	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$678,025
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$71,636	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$71,636
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$109,544	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$109,544
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$46,190	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$46,190
C3020 - Floor Finishes	\$172,223	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$172,223
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$169,573	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$169,573
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$29,614	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$29,614
D5020 - Lighting	\$79,246	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$79,246

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$352,719.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2030	Exterior Doors	\$0.00	\$0.00	\$71,636.00	\$0.00	\$0.00	\$71,636.00
C3020	Floor Finishes	\$0.00	\$0.00	\$172,223.00	\$0.00	\$0.00	\$172,223.00
D5020	Branch Wiring	\$0.00	\$0.00	\$29,614.00	\$0.00	\$0.00	\$29,614.00
D5020	Lighting	\$0.00	\$0.00	\$79,246.00	\$0.00	\$0.00	\$79,246.00
	Total:	\$0.00	\$0.00	\$352,719.00	\$0.00	\$0.00	\$352,719.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$352,719.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B2030 - Exterior Doors



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 7,520.00
Unit of Measure: S.F.
Estimate: \$71,636.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The original exterior doors are aged, rusted, and should be replaced.

System: C3020 - Floor Finishes



Location: Portions of building
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 7,520.00
Unit of Measure: S.F.
Estimate: \$172,223.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The carpet is stained, showing signs of early failure and should be replaced.

System: D5020 - Branch Wiring



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 7,520.00
Unit of Measure: S.F.
Estimate: \$29,614.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The original branch wiring system is operating, but is aged, in poor condition, and should be replaced.

System: D5020 - Lighting



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 7,520.00
Unit of Measure: S.F.
Estimate: \$79,246.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The original lighting system is operating, but is aged, in poor condition, and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	3,762
Year Built:	1982
Last Renovation:	
Replacement Value:	\$659,330
Repair Cost:	\$253,135.00
Total FCI:	38.39 %
Total RSLI:	32.06 %
FCA Score:	61.61







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	3,762
Year Built:	1982	Last Renovation:	
Repair Cost:	\$253,135	Replacement Value:	\$659,330
FCI:	38.39 %	RSLI%:	32.06 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	65.00 %	0.00 %	\$0.00
B10 - Superstructure	65.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	30.85 %	57.80 %	\$43,162.00
B30 - Roofing	40.00 %	0.00 %	\$0.00
C10 - Interior Construction	35.60 %	0.00 %	\$0.00
C30 - Interior Finishes	4.44 %	97.79 %	\$92,489.00
D20 - Plumbing	2.40 %	90.20 %	\$47,507.00
D30 - HVAC	65.45 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	110.00 %	\$20,650.00
D50 - Electrical	23.96 %	46.09 %	\$49,327.00
E10 - Equipment	65.00 %	0.00 %	\$0.00
E20 - Furnishings	15.00 %	0.00 %	\$0.00
Totals:	32.06 %	38.39 %	\$253,135.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). West Elevation - Jan 11, 2017



2). North Elevation - Jan 11, 2017



3). East Elevation - Jan 11, 2017



4). South Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.79	S.F.	3,762	100	1982	2082		65.00 %	0.00 %	65			\$18,020
A1030	Slab on Grade	\$8.43	S.F.	3,762	100	1982	2082		65.00 %	0.00 %	65			\$31,714
B1010	Floor Construction	\$1.64	S.F.	3,762	100	1982	2082		65.00 %	0.00 %	65			\$6,170
B1020	Roof Construction	\$15.76	S.F.	3,762	100	1982	2082		65.00 %	0.00 %	65			\$59,289
B2010	Exterior Walls	\$9.42	S.F.	3,762	100	1982	2082		65.00 %	0.00 %	65			\$35,438
B2020	Exterior Windows	\$9.39	S.F.	3,762	30	1982	2012		0.00 %	110.00 %	-5		\$38,858.00	\$35,325
B2030	Exterior Doors	\$1.04	S.F.	3,762	30	1982	2012		0.00 %	110.02 %	-5		\$4,304.00	\$3,912
B3010130	Preformed Metal Roofing	\$9.66	S.F.	3,762	30	1999	2029		40.00 %	0.00 %	12			\$36,341
C1010	Partitions	\$10.80	S.F.	3,762	75	1982	2057		53.33 %	0.00 %	40			\$40,630
C1020	Interior Doors	\$2.53	S.F.	3,762	20	1982	2002	2021	20.00 %	0.00 %	4			\$9,518
C1030	Fittings	\$9.74	S.F.	3,762	20	1982	2002	2021	20.00 %	0.00 %	4			\$36,642
C3010	Wall Finishes	\$2.79	S.F.	3,762	10	2011	2021		40.00 %	0.00 %	4			\$10,496
C3020	Floor Finishes	\$11.38	S.F.	3,762	20	1982	2002		0.00 %	110.00 %	-15		\$47,093.00	\$42,812
C3030	Ceiling Finishes	\$10.97	S.F.	3,762	25	1982	2007		0.00 %	110.00 %	-10		\$45,396.00	\$41,269
D2010	Plumbing Fixtures	\$11.48	S.F.	3,762	30	1982	2012		0.00 %	110.00 %	-5		\$47,507.00	\$43,188
D2020	Domestic Water Distribution	\$0.98	S.F.	3,762	30	1982	2012	2021	13.33 %	0.00 %	4			\$3,687
D2030	Sanitary Waste	\$1.54	S.F.	3,762	30	1982	2012	2021	13.33 %	0.00 %	4			\$5,793
D3030	Cooling Generating Systems	\$5.27	S.F.	3,762	25	2008	2033		64.00 %	0.00 %	16			\$19,826
D3040	Distribution Systems	\$6.14	S.F.	3,762	30	2008	2038		70.00 %	0.00 %	21			\$23,099
D3060	Controls & Instrumentation	\$1.94	S.F.	3,762	20	2008	2028		55.00 %	0.00 %	11			\$7,298
D4010	Sprinklers	\$4.32	S.F.	3,762	30			2017	0.00 %	110.00 %	0		\$17,877.00	\$16,252
D4020	Standpipes	\$0.67	S.F.	3,762	30			2017	0.00 %	110.00 %	0		\$2,773.00	\$2,521
D5010	Electrical Service/Distribution	\$1.69	S.F.	3,762	40	1982	2022		12.50 %	0.00 %	5			\$6,358
D5020	Branch Wiring	\$5.06	S.F.	3,762	30	1982	2012	2021	13.33 %	0.00 %	4			\$19,036
D5020	Lighting	\$11.92	S.F.	3,762	30	1982	2012		0.00 %	110.00 %	-5		\$49,327.00	\$44,843
D5030810	Security & Detection Systems	\$1.87	S.F.	3,762	15	2012	2027		66.67 %	0.00 %	10			\$7,035
D5030910	Fire Alarm Systems	\$3.39	S.F.	3,762	15	2012	2027		66.67 %	0.00 %	10			\$12,753
D5030920	Data Communication	\$4.40	S.F.	3,762	15	2010	2025		53.33 %	0.00 %	8			\$16,553
D5090	Other Electrical Systems	\$0.12	S.F.	3,762	20	2010	2030		65.00 %	0.00 %	13			\$451
E1020	Institutional Equipment	\$0.30	S.F.	3,762	20	2010	2030		65.00 %	0.00 %	13			\$1,129
E2010	Fixed Furnishings	\$5.83	S.F.	3,762	20	1982	2002	2020	15.00 %	0.00 %	3			\$21,932
Total									32.06 %	38.39 %			\$253,135.00	\$659,330

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1020 - Roof Construction



Note:

System: B2010 - Exterior Walls



Note:


System: B2020 - Exterior Windows



Note:

Campus Assessment Report - 1982 Media Center

System: B2030 - Exterior Doors



Note:

System: B3010130 - Preformed Metal Roofing



Note:

System: C1010 - Partitions



Note:

Campus Assessment Report - 1982 Media Center

System: C1020 - Interior Doors



Note:

System: C1030 - Fittings



Note:



System: C3010 - Wall Finishes



Note:

Campus Assessment Report - 1982 Media Center

System: C3020 - Floor Finishes




Note:

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

Campus Assessment Report - 1982 Media Center

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

System: D3030 - Cooling Generating Systems



Note:

Campus Assessment Report - 1982 Media Center

System: D3040 - Distribution Systems





Note:

System: D3060 - Controls & Instrumentation



Note:


System: D5010 - Electrical Service/Distribution



Note:



Campus Assessment Report - 1982 Media Center

System: D5020 - Branch Wiring




Note:

System: D5020 - Lighting



Note:

System: D5030810 - Security & Detection Systems



Note:

Campus Assessment Report - 1982 Media Center

System: D5030910 - Fire Alarm Systems



Note:

System: D5030920 - Data Communication



Note:

System: D5090 - Other Electrical Systems



Note:

Campus Assessment Report - 1982 Media Center

System: E1020 - Institutional Equipment



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$253,135	\$0	\$0	\$26,363	\$105,448	\$8,108	\$0	\$0	\$23,065	\$0	\$29,252	\$445,371
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$38,858	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$38,858
B2030 - Exterior Doors	\$4,304	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,304
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$11,784	\$0	\$0	\$0	\$0	\$0	\$0	\$11,784
C1030 - Fittings	\$0	\$0	\$0	\$0	\$45,365	\$0	\$0	\$0	\$0	\$0	\$0	\$45,365
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$12,995	\$0	\$0	\$0	\$0	\$0	\$0	\$12,995
C3020 - Floor Finishes	\$47,093	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$47,093
C3030 - Ceiling Finishes	\$45,396	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$45,396
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1982 Media Center

D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$47,507	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$47,507
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$4,564	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,564
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$7,173	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$7,173
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$17,877	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$17,877
D4020 - Standpipes	\$2,773	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,773
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$8,108	\$0	\$0	\$0	\$0	\$0	\$0	\$8,108
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$23,567	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$23,567
D5020 - Lighting	\$49,327	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$49,327
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$10,399	\$10,399
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$18,852	\$18,852
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$23,065	\$0	\$0	\$0	\$23,065
D5090 - Other Electrical Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$26,363	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$26,363

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$253,135.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2020	Exterior Windows	\$0.00	\$0.00	\$38,858.00	\$0.00	\$0.00	\$38,858.00
B2030	Exterior Doors	\$0.00	\$0.00	\$4,304.00	\$0.00	\$0.00	\$4,304.00
C3020	Floor Finishes	\$0.00	\$0.00	\$47,093.00	\$0.00	\$0.00	\$47,093.00
C3030	Ceiling Finishes	\$0.00	\$0.00	\$45,396.00	\$0.00	\$0.00	\$45,396.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$47,507.00	\$0.00	\$0.00	\$47,507.00
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$17,877.00	\$0.00	\$17,877.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$2,773.00	\$0.00	\$2,773.00
D5020	Lighting	\$0.00	\$0.00	\$49,327.00	\$0.00	\$0.00	\$49,327.00
	Total:	\$0.00	\$0.00	\$232,485.00	\$20,650.00	\$0.00	\$253,135.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$253,135.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B2020 - Exterior Windows



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 3,762.00
Unit of Measure: S.F.
Estimate: \$38,858.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The aluminum frame, operable, single pane windows are aged, rusted, not energy efficient, and should be replaced.

System: B2030 - Exterior Doors



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 3,762.00
Unit of Measure: S.F.
Estimate: \$4,304.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The original exterior doors are aged, rusted, and should be replaced.

System: C3020 - Floor Finishes



Location: Media center
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 3,762.00
Unit of Measure: S.F.
Estimate: \$47,093.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The carpet is aged, stained, frayed, and should be replaced.

System: C3030 - Ceiling Finishes



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 3,762.00
Unit of Measure: S.F.
Estimate: \$45,396.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The original ceiling finishes are aged, failing and should be replaced.


System: D2010 - Plumbing Fixtures



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Accessibility Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 3,762.00
Unit of Measure: S.F.
Estimate: \$47,507.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: Plumbing fixtures are in operational conditions. However, they are aged, not ADA compliant and should be replaced with a low-flow water fixtures.

System: D5020 - Lighting



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 3,762.00
Unit of Measure: S.F.
Estimate: \$49,327.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The original lighting system is operating, but is aged, in poor condition, and should be replaced with energy savings models.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 3,762.00
Unit of Measure: S.F.
Estimate: \$17,877.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 3,762.00
Unit of Measure: S.F.
Estimate: \$2,773.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	HS -High School
Gross Area (SF):	54,896
Year Built:	1951
Last Renovation:	
Replacement Value:	\$1,644,137
Repair Cost:	\$680,546.00
Total FCI:	41.39 %
Total RSLI:	13.96 %
FCA Score:	58.61







Description:

The narrative for this site is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	HS -High School	Gross Area:	54,896
Year Built:	1951	Last Renovation:	
Repair Cost:	\$680,546	Replacement Value:	\$1,644,137
FCI:	41.39 %	RSLI%:	13.96 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	3.12 %	63.56 %	\$591,779.00
G30 - Site Mechanical Utilities	30.00 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	24.74 %	34.70 %	\$88,767.00
Totals:	13.96 %	41.39 %	\$680,546.00

Photo Album

The photo album consists of the various cardinal directions of the building..

- 1). Aerial Image of Shaw Academy - Feb 24, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$3.81	S.F.	54,896	25	1982	2007		0.00 %	110.00 %	-10		\$230,069.00	\$209,154
G2020	Parking Lots	\$1.33	S.F.	54,896	25	1982	2007		0.00 %	110.00 %	-10		\$80,313.00	\$73,012
G2030	Pedestrian Paving	\$1.91	S.F.	54,896	30	1982	2012		0.00 %	110.00 %	-5		\$115,337.00	\$104,851
G2040105	Fence & Guardrails	\$1.23	S.F.	54,896	30	1982	2012		0.00 %	110.00 %	-5		\$74,274.00	\$67,522
G2040950	Covered Walkways	\$1.52	S.F.	54,896	25	1991	2016		0.00 %	110.00 %	-1		\$91,786.00	\$83,442
G2040950	Hard Surface Play Area	\$0.75	S.F.	54,896	20	1999	2019		10.00 %	0.00 %	2			\$41,172
G2040950	Playing Field	\$4.54	S.F.	54,896	20	1999	2019		10.00 %	0.00 %	2			\$249,228
G2050	Landscaping	\$1.87	S.F.	54,896	15	1999	2014		0.00 %	0.00 %	-3			\$102,656
G3010	Water Supply	\$2.34	S.F.	54,896	50	1982	2032		30.00 %	0.00 %	15			\$128,457
G3020	Sanitary Sewer	\$1.45	S.F.	54,896	50	1982	2032		30.00 %	0.00 %	15			\$79,599
G3030	Storm Sewer	\$4.54	S.F.	54,896	50	1982	2032		30.00 %	0.00 %	15			\$249,228
G4010	Electrical Distribution	\$2.35	S.F.	54,896	50	1982	2032		30.00 %	0.00 %	15			\$129,006
G4020	Site Lighting	\$1.47	S.F.	54,896	30	1982	2012		0.00 %	110.00 %	-5		\$88,767.00	\$80,697
G4030	Site Communications & Security	\$0.84	S.F.	54,896	15	2010	2025		53.33 %	0.00 %	8			\$46,113
Total									13.96 %	41.39 %			\$680,546.00	\$1,644,137

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: G2010 - Roadways



Note:

System: G2020 - Parking Lots



Note:

System: G2030 - Pedestrian Paving



Note:

Campus Assessment Report - Site

System: G2040105 - Fence & Guardrails



Note:

System: G2040950 - Covered Walkways



Note:

System: G2040950 - Hard Surface Play Area



Note:

Campus Assessment Report - Site

System: G2040950 - Playing Field



Note:

System: G2050 - Landscaping



Note:

System: G3010 - Water Supply



Note:

Campus Assessment Report - Site

System: G3020 - Sanitary Sewer



Note:

System: G3030 - Storm Sewer



Note:

System: G4010 - Electrical Distribution



Note:

Campus Assessment Report - Site

System: G4020 - Site Lighting



Note:

System: G4030 - Site Communications & Security



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$680,546	\$0	\$338,894	\$0	\$0	\$0	\$0	\$0	\$64,256	\$0	\$0	\$1,083,696
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$230,069	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$230,069
G2020 - Parking Lots	\$80,313	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$80,313
G2030 - Pedestrian Paving	\$115,337	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$115,337
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040105 - Fence & Guardrails	\$74,274	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$74,274
G2040950 - Covered Walkways	\$91,786	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$91,786
G2040950 - Hard Surface Play Area	\$0	\$0	\$48,047	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$48,047
G2040950 - Playing Field	\$0	\$0	\$290,847	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$290,847
* G2050 - Landscaping	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3020 - Sanitary Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3030 - Storm Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$88,767	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$88,767
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$64,256	\$0	\$0	\$64,256

** Indicates non-renewable system*


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$680,546.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$680,546.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
G2010	Roadways	\$0.00	\$0.00	\$230,069.00	\$0.00	\$0.00	\$230,069.00
G2020	Parking Lots	\$0.00	\$0.00	\$80,313.00	\$0.00	\$0.00	\$80,313.00
G2030	Pedestrian Paving	\$0.00	\$0.00	\$115,337.00	\$0.00	\$0.00	\$115,337.00
G2040105	Fence & Guardrails	\$0.00	\$0.00	\$74,274.00	\$0.00	\$0.00	\$74,274.00
G2040950	Covered Walkways	\$0.00	\$0.00	\$91,786.00	\$0.00	\$0.00	\$91,786.00
G4020	Site Lighting	\$0.00	\$0.00	\$88,767.00	\$0.00	\$0.00	\$88,767.00
	Total:	\$0.00	\$0.00	\$680,546.00	\$0.00	\$0.00	\$680,546.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$680,546.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: G2010 - Roadways



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance / Building Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 54,896.00
Unit of Measure: S.F.
Estimate: \$230,069.00
Assessor Name: Eduardo Lopez
Date Created: 01/11/2017

Notes: The asphaltic roadway is aged, has many road cuts and repairs, and should be re-surfaced. Provide Fire lane markings per Local Code requirements.

System: G2020 - Parking Lots



Location: Parking
Distress: Beyond Service Life
Category: Deferred Maintenance / Accessibility Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 54,896.00
Unit of Measure: S.F.
Estimate: \$80,313.00
Assessor Name: Eduardo Lopez
Date Created: 01/11/2017

Notes: The parking lot is aged, has many repairs and potholes, and should be replaced and re-striped. ADA signs height needs to be adjusted per minimum ADA standards.

System: G2030 - Pedestrian Paving



Location: Entire site
Distress: Beyond Service Life
Category: Deferred Maintenance / Accessibility Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 54,896.00
Unit of Measure: S.F.
Estimate: \$115,337.00
Assessor Name: Eduardo Lopez
Date Created: 01/11/2017

Notes: The pedestrian paving and walkways are aged and showing inclement weather damage and should be replaced to include missing ADA standard markings and ramps.

System: G2040105 - Fence & Guardrails



Location: Parking/roadways
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 54,896.00
Unit of Measure: S.F.
Estimate: \$74,274.00
Assessor Name: Eduardo Lopez
Date Created: 01/11/2017

Notes: The fence and guardrails are failing, beyond expected life, and not longer an effective barrier and should be scheduled for replacement.

Campus Assessment Report - Site

System: G2040950 - Covered Walkways



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 54,896.00
Unit of Measure: S.F.
Estimate: \$91,786.00
Assessor Name: Eduardo Lopez
Date Created: 01/11/2017

Notes: The covered walkways are rusted, failing and beyond expected life and should be scheduled for replacement.

System: G4020 - Site Lighting



Location: Entire site
Distress: Inadequate
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 54,896.00
Unit of Measure: S.F.
Estimate: \$88,767.00
Assessor Name: Eduardo Lopez
Date Created: 01/11/2017

Notes: Site Lighting is aged and does not adequately cover all areas and should be replaced.

NC School District/830 Scotland County/Middle School

Carver Middle

Draft

Campus Assessment Report

March 8, 2017



Table of Contents

Campus Executive Summary	4
Campus Dashboard Summary	7
Campus Condition Summary	8
<u>2000 Main</u>	10
Executive Summary	10
Dashboard Summary	11
Condition Summary	12
Photo Album	13
Condition Detail	14
System Listing	15
System Notes	17
Renewal Schedule	28
Forecasted Sustainment Requirement	30
Deficiency Summary By System	31
Deficiency Summary By Priority	32
Deficiency By Priority Investment	33
Deficiency Summary By Category	34
Deficiency Details By Priority	35
<u>Site</u>	37
Executive Summary	37
Dashboard Summary	38
Condition Summary	39
Photo Album	40
Condition Detail	41
System Listing	42
System Notes	43
Renewal Schedule	48
Forecasted Sustainment Requirement	49
Deficiency Summary By System	50

Campus Assessment Report

Deficiency Summary By Priority	51
Deficiency By Priority Investment	52
Deficiency Summary By Category	53
Deficiency Details By Priority	54

Campus Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	88,486
Year Built:	2000
Last Renovation:	
Replacement Value:	\$20,678,221
Repair Cost:	\$1,553,460.00
Total FCI:	7.51 %
Total RSLI:	43.28 %
FCA Score:	92.49



Description:

GENERAL:

Carver Middle School is located at 18601 Fieldcrest Rd in Laurel Hill, North Carolina. The 1 story, 88,486 square foot building was originally constructed in 2000 There have been no additions.

This report contains condition and adequacy data collected during the 2017 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for the site and building elements.

A. SUBSTRUCTURE

The building rests on slab-on grade and is assumed to have standard cast-in-place concrete foundations. The building does not have a basement .

Campus Assessment Report - Carver Middle

B. SUPERSTRUCTURE

Floor construction is concrete. Roof construction is steel. The exterior envelope is composed of walls of brick veneer over CMU. Exterior windows are aluminum frame with operable panes. Exterior doors are hollow metal steel mostly with glazing. Roofing is typically pitched standing seam metal. Most building entrances appear to comply with ADA requirements. Roof openings include skylights and roof hatch doors.

C. INTERIORS

Interior partitions are typically CMU. Interior doors are generally solid core wood with hollow steel frames and mostly with glazing. Interior fittings include the following items: white boards, graphics and identifying devices, toilet accessories, storage shelving, handrails, fabricated toilet partitions. The interior wall finishes are typically painted CMU. Floor finishes in common areas are typically vinyl composition tile. Floor finishes in assignable spaces is typically vinyl composition tile. Ceiling finishes in common areas are typically suspended acoustical tile. Ceiling finishes in assignable areas are typically suspended acoustical tile.

CONVEYING:

The building does not include conveying equipment. Conveying equipment includes no hydraulic elevators, and no wheelchair lifts.

D. SERVICES

PLUMBING:

Plumbing fixtures are typically non-low-flow water fixtures with manual control valves. Domestic water distribution is combination of copper and galvanized steel with gas hot water heating. Sanitary waste system is plastic. Rain water drainage system is external.

HVAC:

Heating is provided by 1 gas fired boilers. Cooling is supplied by 1 air cooled chillers. The heating/cooling distribution system is a ductwork system utilizing air handling units. Fresh air is supplied by air handling units. Ceiling mounted exhaust fans are installed in bathrooms and other required areas. Controls and instrumentation are digital and are centrally controlled and monitored by an energy management system. This building has a remote Building Automation System.

FIRE PROTECTION:

The building does not have a fire sprinkler system. The building does have additional fire suppression system in the kitchen. Standpipes are not included within fire stairs. Fire extinguishers and cabinets are distributed near fire exits and corridors.

ELECTRICAL:

The main electrical service is fed from a pad mounted transformer to the main switchboard/distribution panel located in the building. Lighting is lay-in, recessed and surface type, fluorescent and LED light fixtures. Branch circuit wiring is typically copper serving electrical switches and receptacles. Emergency and life safety egress lighting systems are installed and exit signs are present at exit doors and near stairways and are typically illuminated.

COMMUNICATIONS AND SECURITY:

The fire alarm system consists of audible/visual strobe annunciators in common spaces, balconies and interior corridors. The system is activated by manual pull stations and smoke detectors and the system is centrally monitored. The telephone and data systems are segregated and include dedicated equipment closets. This building does have a local area network (LAN). The building includes an internal security system that is actuated by the following items: contacts, infrared, optical or a combination of all devices. The building has controlled entry doors access provided by card readers; entry doors are secured with magnetic door locks. The security system has CCTV cameras and is centrally monitored; this building has a public address and paging system separate from the telephone system.

OTHER ELECTRICAL SYSTEMS:

This building does not have a separately derived emergency power system.

E. EQUIPMENT & FURNISHINGS:

This building includes the following items and equipment: fixed food service, library equipment, athletic equipment, theater and stage, audio-visual, fixed casework, window treatment, floor grilles and mats, and multiple seating furnishings.

G.

SITE

Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, play areas, and fencing. Site mechanical and electrical features include water, sewer, natural gas, and site lighting.

Campus Assessment Report - Carver Middle

Attributes:

General Attributes:





Condition Assessor: Matt Mahaffey Assessment Date:
Suitability Assessor:

School Information:

HS Attendance Area:		LEA School No.:	
No. of Mobile Units:	0	No. of Bldgs.:	1
SF of Mobile Units:		Status:	
School Grades:	20	Site Acreage:	20

Campus Dashboard Summary

Gross Area:	88,486	Last Renovation:	
Year Built:	2000	Replacement Value:	\$20,678,221
Repair Cost:	\$1,553,460	RSLI%:	43.28 %
FCI:	7.51 %		



Campus Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Unifomat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	83.00 %	0.00 %	\$0.00
B10 - Superstructure	83.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	60.74 %	0.00 %	\$0.00
B30 - Roofing	42.37 %	0.00 %	\$0.00
C10 - Interior Construction	35.71 %	0.00 %	\$0.00
C30 - Interior Finishes	12.88 %	49.77 %	\$1,106,694.00
D20 - Plumbing	43.51 %	0.00 %	\$0.00
D30 - HVAC	37.13 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	110.00 %	\$446,766.00
D50 - Electrical	61.26 %	0.00 %	\$0.00
E10 - Equipment	15.00 %	0.00 %	\$0.00
E20 - Furnishings	15.00 %	0.00 %	\$0.00
G20 - Site Improvements	20.59 %	0.00 %	\$0.00
G30 - Site Mechanical Utilities	66.00 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	62.74 %	0.00 %	\$0.00
Totals:	43.28 %	7.51 %	\$1,553,460.00

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance
2000 Main	88,486	8.86	\$0.00	\$0.00	\$0.00	\$1,553,460.00	\$0.00
Site	88,486	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
Total:		7.51	\$0.00	\$0.00	\$0.00	\$1,553,460.00	\$0.00

Deficiencies By Priority



- 1 - Currently Critical (Immediate)
- 2 - Potentially Critical (Year 1)
- 3 - Necessary/Not Yet Critical (Years 2-5)
- 4 - Recommended (Years 6-10) - \$1,553,460.00
- 5 - Codes or Standards Compliance

Budget Estimate Total: \$1,553,460.00

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	MS -Middle School
Gross Area (SF):	88,486
Year Built:	2000
Last Renovation:	
Replacement Value:	\$17,531,657
Repair Cost:	\$1,553,460.00
Total FCI:	8.86 %
Total RSLI:	44.31 %
FCA Score:	91.14







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	MS -Middle School	Gross Area:	88,486
Year Built:	2000	Last Renovation:	
Repair Cost:	\$1,553,460	Replacement Value:	\$17,531,657
FCI:	8.86 %	RSLI%:	44.31 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	83.00 %	0.00 %	\$0.00
B10 - Superstructure	83.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	60.74 %	0.00 %	\$0.00
B30 - Roofing	42.37 %	0.00 %	\$0.00
C10 - Interior Construction	35.71 %	0.00 %	\$0.00
C30 - Interior Finishes	12.88 %	49.77 %	\$1,106,694.00
D20 - Plumbing	43.51 %	0.00 %	\$0.00
D30 - HVAC	37.13 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	110.00 %	\$446,766.00
D50 - Electrical	61.26 %	0.00 %	\$0.00
E10 - Equipment	15.00 %	0.00 %	\$0.00
E20 - Furnishings	15.00 %	0.00 %	\$0.00
Totals:	44.31 %	8.86 %	\$1,553,460.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). West Elevation - Jan 11, 2017



2). North Elevation - Jan 11, 2017



3). East Elevation - Jan 11, 2017



4). South Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.



Campus Assessment Report - 2000 Main

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$1.52	S.F.	88,486	100	2000	2100		83.00 %	0.00 %	83			\$134,499
A1030	Slab on Grade	\$4.40	S.F.	88,486	100	2000	2100		83.00 %	0.00 %	83			\$389,338
B1010	Floor Construction	\$12.43	S.F.	88,486	100	2000	2100		83.00 %	0.00 %	83			\$1,099,881
B1020	Roof Construction	\$8.18	S.F.	88,486	100	2000	2100		83.00 %	0.00 %	83			\$723,815
B2010	Exterior Walls	\$9.02	S.F.	88,486	100	2000	2100		83.00 %	0.00 %	83			\$798,144
B2020	Exterior Windows	\$10.52	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$930,873
B2030	Exterior Doors	\$1.02	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$90,256
B3010120	Single Ply Membrane	\$6.98	S.F.	3,000	20	2000	2020		15.00 %	0.00 %	3			\$20,940
B3010130	Preformed Metal Roofing	\$9.66	S.F.	85,486	30	2000	2030		43.33 %	0.00 %	13			\$825,795
B3020	Roof Openings	\$0.24	S.F.	88,486	25	2000	2025		32.00 %	0.00 %	8			\$21,237
C1010	Partitions	\$6.07	S.F.	88,486	75	2000	2075		77.33 %	0.00 %	58			\$537,110
C1020	Interior Doors	\$2.46	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$217,676
C1030	Fittings	\$13.11	S.F.	88,486	20	2000	2020		15.00 %	0.00 %	3			\$1,160,051
C3010	Wall Finishes	\$3.35	S.F.	88,486	10	2012	2022		50.00 %	0.00 %	5			\$296,428
C3020	Floor Finishes	\$10.41	S.F.	88,486	20	2000	2020		15.00 %	0.00 %	3			\$921,139
C3030	Ceiling Finishes	\$11.37	S.F.	88,486	25	2000	2025	2017	0.00 %	110.00 %	0		\$1,106,694.00	\$1,006,086
D2010	Plumbing Fixtures	\$9.64	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$853,005
D2020	Domestic Water Distribution	\$1.03	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$91,141
D2030	Sanitary Waste	\$1.62	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$143,347
D2040	Rain Water Drainage	\$0.59	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$52,207
D2090	Other Plumbing Systems -Nat Gas	\$0.16	S.F.	88,486	40	2000	2040		57.50 %	0.00 %	23			\$14,158
D3020	Heat Generating Systems	\$8.66	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$766,289
D3030	Cooling Generating Systems	\$8.99	S.F.	88,486	25	2000	2025		32.00 %	0.00 %	8			\$795,489
D3040	Distribution Systems	\$10.65	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$942,376
D3060	Controls & Instrumentation	\$3.33	S.F.	88,486	20	2000	2020		15.00 %	0.00 %	3			\$294,658
D4010	Sprinklers	\$3.92	S.F.	88,486	30			2017	0.00 %	110.00 %	0		\$381,552.00	\$346,865
D4020	Standpipes	\$0.67	S.F.	88,486	30			2017	0.00 %	110.00 %	0		\$65,214.00	\$59,286
D5010	Electrical Service/Distribution	\$1.64	S.F.	88,486	40	2000	2040		57.50 %	0.00 %	23			\$145,117
D5020	Branch Wiring	\$4.91	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$434,466
D5020	Lighting	\$11.44	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$1,012,280
D5030810	Security & Detection Systems	\$2.27	S.F.	88,486	15	2015	2030		86.67 %	0.00 %	13			\$200,863
D5030910	Fire Alarm Systems	\$4.11	S.F.	88,486	15	2015	2030		86.67 %	0.00 %	13			\$363,677
D5030920	Data Communication	\$5.32	S.F.	88,486	15	2015	2030		86.67 %	0.00 %	13			\$470,746
D5090	Other Electrical Systems	\$0.51	S.F.	88,486	20	2010	2030		65.00 %	0.00 %	13			\$45,128
E1020	Institutional Equipment	\$2.73	S.F.	88,486	20	2000	2020		15.00 %	0.00 %	3			\$241,567
E1090	Other Equipment	\$6.82	S.F.	88,486	20	2000	2020		15.00 %	0.00 %	3			\$603,475
E2010	Fixed Furnishings	\$5.45	S.F.	88,486	20	2000	2020		15.00 %	0.00 %	3			\$482,249
Total									44.31 %	8.86 %			\$1,553,460.00	\$17,531,657

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1020 - Roof Construction



Note:

System: B2010 - Exterior Walls



Note:


System: B2020 - Exterior Windows



Note:

Campus Assessment Report - 2000 Main

System: B2030 - Exterior Doors



Note:

System: B3010120 - Single Ply Membrane



Note:

System: B3010130 - Preformed Metal Roofing



Note:


Campus Assessment Report - 2000 Main

System: B3020 - Roof Openings




Note:

System: C1010 - Partitions



Note:


System: C1020 - Interior Doors



Note:


Campus Assessment Report - 2000 Main

System: C1030 - Fittings



Note:

System: C3010 - Wall Finishes



Note:


System: C3020 - Floor Finishes



Note:


Campus Assessment Report - 2000 Main

System: C3030 - Ceiling Finishes




Note:

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:

Campus Assessment Report - 2000 Main

System: D2030 - Sanitary Waste




Note:

System: D2040 - Rain Water Drainage



Note:

System: D2090 - Other Plumbing Systems -Nat Gas



Note:

Campus Assessment Report - 2000 Main

System: D3020 - Heat Generating Systems




Note:

System: D3030 - Cooling Generating Systems



Note:

System: D3040 - Distribution Systems



Note:

Campus Assessment Report - 2000 Main

System: D3060 - Controls & Instrumentation



Note:

System: D5010 - Electrical Service/Distribution



Note:


System: D5020 - Branch Wiring



Note:


Campus Assessment Report - 2000 Main

System: D5020 - Lighting



Note:

System: D5030810 - Security & Detection Systems



Note:


System: D5030910 - Fire Alarm Systems



Note:

Campus Assessment Report - 2000 Main

System: D5030920 - Data Communication



Note:

System: D5090 - Other Electrical Systems



Note:

System: E1020 - Institutional Equipment



Note:

Campus Assessment Report - 2000 Main

System: E1090 - Other Equipment



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$1,553,460	\$0	\$0	\$4,485,495	\$0	\$378,006	\$0	\$0	\$1,138,064	\$0	\$0	\$7,555,024
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$34,323	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$34,323
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$29,592	\$0	\$0	\$29,592
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$1,394,382	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,394,382
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$378,006	\$0	\$0	\$0	\$0	\$0	\$378,006
C3020 - Floor Finishes	\$0	\$0	\$0	\$1,107,209	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,107,209


Campus Assessment Report - 2000 Main

C3030 - Ceiling Finishes	\$1,106,694	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,106,694
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2090 - Other Plumbing Systems -Nat Gas	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,108,472	\$0	\$0	\$0	\$1,108,472
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$354,179	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$354,179
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$381,552	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$381,552
D4020 - Standpipes	\$65,214	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$65,214
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5090 - Other Electrical Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$290,363	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$290,363
E1090 - Other Equipment	\$0	\$0	\$0	\$725,376	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$725,376
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$579,663	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$579,663

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$1,553,460.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
C3030	Ceiling Finishes	\$0.00	\$0.00	\$0.00	\$1,106,694.00	\$0.00	\$1,106,694.00
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$381,552.00	\$0.00	\$381,552.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$65,214.00	\$0.00	\$65,214.00
	Total:	\$0.00	\$0.00	\$0.00	\$1,553,460.00	\$0.00	\$1,553,460.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:




Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 4 - Recommended (Years 6-10):

System: C3030 - Ceiling Finishes



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 88,486.00
Unit of Measure: S.F.
Estimate: \$1,106,694.00
Assessor Name: Eduardo Lopez
Date Created: 01/06/2017

Notes: Painted ceiling in gym is chipping and flaking and should be repainted. The ceiling tiles have been replaced as needed. However the grid shows signs of aging and most tiles are sagging or damaged and should be replaced.

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 88,486.00
Unit of Measure: S.F.
Estimate: \$381,552.00
Assessor Name: Eduardo Lopez
Date Created: 01/06/2017

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 88,486.00
Unit of Measure: S.F.
Estimate: \$65,214.00
Assessor Name: Eduardo Lopez
Date Created: 01/06/2017

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	MS -Middle School
Gross Area (SF):	88,486
Year Built:	2000
Last Renovation:	
Replacement Value:	\$3,146,564
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	37.50 %
FCA Score:	100.00



Description:

The narrative for this site is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	MS -Middle School	Gross Area:	88,486
Year Built:	2000	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$3,146,564
FCI:	0.00 %	RSLI%:	37.50 %

No data found for this asset

No data found for this asset

No data found for this asset

10 Year Investment Forecast



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	20.59 %	0.00 %	\$0.00
G30 - Site Mechanical Utilities	66.00 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	62.74 %	0.00 %	\$0.00
Totals:	37.50 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

- 1). Aerial Image of Caver Middle School - Feb 24, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$4.22	S.F.	88,486	25	2000	2025		32.00 %	0.00 %	8			\$373,411
G2020	Parking Lots	\$1.39	S.F.	88,486	25	2000	2025		32.00 %	0.00 %	8			\$122,996
G2030	Pedestrian Paving	\$1.98	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$175,202
G2040950	Baseball Field	\$7.08	S.F.	88,486	20	2000	2020		15.00 %	0.00 %	3			\$626,481
G2040950	Football Field	\$4.73	S.F.	88,486	20	2000	2020		15.00 %	0.00 %	3			\$418,539
G2040950	Hard Surface Play Area	\$0.65	S.F.	88,486	20	2000	2020		15.00 %	0.00 %	3			\$57,516
G2050	Landscaping	\$1.91	S.F.	88,486	15	2000	2015		0.00 %	0.00 %	-2			\$169,008
G3010	Water Supply	\$2.42	S.F.	88,486	50	2000	2050		66.00 %	0.00 %	33			\$214,136
G3020	Sanitary Sewer	\$1.52	S.F.	88,486	50	2000	2050		66.00 %	0.00 %	33			\$134,499
G3030	Storm Sewer	\$4.67	S.F.	88,486	50	2000	2050		66.00 %	0.00 %	33			\$413,230
G4010	Electrical Distribution	\$2.59	S.F.	88,486	50	2000	2050		66.00 %	0.00 %	33			\$229,179
G4020	Site Lighting	\$1.52	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$134,499
G4030	Site Communications & Security	\$0.88	S.F.	88,486	15	2015	2030		86.67 %	0.00 %	13			\$77,868
Total									37.50 %					\$3,146,564

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: G2010 - Roadways



Note:

System: G2020 - Parking Lots



Note:

System: G2030 - Pedestrian Paving



Note:

Campus Assessment Report - Site

System: G2040950 - Baseball Field



Note:

System: G2040950 - Football Field



Note:

System: G2040950 - Hard Surface Play Area



Note:

Campus Assessment Report - Site

System: G2050 - Landscaping



Note:

System: G3010 - Water Supply



Note:

System: G3020 - Sanitary Sewer



Note:

Campus Assessment Report - Site

System: G3030 - Storm Sewer



Note:

System: G4010 - Electrical Distribution



Note:

System: G4020 - Site Lighting



Note:

Campus Assessment Report - Site

System: G4030 - Site Communications & Security



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$0	\$1,325,247	\$0	\$0	\$0	\$0	\$691,716	\$0	\$0	\$2,016,963
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$520,328	\$0	\$0	\$520,328
G2020 - Parking Lots	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$171,388	\$0	\$0	\$171,388
G2030 - Pedestrian Paving	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040950 - Baseball Field	\$0	\$0	\$0	\$753,030	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$753,030
G2040950 - Football Field	\$0	\$0	\$0	\$503,084	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$503,084
G2040950 - Hard Surface Play Area	\$0	\$0	\$0	\$69,134	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$69,134
* G2050 - Landscaping	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3020 - Sanitary Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3030 - Storm Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

** Indicates non-renewable system*

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

NC School District/830 Scotland County/Middle School

Spring Hill Middle

Draft

Campus Assessment Report

March 7, 2017



Table of Contents

Campus Executive Summary	4
Campus Dashboard Summary	7
Campus Condition Summary	8
<u>2000 Main</u>	10
Executive Summary	10
Dashboard Summary	11
Condition Summary	12
Photo Album	13
Condition Detail	14
System Listing	15
System Notes	17
Renewal Schedule	28
Forecasted Sustainment Requirement	30
Deficiency Summary By System	31
Deficiency Summary By Priority	32
Deficiency By Priority Investment	33
Deficiency Summary By Category	34
Deficiency Details By Priority	35
<u>Site</u>	36
Executive Summary	36
Dashboard Summary	37
Condition Summary	38
Photo Album	39
Condition Detail	40
System Listing	41
System Notes	42
Renewal Schedule	47
Forecasted Sustainment Requirement	48
Deficiency Summary By System	49

Campus Assessment Report

Deficiency Summary By Priority	50
Deficiency By Priority Investment	51
Deficiency Summary By Category	52
Deficiency Details By Priority	53

Campus Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	88,486
Year Built:	2000
Last Renovation:	
Replacement Value:	\$20,861,387
Repair Cost:	\$446,766.00
Total FCI:	2.14 %
Total RSLI:	43.49 %
FCA Score:	97.86



Description:

GENERAL:

Spring Hill Middle School is located at 22801 Airbase Rd in Laurinburg, North Carolina. The 1 story, 88,486 square foot building was originally constructed in 2000 There have been no additions.

This report contains condition and adequacy data collected during the 2017 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for the site and building elements.

A. SUBSTRUCTURE

The building rests on slab-on grade and is assumed to have standard cast-in-place concrete foundations. The building does not have a basement .

Campus Assessment Report - Spring Hill Middle

B. SUPERSTRUCTURE

Floor construction is concrete. Roof construction is steel. The exterior envelope is composed of walls of brick veneer over CMU. Exterior windows are aluminum frame with operable panes. Exterior doors are hollow metal steel mostly with glazing. Roofing is typically pitched standing seam metal. Most building entrances appear to comply with ADA requirements. Roof openings include skylights and roof hatch doors.

C. INTERIORS

Interior partitions are typically CMU. Interior doors are generally solid core wood with hollow steel frames and mostly with glazing. Interior fittings include the following items: white boards, graphics and identifying devices, toilet accessories, storage shelving, handrails, fabricated toilet partitions. The interior wall finishes are typically painted CMU. Floor finishes in common areas are typically vinyl composition tile. Floor finishes in assignable spaces is typically vinyl composition tile. Ceiling finishes in common areas are typically suspended acoustical tile. Ceiling finishes in assignable areas are typically suspended acoustical tile.

CONVEYING:

The building does not include conveying equipment. Conveying equipment includes no hydraulic elevators, and no wheelchair lifts.

D. SERVICES

PLUMBING:

Plumbing fixtures are typically non-low-flow water fixtures with manual control valves. Domestic water distribution is combination of copper and galvanized steel with electric hot water heating. Sanitary waste system is plastic. Rain water drainage system is external.

HVAC:

Heating is provided by 1 gas fired boilers. Cooling is supplied by 1 air cooled chiller. The heating/cooling distribution system is a ductwork system utilizing air handling units. Fresh air is supplied by air handling units. Ceiling mounted exhaust fans are installed in bathrooms and other required areas. Controls and instrumentation are digital and are centrally controlled and monitored by an energy management system. This building has a remote Building Automation System.

FIRE PROTECTION:

The building does not have a fire sprinkler system. The building does have additional fire suppression system in the kitchen. Standpipes are not included within fire stairs. Fire extinguishers and cabinets are distributed near fire exits and corridors.

ELECTRICAL:

The main electrical service is fed from a pad mounted transformer to the main switchboard/distribution panel located in the building. Lighting is lay-in, recessed and surface type, fluorescent and LED light fixtures. Branch circuit wiring is typically copper serving electrical switches and receptacles. Emergency and life safety egress lighting systems are installed and exit signs are present at exit doors and near stairways and are typically illuminated.

COMMUNICATIONS AND SECURITY:

The fire alarm system consists of audible/visual strobe annunciators in common spaces, balconies and interior corridors. The system is activated by manual pull stations and smoke detectors and the system is centrally monitored. The telephone and data systems are segregated and include dedicated equipment closets. This building does have a local area network (LAN). The building includes an internal security system that is actuated by the following items: contacts, infrared, optical or a combination of all devices. The building has controlled entry doors access provided by card readers; entry doors are secured with magnetic door locks. The security system has CCTV cameras and is centrally monitored; this building has a public address and paging system separate from the telephone system.

OTHER ELECTRICAL SYSTEMS:

This building does not have a separately derived emergency power system.

E. EQUIPMENT & FURNISHINGS:

This building includes the following items and equipment: fixed food service, library equipment, athletic equipment, theater and stage, audio-visual, fixed casework, window treatment, floor grilles and mats, and multiple seating furnishings.

G.

SITE

Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, play areas, and fencing. Site mechanical and electrical features include water, sewer, and site lighting.

Campus Assessment Report - Spring Hill Middle

Attributes:

General Attributes:





Condition Assessor:	Matt Mahaffey	Assessment Date:	
Suitability Assessor:			

School Information:

HS Attendance Area:		LEA School No.:	
No. of Mobile Units:	0	No. of Bldgs.:	1
SF of Mobile Units:		Status:	
School Grades:	20	Site Acreage:	20

Campus Dashboard Summary

Gross Area:	88,486	Last Renovation:	
Year Built:	2000	Replacement Value:	\$20,861,387
Repair Cost:	\$446,766	RSLI%:	43.49 %
FCI:	2.14 %		



Campus Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Unifomat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	83.00 %	0.00 %	\$0.00
B10 - Superstructure	83.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	60.74 %	0.00 %	\$0.00
B30 - Roofing	42.37 %	0.00 %	\$0.00
C10 - Interior Construction	35.71 %	0.00 %	\$0.00
C30 - Interior Finishes	28.69 %	0.00 %	\$0.00
D20 - Plumbing	43.33 %	0.00 %	\$0.00
D30 - HVAC	37.13 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	110.00 %	\$446,766.00
D50 - Electrical	50.32 %	0.00 %	\$0.00
E10 - Equipment	15.00 %	0.00 %	\$0.00
E20 - Furnishings	15.00 %	0.00 %	\$0.00
G20 - Site Improvements	21.77 %	0.00 %	\$0.00
G30 - Site Mechanical Utilities	65.09 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	56.86 %	0.00 %	\$0.00
Totals:	43.49 %	2.14 %	\$446,766.00

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance
2000 Main	88,486	2.55	\$0.00	\$0.00	\$0.00	\$446,766.00	\$0.00
Site	88,486	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
Total:		2.14	\$0.00	\$0.00	\$0.00	\$446,766.00	\$0.00

Deficiencies By Priority



- 1 - Currently Critical (Immediate)
- 2 - Potentially Critical (Year 1)
- 3 - Necessary/Not Yet Critical (Years 2-5)
- 4 - Recommended (Years 6-10) - \$446,766.00
- 5 - Codes or Standards Compliance

Budget Estimate Total: \$446,766.00

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	MS -Middle School
Gross Area (SF):	88,486
Year Built:	2000
Last Renovation:	
Replacement Value:	\$17,517,499
Repair Cost:	\$446,766.00
Total FCI:	2.55 %
Total RSLI:	44.64 %
FCA Score:	97.45







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	MS -Middle School	Gross Area:	88,486
Year Built:	2000	Last Renovation:	
Repair Cost:	\$446,766	Replacement Value:	\$17,517,499
FCI:	2.55 %	RSLI%:	44.64 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	83.00 %	0.00 %	\$0.00
B10 - Superstructure	83.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	60.74 %	0.00 %	\$0.00
B30 - Roofing	42.37 %	0.00 %	\$0.00
C10 - Interior Construction	35.71 %	0.00 %	\$0.00
C30 - Interior Finishes	28.69 %	0.00 %	\$0.00
D20 - Plumbing	43.33 %	0.00 %	\$0.00
D30 - HVAC	37.13 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	110.00 %	\$446,766.00
D50 - Electrical	50.32 %	0.00 %	\$0.00
E10 - Equipment	15.00 %	0.00 %	\$0.00
E20 - Furnishings	15.00 %	0.00 %	\$0.00
Totals:	44.64 %	2.55 %	\$446,766.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). West Elevation - Jan 11, 2017



2). South Elevation - Jan 11, 2017



3). East Elevation - Jan 11, 2017



4). North Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.


Campus Assessment Report - 2000 Main

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$1.52	S.F.	88,486	100	2000	2100		83.00 %	0.00 %	83			\$134,499
A1030	Slab on Grade	\$4.40	S.F.	88,486	100	2000	2100		83.00 %	0.00 %	83			\$389,338
B1010	Floor Construction	\$12.43	S.F.	88,486	100	2000	2100		83.00 %	0.00 %	83			\$1,099,881
B1020	Roof Construction	\$8.18	S.F.	88,486	100	2000	2100		83.00 %	0.00 %	83			\$723,815
B2010	Exterior Walls	\$9.02	S.F.	88,486	100	2000	2100		83.00 %	0.00 %	83			\$798,144
B2020	Exterior Windows	\$10.52	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$930,873
B2030	Exterior Doors	\$1.02	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$90,256
B3010120	Single Ply Membrane	\$6.98	S.F.	3,000	20	2000	2020		15.00 %	0.00 %	3			\$20,940
B3010130	Preformed Metal Roofing	\$9.66	S.F.	85,486	30	2000	2030		43.33 %	0.00 %	13			\$825,795
B3020	Roof Openings	\$0.24	S.F.	88,486	25	2000	2025		32.00 %	0.00 %	8			\$21,237
C1010	Partitions	\$6.07	S.F.	88,486	75	2000	2075		77.33 %	0.00 %	58			\$537,110
C1020	Interior Doors	\$2.46	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$217,676
C1030	Fittings	\$13.11	S.F.	88,486	20	2000	2020		15.00 %	0.00 %	3			\$1,160,051
C3010	Wall Finishes	\$3.35	S.F.	88,486	10	2013	2023		60.00 %	0.00 %	6			\$296,428
C3020	Floor Finishes	\$10.41	S.F.	88,486	20	2000	2020		15.00 %	0.00 %	3			\$921,139
C3030	Ceiling Finishes	\$11.37	S.F.	88,486	25	2000	2025		32.00 %	0.00 %	8			\$1,006,086
D2010	Plumbing Fixtures	\$9.64	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$853,005
D2020	Domestic Water Distribution	\$1.03	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$91,141
D2030	Sanitary Waste	\$1.62	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$143,347
D2040	Rain Water Drainage	\$0.59	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$52,207
D3020	Heat Generating Systems	\$8.66	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$766,289
D3030	Cooling Generating Systems	\$8.99	S.F.	88,486	25	2000	2025		32.00 %	0.00 %	8			\$795,489
D3040	Distribution Systems	\$10.65	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$942,376
D3060	Controls & Instrumentation	\$3.33	S.F.	88,486	20	2000	2020		15.00 %	0.00 %	3			\$294,658
D4010	Sprinklers	\$3.92	S.F.	88,486	30			2017	0.00 %	110.00 %	0		\$381,552.00	\$346,865
D4020	Standpipes	\$0.67	S.F.	88,486	30			2017	0.00 %	110.00 %	0		\$65,214.00	\$59,286
D5010	Electrical Service/Distribution	\$1.64	S.F.	88,486	40	2000	2040		57.50 %	0.00 %	23			\$145,117
D5020	Branch Wiring	\$4.91	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$434,466
D5020	Lighting	\$11.44	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$1,012,280
D5030810	Security & Detection Systems	\$2.27	S.F.	88,486	15	2012	2027		66.67 %	0.00 %	10			\$200,863
D5030910	Fire Alarm Systems	\$4.11	S.F.	88,486	15	2012	2027		66.67 %	0.00 %	10			\$363,677
D5030920	Data Communication	\$5.32	S.F.	88,486	15	2010	2025		53.33 %	0.00 %	8			\$470,746
D5090	Other Electrical Systems	\$0.51	S.F.	88,486	20	2000	2020		15.00 %	0.00 %	3			\$45,128
E1020	Institutional Equipment	\$2.73	S.F.	88,486	20	2000	2020		15.00 %	0.00 %	3			\$241,567
E1090	Other Equipment	\$6.82	S.F.	88,486	20	2000	2020		15.00 %	0.00 %	3			\$603,475
E2010	Fixed Furnishings	\$5.45	S.F.	88,486	20	2000	2020		15.00 %	0.00 %	3			\$482,249
Total									44.64 %	2.55 %			\$446,766.00	\$17,517,499

System Notes



The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1020 - Roof Construction



Note:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

Campus Assessment Report - 2000 Main

System: B2030 - Exterior Doors



Note:

System: B3010120 - Single Ply Membrane



Note:

System: B3010130 - Preformed Metal Roofing



Note:

Campus Assessment Report - 2000 Main

System: B3020 - Roof Openings



Note:

System: C1010 - Partitions



Note:

System: C1020 - Interior Doors



Note:



Campus Assessment Report - 2000 Main

System: C1030 - Fittings





Note:

System: C3010 - Wall Finishes



Note:



System: C3020 - Floor Finishes



Note:

Campus Assessment Report - 2000 Main

System: C3030 - Ceiling Finishes




Note:

System: D2010 - Plumbing Fixtures



Note:


System: D2020 - Domestic Water Distribution



Note:

Campus Assessment Report - 2000 Main

System: D2030 - Sanitary Waste




Note:

System: D2040 - Rain Water Drainage



Note:

System: D3020 - Heat Generating Systems



Note:

Campus Assessment Report - 2000 Main

System: D3030 - Cooling Generating Systems



Note:

System: D3040 - Distribution Systems



Note:

System: D3060 - Controls & Instrumentation



Note:

Campus Assessment Report - 2000 Main

System: D5010 - Electrical Service/Distribution






Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Campus Assessment Report - 2000 Main

System: D5030810 - Security & Detection Systems




Note:

System: D5030910 - Fire Alarm Systems



Note:


System: D5030920 - Data Communication



Note:

Campus Assessment Report - 2000 Main

System: D5090 - Other Electrical Systems




Note:

System: E1020 - Institutional Equipment



Note:


System: E1090 - Other Equipment



Note:

Campus Assessment Report - 2000 Main

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$446,766	\$0	\$0	\$4,539,739	\$0	\$0	\$389,346	\$0	\$3,195,949	\$0	\$834,565	\$9,406,365
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$34,323	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$34,323
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$29,592	\$0	\$0	\$29,592
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$1,394,382	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,394,382
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$389,346	\$0	\$0	\$0	\$0	\$389,346
C3020 - Floor Finishes	\$0	\$0	\$0	\$1,107,209	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,107,209


Campus Assessment Report - 2000 Main

C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,401,927	\$0	\$0	\$1,401,927
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,108,472	\$0	\$0	\$1,108,472
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$354,179	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$354,179
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$381,552	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$381,552
D4020 - Standpipes	\$65,214	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$65,214
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$296,938	\$296,938
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$537,627	\$537,627
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$655,959	\$0	\$0	\$655,959
D5090 - Other Electrical Systems	\$0	\$0	\$0	\$54,244	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$54,244
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$290,363	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$290,363
E1090 - Other Equipment	\$0	\$0	\$0	\$725,376	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$725,376
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$579,663	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$579,663

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$446,766.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$381,552.00	\$0.00	\$381,552.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$65,214.00	\$0.00	\$65,214.00
	Total:	\$0.00	\$0.00	\$0.00	\$446,766.00	\$0.00	\$446,766.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 88,486.00
Unit of Measure: S.F.
Estimate: \$381,552.00
Assessor Name: Eduardo Lopez
Date Created: 01/12/2017

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 88,486.00
Unit of Measure: S.F.
Estimate: \$65,214.00
Assessor Name: Eduardo Lopez
Date Created: 01/12/2017

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	MS -Middle School
Gross Area (SF):	88,486
Year Built:	2000
Last Renovation:	
Replacement Value:	\$3,343,888
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	37.46 %
FCA Score:	100.00



Description:

The narrative for this site is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	MS -Middle School	Gross Area:	88,486
Year Built:	2000	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$3,343,888
FCI:	0.00 %	RSLI%:	37.46 %

No data found for this asset

No data found for this asset

No data found for this asset

10 Year Investment Forecast



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	21.77 %	0.00 %	\$0.00
G30 - Site Mechanical Utilities	65.09 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	56.86 %	0.00 %	\$0.00
Totals:	37.46 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). Aerial Image of Spring Hill Middle School -
Feb 24, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$4.22	S.F.	88,486	25	2000	2025		32.00 %	0.00 %	8			\$373,411
G2020	Parking Lots	\$1.39	S.F.	88,486	25	2000	2025		32.00 %	0.00 %	8			\$122,996
G2030	Pedestrian Paving	\$1.98	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$175,202
G2040105	Fence & Guardrails	\$1.20	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$106,183
G2040950	Baseball Field	\$7.08	S.F.	88,486	20	2000	2020		15.00 %	0.00 %	3			\$626,481
G2040950	Football Field	\$4.73	S.F.	88,486	20	2000	2020		15.00 %	0.00 %	3			\$418,539
G2040950	Hard Surface Play Area	\$0.65	S.F.	88,486	20	2000	2020		15.00 %	0.00 %	3			\$57,516
G2050	Landscaping	\$1.91	S.F.	88,486	15	2000	2015		0.00 %	0.00 %	-2			\$169,008
G3010	Water Supply	\$2.42	S.F.	88,486	50	2000	2050		66.00 %	0.00 %	33			\$214,136
G3020	Sanitary Sewer	\$1.52	S.F.	88,486	50	2000	2050		66.00 %	0.00 %	33			\$134,499
G3030	Storm Sewer	\$4.67	S.F.	88,486	50	2000	2050		66.00 %	0.00 %	33			\$413,230
G3060	Fuel Distribution	\$1.03	S.F.	88,486	40	2000	2040		57.50 %	0.00 %	23			\$91,141
G4010	Electrical Distribution	\$2.59	S.F.	88,486	50	2000	2050		66.00 %	0.00 %	33			\$229,179
G4020	Site Lighting	\$1.52	S.F.	88,486	30	2000	2030		43.33 %	0.00 %	13			\$134,499
G4030	Site Communications & Security	\$0.88	S.F.	88,486	15	2010	2025		53.33 %	0.00 %	8			\$77,868
Total									37.46 %					\$3,343,888

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: G2010 - Roadways



Note:

System: G2020 - Parking Lots



Note:

System: G2030 - Pedestrian Paving



Note:

Campus Assessment Report - Site

System: G2040105 - Fence & Guardrails



Note:

System: G2040950 - Baseball Field



Note:

System: G2040950 - Football Field



Note:

Campus Assessment Report - Site

System: G2040950 - Hard Surface Play Area



Note:

System: G2050 - Landscaping



Note:

System: G3010 - Water Supply



Note:

Campus Assessment Report - Site

System: G3020 - Sanitary Sewer



Note:

System: G3030 - Storm Sewer



Note:

System: G3060 - Fuel Distribution



Note:

Campus Assessment Report - Site

System: G4010 - Electrical Distribution



Note:

System: G4020 - Site Lighting



Note:

System: G4030 - Site Communications & Security



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$0	\$1,325,247	\$0	\$0	\$0	\$0	\$800,220	\$0	\$0	\$2,125,467
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$520,328	\$0	\$0	\$520,328
G2020 - Parking Lots	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$171,388	\$0	\$0	\$171,388
G2030 - Pedestrian Paving	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040105 - Fence & Guardrails	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040950 - Baseball Field	\$0	\$0	\$0	\$753,030	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$753,030
G2040950 - Football Field	\$0	\$0	\$0	\$503,084	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$503,084
G2040950 - Hard Surface Play Area	\$0	\$0	\$0	\$69,134	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$69,134
* G2050 - Landscaping	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3020 - Sanitary Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3030 - Storm Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3060 - Fuel Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$108,504	\$0	\$0	\$108,504

** Indicates non-renewable system*

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

NC School District/830 Scotland County/Elementary School

Covington Street Elementary

Draft

Campus Assessment Report

March 7, 2017



Table of Contents

Campus Executive Summary	4
Campus Dashboard Summary	7
Campus Condition Summary	8
<u>1952, 1962, 1982 Main Building</u>	10
Executive Summary	10
Dashboard Summary	11
Condition Summary	12
Photo Album	13
Condition Detail	14
System Listing	15
System Notes	17
Renewal Schedule	27
Forecasted Sustainment Requirement	30
Deficiency Summary By System	31
Deficiency Summary By Priority	32
Deficiency By Priority Investment	33
Deficiency Summary By Category	34
Deficiency Details By Priority	35
<u>Site</u>	44
Executive Summary	44
Dashboard Summary	45
Condition Summary	46
Photo Album	47
Condition Detail	48
System Listing	49
System Notes	50
Renewal Schedule	55
Forecasted Sustainment Requirement	56
Deficiency Summary By System	57

Campus Assessment Report

Deficiency Summary By Priority	58
Deficiency By Priority Investment	59
Deficiency Summary By Category	60
Deficiency Details By Priority	61

Campus Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	32,364
Year Built:	1952
Last Renovation:	
Replacement Value:	\$7,418,805
Repair Cost:	\$2,076,752.61
Total FCI:	27.99 %
Total RSLI:	23.12 %
FCA Score:	72.01



Description:

GENERAL:

Covington Street Elementary School is located at 615 W Covington Street in Laurinburg, North Carolina. The 1 story, 32,364 square foot building was originally constructed in 1952. There have been two additions to the building in 1962 and 1982, but there have been no major renovations. In 1962 classrooms were added and in 1982 the Media Center and more classrooms were added.

This report contains condition and adequacy data collected during the 2016-2017 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for the site and building elements.

A. SUBSTRUCTURE

The building rests on slab-on grade and is assumed to have standard cast-in-place concrete foundations. The building does not have a basement.

Campus Assessment Report - Covington Street Elementary

B. SUPERSTRUCTURE

Floor construction is concrete. Roof construction is metal pan deck with lightweight fill. The exterior envelope is composed of walls of brick veneer over CMU. Exterior windows are aluminum frame with operable panes. Exterior doors are hollow metal steel mostly with glazing. Roofing is typically low slope thermoplastic polyolefin. Roof openings include a roof hatch with fixed ladder access. Most building entrances appear to comply with ADA requirements.

C. INTERIORS

Interior partitions are typically CMU. Interior doors are generally solid core wood with hollow steel frames and mostly with glazing. There are also hollow metal interior doors. Interior fittings include the following items: white boards, graphics and identifying devices, lockers, toilet accessories, storage shelving, fabricated toilet partitions. The interior wall finishes are typically painted CMU. Floor finishes in common areas are typically vinyl composition tile. Floor finishes in assignable spaces is typically carpet, wood, ceramic tiles, and quarry tiles. Ceiling finishes in common areas are typically suspended acoustical tile. Ceiling finishes in assignable areas are typically painted drywall.

CONVEYING:

The building does not include conveying equipment.

D. SERVICES

PLUMBING: Plumbing fixtures are typically non-low-flow water fixtures with manual control valves. Domestic water distribution is combination of copper and galvanized steel with gas hot water heating. Sanitary waste system is cast iron. Rain water drainage system is internal with roof drains. Other plumbing systems is supplied by natural gas.

HVAC:

Heating is provided by 1 gas fired boilers. Cooling is supplied by wall package units. The heating/cooling distribution system is a ductwork system utilizing air handling units. Fresh air is supplied by air handling units. Ceiling mounted exhaust fans are installed in bathrooms and other required areas. Controls and instrumentation are digital and are centrally controlled by an energy management system. This building has a remote Building Automation System.

FIRE PROTECTION:

The building does not have a fire sprinkler system. The building does not have additional fire suppression systems. Standpipes are not included within fire stairs. Fire extinguishers and cabinets are distributed near fire exits and corridors.

ELECTRICAL:

The main electrical service is fed from a pad mounted transformer to the main switchboard/distribution panel located in the building. Lighting is lay-in type, fluorescent light fixtures. Branch circuit wiring is typically copper serving electrical switches and receptacles. Emergency and life safety egress lighting systems are installed and exit signs are present at exit doors and near stairways and are typically illuminated.

COMMUNICATIONS AND SECURITY:

The fire alarm system consists of audible/visual strobe annunciators in interior corridors. The system is activated by manual pull stations and smoke detectors and the system is centrally monitored. The telephone and data systems are segregated and include dedicated equipment closets. This building does have a local area network (LAN). The building does not include an internal security system. The building has controlled entry door access provided by card readers; entry doors are secured with magnetic door locks. The security system has CCTV cameras and is centrally monitored; this building has a public address and paging system combined with the telephone system.

OTHER ELECTRICAL SYSTEMS:

This building does not have a separately derived emergency power system.

E. EQUIPMENT & FURNISHINGS:





This building includes the following items and equipment: fixed food service, library equipment, audio-visual, fixed casework, and window treatment.

G. SITE

Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, play areas, and fencing. Site mechanical and electrical features include water, sewer, natural gas, and site lighting.

Campus Dashboard Summary

Gross Area:	32,364	Last Renovation:	
Year Built:	1952	Replacement Value:	\$7,418,805
Repair Cost:	\$2,076,753	RSLI%:	23.12 %
FCI:	27.99 %		



Campus Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Unifomat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	35.00 %	0.00 %	\$0.00
A20 - Basement Construction	35.00 %	0.00 %	\$0.00
B10 - Superstructure	35.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	23.62 %	5.04 %	\$32,407.73
B30 - Roofing	65.28 %	0.00 %	\$0.00
C10 - Interior Construction	14.69 %	13.83 %	\$103,269.00
C30 - Interior Finishes	16.04 %	38.17 %	\$310,582.82
D20 - Plumbing	2.65 %	88.08 %	\$443,581.00
D30 - HVAC	36.68 %	33.41 %	\$286,842.00
D40 - Fire Protection	0.00 %	110.00 %	\$177,646.00
D50 - Electrical	18.02 %	72.19 %	\$664,660.00
E10 - Equipment	28.18 %	0.00 %	\$0.00
E20 - Furnishings	20.00 %	0.00 %	\$0.00
G20 - Site Improvements	20.44 %	1.35 %	\$5,431.06
G30 - Site Mechanical Utilities	8.21 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	8.84 %	34.70 %	\$52,333.00
Totals:	23.12 %	27.99 %	\$2,076,752.61

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance
1952, 1962, 1982 Main Building	32,364	30.76	\$90,939.82	\$0.00	\$1,750,402.73	\$177,646.00	\$0.00
Site	32,364	6.76	\$0.00	\$0.00	\$57,764.06	\$0.00	\$0.00
Total:		27.99	\$90,939.82	\$0.00	\$1,808,166.79	\$177,646.00	\$0.00

Deficiencies By Priority



- 1 - Currently Critical (Immediate) - \$90,939.82
- 2 - Potentially Critical (Year 1)
- 3 - Necessary/Not Yet Critical (Years 2-5) - \$1,808,166.79
- 4 - Recommended (Years 6-10) - \$177,646.00
- 5 - Codes or Standards Compliance

Budget Estimate Total: \$2,076,752.61

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	32,364
Year Built:	1952
Last Renovation:	
Replacement Value:	\$6,564,718
Repair Cost:	\$2,018,988.55
Total FCI:	30.76 %
Total RSLI:	24.30 %
FCA Score:	69.24







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	ES -Elementary School	Gross Area:	32,364
Year Built:	1952	Last Renovation:	
Repair Cost:	\$2,018,989	Replacement Value:	\$6,564,718
FCI:	30.76 %	RSLI%:	24.30 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	35.00 %	0.00 %	\$0.00
A20 - Basement Construction	35.00 %	0.00 %	\$0.00
B10 - Superstructure	35.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	23.62 %	5.04 %	\$32,407.73
B30 - Roofing	65.28 %	0.00 %	\$0.00
C10 - Interior Construction	14.69 %	13.83 %	\$103,269.00
C30 - Interior Finishes	16.03 %	38.17 %	\$310,582.82
D20 - Plumbing	2.65 %	88.08 %	\$443,581.00
D30 - HVAC	36.68 %	33.41 %	\$286,842.00
D40 - Fire Protection	0.00 %	110.00 %	\$177,646.00
D50 - Electrical	18.02 %	72.19 %	\$664,660.00
E10 - Equipment	28.18 %	0.00 %	\$0.00
E20 - Furnishings	20.00 %	0.00 %	\$0.00
Totals:	24.30 %	30.76 %	\$2,018,988.55

Photo Album

The photo album consists of the various cardinal directions of the building..

1). East Elevation - Jan 09, 2017



2). West Elevation - Jan 09, 2017



3). South Elevation - Jan 09, 2017



4). Southeast Elevation - Jan 09, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Campus Assessment Report - 1952, 1962, 1982 Main Building

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.79	S.F.	32,364	100	1952	2052		35.00 %	0.00 %	35			\$155,024
A1030	Slab on Grade	\$8.43	S.F.	32,364	100	1952	2052		35.00 %	0.00 %	35			\$272,829
A2010	Basement Excavation	\$1.90	S.F.	32,364	100	1952	2052		35.00 %	0.00 %	35			\$61,492
A2020	Basement Walls	\$13.07	S.F.	32,364	100	1952	2052		35.00 %	0.00 %	35			\$422,997
B1020	Roof Construction	\$15.76	S.F.	32,364	100	1952	2052		35.00 %	0.00 %	35			\$510,057
B2010	Exterior Walls	\$9.42	S.F.	32,364	100	1952	2052		35.00 %	4.33 %	35		\$13,200.00	\$304,869
B2020	Exterior Windows	\$9.39	S.F.	32,364	30	1952	1982	2021	13.33 %	6.32 %	4		\$19,207.73	\$303,898
B2030	Exterior Doors	\$1.04	S.F.	32,364	30	1952	1982	2021	13.33 %	0.00 %	4			\$33,659
B3010120	Single Ply Membrane	\$6.98	S.F.	32,364	20	2010	2030		65.00 %	0.00 %	13			\$225,901
B3020	Roof Openings	\$0.29	S.F.	32,364	25	2010	2035		72.00 %	0.00 %	18			\$9,386
C1010	Partitions	\$10.80	S.F.	32,364	75	1952	2027		13.33 %	3.78 %	10		\$13,200.00	\$349,531
C1020	Interior Doors	\$2.53	S.F.	32,364	30	1952	1982		0.00 %	110.00 %	-35		\$90,069.00	\$81,881
C1030	Fittings	\$9.74	S.F.	32,364	20	1952	1972	2021	20.00 %	0.00 %	4			\$315,225
C3010	Wall Finishes	\$2.79	S.F.	32,364	10	1952	1962		0.00 %	110.00 %	-55		\$99,325.00	\$90,296
C3020	Floor Finishes	\$11.38	S.F.	32,364	20	1952	1972	2021	20.00 %	17.52 %	4		\$64,539.82	\$368,302
C3030	Ceiling Finishes	\$10.97	S.F.	32,364	25	1952	1977	2021	16.00 %	41.33 %	4		\$146,718.00	\$355,033
D2010	Plumbing Fixtures	\$11.48	S.F.	32,364	30	1952	1982		0.00 %	110.00 %	-35		\$408,693.00	\$371,539
D2020	Domestic Water Distribution	\$0.98	S.F.	32,364	30	1952	1982		0.00 %	110.00 %	-35		\$34,888.00	\$31,717
D2030	Sanitary Waste	\$1.54	S.F.	32,364	30	1952	1982	2021	13.33 %	0.00 %	4			\$49,841
D2040	Rain Water Drainage	\$1.39	S.F.	32,364	30	1952	1982	2021	13.33 %	0.00 %	4			\$44,986
D2090	Other Plumbing Systems -Nat Gas	\$0.17	S.F.	32,364	40	1982	2022		12.50 %	0.00 %	5			\$5,502
D3020	Heat Generating Systems	\$5.08	S.F.	32,364	30	1952	1982		0.00 %	110.00 %	-35		\$180,850.00	\$164,409
D3040	Distribution Systems	\$6.14	S.F.	32,364	30	1952	1982	2021	13.33 %	0.00 %	4			\$198,715
D3050	Terminal & Package Units	\$13.37	S.F.	32,364	15	2012	2027		66.67 %	8.53 %	10		\$36,927.00	\$432,707
D3060	Controls & Instrumentation	\$1.94	S.F.	32,364	20	1952	1972		0.00 %	110.00 %	-45		\$69,065.00	\$62,786
D4010	Sprinklers	\$4.32	S.F.	32,364	30	1952	1982		0.00 %	110.00 %	-35		\$153,794.00	\$139,812
D4020	Standpipes	\$0.67	S.F.	32,364	30	1952	1982		0.00 %	110.00 %	-35		\$23,852.00	\$21,684
D5010	Electrical Service/Distribution	\$1.69	S.F.	32,364	40	1952	1992		0.00 %	110.00 %	-25		\$60,165.00	\$54,695
D5020	Branch Wiring	\$5.06	S.F.	32,364	30	1952	1982		0.00 %	110.00 %	-35		\$180,138.00	\$163,762
D5020	Lighting	\$11.92	S.F.	32,364	30	1982	2012		0.00 %	110.00 %	-5		\$424,357.00	\$385,779
D5030810	Security & Detection Systems	\$1.87	S.F.	32,364	15	2013	2028		73.33 %	0.00 %	11			\$60,521
D5030910	Fire Alarm Systems	\$3.39	S.F.	32,364	15	2013	2028		73.33 %	0.00 %	11			\$109,714
D5030920	Data Communication	\$4.40	S.F.	32,364	15	1982	1997	2021	26.67 %	0.00 %	4			\$142,402
D5090	Other Electrical Systems	\$0.12	S.F.	32,364	20	2013	2033		80.00 %	0.00 %	16			\$3,884
E1020	Institutional Equipment	\$0.30	S.F.	32,364	20	2013	2033		80.00 %	0.00 %	16			\$9,709
E1090	Other Equipment	\$1.90	S.F.	32,364	20	1982	2002	2021	20.00 %	0.00 %	4			\$61,492
E2010	Fixed Furnishings	\$5.83	S.F.	32,364	20	1982	2002	2021	20.00 %	0.00 %	4			\$188,682
Total									24.30 %	30.76 %			\$2,018,988.55	\$6,564,718

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1952, 1962, 1982 Main Building

System: B3010120 - Single Ply Membrane



Note:

System: B3020 - Roof Openings



Note:


System: C1010 - Partitions



Note:

Campus Assessment Report - 1952, 1962, 1982 Main Building

System: C1020 - Interior Doors



Note: The interior doors are beyond their service life and should be replaced, also while replacing the doors the hardware installed should be ADA compliant.

System: C1030 - Fittings



Note:





System: C3010 - Wall Finishes



Note: The wall finishes are beyond their service life and should be replaced.



Campus Assessment Report - 1952, 1962, 1982 Main Building

System: C3020 - Floor Finishes





Note: The carpet is in poor condition and should be replaced.

System: C3030 - Ceiling Finishes



Note: The acoustical ceiling tiles are beyond their service life and should be replaced.

System: D2010 - Plumbing Fixtures



Note: The plumbing fixtures are beyond their service life and should be replaced.

Campus Assessment Report - 1952, 1962, 1982 Main Building

System: D2020 - Domestic Water Distribution



Note: The domestic water distribution system is beyond its service life and should be replaced.

System: D2030 - Sanitary Waste



Note:

System: D2040 - Rain Water Drainage



Note:

Campus Assessment Report - 1952, 1962, 1982 Main Building

System: D2090 - Other Plumbing Systems -Nat Gas




Note:

System: D3020 - Heat Generating Systems



Note: The heat generation system is beyond its service life and should be replaced.

System: D3040 - Distribution Systems



Note:

Campus Assessment Report - 1952, 1962, 1982 Main Building

System: D3050 - Terminal & Package Units



Note: The radiating heating system is beyond its service life and should be replaced.

System: D3060 - Controls & Instrumentation



Note: The controls are beyond their service life and should be replaced.

System: D4010 - Sprinklers

This system contains no images

Note: The building does not have a fire protection system and it should be installed.

System: D4020 - Standpipes

This system contains no images

Note: The building does not have a fire protection system and it should be installed.


System: D5010 - Electrical Service/Distribution



Note: The electrical service distribution system is beyond its service life and should be replaced.


Campus Assessment Report - 1952, 1962, 1982 Main Building

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note: The lighting system is beyond its service life and should be replaced.


System: D5030810 - Security & Detection Systems



Note:

Campus Assessment Report - 1952, 1962, 1982 Main Building

System: D5030910 - Fire Alarm Systems



Note:

System: D5030920 - Data Communication



Note:


System: D5090 - Other Electrical Systems



Note:

Campus Assessment Report - 1952, 1962, 1982 Main Building

System: E1020 - Institutional Equipment



Note:

System: E1090 - Other Equipment



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$2,018,989	\$0	\$0	\$0	\$2,553,169	\$7,016	\$0	\$0	\$0	\$0	\$773,158	\$5,352,332
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2010 - Exterior Walls	\$13,200	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$13,200
B2020 - Exterior Windows	\$19,208	\$0	\$0	\$0	\$376,244	\$0	\$0	\$0	\$0	\$0	\$0	\$395,452
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$41,671	\$0	\$0	\$0	\$0	\$0	\$0	\$41,671
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$13,200	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$13,200
C1020 - Interior Doors	\$90,069	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$90,069
C1030 - Fittings	\$0	\$0	\$0	\$0	\$390,268	\$0	\$0	\$0	\$0	\$0	\$0	\$390,268
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$99,325	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$133,484	\$232,809


Campus Assessment Report - 1952, 1962, 1982 Main Building

C3020 - Floor Finishes	\$64,540	\$0	\$0	\$0	\$455,981	\$0	\$0	\$0	\$0	\$0	\$0	\$520,521
C3030 - Ceiling Finishes	\$146,718	\$0	\$0	\$0	\$439,552	\$0	\$0	\$0	\$0	\$0	\$0	\$586,270
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$408,693	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$408,693
D2020 - Domestic Water Distribution	\$34,888	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$34,888
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$61,706	\$0	\$0	\$0	\$0	\$0	\$0	\$61,706
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$55,696	\$0	\$0	\$0	\$0	\$0	\$0	\$55,696
D2090 - Other Plumbing Systems -Nat Gas	\$0	\$0	\$0	\$0	\$0	\$7,016	\$0	\$0	\$0	\$0	\$0	\$7,016
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$180,850	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$180,850
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$246,020	\$0	\$0	\$0	\$0	\$0	\$0	\$246,020
D3050 - Terminal & Package Units	\$36,927	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$639,673	\$676,600
D3060 - Controls & Instrumentation	\$69,065	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$69,065
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$153,794	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$153,794
D4020 - Standpipes	\$23,852	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$23,852
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$60,165	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$60,165
D5020 - Branch Wiring	\$180,138	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$180,138
D5020 - Lighting	\$424,357	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$424,357
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$176,302	\$0	\$0	\$0	\$0	\$0	\$0	\$176,302
D5090 - Other Electrical Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$76,131	\$0	\$0	\$0	\$0	\$0	\$0	\$76,131
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$233,599	\$0	\$0	\$0	\$0	\$0	\$0	\$233,599

** Indicates non-renewable system*


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$2,018,988.55

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$2,018,988.55


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2010	Exterior Walls	\$13,200.00	\$0.00	\$0.00	\$0.00	\$0.00	\$13,200.00
B2020	Exterior Windows	\$0.00	\$0.00	\$19,207.73	\$0.00	\$0.00	\$19,207.73
C1010	Partitions	\$13,200.00	\$0.00	\$0.00	\$0.00	\$0.00	\$13,200.00
C1020	Interior Doors	\$0.00	\$0.00	\$90,069.00	\$0.00	\$0.00	\$90,069.00
C3010	Wall Finishes	\$0.00	\$0.00	\$99,325.00	\$0.00	\$0.00	\$99,325.00
C3020	Floor Finishes	\$64,539.82	\$0.00	\$0.00	\$0.00	\$0.00	\$64,539.82
C3030	Ceiling Finishes	\$0.00	\$0.00	\$146,718.00	\$0.00	\$0.00	\$146,718.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$408,693.00	\$0.00	\$0.00	\$408,693.00
D2020	Domestic Water Distribution	\$0.00	\$0.00	\$34,888.00	\$0.00	\$0.00	\$34,888.00
D3020	Heat Generating Systems	\$0.00	\$0.00	\$180,850.00	\$0.00	\$0.00	\$180,850.00
D3050	Terminal & Package Units	\$0.00	\$0.00	\$36,927.00	\$0.00	\$0.00	\$36,927.00
D3060	Controls & Instrumentation	\$0.00	\$0.00	\$69,065.00	\$0.00	\$0.00	\$69,065.00
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$153,794.00	\$0.00	\$153,794.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$23,852.00	\$0.00	\$23,852.00
D5010	Electrical Service/Distribution	\$0.00	\$0.00	\$60,165.00	\$0.00	\$0.00	\$60,165.00
D5020	Branch Wiring	\$0.00	\$0.00	\$180,138.00	\$0.00	\$0.00	\$180,138.00
D5020	Lighting	\$0.00	\$0.00	\$424,357.00	\$0.00	\$0.00	\$424,357.00
	Total:	\$90,939.82	\$0.00	\$1,750,402.73	\$177,646.00	\$0.00	\$2,018,988.55

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$2,018,988.55

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Currently Critical (Immediate):

System: B2010 - Exterior Walls



Location: Exterior walls
Distress: Damaged
Category: Safety / Building Code Compliance
Priority: 1 - Currently Critical (Immediate)
Correction: Engineering Study-2016-11-15 17:41:59
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$13,200.00
Assessor Name: Terence Davis
Date Created: 01/05/2017

Notes: There are multiple areas where the bricks are missing or there are visible cracks on the exterior walls, a professional engineer should study the problem.


System: C1010 - Partitions



Location: Office and Media Center
Distress: Damaged
Category: Safety / Building Code Compliance
Priority: 1 - Currently Critical (Immediate)
Correction: Engineering Study
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$13,200.00
Assessor Name: Terence Davis
Date Created: 01/05/2017

Notes: There are visible cracks on the partition wall which should be studied by a professional engineer.

System: C3020 - Floor Finishes



Location: Throughout the building
Distress: Failing
Category: Life Safety Code Compliance
Priority: 1 - Currently Critical (Immediate)
Correction: Replace carpet
Qty: 755.00
Unit of Measure: S.Y.
Estimate: \$64,539.82
Assessor Name: Terence Davis
Date Created: 01/05/2017

Notes: The carpet is in poor condition and should be replaced as it has become a tripping hazard.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B2020 - Exterior Windows



Location: Exterior wall
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Replace 3' x 4' aluminum window - 1st floor
Qty: 15.00
Unit of Measure: Ea.
Estimate: \$19,207.73
Assessor Name: Terence Davis
Date Created: 01/09/2017

Notes: The exterior windows on the cafeteria and few places on the original building are beyond their service life and should be replaced.

System: C1020 - Interior Doors



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 32,364.00
Unit of Measure: S.F.
Estimate: \$90,069.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The interior doors are beyond their service life and should be replaced, also while replacing the doors the hardware installed should be ADA compliant.


System: C3010 - Wall Finishes



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 32,364.00
Unit of Measure: S.F.
Estimate: \$99,325.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The wall finishes are beyond their service life and should be replaced.

System: C3030 - Ceiling Finishes



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Replace acoustic tile ceiling, non fire-rated
Qty: 195.00
Unit of Measure: C.S.F.
Estimate: \$146,718.00
Assessor Name: Terence Davis
Date Created: 01/05/2017

Notes: The acoustical ceiling tiles are beyond their service life and should be replaced.

System: D2010 - Plumbing Fixtures



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 32,364.00
Unit of Measure: S.F.
Estimate: \$408,693.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The plumbing fixtures are beyond their service life and should be replaced.

System: D2020 - Domestic Water Distribution



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 32,364.00
Unit of Measure: S.F.
Estimate: \$34,888.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The domestic water distribution system is beyond its service life and should be replaced.

System: D3020 - Heat Generating Systems



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 32,364.00
Unit of Measure: S.F.
Estimate: \$180,850.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The heat generation system is beyond its service life and should be replaced.


System: D3050 - Terminal & Package Units



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Replace heat pump, thru-wall unit, 1.5 ton
Qty: 5.00
Unit of Measure: Ea.
Estimate: \$36,927.00
Assessor Name: Terence Davis
Date Created: 01/05/2017

Notes: The radiating heaters are beyond their service life and should be replaced.

System: D3060 - Controls & Instrumentation



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 32,364.00
Unit of Measure: S.F.
Estimate: \$69,065.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The controls are beyond their service life and should be replaced.

System: D5010 - Electrical Service/Distribution



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 32,364.00
Unit of Measure: S.F.
Estimate: \$60,165.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The electrical service distribution system is beyond its service life and should be replaced.

System: D5020 - Branch Wiring



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 32,364.00
Unit of Measure: S.F.
Estimate: \$180,138.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The branch wiring is beyond its service life and should be replaced.

System: D5020 - Lighting



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 32,364.00
Unit of Measure: S.F.
Estimate: \$424,357.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The lighting system is beyond its service life and should be replaced.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout Building
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 32,364.00
Unit of Measure: S.F.
Estimate: \$153,794.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The building does not have a fire protection system and it should be installed.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout Building
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 32,364.00
Unit of Measure: S.F.
Estimate: \$23,852.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The building does not have a fire protection system and it should be installed.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as $100 - \text{Total FCI}$ (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	32,364
Year Built:	1952
Last Renovation:	
Replacement Value:	\$854,087
Repair Cost:	\$57,764.06
Total FCI:	6.76 %
Total RSLI:	14.08 %
FCA Score:	93.24







Description:

The narrative for this site is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	ES -Elementary School	Gross Area:	32,364
Year Built:	1952	Last Renovation:	
Repair Cost:	\$57,764	Replacement Value:	\$854,087
FCI:	6.76 %	RSLI%:	14.08 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	20.44 %	1.35 %	\$5,431.06
G30 - Site Mechanical Utilities	8.21 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	8.84 %	34.70 %	\$52,333.00
Totals:	14.08 %	6.76 %	\$57,764.06

Photo Album

The photo album consists of the various cardinal directions of the building..

- 1). Aerial Image of Covington Street Elementary School - Dec 30, 2016



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$3.81	S.F.	32,364	25	1982	2007	2021	16.00 %	0.00 %	4			\$123,307
G2020	Parking Lots	\$1.33	S.F.	32,364	25	2013	2038		84.00 %	12.62 %	21		\$5,431.06	\$43,044
G2030	Pedestrian Paving	\$1.91	S.F.	32,364	30	1982	2012	2021	13.33 %	0.00 %	4			\$61,815
G2040105	Fence & Guardrails	\$1.23	S.F.	32,364	30	1982	2012	2021	13.33 %	0.00 %	4			\$39,808
G2040950	Covered Walkways	\$1.52	S.F.	32,364	25	1982	2007	2021	16.00 %	0.00 %	4			\$49,193
G2040950	Hard Surface Play Area	\$0.75	S.F.	32,364	20	1982	2002	2021	20.00 %	0.00 %	4			\$24,273
G2050	Landscaping	\$1.87	S.F.	32,364	15	1952	1967		0.00 %	0.00 %	-50			\$60,521
G3010	Water Supply	\$2.34	S.F.	32,364	50	1952	2002	2021	8.00 %	0.00 %	4			\$75,732
G3020	Sanitary Sewer	\$1.45	S.F.	32,364	50	1952	2002	2021	8.00 %	0.00 %	4			\$46,928
G3030	Storm Sewer	\$4.54	S.F.	32,364	50	1952	2002	2021	8.00 %	0.00 %	4			\$146,933
G3060	Fuel Distribution	\$0.98	S.F.	32,364	40	1952	1992	2021	10.00 %	0.00 %	4			\$31,717
G4010	Electrical Distribution	\$2.35	S.F.	32,364	50	1952	2002	2021	8.00 %	0.00 %	4			\$76,055
G4020	Site Lighting	\$1.47	S.F.	32,364	30	1982	2012		0.00 %	110.00 %	-5		\$52,333.00	\$47,575
G4030	Site Communications & Security	\$0.84	S.F.	32,364	15	1982	1997	2021	26.67 %	0.00 %	4			\$27,186
Total									14.08 %	6.76 %			\$57,764.06	\$854,087

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: G2010 - Roadways



Note:

System: G2020 - Parking Lots



Note:

System: G2030 - Pedestrian Paving



Note:

Campus Assessment Report - Site

System: G2040105 - Fence & Guardrails



Note:

System: G2040950 - Covered Walkways



Note:

System: G2040950 - Hard Surface Play Area



Note:

Campus Assessment Report - Site

System: G2050 - Landscaping



Note:

System: G3010 - Water Supply



Note:

System: G3020 - Sanitary Sewer



Note:

Campus Assessment Report - Site

System: G3030 - Storm Sewer



Note:

System: G3060 - Fuel Distribution



Note:

System: G4010 - Electrical Distribution



Note:

Campus Assessment Report - Site

System: G4020 - Site Lighting



Note: The site lighting system is beyond its service life and should be replaced.

System: G4030 - Site Communications & Security



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$57,764	\$0	\$0	\$0	\$870,290	\$0	\$0	\$0	\$0	\$0	\$0	\$928,054
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$0	\$0	\$0	\$0	\$152,662	\$0	\$0	\$0	\$0	\$0	\$0	\$152,662
G2020 - Parking Lots	\$5,431	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$5,431
G2030 - Pedestrian Paving	\$0	\$0	\$0	\$0	\$76,531	\$0	\$0	\$0	\$0	\$0	\$0	\$76,531
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040105 - Fence & Guardrails	\$0	\$0	\$0	\$0	\$49,284	\$0	\$0	\$0	\$0	\$0	\$0	\$49,284
G2040950 - Covered Walkways	\$0	\$0	\$0	\$0	\$60,905	\$0	\$0	\$0	\$0	\$0	\$0	\$60,905
G2040950 - Hard Surface Play Area	\$0	\$0	\$0	\$0	\$30,051	\$0	\$0	\$0	\$0	\$0	\$0	\$30,051
* G2050 - Landscaping	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$0	\$0	\$0	\$0	\$93,761	\$0	\$0	\$0	\$0	\$0	\$0	\$93,761
G3020 - Sanitary Sewer	\$0	\$0	\$0	\$0	\$58,100	\$0	\$0	\$0	\$0	\$0	\$0	\$58,100
G3030 - Storm Sewer	\$0	\$0	\$0	\$0	\$181,911	\$0	\$0	\$0	\$0	\$0	\$0	\$181,911
G3060 - Fuel Distribution	\$0	\$0	\$0	\$0	\$39,267	\$0	\$0	\$0	\$0	\$0	\$0	\$39,267
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$0	\$0	\$0	\$0	\$94,161	\$0	\$0	\$0	\$0	\$0	\$0	\$94,161
G4020 - Site Lighting	\$52,333	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$52,333
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$33,657	\$0	\$0	\$0	\$0	\$0	\$0	\$33,657

** Indicates non-renewable system*


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$57,764.06


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
G2020	Parking Lots	\$0.00	\$0.00	\$5,431.06	\$0.00	\$0.00	\$5,431.06
G4020	Site Lighting	\$0.00	\$0.00	\$52,333.00	\$0.00	\$0.00	\$52,333.00
	Total:	\$0.00	\$0.00	\$57,764.06	\$0.00	\$0.00	\$57,764.06

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: G2020 - Parking Lots



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Parking lot repair and resurface
Qty: 4.00
Unit of Measure: M.S.F.
Estimate: \$5,431.06
Assessor Name: Eduardo Lopez
Date Created: 01/05/2017

Notes: The parking lot on the northwest side needs to be repaired and restriped.

System: G4020 - Site Lighting



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 32,364.00
Unit of Measure: S.F.
Estimate: \$52,333.00
Assessor Name: Eduardo Lopez
Date Created: 12/30/2016

Notes: The site lighting system is beyond its service life and should be replaced.

NC School District/830 Scotland County/Elementary School

I E Johnson Elementary

Draft

Campus Assessment Report

March 7, 2017



Table of Contents

Campus Executive Summary	5
Campus Dashboard Summary	8
Campus Condition Summary	9
<u>1952 Classroom Building</u>	11
Executive Summary	11
Dashboard Summary	12
Condition Summary	13
Photo Album	14
Condition Detail	15
System Listing	16
System Notes	17
Renewal Schedule	25
Forecasted Sustainment Requirement	27
Deficiency Summary By System	28
Deficiency Summary By Priority	29
Deficiency By Priority Investment	30
Deficiency Summary By Category	31
Deficiency Details By Priority	32
<u>1952 Main Building</u>	37
Executive Summary	37
Dashboard Summary	38
Condition Summary	39
Photo Album	40
Condition Detail	41
System Listing	42
System Notes	44
Renewal Schedule	53
Forecasted Sustainment Requirement	55
Deficiency Summary By System	56

Campus Assessment Report

Deficiency Summary By Priority	57
Deficiency By Priority Investment	58
Deficiency Summary By Category	59
Deficiency Details By Priority	60
<u>1952 Storage</u>	67
Executive Summary	67
Dashboard Summary	68
Condition Summary	69
Photo Album	70
Condition Detail	71
System Listing	72
System Notes	73
Renewal Schedule	79
Forecasted Sustainment Requirement	81
Deficiency Summary By System	82
Deficiency Summary By Priority	83
Deficiency By Priority Investment	84
Deficiency Summary By Category	85
Deficiency Details By Priority	86
<u>Site</u>	93
Executive Summary	93
Dashboard Summary	94
Condition Summary	95
Photo Album	96
Condition Detail	97
System Listing	98
System Notes	99
Renewal Schedule	104
Forecasted Sustainment Requirement	105
Deficiency Summary By System	106
Deficiency Summary By Priority	107

Campus Assessment Report

Deficiency By Priority Investment	108
Deficiency Summary By Category	109
Deficiency Details By Priority	110

Campus Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	48,584
Year Built:	1952
Last Renovation:	
Replacement Value:	\$11,244,263
Repair Cost:	\$3,923,845.00
Total FCI:	34.90 %
Total RSLI:	17.83 %
FCA Score:	65.10



Description:

GENERAL:

I E Johnson Elementary School is located at 815 McGirts Bridge Road in Laurinburg, North Carolina. The 1 story, 61,802 square foot building was originally constructed in 1952. There has been one addition to the building in 1983. A Kitchen and a Media Center was added.

This report contains condition and adequacy data collected during the 2016-2017 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for the site and building elements.

A. SUBSTRUCTURE

The building rests on slab-on grade and is assumed to have standard cast-in-place concrete foundations. The building does have a partial basement.

B. SUPERSTRUCTURE

Floor construction is concrete. Roof construction is metal pan deck with lightweight fill. The exterior envelope is composed of walls of brick veneer over CMU. Exterior windows are aluminum frame with operable panes. Exterior doors are hollow metal steel mostly with glazing. Roofing is typically performed metal roof, foam roofing, asphalt roll roofing and a low slope thermoplastic polyolefin. Roof openings include a roof hatch with fixed ladder access. Most building entrances appear to comply with ADA requirements.

C. INTERIORS

Interior partitions are typically CMU. Interior doors are generally solid core wood with hollow steel frames and mostly with glazing. Interior fittings include the following items: white boards, graphics and identifying devices, toilet accessories, storage shelving, fabricated toilet partitions. The interior wall finishes are typically painted CMU. Floor finishes in common areas are typically vinyl composition tile. Floor finishes in assignable spaces is typically ceramic tiles, and quarry tiles. Ceiling finishes in common areas are typically suspended acoustical tile. Ceiling finishes in assignable areas are typically painted drywall.

CONVEYING:

The building does not include conveying equipment.

D. SERVICES

PLUMBING: Plumbing fixtures are typically non-low-flow water fixtures with manual control valves. Domestic water distribution is combination of copper and galvanized steel with gas hot water heating. Sanitary waste system is cast iron. Rain water drainage system is internal with roof drains. Other plumbing systems is supplied by natural gas.

HVAC:

Heating is provided by 2 gas fired boilers. Cooling is supplied by wall package units. The heating distribution system is piping connected to radiators as a secondary heating system. Ceiling mounted exhaust fans are installed in bathrooms and other required areas. Controls and instrumentation are digital and are centrally controlled by an energy management system. This building has a remote Building Automation System.

FIRE PROTECTION:

The building does not have a fire sprinkler system. Fire extinguishers and cabinets are distributed near fire exits and corridors.

ELECTRICAL:

The main electrical service is fed from a pad mounted transformer to the main switchboard/distribution panel located in the building. Lighting is lay-in type, fluorescent light fixtures. Branch circuit wiring is typically copper serving electrical switches and receptacles. Emergency and life safety egress lighting systems are installed and exit signs are present at exit doors and near stairways and are typically illuminated.

COMMUNICATIONS AND SECURITY:

The fire alarm system consists of audible/visual strobe annunciators in interior corridors. The system is activated by manual pull stations and smoke detectors and the system is centrally monitored. The telephone and data systems are segregated and include dedicated equipment closets. This building does have a local area network (LAN). The building does not include an internal security system. The building has controlled entry door access provided by card readers; entry doors are secured with magnetic door locks. The security system has CCTV cameras and is centrally monitored; this building has a public address and paging system combined with the telephone system.

OTHER ELECTRICAL SYSTEMS:

This building does not have a separately derived emergency power system.

E. EQUIPMENT & FURNISHINGS:

This building includes the following items and equipment: fixed food service, library equipment, audio-visual, fixed casework, and window treatment.

G. SITE

Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, play areas, and fencing. Site mechanical and electrical features include water, sewer, natural gas, and site lighting.

Campus Assessment Report - I E Johnson Elementary

Attributes:

General Attributes:





Condition Assessor:	Terence Davis	Assessment Date:	
Suitability Assessor:			

School Information:

HS Attendance Area:		LEA School No.:	
No. of Mobile Units:	0	No. of Bldgs.:	1
SF of Mobile Units:	Active	Status:	Active
School Grades:	15	Site Acreage:	15

Campus Dashboard Summary

Gross Area:	48,584	Last Renovation:	
Year Built:	1952	Replacement Value:	\$11,244,263
Repair Cost:	\$3,923,845	RSLI%:	17.83 %
FCI:	34.90 %		



Campus Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	35.00 %	0.00 %	\$0.00
A20 - Basement Construction	35.00 %	0.00 %	\$0.00
B10 - Superstructure	35.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	23.26 %	5.98 %	\$55,171.00
B30 - Roofing	7.13 %	60.30 %	\$430,188.00
C10 - Interior Construction	13.70 %	13.11 %	\$140,985.00
C30 - Interior Finishes	8.58 %	73.80 %	\$891,669.00
D20 - Plumbing	0.12 %	109.09 %	\$741,294.00
D30 - HVAC	15.78 %	44.48 %	\$505,665.00
D40 - Fire Protection	0.00 %	110.00 %	\$244,464.00
D50 - Electrical	21.75 %	32.27 %	\$432,079.00
E10 - Equipment	15.00 %	0.00 %	\$0.00
E20 - Furnishings	3.15 %	92.68 %	\$207,636.00
G20 - Site Improvements	10.98 %	33.34 %	\$274,694.00
G30 - Site Mechanical Utilities	8.74 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	47.83 %	0.00 %	\$0.00
Totals:	17.83 %	34.90 %	\$3,923,845.00

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance
1952 Classroom Building	12,000	22.46	\$0.00	\$0.00	\$462,000.00	\$67,320.00	\$0.00
1952 Main Building	33,000	40.98	\$0.00	\$0.00	\$2,646,204.00	\$177,144.00	\$0.00
1952 Storage	3,584	59.83	\$196,410.00	\$0.00	\$100,073.00	\$0.00	\$0.00
Site	48,584	18.28	\$0.00	\$0.00	\$274,694.00	\$0.00	\$0.00
Total:		34.90	\$196,410.00	\$0.00	\$3,482,971.00	\$244,464.00	\$0.00

Deficiencies By Priority



- 1 - Currently Critical (Immediate) - \$196,410.00
- 2 - Potentially Critical (Year 1)
- 3 - Necessary/Not Yet Critical (Years 2-5) - \$3,482,971.00
- 4 - Recommended (Years 6-10) - \$244,464.00
- 5 - Codes or Standards Compliance

Budget Estimate Total: \$3,923,845.00

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as $100 - \text{Total FCI}$ (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	12,000
Year Built:	1952
Last Renovation:	
Replacement Value:	\$2,356,920
Repair Cost:	\$529,320.00
Total FCI:	22.46 %
Total RSLI:	21.47 %
FCA Score:	77.54







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	ES -Elementary School	Gross Area:	12,000
Year Built:	1952	Last Renovation:	
Repair Cost:	\$529,320	Replacement Value:	\$2,356,920
FCI:	22.46 %	RSLI%:	21.47 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	35.00 %	0.00 %	\$0.00
A20 - Basement Construction	35.00 %	0.00 %	\$0.00
B10 - Superstructure	35.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	22.91 %	5.81 %	\$14,124.00
B30 - Roofing	10.00 %	0.00 %	\$0.00
C10 - Interior Construction	7.70 %	46.45 %	\$131,208.00
C30 - Interior Finishes	24.90 %	0.00 %	\$0.00
D20 - Plumbing	0.00 %	110.00 %	\$188,364.00
D30 - HVAC	18.56 %	33.33 %	\$82,632.00
D40 - Fire Protection	0.00 %	110.00 %	\$67,320.00
D50 - Electrical	26.63 %	13.17 %	\$45,672.00
E10 - Equipment	15.00 %	0.00 %	\$0.00
E20 - Furnishings	20.00 %	0.00 %	\$0.00
Totals:	21.47 %	22.46 %	\$529,320.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). West Elevation - Jan 12, 2017



2). East Elevation - Jan 12, 2017



3). South Elevation - Jan 12, 2017



4). North Elevation - Jan 12, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

Campus Assessment Report - 1952 Classroom Building

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.88	S.F.	12,000	100	1952	2052		35.00 %	0.00 %	35			\$58,560
A1030	Slab on Grade	\$8.61	S.F.	12,000	100	1952	2052		35.00 %	0.00 %	35			\$103,320
A2010	Basement Excavation	\$1.95	S.F.	12,000	100	1952	2052		35.00 %	0.00 %	35			\$23,400
A2020	Basement Walls	\$13.35	S.F.	12,000	100	1952	2052		35.00 %	0.00 %	35			\$160,200
B1010	Floor Construction	\$1.66	S.F.	12,000	100	1952	2052		35.00 %	0.00 %	35			\$19,920
B1020	Roof Construction	\$16.08	S.F.	12,000	100	1952	2052		35.00 %	0.00 %	35			\$192,960
B2010	Exterior Walls	\$9.61	S.F.	12,000	100	1952	2052		35.00 %	0.00 %	35			\$115,320
B2020	Exterior Windows	\$9.57	S.F.	12,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$114,840
B2030	Exterior Doors	\$1.07	S.F.	12,000	30	1983	2013		0.00 %	110.00 %	-4		\$14,124.00	\$12,840
B3010120	Preformed Metal Roofing	\$6.98	S.F.	12,000	30	1990	2020		10.00 %	0.00 %	3			\$83,760
C1010	Partitions	\$11.01	S.F.	12,000	75	1952	2027		13.33 %	0.00 %	10			\$132,120
C1020	Interior Doors	\$2.59	S.F.	12,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$31,080
C1030	Fittings	\$9.94	S.F.	12,000	20	1983	2003		0.00 %	110.00 %	-14		\$131,208.00	\$119,280
C3010	Wall Finishes	\$2.84	S.F.	12,000	10	2015	2025		80.00 %	0.00 %	8			\$34,080
C3020	Floor Finishes	\$11.60	S.F.	12,000	20	1983	2003	2021	20.00 %	0.00 %	4			\$139,200
C3030	Ceiling Finishes	\$11.19	S.F.	12,000	25	1983	2008	2021	16.00 %	0.00 %	4			\$134,280
D2010	Plumbing Fixtures	\$11.71	S.F.	12,000	30	1983	2013		0.00 %	110.00 %	-4		\$154,572.00	\$140,520
D2020	Domestic Water Distribution	\$0.99	S.F.	12,000	30	1983	2013		0.00 %	110.00 %	-4		\$13,068.00	\$11,880
D2030	Sanitary Waste	\$1.57	S.F.	12,000	30	1983	2013		0.00 %	110.00 %	-4		\$20,724.00	\$18,840
D3040	Distribution Systems	\$6.26	S.F.	12,000	30	1952	1982		0.00 %	110.00 %	-35		\$82,632.00	\$75,120
D3050	Terminal & Package Units	\$14.10	S.F.	12,000	15	2002	2017	2021	26.67 %	0.00 %	4			\$169,200
D3060	Controls & Instrumentation	\$0.30	S.F.	12,000	20	2002	2022		25.00 %	0.00 %	5			\$3,600
D4010	Sprinklers	\$4.41	S.F.	12,000	30			2016	0.00 %	110.00 %	-1		\$58,212.00	\$52,920
D4020	Standpipes	\$0.69	S.F.	12,000	30			2016	0.00 %	110.00 %	-1		\$9,108.00	\$8,280
D5010	Electrical Service/Distribution	\$1.73	S.F.	12,000	40	1983	2023		15.00 %	0.00 %	6			\$20,760
D5020	Branch Wiring	\$5.20	S.F.	12,000	30	1952	1982	2021	13.33 %	0.00 %	4			\$62,400
D5020	Lighting	\$12.12	S.F.	12,000	30	1990	2020		10.00 %	0.00 %	3			\$145,440
D5030810	Security & Detection Systems	\$1.91	S.F.	12,000	15	2015	2030		86.67 %	0.00 %	13			\$22,920
D5030910	Fire Alarm Systems	\$3.46	S.F.	12,000	15	1983	1998		0.00 %	110.00 %	-19		\$45,672.00	\$41,520
D5030920	Data Communication	\$4.47	S.F.	12,000	15	2015	2030		86.67 %	0.00 %	13			\$53,640
E1020	Institutional Equipment	\$1.62	S.F.	12,000	20	2000	2020		15.00 %	0.00 %	3			\$19,440
E2010	Fixed Furnishings	\$2.94	S.F.	12,000	20	1983	2003	2021	20.00 %	0.00 %	4			\$35,280
Total									21.47 %	22.46 %			\$529,320.00	\$2,356,920

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:




Campus Assessment Report - 1952 Classroom Building

System: B3010120 - Preformed Metal Roofing




Note:

System: C1010 - Partitions



Note:

System: C1020 - Interior Doors



Note:



Campus Assessment Report - 1952 Classroom Building

System: C1030 - Fittings




Note:

System: C3010 - Wall Finishes



Note:


System: C3020 - Floor Finishes



Note:

Campus Assessment Report - 1952 Classroom Building

System: C3030 - Ceiling Finishes




Note:

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:


Campus Assessment Report - 1952 Classroom Building

System: D2030 - Sanitary Waste



Note:

System: D3040 - Distribution Systems



Note:

System: D3050 - Terminal & Package Units



Note:


Campus Assessment Report - 1952 Classroom Building

System: D3060 - Controls & Instrumentation






Note:

System: D5010 - Electrical Service/Distribution



Note:


System: D5020 - Branch Wiring



Note:

Campus Assessment Report - 1952 Classroom Building

System: D5020 - Lighting



Note:

System: D5030810 - Security & Detection Systems



Note:

System: D5030910 - Fire Alarm Systems



Note:

Campus Assessment Report - 1952 Classroom Building

System: D5030920 - Data Communication



Note:

System: E1020 - Institutional Equipment



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$529,320	\$0	\$0	\$335,476	\$849,656	\$4,591	\$27,267	\$0	\$47,489	\$0	\$0	\$1,793,798
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$142,179	\$0	\$0	\$0	\$0	\$0	\$0	\$142,179
B2030 - Exterior Doors	\$14,124	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$14,124
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Preformed Metal Roofing	\$0	\$0	\$0	\$137,290	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$137,290
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$38,479	\$0	\$0	\$0	\$0	\$0	\$0	\$38,479
C1030 - Fittings	\$131,208	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$131,208
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$47,489	\$0	\$0	\$47,489


Campus Assessment Report - 1952 Classroom Building

C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$172,338	\$0	\$0	\$0	\$0	\$0	\$0	\$172,338
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$166,247	\$0	\$0	\$0	\$0	\$0	\$0	\$166,247
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$154,572	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$154,572
D2020 - Domestic Water Distribution	\$13,068	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$13,068
D2030 - Sanitary Waste	\$20,724	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$20,724
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$82,632	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$82,632
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$209,480	\$0	\$0	\$0	\$0	\$0	\$0	\$209,480
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$4,591	\$0	\$0	\$0	\$0	\$0	\$4,591
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$58,212	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$58,212
D4020 - Standpipes	\$9,108	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$9,108
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$27,267	\$0	\$0	\$0	\$0	\$27,267
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$77,255	\$0	\$0	\$0	\$0	\$0	\$0	\$77,255
D5020 - Lighting	\$0	\$0	\$0	\$174,819	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$174,819
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Fire Alarm Systems	\$45,672	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$45,672
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$23,367	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$23,367
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$43,679	\$0	\$0	\$0	\$0	\$0	\$0	\$43,679

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$529,320.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$529,320.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2030	Exterior Doors	\$0.00	\$0.00	\$14,124.00	\$0.00	\$0.00	\$14,124.00
C1030	Fittings	\$0.00	\$0.00	\$131,208.00	\$0.00	\$0.00	\$131,208.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$154,572.00	\$0.00	\$0.00	\$154,572.00
D2020	Domestic Water Distribution	\$0.00	\$0.00	\$13,068.00	\$0.00	\$0.00	\$13,068.00
D2030	Sanitary Waste	\$0.00	\$0.00	\$20,724.00	\$0.00	\$0.00	\$20,724.00
D3040	Distribution Systems	\$0.00	\$0.00	\$82,632.00	\$0.00	\$0.00	\$82,632.00
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$58,212.00	\$0.00	\$58,212.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$9,108.00	\$0.00	\$9,108.00
D5030910	Fire Alarm Systems	\$0.00	\$0.00	\$45,672.00	\$0.00	\$0.00	\$45,672.00
	Total:	\$0.00	\$0.00	\$462,000.00	\$67,320.00	\$0.00	\$529,320.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B2030 - Exterior Doors



Location: Exterior
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 12,000.00
Unit of Measure: S.F.
Estimate: \$14,124.00
Assessor Name: Terence Davis
Date Created: 01/13/2017

Notes: The original metal exterior doors are aged, rusted, damaged and should be replaced with energy efficient doors

System: C1030 - Fittings



Location: Restrooms
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 12,000.00
Unit of Measure: S.F.
Estimate: \$131,208.00
Assessor Name: Terence Davis
Date Created: 01/12/2017

Notes: The bathroom fittings and toilet partitions are aged, worn, damaged and should be replaced. The original fittings are aged, and should be replaced. The room signs are inadequate, do not comply with present requirements and is recommended to replace them.

System: D2010 - Plumbing Fixtures



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 12,000.00
Unit of Measure: S.F.
Estimate: \$154,572.00
Assessor Name: Terence Davis
Date Created: 01/12/2017

Notes: The plumbing fixtures are original beyond its service life, not efficient or low flow fixtures.

System: D2020 - Domestic Water Distribution



Location: Throughout the building.
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 12,000.00
Unit of Measure: S.F.
Estimate: \$13,068.00
Assessor Name: Terence Davis
Date Created: 01/13/2017

Notes: There are no reported issues or observed deficiencies with the domestic water piping. Due to the age of the pipe there can be internal pitting corrosion that may be a costly problem that leads to the formation of pinhole leaks and possible water contamination.

System: D2030 - Sanitary Waste



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 12,000.00
Unit of Measure: S.F.
Estimate: \$20,724.00
Assessor Name: Terence Davis
Date Created: 01/13/2017

Notes: There are no reported issues or observed deficiencies with the sanitary waste piping. The aging sanitary sewer piping is subject to leaks, infiltration, and it can even collapse in the interior walls. The system should be inspected with cameras to ensure that none of these deficiencies exist.

System: D3040 - Distribution Systems



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 12,000.00
Unit of Measure: S.F.
Estimate: \$82,632.00
Assessor Name: Terence Davis
Date Created: 01/13/2017

Notes: The exhaust fans, and hot water supply distribution system is aged, in marginal condition, and should be replaced.

System: D5030910 - Fire Alarm Systems



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 12,000.00
Unit of Measure: S.F.
Estimate: \$45,672.00
Assessor Name: Terence Davis
Date Created: 01/13/2017

Notes: The original alarm system is operating but is aged. The system should be inspected and repaired or replaced to ensure that the life safety codes are preserved.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout the building
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 12,000.00
Unit of Measure: S.F.
Estimate: \$58,212.00
Assessor Name: Terence Davis
Date Created: 01/12/2017

Notes: There are no sprinklers in the building.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout the building
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 12,000.00
Unit of Measure: S.F.
Estimate: \$9,108.00
Assessor Name: Terence Davis
Date Created: 01/12/2017

Notes: There are no sprinklers in the building.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	33,000
Year Built:	1952
Last Renovation:	
Replacement Value:	\$6,889,080
Repair Cost:	\$2,823,348.00
Total FCI:	40.98 %
Total RSLI:	17.24 %
FCA Score:	59.02







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	ES -Elementary School	Gross Area:	33,000
Year Built:	1952	Last Renovation:	
Repair Cost:	\$2,823,348	Replacement Value:	\$6,889,080
FCI:	40.98 %	RSLI%:	17.24 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	35.00 %	0.00 %	\$0.00
A20 - Basement Construction	35.00 %	0.00 %	\$0.00
B10 - Superstructure	35.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	22.92 %	5.77 %	\$37,026.00
B30 - Roofing	6.92 %	66.37 %	\$407,583.00
C10 - Interior Construction	16.15 %	0.00 %	\$0.00
C30 - Interior Finishes	3.33 %	97.80 %	\$794,607.00
D20 - Plumbing	0.18 %	108.66 %	\$498,762.00
D30 - HVAC	15.38 %	46.04 %	\$399,300.00
D40 - Fire Protection	0.00 %	110.00 %	\$177,144.00
D50 - Electrical	21.74 %	32.94 %	\$301,290.00
E10 - Equipment	15.00 %	0.00 %	\$0.00
E20 - Furnishings	0.00 %	110.00 %	\$207,636.00
Totals:	17.24 %	40.98 %	\$2,823,348.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). Northwest Elevation - Jan 10, 2017



2). Northeast Elevation - Jan 10, 2017



3). Southeast Elevation - Jan 10, 2017



4). Southwest Elevation - Jan 10, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Campus Assessment Report - 1952 Main Building

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.70	S.F.	33,000	100	1952	2052		35.00 %	0.00 %	35			\$155,100
A1030	Slab on Grade	\$8.26	S.F.	33,000	100	1952	2052		35.00 %	0.00 %	35			\$272,580
A2010	Basement Excavation	\$1.85	S.F.	33,000	100	1952	2052		35.00 %	0.00 %	35			\$61,050
A2020	Basement Walls	\$12.79	S.F.	33,000	100	1952	2052		35.00 %	0.00 %	35			\$422,070
B1010	Floor Construction	\$1.61	S.F.	33,000	100	1952	2052		35.00 %	0.00 %	35			\$53,130
B1020	Roof Construction	\$15.44	S.F.	33,000	100	1952	2052		35.00 %	0.00 %	35			\$509,520
B2010	Exterior Walls	\$9.24	S.F.	33,000	100	1952	2052		35.00 %	0.00 %	35			\$304,920
B2020	Exterior Windows	\$9.20	S.F.	33,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$303,600
B2030	Exterior Doors	\$1.02	S.F.	33,000	30	1983	2013		0.00 %	110.00 %	-4		\$37,026.00	\$33,660
B3010105	Foam Roofing	\$8.95	S.F.	33,000	25	1952	1977		0.00 %	138.00 %	-40		\$407,583.00	\$295,350
B3010130	Preformed Metal Roofing	\$9.66	S.F.	33,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$318,780
C1010	Partitions	\$10.59	S.F.	33,000	75	1952	2027		13.33 %	0.00 %	10			\$349,470
C1020	Interior Doors	\$2.48	S.F.	33,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$81,840
C1030	Fittings	\$9.54	S.F.	33,000	20	1983	2003	2021	20.00 %	0.00 %	4			\$314,820
C3010	Wall Finishes	\$2.73	S.F.	33,000	10	2010	2020		30.00 %	0.00 %	3			\$90,090
C3020	Floor Finishes	\$11.15	S.F.	33,000	20	1983	2003		0.00 %	110.00 %	-14		\$404,745.00	\$367,950
C3030	Ceiling Finishes	\$10.74	S.F.	33,000	25	1983	2008		0.00 %	110.00 %	-9		\$389,862.00	\$354,420
D2010	Plumbing Fixtures	\$11.26	S.F.	33,000	30	1983	2013		0.00 %	110.00 %	-4		\$408,738.00	\$371,580
D2020	Domestic Water Distribution	\$0.96	S.F.	33,000	30	1952	1982		0.00 %	110.00 %	-35		\$34,848.00	\$31,680
D2030	Sanitary Waste	\$1.52	S.F.	33,000	30	1952	1982		0.00 %	110.00 %	-35		\$55,176.00	\$50,160
D2090	Other Plumbing Systems -Nat Gas	\$0.17	S.F.	33,000	40	1983	2023		15.00 %	0.00 %	6			\$5,610
D3020	Heat Generating Systems	\$4.98	S.F.	33,000	30	1983	2013		0.00 %	110.00 %	-4		\$180,774.00	\$164,340
D3040	Distribution Systems	\$6.02	S.F.	33,000	30	1983	2013		0.00 %	110.00 %	-4		\$218,526.00	\$198,660
D3050	Terminal & Package Units	\$13.37	S.F.	33,000	15	2002	2017	2021	26.67 %	0.00 %	4			\$441,210
D3060	Controls & Instrumentation	\$1.91	S.F.	33,000	20	2002	2022		25.00 %	0.00 %	5			\$63,030
D4010	Sprinklers	\$4.22	S.F.	33,000	30			2016	0.00 %	110.00 %	-1		\$153,186.00	\$139,260
D4020	Standpipes	\$0.66	S.F.	33,000	30			2016	0.00 %	110.00 %	-1		\$23,958.00	\$21,780
D5010	Electrical Service/Distribution	\$1.65	S.F.	33,000	40	1983	2023	2021	10.00 %	0.00 %	4			\$54,450
D5020	Branch Wiring	\$4.99	S.F.	33,000	30	1952	1982		0.00 %	110.00 %	-35		\$181,137.00	\$164,670
D5020	Lighting	\$11.64	S.F.	33,000	30	1990	2020		10.00 %	0.00 %	3			\$384,120
D5030810	Security & Detection Systems	\$1.83	S.F.	33,000	15	2017	2032		100.00 %	0.00 %	15			\$60,390
D5030910	Fire Alarm Systems	\$3.31	S.F.	33,000	15	1983	1998		0.00 %	110.00 %	-19		\$120,153.00	\$109,230
D5030920	Data Communication	\$4.30	S.F.	33,000	15	2012	2027		66.67 %	0.00 %	10			\$141,900
E1020	Institutional Equipment	\$0.30	S.F.	33,000	20	2000	2020		15.00 %	0.00 %	3			\$9,900
E2010	Fixed Furnishings	\$5.72	S.F.	33,000	20	1983	2003		0.00 %	110.00 %	-14		\$207,636.00	\$188,760
Total									17.24 %	40.98 %			\$2,823,348.00	\$6,889,080

System Notes


The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1952 Main Building

System: B3010105 - Foam Roofing



Note:

System: B3010130 - Preformed Metal Roofing



Note:


System: C1010 - Partitions



Note:


Campus Assessment Report - 1952 Main Building

System: C1020 - Interior Doors




Note:

System: C1030 - Fittings



Note:



System: C3010 - Wall Finishes



Note:



Campus Assessment Report - 1952 Main Building

System: C3020 - Floor Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

Campus Assessment Report - 1952 Main Building

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

System: D2090 - Other Plumbing Systems -Nat Gas



Note:


Campus Assessment Report - 1952 Main Building

System: D3020 - Heat Generating Systems



Note:

System: D3040 - Distribution Systems



Note:

System: D3050 - Terminal & Package Units



Note:

Campus Assessment Report - 1952 Main Building

System: D3060 - Controls & Instrumentation



Note:

System: D5010 - Electrical Service/Distribution



Note:



System: D5020 - Branch Wiring



Note:

Campus Assessment Report - 1952 Main Building

System: D5020 - Lighting



Note:

System: D5030810 - Security & Detection Systems



Note:


System: D5030910 - Fire Alarm Systems



Note:


Campus Assessment Report - 1952 Main Building

System: D5030920 - Data Communication



Note: Telephone and PA systems are separate.

System: E1020 - Institutional Equipment



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$2,823,348	\$0	\$0	\$581,900	\$1,975,750	\$80,376	\$7,368	\$0	\$0	\$0	\$209,772	\$5,678,514
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$375,875	\$0	\$0	\$0	\$0	\$0	\$0	\$375,875
B2030 - Exterior Doors	\$37,026	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$37,026
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010105 - Foam Roofing	\$407,583	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$407,583
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$495,129	\$0	\$0	\$0	\$0	\$0	\$0	\$495,129
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$101,323	\$0	\$0	\$0	\$0	\$0	\$0	\$101,323
C1030 - Fittings	\$0	\$0	\$0	\$0	\$389,766	\$0	\$0	\$0	\$0	\$0	\$0	\$389,766
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1952 Main Building

C3010 - Wall Finishes	\$0	\$0	\$0	\$108,288	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$108,288
C3020 - Floor Finishes	\$404,745	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$404,745
C3030 - Ceiling Finishes	\$389,862	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$389,862
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$408,738	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$408,738
D2020 - Domestic Water Distribution	\$34,848	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$34,848
D2030 - Sanitary Waste	\$55,176	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$55,176
D2090 - Other Plumbing Systems -Nat Gas	\$0	\$0	\$0	\$0	\$0	\$0	\$7,368	\$0	\$0	\$0	\$0	\$0	\$7,368
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$180,774	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$180,774
D3040 - Distribution Systems	\$218,526	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$218,526
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$546,244	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$546,244
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$80,376	\$0	\$0	\$0	\$0	\$0	\$0	\$80,376
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$153,186	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$153,186
D4020 - Standpipes	\$23,958	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$23,958
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$67,412	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$67,412
D5020 - Branch Wiring	\$181,137	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$181,137
D5020 - Lighting	\$0	\$0	\$0	\$461,712	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$461,712
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Fire Alarm Systems	\$120,153	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$120,153
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$209,772	\$0	\$209,772
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$11,900	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$11,900
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$207,636	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$207,636

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$2,823,348.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$2,823,348.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2030	Exterior Doors	\$0.00	\$0.00	\$37,026.00	\$0.00	\$0.00	\$37,026.00
B3010105	Foam Roofing	\$0.00	\$0.00	\$407,583.00	\$0.00	\$0.00	\$407,583.00
C3020	Floor Finishes	\$0.00	\$0.00	\$404,745.00	\$0.00	\$0.00	\$404,745.00
C3030	Ceiling Finishes	\$0.00	\$0.00	\$389,862.00	\$0.00	\$0.00	\$389,862.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$408,738.00	\$0.00	\$0.00	\$408,738.00
D2020	Domestic Water Distribution	\$0.00	\$0.00	\$34,848.00	\$0.00	\$0.00	\$34,848.00
D2030	Sanitary Waste	\$0.00	\$0.00	\$55,176.00	\$0.00	\$0.00	\$55,176.00
D3020	Heat Generating Systems	\$0.00	\$0.00	\$180,774.00	\$0.00	\$0.00	\$180,774.00
D3040	Distribution Systems	\$0.00	\$0.00	\$218,526.00	\$0.00	\$0.00	\$218,526.00
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$153,186.00	\$0.00	\$153,186.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$23,958.00	\$0.00	\$23,958.00
D5020	Branch Wiring	\$0.00	\$0.00	\$181,137.00	\$0.00	\$0.00	\$181,137.00
D5030910	Fire Alarm Systems	\$0.00	\$0.00	\$120,153.00	\$0.00	\$0.00	\$120,153.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$207,636.00	\$0.00	\$0.00	\$207,636.00
	Total:	\$0.00	\$0.00	\$2,646,204.00	\$177,144.00	\$0.00	\$2,823,348.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B2030 - Exterior Doors



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 33,000.00
Unit of Measure: S.F.
Estimate: \$37,026.00
Assessor Name: Terence Davis
Date Created: 01/10/2017

Notes: The original metal exterior doors are aged, rusted, damaged and should be replaced with energy efficient doors

System: B3010105 - Foam Roofing



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 33,000.00
Unit of Measure: S.F.
Estimate: \$407,583.00
Assessor Name: Terence Davis
Date Created: 01/10/2017

Notes: The built-up roofing is aged, has reported leaks and should be replaced.

System: C3020 - Floor Finishes



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 33,000.00
Unit of Measure: S.F.
Estimate: \$404,745.00
Assessor Name: Terence Davis
Date Created: 01/13/2017

Notes: The flooring is beyond its service life and it should be replaced.

System: C3030 - Ceiling Finishes



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 33,000.00
Unit of Measure: S.F.
Estimate: \$389,862.00
Assessor Name: Terence Davis
Date Created: 01/10/2017

Notes: The ceiling finishes are beyond their service life and should be replaced.

System: D2010 - Plumbing Fixtures



Location: Restrooms
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 33,000.00
Unit of Measure: S.F.
Estimate: \$408,738.00
Assessor Name: Terence Davis
Date Created: 01/13/2017

Notes: The plumbing fixtures are original beyond its service life, not efficient or low flow fixtures.

System: D2020 - Domestic Water Distribution



Location: Througihut the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 33,000.00
Unit of Measure: S.F.
Estimate: \$34,848.00
Assessor Name: Terence Davis
Date Created: 01/10/2017

Notes: There are no reported issues or observed deficiencies with the domestic water piping. Due to the age of the pipe there can be internal pitting corrosion that may be a costly problem that leads to the formation of pinhole leaks and possible water contamination.

System: D2030 - Sanitary Waste



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 33,000.00
Unit of Measure: S.F.
Estimate: \$55,176.00
Assessor Name: Terence Davis
Date Created: 01/10/2017

Notes: There are no reported issues or observed deficiencies with the sanitary waste piping. The aging sanitary sewer piping is subject to leaks, infiltration, and it can even collapse in the interior walls. The system should be inspected with cameras to ensure that none of these deficiencies exist.

System: D3020 - Heat Generating Systems



Location: Mechanical Room
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 33,000.00
Unit of Measure: S.F.
Estimate: \$180,774.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The original gas fired boiler is aged, inefficient, and becoming logistically unsupportable and should be replaced with an energy efficient model.

System: D3040 - Distribution Systems



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 33,000.00
Unit of Measure: S.F.
Estimate: \$218,526.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The exhaust fans, and hot water supply distribution system is aged, in marginal condition, and should be replaced.

System: D5020 - Branch Wiring



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 33,000.00
Unit of Measure: S.F.
Estimate: \$181,137.00
Assessor Name: Terence Davis
Date Created: 01/13/2017

Notes: The original branch wiring system is operating but is aged, nearing capacity, and should be replaced.

System: D5030910 - Fire Alarm Systems



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 33,000.00
Unit of Measure: S.F.
Estimate: \$120,153.00
Assessor Name: Terence Davis
Date Created: 01/10/2017

Notes: The original alarm system is operating but is aged. The system should be inspected and repaired or replaced to ensure that the life safety codes are preserved.

System: E2010 - Fixed Furnishings



Location: Classroom
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 33,000.00
Unit of Measure: S.F.
Estimate: \$207,636.00
Assessor Name: Terence Davis
Date Created: 01/13/2017

Notes: The building casework is aged and worn and should be replaced.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout the building
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 33,000.00
Unit of Measure: S.F.
Estimate: \$153,186.00
Assessor Name: Terence Davis
Date Created: 01/10/2017

Notes: There are no sprinklers in the building.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout the building
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 33,000.00
Unit of Measure: S.F.
Estimate: \$23,958.00
Assessor Name: Terence Davis
Date Created: 01/10/2017

Notes: There are no sprinklers in the building.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	3,584
Year Built:	1952
Last Renovation:	
Replacement Value:	\$495,561
Repair Cost:	\$296,483.00
Total FCI:	59.83 %
Total RSLI:	14.66 %
FCA Score:	40.17







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	ES -Elementary School	Gross Area:	3,584
Year Built:	1952	Last Renovation:	
Repair Cost:	\$296,483	Replacement Value:	\$495,561
FCI:	59.83 %	RSLI%:	14.66 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	35.00 %	0.00 %	\$0.00
A20 - Basement Construction	35.00 %	0.00 %	\$0.00
B10 - Superstructure	35.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	31.52 %	10.93 %	\$4,021.00
B30 - Roofing	0.00 %	146.00 %	\$22,605.00
C10 - Interior Construction	10.80 %	20.87 %	\$9,777.00
C30 - Interior Finishes	0.00 %	110.00 %	\$97,062.00
D20 - Plumbing	0.00 %	110.00 %	\$54,168.00
D30 - HVAC	0.00 %	110.00 %	\$23,733.00
D50 - Electrical	0.00 %	110.00 %	\$85,117.00
Totals:	14.66 %	59.83 %	\$296,483.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). South Elevation - Feb 21, 2017



2). East Elevation - Feb 21, 2017



3). West Elevation - Feb 21, 2017



4). Northeast Elevation - Jan 10, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.70	S.F.	3,584	100	1952	2052		35.00 %	0.00 %	35			\$16,845
A1030	Slab on Grade	\$8.26	S.F.	3,584	100	1952	2052		35.00 %	0.00 %	35			\$29,604
A2010	Basement Excavation	\$1.85	S.F.	3,584	100	1952	2052		35.00 %	0.00 %	35			\$6,630
A2020	Basement Walls	\$12.79	S.F.	3,584	100	1952	2052		35.00 %	0.00 %	35			\$45,839
B1010	Floor Construction	\$1.61	S.F.	3,584	100	1952	2052		35.00 %	0.00 %	35			\$5,770
B1020	Roof Construction	\$15.44	S.F.	3,584	100	1952	2052		35.00 %	0.00 %	35			\$55,337
B2010	Exterior Walls	\$9.24	S.F.	3,584	100	1952	2052		35.00 %	0.00 %	35			\$33,116
B2030	Exterior Doors	\$1.02	S.F.	3,584	30	1952	1982		0.00 %	109.98 %	-35		\$4,021.00	\$3,656
B3010140	Asphalt Shingles	\$4.32	S.F.	3,584	20	1952	1972		0.00 %	146.00 %	-45		\$22,605.00	\$15,483
C1010	Partitions	\$10.59	S.F.	3,584	75	1952	2027		13.33 %	0.00 %	10			\$37,955
C1020	Interior Doors	\$2.48	S.F.	3,584	30	1952	1982		0.00 %	110.00 %	-35		\$9,777.00	\$8,888
C3010	Wall Finishes	\$2.73	S.F.	3,584	10	1952	1962		0.00 %	110.01 %	-55		\$10,763.00	\$9,784
C3020	Floor Finishes	\$11.15	S.F.	3,584	20	1952	1972		0.00 %	110.00 %	-45		\$43,958.00	\$39,962
C3030	Ceiling Finishes	\$10.74	S.F.	3,584	25	1952	1977		0.00 %	110.00 %	-40		\$42,341.00	\$38,492
D2010	Plumbing Fixtures	\$11.26	S.F.	3,584	30	1952	1982		0.00 %	110.00 %	-35		\$44,391.00	\$40,356
D2020	Domestic Water Distribution	\$0.96	S.F.	3,584	30	1952	1982		0.00 %	110.00 %	-35		\$3,785.00	\$3,441
D2030	Sanitary Waste	\$1.52	S.F.	3,584	30	1952	1982		0.00 %	109.99 %	-35		\$5,992.00	\$5,448
D3040	Distribution Systems	\$6.02	S.F.	3,584	30	1952	1982		0.00 %	110.00 %	-35		\$23,733.00	\$21,576
D5010	Electrical Service/Distribution	\$1.65	S.F.	3,584	40	1952	1992		0.00 %	109.99 %	-25		\$6,505.00	\$5,914
D5020	Branch Wiring	\$4.99	S.F.	3,584	30	1952	1982		0.00 %	110.00 %	-35		\$19,673.00	\$17,884
D5020	Lighting	\$11.64	S.F.	3,584	30	1952	1982		0.00 %	110.00 %	-35		\$45,890.00	\$41,718
D5030910	Fire Alarm Systems	\$3.31	S.F.	3,584	15	1952	1967		0.00 %	110.00 %	-50		\$13,049.00	\$11,863
Total									14.66 %	59.83 %			\$296,483.00	\$495,561

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2030 - Exterior Doors



Note:

System: B3010140 - Asphalt Shingles



Note:

Campus Assessment Report - 1952 Storage

System: C1010 - Partitions



Note:

System: C1020 - Interior Doors



Note:

System: C3010 - Wall Finishes



Note:

Campus Assessment Report - 1952 Storage

System: C3020 - Floor Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

Campus Assessment Report - 1952 Storage

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

System: D3040 - Distribution Systems



Note:

Campus Assessment Report - 1952 Storage

System: D5010 - Electrical Service/Distribution



Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Campus Assessment Report - 1952 Storage

System: D5030910 - Fire Alarm Systems



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$296,483	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$14,465	\$310,948
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$4,021	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,021
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$22,605	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$22,605
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$9,777	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$9,777
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$10,763	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$14,465	\$25,228
C3020 - Floor Finishes	\$43,958	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$43,958
C3030 - Ceiling Finishes	\$42,341	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$42,341


Campus Assessment Report - 1952 Storage

D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$44,391	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$44,391
D2020 - Domestic Water Distribution	\$3,785	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,785
D2030 - Sanitary Waste	\$5,992	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$5,992
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$23,733	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$23,733
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$6,505	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$6,505
D5020 - Branch Wiring	\$19,673	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$19,673
D5020 - Lighting	\$45,890	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$45,890
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Fire Alarm Systems	\$13,049	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$13,049

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$296,483.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$296,483.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2030	Exterior Doors	\$4,021.00	\$0.00	\$0.00	\$0.00	\$0.00	\$4,021.00
B3010140	Asphalt Shingles	\$0.00	\$0.00	\$22,605.00	\$0.00	\$0.00	\$22,605.00
C1020	Interior Doors	\$0.00	\$0.00	\$9,777.00	\$0.00	\$0.00	\$9,777.00
C3010	Wall Finishes	\$10,763.00	\$0.00	\$0.00	\$0.00	\$0.00	\$10,763.00
C3020	Floor Finishes	\$0.00	\$0.00	\$43,958.00	\$0.00	\$0.00	\$43,958.00
C3030	Ceiling Finishes	\$42,341.00	\$0.00	\$0.00	\$0.00	\$0.00	\$42,341.00
D2010	Plumbing Fixtures	\$44,391.00	\$0.00	\$0.00	\$0.00	\$0.00	\$44,391.00
D2020	Domestic Water Distribution	\$3,785.00	\$0.00	\$0.00	\$0.00	\$0.00	\$3,785.00
D2030	Sanitary Waste	\$5,992.00	\$0.00	\$0.00	\$0.00	\$0.00	\$5,992.00
D3040	Distribution Systems	\$0.00	\$0.00	\$23,733.00	\$0.00	\$0.00	\$23,733.00
D5010	Electrical Service/Distribution	\$6,505.00	\$0.00	\$0.00	\$0.00	\$0.00	\$6,505.00
D5020	Branch Wiring	\$19,673.00	\$0.00	\$0.00	\$0.00	\$0.00	\$19,673.00
D5020	Lighting	\$45,890.00	\$0.00	\$0.00	\$0.00	\$0.00	\$45,890.00
D5030910	Fire Alarm Systems	\$13,049.00	\$0.00	\$0.00	\$0.00	\$0.00	\$13,049.00
	Total:	\$196,410.00	\$0.00	\$100,073.00	\$0.00	\$0.00	\$296,483.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Currently Critical (Immediate):

System: B2030 - Exterior Doors



Location: Exterior
Distress: Damaged
Category: Deferred Maintenance
Priority: 1 - Currently Critical (Immediate)
Correction: Renew System
Qty: 3,584.00
Unit of Measure: S.F.
Estimate: \$4,021.00
Assessor Name: Eduardo Lopez
Date Created: 01/10/2017

Notes: The original metal exterior doors are aged, rusted, damaged and should be replaced with energy efficient doors.

System: C3010 - Wall Finishes



Location: Throughout the building
Distress: Damaged
Category: Deferred Maintenance
Priority: 1 - Currently Critical (Immediate)
Correction: Renew System
Qty: 3,584.00
Unit of Measure: S.F.
Estimate: \$10,763.00
Assessor Name: Eduardo Lopez
Date Created: 01/10/2017

Notes: The original painted wall finish is aged, chipped, stained and should be replaced.

System: C3030 - Ceiling Finishes



Location: Throughout the building
Distress: Damaged
Category: Deferred Maintenance
Priority: 1 - Currently Critical (Immediate)
Correction: Renew System
Qty: 3,584.00
Unit of Measure: S.F.
Estimate: \$42,341.00
Assessor Name: Eduardo Lopez
Date Created: 01/10/2017

Notes: The original ceiling finish is aged, chipped, stained and should be replaced.

System: D2010 - Plumbing Fixtures



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 1 - Currently Critical (Immediate)
Correction: Renew System
Qty: 3,584.00
Unit of Measure: S.F.
Estimate: \$44,391.00
Assessor Name: Eduardo Lopez
Date Created: 01/10/2017

Notes: The original plumbing fixtures are aged, chipped, stained, showing signs of failure and should be replaced.

System: D2020 - Domestic Water Distribution



Location: Throughout the building
Distress: Failing
Category: Deferred Maintenance
Priority: 1 - Currently Critical (Immediate)
Correction: Renew System
Qty: 3,584.00
Unit of Measure: S.F.
Estimate: \$3,785.00
Assessor Name: Eduardo Lopez
Date Created: 01/10/2017

Notes: The original copper water distribution system is aged, corroded, has reported leaks and should be replaced.

System: D2030 - Sanitary Waste



Location: Restroom
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 1 - Currently Critical (Immediate)
Correction: Renew System
Qty: 3,584.00
Unit of Measure: S.F.
Estimate: \$5,992.00
Assessor Name: Eduardo Lopez
Date Created: 01/10/2017

Notes: The original sanitary waste system is operating but is in poor condition and should be replaced.

System: D5010 - Electrical Service/Distribution



Location: Throughout
Distress: Damaged
Category: Deferred Maintenance
Priority: 1 - Currently Critical (Immediate)
Correction: Renew System
Qty: 3,584.00
Unit of Measure: S.F.
Estimate: \$6,505.00
Assessor Name: Eduardo Lopez
Date Created: 01/10/2017

Notes: The original distribution wiring system is damaged, in poor condition and should be replaced.

System: D5020 - Branch Wiring



Location: Throughout the building
Distress: Damaged
Category: Deferred Maintenance
Priority: 1 - Currently Critical (Immediate)
Correction: Renew System
Qty: 3,584.00
Unit of Measure: S.F.
Estimate: \$19,673.00
Assessor Name: Eduardo Lopez
Date Created: 01/10/2017

Notes: The original branch wiring system is damaged, aged, in poor condition and should be replaced.


System: D5020 - Lighting



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 1 - Currently Critical (Immediate)
Correction: Renew System
Qty: 3,584.00
Unit of Measure: S.F.
Estimate: \$45,890.00
Assessor Name: Eduardo Lopez
Date Created: 01/10/2017

Notes: The original lighting system is operating properly but is aged, inefficient, in poor condition and should be replaced with an energy efficient system.

System: D5030910 - Fire Alarm Systems



Location: Throughout the building
Distress: Beyond Service Life
Category: Building Code Compliance
Priority: 1 - Currently Critical (Immediate)
Correction: Renew System
Qty: 3,584.00
Unit of Measure: S.F.
Estimate: \$13,049.00
Assessor Name: Eduardo Lopez
Date Created: 01/10/2017

Notes: The original fire alarm system is aged and should be replaced.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B3010140 - Asphalt Shingles



Location: Roof
Distress: Damaged
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 3,584.00
Unit of Measure: S.F.
Estimate: \$22,605.00
Assessor Name: Eduardo Lopez
Date Created: 01/10/2017

Notes: The roofing is aged, has reported leaks and should be replaced.

System: C1020 - Interior Doors



Location: Throughout the building
Distress: Damaged
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 3,584.00
Unit of Measure: S.F.
Estimate: \$9,777.00
Assessor Name: Eduardo Lopez
Date Created: 01/10/2017

Notes: The original wood interior doors are aged, worn and should be replaced.

System: C3020 - Floor Finishes



Location: Throughout the building
Distress: Damaged
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 3,584.00
Unit of Measure: S.F.
Estimate: \$43,958.00
Assessor Name: Eduardo Lopez
Date Created: 01/10/2017

Notes: The original floor finish is aged, chipped, stained and should be replaced.

System: D3040 - Distribution Systems



Location: Throughout the building
Distress: Failing
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 3,584.00
Unit of Measure: S.F.
Estimate: \$23,733.00
Assessor Name: Eduardo Lopez
Date Created: 01/10/2017

Notes: The original distribution system is operating but is in poor condition and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	48,584
Year Built:	1952
Last Renovation:	
Replacement Value:	\$1,502,702
Repair Cost:	\$274,694.00
Total FCI:	18.28 %
Total RSLI:	15.86 %
FCA Score:	81.72







Description:

The narrative for this site is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	ES -Elementary School	Gross Area:	48,584
Year Built:	1952	Last Renovation:	
Repair Cost:	\$274,694	Replacement Value:	\$1,502,702
FCI:	18.28 %	RSLI%:	15.86 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	10.98 %	33.34 %	\$274,694.00
G30 - Site Mechanical Utilities	8.74 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	47.83 %	0.00 %	\$0.00
Totals:	15.86 %	18.28 %	\$274,694.00

Photo Album

The photo album consists of the various cardinal directions of the building..

- 1). Aerial Image of I E Johnson Elementary School - Feb 27, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$3.81	S.F.	48,584	25	1983	2008		0.00 %	110.00 %	-9		\$203,616.00	\$185,105
G2020	Parking Lots	\$1.33	S.F.	48,584	25	1983	2008		0.00 %	110.00 %	-9		\$71,078.00	\$64,617
G2030	Pedestrian Paving	\$1.91	S.F.	48,584	30	1983	2013	2021	13.33 %	0.00 %	4			\$92,795
G2040105	Fence & Guardrails	\$1.23	S.F.	48,584	30	2000	2030		43.33 %	0.00 %	13			\$59,758
G2040950	Covered Walkways	\$1.52	S.F.	48,584	25	1983	2008	2021	16.00 %	0.00 %	4			\$73,848
G2040950	Hard Surface Play Area	\$0.75	S.F.	48,584	20	1952	1972	2021	20.00 %	0.00 %	4			\$36,438
G2040950	Playing Field	\$4.54	S.F.	48,584	20	2000	2020		15.00 %	0.00 %	3			\$220,571
G2050	Landscaping	\$1.87	S.F.	48,584	15	1952	1967		0.00 %	0.00 %	-50			\$90,852
G3010	Water Supply	\$2.34	S.F.	48,584	50	1952	2002	2021	8.00 %	0.00 %	4			\$113,687
G3020	Sanitary Sewer	\$1.45	S.F.	48,584	50	1952	2002	2021	8.00 %	0.00 %	4			\$70,447
G3030	Storm Sewer	\$4.54	S.F.	48,584	50	1952	2002	2021	8.00 %	0.00 %	4			\$220,571
G3060	Fuel Distribution	\$0.98	S.F.	48,584	40	1983	2023		15.00 %	0.00 %	6			\$47,612
G4010	Electrical Distribution	\$2.35	S.F.	48,584	50	1983	2033		32.00 %	0.00 %	16			\$114,172
G4020	Site Lighting	\$1.47	S.F.	48,584	30	2000	2030		43.33 %	0.00 %	13			\$71,418
G4030	Site Communications & Security	\$0.84	S.F.	48,584	15	2017	2032		100.00 %	0.00 %	15			\$40,811
Total									15.86 %	18.28 %			\$274,694.00	\$1,502,702

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: G2010 - Roadways



Note:

System: G2020 - Parking Lots



Note:

System: G2030 - Pedestrian Paving



Note:

Campus Assessment Report - Site

System: G2040105 - Fence & Guardrails



Note:

System: G2040950 - Covered Walkways



Note:

System: G2040950 - Hard Surface Play Area



Note:

Campus Assessment Report - Site

System: G2040950 - Playing Field



Note:

System: G2050 - Landscaping



Note:

System: G3010 - Water Supply



Note:

Campus Assessment Report - Site

System: G3020 - Sanitary Sewer



Note:

System: G3030 - Storm Sewer



Note:

System: G3060 - Fuel Distribution



Note:

Campus Assessment Report - Site

System: G4010 - Electrical Distribution



Note:

System: G4020 - Site Lighting



Note:

System: G4030 - Site Communications & Security



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$274,694	\$0	\$0	\$265,126	\$752,474	\$0	\$62,537	\$0	\$0	\$0	\$0	\$1,354,831
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$203,616	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$203,616
G2020 - Parking Lots	\$71,078	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$71,078
G2030 - Pedestrian Paving	\$0	\$0	\$0	\$0	\$114,886	\$0	\$0	\$0	\$0	\$0	\$0	\$114,886
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040105 - Fence & Guardrails	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040950 - Covered Walkways	\$0	\$0	\$0	\$0	\$91,427	\$0	\$0	\$0	\$0	\$0	\$0	\$91,427
G2040950 - Hard Surface Play Area	\$0	\$0	\$0	\$0	\$45,113	\$0	\$0	\$0	\$0	\$0	\$0	\$45,113
G2040950 - Playing Field	\$0	\$0	\$0	\$265,126	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$265,126
* G2050 - Landscaping	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$0	\$0	\$0	\$0	\$140,751	\$0	\$0	\$0	\$0	\$0	\$0	\$140,751
G3020 - Sanitary Sewer	\$0	\$0	\$0	\$0	\$87,217	\$0	\$0	\$0	\$0	\$0	\$0	\$87,217
G3030 - Storm Sewer	\$0	\$0	\$0	\$0	\$273,080	\$0	\$0	\$0	\$0	\$0	\$0	\$273,080
G3060 - Fuel Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$62,537	\$0	\$0	\$0	\$0	\$62,537
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

** Indicates non-renewable system*


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$274,694.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
G2010	Roadways	\$0.00	\$0.00	\$203,616.00	\$0.00	\$0.00	\$203,616.00
G2020	Parking Lots	\$0.00	\$0.00	\$71,078.00	\$0.00	\$0.00	\$71,078.00
	Total:	\$0.00	\$0.00	\$274,694.00	\$0.00	\$0.00	\$274,694.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):


System: G2010 - Roadways



Location: Site
Distress: Damaged
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 48,584.00
Unit of Measure: S.F.
Estimate: \$203,616.00
Assessor Name: Terence Davis
Date Created: 12/29/2016

Notes: The asphaltic roadways are aged, have many road cuts, pot holes, significant cracking, and need re-surfacing.

System: G2020 - Parking Lots



Location: Site
Distress: Damaged
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 48,584.00
Unit of Measure: S.F.
Estimate: \$71,078.00
Assessor Name: Terence Davis
Date Created: 12/29/2016

Notes: The asphaltic parking lots are aged, have cuts and repairs, and should be re-surfaced and restriped.

NC School District/830 Scotland County/Elementary School

Laurel Hill Elementary

Draft

Campus Assessment Report

March 7, 2017



Table of Contents

Campus Executive Summary	4
Campus Dashboard Summary	7
Campus Condition Summary	8
<u>1999 Main Building</u>	10
Executive Summary	10
Dashboard Summary	11
Condition Summary	12
Photo Album	13
Condition Detail	14
System Listing	15
System Notes	17
Renewal Schedule	27
Forecasted Sustainment Requirement	30
Deficiency Summary By System	31
Deficiency Summary By Priority	32
Deficiency By Priority Investment	33
Deficiency Summary By Category	34
Deficiency Details By Priority	35
<u>Site</u>	36
Executive Summary	36
Dashboard Summary	37
Condition Summary	38
Photo Album	39
Condition Detail	40
System Listing	41
System Notes	42
Renewal Schedule	48
Forecasted Sustainment Requirement	49
Deficiency Summary By System	50

Campus Assessment Report

Deficiency Summary By Priority	51
Deficiency By Priority Investment	52
Deficiency Summary By Category	53
Deficiency Details By Priority	54

Campus Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	75,150
Year Built:	1999
Last Renovation:	
Replacement Value:	\$17,536,264
Repair Cost:	\$403,405.00
Total FCI:	2.30 %
Total RSLI:	45.38 %
FCA Score:	97.70



Description:

GENERAL:

Laurel Hill Elementary is located at 11340 Old Wire Road in Laurinburg, North Carolina. The 1 story, 75,150 square foot building was originally constructed in 1999. There have been no additions to the building.

This report contains condition and adequacy data collected during the 2016-2017 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for the site and building elements.

A. SUBSTRUCTURE

The building rests on slab-on grade and is assumed to have standard cast-in-place concrete foundations. The building does not have a basement.

Campus Assessment Report - Laurel Hill Elementary

B. SUPERSTRUCTURE

Floor construction is concrete. Roof construction is metal pan deck with lightweight fill. The exterior envelope is composed of walls of brick veneer over CMU. Exterior windows are aluminum frame with operable panes. Exterior doors are Tubelite architectural aluminum with glazing. Roofing is typically performed metal roof covering. Building entrances appear to comply with ADA requirements.

C. INTERIORS

Interior partitions are typically CMU. Interior doors are generally solid core wood with hollow steel frames and mostly with glazing. Interior fittings include the following items: white boards, graphics and identifying devices, toilet accessories, storage shelving, fabricated toilet partitions. The interior wall finishes are typically painted CMU. Floor finishes in common areas are typically vinyl composition tile. Floor finishes in assignable spaces is typically ceramic tiles, and quarry tiles. Ceiling finishes in common areas are typically suspended acoustical tile. Ceiling finishes in assignable areas are typically painted drywall.

CONVEYING:

The building does not include conveying equipment.

D. SERVICES

PLUMBING: Plumbing fixtures are typically non-low-flow water fixtures with manual control valves. Domestic water distribution is combination of copper and galvanized steel with gas hot water heating. Sanitary waste system is cast iron. Rain water drainage system is internal with roof drains. Other plumbing systems is supplied by natural gas.

HVAC:

Heating is provided by a gas fired boilers. Cooling is supplied a forced draft, centrifugal fan cooling tower. The heating/cooling distribution system is a duct work system utilizing air handling units. Fresh air is supplied by air handling units.. Ceiling mounted exhaust fans are installed in bathrooms and other required areas. Controls and instrumentation are digital and are centrally controlled by an energy management system. This building has a remote Building Automation System.

FIRE PROTECTION:

The building does not have a fire sprinkler system. Fire extinguishers and cabinets are distributed near fire exits and corridors.

ELECTRICAL:

The main electrical service is fed from a pad mounted transformer to the main switchboard/distribution panel located in the building. Lighting is lay-in type, fluorescent light fixtures. Branch circuit wiring is typically copper serving electrical switches and receptacles. Emergency and life safety egress lighting systems are installed and exit signs are present at exit doors and near stairways and are typically illuminated.

COMMUNICATIONS AND SECURITY:

The fire alarm system consists of audible/visual strobe annunciators in interior corridors. The system is activated by manual pull stations and smoke detectors and the system is centrally monitored. The telephone and data systems are segregated and include dedicated equipment closets. This building does have a local area network (LAN). The building does not include an internal security system. The building has controlled entry door access provided by card readers; entry doors are secured with magnetic door locks. The security system has CCTV cameras and is centrally monitored; this building has a public address and paging system combined with the telephone system.

OTHER ELECTRICAL SYSTEMS:

This building does not have a separately derived emergency power system.

E. EQUIPMENT & FURNISHINGS:

This building includes the following items and equipment: fixed food service, library equipment, audio-visual, fixed casework, and window treatment.

G. SITE

Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, play areas, and fencing. Site mechanical and electrical features include water, sewer, natural gas, and site lighting.

Campus Assessment Report - Laurel Hill Elementary

Attributes:

General Attributes:





Condition Assessor:	Terence Davis	Assessment Date:	
Suitability Assessor:			

School Information:

HS Attendance Area:		LEA School No.:	
No. of Mobile Units:	0	No. of Bldgs.:	1
SF of Mobile Units:		Status:	
School Grades:	20	Site Acreage:	20

Campus Dashboard Summary

Gross Area:	75,150	Last Renovation:	
Year Built:	1999	Replacement Value:	\$17,536,264
Repair Cost:	\$403,405	RSLI%:	45.38 %
FCI:	2.30 %		



Campus Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Unifomat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	82.00 %	0.00 %	\$0.00
A20 - Basement Construction	82.00 %	0.00 %	\$0.00
B10 - Superstructure	82.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	59.94 %	0.00 %	\$0.00
B30 - Roofing	39.65 %	0.00 %	\$0.00
C10 - Interior Construction	44.20 %	0.00 %	\$0.00
C30 - Interior Finishes	25.61 %	0.00 %	\$0.00
D20 - Plumbing	40.18 %	0.00 %	\$0.00
D30 - HVAC	31.10 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	110.00 %	\$403,405.00
D50 - Electrical	37.15 %	0.00 %	\$0.00
E10 - Equipment	10.00 %	0.00 %	\$0.00
E20 - Furnishings	10.00 %	0.00 %	\$0.00
G20 - Site Improvements	21.68 %	0.00 %	\$0.00
G30 - Site Mechanical Utilities	63.05 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	61.72 %	0.00 %	\$0.00
Totals:	45.38 %	2.30 %	\$403,405.00

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance
1999 Main Building	75,150	2.66	\$0.00	\$0.00	\$0.00	\$403,405.00	\$0.00
Site	75,150	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
Total:		2.30	\$0.00	\$0.00	\$0.00	\$403,405.00	\$0.00

Deficiencies By Priority



- 1 - Currently Critical (Immediate)
- 2 - Potentially Critical (Year 1)
- 3 - Necessary/Not Yet Critical (Years 2-5)
- 4 - Recommended (Years 6-10) - \$403,405.00
- 5 - Codes or Standards Compliance

Budget Estimate Total: \$403,405.00

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as $100 - \text{Total FCI}$ (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	75,150
Year Built:	1999
Last Renovation:	
Replacement Value:	\$15,178,804
Repair Cost:	\$403,405.00
Total FCI:	2.66 %
Total RSLI:	46.23 %
FCA Score:	97.34







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	ES -Elementary School	Gross Area:	75,150
Year Built:	1999	Last Renovation:	
Repair Cost:	\$403,405	Replacement Value:	\$15,178,804
FCI:	2.66 %	RSLI%:	46.23 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	82.00 %	0.00 %	\$0.00
A20 - Basement Construction	82.00 %	0.00 %	\$0.00
B10 - Superstructure	82.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	59.94 %	0.00 %	\$0.00
B30 - Roofing	39.65 %	0.00 %	\$0.00
C10 - Interior Construction	44.20 %	0.00 %	\$0.00
C30 - Interior Finishes	25.61 %	0.00 %	\$0.00
D20 - Plumbing	40.18 %	0.00 %	\$0.00
D30 - HVAC	31.10 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	110.00 %	\$403,405.00
D50 - Electrical	37.15 %	0.00 %	\$0.00
E10 - Equipment	10.00 %	0.00 %	\$0.00
E20 - Furnishings	10.00 %	0.00 %	\$0.00
Totals:	46.23 %	2.66 %	\$403,405.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). South Elevation - Jan 11, 2017



2). West Elevation - Jan 11, 2017



3). North Elevation - Jan 11, 2017



4). East Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Campus Assessment Report - 1999 Main Building

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.70	S.F.	75,150	100	1999	2099		82.00 %	0.00 %	82			\$353,205
A1030	Slab on Grade	\$8.26	S.F.	75,150	100	1999	2099		82.00 %	0.00 %	82			\$620,739
A2010	Basement Excavation	\$1.85	S.F.	75,150	100	1999	2099		82.00 %	0.00 %	82			\$139,028
A2020	Basement Walls	\$12.79	S.F.	75,150	100	1999	2099		82.00 %	0.00 %	82			\$961,169
B1010	Floor Construction	\$1.61	S.F.	75,150	100	1999	2099		82.00 %	0.00 %	82			\$120,992
B1020	Roof Construction	\$15.44	S.F.	75,150	100	1999	2099		82.00 %	0.00 %	82			\$1,160,316
B2010	Exterior Walls	\$9.24	S.F.	75,150	100	1999	2099		82.00 %	0.00 %	82			\$694,386
B2020	Exterior Windows	\$9.20	S.F.	75,150	30	1999	2029		40.00 %	0.00 %	12			\$691,380
B2030	Exterior Doors	\$1.02	S.F.	75,150	30	1999	2029		40.00 %	0.00 %	12			\$76,653
B3010130	Preformed Metal Roofing	\$9.66	S.F.	75,150	30	1999	2029		40.00 %	0.00 %	12			\$725,949
B3020	Roof Openings	\$0.29	S.F.	75,150	25	1999	2024		28.00 %	0.00 %	7			\$21,794
C1010	Partitions	\$10.59	S.F.	75,150	75	1999	2074		76.00 %	0.00 %	57			\$795,839
C1020	Interior Doors	\$2.48	S.F.	75,150	30	1999	2029		40.00 %	0.00 %	12			\$186,372
C1030	Fittings	\$9.54	S.F.	75,150	20	1999	2019		10.00 %	0.00 %	2			\$716,931
C3010	Wall Finishes	\$2.73	S.F.	75,150	10	2015	2025		80.00 %	0.00 %	8			\$205,160
C3020	Floor Finishes	\$11.15	S.F.	75,150	20	1999	2019		10.00 %	0.00 %	2			\$837,923
C3030	Ceiling Finishes	\$10.74	S.F.	75,150	25	1999	2024		28.00 %	0.00 %	7			\$807,111
D2010	Plumbing Fixtures	\$11.26	S.F.	75,150	30	1999	2029		40.00 %	0.00 %	12			\$846,189
D2020	Domestic Water Distribution	\$0.96	S.F.	75,150	30	1999	2029		40.00 %	0.00 %	12			\$72,144
D2030	Sanitary Waste	\$1.52	S.F.	75,150	30	1999	2029		40.00 %	0.00 %	12			\$114,228
D2090	Other Plumbing Systems -Nat Gas	\$0.17	S.F.	75,150	40	1999	2039		55.00 %	0.00 %	22			\$12,776
D3020	Heat Generating Systems	\$4.98	S.F.	75,150	30	1999	2029		40.00 %	0.00 %	12			\$374,247
D3030	Cooling Generating Systems	\$5.16	S.F.	75,150	25	1999	2024		28.00 %	0.00 %	7			\$387,774
D3040	Distribution Systems	\$6.02	S.F.	75,150	30	1999	2029		40.00 %	0.00 %	12			\$452,403
D3050	Terminal & Package Units	\$7.93	S.F.	75,150	15	1999	2014	2021	26.67 %	0.00 %	4			\$595,940
D3060	Controls & Instrumentation	\$1.91	S.F.	75,150	20	1999	2019		10.00 %	0.00 %	2			\$143,537
D3090	Other HVAC Systems/Equip	\$0.30	S.F.	75,150	20	1999	2019		10.00 %	0.00 %	2			\$22,545
D4010	Sprinklers	\$4.22	S.F.	75,150	30			2016	0.00 %	110.00 %	-1		\$348,846.00	\$317,133
D4020	Standpipes	\$0.66	S.F.	75,150	30			2016	0.00 %	110.00 %	-1		\$54,559.00	\$49,599
D5010	Electrical Service/Distribution	\$1.65	S.F.	75,150	40	1999	2039		55.00 %	0.00 %	22			\$123,998
D5020	Branch Wiring	\$4.99	S.F.	75,150	30	1999	2029		40.00 %	0.00 %	12			\$374,999
D5020	Lighting	\$11.64	S.F.	75,150	30	1999	2029		40.00 %	0.00 %	12			\$874,746
D5030810	Security & Detection Systems	\$1.83	S.F.	75,150	15	1999	2014	2021	26.67 %	0.00 %	4			\$137,525
D5030910	Fire Alarm Systems	\$3.31	S.F.	75,150	15	2007	2022		33.33 %	0.00 %	5			\$248,747
D5030920	Data Communication	\$4.30	S.F.	75,150	15	1999	2014	2021	26.67 %	0.00 %	4			\$323,145
E1020	Institutional Equipment	\$0.30	S.F.	75,150	20	1999	2019		10.00 %	0.00 %	2			\$22,545
E1090	Other Equipment	\$1.86	S.F.	75,150	20	1999	2019		10.00 %	0.00 %	2			\$139,779
E2010	Fixed Furnishings	\$5.72	S.F.	75,150	20	1999	2019		10.00 %	0.00 %	2			\$429,858
Total									46.23 %	2.66 %			\$403,405.00	\$15,178,804

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1999 Main Building

System: B3010130 - Preformed Metal Roofing



Note:

System: B3020 - Roof Openings



Note:


System: C1010 - Partitions



Note:

Campus Assessment Report - 1999 Main Building

System: C1020 - Interior Doors



Note:

System: C1030 - Fittings



Note:

System: C3010 - Wall Finishes



Note:


Campus Assessment Report - 1999 Main Building

System: C3020 - Floor Finishes






Note:

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

Campus Assessment Report - 1999 Main Building

System: D2020 - Domestic Water Distribution




Note:

System: D2030 - Sanitary Waste



Note:

System: D2090 - Other Plumbing Systems -Nat Gas



Note:

Campus Assessment Report - 1999 Main Building

System: D3020 - Heat Generating Systems



Note:

System: D3030 - Cooling Generating Systems



Note:

System: D3040 - Distribution Systems



Note:

Campus Assessment Report - 1999 Main Building

System: D3050 - Terminal & Package Units



Note:

System: D3060 - Controls & Instrumentation



Note:

System: D3090 - Other HVAC Systems/Equip



Note:

Campus Assessment Report - 1999 Main Building

System: D5010 - Electrical Service/Distribution




Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Campus Assessment Report - 1999 Main Building

System: D5030810 - Security & Detection Systems




Note:

System: D5030910 - Fire Alarm Systems



Note:


System: D5030920 - Data Communication



Note:

Campus Assessment Report - 1999 Main Building

System: E1020 - Institutional Equipment



Note:

System: E1090 - Other Equipment



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$403,405	\$0	\$2,699,386	\$0	\$1,308,145	\$317,202	\$0	\$1,645,997	\$285,878	\$0	\$0	\$6,660,013
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$29,484	\$0	\$0	\$0	\$29,484
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$836,651	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$836,651
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1999 Main Building

C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$285,878	\$0	\$0	\$285,878
C3020 - Floor Finishes	\$0	\$0	\$977,847	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$977,847
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,091,909	\$0	\$0	\$0	\$1,091,909
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2090 - Other Plumbing Systems -Nat Gas	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$524,604	\$0	\$0	\$0	\$524,604
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$737,808	\$0	\$0	\$0	\$0	\$0	\$0	\$737,808
D3060 - Controls & Instrumentation	\$0	\$0	\$167,506	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$167,506
D3090 - Other HVAC Systems/Equip	\$0	\$0	\$26,310	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$26,310
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$348,846	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$348,846
D4020 - Standpipes	\$54,559	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$54,559
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$170,264	\$0	\$0	\$0	\$0	\$0	\$0	\$170,264
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$0	\$317,202	\$0	\$0	\$0	\$0	\$0	\$317,202
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$400,073	\$0	\$0	\$0	\$0	\$0	\$0	\$400,073
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$26,310	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$26,310
E1090 - Other Equipment	\$0	\$0	\$163,121	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$163,121
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$501,640	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$501,640

** Indicates non-renewable system*


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$403,405.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$348,846.00	\$0.00	\$348,846.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$54,559.00	\$0.00	\$54,559.00
	Total:	\$0.00	\$0.00	\$0.00	\$403,405.00	\$0.00	\$403,405.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout the building
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 75,150.00
Unit of Measure: S.F.
Estimate: \$348,846.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: There is no sprinkler system.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout the building
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 75,150.00
Unit of Measure: S.F.
Estimate: \$54,559.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: There is no sprinkler system.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	75,150
Year Built:	1999
Last Renovation:	
Replacement Value:	\$2,357,460
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	39.91 %
FCA Score:	100.00



Description:

The narrative for this site is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary


Function:	ES -Elementary School	Gross Area:	75,150
Year Built:	1999	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$2,357,460
FCI:	0.00 %	RSLI%:	39.91 %

No data found for this asset

No data found for this asset

No data found for this asset

10 Year Investment Forecast



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	21.68 %	0.00 %	\$0.00
G30 - Site Mechanical Utilities	63.05 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	61.72 %	0.00 %	\$0.00
Totals:	39.91 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

- 1). Aerial Image of Laurel Hill Elementary School - Feb 27, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$3.81	S.F.	75,150	25	1999	2024		28.00 %	0.00 %	7			\$286,322
G2020	Parking Lots	\$1.33	S.F.	75,150	25	1999	2024		28.00 %	0.00 %	7			\$99,950
G2030	Pedestrian Paving	\$1.91	S.F.	75,150	30	1999	2029		40.00 %	0.00 %	12			\$143,537
G2040105	Fence & Guardrails	\$1.23	S.F.	75,150	30	1999	2029		40.00 %	0.00 %	12			\$92,435
G2040950	Canopies	\$0.44	S.F.	75,150	25	1999	2024		28.00 %	0.00 %	7			\$33,066
G2040950	Covered Walkways	\$1.52	S.F.	75,150	25	1999	2024		28.00 %	0.00 %	7			\$114,228
G2040950	Hard Surface Play Area	\$0.75	S.F.	75,150	20	1999	2019		10.00 %	0.00 %	2			\$56,363
G2040950	Playing Field	\$4.54	S.F.	75,150	20	1999	2019		10.00 %	0.00 %	2			\$341,181
G2050	Landscaping	\$1.87	S.F.	75,150	15	1999	2014		0.00 %	0.00 %	-3			\$140,531
G3010	Water Supply	\$2.34	S.F.	75,150	50	1999	2049		64.00 %	0.00 %	32			\$175,851
G3020	Sanitary Sewer	\$1.45	S.F.	75,150	50	1999	2049		64.00 %	0.00 %	32			\$108,968
G3030	Storm Sewer	\$4.54	S.F.	75,150	50	1999	2049		64.00 %	0.00 %	32			\$341,181
G3060	Fuel Distribution	\$0.98	S.F.	75,150	40	1999	2039		55.00 %	0.00 %	22			\$73,647
G4010	Electrical Distribution	\$2.35	S.F.	75,150	50	1999	2049		64.00 %	0.00 %	32			\$176,603
G4020	Site Lighting	\$1.47	S.F.	75,150	30	1999	2029		40.00 %	0.00 %	12			\$110,471
G4030	Site Communications & Security	\$0.84	S.F.	75,150	15	2016	2031		93.33 %	0.00 %	14			\$63,126
Total									39.91 %					\$2,357,460

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: G2010 - Roadways



Note:

System: G2020 - Parking Lots



Note:

System: G2030 - Pedestrian Paving



Note:

Campus Assessment Report - Site

System: G2040105 - Fence & Guardrails



Note:

System: G2040950 - Canopies



Note:

System: G2040950 - Covered Walkways



Note:

Campus Assessment Report - Site

System: G2040950 - Hard Surface Play Area



Note:

System: G2040950 - Playing Field



Note:

System: G2050 - Landscaping



Note:

Campus Assessment Report - Site

System: G3010 - Water Supply



Note:

System: G3020 - Sanitary Sewer



Note:

System: G3030 - Storm Sewer



Note:

Campus Assessment Report - Site

System: G3060 - Fuel Distribution



Note:

System: G4010 - Electrical Distribution



Note:

System: G4020 - Site Lighting



Note:

Campus Assessment Report - Site

System: G4030 - Site Communications & Security



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$463,929	\$0	\$0	\$0	\$0	\$721,840	\$0	\$0	\$0	\$1,185,769
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$387,354	\$0	\$0	\$0	\$387,354
G2020 - Parking Lots	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$135,217	\$0	\$0	\$0	\$135,217
G2030 - Pedestrian Paving	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040105 - Fence & Guardrails	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040950 - Canopies	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$44,734	\$0	\$0	\$0	\$44,734
G2040950 - Covered Walkways	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$154,535	\$0	\$0	\$0	\$154,535
G2040950 - Hard Surface Play Area	\$0	\$0	\$65,775	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$65,775
G2040950 - Playing Field	\$0	\$0	\$398,155	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$398,155
* G2050 - Landscaping	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3020 - Sanitary Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3030 - Storm Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3060 - Fuel Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

** Indicates non-renewable system*

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

NC School District/830 Scotland County/Elementary School

North Laurinburg Elementary

Draft

Campus Assessment Report

March 7, 2017



Table of Contents

Campus Executive Summary	5
Campus Dashboard Summary	8
Campus Condition Summary	9
<u>1958 Building Main</u>	11
Executive Summary	11
Dashboard Summary	12
Condition Summary	13
Photo Album	14
Condition Detail	15
System Listing	16
System Notes	18
Renewal Schedule	28
Forecasted Sustainment Requirement	30
Deficiency Summary By System	31
Deficiency Summary By Priority	32
Deficiency By Priority Investment	33
Deficiency Summary By Category	34
Deficiency Details By Priority	35
<u>1962 Building</u>	43
Executive Summary	43
Dashboard Summary	44
Condition Summary	45
Photo Album	46
Condition Detail	47
System Listing	48
System Notes	50
Renewal Schedule	59
Forecasted Sustainment Requirement	61
Deficiency Summary By System	62

Campus Assessment Report

Deficiency Summary By Priority	63
Deficiency By Priority Investment	64
Deficiency Summary By Category	65
Deficiency Details By Priority	66
<u>1983 Media Center</u>	71
Executive Summary	71
Dashboard Summary	72
Condition Summary	73
Photo Album	74
Condition Detail	75
System Listing	76
System Notes	78
Renewal Schedule	87
Forecasted Sustainment Requirement	89
Deficiency Summary By System	90
Deficiency Summary By Priority	91
Deficiency By Priority Investment	92
Deficiency Summary By Category	93
Deficiency Details By Priority	94
<u>Site</u>	99
Executive Summary	99
Dashboard Summary	100
Condition Summary	101
Photo Album	102
Condition Detail	103
System Listing	104
System Notes	105
Renewal Schedule	110
Forecasted Sustainment Requirement	111
Deficiency Summary By System	112
Deficiency Summary By Priority	113

Campus Assessment Report

Deficiency By Priority Investment	114
Deficiency Summary By Category	115
Deficiency Details By Priority	116

Campus Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	46,992
Year Built:	1958
Last Renovation:	
Replacement Value:	\$10,756,826
Repair Cost:	\$2,994,249.00
Total FCI:	27.84 %
Total RSLI:	24.43 %
FCA Score:	72.16



Description:

GENERAL:

North Laurinburg Elementary is located at 815 N Gill Street in Laurinburg, North Carolina. The 1 story, 46,992 square foot building was originally constructed in 1958. There have been 2 additions to the building. There were classrooms added in 1962 and classrooms and a media center added in 1982.

This report contains condition and adequacy data collected during the 2016-2017 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for the site and building elements.

A. SUBSTRUCTURE

The building rests on slab-on grade and is assumed to have standard cast-in-place concrete foundations. The building does not have a basement.

B. SUPERSTRUCTURE

Roof construction is steel and metal decking. The exterior envelope is composed of walls of brick veneer over CMU. Exterior windows are aluminum frame with operable panes. Exterior doors are hollow metal steel mostly with glazing. Roofing is typically asphalt shingle roofing and a low slope thermoplastic polyolefin. Roof openings include a roof hatch with fixed ladder access. Most building entrances appear to comply with minimum ADA requirements.

C. INTERIORS

Interior partitions are typically CMU. Interior doors are generally solid core wood with wood frames. Interior fittings include the following items: lockers, white boards, toilet accessories, storage shelving, and fabricated toilet partitions. The interior wall finishes are typically painted CMU. Floor finishes throughout are typically vinyl composition tile, and ceramic tile in the restrooms. Ceiling finishes throughout are typically suspended acoustical tile.

CONVEYING:

The building does not include conveying equipment.

D. SERVICES

PLUMBING: Plumbing fixtures are typically non-low-flow water fixtures with manual control valves. Domestic water distribution is copper with electric hot water heating. Sanitary waste system is galvanized piping. Rain water drainage system is internal with roof drains.

HVAC:

Heating and Cooling is provided by wall mounted package units. And secondary heating is provided by a gas fired boiler. Ceiling mounted exhaust fans are installed in bathrooms and other required areas. Controls and instrumentation are digital and are centrally controlled by an energy management system.

FIRE PROTECTION:

The building does not have a fire sprinkler system. The building does have additional fire suppression systems, which include dry chemical for the kitchen hood protection. Fire extinguishers and cabinets are distributed near fire exits and corridors.

ELECTRICAL:

The main electrical service is fed from a pad mounted transformer to the main switchboard/distribution panel located in the building. Lighting is lay-in type, fluorescent light fixtures. Branch circuit wiring is typically copper serving electrical switches and receptacles. Emergency and life safety egress lighting systems are installed and exit signs are present at exit doors and near stairways and are typically illuminated.

COMMUNICATIONS AND SECURITY:

The fire alarm system consists of audible/visual strobe annunciators in common spaces, balconies and interior corridors. The system is activated by manual pull stations and smoke detectors and the system is centrally monitored. The telephone and data systems are segregated and include dedicated equipment closets. This building does have a local area network (LAN). The building includes an internal security system that is actuated by the following items: contacts, infrared, optical or a combination of all devices. The building has controlled entry doors access provided by card readers; entry doors are secured with magnetic door locks. The security system has CCTV cameras and is centrally monitored; this building has a public address and paging system separate from the telephone system.

OTHER ELECTRICAL SYSTEMS:

This building does not have a separately derived emergency power system.

E. EQUIPMENT & FURNISHINGS:

Campus Assessment Report - North Laurinburg Elementary

This building includes the following items and equipment: fixed food service, library equipment, athletic equipment, theater and stage, audio-visual, fixed casework, window treatment, floor grilles and mats, and multiple seating furnishings.

G. SITE:

Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, play areas, and fencing. Site mechanical and electrical features include water, sewer, natural gas, and site lighting.

Attributes:

General Attributes:





Condition Assessor:	Terence Davis	Assessment Date:	
Suitability Assessor:			

School Information:

HS Attendance Area:		LEA School No.:	
No. of Mobile Units:	0	No. of Bldgs.:	1
SF of Mobile Units:	Active	Status:	Active
School Grades:	9.9	Site Acreage:	9.9

Campus Dashboard Summary

Gross Area:	46,992	Last Renovation:	
Year Built:	1958	Replacement Value:	\$10,756,826
Repair Cost:	\$2,994,249	RSLI%:	24.43 %
FCI:	27.84 %		



Campus Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Uniformat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	50.39 %	0.00 %	\$0.00
A20 - Basement Construction	50.39 %	0.00 %	\$0.00
B10 - Superstructure	50.39 %	0.00 %	\$0.00
B20 - Exterior Enclosure	30.45 %	3.83 %	\$36,477.00
B30 - Roofing	11.69 %	36.20 %	\$109,363.00
C10 - Interior Construction	23.63 %	0.00 %	\$0.00
C30 - Interior Finishes	8.27 %	87.28 %	\$1,051,260.00
D20 - Plumbing	1.68 %	96.74 %	\$692,578.00
D30 - HVAC	17.88 %	28.00 %	\$310,374.00
D40 - Fire Protection	0.00 %	110.00 %	\$263,625.00
D50 - Electrical	27.97 %	13.17 %	\$178,852.00
E10 - Equipment	5.66 %	68.53 %	\$44,157.00
E20 - Furnishings	0.00 %	110.00 %	\$307,563.00
G20 - Site Improvements	15.83 %	0.00 %	\$0.00
G30 - Site Mechanical Utilities	9.44 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	45.43 %	0.00 %	\$0.00
Totals:	24.43 %	27.84 %	\$2,994,249.00

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance
1958 Building Main	20,692	35.14	\$0.00	\$78,754.00	\$1,242,762.00	\$160,239.00	\$0.00
1962 Building	10,300	25.20	\$0.00	\$0.00	\$482,772.00	\$57,783.00	\$0.00
1983 Media Center	16,000	30.81	\$0.00	\$0.00	\$882,179.00	\$89,760.00	\$0.00
Site	46,992	0.00	\$0.00	\$0.00	\$0.00	\$0.00	\$0.00
Total:		27.84	\$0.00	\$78,754.00	\$2,607,713.00	\$307,782.00	\$0.00

Deficiencies By Priority



Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as $100 - \text{Total FCI}$ (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	20,692
Year Built:	1958
Last Renovation:	
Replacement Value:	\$4,217,024
Repair Cost:	\$1,481,755.00
Total FCI:	35.14 %
Total RSLI:	20.53 %
FCA Score:	64.86







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	ES -Elementary School	Gross Area:	20,692
Year Built:	1958	Last Renovation:	
Repair Cost:	\$1,481,755	Replacement Value:	\$4,217,024
FCI:	35.14 %	RSLI%:	20.53 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	41.00 %	0.00 %	\$0.00
A20 - Basement Construction	41.00 %	0.00 %	\$0.00
B10 - Superstructure	41.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	25.76 %	5.81 %	\$24,354.00
B30 - Roofing	15.68 %	0.00 %	\$0.00
C10 - Interior Construction	17.78 %	0.00 %	\$0.00
C30 - Interior Finishes	3.32 %	97.81 %	\$518,728.00
D20 - Plumbing	1.42 %	99.60 %	\$324,803.00
D30 - HVAC	13.26 %	51.11 %	\$239,448.00
D40 - Fire Protection	0.00 %	110.00 %	\$116,082.00
D50 - Electrical	28.03 %	13.17 %	\$78,754.00
E10 - Equipment	2.01 %	95.27 %	\$44,157.00
E20 - Furnishings	0.00 %	110.00 %	\$135,429.00
Totals:	20.53 %	35.14 %	\$1,481,755.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). South Elevation - Jan 09, 2017



2). West Elevation - Jan 09, 2017



3). West Elevation - Jan 09, 2017



4). East Elevation - Jan 09, 2017



5). East Elevation - Jan 09, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Campus Assessment Report - 1958 Building Main

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.88	S.F.	20,692	100	1958	2058		41.00 %	0.00 %	41			\$100,977
A1030	Slab on Grade	\$8.61	S.F.	20,692	100	1958	2058		41.00 %	0.00 %	41			\$178,158
A2010	Basement Excavation	\$1.95	S.F.	20,692	100	1958	2058		41.00 %	0.00 %	41			\$40,349
A2020	Basement Walls	\$13.35	S.F.	20,692	100	1958	2058		41.00 %	0.00 %	41			\$276,238
B1010	Floor Construction	\$1.66	S.F.	20,692	100	1958	2058		41.00 %	0.00 %	41			\$34,349
B1020	Roof Construction	\$16.08	S.F.	20,692	100	1958	2058		41.00 %	0.00 %	41			\$332,727
B2010	Exterior Walls	\$9.61	S.F.	20,692	100	1958	2058		41.00 %	0.00 %	41			\$198,850
B2020	Exterior Windows	\$9.57	S.F.	20,692	30	1983	2013	2021	13.33 %	0.00 %	4			\$198,022
B2030	Exterior Doors	\$1.07	S.F.	20,692	30	1983	2013		0.00 %	110.00 %	-4		\$24,354.00	\$22,140
B3010120	Single Ply Membrane	\$6.98	S.F.	20,692	20	2000	2020		15.00 %	0.00 %	3			\$144,430
B3020	Roof Openings	\$0.29	S.F.	20,692	25	2000	2025		32.00 %	0.00 %	8			\$6,001
C1010	Partitions	\$11.01	S.F.	20,692	75	1958	2033		21.33 %	0.00 %	16			\$227,819
C1020	Interior Doors	\$2.59	S.F.	20,692	30	1983	2013	2021	13.33 %	0.00 %	4			\$53,592
C1030	Fittings	\$9.94	S.F.	20,692	20	2000	2020		15.00 %	0.00 %	3			\$205,678
C3010	Wall Finishes	\$2.84	S.F.	20,692	10	2010	2020		30.00 %	0.00 %	3			\$58,765
C3020	Floor Finishes	\$11.60	S.F.	20,692	20	1983	2003		0.00 %	110.00 %	-14		\$264,030.00	\$240,027
C3030	Ceiling Finishes	\$11.19	S.F.	20,692	25	1983	2008		0.00 %	110.00 %	-9		\$254,698.00	\$231,543
D2010	Plumbing Fixtures	\$11.71	S.F.	20,692	30	1983	2013		0.00 %	110.00 %	-4		\$266,534.00	\$242,303
D2020	Domestic Water Distribution	\$0.99	S.F.	20,692	30	1958	1988		0.00 %	110.00 %	-29		\$22,534.00	\$20,485
D2030	Sanitary Waste	\$1.57	S.F.	20,692	30	1958	1988		0.00 %	110.00 %	-29		\$35,735.00	\$32,486
D2090	Other Plumbing Systems -Nat Gas	\$1.49	S.F.	20,692	40	1983	2023		15.00 %	0.00 %	6			\$30,831
D3020	Heat Generating Systems	\$4.26	S.F.	20,692	30	1983	2013		0.00 %	110.00 %	-4		\$96,963.00	\$88,148
D3040	Distribution Systems	\$6.26	S.F.	20,692	30	1983	2013		0.00 %	110.00 %	-4		\$142,485.00	\$129,532
D3050	Terminal & Package Units	\$10.14	S.F.	20,692	15	2000	2015	2021	26.67 %	0.00 %	4			\$209,817
D3060	Controls & Instrumentation	\$1.98	S.F.	20,692	20	2000	2020		15.00 %	0.00 %	3			\$40,970
D4010	Sprinklers	\$4.41	S.F.	20,692	30			2016	0.00 %	110.00 %	-1		\$100,377.00	\$91,252
D4020	Standpipes	\$0.69	S.F.	20,692	30			2016	0.00 %	110.00 %	-1		\$15,705.00	\$14,277
D5010	Electrical Service/Distribution	\$1.73	S.F.	20,692	40	1983	2023		15.00 %	0.00 %	6			\$35,797
D5020	Branch Wiring	\$5.20	S.F.	20,692	30	1958	1988	2021	13.33 %	0.00 %	4			\$107,598
D5020	Lighting	\$12.12	S.F.	20,692	30	1983	2013	2021	13.33 %	0.00 %	4			\$250,787
D5030810	Security & Detection Systems	\$1.91	S.F.	20,692	15	2015	2030		86.67 %	0.00 %	13			\$39,522
D5030910	Fire Alarm Systems	\$3.46	S.F.	20,692	15	1983	1998		0.00 %	110.00 %	-19		\$78,754.00	\$71,594
D5030920	Data Communication	\$4.47	S.F.	20,692	15	2015	2030		86.67 %	0.00 %	13			\$92,493
E1020	Institutional Equipment	\$0.30	S.F.	20,692	20	2000	2020		15.00 %	0.00 %	3			\$6,208
E1090	Other Equipment	\$1.94	S.F.	20,692	20	1983	2003		0.00 %	110.00 %	-14		\$44,157.00	\$40,142
E2010	Fixed Furnishings	\$5.95	S.F.	20,692	20	1990	2010		0.00 %	110.00 %	-7		\$135,429.00	\$123,117
Total									20.53 %	35.14 %			\$1,481,755.00	\$4,217,024

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1958 Building Main

System: B3010120 - Single Ply Membrane



Note:

System: B3020 - Roof Openings



Note:

System: C1010 - Partitions



Note:

Campus Assessment Report - 1958 Building Main

System: C1020 - Interior Doors



Note:

System: C1030 - Fittings



Note:


System: C3010 - Wall Finishes



Note:



Campus Assessment Report - 1958 Building Main

System: C3020 - Floor Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

Campus Assessment Report - 1958 Building Main

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

System: D2090 - Other Plumbing Systems -Nat Gas



Note:

Campus Assessment Report - 1958 Building Main

System: D3020 - Heat Generating Systems



Note:

System: D3040 - Distribution Systems



Note:

System: D3050 - Terminal & Package Units



Note:

Campus Assessment Report - 1958 Building Main

System: D3060 - Controls & Instrumentation



Note:

System: D5010 - Electrical Service/Distribution



Note:


System: D5020 - Branch Wiring



Note:

Campus Assessment Report - 1958 Building Main

System: D5020 - Lighting



Note:

System: D5030810 - Security & Detection Systems



Note:


System: D5030910 - Fire Alarm Systems



Note:


Campus Assessment Report - 1958 Building Main

System: D5030920 - Data Communication



Note:

System: E1020 - Institutional Equipment



Note:

System: E1090 - Other Equipment



Note:

Campus Assessment Report - 1958 Building Main

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$1,481,755	\$0	\$0	\$611,302	\$1,014,984	\$0	\$87,513	\$0	\$8,362	\$0	\$0	\$3,203,916
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$245,164	\$0	\$0	\$0	\$0	\$0	\$0	\$245,164
B2030 - Exterior Doors	\$24,354	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$24,354
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$236,734	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$236,734
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$8,362	\$0	\$0	\$8,362
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$66,351	\$0	\$0	\$0	\$0	\$0	\$0	\$66,351
C1030 - Fittings	\$0	\$0	\$0	\$247,225	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$247,225
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1958 Building Main

C3010 - Wall Finishes	\$0	\$0	\$0	\$70,636	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$70,636
C3020 - Floor Finishes	\$264,030	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$264,030
C3030 - Ceiling Finishes	\$254,698	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$254,698
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$266,534	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$266,534
D2020 - Domestic Water Distribution	\$22,534	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$22,534
D2030 - Sanitary Waste	\$35,735	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$35,735
D2090 - Other Plumbing Systems -Nat Gas	\$0	\$0	\$0	\$0	\$0	\$0	\$40,495	\$0	\$0	\$0	\$0	\$0	\$40,495
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$96,963	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$96,963
D3040 - Distribution Systems	\$142,485	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$142,485
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$259,766	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$259,766
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$49,246	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$49,246
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$100,377	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$100,377
D4020 - Standpipes	\$15,705	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$15,705
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$47,018	\$0	\$0	\$0	\$0	\$0	\$47,018
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$133,213	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$133,213
D5020 - Lighting	\$0	\$0	\$0	\$0	\$310,490	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$310,490
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Fire Alarm Systems	\$78,754	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$78,754
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$7,461	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$7,461
E1090 - Other Equipment	\$44,157	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$44,157
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$135,429	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$135,429

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$1,481,755.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$1,481,755.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2030	Exterior Doors	\$0.00	\$0.00	\$24,354.00	\$0.00	\$0.00	\$24,354.00
C3020	Floor Finishes	\$0.00	\$0.00	\$264,030.00	\$0.00	\$0.00	\$264,030.00
C3030	Ceiling Finishes	\$0.00	\$0.00	\$254,698.00	\$0.00	\$0.00	\$254,698.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$266,534.00	\$0.00	\$0.00	\$266,534.00
D2020	Domestic Water Distribution	\$0.00	\$0.00	\$22,534.00	\$0.00	\$0.00	\$22,534.00
D2030	Sanitary Waste	\$0.00	\$0.00	\$35,735.00	\$0.00	\$0.00	\$35,735.00
D3020	Heat Generating Systems	\$0.00	\$0.00	\$96,963.00	\$0.00	\$0.00	\$96,963.00
D3040	Distribution Systems	\$0.00	\$0.00	\$142,485.00	\$0.00	\$0.00	\$142,485.00
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$100,377.00	\$0.00	\$100,377.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$15,705.00	\$0.00	\$15,705.00
D5030910	Fire Alarm Systems	\$0.00	\$78,754.00	\$0.00	\$0.00	\$0.00	\$78,754.00
E1090	Other Equipment	\$0.00	\$0.00	\$0.00	\$44,157.00	\$0.00	\$44,157.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$135,429.00	\$0.00	\$0.00	\$135,429.00
	Total:	\$0.00	\$78,754.00	\$1,242,762.00	\$160,239.00	\$0.00	\$1,481,755.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 2 - Potentially Critical (Year 1):

System: D5030910 - Fire Alarm Systems



Location: Throughout the building.
Distress: Beyond Service Life
Category: Building Code Compliance
Priority: 2 - Potentially Critical (Year 1)
Correction: Renew System
Qty: 20,692.00
Unit of Measure: S.F.
Estimate: \$78,754.00
Assessor Name: Eduardo Lopez
Date Created: 01/04/2017

Notes: The original fire alarm system operating as designed, but is beyond its service life and should be replaced.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B2030 - Exterior Doors



Location: Exterior
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 20,692.00
Unit of Measure: S.F.
Estimate: \$24,354.00
Assessor Name: Eduardo Lopez
Date Created: 01/13/2017

Notes: The original metal exterior doors are aged, rusted, damaged and should be replaced with energy efficient doors


System: C3020 - Floor Finishes



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 20,692.00
Unit of Measure: S.F.
Estimate: \$264,030.00
Assessor Name: Eduardo Lopez
Date Created: 01/04/2017

Notes: The original flooring is in poor conditions, with different areas bubbling or separating seams, and should be replaced.

System: C3030 - Ceiling Finishes



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 20,692.00
Unit of Measure: S.F.
Estimate: \$254,698.00
Assessor Name: Eduardo Lopez
Date Created: 01/04/2017

Notes: The ceiling tiles have been replaced as needed. However the grid shows signs of aging and most tiles are sagging or damaged and should be replaced.

System: D2010 - Plumbing Fixtures



Location: Restroom/Classroom
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 20,692.00
Unit of Measure: S.F.
Estimate: \$266,534.00
Assessor Name: Eduardo Lopez
Date Created: 01/04/2017

Notes: The plumbing fixtures are original beyond its service life, not efficient or low flow fixtures.

System: D2020 - Domestic Water Distribution



Location: Throughout the building.
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 20,692.00
Unit of Measure: S.F.
Estimate: \$22,534.00
Assessor Name: Eduardo Lopez
Date Created: 01/13/2017

Notes: There are no reported issues or observed deficiencies with the domestic water piping. Due to the age of the pipe there can be internal pitting corrosion that may be a costly problem that leads to the formation of pinhole leaks and possible water contamination.

System: D2030 - Sanitary Waste



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 20,692.00
Unit of Measure: S.F.
Estimate: \$35,735.00
Assessor Name: Eduardo Lopez
Date Created: 01/13/2017

Notes: There are no reported issues or observed deficiencies with the sanitary waste piping. The aging sanitary sewer piping is subject to leaks, infiltration, and it can even collapse in the interior walls. The system should be inspected with cameras to ensure that none of these deficiencies exist.

System: D3020 - Heat Generating Systems



Location: Mechanical Room
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 20,692.00
Unit of Measure: S.F.
Estimate: \$96,963.00
Assessor Name: Eduardo Lopez
Date Created: 01/09/2017

Notes: The original gas fired boiler is aged, rusted, inefficient, becoming logistically unsupportable and should be replaced with an energy efficient model.

System: D3040 - Distribution Systems



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 20,692.00
Unit of Measure: S.F.
Estimate: \$142,485.00
Assessor Name: Eduardo Lopez
Date Created: 01/13/2017

Notes: The exhaust fans, and hot water supply distribution system is aged, in marginal condition, and should be replaced.

System: E2010 - Fixed Furnishings



Location: Classroom
Distress: Damaged
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 20,692.00
Unit of Measure: S.F.
Estimate: \$135,429.00
Assessor Name: Eduardo Lopez
Date Created: 01/04/2017

Notes: The building casework is aged and worn and should be replaced.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout the building
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 20,692.00
Unit of Measure: S.F.
Estimate: \$100,377.00
Assessor Name: Eduardo Lopez
Date Created: 01/04/2017

Notes: There are no sprinklers in the building.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout the building
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 20,692.00
Unit of Measure: S.F.
Estimate: \$15,705.00
Assessor Name: Eduardo Lopez
Date Created: 01/04/2017

Notes: There are no sprinklers in the building.

System: E1090 - Other Equipment



Location: Kitchen
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 20,692.00
Unit of Measure: S.F.
Estimate: \$44,157.00
Assessor Name: Eduardo Lopez
Date Created: 01/04/2017

Notes: The kitchen equipment is beyond its expected service life, becoming logistically unsupportable and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	10,300
Year Built:	1962
Last Renovation:	
Replacement Value:	\$2,145,284
Repair Cost:	\$540,555.00
Total FCI:	25.20 %
Total RSLI:	24.53 %
FCA Score:	74.80







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	ES -Elementary School	Gross Area:	10,300
Year Built:	1962	Last Renovation:	
Repair Cost:	\$540,555	Replacement Value:	\$2,145,284
FCI:	25.20 %	RSLI%:	24.53 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	45.00 %	0.00 %	\$0.00
A20 - Basement Construction	45.00 %	0.00 %	\$0.00
B10 - Superstructure	45.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	27.66 %	5.81 %	\$12,123.00
B30 - Roofing	15.68 %	0.00 %	\$0.00
C10 - Interior Construction	20.27 %	0.00 %	\$0.00
C30 - Interior Finishes	17.30 %	49.79 %	\$131,428.00
D20 - Plumbing	1.20 %	100.11 %	\$161,679.00
D30 - HVAC	20.62 %	24.46 %	\$70,926.00
D40 - Fire Protection	0.00 %	110.00 %	\$57,783.00
D50 - Electrical	27.73 %	13.17 %	\$39,202.00
E10 - Equipment	15.00 %	0.00 %	\$0.00
E20 - Furnishings	0.00 %	110.00 %	\$67,414.00
Totals:	24.53 %	25.20 %	\$540,555.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). North Elevation - Jan 06, 2017



2). East Elevation - Jan 06, 2017



3). West Elevation - Jan 06, 2017



4). South Elevation - Jan 06, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

Campus Assessment Report - 1962 Building

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.88	S.F.	10,300	100	1962	2062		45.00 %	0.00 %	45			\$50,264
A1030	Slab on Grade	\$8.61	S.F.	10,300	100	1962	2062		45.00 %	0.00 %	45			\$88,683
A2010	Basement Excavation	\$1.95	S.F.	10,300	100	1962	2062		45.00 %	0.00 %	45			\$20,085
A2020	Basement Walls	\$13.35	S.F.	10,300	100	1962	2062		45.00 %	0.00 %	45			\$137,505
B1010	Floor Construction	\$1.66	S.F.	10,300	100	1962	2062		45.00 %	0.00 %	45			\$17,098
B1020	Roof Construction	\$16.08	S.F.	10,300	100	1962	2062		45.00 %	0.00 %	45			\$165,624
B2010	Exterior Walls	\$9.61	S.F.	10,300	100	1962	2062		45.00 %	0.00 %	45			\$98,983
B2020	Exterior Windows	\$9.57	S.F.	10,300	30	1983	2013	2021	13.33 %	0.00 %	4			\$98,571
B2030	Exterior Doors	\$1.07	S.F.	10,300	30	1983	2013		0.00 %	110.00 %	-4		\$12,123.00	\$11,021
B3010120	Single Ply Membrane	\$6.98	S.F.	10,300	20	2000	2020		15.00 %	0.00 %	3			\$71,894
B3020	Roof Openings	\$0.29	S.F.	10,300	25	2000	2025		32.00 %	0.00 %	8			\$2,987
C1010	Partitions	\$11.01	S.F.	10,300	75	1962	2037		26.67 %	0.00 %	20			\$113,403
C1020	Interior Doors	\$2.59	S.F.	10,300	30	1983	2013	2021	13.33 %	0.00 %	4			\$26,677
C1030	Fittings	\$9.94	S.F.	10,300	20	2000	2020		15.00 %	0.00 %	3			\$102,382
C3010	Wall Finishes	\$2.84	S.F.	10,300	10	2010	2020		30.00 %	0.00 %	3			\$29,252
C3020	Floor Finishes	\$11.60	S.F.	10,300	20	1983	2003		0.00 %	110.00 %	-14		\$131,428.00	\$119,480
C3030	Ceiling Finishes	\$11.19	S.F.	10,300	25	2000	2025		32.00 %	0.00 %	8			\$115,257
D2010	Plumbing Fixtures	\$11.71	S.F.	10,300	30	1983	2013		0.00 %	110.00 %	-4		\$132,674.00	\$120,613
D2020	Domestic Water Distribution	\$0.99	S.F.	10,300	30	1962	1992		0.00 %	110.00 %	-25		\$11,217.00	\$10,197
D2030	Sanitary Waste	\$1.57	S.F.	10,300	30	1962	1992		0.00 %	110.00 %	-25		\$17,788.00	\$16,171
D2040	Rain Water Drainage	\$1.41	S.F.	10,300	30	1962	1992	2021	13.33 %	0.00 %	4			\$14,523
D3040	Distribution Systems	\$6.26	S.F.	10,300	30	1962	1992		0.00 %	110.00 %	-25		\$70,926.00	\$64,478
D3050	Terminal & Package Units	\$19.91	S.F.	10,300	15	2002	2017	2021	26.67 %	0.00 %	4			\$205,073
D3060	Controls & Instrumentation	\$1.98	S.F.	10,300	20	2002	2022		25.00 %	0.00 %	5			\$20,394
D4010	Sprinklers	\$4.41	S.F.	10,300	30			2016	0.00 %	110.00 %	-1		\$49,965.00	\$45,423
D4020	Standpipes	\$0.69	S.F.	10,300	30			2016	0.00 %	110.00 %	-1		\$7,818.00	\$7,107
D5010	Electrical Service/Distribution	\$1.73	S.F.	10,300	40	1962	2002	2021	10.00 %	0.00 %	4			\$17,819
D5020	Branch Wiring	\$5.20	S.F.	10,300	30	1962	1992	2021	13.33 %	0.00 %	4			\$53,560
D5020	Lighting	\$12.12	S.F.	10,300	30	1983	2013	2021	13.33 %	0.00 %	4			\$124,836
D5030810	Security & Detection Systems	\$1.91	S.F.	10,300	15	2015	2030		86.67 %	0.00 %	13			\$19,673
D5030910	Fire Alarm Systems	\$3.46	S.F.	10,300	15	1983	1998		0.00 %	110.00 %	-19		\$39,202.00	\$35,638
D5030920	Data Communication	\$4.47	S.F.	10,300	15	2015	2030		86.67 %	0.00 %	13			\$46,041
E1020	Institutional Equipment	\$1.29	S.F.	10,300	20	2000	2020		15.00 %	0.00 %	3			\$13,287
E2010	Fixed Furnishings	\$5.95	S.F.	10,300	20	1983	2003		0.00 %	110.00 %	-14		\$67,414.00	\$61,285
Total									24.53 %	25.20 %			\$540,555.00	\$2,145,284

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1962 Building

System: B3010120 - Single Ply Membrane




Note:

System: B3020 - Roof Openings



Note:



System: C1010 - Partitions



Note:


Campus Assessment Report - 1962 Building

System: C1020 - Interior Doors






Note:

System: C1030 - Fittings



Note:


System: C3010 - Wall Finishes



Note:



Campus Assessment Report - 1962 Building

System: C3020 - Floor Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

Campus Assessment Report - 1962 Building

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

System: D2040 - Rain Water Drainage



Note:

Campus Assessment Report - 1962 Building

System: D3040 - Distribution Systems



Note:

System: D3050 - Terminal & Package Units



Note:

System: D3060 - Controls & Instrumentation



Note:

Campus Assessment Report - 1962 Building

System: D5010 - Electrical Service/Distribution




Note:

System: D5020 - Branch Wiring



Note:


System: D5020 - Lighting



Note:

Campus Assessment Report - 1962 Building

System: D5030810 - Security & Detection Systems



Note:

System: D5030910 - Fire Alarm Systems



Note:

System: D5030920 - Data Communication



Note:

Campus Assessment Report - 1962 Building

System: E1020 - Institutional Equipment



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$540,555	\$0	\$0	\$292,036	\$669,863	\$26,006	\$0	\$0	\$164,768	\$0	\$0	\$1,693,228
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$122,037	\$0	\$0	\$0	\$0	\$0	\$0	\$122,037
B2030 - Exterior Doors	\$12,123	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$12,123
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$117,841	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$117,841
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$4,163	\$0	\$0	\$4,163
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$33,028	\$0	\$0	\$0	\$0	\$0	\$0	\$33,028
C1030 - Fittings	\$0	\$0	\$0	\$123,063	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$123,063
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1962 Building

C3010 - Wall Finishes	\$0	\$0	\$0	\$35,161	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$35,161
C3020 - Floor Finishes	\$131,428	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$131,428
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$160,605	\$0	\$0	\$160,605
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$132,674	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$132,674
D2020 - Domestic Water Distribution	\$11,217	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$11,217
D2030 - Sanitary Waste	\$17,788	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$17,788
D2040 - Rain Water Drainage	\$0	\$0	\$0	\$0	\$17,980	\$0	\$0	\$0	\$0	\$0	\$0	\$17,980
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$70,926	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$70,926
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$253,892	\$0	\$0	\$0	\$0	\$0	\$0	\$253,892
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$26,006	\$0	\$0	\$0	\$0	\$0	\$26,006
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$49,965	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$49,965
D4020 - Standpipes	\$7,818	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$7,818
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$22,061	\$0	\$0	\$0	\$0	\$0	\$0	\$22,061
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$66,310	\$0	\$0	\$0	\$0	\$0	\$0	\$66,310
D5020 - Lighting	\$0	\$0	\$0	\$0	\$154,555	\$0	\$0	\$0	\$0	\$0	\$0	\$154,555
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Fire Alarm Systems	\$39,202	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$39,202
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$15,971	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$15,971
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$67,414	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$67,414

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$540,555.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$540,555.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2030	Exterior Doors	\$0.00	\$0.00	\$12,123.00	\$0.00	\$0.00	\$12,123.00
C3020	Floor Finishes	\$0.00	\$0.00	\$131,428.00	\$0.00	\$0.00	\$131,428.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$132,674.00	\$0.00	\$0.00	\$132,674.00
D2020	Domestic Water Distribution	\$0.00	\$0.00	\$11,217.00	\$0.00	\$0.00	\$11,217.00
D2030	Sanitary Waste	\$0.00	\$0.00	\$17,788.00	\$0.00	\$0.00	\$17,788.00
D3040	Distribution Systems	\$0.00	\$0.00	\$70,926.00	\$0.00	\$0.00	\$70,926.00
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$49,965.00	\$0.00	\$49,965.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$7,818.00	\$0.00	\$7,818.00
D5030910	Fire Alarm Systems	\$0.00	\$0.00	\$39,202.00	\$0.00	\$0.00	\$39,202.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$67,414.00	\$0.00	\$0.00	\$67,414.00
Total:		\$0.00	\$0.00	\$482,772.00	\$57,783.00	\$0.00	\$540,555.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$540,555.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):


System: B2030 - Exterior Doors



Location: Exterior
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 10,300.00
Unit of Measure: S.F.
Estimate: \$12,123.00
Assessor Name: Eduardo Lopez
Date Created: 01/13/2017

Notes: The original metal exterior doors are aged, rusted, damaged and should be replaced with energy efficient doors

System: C3020 - Floor Finishes



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 10,300.00
Unit of Measure: S.F.
Estimate: \$131,428.00
Assessor Name: Eduardo Lopez
Date Created: 01/04/2017

Notes: The flooring is beyond its service life and should be inspected and replaced.

System: D2010 - Plumbing Fixtures



Location: Restrooms
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 10,300.00
Unit of Measure: S.F.
Estimate: \$132,674.00
Assessor Name: Eduardo Lopez
Date Created: 01/04/2017

Notes: The plumbing fixtures are original, not efficient or low flow fixtures.

System: D2020 - Domestic Water Distribution



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 10,300.00
Unit of Measure: S.F.
Estimate: \$11,217.00
Assessor Name: Eduardo Lopez
Date Created: 01/13/2017

Notes: There are no reported issues or observed deficiencies with the domestic water piping. Due to the age of the pipe there can be internal pitting corrosion that may be a costly problem that leads to the formation of pinhole leaks and possible water contamination.

System: D2030 - Sanitary Waste



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 10,300.00
Unit of Measure: S.F.
Estimate: \$17,788.00
Assessor Name: Eduardo Lopez
Date Created: 01/13/2017

Notes: There are no reported issues or observed deficiencies with the sanitary waste piping. The aging sanitary sewer piping is subject to leaks, infiltration, and it can even collapse in the interior walls. The system should be inspected with cameras to ensure that none of these deficiencies exist.

System: D3040 - Distribution Systems



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 10,300.00
Unit of Measure: S.F.
Estimate: \$70,926.00
Assessor Name: Eduardo Lopez
Date Created: 01/13/2017

Notes: The exhaust fans, and hot water supply distribution system is aged, in marginal condition, and should be replaced.

System: D5030910 - Fire Alarm Systems



Location: Throughout
Distress: Beyond Service Life
Category: Building Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 10,300.00
Unit of Measure: S.F.
Estimate: \$39,202.00
Assessor Name: Eduardo Lopez
Date Created: 01/04/2017

Notes: The original alarm system is operating but is aged. The system should be inspected and repaired or replaced to ensure that the life safety codes are preserved.

System: E2010 - Fixed Furnishings



Location: Classrooms
Distress: Damaged
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 10,300.00
Unit of Measure: S.F.
Estimate: \$67,414.00
Assessor Name: Eduardo Lopez
Date Created: 01/04/2017

Notes: The building casework is aged and worn and should be replaced.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout the building
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 10,300.00
Unit of Measure: S.F.
Estimate: \$49,965.00
Assessor Name: Eduardo Lopez
Date Created: 01/04/2017

Notes: There are no sprinklers in the building.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout the building
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 10,300.00
Unit of Measure: S.F.
Estimate: \$7,818.00
Assessor Name: Eduardo Lopez
Date Created: 01/04/2017

Notes: There are no sprinklers in the building.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	16,000
Year Built:	1983
Last Renovation:	
Replacement Value:	\$3,154,400
Repair Cost:	\$971,939.00
Total FCI:	30.81 %
Total RSLI:	31.37 %
FCA Score:	69.19







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	ES -Elementary School	Gross Area:	16,000
Year Built:	1983	Last Renovation:	
Repair Cost:	\$971,939	Replacement Value:	\$3,154,400
FCI:	30.81 %	RSLI%:	31.37 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	66.00 %	0.00 %	\$0.00
A20 - Basement Construction	66.00 %	0.00 %	\$0.00
B10 - Superstructure	66.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	38.33 %	0.00 %	\$0.00
B30 - Roofing	0.00 %	142.40 %	\$109,363.00
C10 - Interior Construction	33.37 %	0.00 %	\$0.00
C30 - Interior Finishes	8.86 %	97.81 %	\$401,104.00
D20 - Plumbing	2.39 %	90.27 %	\$206,096.00
D30 - HVAC	21.80 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	110.00 %	\$89,760.00
D50 - Electrical	28.03 %	13.17 %	\$60,896.00
E10 - Equipment	15.00 %	0.00 %	\$0.00
E20 - Furnishings	0.00 %	110.00 %	\$104,720.00
Totals:	31.37 %	30.81 %	\$971,939.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). East Elevation - Jan 10, 2017



2). South Elevation - Jan 10, 2017



3). West Elevation - Jan 10, 2017



4). North Elevation - Jan 10, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

Campus Assessment Report - 1983 Media Center

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.88	S.F.	16,000	100	1983	2083		66.00 %	0.00 %	66			\$78,080
A1030	Slab on Grade	\$8.61	S.F.	16,000	100	1983	2083		66.00 %	0.00 %	66			\$137,760
A2010	Basement Excavation	\$1.95	S.F.	16,000	100	1983	2083		66.00 %	0.00 %	66			\$31,200
A2020	Basement Walls	\$13.35	S.F.	16,000	100	1983	2083		66.00 %	0.00 %	66			\$213,600
B1010	Floor Construction	\$1.66	S.F.	16,000	100	1983	2083		66.00 %	0.00 %	66			\$26,560
B1020	Roof Construction	\$16.08	S.F.	16,000	100	1983	2083		66.00 %	0.00 %	66			\$257,280
B2010	Exterior Walls	\$9.61	S.F.	16,000	100	1983	2083		66.00 %	0.00 %	66			\$153,760
B2020	Exterior Windows	\$9.57	S.F.	16,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$153,120
B2030	Exterior Doors	\$1.07	S.F.	16,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$17,120
B3010140	Asphalt Shingles	\$4.32	S.F.	16,000	20	1983	2003		0.00 %	146.00 %	-14		\$100,915.00	\$69,120
B3020	Roof Openings	\$0.48	S.F.	16,000	20	1983	2003		0.00 %	110.00 %	-14		\$8,448.00	\$7,680
C1010	Partitions	\$11.01	S.F.	16,000	75	1983	2058		54.67 %	0.00 %	41			\$176,160
C1020	Interior Doors	\$2.59	S.F.	16,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$41,440
C1030	Fittings	\$9.94	S.F.	16,000	20	2000	2020		15.00 %	0.00 %	3			\$159,040
C3010	Wall Finishes	\$2.84	S.F.	16,000	10	2015	2025		80.00 %	0.00 %	8			\$45,440
C3020	Floor Finishes	\$11.60	S.F.	16,000	20	1983	2003		0.00 %	110.00 %	-14		\$204,160.00	\$185,600
C3030	Ceiling Finishes	\$11.19	S.F.	16,000	25	1983	2008		0.00 %	110.00 %	-9		\$196,944.00	\$179,040
D2010	Plumbing Fixtures	\$11.71	S.F.	16,000	30	1983	2013		0.00 %	110.00 %	-4		\$206,096.00	\$187,360
D2020	Domestic Water Distribution	\$0.99	S.F.	16,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$15,840
D2030	Sanitary Waste	\$1.57	S.F.	16,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$25,120
D3040	Distribution Systems	\$6.26	S.F.	16,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$100,160
D3050	Terminal & Package Units	\$13.65	S.F.	16,000	15	2000	2015	2021	26.67 %	0.00 %	4			\$218,400
D3060	Controls & Instrumentation	\$1.98	S.F.	16,000	20	2000	2020		15.00 %	0.00 %	3			\$31,680
D4010	Sprinklers	\$4.41	S.F.	16,000	30			2016	0.00 %	110.00 %	-1		\$77,616.00	\$70,560
D4020	Standpipes	\$0.69	S.F.	16,000	30			2016	0.00 %	110.00 %	-1		\$12,144.00	\$11,040
D5010	Electrical Service/Distribution	\$1.73	S.F.	16,000	40	1983	2023		15.00 %	0.00 %	6			\$27,680
D5020	Branch Wiring	\$5.20	S.F.	16,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$83,200
D5020	Lighting	\$12.12	S.F.	16,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$193,920
D5030810	Security & Detection Systems	\$1.91	S.F.	16,000	15	2015	2030		86.67 %	0.00 %	13			\$30,560
D5030910	Fire Alarm Systems	\$3.46	S.F.	16,000	15	1983	1998		0.00 %	110.00 %	-19		\$60,896.00	\$55,360
D5030920	Data Communication	\$4.47	S.F.	16,000	15	2015	2030		86.67 %	0.00 %	13			\$71,520
E1020	Institutional Equipment	\$0.30	S.F.	16,000	20	2000	2020		15.00 %	0.00 %	3			\$4,800
E2010	Fixed Furnishings	\$5.95	S.F.	16,000	20	1983	2003		0.00 %	110.00 %	-14		\$104,720.00	\$95,200
Total									31.37 %	30.81 %			\$971,939.00	\$3,154,400

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1983 Media Center

System: B3010140 - Asphalt Shingles



Note:

System: B3020 - Roof Openings



Note:

System: C1010 - Partitions



Note:

Campus Assessment Report - 1983 Media Center

System: C1020 - Interior Doors




Note:

System: C1030 - Fittings



Note:

System: C3010 - Wall Finishes



Note:

Campus Assessment Report - 1983 Media Center

System: C3020 - Floor Finishes



Note:

System: C3030 - Ceiling Finishes



Note:


System: D2010 - Plumbing Fixtures



Note:




Campus Assessment Report - 1983 Media Center

System: D2020 - Domestic Water Distribution




Note:

System: D2030 - Sanitary Waste



Note:

System: D3040 - Distribution Systems



Note:

Campus Assessment Report - 1983 Media Center

System: D3050 - Terminal & Package Units



Note:

System: D3060 - Controls & Instrumentation



Note:

System: D5010 - Electrical Service/Distribution



Note:



Campus Assessment Report - 1983 Media Center

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

System: D5030810 - Security & Detection Systems



Note:

Campus Assessment Report - 1983 Media Center

System: D5030910 - Fire Alarm Systems




Note:

System: D5030920 - Data Communication



Note:

System: E1020 - Institutional Equipment



Note:

Campus Assessment Report - 1983 Media Center

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$971,939	\$0	\$0	\$235,015	\$1,050,271	\$0	\$36,357	\$0	\$63,318	\$0	\$0	\$2,356,900
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$189,572	\$0	\$0	\$0	\$0	\$0	\$0	\$189,572
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$21,196	\$0	\$0	\$0	\$0	\$0	\$0	\$21,196
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010140 - Asphalt Shingles	\$100,915	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$100,915
B3020 - Roof Openings	\$8,448	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$8,448
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$51,305	\$0	\$0	\$0	\$0	\$0	\$0	\$51,305
C1030 - Fittings	\$0	\$0	\$0	\$191,166	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$191,166
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1983 Media Center

C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$63,318	\$0	\$0	\$63,318
C3020 - Floor Finishes	\$204,160	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$204,160
C3030 - Ceiling Finishes	\$196,944	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$196,944
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$206,096	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$206,096
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$19,611	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$19,611
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$31,100	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$31,100
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$124,004	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$124,004
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$270,392	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$270,392
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$38,079	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$38,079
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$77,616	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$77,616
D4020 - Standpipes	\$12,144	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$12,144
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$36,357	\$0	\$0	\$0	\$0	\$0	\$36,357
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$103,007	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$103,007
D5020 - Lighting	\$0	\$0	\$0	\$0	\$240,085	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$240,085
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Fire Alarm Systems	\$60,896	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$60,896
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$5,770	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$5,770
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$104,720	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$104,720

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$971,939.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$971,939.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B3010140	Asphalt Shingles	\$0.00	\$0.00	\$100,915.00	\$0.00	\$0.00	\$100,915.00
B3020	Roof Openings	\$0.00	\$0.00	\$8,448.00	\$0.00	\$0.00	\$8,448.00
C3020	Floor Finishes	\$0.00	\$0.00	\$204,160.00	\$0.00	\$0.00	\$204,160.00
C3030	Ceiling Finishes	\$0.00	\$0.00	\$196,944.00	\$0.00	\$0.00	\$196,944.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$206,096.00	\$0.00	\$0.00	\$206,096.00
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$77,616.00	\$0.00	\$77,616.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$12,144.00	\$0.00	\$12,144.00
D5030910	Fire Alarm Systems	\$0.00	\$0.00	\$60,896.00	\$0.00	\$0.00	\$60,896.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$104,720.00	\$0.00	\$0.00	\$104,720.00
	Total:	\$0.00	\$0.00	\$882,179.00	\$89,760.00	\$0.00	\$971,939.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B3010140 - Asphalt Shingles



Location: Roof
Distress: Damaged
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 16,000.00
Unit of Measure: S.F.
Estimate: \$100,915.00
Assessor Name: Terence Davis
Date Created: 01/10/2017

Notes: The roofing is aged, has reported leaks and should be replaced.

System: B3020 - Roof Openings



Location: 1983 Media Center
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 16,000.00
Unit of Measure: S.F.
Estimate: \$8,448.00
Assessor Name: Terence Davis
Date Created: 02/21/2017

Notes:

System: C3020 - Floor Finishes



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 16,000.00
Unit of Measure: S.F.
Estimate: \$204,160.00
Assessor Name: Terence Davis
Date Created: 01/04/2017

Notes:

System: C3030 - Ceiling Finishes



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 16,000.00
Unit of Measure: S.F.
Estimate: \$196,944.00
Assessor Name: Terence Davis
Date Created: 01/04/2017

Notes: The ceiling finishes are beyond their service life and should be replaced.

System: D2010 - Plumbing Fixtures



Location: Restroom
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 16,000.00
Unit of Measure: S.F.
Estimate: \$206,096.00
Assessor Name: Terence Davis
Date Created: 01/04/2017

Notes: The plumbing fixtures are original, not efficient or low flow fixtures.

System: D5030910 - Fire Alarm Systems



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 16,000.00
Unit of Measure: S.F.
Estimate: \$60,896.00
Assessor Name: Terence Davis
Date Created: 01/04/2017

Notes: The original alarm system is operating but is aged. The system should be inspected and repaired or replaced to ensure that the life safety codes are preserved.

System: E2010 - Fixed Furnishings



Location: Classrooms
Distress: Damaged
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 16,000.00
Unit of Measure: S.F.
Estimate: \$104,720.00
Assessor Name: Terence Davis
Date Created: 01/04/2017

Notes: The building casework is aged and worn and should be replaced.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout the building
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 16,000.00
Unit of Measure: S.F.
Estimate: \$77,616.00
Assessor Name: Terence Davis
Date Created: 01/04/2017

Notes: There are no sprinklers in the building.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout the building
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 16,000.00
Unit of Measure: S.F.
Estimate: \$12,144.00
Assessor Name: Terence Davis
Date Created: 01/04/2017

Notes: There are no sprinklers in the building.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	46,992
Year Built:	1958
Last Renovation:	
Replacement Value:	\$1,240,118
Repair Cost:	\$0.00
Total FCI:	0.00 %
Total RSLI:	19.90 %
FCA Score:	100.00



Description:

The narrative for this site is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.


Dashboard Summary

Function:	ES -Elementary School	Gross Area:	46,992
Year Built:	1958	Last Renovation:	
Repair Cost:	\$0	Replacement Value:	\$1,240,118
FCI:	0.00 %	RSLI%:	19.90 %

No data found for this asset

No data found for this asset

No data found for this asset



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	15.83 %	0.00 %	\$0.00
G30 - Site Mechanical Utilities	9.44 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	45.43 %	0.00 %	\$0.00
Totals:	19.90 %	0.00 %	\$0.00

Photo Album

The photo album consists of the various cardinal directions of the building..

- 1). Aerial Image of North Laurinburg Elementary School - Feb 27, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$3.81	S.F.	46,992	25	1958	1983	2021	16.00 %	0.00 %	4			\$179,040
G2020	Parking Lots	\$1.33	S.F.	46,992	25	1958	1983	2021	16.00 %	0.00 %	4			\$62,499
G2030	Pedestrian Paving	\$1.91	S.F.	46,992	30	1958	1988	2021	13.33 %	0.00 %	4			\$89,755
G2040105	Fence & Guardrails	\$1.23	S.F.	46,992	30	2000	2030		43.33 %	0.00 %	13			\$57,800
G2040950	Covered Walkways	\$1.52	S.F.	46,992	25	1983	2008	2021	16.00 %	0.00 %	4			\$71,428
G2040950	Hard Surface Play Area	\$0.75	S.F.	46,992	20	1958	1978	2021	20.00 %	0.00 %	4			\$35,244
G2040950	Playing Field	\$4.54	S.F.	46,992	20	2000	2020		15.00 %	0.00 %	3			\$213,344
G2050	Landscaping	\$1.87	S.F.	46,992	15	1958	1973		0.00 %	0.00 %	-44			\$87,875
G3010	Water Supply	\$2.34	S.F.	46,992	50	1958	2008	2021	8.00 %	0.00 %	4			\$109,961
G3020	Sanitary Sewer	\$1.45	S.F.	46,992	50	1958	2008	2021	8.00 %	0.00 %	4			\$68,138
G3060	Fuel Distribution	\$0.98	S.F.	46,992	40	1983	2023		15.00 %	0.00 %	6			\$46,052
G4010	Electrical Distribution	\$2.35	S.F.	46,992	50	1983	2033		32.00 %	0.00 %	16			\$110,431
G4020	Site Lighting	\$1.47	S.F.	46,992	30	2000	2030		43.33 %	0.00 %	13			\$69,078
G4030	Site Communications & Security	\$0.84	S.F.	46,992	15	2015	2030		86.67 %	0.00 %	13			\$39,473
Total									19.90 %					\$1,240,118

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: G2010 - Roadways



Note:

System: G2020 - Parking Lots



Note:

System: G2030 - Pedestrian Paving



Note:

Campus Assessment Report - Site

System: G2040105 - Fence & Guardrails



Note:

System: G2040950 - Covered Walkways



Note:

System: G2040950 - Hard Surface Play Area



Note:

Campus Assessment Report - Site

System: G2040950 - Playing Field



Note:

System: G2050 - Landscaping



Note:

System: G3010 - Water Supply



Note:

Campus Assessment Report - Site

System: G3020 - Sanitary Sewer



Note:

System: G3060 - Fuel Distribution



Note:

System: G4010 - Electrical Distribution



Note:

Campus Assessment Report - Site

System: G4020 - Site Lighting



Note:

System: G4030 - Site Communications & Security



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$0	\$0	\$0	\$256,439	\$762,724	\$0	\$60,487	\$0	\$0	\$0	\$0	\$1,079,650
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$0	\$0	\$0	\$0	\$221,661	\$0	\$0	\$0	\$0	\$0	\$0	\$221,661
G2020 - Parking Lots	\$0	\$0	\$0	\$0	\$77,378	\$0	\$0	\$0	\$0	\$0	\$0	\$77,378
G2030 - Pedestrian Paving	\$0	\$0	\$0	\$0	\$111,121	\$0	\$0	\$0	\$0	\$0	\$0	\$111,121
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040105 - Fence & Guardrails	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040950 - Covered Walkways	\$0	\$0	\$0	\$0	\$88,432	\$0	\$0	\$0	\$0	\$0	\$0	\$88,432
G2040950 - Hard Surface Play Area	\$0	\$0	\$0	\$0	\$43,634	\$0	\$0	\$0	\$0	\$0	\$0	\$43,634
G2040950 - Playing Field	\$0	\$0	\$0	\$256,439	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$256,439
* G2050 - Landscaping	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$0	\$0	\$0	\$0	\$136,138	\$0	\$0	\$0	\$0	\$0	\$0	\$136,138
G3020 - Sanitary Sewer	\$0	\$0	\$0	\$0	\$84,359	\$0	\$0	\$0	\$0	\$0	\$0	\$84,359
G3060 - Fuel Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$60,487	\$0	\$0	\$0	\$0	\$60,487
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system

Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.

No data found for this asset

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:

No data found for this asset

Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

No data found for this asset

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:

No data found for this asset

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

No data found for this asset

NC School District/830 Scotland County/Elementary School

South Scotland Elementary

Draft

Campus Assessment Report

March 7, 2017



Table of Contents

Campus Executive Summary	4
Campus Dashboard Summary	7
Campus Condition Summary	8
<u>1960, 1983 Main Building</u>	10
Executive Summary	10
Dashboard Summary	11
Condition Summary	12
Photo Album	13
Condition Detail	14
System Listing	15
System Notes	17
Renewal Schedule	27
Forecasted Sustainment Requirement	29
Deficiency Summary By System	30
Deficiency Summary By Priority	31
Deficiency By Priority Investment	32
Deficiency Summary By Category	33
Deficiency Details By Priority	34
<u>Site</u>	43
Executive Summary	43
Dashboard Summary	44
Condition Summary	45
Photo Album	46
Condition Detail	47
System Listing	48
System Notes	49
Renewal Schedule	54
Forecasted Sustainment Requirement	55
Deficiency Summary By System	56

Campus Assessment Report

Deficiency Summary By Priority	57
Deficiency By Priority Investment	58
Deficiency Summary By Category	59
Deficiency Details By Priority	60

Campus Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	42,369
Year Built:	1960
Last Renovation:	
Replacement Value:	\$9,581,674
Repair Cost:	\$3,612,368.32
Total FCI:	37.70 %
Total RSLI:	24.74 %
FCA Score:	62.30



Description:

GENERAL:

South Scotland Elementary School is located at 17200 Barnes Bridge Road, in Laurinburg, North Carolina. The 1 story, 29,609 square foot building was originally constructed in 1960. There have been 1 addition but no renovations. In 1983 12,760 square feet were added which is currently the media center and classrooms. In addition to the main building, the campus does not contain ancillary buildings.

This report contains condition and adequacy data collected during the 2016 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for the site and building elements.

A. SUBSTRUCTURE

The building rests on footings and foundation walls and is assumed to have standard cast-in-place concrete foundations. The building

Campus Assessment Report - South Scotland Elementary

does not have a basement.

B. SUPERSTRUCTURE

Floor construction is concrete. Roof construction is wood. The exterior envelope is composed of walls of brick veneer over CMU. Exterior windows are aluminum frame with operable panes. Exterior doors are hollow metal steel mostly with glazing. Roofing is typically low slope single ply membrane, the 1983 addition has pitched roof with asphalt shingle roofing. Roof opening include roof hatch with fixed ladder access. Most building entrances appear to comply with ADA requirements.

C. INTERIORS

Interior partitions are typically CMU. Interior doors are generally hollow core wood with hollow steel frames and mostly without glazing. Interior fittings include the following items: white boards, graphics and identifying devices, toilet accessories, storage shelving, and fabricated toilet partitions. The interior wall finishes are typically painted CMU and ceramic tiles. Floor finishes in common areas are typically vinyl composition tile. Floor finishes in assignable spaces is typically ceramic tile, quarry tiles and carpet. Ceiling finishes in common areas are typically suspended acoustical tile. Ceiling finishes in assignable areas are typically painted drywall.

CONVEYING:

The building does not include conveying equipment.

D. SERVICES

PLUMBING: Plumbing fixtures are typically non-low-flow water fixtures with manual control valves. Domestic water distribution is combination of copper and galvanized steel with electric hot water heating. Sanitary waste system is cast iron. Rain water drainage system is external with gutters and downspouts.

HVAC:

Heating is provided by 1 electric boilers. Cooling is supplied by pad and/or wall mounted package units. The heating/cooling distribution system is a ductwork system utilizing air handling units. Fresh air is supplied by air handling units. Ceiling mounted exhaust fans are installed in bathrooms and other required areas. Controls and instrumentation are digital and are centrally controlled by an energy management system. This building has a remote Building Automation System.

FIRE PROTECTION:

The building does not have a fire sprinkler system. The building does not have additional fire suppression systems. Fire extinguishers and cabinets are distributed near fire exits and corridors.

ELECTRICAL:

The main electrical service is fed from a pad mounted transformer to the main switchboard/distribution panel located in the building. Lighting is lay-in type, fluorescent light fixtures. Branch circuit wiring is typically copper serving electrical switches and receptacles. Emergency and life safety egress lighting systems are installed and exit signs are present at exit doors and are typically illuminated.

COMMUNICATIONS AND SECURITY:

The fire alarm system consists of audible/visual strobe annunciators in interior corridors. The system is activated by manual pull stations and smoke detectors and the system is centrally monitored. The telephone and data systems are segregated and include dedicated equipment closets. This building does have a local area network (LAN). The building includes an internal security system that is actuated by the following items: optical devices. The building has controlled entry doors access provided by camera access at the main door; entry doors are secured with magnetic door locks. The security system has only the burglar alarm system which is centrally monitored; this building has a public address and paging system combined with the telephone system.

OTHER ELECTRICAL SYSTEMS:

This building does not have a separately derived emergency power system. There are no natural gas emergency generator.

E. EQUIPMENT & FURNISHINGS:

This building includes the following items and equipment: fixed food service, theater and stage, audio-visual, fixed casework, and window treatment.

G. SITE

Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, play areas, and fencing. Site mechanical and electrical features include water, sewer, and site lighting.

Campus Assessment Report - South Scotland Elementary

Attributes:

General Attributes:





Condition Assessor: Somnath Das Assessment Date:
Suitability Assessor:

School Information:

HS Attendance Area:		LEA School No.:	
No. of Mobile Units:	0	No. of Bldgs.:	1
SF of Mobile Units:		Status:	
School Grades:	15	Site Acreage:	15

Campus Dashboard Summary

Gross Area:	42,369	Last Renovation:	
Year Built:	1960	Replacement Value:	\$9,581,674
Repair Cost:	\$3,612,368	RSLI%:	24.74 %
FCI:	37.70 %		



Campus Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Unifomat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	43.00 %	0.00 %	\$0.00
A20 - Basement Construction	43.00 %	0.00 %	\$0.00
B10 - Superstructure	43.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	27.41 %	0.00 %	\$0.00
B30 - Roofing	19.10 %	4.95 %	\$13,516.00
C10 - Interior Construction	11.24 %	59.85 %	\$585,054.00
C30 - Interior Finishes	13.49 %	48.80 %	\$519,815.32
D20 - Plumbing	2.40 %	90.20 %	\$535,036.00
D30 - HVAC	67.43 %	21.64 %	\$245,800.00
D40 - Fire Protection	0.00 %	110.00 %	\$232,563.00
D50 - Electrical	12.64 %	72.19 %	\$870,132.00
E10 - Equipment	2.73 %	95.00 %	\$88,551.00
E20 - Furnishings	0.00 %	110.00 %	\$271,712.00
G20 - Site Improvements	9.90 %	26.82 %	\$141,131.00
G30 - Site Mechanical Utilities	5.75 %	30.90 %	\$109,058.00
G40 - Site Electrical Utilities	13.05 %	0.00 %	\$0.00
Totals:	24.74 %	37.70 %	\$3,612,368.32

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance
1960, 1983 Main Building	42,369	39.53	\$13,200.00	\$0.00	\$3,348,979.32	\$0.00	\$0.00
Site	42,369	23.24	\$0.00	\$0.00	\$250,189.00	\$0.00	\$0.00
Total:		37.70	\$13,200.00	\$0.00	\$3,599,168.32	\$0.00	\$0.00

Deficiencies By Priority



- 1 - Currently Critical (Immediate) - \$13,200.00
- 2 - Potentially Critical (Year 1)
- 3 - Necessary/Not Yet Critical (Years 2-5) - \$3,599,168.32
- 4 - Recommended (Years 6-10)
- 5 - Codes or Standards Compliance

Budget Estimate Total: \$3,612,368.32

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	42,369
Year Built:	1960
Last Renovation:	
Replacement Value:	\$8,505,078
Repair Cost:	\$3,362,179.32
Total FCI:	39.53 %
Total RSLI:	26.72 %
FCA Score:	60.47







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	ES -Elementary School	Gross Area:	42,369
Year Built:	1960	Last Renovation:	
Repair Cost:	\$3,362,179	Replacement Value:	\$8,505,078
FCI:	39.53 %	RSLI%:	26.72 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	43.00 %	0.00 %	\$0.00
A20 - Basement Construction	43.00 %	0.00 %	\$0.00
B10 - Superstructure	43.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	27.41 %	0.00 %	\$0.00
B30 - Roofing	19.10 %	4.95 %	\$13,516.00
C10 - Interior Construction	11.24 %	59.85 %	\$585,054.00
C30 - Interior Finishes	13.49 %	48.80 %	\$519,815.32
D20 - Plumbing	2.40 %	90.20 %	\$535,036.00
D30 - HVAC	67.43 %	21.64 %	\$245,800.00
D40 - Fire Protection	0.00 %	110.00 %	\$232,563.00
D50 - Electrical	12.64 %	72.19 %	\$870,132.00
E10 - Equipment	2.73 %	95.00 %	\$88,551.00
E20 - Furnishings	0.00 %	110.00 %	\$271,712.00
Totals:	26.72 %	39.53 %	\$3,362,179.32

Photo Album

The photo album consists of the various cardinal directions of the building..

1). North Elevation - Feb 10, 2017



2). South Elevation - Feb 10, 2017



3). West Elevation - Feb 10, 2017



4). South Elevation - Feb 10, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Campus Assessment Report - 1960, 1983 Main Building

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.79	S.F.	42,369	100	1960	2060		43.00 %	0.00 %	43			\$202,948
A1030	Slab on Grade	\$8.43	S.F.	42,369	100	1960	2060		43.00 %	0.00 %	43			\$357,171
A2010	Basement Excavation	\$1.90	S.F.	42,369	100	1960	2060		43.00 %	0.00 %	43			\$80,501
A2020	Basement Walls	\$13.07	S.F.	42,369	100	1960	2060		43.00 %	0.00 %	43			\$553,763
B1020	Roof Construction	\$15.76	S.F.	42,369	100	1960	2060		43.00 %	0.00 %	43			\$667,735
B2010	Exterior Walls	\$9.42	S.F.	42,369	100	1960	2060		43.00 %	0.00 %	43			\$399,116
B2020	Exterior Windows	\$9.39	S.F.	42,369	30	1960	1990	2021	13.33 %	0.00 %	4			\$397,845
B2030	Exterior Doors	\$1.04	S.F.	42,369	30	1960	1990	2021	13.33 %	0.00 %	4			\$44,064
B3010120	Single Ply Membrane	\$6.98	S.F.	29,279	20	1960	1980	2021	20.00 %	0.00 %	4			\$204,367
B3010140	Asphalt Shingles	\$4.32	S.F.	13,090	20	1983	2003	2021	20.00 %	0.00 %	4			\$56,549
B3020	Roof Openings	\$0.29	S.F.	42,369	25	1960	1985		0.00 %	110.00 %	-32		\$13,516.00	\$12,287
C1010	Partitions	\$10.80	S.F.	42,369	75	1960	2035		24.00 %	2.88 %	18		\$13,200.00	\$457,585
C1020	Interior Doors	\$2.53	S.F.	42,369	30	1960	1990		0.00 %	110.00 %	-27		\$117,913.00	\$107,194
C1030	Fittings	\$9.74	S.F.	42,369	20	1960	1980		0.00 %	110.00 %	-37		\$453,941.00	\$412,674
C3010	Wall Finishes	\$2.79	S.F.	42,369	10	1960	1970	2021	40.00 %	0.00 %	4			\$118,210
C3020	Floor Finishes	\$11.38	S.F.	42,369	20	1960	1980	2021	20.00 %	1.77 %	4		\$8,548.32	\$482,159
C3030	Ceiling Finishes	\$10.97	S.F.	42,369	25	1960	1985		0.00 %	110.00 %	-32		\$511,267.00	\$464,788
D2010	Plumbing Fixtures	\$11.48	S.F.	42,369	30	1960	1990		0.00 %	110.00 %	-27		\$535,036.00	\$486,396
D2020	Domestic Water Distribution	\$0.98	S.F.	42,369	30	1960	1990	2021	13.33 %	0.00 %	4			\$41,522
D2030	Sanitary Waste	\$1.54	S.F.	42,369	30	1960	1990	2021	13.33 %	0.00 %	4			\$65,248
D3020	Heat Generating Systems	\$5.08	S.F.	42,369	30	1960	1990		0.00 %	110.00 %	-27		\$236,758.00	\$215,235
D3040	Distribution Systems	\$6.14	S.F.	42,369	30	2009	2039		73.33 %	0.00 %	22			\$260,146
D3050	Terminal & Package Units	\$13.65	S.F.	42,369	15	2015	2030		86.67 %	1.56 %	13		\$9,042.00	\$578,337
D3060	Controls & Instrumentation	\$1.94	S.F.	42,369	20	2015	2035		90.00 %	0.00 %	18			\$82,196
D4010	Sprinklers	\$4.32	S.F.	42,369	30			2016	0.00 %	110.00 %	-1		\$201,337.00	\$183,034
D4020	Standpipes	\$0.67	S.F.	42,369	30			2016	0.00 %	110.00 %	-1		\$31,226.00	\$28,387
D5010	Electrical Service/Distribution	\$1.69	S.F.	42,369	40	1960	2000		0.00 %	110.00 %	-17		\$78,764.00	\$71,604
D5020	Branch Wiring	\$5.06	S.F.	42,369	30	1960	1990		0.00 %	110.00 %	-27		\$235,826.00	\$214,387
D5020	Lighting	\$11.92	S.F.	42,369	30	1960	1990		0.00 %	110.00 %	-27		\$555,542.00	\$505,038
D5030810	Security & Detection Systems	\$1.87	S.F.	42,369	15	2014	2029		80.00 %	0.00 %	12			\$79,230
D5030910	Fire Alarm Systems	\$3.39	S.F.	42,369	15	1960	1975	2021	26.67 %	0.00 %	4			\$143,631
D5030920	Data Communication	\$4.40	S.F.	42,369	15	1960	1975	2021	26.67 %	0.00 %	4			\$186,424
D5090	Other Electrical Systems	\$0.12	S.F.	42,369	20	1960	1980	2021	20.00 %	0.00 %	4			\$5,084
E1020	Institutional Equipment	\$0.30	S.F.	42,369	20	1960	1980	2021	20.00 %	0.00 %	4			\$12,711
E1090	Other Equipment	\$1.90	S.F.	42,369	20	1960	1980		0.00 %	110.00 %	-37		\$88,551.00	\$80,501
E2010	Fixed Furnishings	\$5.83	S.F.	42,369	20	1960	1980		0.00 %	110.00 %	-37		\$271,712.00	\$247,011
Total									26.72 %	39.53 %			\$3,362,179.32	\$8,505,078

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls




Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1960, 1983 Main Building

System: B3010120 - Single Ply Membrane



Note: The TPO was installed in 2015

System: B3010140 - Asphalt Shingles



Note:



System: B3020 - Roof Openings



Note: The roof opening is beyond its service life and should be replaced with an OSHA compliant access hatch.


Campus Assessment Report - 1960, 1983 Main Building

System: C1010 - Partitions




Note:

System: C1020 - Interior Doors



Note: The interior doors are beyond their service life and should be replaced.


System: C1030 - Fittings



Note: The fittings are beyond their service life and should be replaced.


Campus Assessment Report - 1960, 1983 Main Building

System: C3010 - Wall Finishes





Note:

System: C3020 - Floor Finishes



Note: The carpet is beyond its service life and should be replaced.


System: C3030 - Ceiling Finishes



Note: The acoustical ceiling tiles are beyond their service life and should be replaced.

Campus Assessment Report - 1960, 1983 Main Building

System: D2010 - Plumbing Fixtures



Note: The plumbing fixtures are beyond their service life and should be replaced.

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

Campus Assessment Report - 1960, 1983 Main Building

System: D3020 - Heat Generating Systems



Note:

System: D3040 - Distribution Systems



Note:

System: D3050 - Terminal & Package Units



Note:

Campus Assessment Report - 1960, 1983 Main Building

System: D3060 - Controls & Instrumentation



Note:

System: D4010 - Sprinklers

This system contains no images

Note: The building does not have a fire protection system and it should be installed.

System: D4020 - Standpipes

This system contains no images


Note: The building does not have a fire protection system and it should be installed.

System: D5010 - Electrical Service/Distribution



Note: The main electrical system is beyond its service life and should be replaced.




System: D5020 - Branch Wiring



Note: The branch wiring system is beyond its service life and should be replaced.

Campus Assessment Report - 1960, 1983 Main Building

System: D5020 - Lighting



Note: The lights are primarily T-12's and are beyond their service life and they get replaced by T-8's as per needs basis.

System: D5030810 - Security & Detection Systems



Note:


System: D5030910 - Fire Alarm Systems



Note:

Campus Assessment Report - 1960, 1983 Main Building

System: D5030920 - Data Communication



Note:

System: D5090 - Other Electrical Systems



Note:

System: E1020 - Institutional Equipment



Note:

Campus Assessment Report - 1960, 1983 Main Building

System: E1090 - Other Equipment



Note: The kitchen equipment is beyond its service life and should be replaced.

System: E2010 - Fixed Furnishings



Note: The fixed furnishings are beyond their service life and should be replaced.

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$3,362,179	\$0	\$0	\$0	\$2,291,196	\$0	\$0	\$0	\$0	\$0	\$0	\$5,653,375
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$492,555	\$0	\$0	\$0	\$0	\$0	\$0	\$492,555
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$54,553	\$0	\$0	\$0	\$0	\$0	\$0	\$54,553
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010120 - Single Ply Membrane	\$0	\$0	\$0	\$0	\$345,026	\$0	\$0	\$0	\$0	\$0	\$0	\$345,026
B3010140 - Asphalt Shingles	\$0	\$0	\$0	\$0	\$92,923	\$0	\$0	\$0	\$0	\$0	\$0	\$92,923
B3020 - Roof Openings	\$13,516	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$13,516
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$13,200	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$13,200
C1020 - Interior Doors	\$117,913	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$117,913
C1030 - Fittings	\$453,941	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$453,941
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1960, 1983 Main Building

C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$146,350	\$0	\$0	\$0	\$0	\$0	\$0	\$146,350
C3020 - Floor Finishes	\$8,548	\$0	\$0	\$0	\$596,942	\$0	\$0	\$0	\$0	\$0	\$0	\$605,490
C3030 - Ceiling Finishes	\$511,267	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$511,267
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$535,036	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$535,036
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$51,406	\$0	\$0	\$0	\$0	\$0	\$0	\$51,406
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$80,781	\$0	\$0	\$0	\$0	\$0	\$0	\$80,781
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$236,758	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$236,758
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$9,042	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$9,042
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$201,337	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$201,337
D4020 - Standpipes	\$31,226	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$31,226
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$78,764	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$78,764
D5020 - Branch Wiring	\$235,826	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$235,826
D5020 - Lighting	\$555,542	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$555,542
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$177,824	\$0	\$0	\$0	\$0	\$0	\$0	\$177,824
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$230,804	\$0	\$0	\$0	\$0	\$0	\$0	\$230,804
D5090 - Other Electrical Systems	\$0	\$0	\$0	\$0	\$6,295	\$0	\$0	\$0	\$0	\$0	\$0	\$6,295
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$15,737	\$0	\$0	\$0	\$0	\$0	\$0	\$15,737
E1090 - Other Equipment	\$88,551	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$88,551
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$271,712	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$271,712

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$3,362,179.32

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$3,362,179.32


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B3020	Roof Openings	\$0.00	\$0.00	\$13,516.00	\$0.00	\$0.00	\$13,516.00
C1010	Partitions	\$13,200.00	\$0.00	\$0.00	\$0.00	\$0.00	\$13,200.00
C1020	Interior Doors	\$0.00	\$0.00	\$117,913.00	\$0.00	\$0.00	\$117,913.00
C1030	Fittings	\$0.00	\$0.00	\$453,941.00	\$0.00	\$0.00	\$453,941.00
C3020	Floor Finishes	\$0.00	\$0.00	\$8,548.32	\$0.00	\$0.00	\$8,548.32
C3030	Ceiling Finishes	\$0.00	\$0.00	\$511,267.00	\$0.00	\$0.00	\$511,267.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$535,036.00	\$0.00	\$0.00	\$535,036.00
D3020	Heat Generating Systems	\$0.00	\$0.00	\$236,758.00	\$0.00	\$0.00	\$236,758.00
D3050	Terminal & Package Units	\$0.00	\$0.00	\$9,042.00	\$0.00	\$0.00	\$9,042.00
D4010	Sprinklers	\$0.00	\$0.00	\$201,337.00	\$0.00	\$0.00	\$201,337.00
D4020	Standpipes	\$0.00	\$0.00	\$31,226.00	\$0.00	\$0.00	\$31,226.00
D5010	Electrical Service/Distribution	\$0.00	\$0.00	\$78,764.00	\$0.00	\$0.00	\$78,764.00
D5020	Branch Wiring	\$0.00	\$0.00	\$235,826.00	\$0.00	\$0.00	\$235,826.00
D5020	Lighting	\$0.00	\$0.00	\$555,542.00	\$0.00	\$0.00	\$555,542.00
E1090	Other Equipment	\$0.00	\$0.00	\$88,551.00	\$0.00	\$0.00	\$88,551.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$271,712.00	\$0.00	\$0.00	\$271,712.00
	Total:	\$13,200.00	\$0.00	\$3,348,979.32	\$0.00	\$0.00	\$3,362,179.32

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:




Budget Estimate Total: \$3,362,179.32

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 1 - Currently Critical (Immediate):

System: C1010 - Partitions



Location: Media Center
Distress: Failing
Category: Safety / Building Code Compliance
Priority: 1 - Currently Critical (Immediate)
Correction: Engineering Study
Qty: 1.00
Unit of Measure: Ea.
Estimate: \$13,200.00
Assessor Name: Terence Davis
Date Created: 01/04/2017

Notes: There are visible cracks on the partition wall which should be studied by a professional engineer.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B3020 - Roof Openings



Location: Roof
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 42,369.00
Unit of Measure: S.F.
Estimate: \$13,516.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The roof opening is beyond its service life and should be replaced with an OSHA compliant access hatch.

System: C1020 - Interior Doors



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 42,369.00
Unit of Measure: S.F.
Estimate: \$117,913.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The interior doors are beyond their service life and should be replaced.

System: C1030 - Fittings



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 42,369.00
Unit of Measure: S.F.
Estimate: \$453,941.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The fittings are beyond their service life and should be replaced.

System: C3020 - Floor Finishes



Location: Media Center
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Replace carpet
Qty: 100.00
Unit of Measure: S.Y.
Estimate: \$8,548.32
Assessor Name: Terence Davis
Date Created: 02/10/2017

Notes: The carpet is beyond its service life and should be replaced.

System: C3030 - Ceiling Finishes



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 42,369.00
Unit of Measure: S.F.
Estimate: \$511,267.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The acoustical ceiling tiles are beyond their service life and should be replaced.

System: D2010 - Plumbing Fixtures



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 42,369.00
Unit of Measure: S.F.
Estimate: \$535,036.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The plumbing fixtures are beyond their service life and should be replaced.

System: D3020 - Heat Generating Systems



Location: Mechanical Room
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 42,369.00
Unit of Measure: S.F.
Estimate: \$236,758.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The heat generating systems is beyond their service life and should be replaced.

System: D3050 - Terminal & Package Units



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Replace baseboard heater units
Qty: 25.00
Unit of Measure: Ea.
Estimate: \$9,042.00
Assessor Name: Terence Davis
Date Created: 01/04/2017

Notes: The unit heaters and the radiating heaters are beyond their service life and should be replaced.

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout Building
Distress: Missing
Category: Building Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 42,369.00
Unit of Measure: S.F.
Estimate: \$201,337.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The building does not have a fire protection system and it should be installed.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout Building
Distress: Missing
Category: Building Code Compliance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 42,369.00
Unit of Measure: S.F.
Estimate: \$31,226.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The building does not have a fire protection system and it should be installed.

System: D5010 - Electrical Service/Distribution



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 42,369.00
Unit of Measure: S.F.
Estimate: \$78,764.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The main electrical system is beyond its service life and should be replaced.

System: D5020 - Branch Wiring



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 42,369.00
Unit of Measure: S.F.
Estimate: \$235,826.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The branch wiring system is beyond its service life and should be replaced.

System: D5020 - Lighting



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 42,369.00
Unit of Measure: S.F.
Estimate: \$555,542.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The lights are primarily T-12's and are beyond their service life and they get replaced by T-8's as per needs basis.

System: E1090 - Other Equipment



Location: Kitchen
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 42,369.00
Unit of Measure: S.F.
Estimate: \$88,551.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The kitchen equipment is beyond its service life and should be replaced.

System: E2010 - Fixed Furnishings



Location: Throughout Building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 42,369.00
Unit of Measure: S.F.
Estimate: \$271,712.00
Assessor Name: Terence Davis
Date Created: 12/30/2016

Notes: The fixed furnishings are beyond their service life and should be replaced.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	42,369
Year Built:	1960
Last Renovation:	
Replacement Value:	\$1,076,596
Repair Cost:	\$250,189.00
Total FCI:	23.24 %
Total RSLI:	9.12 %
FCA Score:	76.76







Description:

The narrative for this site is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	ES -Elementary School	Gross Area:	42,369
Year Built:	1960	Last Renovation:	
Repair Cost:	\$250,189	Replacement Value:	\$1,076,596
FCI:	23.24 %	RSLI%:	9.12 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	9.90 %	26.82 %	\$141,131.00
G30 - Site Mechanical Utilities	5.75 %	30.90 %	\$109,058.00
G40 - Site Electrical Utilities	13.05 %	0.00 %	\$0.00
Totals:	9.12 %	23.24 %	\$250,189.00

Photo Album

The photo album consists of the various cardinal directions of the building..

- 1). Aerial Image of South Scotland Elementary School - Dec 30, 2016



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$3.81	S.F.	42,369	25	1960	1985	2021	16.00 %	10.63 %	4		\$17,160.00	\$161,426
G2020	Parking Lots	\$1.33	S.F.	42,369	25	1960	1985	2021	16.00 %	0.00 %	4			\$56,351
G2030	Pedestrian Paving	\$1.91	S.F.	42,369	30	1960	1990		0.00 %	110.00 %	-27		\$89,017.00	\$80,925
G2040105	Fence & Guardrails	\$1.23	S.F.	42,369	30	1960	1990	2021	13.33 %	0.00 %	4			\$52,114
G2040950	Covered Walkways	\$1.52	S.F.	42,369	25	1960	1985	2021	16.00 %	0.00 %	4			\$64,401
G2040950	Hard Surface Play Area	\$0.75	S.F.	42,369	20	1960	1980		0.00 %	110.00 %	-37		\$34,954.00	\$31,777
G2050	Landscaping	\$1.87	S.F.	42,369	15	1960	1975		0.00 %	0.00 %	-42			\$79,230
G3010	Water Supply	\$2.34	S.F.	42,369	50	1960	2010		0.00 %	110.00 %	-7		\$109,058.00	\$99,143
G3020	Sanitary Sewer	\$1.45	S.F.	42,369	50	1960	2010	2021	8.00 %	0.00 %	4			\$61,435
G3030	Storm Sewer	\$4.54	S.F.	42,369	50	1960	2010	2021	8.00 %	0.00 %	4			\$192,355
G4010	Electrical Distribution	\$2.35	S.F.	42,369	50	1960	2010	2021	8.00 %	0.00 %	4			\$99,567
G4020	Site Lighting	\$1.47	S.F.	42,369	30	1960	1990	2021	13.33 %	0.00 %	4			\$62,282
G4030	Site Communications & Security	\$0.84	S.F.	42,369	15	1960	1975	2021	26.67 %	0.00 %	4			\$35,590
Total									9.12 %	23.24 %			\$250,189.00	\$1,076,596

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: G2010 - Roadways



Note: The roads need to be resealed.

System: G2020 - Parking Lots



Note: The parking striping was done in 2014.

System: G2030 - Pedestrian Paving



Note: The pedestrian paving is cracked and beyond its service life and should be replaced.

Campus Assessment Report - Site

System: G2040105 - Fence & Guardrails



Note:

System: G2040950 - Covered Walkways



Note:

System: G2040950 - Hard Surface Play Area



Note: The hard surface is beyond its service life and should be replaced.

Campus Assessment Report - Site

System: G2050 - Landscaping



Note:

System: G3010 - Water Supply



Note:

System: G3020 - Sanitary Sewer



Note:

Campus Assessment Report - Site

System: G3030 - Storm Sewer



Note:

System: G4010 - Electrical Distribution



Note:

System: G4020 - Site Lighting



Note:

Campus Assessment Report - Site

System: G4030 - Site Communications & Security



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$250,189	\$0	\$0	\$0	\$972,523	\$0	\$0	\$0	\$0	\$0	\$0	\$1,222,712
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$17,160	\$0	\$0	\$0	\$199,854	\$0	\$0	\$0	\$0	\$0	\$0	\$217,014
G2020 - Parking Lots	\$0	\$0	\$0	\$0	\$69,766	\$0	\$0	\$0	\$0	\$0	\$0	\$69,766
G2030 - Pedestrian Paving	\$89,017	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$89,017
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040105 - Fence & Guardrails	\$0	\$0	\$0	\$0	\$64,520	\$0	\$0	\$0	\$0	\$0	\$0	\$64,520
G2040950 - Covered Walkways	\$0	\$0	\$0	\$0	\$79,732	\$0	\$0	\$0	\$0	\$0	\$0	\$79,732
G2040950 - Hard Surface Play Area	\$34,954	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$34,954
* G2050 - Landscaping	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$109,058	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$109,058
G3020 - Sanitary Sewer	\$0	\$0	\$0	\$0	\$76,061	\$0	\$0	\$0	\$0	\$0	\$0	\$76,061
G3030 - Storm Sewer	\$0	\$0	\$0	\$0	\$238,148	\$0	\$0	\$0	\$0	\$0	\$0	\$238,148
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$0	\$0	\$0	\$0	\$123,270	\$0	\$0	\$0	\$0	\$0	\$0	\$123,270
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$77,110	\$0	\$0	\$0	\$0	\$0	\$0	\$77,110
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$44,063	\$0	\$0	\$0	\$0	\$0	\$0	\$44,063

** Indicates non-renewable system*


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$250,189.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$250,189.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
G2010	Roadways	\$0.00	\$0.00	\$17,160.00	\$0.00	\$0.00	\$17,160.00
G2030	Pedestrian Paving	\$0.00	\$0.00	\$89,017.00	\$0.00	\$0.00	\$89,017.00
G2040950	Hard Surface Play Area	\$0.00	\$0.00	\$34,954.00	\$0.00	\$0.00	\$34,954.00
G3010	Water Supply	\$0.00	\$0.00	\$109,058.00	\$0.00	\$0.00	\$109,058.00
	Total:	\$0.00	\$0.00	\$250,189.00	\$0.00	\$0.00	\$250,189.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: G2010 - Roadways



Location: Site
Distress: Failing
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Resurface the roadway
Qty: 100.00
Unit of Measure: L.F.
Estimate: \$17,160.00
Assessor Name: Eduardo Lopez
Date Created: 01/05/2017

Notes: The roadways are cracking and they need to be resurfaced and resealed.

System: G2030 - Pedestrian Paving



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 42,369.00
Unit of Measure: S.F.
Estimate: \$89,017.00
Assessor Name: Eduardo Lopez
Date Created: 02/10/2017

Notes: The pedestrian paving is cracked and beyond its service life and should be replaced.

System: G2040950 - Hard Surface Play Area



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 42,369.00
Unit of Measure: S.F.
Estimate: \$34,954.00
Assessor Name: Eduardo Lopez
Date Created: 02/10/2017

Notes: The hard surface is beyond its service life and should be replaced.

System: G3010 - Water Supply



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 42,369.00
Unit of Measure: S.F.
Estimate: \$109,058.00
Assessor Name: Eduardo Lopez
Date Created: 02/10/2017

Notes: The water supply system is beyond its service life and should be replaced.

NC School District/830 Scotland County/Elementary School

Sycamore Lane Elementary

Draft

Campus Assessment Report

March 9, 2017



Table of Contents

Campus Executive Summary	4
Campus Dashboard Summary	7
Campus Condition Summary	8
<u>1983 Building</u>	10
Executive Summary	10
Dashboard Summary	11
Condition Summary	12
Photo Album	13
Condition Detail	14
System Listing	15
System Notes	17
Renewal Schedule	26
Forecasted Sustainment Requirement	28
Deficiency Summary By System	29
Deficiency Summary By Priority	30
Deficiency By Priority Investment	31
Deficiency Summary By Category	32
Deficiency Details By Priority	33
<u>Site</u>	36
Executive Summary	36
Dashboard Summary	37
Condition Summary	38
Photo Album	39
Condition Detail	40
System Listing	41
System Notes	42
Renewal Schedule	47
Forecasted Sustainment Requirement	48
Deficiency Summary By System	49

Campus Assessment Report

Deficiency Summary By Priority	50
Deficiency By Priority Investment	51
Deficiency Summary By Category	52
Deficiency Details By Priority	53

Campus Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	80,000
Year Built:	1983
Last Renovation:	
Replacement Value:	\$18,891,200
Repair Cost:	\$3,669,600.00
Total FCI:	19.42 %
Total RSLI:	30.57 %
FCA Score:	80.58



Description:

GENERAL:

Sycamore Lane Elementary is located at 2100 Sycamore Lane in Laurinburg, North Carolina. The 1 story, 80,000 square foot building was originally constructed in 1983 There have been no additions or no renovations.

This report contains condition and adequacy data collected during the 2016 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for the site and building elements.

A. SUBSTRUCTURE

The building rests on slab-on grade and is assumed to have standard cast-in-place concrete foundations. The building does not have a basement of cast in-place construction.

Campus Assessment Report - Sycamore Lane Elementary

B. SUPERSTRUCTURE

Roof construction is steel and metal decking. The exterior envelope is composed of walls of brick veneer over CMU. Exterior windows are aluminum frame with operable panes. Exterior doors are hollow metal steel mostly with glazing. Roofing is typically low slope Preformed Metal roofing. Most building entrances appear to comply with minimum ADA requirements.

C. INTERIORS

Interior partitions are typically CMU. Interior doors are generally solid core wood with wood frames. Interior fittings include the following items: lockers, white boards, toilet accessories, storage shelving, and fabricated toilet partitions. The interior wall finishes are typically painted CMU. Floor finishes throughout are typically vinyl composition tile, and ceramic tile in the restrooms. Ceiling finishes throughout are typically suspended acoustical tile.

CONVEYING:

The building does not include conveying equipment.

D. SERVICES

PLUMBING:

Plumbing fixtures are typically non-low-flow water fixtures with manual control valves. Domestic water distribution is copper with electric hot water heating. Sanitary waste system is galvanized piping. Rain water drainage system is internal with roof drains.

HVAC:

Heating is provided by an electric boiler connected to a large water storage tank. Cooling is supplied a forced draft, centrifugal fan cooling tower. The heating/cooling distribution system is a ductwork system utilizing air handling units. Fresh air is supplied by air handling units. Ceiling mounted exhaust fans are installed in bathrooms and other required areas. Controls and instrumentation are digital and are centrally controlled by an energy management system.

FIRE PROTECTION:

The building does not have a fire sprinkler system. The building does have additional fire suppression systems, which include dry chemical for the kitchen hood protection. Fire extinguishers and cabinets are distributed near fire exits and corridors.

ELECTRICAL:

The main electrical service is fed from a pad mounted transformer to the main switchboard/distribution panel located in the building. Lighting is lay-in type, fluorescent light fixtures. Branch circuit wiring is typically copper serving electrical switches and receptacles. Emergency and life safety egress lighting systems are installed and exit signs are present at exit doors and near stairways and are typically illuminated.

COMMUNICATIONS AND SECURITY:

The fire alarm system consists of audible/visual strobe annunciators in common spaces, balconies and interior corridors. The system is activated by manual pull stations and smoke detectors and the system is centrally monitored. The telephone and data systems are segregated and include dedicated equipment closets. This building does have a local area network (LAN). The building includes an internal security system that is actuated by the following items: contacts, infrared, optical or a combination of all devices. The building has controlled entry doors access provided by card readers; entry doors are secured with magnetic door locks. The security system has CCTV cameras and is centrally monitored; this building has a public address and paging system separate from the telephone system.

OTHER ELECTRICAL SYSTEMS:

This building does not have a separately derived emergency power system.

E. EQUIPMENT & FURNISHINGS:

This building includes the following items and equipment: fixed food service, library equipment, athletic equipment, theater and stage, audio-visual, fixed casework, window treatment, floor grilles and mats, and multiple seating furnishings.

G. SITE:

Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, play areas, and fencing. Site mechanical and electrical features include water, sewer, natural gas, and site lighting.

Campus Assessment Report - Sycamore Lane Elementary

Attributes:

General Attributes:





Condition Assessor: Terence Davis Assessment Date:
Suitability Assessor:

School Information:

HS Attendance Area: LEA School No.:
No. of Mobile Units: 9 No. of Bldgs.: 1
SF of Mobile Units: Status:
School Grades: Site Acreage:

Campus Dashboard Summary

Gross Area:	80,000	Last Renovation:	
Year Built:	1983	Replacement Value:	\$18,891,200
Repair Cost:	\$3,669,600	RSLI%:	30.57 %
FCI:	19.42 %		



Campus Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Unifomat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	66.00 %	0.00 %	\$0.00
A20 - Basement Construction	66.00 %	0.00 %	\$0.00
B10 - Superstructure	66.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	38.33 %	0.00 %	\$0.00
B30 - Roofing	13.41 %	0.00 %	\$0.00
C10 - Interior Construction	33.39 %	0.00 %	\$0.00
C30 - Interior Finishes	8.88 %	97.79 %	\$1,966,800.00
D20 - Plumbing	13.33 %	0.00 %	\$0.00
D30 - HVAC	25.38 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	110.00 %	\$439,120.00
D50 - Electrical	26.66 %	13.16 %	\$298,320.00
E10 - Equipment	19.32 %	0.00 %	\$0.00
E20 - Furnishings	0.00 %	110.00 %	\$513,040.00
G20 - Site Improvements	15.18 %	21.94 %	\$452,320.00
G30 - Site Mechanical Utilities	32.00 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	45.43 %	0.00 %	\$0.00
Totals:	30.57 %	19.42 %	\$3,669,600.00

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance
1983 Building	80,000	20.37	\$0.00	\$0.00	\$2,778,160.00	\$439,120.00	\$0.00
Site	80,000	14.59	\$0.00	\$0.00	\$452,320.00	\$0.00	\$0.00
Total:		19.42	\$0.00	\$0.00	\$3,230,480.00	\$439,120.00	\$0.00

Deficiencies By Priority



- 1 - Currently Critical (Immediate)
- 2 - Potentially Critical (Year 1)
- 3 - Necessary/Not Yet Critical (Years 2-5) - \$3,230,480.00
- 4 - Recommended (Years 6-10) - \$439,120.00
- 5 - Codes or Standards Compliance

Budget Estimate Total: \$3,669,600.00

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	80,000
Year Built:	1983
Last Renovation:	
Replacement Value:	\$15,790,400
Repair Cost:	\$3,217,280.00
Total FCI:	20.37 %
Total RSLI:	32.17 %
FCA Score:	79.63







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	ES -Elementary School	Gross Area:	80,000
Year Built:	1983	Last Renovation:	
Repair Cost:	\$3,217,280	Replacement Value:	\$15,790,400
FCI:	20.37 %	RSLI%:	32.17 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	66.00 %	0.00 %	\$0.00
A20 - Basement Construction	66.00 %	0.00 %	\$0.00
B10 - Superstructure	66.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	38.33 %	0.00 %	\$0.00
B30 - Roofing	13.41 %	0.00 %	\$0.00
C10 - Interior Construction	33.39 %	0.00 %	\$0.00
C30 - Interior Finishes	8.88 %	97.79 %	\$1,966,800.00
D20 - Plumbing	13.33 %	0.00 %	\$0.00
D30 - HVAC	25.38 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	110.00 %	\$439,120.00
D50 - Electrical	26.66 %	13.16 %	\$298,320.00
E10 - Equipment	19.32 %	0.00 %	\$0.00
E20 - Furnishings	0.00 %	110.00 %	\$513,040.00
Totals:	32.17 %	20.37 %	\$3,217,280.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). East Elevation - Feb 15, 2017



2). North Elevation - Feb 15, 2017



3). South Elevation - Feb 15, 2017



4). West Elevation - Feb 15, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

Campus Assessment Report - 1983 Building

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.79	S.F.	80,000	100	1983	2083		66.00 %	0.00 %	66			\$383,200
A1030	Slab on Grade	\$8.43	S.F.	80,000	100	1983	2083		66.00 %	0.00 %	66			\$674,400
A2010	Basement Excavation	\$1.90	S.F.	80,000	100	1983	2083		66.00 %	0.00 %	66			\$152,000
A2020	Basement Walls	\$13.07	S.F.	80,000	100	1983	2083		66.00 %	0.00 %	66			\$1,045,600
B1010	Floor Construction	\$1.64	S.F.	80,000	100	1983	2083		66.00 %	0.00 %	66			\$131,200
B1020	Roof Construction	\$15.76	S.F.	80,000	100	1983	2083		66.00 %	0.00 %	66			\$1,260,800
B2010	Exterior Walls	\$9.42	S.F.	80,000	100	1983	2083		66.00 %	0.00 %	66			\$753,600
B2020	Exterior Windows	\$9.39	S.F.	80,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$751,200
B2030	Exterior Doors	\$1.04	S.F.	80,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$83,200
B3010130	Preformed Metal Roofing	\$9.66	S.F.	80,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$772,800
B3020	Roof Openings	\$0.29	S.F.	80,000	25	1983	2008	2021	16.00 %	0.00 %	4			\$23,200
C1010	Partitions	\$10.80	S.F.	80,000	75	1983	2058		54.67 %	0.00 %	41			\$864,000
C1020	Interior Doors	\$2.53	S.F.	80,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$202,400
C1030	Fittings	\$9.74	S.F.	80,000	20	2000	2020		15.00 %	0.00 %	3			\$779,200
C3010	Wall Finishes	\$2.79	S.F.	80,000	10	2015	2025		80.00 %	0.00 %	8			\$223,200
C3020	Floor Finishes	\$11.38	S.F.	80,000	20	1983	2003		0.00 %	110.00 %	-14		\$1,001,440.00	\$910,400
C3030	Ceiling Finishes	\$10.97	S.F.	80,000	25	1983	2008		0.00 %	110.00 %	-9		\$965,360.00	\$877,600
D2010	Plumbing Fixtures	\$11.48	S.F.	80,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$918,400
D2020	Domestic Water Distribution	\$0.98	S.F.	80,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$78,400
D2030	Sanitary Waste	\$1.54	S.F.	80,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$123,200
D3020	Heat Generating Systems	\$5.08	S.F.	80,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$406,400
D3030	Cooling Generating Systems	\$5.27	S.F.	80,000	25	1983	2008	2021	16.00 %	0.00 %	4			\$421,600
D3040	Distribution Systems	\$6.14	S.F.	80,000	30	2001	2031		46.67 %	0.00 %	14			\$491,200
D3060	Controls & Instrumentation	\$1.94	S.F.	80,000	20	2000	2020		15.00 %	0.00 %	3			\$155,200
D4010	Sprinklers	\$4.32	S.F.	80,000	30			2016	0.00 %	110.00 %	-1		\$380,160.00	\$345,600
D4020	Standpipes	\$0.67	S.F.	80,000	30			2016	0.00 %	110.00 %	-1		\$58,960.00	\$53,600
D5010	Electrical Service/Distribution	\$1.69	S.F.	80,000	40	1983	2023		15.00 %	0.00 %	6			\$135,200
D5020	Branch Wiring	\$5.06	S.F.	80,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$404,800
D5020	Lighting	\$11.92	S.F.	80,000	30	1990	2020		10.00 %	0.00 %	3			\$953,600
D5030810	Security & Detection Systems	\$1.87	S.F.	80,000	15	2015	2030		86.67 %	0.00 %	13			\$149,600
D5030910	Fire Alarm Systems	\$3.39	S.F.	80,000	15	1983	1998		0.00 %	110.00 %	-19		\$298,320.00	\$271,200
D5030920	Data Communication	\$4.40	S.F.	80,000	15	2015	2030		86.67 %	0.00 %	13			\$352,000
E1020	Institutional Equipment	\$0.30	S.F.	80,000	20	2000	2020		15.00 %	0.00 %	3			\$24,000
E1090	Other Equipment	\$1.90	S.F.	80,000	20	1983	2003	2021	20.00 %	0.00 %	4			\$152,000
E2010	Fixed Furnishings	\$5.83	S.F.	80,000	20	1983	2003		0.00 %	110.00 %	-14		\$513,040.00	\$466,400
Total									32.17 %	20.37 %			\$3,217,280.00	\$15,790,400

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B2010 - Exterior Walls



Note:

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1983 Building

System: B3010130 - Preformed Metal Roofing



Note:

System: B3020 - Roof Openings



Note:


System: C1010 - Partitions



Note:


Campus Assessment Report - 1983 Building

System: C1020 - Interior Doors




Note:

System: C1030 - Fittings



Note:

System: C3010 - Wall Finishes



Note:

Campus Assessment Report - 1983 Building

System: C3020 - Floor Finishes



Note: Replace as needed. Entire system need to be upgraded.

System: C3030 - Ceiling Finishes



Note:

System: D2010 - Plumbing Fixtures



Note:

Campus Assessment Report - 1983 Building

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

System: D3020 - Heat Generating Systems



Note:

Campus Assessment Report - 1983 Building

System: D3030 - Cooling Generating Systems



Note: Cooling tower replaced around 2011

System: D3040 - Distribution Systems



Note:

System: D3060 - Controls & Instrumentation



Note:

Campus Assessment Report - 1983 Building

System: D5010 - Electrical Service/Distribution




Note:

System: D5020 - Branch Wiring



Note:


System: D5020 - Lighting



Note:


Campus Assessment Report - 1983 Building

System: D5030810 - Security & Detection Systems




Note:

System: D5030910 - Fire Alarm Systems



Note:

System: D5030920 - Data Communication



Note:

Campus Assessment Report - 1983 Building

System: E1020 - Institutional Equipment



Note:

System: E1090 - Other Equipment



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$3,217,280	\$0	\$0	\$2,298,223	\$5,613,750	\$0	\$177,579	\$0	\$311,017	\$0	\$0	\$11,617,850
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A20 - Basement Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2010 - Basement Excavation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A2020 - Basement Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$930,030	\$0	\$0	\$0	\$0	\$0	\$0	\$930,030
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$103,007	\$0	\$0	\$0	\$0	\$0	\$0	\$103,007
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$1,200,315	\$0	\$0	\$0	\$0	\$0	\$0	\$1,200,315
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$28,723	\$0	\$0	\$0	\$0	\$0	\$0	\$28,723
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$250,583	\$0	\$0	\$0	\$0	\$0	\$0	\$250,583
C1030 - Fittings	\$0	\$0	\$0	\$936,598	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$936,598
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 1983 Building

C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$311,017	\$0	\$0	\$311,017
C3020 - Floor Finishes	\$1,001,440	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,001,440
C3030 - Ceiling Finishes	\$965,360	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$965,360
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$1,137,034	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,137,034
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$97,064	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$97,064
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$152,529	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$152,529
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$0	\$0	\$0	\$0	\$503,147	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$503,147
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$521,966	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$521,966
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$186,550	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$186,550
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$380,160	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$380,160
D4020 - Standpipes	\$58,960	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$58,960
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$177,579	\$0	\$0	\$0	\$0	\$0	\$177,579
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$501,167	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$501,167
D5020 - Lighting	\$0	\$0	\$0	\$1,146,227	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$1,146,227
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030910 - Fire Alarm Systems	\$298,320	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$298,320
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$28,848	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$28,848
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$188,185	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$188,185
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$513,040	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$513,040

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$3,217,280.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$3,217,280.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
C3020	Floor Finishes	\$0.00	\$0.00	\$1,001,440.00	\$0.00	\$0.00	\$1,001,440.00
C3030	Ceiling Finishes	\$0.00	\$0.00	\$965,360.00	\$0.00	\$0.00	\$965,360.00
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$380,160.00	\$0.00	\$380,160.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$58,960.00	\$0.00	\$58,960.00
D5030910	Fire Alarm Systems	\$0.00	\$0.00	\$298,320.00	\$0.00	\$0.00	\$298,320.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$513,040.00	\$0.00	\$0.00	\$513,040.00
	Total:	\$0.00	\$0.00	\$2,778,160.00	\$439,120.00	\$0.00	\$3,217,280.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$3,217,280.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: C3020 - Floor Finishes



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 80,000.00
Unit of Measure: S.F.
Estimate: \$1,001,440.00
Assessor Name: Eduardo Lopez
Date Created: 01/12/2017

Notes: The original floor finishes are aged, failing and should be replaced.

System: C3030 - Ceiling Finishes



Location: Throughout the building
Distress: Failing
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 80,000.00
Unit of Measure: S.F.
Estimate: \$965,360.00
Assessor Name: Eduardo Lopez
Date Created: 01/12/2017

Notes: The original ceiling finishes are aged, failing and should be replaced.

System: D5030910 - Fire Alarm Systems



Location: Throughout the building
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 80,000.00
Unit of Measure: S.F.
Estimate: \$298,320.00
Assessor Name: Eduardo Lopez
Date Created: 01/12/2017

Notes: The original alarm system is operating but is aged. The system should be inspected and repaired or replaced to ensure that the life safety codes are preserved.

System: E2010 - Fixed Furnishings



Location: Throughout the building
Distress: Damaged
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 80,000.00
Unit of Measure: S.F.
Estimate: \$513,040.00
Assessor Name: Eduardo Lopez
Date Created: 01/12/2017

Notes: The building casework is aged and worn and should be replaced.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout the building
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 80,000.00
Unit of Measure: S.F.
Estimate: \$380,160.00
Assessor Name: Eduardo Lopez
Date Created: 12/12/2016

Notes: There is no sprinkler system.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout the building
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 80,000.00
Unit of Measure: S.F.
Estimate: \$58,960.00
Assessor Name: Eduardo Lopez
Date Created: 12/12/2016

Notes: There is no sprinkler system.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	80,000
Year Built:	1983
Last Renovation:	
Replacement Value:	\$3,100,800
Repair Cost:	\$452,320.00
Total FCI:	14.59 %
Total RSLI:	22.43 %
FCA Score:	85.41







Description:

The narrative for this site is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	ES -Elementary School	Gross Area:	80,000
Year Built:	1983	Last Renovation:	
Repair Cost:	\$452,320	Replacement Value:	\$3,100,800
FCI:	14.59 %	RSLI%:	22.43 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	15.18 %	21.94 %	\$452,320.00
G30 - Site Mechanical Utilities	32.00 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	45.43 %	0.00 %	\$0.00
Totals:	22.43 %	14.59 %	\$452,320.00

Photo Album

The photo album consists of the various cardinal directions of the building..

- 1). Aerial Image of Sycamore Lane Elementary School - Feb 27, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$3.81	S.F.	80,000	25	1983	2008		0.00 %	110.00 %	-9		\$335,280.00	\$304,800
G2020	Parking Lots	\$1.33	S.F.	80,000	25	1983	2008		0.00 %	110.00 %	-9		\$117,040.00	\$106,400
G2030	Pedestrian Paving	\$1.91	S.F.	80,000	30	1983	2013	2021	13.33 %	0.00 %	4			\$152,800
G2040105	Fence & Guardrails	\$1.23	S.F.	80,000	30	2000	2030		43.33 %	0.00 %	13			\$98,400
G2040950	Baseball Field	\$5.76	S.F.	80,000	20	1983	2003	2021	20.00 %	0.00 %	4			\$460,800
G2040950	Playing Field	\$4.54	S.F.	80,000	20	1983	2003	2021	20.00 %	0.00 %	4			\$363,200
G2040950	Softball Field	\$5.32	S.F.	80,000	20	1983	2003	2021	20.00 %	0.00 %	4			\$425,600
G2050	Landscaping	\$1.87	S.F.	80,000	15	1983	1998		0.00 %	0.00 %	-19			\$149,600
G3010	Water Supply	\$2.34	S.F.	80,000	50	1983	2033		32.00 %	0.00 %	16			\$187,200
G3020	Sanitary Sewer	\$1.45	S.F.	80,000	50	1983	2033		32.00 %	0.00 %	16			\$116,000
G3030	Storm Sewer	\$4.54	S.F.	80,000	50	1983	2033		32.00 %	0.00 %	16			\$363,200
G4010	Electrical Distribution	\$2.35	S.F.	80,000	50	1983	2033		32.00 %	0.00 %	16			\$188,000
G4020	Site Lighting	\$1.47	S.F.	80,000	30	2000	2030		43.33 %	0.00 %	13			\$117,600
G4030	Site Communications & Security	\$0.84	S.F.	80,000	15	2015	2030		86.67 %	0.00 %	13			\$67,200
Total									22.43 %	14.59 %			\$452,320.00	\$3,100,800

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: G2010 - Roadways



Note:

System: G2020 - Parking Lots



Note:

System: G2030 - Pedestrian Paving



Note:

Campus Assessment Report - Site

System: G2040105 - Fence & Guardrails



Note:

System: G2040950 - Baseball Field



Note:

System: G2040950 - Playing Field



Note:

Campus Assessment Report - Site

System: G2040950 - Softball Field




Note:

System: G2050 - Landscaping



Note:

System: G3010 - Water Supply



Note:

Campus Assessment Report - Site

System: G3020 - Sanitary Sewer



Note:

System: G3030 - Storm Sewer



Note:

System: G4010 - Electrical Distribution



Note:

Campus Assessment Report - Site

System: G4020 - Site Lighting



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$452,320	\$0	\$0	\$0	\$1,736,255	\$0	\$0	\$0	\$0	\$0	\$0	\$2,188,575
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$335,280	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$335,280
G2020 - Parking Lots	\$117,040	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$117,040
G2030 - Pedestrian Paving	\$0	\$0	\$0	\$0	\$189,176	\$0	\$0	\$0	\$0	\$0	\$0	\$189,176
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040105 - Fence & Guardrails	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040950 - Baseball Field	\$0	\$0	\$0	\$0	\$570,498	\$0	\$0	\$0	\$0	\$0	\$0	\$570,498
G2040950 - Playing Field	\$0	\$0	\$0	\$0	\$449,663	\$0	\$0	\$0	\$0	\$0	\$0	\$449,663
G2040950 - Softball Field	\$0	\$0	\$0	\$0	\$526,918	\$0	\$0	\$0	\$0	\$0	\$0	\$526,918
* G2050 - Landscaping	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3020 - Sanitary Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3030 - Storm Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

** Indicates non-renewable system*


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$452,320.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
G2010	Roadways	\$0.00	\$0.00	\$335,280.00	\$0.00	\$0.00	\$335,280.00
G2020	Parking Lots	\$0.00	\$0.00	\$117,040.00	\$0.00	\$0.00	\$117,040.00
	Total:	\$0.00	\$0.00	\$452,320.00	\$0.00	\$0.00	\$452,320.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: G2010 - Roadways



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 80,000.00
Unit of Measure: S.F.
Estimate: \$335,280.00
Assessor Name: Eduardo Lopez
Date Created: 01/12/2017

Notes: The asphalt roadways are aged, have many road cuts, significant cracking, and need re-surfacing.

System: G2020 - Parking Lots



Location: Site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 80,000.00
Unit of Measure: S.F.
Estimate: \$117,040.00
Assessor Name: Eduardo Lopez
Date Created: 01/12/2017

Notes: The asphalt parking lots are aged, have cuts and repairs, and should be re-surfaced and re striped.

NC School District/830 Scotland County/Elementary School

Wagram Elementary

Draft

Campus Assessment Report

March 7, 2017



Table of Contents

Campus Executive Summary	4
Campus Dashboard Summary	7
Campus Condition Summary	8
<u>1983 Main</u>	10
Executive Summary	10
Dashboard Summary	11
Condition Summary	12
Photo Album	13
Condition Detail	14
System Listing	15
System Notes	17
Renewal Schedule	28
Forecasted Sustainment Requirement	30
Deficiency Summary By System	31
Deficiency Summary By Priority	32
Deficiency By Priority Investment	33
Deficiency Summary By Category	34
Deficiency Details By Priority	35
<u>2011 Addition/Gym</u>	42
Executive Summary	42
Dashboard Summary	43
Condition Summary	44
Photo Album	45
Condition Detail	46
System Listing	47
System Notes	48
Renewal Schedule	57
Forecasted Sustainment Requirement	59
Deficiency Summary By System	60

Campus Assessment Report

Deficiency Summary By Priority	61
Deficiency By Priority Investment	62
Deficiency Summary By Category	63
Deficiency Details By Priority	64
Site	65
Executive Summary	65
Dashboard Summary	66
Condition Summary	67
Photo Album	68
Condition Detail	69
System Listing	70
System Notes	71
Renewal Schedule	76
Forecasted Sustainment Requirement	77
Deficiency Summary By System	78
Deficiency Summary By Priority	79
Deficiency By Priority Investment	80
Deficiency Summary By Category	81
Deficiency Details By Priority	82

Campus Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Gross Area (SF):	73,960
Year Built:	1983
Last Renovation:	
Replacement Value:	\$15,382,032
Repair Cost:	\$4,185,494.00
Total FCI:	27.21 %
Total RSLI:	50.79 %
FCA Score:	72.79



Description:

GENERAL:

Wagram Elementary is located at 24081 Main St. in Wagram, North Carolina. The 1 story, 73,960 square foot building was originally constructed in 1983 There have been 1 addition. In addition to the main building, the campus contains a 2011 classroom and gymnasium addition.

This report contains condition and adequacy data collected during the 2017 Facility Condition Assessment (FCA). Detailed condition and deficiency statements are contained in this report for the site and building elements.

A. SUBSTRUCTURE

The building rests on slab-on grade and is assumed to have standard cast-in-place concrete foundations. The building does not have a basement .

Campus Assessment Report - Wagram Elementary

B. SUPERSTRUCTURE

Floor construction is concrete. Roof construction is steel. The exterior envelope is composed of walls of brick veneer over CMU. Exterior windows are aluminum frame with operable panes. Exterior doors are hollow metal steel mostly with glazing. Roofing is typically low slope standing seam metal. Roof opening include roof hatch door. Most building entrances appear to comply with ADA requirements.

C. INTERIORS

Interior partitions are typically CMU. Interior doors are generally solid core wood with hollow steel frames and mostly with glazing. Interior fittings include the following items: white boards, graphics and identifying devices, toilet accessories, storage shelving, handrails, fabricated toilet partitions. The interior wall finishes are typically painted CMU. Floor finishes in common areas are typically vinyl composition tile. Floor finishes in assignable spaces is typically vinyl composition tile. Ceiling finishes in common areas are typically suspended acoustical tile. Ceiling finishes in assignable areas are typically suspended acoustical tile.

CONVEYING:

The building does not include conveying equipment. Conveying equipment includes no hydraulic elevators, and no wheelchair lifts.

D. SERVICES

PLUMBING:

Plumbing fixtures are typically non-low-flow water fixtures with manual control valves. Domestic water distribution is combination of copper and galvanized steel with electric hot water heating. Sanitary waste system is cast iron and plastic. Rain water drainage system is external with gutters.

HVAC:

Heating is provided by 1 electric boilers. Cooling is supplied by 1 air cooled chillers. The heating/cooling distribution system is a ductwork system utilizing air handling units. Fresh air is supplied by air handling units. Ceiling mounted exhaust fans are installed in bathrooms and other required areas. Controls and instrumentation are digital and are centrally controlled by an energy management system. This building does not have a locally controlled Building Automation System.

FIRE PROTECTION:

The building does not have a fire sprinkler system. The building does have additional fire suppression system in the kitchen. Standpipes are not included within fire stairs. Fire extinguishers and cabinets are distributed near fire exits and corridors.

ELECTRICAL:

The main electrical service is fed from a pad mounted transformer to the main switchboard/distribution panel located in the building. Lighting is lay-in, recessed and surface type, fluorescent and LED light fixtures. Branch circuit wiring is typically copper serving electrical switches and receptacles. Emergency and life safety egress lighting systems are installed and exit signs are present at exit doors and near stairways and are typically illuminated.

COMMUNICATIONS AND SECURITY:

The fire alarm system consists of audible/visual strobe annunciators in common spaces, balconies and interior corridors. The system is activated by manual pull stations and smoke detectors and the system is centrally monitored. The telephone and data systems are segregated and include dedicated equipment closets. This building does have a local area network (LAN). The building includes an internal security system that is actuated by the following items: contacts, infrared, optical or a combination of all devices. The building has controlled entry doors access provided by card readers; entry doors are secured with magnetic door locks. The security system has CCTV cameras and is not centrally monitored; this building has a public address and paging system separate from the telephone system.

OTHER ELECTRICAL SYSTEMS:

This building does not have a separately derived emergency power system.

E. EQUIPMENT & FURNISHINGS:

This building includes the following items and equipment: fixed food service, library equipment, athletic equipment, theater and stage, audio-visual, vehicle equipment, fixed casework, window treatment, floor grilles and mats, and multiple seating furnishings.

G.

SITE

Campus site features include paved driveways and parking lots, pedestrian pavement, flag pole, landscaping, play areas, and fencing. Site mechanical and electrical features include water, sewer, propane, natural gas, and site lighting.

Campus Assessment Report - Wagram Elementary

Attributes:

General Attributes:





Condition Assessor: Matt Mahaffey Assessment Date:
Suitability Assessor:

School Information:

HS Attendance Area:		LEA School No.:	
No. of Mobile Units:	0	No. of Bldgs.:	2
SF of Mobile Units:		Status:	
School Grades:	15	Site Acreage:	15

Campus Dashboard Summary

Gross Area:	73,960	Last Renovation:	
Year Built:	1983	Replacement Value:	\$15,382,032
Repair Cost:	\$4,185,494	RSLI%:	50.79 %
FCI:	27.21 %		



Campus Condition Summary

The Table below shows the RSLI and FCI for each major system shown at the UNIFORMAT II classification Level 2. Note that Systems with lower FCIs require less investment than systems with higher FCIs.


Current Investment Requirement and Condition by Unifomat Classification

UNIFORMAT Classification	RSLI%	FCI %	Current Repair
A10 - Foundations	75.46 %	0.00 %	\$0.00
B10 - Superstructure	75.46 %	0.00 %	\$0.00
B20 - Exterior Enclosure	50.03 %	38.24 %	\$550,408.00
B30 - Roofing	61.99 %	0.00 %	\$0.00
C10 - Interior Construction	44.46 %	38.71 %	\$647,349.00
C30 - Interior Finishes	42.85 %	31.77 %	\$578,413.00
D20 - Plumbing	27.04 %	72.82 %	\$739,982.00
D30 - HVAC	46.63 %	38.72 %	\$546,100.00
D40 - Fire Protection	0.00 %	110.00 %	\$397,017.00
D50 - Electrical	57.03 %	0.00 %	\$0.00
E10 - Equipment	49.16 %	0.00 %	\$0.00
E20 - Furnishings	23.66 %	72.82 %	\$308,056.00
G20 - Site Improvements	47.23 %	37.37 %	\$418,169.00
G30 - Site Mechanical Utilities	57.48 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	80.43 %	0.00 %	\$0.00
Totals:	50.79 %	27.21 %	\$4,185,494.00

Condition Deficiency Priority

Facility Name	Gross Area (S.F.)	FCI %	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance
1983 Main	48,960	41.44	\$0.00	\$0.00	\$3,370,308.00	\$262,817.00	\$0.00
2011 Addition/Gym	25,000	2.96	\$0.00	\$0.00	\$0.00	\$134,200.00	\$0.00
Site	73,960	20.11	\$0.00	\$0.00	\$418,169.00	\$0.00	\$0.00
Total:		27.21	\$0.00	\$0.00	\$3,788,477.00	\$397,017.00	\$0.00

Deficiencies By Priority



- 1 - Currently Critical (Immediate)
- 2 - Potentially Critical (Year 1)
- 3 - Necessary/Not Yet Critical (Years 2-5) - \$3,788,477.00
- 4 - Recommended (Years 6-10) - \$397,017.00
- 5 - Codes or Standards Compliance

Budget Estimate Total: \$4,185,494.00

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	48,960
Year Built:	1983
Last Renovation:	
Replacement Value:	\$8,766,778
Repair Cost:	\$3,633,125.00
Total FCI:	41.44 %
Total RSLI:	36.00 %
FCA Score:	58.56







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	ES -Elementary School	Gross Area:	48,960
Year Built:	1983	Last Renovation:	
Repair Cost:	\$3,633,125	Replacement Value:	\$8,766,778
FCI:	41.44 %	RSLI%:	36.00 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	66.00 %	0.00 %	\$0.00
B10 - Superstructure	66.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	31.34 %	57.77 %	\$550,408.00
B30 - Roofing	53.06 %	0.00 %	\$0.00
C10 - Interior Construction	25.60 %	58.48 %	\$647,349.00
C30 - Interior Finishes	29.34 %	47.99 %	\$578,413.00
D20 - Plumbing	0.00 %	110.00 %	\$739,982.00
D30 - HVAC	32.41 %	61.73 %	\$546,100.00
D40 - Fire Protection	0.00 %	110.00 %	\$262,817.00
D50 - Electrical	48.63 %	0.00 %	\$0.00
E10 - Equipment	40.00 %	0.00 %	\$0.00
E20 - Furnishings	0.00 %	110.00 %	\$308,056.00
Totals:	36.00 %	41.44 %	\$3,633,125.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). West Elevation - Jan 11, 2017



2). South Elevation - Jan 11, 2017



3). East Elevation - Jan 11, 2017



4). North Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

Campus Assessment Report - 1983 Main


The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.70	S.F.	48,960	100	1983	2083		66.00 %	0.00 %	66			\$230,112
A1030	Slab on Grade	\$8.26	S.F.	48,960	100	1983	2083		66.00 %	0.00 %	66			\$404,410
B1010	Floor Construction	\$1.61	S.F.	48,960	100	1983	2083		66.00 %	0.00 %	66			\$78,826
B1020	Roof Construction	\$15.44	S.F.	48,960	100	1983	2083		66.00 %	0.00 %	66			\$755,942
B2010	Exterior Walls	\$9.24	S.F.	48,960	100	1983	2083		66.00 %	0.00 %	66			\$452,390
B2020	Exterior Windows	\$9.20	S.F.	48,960	30	1983	2013		0.00 %	110.00 %	-4		\$495,475.00	\$450,432
B2030	Exterior Doors	\$1.02	S.F.	48,960	30	1983	2013		0.00 %	110.00 %	-4		\$54,933.00	\$49,939
B3010130	Preformed Metal Roofing	\$9.66	S.F.	48,960	30	2003	2033		53.33 %	0.00 %	16			\$472,954
B3020	Roof Openings	\$0.29	S.F.	48,960	25	2003	2028		44.00 %	0.00 %	11			\$14,198
C1010	Partitions	\$10.59	S.F.	48,960	75	1983	2058		54.67 %	0.00 %	41			\$518,486
C1020	Interior Doors	\$2.48	S.F.	48,960	30	1983	2013		0.00 %	110.00 %	-4		\$133,563.00	\$121,421
C1030	Fittings	\$9.54	S.F.	48,960	20	1983	2003		0.00 %	110.00 %	-14		\$513,786.00	\$467,078
C3010	Wall Finishes	\$2.73	S.F.	48,960	10	2011	2021		40.00 %	0.00 %	4			\$133,661
C3020	Floor Finishes	\$11.15	S.F.	48,960	20	2008	2028		55.00 %	0.00 %	11			\$545,904
C3030	Ceiling Finishes	\$10.74	S.F.	48,960	25	1983	2008		0.00 %	110.00 %	-9		\$578,413.00	\$525,830
D2010	Plumbing Fixtures	\$11.26	S.F.	48,960	30	1983	2013		0.00 %	110.00 %	-4		\$606,419.00	\$551,290
D2020	Domestic Water Distribution	\$0.96	S.F.	48,960	30	1983	2013		0.00 %	110.00 %	-4		\$51,702.00	\$47,002
D2030	Sanitary Waste	\$1.52	S.F.	48,960	30	1983	2013		0.00 %	110.00 %	-4		\$81,861.00	\$74,419
D3020	Heat Generating Systems	\$4.98	S.F.	48,960	30	1983	2013		0.00 %	110.00 %	-4		\$268,203.00	\$243,821
D3030	Cooling Generating Systems	\$5.16	S.F.	48,960	25	1983	2008		0.00 %	110.00 %	-9		\$277,897.00	\$252,634
D3040	Distribution Systems	\$6.02	S.F.	48,960	30	2010	2040		76.67 %	0.00 %	23			\$294,739
D3060	Controls & Instrumentation	\$1.91	S.F.	48,960	20	2010	2030		65.00 %	0.00 %	13			\$93,514
D4010	Sprinklers	\$4.22	S.F.	48,960	30			2016	0.00 %	110.00 %	-1		\$227,272.00	\$206,611
D4020	Standpipes	\$0.66	S.F.	48,960	30			2016	0.00 %	110.00 %	-1		\$35,545.00	\$32,314
D5010	Electrical Service/Distribution	\$1.65	S.F.	48,960	40	1983	2023		15.00 %	0.00 %	6			\$80,784
D5020	Branch Wiring	\$4.99	S.F.	48,960	30	1983	2013	2021	13.33 %	0.00 %	4			\$244,310
D5020	Lighting	\$11.64	S.F.	48,960	30	2008	2038		70.00 %	0.00 %	21			\$569,894
D5030810	Security & Detection Systems	\$1.83	S.F.	48,960	15	2009	2024		46.67 %	0.00 %	7			\$89,597
D5030910	Fire Alarm Systems	\$3.31	S.F.	48,960	15	2009	2024		46.67 %	0.00 %	7			\$162,058
D5030920	Data Communication	\$4.30	S.F.	48,960	15	2009	2024		46.67 %	0.00 %	7			\$210,528
D5090	Other Electrical Systems	\$0.12	S.F.	48,960	20	2009	2029		60.00 %	0.00 %	12			\$5,875
E1020	Institutional Equipment	\$0.30	S.F.	48,960	20	2005	2025		40.00 %	0.00 %	8			\$14,688
E1090	Other Equipment	\$1.86	S.F.	48,960	20	2005	2025		40.00 %	0.00 %	8			\$91,066
E2010	Fixed Furnishings	\$5.72	S.F.	48,960	20	1983	2003		0.00 %	110.00 %	-14		\$308,056.00	\$280,051
Total									36.00 %	41.44 %			\$3,633,125.00	\$8,766,778

System Notes


The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1020 - Roof Construction



Note:

System: B2010 - Exterior Walls



Note:


Campus Assessment Report - 1983 Main

System: B2020 - Exterior Windows



Note:

System: B2030 - Exterior Doors



Note:

Campus Assessment Report - 1983 Main

System: B3010130 - Preformed Metal Roofing






Note:

System: B3020 - Roof Openings



Note:

System: C1010 - Partitions



Note:

Campus Assessment Report - 1983 Main

System: C1020 - Interior Doors




Note:

System: C1030 - Fittings



Note:


System: C3010 - Wall Finishes



Note:



Campus Assessment Report - 1983 Main

System: C3020 - Floor Finishes



Note:

System: C3030 - Ceiling Finishes



Note:

Campus Assessment Report - 1983 Main

System: D2010 - Plumbing Fixtures



Note:

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

Campus Assessment Report - 1983 Main

System: D3020 - Heat Generating Systems



Note:

System: D3030 - Cooling Generating Systems



Note:

Campus Assessment Report - 1983 Main

System: D3040 - Distribution Systems



Note:

System: D3060 - Controls & Instrumentation



Note:


System: D5010 - Electrical Service/Distribution



Note:



Campus Assessment Report - 1983 Main

System: D5020 - Branch Wiring




Note:

System: D5020 - Lighting



Note:

System: D5030810 - Security & Detection Systems



Note:

Campus Assessment Report - 1983 Main

System: D5030910 - Fire Alarm Systems



Note:

System: D5030920 - Data Communication



Note:

System: D5090 - Other Electrical Systems



Note:

Campus Assessment Report - 1983 Main

System: E1020 - Institutional Equipment



Note:

System: E1090 - Other Equipment



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$3,633,125	\$0	\$0	\$0	\$467,951	\$0	\$106,106	\$625,268	\$147,362	\$0	\$0	\$4,979,811
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$495,475	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$495,475
B2030 - Exterior Doors	\$54,933	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$54,933
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3020 - Roof Openings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$133,563	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$133,563
C1030 - Fittings	\$513,786	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$513,786
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$165,480	\$0	\$0	\$0	\$0	\$0	\$0	\$165,480
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$578,413	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$578,413


Campus Assessment Report - 1983 Main

D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$606,419	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$606,419
D2020 - Domestic Water Distribution	\$51,702	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$51,702
D2030 - Sanitary Waste	\$81,861	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$81,861
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3020 - Heat Generating Systems	\$268,203	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$268,203
D3030 - Cooling Generating Systems	\$277,897	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$277,897
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$227,272	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$227,272
D4020 - Standpipes	\$35,545	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$35,545
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$106,106	\$0	\$0	\$0	\$0	\$0	\$106,106
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$302,470	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$302,470
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$121,211	\$0	\$0	\$0	\$0	\$121,211
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$219,241	\$0	\$0	\$0	\$0	\$219,241
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$284,815	\$0	\$0	\$0	\$0	\$284,815
D5090 - Other Electrical Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1020 - Institutional Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$20,467	\$0	\$0	\$0	\$20,467
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$126,895	\$0	\$0	\$0	\$126,895
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$308,056	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$308,056

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.



Deficiency Summary by System


Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Budget Estimate Total: \$3,633,125.00

Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$3,633,125.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
B2020	Exterior Windows	\$0.00	\$0.00	\$495,475.00	\$0.00	\$0.00	\$495,475.00
B2030	Exterior Doors	\$0.00	\$0.00	\$54,933.00	\$0.00	\$0.00	\$54,933.00
C1020	Interior Doors	\$0.00	\$0.00	\$133,563.00	\$0.00	\$0.00	\$133,563.00
C1030	Fittings	\$0.00	\$0.00	\$513,786.00	\$0.00	\$0.00	\$513,786.00
C3030	Ceiling Finishes	\$0.00	\$0.00	\$578,413.00	\$0.00	\$0.00	\$578,413.00
D2010	Plumbing Fixtures	\$0.00	\$0.00	\$606,419.00	\$0.00	\$0.00	\$606,419.00
D2020	Domestic Water Distribution	\$0.00	\$0.00	\$51,702.00	\$0.00	\$0.00	\$51,702.00
D2030	Sanitary Waste	\$0.00	\$0.00	\$81,861.00	\$0.00	\$0.00	\$81,861.00
D3020	Heat Generating Systems	\$0.00	\$0.00	\$268,203.00	\$0.00	\$0.00	\$268,203.00
D3030	Cooling Generating Systems	\$0.00	\$0.00	\$277,897.00	\$0.00	\$0.00	\$277,897.00
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$227,272.00	\$0.00	\$227,272.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$35,545.00	\$0.00	\$35,545.00
E2010	Fixed Furnishings	\$0.00	\$0.00	\$308,056.00	\$0.00	\$0.00	\$308,056.00
	Total:	\$0.00	\$0.00	\$3,370,308.00	\$262,817.00	\$0.00	\$3,633,125.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Budget Estimate Total: \$3,633,125.00

Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: B2020 - Exterior Windows



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 48,960.00
Unit of Measure: S.F.
Estimate: \$495,475.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The aluminum frame, operable, single pane windows are aged, not energy efficient, and should be replaced.


System: B2030 - Exterior Doors



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 48,960.00
Unit of Measure: S.F.
Estimate: \$54,933.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The original exterior doors are aged, rusted, and should be replaced.

System: C1020 - Interior Doors



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 48,960.00
Unit of Measure: S.F.
Estimate: \$133,563.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The interior doors are aged and should be replaced

System: C1030 - Fittings



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 48,960.00
Unit of Measure: S.F.
Estimate: \$513,786.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The original fittings are aged, rusted and should be replaced.

System: C3030 - Ceiling Finishes



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 48,960.00
Unit of Measure: S.F.
Estimate: \$578,413.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The ceiling tiles have been replaced as needed. However the grid shows signs of aging and most tiles are sagging or damaged and should be replaced.

System: D2010 - Plumbing Fixtures



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Energy
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 48,960.00
Unit of Measure: S.F.
Estimate: \$606,419.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: Plumbing fixtures are in operational conditions. However, they are aged and should be replaced with a low-flow water fixtures.

System: D2020 - Domestic Water Distribution



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 48,960.00
Unit of Measure: S.F.
Estimate: \$51,702.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The domestic water distribution system is aged and should be replaced.

System: D2030 - Sanitary Waste



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 48,960.00
Unit of Measure: S.F.
Estimate: \$81,861.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The sanitary waste system is aged, has reported periodic failures, and should be replaced.

System: D3020 - Heat Generating Systems



Location: Mechanical Room
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 48,960.00
Unit of Measure: S.F.
Estimate: \$268,203.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The electric boiler is operating properly and are in fair condition but; is aging, inefficient, becoming logistically unsupportable, and should be replaced with energy efficient model.

System: D3030 - Cooling Generating Systems



Location: Chiller yard
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 48,960.00
Unit of Measure: S.F.
Estimate: \$277,897.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: Chiller is aging and logistically unsupportable, and should be replaced with an energy efficient model.

System: E2010 - Fixed Furnishings



Location: Throughout
Distress: Beyond Service Life
Category: Deferred Maintenance / Appearance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 48,960.00
Unit of Measure: S.F.
Estimate: \$308,056.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The fixed furnishings are aged, in marginal condition, and should be replaced.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 48,960.00
Unit of Measure: S.F.
Estimate: \$227,272.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 48,960.00
Unit of Measure: S.F.
Estimate: \$35,545.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	25,000
Year Built:	2011
Last Renovation:	
Replacement Value:	\$4,535,500
Repair Cost:	\$134,200.00
Total FCI:	2.96 %
Total RSLI:	77.09 %
FCA Score:	97.04







Description:

The narrative for this building is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	ES -Elementary School	Gross Area:	25,000
Year Built:	2011	Last Renovation:	
Repair Cost:	\$134,200	Replacement Value:	\$4,535,500
FCI:	2.96 %	RSLI%:	77.09 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
A10 - Foundations	94.00 %	0.00 %	\$0.00
B10 - Superstructure	94.00 %	0.00 %	\$0.00
B20 - Exterior Enclosure	86.65 %	0.00 %	\$0.00
B30 - Roofing	80.00 %	0.00 %	\$0.00
C10 - Interior Construction	81.40 %	0.00 %	\$0.00
C30 - Interior Finishes	69.29 %	0.00 %	\$0.00
D20 - Plumbing	80.00 %	0.00 %	\$0.00
D30 - HVAC	70.56 %	0.00 %	\$0.00
D40 - Fire Protection	0.00 %	110.00 %	\$134,200.00
D50 - Electrical	73.47 %	0.00 %	\$0.00
E10 - Equipment	70.00 %	0.00 %	\$0.00
E20 - Furnishings	70.00 %	0.00 %	\$0.00
Totals:	77.09 %	2.96 %	\$134,200.00

Photo Album

The photo album consists of the various cardinal directions of the building..

1). West Elevation - Jan 11, 2017



2). North Elevation - Jan 11, 2017



3). South Elevation - Jan 11, 2017



4). East Elevation - Jan 11, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
A1010	Standard Foundations	\$4.70	S.F.	25,000	100	2011	2111		94.00 %	0.00 %	94			\$117,500
A1030	Slab on Grade	\$8.26	S.F.	25,000	100	2011	2111		94.00 %	0.00 %	94			\$206,500
B1010	Floor Construction	\$1.61	S.F.	25,000	100	2011	2111		94.00 %	0.00 %	94			\$40,250
B1020	Roof Construction	\$15.44	S.F.	25,000	100	2011	2111		94.00 %	0.00 %	94			\$386,000
B2010	Exterior Walls	\$9.24	S.F.	25,000	100	2011	2111		94.00 %	0.00 %	94			\$231,000
B2020	Exterior Windows	\$9.20	S.F.	25,000	30	2011	2041		80.00 %	0.00 %	24			\$230,000
B2030	Exterior Doors	\$1.02	S.F.	25,000	30	2011	2041		80.00 %	0.00 %	24			\$25,500
B3010130	Preformed Metal Roofing	\$9.66	S.F.	25,000	30	2011	2041		80.00 %	0.00 %	24			\$241,500
C1010	Partitions	\$10.59	S.F.	25,000	75	2011	2086		92.00 %	0.00 %	69			\$264,750
C1020	Interior Doors	\$2.48	S.F.	25,000	30	2011	2041		80.00 %	0.00 %	24			\$62,000
C1030	Fittings	\$9.54	S.F.	25,000	20	2011	2031		70.00 %	0.00 %	14			\$238,500
C3010	Wall Finishes	\$2.73	S.F.	25,000	10	2011	2021		40.00 %	0.00 %	4			\$68,250
C3020	Floor Finishes	\$11.15	S.F.	25,000	20	2011	2031		70.00 %	0.00 %	14			\$278,750
C3030	Ceiling Finishes	\$10.74	S.F.	25,000	25	2011	2036		76.00 %	0.00 %	19			\$268,500
D2010	Plumbing Fixtures	\$11.26	S.F.	25,000	30	2011	2041		80.00 %	0.00 %	24			\$281,500
D2020	Domestic Water Distribution	\$0.96	S.F.	25,000	30	2011	2041		80.00 %	0.00 %	24			\$24,000
D2030	Sanitary Waste	\$1.52	S.F.	25,000	30	2011	2041		80.00 %	0.00 %	24			\$38,000
D3030	Cooling Generating Systems	\$5.16	S.F.	25,000	25	2011	2036		76.00 %	0.00 %	19			\$129,000
D3040	Distribution Systems	\$6.02	S.F.	25,000	30	2011	2041		80.00 %	0.00 %	24			\$150,500
D3050	Terminal & Package Units	\$7.93	S.F.	25,000	15	2011	2026		60.00 %	0.00 %	9			\$198,250
D3060	Controls & Instrumentation	\$1.91	S.F.	25,000	20	2011	2031		70.00 %	0.00 %	14			\$47,750
D4010	Sprinklers	\$4.22	S.F.	25,000	30			2016	0.00 %	110.00 %	-1		\$116,050.00	\$105,500
D4020	Standpipes	\$0.66	S.F.	25,000	30			2016	0.00 %	110.00 %	-1		\$18,150.00	\$16,500
D5010	Electrical Service/Distribution	\$1.65	S.F.	25,000	40	2011	2051		85.00 %	0.00 %	34			\$41,250
D5020	Branch Wiring	\$4.99	S.F.	25,000	30	2011	2041		80.00 %	0.00 %	24			\$124,750
D5020	Lighting	\$11.64	S.F.	25,000	30	2011	2041		80.00 %	0.00 %	24			\$291,000
D5030810	Security & Detection Systems	\$1.83	S.F.	25,000	15	2011	2026		60.00 %	0.00 %	9			\$45,750
D5030910	Fire Alarm Systems	\$3.31	S.F.	25,000	15	2011	2026		60.00 %	0.00 %	9			\$82,750
D5030920	Data Communication	\$4.30	S.F.	25,000	15	2011	2026		60.00 %	0.00 %	9			\$107,500
D5090	Other Electrical Systems	\$0.12	S.F.	25,000	20	2011	2031		70.00 %	0.00 %	14			\$3,000
E1090	Other Equipment	\$1.86	S.F.	25,000	20	2011	2031		70.00 %	0.00 %	14			\$46,500
E2010	Fixed Furnishings	\$5.72	S.F.	25,000	20	2011	2031		70.00 %	0.00 %	14			\$143,000
Total									77.09 %	2.96 %			\$134,200.00	\$4,535,500

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: B1020 - Roof Construction



Note:

System: B2010 - Exterior Walls



Note:


System: B2020 - Exterior Windows



Note:

Campus Assessment Report - 2011 Addition/Gym

System: B2030 - Exterior Doors



Note:

System: B3010130 - Preformed Metal Roofing



Note:



System: C1010 - Partitions



Note:


Campus Assessment Report - 2011 Addition/Gym

System: C1020 - Interior Doors



Note:

System: C1030 - Fittings



Note:


System: C3010 - Wall Finishes



Note:



Campus Assessment Report - 2011 Addition/Gym

System: C3020 - Floor Finishes



Note:

System: C3030 - Ceiling Finishes



Note:


System: D2010 - Plumbing Fixtures



Note:

Campus Assessment Report - 2011 Addition/Gym

System: D2020 - Domestic Water Distribution



Note:

System: D2030 - Sanitary Waste



Note:

System: D3030 - Cooling Generating Systems



Note:

Campus Assessment Report - 2011 Addition/Gym

System: D3040 - Distribution Systems



Note:

System: D3050 - Terminal & Package Units



Note:

System: D3060 - Controls & Instrumentation



Note:

Campus Assessment Report - 2011 Addition/Gym

System: D5010 - Electrical Service/Distribution




Note:

System: D5020 - Branch Wiring



Note:

System: D5020 - Lighting



Note:

Campus Assessment Report - 2011 Addition/Gym

System: D5030810 - Security & Detection Systems




Note:

System: D5030910 - Fire Alarm Systems



Note:

System: D5030920 - Data Communication



Note:

Campus Assessment Report - 2011 Addition/Gym

System: D5090 - Other Electrical Systems




Note:

System: E1090 - Other Equipment



Note:

System: E2010 - Fixed Furnishings



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.

Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$134,200	\$0	\$0	\$0	\$84,498	\$0	\$0	\$0	\$0	\$623,258	\$0	\$841,955
* A - Substructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A10 - Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1010 - Standard Foundations	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* A1030 - Slab on Grade	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B - Shell	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B10 - Superstructure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1010 - Floor Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B1020 - Roof Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B20 - Exterior Enclosure	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* B2010 - Exterior Walls	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2020 - Exterior Windows	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B2030 - Exterior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B30 - Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010 - Roof Coverings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
B3010130 - Preformed Metal Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C - Interiors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C10 - Interior Construction	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* C1010 - Partitions	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1020 - Interior Doors	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C1030 - Fittings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C30 - Interior Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3010 - Wall Finishes	\$0	\$0	\$0	\$0	\$84,498	\$0	\$0	\$0	\$0	\$0	\$0	\$84,498
C3020 - Floor Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
C3030 - Ceiling Finishes	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D - Services	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0


Campus Assessment Report - 2011 Addition/Gym

D20 - Plumbing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2010 - Plumbing Fixtures	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2020 - Domestic Water Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D2030 - Sanitary Waste	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D30 - HVAC	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3030 - Cooling Generating Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3040 - Distribution Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D3050 - Terminal & Package Units	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$284,538	\$0	\$284,538
D3060 - Controls & Instrumentation	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D40 - Fire Protection	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D4010 - Sprinklers	\$116,050	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$116,050
D4020 - Standpipes	\$18,150	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$18,150
D50 - Electrical	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5010 - Electrical Service/Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Branch Wiring	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5020 - Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030 - Communications and Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
D5030810 - Security & Detection Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$65,663	\$0	\$65,663
D5030910 - Fire Alarm Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$118,767	\$0	\$118,767
D5030920 - Data Communication	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$154,289	\$0	\$154,289
D5090 - Other Electrical Systems	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E - Equipment & Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E10 - Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E1090 - Other Equipment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E20 - Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
E2010 - Fixed Furnishings	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0

* Indicates non-renewable system


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$134,200.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
D4010	Sprinklers	\$0.00	\$0.00	\$0.00	\$116,050.00	\$0.00	\$116,050.00
D4020	Standpipes	\$0.00	\$0.00	\$0.00	\$18,150.00	\$0.00	\$18,150.00
	Total:	\$0.00	\$0.00	\$0.00	\$134,200.00	\$0.00	\$134,200.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 4 - Recommended (Years 6-10):

System: D4010 - Sprinklers

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 25,000.00
Unit of Measure: S.F.
Estimate: \$116,050.00
Assessor Name: Terence Davis
Date Created: 12/21/2016

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

System: D4020 - Standpipes

This deficiency has no image.

Location: Throughout
Distress: Missing
Category: Building Code Compliance
Priority: 4 - Recommended (Years 6-10)
Correction: Renew System
Qty: 25,000.00
Unit of Measure: S.F.
Estimate: \$18,150.00
Assessor Name: Terence Davis
Date Created: 12/21/2016

Notes: A Sprinkler system is missing and is recommended to be provided to comply with current codes.

Executive Summary

Building condition is evaluated based on the functional systems and elements of a building and organized according to the UNIFORMAT II Elemental Classification. The grouping of these systems and elements and applying a current replacement value to them develops a representative building cost model. Cost Models are developed for similar building types and functions. Systems and their elements are evaluated based on their current replacement values, life cycles, installation dates and next renewal dates. Systems and their elements that are within their useful lives are further evaluated to identify current deficient conditions that may have a significant impact on a system's or element's remaining service life, and to determine if they are beyond their predicted expected life. The system's or element's current replacement value is based on RS Means Commercial Cost Data.

Following are the cost model's system details for this facility. The **Replacement Value** is the amount needed to replace the property of the same present scope. The **Repair Cost** (the sum of the cost to repair/replace the Deficiencies) represents the budgeted contractor-installed costs plus owner's soft costs for the repair, replacement or renewal for a component or system level deficiency. It excludes contributing costs for other components or systems that might also be associated with the corrective actions due to packaging of the work. **Facility Condition Index (FCI)** is an industry-standard measurement of facility condition calculated as the ratio of the costs to correct a facility's deficiencies (Condition Needs) to the facility's Current Replacement Value. It ranges from 0% (new) to 100% (very poor - beyond service life). The **Remaining Service Life Index (RSLI)** is calculated as the sum of a renewable system's **Remaining Service Life (RSL)** divided by the sum of a system's Replacement Value (both values exclude soft-cost to simplify calculation updates) expressed as a percentage ranging from 100% (new) to 0% (expired). The relationship between the key metrics FCI and RSLI is an important indicator, at either the facility, building, system, or component levels, of the condition trend and the imminent need for capital renewal. These indices exist in an inverse relationship wherein the FCI increases when systems reach their expected life-cycle age, whereas the RSLI decreases annually indicating the relative time remaining before reaching the life-cycle expiration age. For example, a facility or a system with a high RSLI and a low FCI indicates it is in the early portion of its useful life. However, a low RSLI indicates that expiration dates are approaching at which point the FCI would increase. The term **FCA Score** is the inverse of Total FCI and calculated as 100-Total FCI (without the %) where 100 is best and 0 is worst condition.

Function:	ES -Elementary School
Gross Area (SF):	73,960
Year Built:	1983
Last Renovation:	2009
Replacement Value:	\$2,079,754
Repair Cost:	\$418,169.00
Total FCI:	20.11 %
Total RSLI:	55.77 %
FCA Score:	79.89







Description:

The narrative for this site is included in the Executive Summary Description at the front of this report.

Attributes: This asset has no attributes.

Dashboard Summary

Function:	ES -Elementary School	Gross Area:	73,960
Year Built:	1983	Last Renovation:	2009
Repair Cost:	\$418,169	Replacement Value:	\$2,079,754
FCI:	20.11 %	RSLI%:	55.77 %



Condition Summary

The Table below shows the RSLI and FCI for each major building system shown at the UNIFORMAT classification Level II. Note that Systems with lower FCIs require less investment than systems with higher FCIs.

UNIFORMAT Classification	RSLI %	FCI %	Current Repair Cost
G20 - Site Improvements	47.23 %	37.37 %	\$418,169.00
G30 - Site Mechanical Utilities	57.48 %	0.00 %	\$0.00
G40 - Site Electrical Utilities	80.43 %	0.00 %	\$0.00
Totals:	55.77 %	20.11 %	\$418,169.00

Photo Album

The photo album consists of the various cardinal directions of the building..

- 1). Aerial Image of Wagram Elementary School - Feb 24, 2017



Condition Detail

This section of the report contains results of the Facility Condition Assessment. The building is separated into system components based on UNIFORMAT II. The columns in the System Listing table represent the following:

1. System Code: A code that identifies the system.
2. System Description: A brief description of a system present in the building.
3. Unit Price \$: The unit price of the system.
4. UoM: The unit of measure of the system.
5. Qty: The quantity for the system
6. Life: Building Owners and Managers Association (BOMA) recommended system design life.
7. Year Installed: The date of system installation.
8. Calc Next Renewal Year: The date of system expiration based on the life, NR stands for non renewable.
9. Next Renewal Year: The suggested system expiration date by the assessor based on visual inspection.
10. RSLI: The Remaining Service Life Index of the system.
11. FCI: The Facility Condition Index of the system.
12. RSL: Remaining Service Life in years.
13. eCR: eCOMET Condition Rating (not used in this assessment).
14. Deficiency \$: The financial investment to repair/replace system to address deficiency.
15. Replacement Value \$: The replacement cost of the system.

System Listing

The System Listing table below lists each of the systems organized by their UNIFORMAT II classification. The assessment team was tasked with recording the most recent replacement year of each system, determining the remaining service life based on the theoretical life, and evaluating the condition to confirm the forecast next replacement year. The system listing is the basis for all data contained in the Building Assessment Report.

System Code	System Description	Unit Price \$	UoM	Qty	Life	Year Installed	Calc Next Renewal Year	Next Renewal Year	RSLI%	FCI%	RSL	eCR	Deficiency \$	Replacement Value \$
G2010	Roadways	\$3.81	S.F.	73,960	25	1983	2008		0.00 %	110.00 %	-9		\$309,966.00	\$281,788
G2020	Parking Lots	\$1.33	S.F.	73,960	25	1983	2008		0.00 %	110.00 %	-9		\$108,203.00	\$98,367
G2030	Pedestrian Paving	\$1.91	S.F.	73,960	30	2011	2041		80.00 %	0.00 %	24			\$141,264
G2040105	Fence & Guardrails	\$1.23	S.F.	73,960	30	2011	2041		80.00 %	0.00 %	24			\$90,971
G2040950	Canopies	\$0.44	S.F.	73,960	25	2011	2036		76.00 %	0.00 %	19			\$32,542
G2040950	Playing Field	\$4.54	S.F.	73,960	20	2011	2031		70.00 %	0.00 %	14			\$335,778
G2050	Landscaping	\$1.87	S.F.	73,960	15	2011	2026		60.00 %	0.00 %	9			\$138,305
G3010	Water Supply	\$2.34	S.F.	73,960	50	2011	2061		88.00 %	0.00 %	44			\$173,066
G3020	Sanitary Sewer	\$1.45	S.F.	73,960	50	2011	2061		88.00 %	0.00 %	44			\$107,242
G3030	Storm Sewer	\$4.54	S.F.	73,960	50	1983	2033		32.00 %	0.00 %	16			\$335,778
G4010	Electrical Distribution	\$2.35	S.F.	73,960	50	2011	2061		88.00 %	0.00 %	44			\$173,806
G4020	Site Lighting	\$1.47	S.F.	73,960	30	2011	2041		80.00 %	0.00 %	24			\$108,721
G4030	Site Communications & Security	\$0.84	S.F.	73,960	15	2011	2026		60.00 %	0.00 %	9			\$62,126
Total									55.77 %	20.11 %			\$418,169.00	\$2,079,754

System Notes

The facility description in the executive summary contains an overview of each system. The photos of each system and any associated notes listed below provide additional information on select systems found within the facility:

System: G2010 - Roadways



Note:

System: G2020 - Parking Lots



Note:

System: G2030 - Pedestrian Paving



Note:

Campus Assessment Report - Site

System: G2040105 - Fence & Guardrails



Note:

System: G2040950 - Canopies



Note:

System: G2040950 - Playing Field



Note:

Campus Assessment Report - Site

System: G2050 - Landscaping



Note:

System: G3010 - Water Supply



Note:

System: G3020 - Sanitary Sewer



Note:

Campus Assessment Report - Site

System: G3030 - Storm Sewer



Note:

System: G4010 - Electrical Distribution



Note:

System: G4020 - Site Lighting



Note:

Campus Assessment Report - Site

System: G4030 - Site Communications & Security



Note:

Renewal Schedule

eCOMET forecasts future Capital Renewal projects for expiring systems based on the Calculated Next Renewal year found in the system listing. There is a 3% yearly inflation factor applied to the system costs expiring in the future. The table below reflects Capital Renewal projects over the next 10 years. Note: Blank cells (or \$0) indicate no systems are scheduled for renewal in that year.


Inflation Rate: 3%

System	Current Deficiencies	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	Total
Total:	\$418,169	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$89,167	\$0	\$507,336
G - Building Sitework	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G20 - Site Improvements	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2010 - Roadways	\$309,966	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$309,966
G2020 - Parking Lots	\$108,203	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$108,203
G2030 - Pedestrian Paving	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040 - Site Development	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040105 - Fence & Guardrails	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040950 - Canopies	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G2040950 - Playing Field	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
* G2050 - Landscaping	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G30 - Site Mechanical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3010 - Water Supply	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3020 - Sanitary Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G3030 - Storm Sewer	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G40 - Site Electrical Utilities	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4010 - Electrical Distribution	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4020 - Site Lighting	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
G4030 - Site Communications & Security	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$89,167	\$0	\$89,167

** Indicates non-renewable system*


Forecasted Capital Renewal Requirement

The following chart shows the current building deficiencies and forecasting capital renewal or sustainment requirements over the next ten years.




Deficiency Summary by System

Current deficiencies included assemblies that have reached or exceeded their design life or components of the assemblies that are in need of repair. Assemblies that have reached their design life are identified as current deficiencies and assigned the distress 'Beyond Useful Life'. The following chart lists all current deficiencies associated with this facility.



Deficiency Summary by Priority

The following chart shows the total repair costs broken down by priority. Assessors assigned deficiencies within eCOMET to one of the following priority categories:



Budget Estimate Total: \$418,169.00


Deficiency By Priority Investment Table

The table below shows the current investment cost grouped by deficiency priority and building system.

System Code	System Description	1 - Currently Critical (Immediate)	2 - Potentially Critical (Year 1)	3 - Necessary/Not Yet Critical (Years 2-5)	4 - Recommended (Years 6-10)	5 - Codes or Standards Compliance	Total
G2010	Roadways	\$0.00	\$0.00	\$309,966.00	\$0.00	\$0.00	\$309,966.00
G2020	Parking Lots	\$0.00	\$0.00	\$108,203.00	\$0.00	\$0.00	\$108,203.00
	Total:	\$0.00	\$0.00	\$418,169.00	\$0.00	\$0.00	\$418,169.00

Deficiency Summary by Category

The following chart shows the total repair costs broken down by deficiency categories. Assessors assigned deficiencies to one of the following categories:



Deficiency Details by Priority

The deficiency detail notes listed below provide additional information on identified deficiencies found within the facility.

Priority 3 - Necessary/Not Yet Critical (Years 2-5):

System: G2010 - Roadways



Location: Entire site
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 73,960.00
Unit of Measure: S.F.
Estimate: \$309,966.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The asphaltic roadway is aged, has many road cuts and repairs, and should be re-surfaced.

System: G2020 - Parking Lots



Location: North and East sides
Distress: Beyond Service Life
Category: Deferred Maintenance
Priority: 3 - Necessary/Not Yet Critical (Years 2-5)
Correction: Renew System
Qty: 73,960.00
Unit of Measure: S.F.
Estimate: \$108,203.00
Assessor Name: Terence Davis
Date Created: 01/11/2017

Notes: The majority of the parking lot is aged, has many repairs and potholes, and should be re-surfaced.