

Educational Suitability Reports by County by Grade

Suitability Report - Full

Project #: 8272	County: Anson	Site #: 370018000042
Project: Assessments 2016	Region: 40	Site: ANSONVILLE ELEMENTA
Grade Config: PK-06	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Excel	2.00	2.00	100.00
Exterior Environment	Excel	1.50	1.50	100.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Good	9.80	12.25	80.00
Location	Excel	3.68	3.68	100.00
Storage/Fixed Equip	Excel	3.68	3.68	100.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Excel	1.04	1.04	100.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Excel	0.31	0.31	100.00
ECE				
Environment	Excel	0.50	0.50	100.00
Size	Excel	1.25	1.25	100.00
Location	Excel	0.37	0.37	100.00
Storage/Fixed Equip	Excel	0.37	0.37	100.00
Self-Contained Special Ed				
Environment	Excel	0.48	0.48	100.00
Size	Excel	1.20	1.20	100.00
Location	Excel	0.36	0.36	100.00
Storage/Fixed Equip	Excel	0.36	0.36	100.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Excel	1.80	1.80	100.00
Location	Excel	0.54	0.54	100.00
Storage/Fixed Equip	Excel	0.54	0.54	100.00
Science				
Environment	Good	0.40	0.50	80.00
Size	Good	1.00	1.25	80.00
Location	Excel	0.38	0.38	100.00
Storage/Fixed Equip	Good	0.30	0.38	80.00
Music				
Environment	Good	0.59	0.74	80.00

Project #: 8272

County: Anson

Site #: 370018000042

Project: Assessments 2016

Region: 40

Site: ANSONVILLE ELEMENTA

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	1.85	1.85	100.00
Location	Excel	0.56	0.56	100.00
Storage/Fixed Equip	Excel	0.56	0.56	100.00
Art				
Environment	Good	0.37	0.47	80.00
Size	Excel	1.17	1.17	100.00
Location	Excel	0.35	0.35	100.00
Storage/Fixed Equip	Excel	0.35	0.35	100.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Good	0.68	0.85	80.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Poor	0.96	1.92	50.00
Size	Fair	3.12	4.80	65.00
Location	Good	1.15	1.44	80.00
Storage/Fixed Equip	Poor	0.72	1.44	50.00
Performing Arts				
Environment	Poor	0.30	0.60	50.00
Size	Fair	0.98	1.51	65.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Poor	0.23	0.45	50.00
Media Center				
Environment	Excel	0.97	0.97	100.00
Size	Good	1.95	2.44	80.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Excel	0.73	0.73	100.00
Restrooms (Student)	Excel	0.89	0.89	100.00
Administration	Excel	2.56	2.56	100.00
Counseling	Excel	0.29	0.29	100.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Excel	1.27	1.27	100.00
Cafeteria	Good	4.00	5.00	80.00
Food Service and Prep	Excel	6.20	6.20	100.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Excel	2.00	2.00	100.00
Pedestrian Traffic	Excel	0.97	0.97	100.00
Parking	Excel	0.81	0.81	100.00
Play Areas	Excel	2.34	2.34	100.00
Safety and Security				
Fencing	Excel	0.75	0.75	100.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Good	0.40	0.50	80.00

Project #: 8272

County: Anson

Site #: 370018000042

Project: Assessments 2016

Region: 40

Site: ANSONVILLE ELEMENTA

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		86.28	100.00	86.28

Comments

Suitability - ES

Ansonville Elementary School is located in North Wadesboro, NC and serves students in grades K through 6. It is one of the newer schools in the county, having been built in 1999. The school has a patio courtyard area that facilitates outdoor learning.

Suitability - ES->Learning Environment-->Learning Style Variety

There are flexible use spaces within the school that allow for differentiated instruction.

Suitability - ES->Learning Environment-->Interior Environment

The school's interior is very attractive and well-lit.

Suitability - ES->Learning Environment-->Exterior Environment

There are attractive outdoor learning spaces at the school that are frequently used by teachers.

Suitability - ES->ECE

There are no early childhood education (PK) classes at the school, but the spaces are there and meet all suitability standards.

Suitability - ES->Self-Contained Special Ed

This space meets all the suitability standards; however, currently the program does not exist at the school and the space is used by other itinerant resource personnel.

Suitability - ES->Music

The school has a music room that meets the suitability standards; however, there is no music teacher at the school, and so part of the space is used for 6th grade band by an itinerant teacher.

Suitability - ES->Art

The designated space for art meets the majority of the suitability standards; however, it is not being used because there is no art teacher at the school.

Suitability - ES->Computer Labs

There are two computer labs, but neither is in use (both vacant).

Suitability - ES->P.E.-->Environment

Acoustics in the gym are unacceptable and sound echoes throughout the space. It does not have sufficient air circulation.

Suitability - ES->P.E.-->Size

The space is under the size standards.

Suitability - ES->P.E.-->Storage/Fixed Equip

There is a space for chair storage, but no other dedicated space for storage.

Suitability - ES->Performing Arts-->Environment

The space is located in the gym but has an insufficient sound system, and no curtains. There is no designated storage space. The acoustics are inadequate.

Suitability - ES->Performing Arts-->Size

The space does not meet the size requirement.

Suitability - ES->Performing Arts-->Storage/Fixed Equip

There is one closet designated for chairs but little additional storage.

Suitability - ES->Clinic

Only sufficient space for one cot, and overall square footage is slightly below the size standards.

Project #: 8272

County: Anson

Site #: 370018000042

Project: Assessments 2016

Region: 40

Site: ANSONVILLE ELEMENTA

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Cafeteria Cafeteria is slightly below the size standards.				
Suitability - ES->Outside-->Play Areas Early childhood (PK) playground is adjacent to the classrooms and completed fenced in. Other primary classes (K-2) have a separate playground area and equipment from students in the upper grades.				
Suitability - ES->Safety and Security-->Signage & Way Finding With the exception of the main entrance and main office there is no clearly visible way-finding signage in the building.				
Suitability - ES->Safety and Security-->Ease of Supervision Much of the ease of supervision is dependent upon functioning security cameras throughout the building; however, many of the cameras were inoperable during the visit and school administrators reported that this had been the case for some time.				
Suitability - ES->Safety and Security-->Controlled Entrances The school has a security vestibule and is in the direct line of sight of the main office.				

Suitability Report - Full

Project #: 8272	County: Anson	Site #: 37001800049
Project: Assessments 2016	Region: 40	Site: LILESVILLE ELEMENTAR
Grade Config: PK-06	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Excel	12.25	12.25	100.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Good	2.94	3.68	80.00
Kindergarten				
Environment	Good	0.33	0.42	80.00
Size	Excel	1.04	1.04	100.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Good	0.25	0.31	80.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	Good	0.38	0.48	80.00
Size	Excel	1.20	1.20	100.00
Location	Good	0.29	0.36	80.00
Storage/Fixed Equip	Fair	0.23	0.36	65.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Good	1.44	1.80	80.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Fair	0.48	0.74	65.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	1.85	1.85	100.00
Location	Fair	0.36	0.56	65.00
Storage/Fixed Equip	Fair	0.36	0.56	65.00
Art				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Excel	0.85	0.85	100.00
Location	Excel	0.26	0.26	100.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Fair	1.25	1.92	65.00
Size	Excel	4.80	4.80	100.00
Location	Good	1.15	1.44	80.00
Storage/Fixed Equip	Good	1.15	1.44	80.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Good	1.95	2.44	80.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Excel	0.73	0.73	100.00
Restrooms (Student)	Fair	0.58	0.89	65.00
Administration	Good	2.05	2.56	80.00
Counseling	Good	0.23	0.29	80.00
Clinic	Good	0.47	0.58	80.00
Staff Lounge-WkRm	Excel	1.27	1.27	100.00
Cafeteria	Good	4.00	5.00	80.00
Food Service and Prep	Excel	6.20	6.20	100.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Excel	0.97	0.97	100.00
Parking	Poor	0.41	0.81	50.00
Play Areas	Excel	2.34	2.34	100.00
Safety and Security				
Fencing	Good	0.60	0.75	80.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Excel	0.50	0.50	100.00

Project #: 8272

County: Anson

Site #: 370018000049

Project: Assessments 2016

Region: 40

Site: LILESVILLE ELEMENTAR

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		77.88	89.64	86.88

Comments

Suitability - ES

Lilesville Elementary School is a K-6 grade facility built in the 1990s. The school has two classrooms to serve special education students. The school does not have any portable classrooms. Large classrooms allow for flexible configurations with adequate storage space.

Suitability - ES->Learning Environment-->Interior Environment

Roof leaks on occasion.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Some classroom materials are stored in the back of the cafeteria.

Suitability - ES->Kindergarten-->Storage/Fixed Equip

Some classroom materials are stored in the back of the cafeteria. Has built-in storage and movable storage.

Suitability - ES->Self-Contained Special Ed-->Storage/Fixed Equip

No internal restroom. Does have sink and some related equipment.

Suitability - ES->Music-->Environment

Limited , spatial configurations, and acoustics. No natural light.

Suitability - ES->Music-->Location

Located across from the media center.

Suitability - ES->Music-->Storage/Fixed Equip

Limited storage space.

Suitability - ES->P.E.-->Environment

Some water leaks in the ceiling. The main sound system is broken (using portable system). Adequate lighting.

Suitability - ES->Media Center-->Environment

Library has storage space, good aesthetics, and includes a reading nook. There is a loud buzzing from the light fixtures. Adequate natural/artificial light.

Suitability - ES->Restrooms (Student)

Boys' restrooms lack urinal privacy dividers.

Suitability - ES->Administration

Some roof leaks in the administration area.

Suitability - ES->Clinic

Only lacking a shower area.

Suitability - ES->Cafeteria

Met 85% of the square footage standard. Some classroom materials are stored in the back of the cafeteria.

Suitability - ES->Outside-->Parking

Lack adequate parking space for staff, visitors, and buses. Buses and visitors will park in the grass.

Suitability Report - Full

Project #: 8272	County: Anson	Site #: 37001800046
Project: Assessments 2016	Region: 40	Site: MORVEN ELEMENTARY
Grade Config: PK-06	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Good	9.80	12.25	80.00
Location	Excel	3.68	3.68	100.00
Storage/Fixed Equip	Excel	3.68	3.68	100.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Excel	1.04	1.04	100.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Excel	0.31	0.31	100.00
ECE				
Environment	Excel	0.50	0.50	100.00
Size	Good	1.00	1.25	80.00
Location	Excel	0.37	0.37	100.00
Storage/Fixed Equip	Good	0.30	0.37	80.00
Self-Contained Special Ed				
Environment	Excel	0.48	0.48	100.00
Size	Excel	1.20	1.20	100.00
Location	Excel	0.36	0.36	100.00
Storage/Fixed Equip	Excel	0.36	0.36	100.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Good	1.44	1.80	80.00
Location	Excel	0.54	0.54	100.00
Storage/Fixed Equip	Excel	0.54	0.54	100.00
Science				
Environment	Good	0.40	0.50	80.00
Size	Good	1.00	1.25	80.00
Location	Good	0.30	0.38	80.00
Storage/Fixed Equip	Good	0.30	0.38	80.00
Music				
Environment	Good	0.59	0.74	80.00

Project #: 8272

County: Anson

Site #: 370018000046

Project: Assessments 2016

Region: 40

Site: MORVEN ELEMENTARY

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	1.85	1.85	100.00
Location	Excel	0.56	0.56	100.00
Storage/Fixed Equip	Excel	0.56	0.56	100.00
Art				
Environment	Good	0.37	0.47	80.00
Size	Excel	1.17	1.17	100.00
Location	Excel	0.35	0.35	100.00
Storage/Fixed Equip	Excel	0.35	0.35	100.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Good	0.68	0.85	80.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Poor	0.96	1.92	50.00
Size	Fair	3.12	4.80	65.00
Location	Good	1.15	1.44	80.00
Storage/Fixed Equip	Fair	0.94	1.44	65.00
Performing Arts				
Environment	Poor	0.30	0.60	50.00
Size	Fair	0.98	1.51	65.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Poor	0.23	0.45	50.00
Media Center				
Environment	Excel	0.97	0.97	100.00
Size	Good	1.95	2.44	80.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Excel	0.73	0.73	100.00
Restrooms (Student)	Excel	0.89	0.89	100.00
Administration	Good	2.05	2.56	80.00
Counseling	Excel	0.29	0.29	100.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Excel	1.27	1.27	100.00
Cafeteria	Good	4.00	5.00	80.00
Food Service and Prep	Excel	6.20	6.20	100.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Excel	2.00	2.00	100.00
Pedestrian Traffic	Excel	0.97	0.97	100.00
Parking	Excel	0.81	0.81	100.00
Play Areas	Excel	2.34	2.34	100.00
Safety and Security				
Fencing	Unsat	0.00	0.75	0.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Poor	1.50	3.00	50.00
Controlled Entrances	Fair	0.33	0.50	65.00

Project #: 8272

County: Anson

Site #: 370018000046

Project: Assessments 2016

Region: 40

Site: MORVEN ELEMENTARY

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		82.95	100.00	82.95

Comments

Suitability - ES

Morven Elementary School is located in South Morven, NC, and was built in 1994. It serves students in grades PK through 6. In addition to the main school building, there are outdoor learning spaces in a courtyard that is routinely used for science classes and other subjects.

Suitability - ES->Learning Environment-->Learning Style Variety

The school has several spaces that allow for various group sizes and for differentiated instruction to accommodate various teaching and learning styles.

Suitability - ES->Learning Environment-->Interior Environment

Main hallways in the building are poorly lit due to the design of the lighting. Ceilings are high and lit mainly through recessed lights.

Suitability - ES->Self-Contained Special Ed

This space meets all the suitability standards; however, currently the program does not exist at the school and the space is used by other itinerant resource personnel.

Suitability - ES->Instructional Resource Rooms

There are several of these spaces conveniently located throughout the school.

Suitability - ES->Music

The school has a music room that meets the suitability standards; however, there is no music teacher at the school, and so part of the space is used for 6th grade band by an itinerant teacher.

Suitability - ES->Art

The designated space for art meets the majority of the suitability standards; however, it is not being used because there is no art teacher at the school.

Suitability - ES->P.E.-->Environment

Acoustics in the gym are unacceptable and sound echoes throughout the space. It does not have sufficient air circulation.

Suitability - ES->P.E.-->Size

The space is under the size standards.

Suitability - ES->P.E.-->Storage/Fixed Equip

There is a locked storage room with shelving at the front of the gym.

Suitability - ES->Performing Arts-->Environment

The space is located in the gym but has no fixed sound system, or curtains. There is no designated storage space. The acoustics are very inadequate and the temperature is not well regulated to maintain a comfortable temperature in the space.

Suitability - ES->Performing Arts-->Size

The space does not meet the size requirement.

Suitability - ES->Performing Arts-->Storage/Fixed Equip

The stage is located in the gym, and there is a storage room for chairs, but no other designated storage space.

Suitability - ES->Clinic

Only sufficient space for one cot, and overall square footage is slightly below the size standards.

Suitability - ES->Cafeteria

Cafeteria is slightly below the size standards.

Project #: 8272

County: Anson

Site #: 370018000046

Project: Assessments 2016

Region: 40

Site: MORVEN ELEMENTARY

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Safety and Security-->Fencing There is no secured fencing on the school campus.				
Suitability - ES->Safety and Security-->Signage & Way Finding There are two doors at the front of the school and neither one is clearly marked other than at the entrance to direct visitors to the correct door. Once in the building, there is no way-finding signage to guide visitors to major areas of the building.				
Suitability - ES->Safety and Security-->Ease of Supervision The layout of the building does not have clear lines of sight into all spaces. Also, security cameras are on the interior of the building only, and do not transmit video of the school's exterior.				
Suitability - ES->Safety and Security-->Controlled Entrances All exterior doors are kept closed and locked during the day, and the main entrance remains unlocked all day, but leads into a security vestibule where visitors must sign a log and be buzzed into the building.				

Suitability Report - Full

Project #: 8272

County: Anson

Site #: 370018000953

Project: Assessments 2016

Region: 40

Site: PEACHLAND-POLKTON E

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Poor	2.50	5.00	50.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Fair	3.19	4.90	65.00
Size	Good	9.80	12.25	80.00
Location	Excel	3.68	3.68	100.00
Storage/Fixed Equip	Excel	3.68	3.68	100.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Excel	1.04	1.04	100.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Excel	0.31	0.31	100.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	Excel	0.48	0.48	100.00
Size	Excel	1.20	1.20	100.00
Location	Excel	0.36	0.36	100.00
Storage/Fixed Equip	Excel	0.36	0.36	100.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Good	1.44	1.80	80.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Excel	0.54	0.54	100.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Project #: 8272

County: Anson

Site #: 370018000953

Project: Assessments 2016

Region: 40

Site: PEACHLAND-POLKTON E

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	1.85	1.85	100.00
Location	Excel	0.56	0.56	100.00
Storage/Fixed Equip	Excel	0.56	0.56	100.00
Art				
Environment	Good	0.37	0.47	80.00
Size	Excel	1.17	1.17	100.00
Location	Excel	0.35	0.35	100.00
Storage/Fixed Equip	Excel	0.35	0.35	100.00
Computer Labs				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
P.E.				
Environment	Poor	0.96	1.92	50.00
Size	Fair	3.12	4.80	65.00
Location	Fair	0.94	1.44	65.00
Storage/Fixed Equip	Fair	0.94	1.44	65.00
Performing Arts				
Environment	Poor	0.30	0.60	50.00
Size	Fair	0.98	1.51	65.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Poor	0.23	0.45	50.00
Media Center				
Environment	Excel	0.97	0.97	100.00
Size	Good	1.95	2.44	80.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Excel	0.73	0.73	100.00
Restrooms (Student)	Fair	0.58	0.89	65.00
Administration	Excel	2.56	2.56	100.00
Counseling	Fair	0.19	0.29	65.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Poor	2.50	5.00	50.00
Food Service and Prep	Good	4.96	6.20	80.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Fair	1.30	2.00	65.00
Pedestrian Traffic	Poor	0.49	0.97	50.00
Parking	Fair	0.53	0.81	65.00
Play Areas	Fair	1.52	2.34	65.00
Safety and Security				
Fencing	Poor	0.38	0.75	50.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Poor	1.50	3.00	50.00
Controlled Entrances	Excel	0.50	0.50	100.00

Project #: 8272

County: Anson

Site #: 370018000953

Project: Assessments 2016

Region: 40

Site: PEACHLAND-POLKTON E

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		69.89	93.30	74.91

Comments

Suitability - ES

Peachland-Polkton Elementary School is located in East Peachland, NC, and is surrounded by communities that have experienced high population growth. The school serves students in grades K through 6. The school was built in 1994, and is one of the newer schools in the district.

Suitability - ES->Learning Environment-->Learning Style Variety

There are not flexible use spaces that accommodate varying teaching and learning styles. In one case where a computer lab is being used as a general classroom, the configuration of requires teacher and students to work around the fixed work surfaces and cabinets.

Suitability - ES->Learning Environment-->Interior Environment

Throughout the building there are a number of rooms that do not have windows and the HVAC system does not provide for proper temperature control throughout the building.

Suitability - ES->Learning Environment-->Exterior Environment

There are outdoor furnishing but its condition and location does not facilitate its use, and is seldom used by teachers.

Suitability - ES->General Classrooms-->Environment

Most rooms meet the suitability standard; however many of the rooms have poorly functioning HVAC systems that do not maintain comfortable temperatures in most rooms.

Suitability - ES->Kindergarten-->Storage/Fixed Equip

Rooms have permanent casework in the classrooms and shared office space between rooms.

Suitability - ES->ECE

The school does not have an early childhood education program.

Suitability - ES->Self-Contained Special Ed

The school has a room that meets the suitability standards but has been taken for a kindergarten classroom.

Suitability - ES->Instructional Resource Rooms

The instructional resource spaces are being used by several itinerant staff members including, ESL, speech therapy, and gifted classes .

Suitability - ES->Science

This is not a required space at the elementary level, and none exists in this school.

Suitability - ES->Music

The school has a music room that meets the suitability standards; however, the room is being used as a regular classroom.

Suitability - ES->Art

The designated space for art meets the majority of the suitability standards; however, it is being used as a regular classroom due to increased student enrollment.

Suitability - ES->Computer Labs

The school has no computer lab.

Suitability - ES->P.E.-->Environment

Acoustics in the gym are unacceptable and sound echoes throughout the space. It does not meet the size standards, and the HVAC system does not maintain a comfortable room temperature (too hot).

Suitability - ES->P.E.-->Size

Gym does not meet a high percentage of the size requirement.

Project #: 8272

County: Anson

Site #: 370018000953

Project: Assessments 2016

Region: 40

Site: PEACHLAND-POLKTON E

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->P.E.-->Location The gym is located at the main entrance of the school and the noise from the space can be heard in the hallway and in a neighboring classroom.				
Suitability - ES->P.E.-->Storage/Fixed Equip There is a locked storage room with shelving at the front of the gym.				
Suitability - ES->Performing Arts-->Environment The space is located in the gym but has no fixed sound system, or curtains. There is no designated storage space. The acoustics are very inadequate and the temperature is not well regulated to maintain a comfortable temperature in the space.				
Suitability - ES->Performing Arts-->Size The space does not meet the size requirement.				
Suitability - ES->Performing Arts-->Storage/Fixed Equip The stage is located in the gym, and there is a storage room for chairs, but no other designated storage space.				
Suitability - ES->Restrooms (Student) There are two sets of communal bathrooms for a student population of nearly 500. Kindergarten classes have shared boys and girls bathrooms between classes. The bathrooms have peeling paint due to humidity and surfaces are rusting and stained.				
Suitability - ES->Counseling The guidance space is undersized and does not have space for a waiting room or student records, which are stored in the data manager's office down the hall from the guidance office.				
Suitability - ES->Clinic The small size of the clinic does not provide space for two cots and the refrigerator is located in an adjoining work room.				
Suitability - ES->Staff Lounge-WkRm The school has multiple workrooms across the building and the main office workroom has two adult bathrooms. There is no faculty lounge independent of a teacher work space.				
Suitability - ES->Cafeteria The cafeteria does not meet the size standard and requires lunch schedule that runs from 10:30 to 1:00 daily to accommodate the student enrollment. There is congestion once older students enter. The HVAC is insufficient to maintain a comfortable temperature and runs loudly creating terrible acoustics.				
Suitability - ES->Food Service and Prep Kitchen is slightly undersized for the size of the meal preparation requirements of the population. The temperature in the kitchen is very hot with poor air circulation.				
Suitability - ES->Outside-->Vehicular Traffic There is good separation of bus loading and parent pick-up and drop-off; however, the parent area is very small and produces long lines that extend into the main road and the line extension blocks the view of cars exiting the campus from seeing oncoming traffic.				
Suitability - ES->Outside-->Pedestrian Traffic There is not adequate walking access that does not cross into the parent pick-up area. There are no walkers at the school.				
Suitability - ES->Outside-->Parking There is not adequate paved parking for all faculty. Some who work on the west side of the building and want to park closer to their classrooms have to park on gravel surfaces.				

Project #: 8272

County: Anson

Site #: 370018000953

Project: Assessments 2016

Region: 40

Site: PEACHLAND-POLKTON E

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability

Rating

Score

Possible
Score

Percent
Score

Suitability - ES->Outside-->Play Areas

The school has a large play area and the kindergarten playground is physically separated from the other play areas; however, drainage in the area is very poor and puddles were under playground equipment and on the ground surrounding the area from a recent rain storm.

Suitability - ES->Safety and Security-->Fencing

There is no fencing on the school property.

Suitability - ES->Safety and Security-->Signage & Way Finding

There is no way-finding signage in the building to guide visitors to major spaces.

Suitability - ES->Safety and Security-->Ease of Supervision

The design layout of the school produces numerous blind spots, many of which do not have coverage through camera monitoring.

Suitability - ES->Safety and Security-->Controlled Entrances

All entrances are secured throughout the day with a security vestibule at the front of the building.

Suitability Report - Full

Project #: 8272	County: Anson	Site #: 370018000050
Project: Assessments 2016	Region: 40	Site: WADESBORO ELEMEN
Grade Config: 05-06	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Poor	1.00	2.00	50.00
Exterior Environment	Poor	0.75	1.50	50.00
General Classrooms				
Environment	Poor	2.45	4.90	50.00
Size	Fair	7.96	12.25	65.00
Location	Fair	2.39	3.68	65.00
Storage/Fixed Equip	Good	2.94	3.68	80.00
Kindergarten				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Fair	0.47	0.72	65.00
Size	Excel	1.80	1.80	100.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Unsat	0.00	0.74	0.00

Project #: 8272

County: Anson

Site #: 370018000050

Project: Assessments 2016

Region: 40

Site: WADESBORO ELEMEN

Grade Config: 05-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	1.48	1.85	80.00
Location	Poor	0.28	0.56	50.00
Storage/Fixed Equip	Poor	0.28	0.56	50.00
Art				
Environment	Unsat	0.00	0.47	0.00
Size	Fair	0.76	1.17	65.00
Location	Poor	0.18	0.35	50.00
Storage/Fixed Equip	Poor	0.18	0.35	50.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Poor	0.43	0.85	50.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Fair	1.25	1.92	65.00
Size	Excel	4.80	4.80	100.00
Location	Good	1.15	1.44	80.00
Storage/Fixed Equip	Fair	0.94	1.44	65.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Fair	0.63	0.97	65.00
Size	Fair	1.58	2.44	65.00
Location	Good	0.58	0.73	80.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Fair	0.58	0.89	65.00
Administration	Fair	1.66	2.56	65.00
Counseling	Good	0.23	0.29	80.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Good	4.00	5.00	80.00
Food Service and Prep	Fair	4.03	6.20	65.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Fair	0.63	0.97	65.00
Parking	Good	0.65	0.81	80.00
Play Areas	Poor	1.17	2.34	50.00
Safety and Security				
Fencing	Poor	0.38	0.75	50.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Poor	1.50	3.00	50.00
Controlled Entrances	Good	0.40	0.50	80.00

Project #: 8272

County: Anson

Site #: 370018000050

Project: Assessments 2016

Region: 40

Site: WADESBORO ELEMEN

Grade Config: 05-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		58.93	87.49	67.36

Comments

Suitability - ES

Wadesboro Elementary School is a 5th-6th grade facility. The school does not serve special education students and does not have any portable classrooms. Many of the facility's spaces are vacant, used by the neighboring Academy, or used by the District/County office. Noise travels easily room to room and frequently disrupts other classes/testing.

Suitability - ES->Learning Environment-->Learning Style Variety

Room sizes allow for flexibility in teaching styles and to create workgroups; Lack of furniture for creating the different spaces.

Suitability - ES->Learning Environment-->Interior Environment

Limited/no aesthetics per instructional program. Noise easily travels from room to room (very loud). Rooms tend to be warm.

Suitability - ES->Learning Environment-->Exterior Environment

Play area offers some space for social gathering. Limited/no other spaces around other parts of the facility (other space is located by the city street).

Suitability - ES->General Classrooms-->Environment

Limited/no aesthetics and very little/no educational/instructional bulletins/fixtures. Noise easily travels from room to room (very loud). Music room can easily be heard within general classrooms. Some flexible space present. Rooms tend to be warm.

Suitability - ES->General Classrooms-->Size

Met 74% of square footage standard.

Suitability - ES->General Classrooms-->Location

Noise easily travels from room to room (very loud). Music room can easily be heard within general classrooms.

Suitability - ES->Instructional Resource Rooms-->Environment

Limited aesthetics. Noise easily travels from room to room (very loud).

Suitability - ES->Music-->Environment

No aesthetics/indication that music is taught aside from a keyboard. Noise easily travels from room to room (very loud).

Suitability - ES->Music-->Location

Limited aesthetics. Noise easily travels from room to room (very loud). Located between general classrooms. The space is also used as an art classroom.

Suitability - ES->Music-->Storage/Fixed Equip

Limited music related equipment.

Suitability - ES->Art-->Environment

No aesthetics/indication that art is taught aside from a markers, poster board, and a blank bulletin board labeled "Art". No direct access to outside. Noise easily travels from room to room (very loud).

Suitability - ES->Art-->Size

Met 79% of the square footage standard.

Suitability - ES->Art-->Location

The space is also used as a music classroom. The space is located between general classrooms.

Suitability - ES->Art-->Storage/Fixed Equip

No clay trap on the sink. No fixed equipment and limited art supplies.

Project #: 8272

County: Anson

Site #: 370018000050

Project: Assessments 2016

Region: 40

Site: WADESBORO ELEMEN

Grade Config: 05-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Computer Labs-->Size Met 50% of square footage standard.				
Suitability - ES->P.E.-->Environment The space is shared with the Academy. Access to the gym is either through Academy offices or via the sidewalk next to the city street.				
Suitability - ES->P.E.-->Storage/Fixed Equip Buzzing noise heard from gym lighting. One water fountain present. No safety padding present.				
Suitability - ES->Media Center-->Environment Inadequate natural and artificial light. Limited aesthetics.				
Suitability - ES->Media Center-->Size Met 71% of square footage standard.				
Suitability - ES->Media Center-->Storage/Fixed Equip Media center lacks outlet for Smartboard wall. Good storage throughout.				
Suitability - ES->Restrooms (Student) All boys' restrooms lack urinal privacy partitions.				
Suitability - ES->Administration Administrative offices are split between the main office area and the area of the building used by the District/County.				
Suitability - ES->Clinic Nurse area lacks internal restroom/shower. Space is small but fits a cot.				
Suitability - ES->Cafeteria Meets the standard for square footage. Some ceiling tiles are buckled/damaged.				
Suitability - ES->Food Service and Prep Sewage smells present on the exterior between the cafeteria and gym. Some appliances are not functioning (warmer, mixer).				
Suitability - ES->Outside-->Pedestrian Traffic To access the gym, students must either access via the Academy offices through the 1st floor of the gym, or use the city sidewalk to access the gym (which is on the 2nd floor of the building). There is no separation between the sidewalk and street traffic.				
Suitability - ES->Outside-->Parking No bus parking; buses are shared with the primary school and only pick-up/drop-off.				
Suitability - ES->Outside-->Play Areas Old/unusable equipment present next to newer fixed equipment. Newer fixed equipment is constructed for younger grade levels than what is currently offered/served (5th-6th). Area does not have fencing and is open to adjacent neighborhood/buildings.				
Suitability - ES->Safety and Security-->Fencing No perimeter fencing. Entrances to cafeteria/gym areas are open to street access.				
Suitability - ES->Safety and Security-->Signage & Way Finding Lacks directional/informational signage outside. Signage present inside the school, but the majority are incorrect.				
Suitability - ES->Safety and Security-->Ease of Supervision There are many empty rooms/spaces that increase the number of blind spots. No/limited camera coverage inside/outside. Front entrance is properly supervised.				

Suitability Report - Full

Project #: 8272	County: Anson	Site #: 370018000044
Project: Assessments 2016	Region: 40	Site: WADESBORO PRIMARY
Grade Config: PK-04	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Fair	3.19	4.90	65.00
Size	Excel	12.25	12.25	100.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Fair	2.39	3.68	65.00
Kindergarten				
Environment	Good	0.33	0.42	80.00
Size	Good	0.83	1.04	80.00
Location	Good	0.25	0.31	80.00
Storage/Fixed Equip	Excel	0.31	0.31	100.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	Good	0.38	0.48	80.00
Size	Good	0.96	1.20	80.00
Location	Good	0.29	0.36	80.00
Storage/Fixed Equip	Good	0.29	0.36	80.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Good	1.44	1.80	80.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Project #: 8272

County: Anson

Site #: 370018000044

Project: Assessments 2016

Region: 40

Site: WADESBORO PRIMARY

Grade Config: PK-04

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	1.85	1.85	100.00
Location	Good	0.44	0.56	80.00
Storage/Fixed Equip	Good	0.44	0.56	80.00
Art				
Environment	Good	0.37	0.47	80.00
Size	Excel	1.17	1.17	100.00
Location	Good	0.28	0.35	80.00
Storage/Fixed Equip	Fair	0.23	0.35	65.00
Computer Labs				
Environment	Poor	0.17	0.34	50.00
Size	Poor	0.43	0.85	50.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Poor	0.96	1.92	50.00
Size	Good	3.84	4.80	80.00
Location	Fair	0.94	1.44	65.00
Storage/Fixed Equip	Poor	0.72	1.44	50.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Fair	1.58	2.44	65.00
Location	Good	0.58	0.73	80.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Fair	0.58	0.89	65.00
Administration	Excel	2.56	2.56	100.00
Counseling	Good	0.23	0.29	80.00
Clinic	Excel	0.58	0.58	100.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Fair	3.25	5.00	65.00
Food Service and Prep	Poor	3.10	6.20	50.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Excel	2.00	2.00	100.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Good	0.65	0.81	80.00
Play Areas	Good	1.87	2.34	80.00
Safety and Security				
Fencing	Poor	0.38	0.75	50.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Good	0.40	0.50	80.00

Project #: 8272

County: Anson

Site #: 370018000044

Project: Assessments 2016

Region: 40

Site: WADESBORO PRIMARY

Grade Config: PK-04

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		70.60	91.98	76.75

Comments

Suitability - ES

Wadesboro Primary School is a K-4 grade facility built in 2000. The school does not serve physically-disabled special education students and does not have any portable classrooms. HVAC system and power outages disrupt operations.

Suitability - ES->Learning Environment-->Interior Environment

Limited aesthetics in some general classrooms.

Suitability - ES->Learning Environment-->Exterior Environment

There are a few social gathering spaces located in the back of the school within the playground area.

Suitability - ES->General Classrooms-->Environment

There are HVAC issues throughout the building. There are limited aesthetics in some of the general classrooms.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Rooms lack appropriate number of power outlets for the equipment used, particularly in the 3rd-4th grade rooms.

Suitability - ES->Kindergarten-->Size

Met 84% of the square footage standard.

Suitability - ES->Self-Contained Special Ed-->Size

No fixed equipment to serve physical SPED, but no physical SPED students served. Equipment is appropriate for current program.

Suitability - ES->Music-->Location

Music and Art classes take place in the same room by a single instructor.

Suitability - ES->Art-->Location

Music and Art classes take place in the same room by a single instructor.

Suitability - ES->Art-->Storage/Fixed Equip

Limited fixed/related equipment.

Suitability - ES->Computer Labs-->Environment

The computer lab tends to be humid and hot. Doors must be propped open, and lights have been removed to reduce heat, creating a very dim room. Poor aesthetics.

Suitability - ES->Computer Labs-->Size

Met 58% of the square footage standard.

Suitability - ES->P.E.-->Environment

The gym area is a multipurpose room and extension of the cafeteria, divided by a partitioned wall. The floor is tile and the room has limited/no fixed equipment, but does have a mobile basketball goal and some other play equipment (ball, hula hoops, etc.). Limited aesthetics and typical gym environment.

Suitability - ES->P.E.-->Location

Located across from the media center and next to the cafeteria (divided by partitioned wall).

Suitability - ES->P.E.-->Storage/Fixed Equip

The play space of the gym is used to house folding chairs and other equipment. There is limited/no fixed equipment, but does have a mobile basketball goal and some other play equipment (ball, hula hoops, etc.). There are no water fountains or fixed safety padding.

Suitability - ES->Media Center-->Size

Met 65% of the square footage standard. Power strips are used to connect computers/equipment to power outlets.

Project #: 8272

County: Anson

Site #: 370018000044

Project: Assessments 2016

Region: 40

Site: WADESBORO PRIMARY

Grade Config: PK-04

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Restrooms (Student) Boys' restrooms lack urinal privacy partitions.				
Suitability - ES->Cafeteria Met 73% of the square footage standard. Reported capacity issues during lunch times and the need for another lunch service line.				
Suitability - ES->Food Service and Prep Electrical power and fire alarm system do not work appropriately, resulting in outages and false fire alarms. There is a lack of appropriate freezer space.				
Suitability - ES->Safety and Security-->Fencing No perimeter fencing.				
Suitability - ES->Safety and Security-->Ease of Supervision There is a lack of adequate camera coverage and the system is old. There are many blind spots. Outside camera coverage only spans the playground.				

Suitability Report - Full

Project #: 8272	County: Anson	Site #: 370018002056
Project: Assessments 2016	Region: 40	Site: ANSON MIDDLE
Grade Config: 07-08	Site Type: Middle	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Fair	2.54	3.90	65.00
Size	Excel	9.75	9.75	100.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Poor	1.46	2.93	50.00
Self-Contained Special Ed				
Environment	Fair	0.35	0.55	65.00
Size	Excel	1.36	1.36	100.00
Location	Fair	0.27	0.41	65.00
Storage/Fixed Equip	Fair	0.27	0.41	65.00
Instructional Resource Rooms				
Environment	Fair	0.53	0.82	65.00
Size	Good	1.64	2.05	80.00
Location	Good	0.49	0.61	80.00
Storage/Fixed Equip	Good	0.49	0.61	80.00
Science				
Environment	Good	0.76	0.95	80.00
Size	Good	1.91	2.39	80.00
Location	Good	0.57	0.72	80.00
Storage/Fixed Equip	Fair	0.47	0.72	65.00
Music				
Environment	Fair	0.48	0.74	65.00
Size	Excel	1.84	1.84	100.00
Location	Good	0.44	0.55	80.00
Storage/Fixed Equip	Good	0.44	0.55	80.00
Art				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Career Tech Ed				
Environment	Fair	0.88	1.35	65.00

Project #: 8272

County: Anson

Site #: 370018002056

Project: Assessments 2016

Region: 40

Site: ANSON MIDDLE

Grade Config: 07-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	2.70	3.37	80.00
Location	Good	0.81	1.01	80.00
Storage/Fixed Equip	Fair	0.66	1.01	65.00
Computer Labs				
Environment	Good	0.24	0.30	80.00
Size	Excel	0.75	0.75	100.00
Location	Excel	0.23	0.23	100.00
Storage/Fixed Equip	Good	0.18	0.23	80.00
P.E.				
Environment	Fair	1.56	2.40	65.00
Size	Good	4.80	6.00	80.00
Location	Good	1.44	1.80	80.00
Storage/Fixed Equip	Good	1.44	1.80	80.00
Performing Arts				
Environment	Poor	0.21	0.42	50.00
Size	Good	0.84	1.05	80.00
Location	Good	0.25	0.31	80.00
Storage/Fixed Equip	Poor	0.16	0.31	50.00
Media Center				
Environment	Good	0.74	0.93	80.00
Size	Good	1.86	2.32	80.00
Location	Good	0.56	0.70	80.00
Storage/Fixed Equip	Fair	0.45	0.70	65.00
Restrooms (Student)	Fair	0.60	0.93	65.00
Administration	Fair	1.36	2.10	65.00
Counseling	Good	0.34	0.42	80.00
Clinic	Fair	0.22	0.34	65.00
Staff Lounge-WkRm	Fair	0.59	0.91	65.00
Cafeteria	Fair	2.60	4.00	65.00
Food Service and Prep	Poor	2.86	5.72	50.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Fair	2.60	4.00	65.00
Pedestrian Traffic	Good	0.35	0.43	80.00
Parking	Fair	0.56	0.86	65.00
Athletic Courts and Fields	Fair	0.68	1.05	65.00
Safety and Security				
Fencing	Good	0.62	0.78	80.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Fair	0.33	0.50	65.00
Total For Site:		71.37	96.78	73.75

Comments

Project #: 8272

County: Anson

Site #: 370018002056

Project: Assessments 2016

Region: 40

Site: ANSON MIDDLE

Grade Config: 07-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Anson Middle School is a 7th-8th grade facility built in the 1960s and was previously a high school. The school serves special education students. The school does not have any portable classrooms. Reported major issues with plumbing, electrical, and HVAC system throughout the building. The H-Building is current not used except for storage. The gym has considerable structural issues.				
Suitability - MS->Learning Environment-->Learning Style Variety				
Some flexibility and space for workstations and groups. Several classrooms lack Smartboards, or Smartboards are covering up white board space.				
Suitability - MS->Learning Environment-->Interior Environment				
Some flexibility and space for workstations and groups. Sounds tends to travel to other rooms. Limited aesthetics.				
Suitability - MS->Learning Environment-->Exterior Environment				
There is a gathering space outside the library. There are picnic tables by the cafeteria but they are reportedly not used.				
Suitability - MS->General Classrooms-->Environment				
Limited aesthetics/acoustics. Sounds tends to travel to neighboring rooms. Some flexibility and space for groups and different configurations.				
Suitability - MS->General Classrooms-->Storage/Fixed Equip				
All rooms have built-in storage and movable storage. A few rooms needed more storage space. Several classrooms lack Smartboards, or Smartboards are covering up white board space.				
Suitability - MS->Self-Contained Special Ed-->Environment				
Some aesthetics.				
Suitability - MS->Self-Contained Special Ed-->Location				
Located next to and across from 8th grade science rooms.				
Suitability - MS->Self-Contained Special Ed-->Storage/Fixed Equip				
Lacks internal restroom/shower (uses handicap restroom across the hall). Some equipment present.				
Suitability - MS->Instructional Resource Rooms-->Environment				
Limited aesthetics.				
Suitability - MS->Instructional Resource Rooms-->Storage/Fixed Equip				
A mix of built-in and movable storage space.				
Suitability - MS->Science-->Size				
Met 87% of the square footage standard.				
Suitability - MS->Science-->Storage/Fixed Equip				
Storage space, sink, and fixed equipment lacking in the 7th grade science rooms. The 8th grade science rooms are properly equipped and have ample built storage space.				
Suitability - MS->Music-->Environment				
Fair aesthetics/acoustics and limited lighting.				
Suitability - MS->Career Tech Ed-->Environment				
Limited aesthetics and configurations.				
Suitability - MS->Career Tech Ed-->Storage/Fixed Equip				
A mix of built-in and movable storage space. Inadequate storage space in most of the rooms.				
Suitability - MS->P.E.				
Noted that the wall/supports of the gym are weak, and that the wall had to be braced. Structure decayed.				
Suitability - MS->P.E.-->Environment				
Water damage has caused the floor to buckle.				

Project #: 8272

County: Anson

Site #: 370018002056

Project: Assessments 2016

Region: 40

Site: ANSON MIDDLE

Grade Config: 07-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS->Performing Arts-->Environment Poor aesthetics. Lacks proper acoustics, sound system, curtain, lighting, and proper seating.				
Suitability - MS->Performing Arts-->Storage/Fixed Equip Lacks fixed seating (folding chairs only), sound system, curtains, lighting, and related technology. Poor acoustics. Storage space currently houses a server and unused furniture/equipment.				
Suitability - MS->Media Center-->Storage/Fixed Equip Using drops/power strips to connect computers and other technology.				
Suitability - MS->Restrooms (Student) Restrooms do not have hot water. The boys' restroom on the 7th grade hall is locked and unused due to plumbing issues.				
Suitability - MS->Administration Conference room is located away from the office area and is housed in an unused classroom. Records are kept in two different locations due to lack of space.				
Suitability - MS->Clinic Lacks an internal restroom, shower, and refrigerator.				
Suitability - MS->Staff Lounge-WkRm Some workrooms lack common equipment and have poor lighting.				
Suitability - MS->Cafeteria The cafeteria met the standard for square footage and has proper seating. Need additional serving line/space. Students finishing lunch are routed outside to allow for the next lunch to enter the cafeteria.				
Suitability - MS->Food Service and Prep The freezer is located outside, as well as the custodial supply closet for the kitchen. The heater in the staff bathroom does not work. There is an electrical outlet located above the dish wash area and is an electrical hazard. There is inadequate storage space. The kitchen tends to be too warm/hot and staff use fans/prop open the door. The AC unit tends to freeze.				
Suitability - MS->Outside-->Vehicular Traffic Morning traffic can extend into the street. Lacking some separation between staff parking and bus lot.				
Suitability - MS->Outside-->Parking Adequate parking for needs. The lot needs repaving. Inadequate lighting for parking lots at night.				
Suitability - MS->Outside-->Athletic Courts and Fields Noted that fields lack irrigation and proper sound system.				
Suitability - MS->Safety and Security-->Signage & Way Finding Lacks some directional/informational signage at the entrances and interior rooms.				
Suitability - MS->Safety and Security-->Ease of Supervision No security cameras for the parking lots.				
Suitability - MS->Safety and Security-->Controlled Entrances Building locks are old/tend to stick.				

Suitability Report - Full

Project #: 8272	County: Anson	Site #: 370018002367
Project: Assessments 2016	Region: 40	Site: ANSON ACADEMY
Grade Config: 09-12	Site Type: High	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Poor	1.00	2.00	50.00
Exterior Environment	Unsat	0.00	1.50	0.00
General Classrooms				
Environment	Fair	2.54	3.90	65.00
Size	Good	7.80	9.75	80.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Good	2.34	2.93	80.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Good	0.64	0.80	80.00
Size	Good	1.60	2.00	80.00
Location	Good	0.48	0.60	80.00
Storage/Fixed Equip	Good	0.48	0.60	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Art				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Career Tech Ed				
Environment	(N/A)	0.00	0.00	0.00

Project #: 8272

County: Anson

Site #: 370018002367

Project: Assessments 2016

Region: 40

Site: ANSON ACADEMY

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Computer Labs				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
P.E.				
Environment	Fair	1.56	2.40	65.00
Size	Good	4.80	6.00	80.00
Location	Good	1.44	1.80	80.00
Storage/Fixed Equip	Poor	0.90	1.80	50.00
Performing Arts				
Environment	Unsat	0.00	0.32	0.00
Size	Unsat	0.00	0.80	0.00
Location	Unsat	0.00	0.24	0.00
Storage/Fixed Equip	Unsat	0.00	0.24	0.00
Media Center				
Environment	Unsat	0.00	0.84	0.00
Size	Unsat	0.00	2.11	0.00
Location	Unsat	0.00	0.63	0.00
Storage/Fixed Equip	Unsat	0.00	0.63	0.00
Restrooms (Student)	Good	0.73	0.91	80.00
Administration	Poor	1.31	2.61	50.00
Counseling	Poor	0.38	0.76	50.00
Clinic	Unsat	0.00	0.24	0.00
Staff Lounge-WkRm	Good	0.57	0.71	80.00
Cafeteria	Unsat	0.00	4.00	0.00
Food Service and Prep	Unsat	0.00	5.11	0.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Unsat	0.00	1.00	0.00
Pedestrian Traffic	Excel	0.98	0.98	100.00
Parking	Poor	1.05	2.11	50.00
Athletic Courts and Fields	(N/A)	0.00	0.00	0.00
Safety and Security				
Fencing	Unsat	0.00	0.85	0.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Poor	0.25	0.50	50.00
Total For Site:		39.83	74.08	53.76

Comments

Project #: 8272

County: Anson

Site #: 370018002367

Project: Assessments 2016

Region: 40

Site: ANSON ACADEMY

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Anson Academy is located in Wadesboro, NC and is an alternative school that serves students in grades 9 through 12. The school is on the campus of Wadesboro Elementary School, which provides food services for the school.				
Suitability - HS->Learning Environment-->Learning Style Variety				
Spaces in the school area not designed to be flexible or to promote differentiated instruction to accommodate multiple teaching and learning styles.				
Suitability - HS->Learning Environment-->Interior Environment				
The building provides space for this alternative program, but has little else in terms of an interior environment that promotes quality teaching and learning, Lighting levels are low in rooms without windows, and the overall aesthetics of the rooms are less than ideal.				
Suitability - HS->Learning Environment-->Exterior Environment				
The school has no exterior learning spaces.				
Suitability - HS->General Classrooms-->Environment				
Several of the rooms have no window, and the overall aesthetics in most rooms are less than ideal.				
Suitability - HS->General Classrooms-->Location				
There are only six classrooms in the school.				
Suitability - HS->Self-Contained Special Ed				
This special education program is not provided at this school.				
Suitability - HS->Science				
There are no science labs at the school.				
Suitability - HS->Music				
No music programs are offered at this school.				
Suitability - HS->Art				
There is no art program at the school.				
Suitability - HS->Career Tech Ed				
The school does not have CTE programs.				
Suitability - HS->Computer Labs				
There is no computer lab in the school.				
Suitability - HS->P.E.-->Environment				
Fixtures in the gym are aged and worn, There is very limited storage and the lighting is not sufficient. There is little air circulation.				
Suitability - HS->P.E.-->Storage/Fixed Equip				
The space has limited storage space.				
Suitability - HS->Performing Arts-->Environment				
There is no performing arts space in the building.				
Suitability - HS->Performing Arts-->Size				
There is no performing arts space in the building.				
Suitability - HS->Performing Arts-->Location				
There is no performing arts space in the building.				
Suitability - HS->Performing Arts-->Storage/Fixed Equip				
There is no performing arts space in the building.				
Suitability - HS->Media Center-->Environment				
There is no media center in the school.				

Project #: 8272

County: Anson

Site #: 370018002367

Project: Assessments 2016

Region: 40

Site: ANSON ACADEMY

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS->Media Center-->Size There is no media center in the school.				
Suitability - HS->Media Center-->Location There is no media center in the school.				
Suitability - HS->Media Center-->Storage/Fixed Equip There is no media center in the school.				
Suitability - HS->Restrooms (Student) There are no separate bathrooms for students and adults. There is a unisex bathroom in the space used as a custodial office and a male and female facility near the school's main entrance.				
Suitability - HS->Administration The administrative spaces are undersize and lack the amenities to meet the suitability standards.				
Suitability - HS->Counseling The counselor's office space is not configured in a way that meets the standards for the space.				
Suitability - HS->Clinic The school has no clinic.				
Suitability - HS->Cafeteria The school has no cafeteria. A multipurpose room serves as an eating area for staff and students.				
Suitability - HS->Food Service and Prep The school has no food service/prep area.				
Suitability - HS->Outside-->Vehicular Traffic There are no designated off-street bus loading zones or parent pick-up areas.				
Suitability - HS->Outside-->Parking There is no paved parking at the school, and the parking lot is shared with the adjacent county health department offices.				
Suitability - HS->Outside-->Athletic Courts and Fields Anson is an alternative school and has no exterior courts or fields.				
Suitability - HS->Safety and Security-->Fencing There is no exterior fencing at the school.				
Suitability - HS->Safety and Security-->Signage & Way Finding Other than the name of the school at the main entrance, and "main office" sign, there is no other way-finding signage at the school.				
Suitability - HS->Safety and Security-->Controlled Entrances The main entrance is not secured and there is no security vestibule. There is a second story entrance that goes directly into the school's gym, and the door was propped open during the site visit.				

Suitability Report - Full

Project #: 8272

County: Anson

Site #: 370018002748

Project: Assessments 2016

Region: 40

Site: ANSON CO. EARLY COL

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Unsat	0.00	1.50	0.00
General Classrooms				
Environment	Good	3.12	3.90	80.00
Size	Excel	9.75	9.75	100.00
Location	Excel	2.93	2.93	100.00
Storage/Fixed Equip	Good	2.34	2.93	80.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Good	0.64	0.80	80.00
Size	Good	1.60	2.00	80.00
Location	Good	0.48	0.60	80.00
Storage/Fixed Equip	Good	0.48	0.60	80.00
Science				
Environment	Good	0.66	0.83	80.00
Size	Excel	2.07	2.07	100.00
Location	Excel	0.62	0.62	100.00
Storage/Fixed Equip	Excel	0.62	0.62	100.00
Music				
Environment	Unsat	0.00	0.59	0.00
Size	Unsat	0.00	1.48	0.00
Location	Unsat	0.00	0.45	0.00
Storage/Fixed Equip	Unsat	0.00	0.45	0.00
Art				
Environment	Unsat	0.00	0.67	0.00
Size	Unsat	0.00	1.66	0.00
Location	Unsat	0.00	0.50	0.00
Storage/Fixed Equip	Unsat	0.00	0.50	0.00
Career Tech Ed				
Environment	(N/A)	0.00	0.00	0.00

Project #: 8272

County: Anson

Site #: 370018002748

Project: Assessments 2016

Region: 40

Site: ANSON CO. EARLY COL

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Computer Labs				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
P.E.				
Environment	Unsat	0.00	2.40	0.00
Size	Unsat	0.00	6.00	0.00
Location	Unsat	0.00	1.80	0.00
Storage/Fixed Equip	Unsat	0.00	1.80	0.00
Performing Arts				
Environment	Unsat	0.00	0.32	0.00
Size	Unsat	0.00	0.80	0.00
Location	Unsat	0.00	0.24	0.00
Storage/Fixed Equip	Unsat	0.00	0.24	0.00
Media Center				
Environment	Unsat	0.00	0.84	0.00
Size	Unsat	0.00	2.11	0.00
Location	Unsat	0.00	0.63	0.00
Storage/Fixed Equip	Unsat	0.00	0.63	0.00
Restrooms (Student)	Excel	0.91	0.91	100.00
Administration	Poor	1.31	2.61	50.00
Counseling	Fair	0.49	0.76	65.00
Clinic	Unsat	0.00	0.24	0.00
Staff Lounge-WkRm	Excel	0.71	0.71	100.00
Cafeteria	Unsat	0.00	4.00	0.00
Food Service and Prep	Unsat	0.00	5.11	0.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Unsat	0.00	1.00	0.00
Pedestrian Traffic	Good	0.78	0.98	80.00
Parking	Excel	2.11	2.11	100.00
Athletic Courts and Fields	Unsat	0.00	2.77	0.00
Safety and Security				
Fencing	Unsat	0.00	0.85	0.00
Signage & Way Finding	Unsat	0.00	1.00	0.00
Ease of Supervision	Unsat	0.00	3.00	0.00
Controlled Entrances	Unsat	0.00	0.50	0.00
Total For Site:		37.73	87.29	43.22

Comments

Project #: 8272

County: Anson

Site #: 370018002748

Project: Assessments 2016

Region: 40

Site: ANSON CO. EARLY COL

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS Anson County Early College High School is located in West Polkton, NC and is housed on the campus of South Piedmont Community College. The specialty high school provides only core academic course and serves students in grades 9 through 12. The school provides students the opportunity to take college courses and complete an associate's degree upon completion of high school.				
Suitability - HS->Learning Environment-->Exterior Environment There are no spaces like this on campus.				
Suitability - HS->Self-Contained Special Ed There are no students requiring this service served at this school. It is a high school for academically advanced students.				
Suitability - HS->Music-->Environment There are no music classrooms. No music programs are available at the school.				
Suitability - HS->Music-->Size There are no music classrooms. No music programs are available at the school.				
Suitability - HS->Music-->Location There are no music classrooms. No music programs are available at the school.				
Suitability - HS->Music-->Storage/Fixed Equip There are no music classrooms. No music programs are available at the school.				
Suitability - HS->Art-->Environment There are no art classrooms. This subject is not available at the school.				
Suitability - HS->Art-->Size There are no art classrooms. This subject is not available at the school.				
Suitability - HS->Art-->Location There are no art classrooms. This subject is not available at the school.				
Suitability - HS->Art-->Storage/Fixed Equip There are no art classrooms. This subject is not available at the school.				
Suitability - HS->Career Tech Ed The school has no CTE programs.				
Suitability - HS->Computer Labs The school has no computer lab.				
Suitability - HS->P.E.-->Environment The school has no gym.				
Suitability - HS->P.E.-->Size The school has no gym.				
Suitability - HS->P.E.-->Location The school has no gym.				
Suitability - HS->P.E.-->Storage/Fixed Equip The school has no gym.				
Suitability - HS->Performing Arts-->Environment The school has no performance areas.				
Suitability - HS->Performing Arts-->Size The school has no performance areas.				

Project #: 8272

County: Anson

Site #: 370018002748

Project: Assessments 2016

Region: 40

Site: ANSON CO. EARLY COL

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS->Performing Arts-->Location The school has no performance areas.				
Suitability - HS->Performing Arts-->Storage/Fixed Equip The school has no performance areas.				
Suitability - HS->Media Center-->Environment The school has no media center.				
Suitability - HS->Media Center-->Size The school has no media center.				
Suitability - HS->Media Center-->Location The school has no media center.				
Suitability - HS->Media Center-->Storage/Fixed Equip The school has no media center.				
Suitability - HS->Restrooms (Student) There are bathrooms for male and female students near the school's main entrance with multiple stalls, and ADA compliant fixtures.				
Suitability - HS->Administration There is no main office for the school. The area that would be the main office belongs to the community college where the school is housed. The school's offices consist of adjoining secretary and principal offices. There is no reception area.				
Suitability - HS->Counseling The guidance area has no waiting area and proximity of guidance office to other offices limit confidentiality.				
Suitability - HS->Clinic The school does not have a clinic.				
Suitability - HS->Cafeteria School has no cafeteria.				
Suitability - HS->Food Service and Prep The school has no kitchen or food prep area.				
Suitability - HS->Outside-->Vehicular Traffic There is no vehicular separation between buses and car riders. These vehicles arrive at different times in the morning, but there is traffic congestion during dismissal.				
Suitability - HS->Outside-->Athletic Courts and Fields The school has no athletic fields or courts.				
Suitability - HS->Safety and Security-->Fencing There is no fencing on the school grounds.				
Suitability - HS->Safety and Security-->Signage & Way Finding There is a sign at the outside entrance to the building with the name of the school, but no other way-finding signage in the building.				
Suitability - HS->Safety and Security-->Ease of Supervision The layout of the main building only allows for direct sight lines along hallways. Portable classrooms can be monitored by security cameras.				
Suitability - HS->Safety and Security-->Controlled Entrances There are no secured entrances on the school campus.				

Suitability Report - Full

Project #: 8272

County: Anson

Site #: 370018002054

Project: Assessments 2016

Region: 40

Site: ANSON HIGH SCHOOL

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Poor	1.00	2.00	50.00
Exterior Environment	Poor	0.75	1.50	50.00
General Classrooms				
Environment	Fair	2.54	3.90	65.00
Size	Good	7.80	9.75	80.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Poor	1.46	2.93	50.00
Self-Contained Special Ed				
Environment	Fair	0.35	0.53	65.00
Size	Excel	1.33	1.33	100.00
Location	Excel	0.40	0.40	100.00
Storage/Fixed Equip	Good	0.32	0.40	80.00
Instructional Resource Rooms				
Environment	Good	0.64	0.80	80.00
Size	Excel	2.00	2.00	100.00
Location	Excel	0.60	0.60	100.00
Storage/Fixed Equip	Poor	0.30	0.60	50.00
Science				
Environment	Good	0.66	0.83	80.00
Size	Good	1.66	2.07	80.00
Location	Excel	0.62	0.62	100.00
Storage/Fixed Equip	Fair	0.40	0.62	65.00
Music				
Environment	Good	0.48	0.59	80.00
Size	Good	1.19	1.48	80.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Good	0.36	0.45	80.00
Art				
Environment	Good	0.53	0.67	80.00
Size	Good	1.33	1.66	80.00
Location	Poor	0.25	0.50	50.00
Storage/Fixed Equip	Good	0.40	0.50	80.00
Career Tech Ed				
Environment	Good	1.37	1.71	80.00

Project #: 8272

County: Anson

Site #: 370018002054

Project: Assessments 2016

Region: 40

Site: ANSON HIGH SCHOOL

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	3.42	4.27	80.00
Location	Fair	0.83	1.28	65.00
Storage/Fixed Equip	Good	1.03	1.28	80.00
Computer Labs				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
P.E.				
Environment	Good	1.92	2.40	80.00
Size	Good	4.80	6.00	80.00
Location	Good	1.44	1.80	80.00
Storage/Fixed Equip	Poor	0.90	1.80	50.00
Performing Arts				
Environment	Unsat	0.00	0.32	0.00
Size	Unsat	0.00	0.80	0.00
Location	Unsat	0.00	0.24	0.00
Storage/Fixed Equip	Unsat	0.00	0.24	0.00
Media Center				
Environment	Excel	0.84	0.84	100.00
Size	Excel	2.11	2.11	100.00
Location	Excel	0.63	0.63	100.00
Storage/Fixed Equip	Excel	0.63	0.63	100.00
Restrooms (Student)	Excel	0.91	0.91	100.00
Administration	Excel	2.61	2.61	100.00
Counseling	Excel	0.76	0.76	100.00
Clinic	Fair	0.15	0.24	65.00
Staff Lounge-WkRm	Excel	0.71	0.71	100.00
Cafeteria	Poor	2.00	4.00	50.00
Food Service and Prep	Excel	5.11	5.11	100.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Excel	1.00	1.00	100.00
Pedestrian Traffic	Fair	0.64	0.98	65.00
Parking	Excel	2.11	2.11	100.00
Athletic Courts and Fields	Good	2.21	2.77	80.00
Safety and Security				
Fencing	Poor	0.42	0.85	50.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Fair	0.33	0.50	65.00
Total For Site:		75.88	98.50	77.04

Comments

Project #: 8272

County: Anson

Site #: 370018002054

Project: Assessments 2016

Region: 40

Site: ANSON HIGH SCHOOL

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Anson County High School is located in Wadesboro, NC and was built in 1958, with expansions and renovations in 1996. The school currently serves students in grades 9 through 12. In addition to spaces for core academic courses, the school provides CTE classes in auto mechanics, carpentry, drafting, business, and aquaponics.				
Suitability - HS->Learning Environment-->Learning Style Variety				
There are several spaces around the campus (e.g., in the library, in the commons area next to the cafeteria) that provide flexible learning spaces, but such spaces are not prevalent across the campus.				
Suitability - HS->Learning Environment-->Interior Environment				
The HVAC system performs poorly throughout the building with most rooms either too hot or too cold. Hallways are poor lit due to insufficient lighting (e.g., most halls have only a string of single florescent tube lights down the halls).				
Suitability - HS->Learning Environment-->Exterior Environment				
The school has a poorly located greenhouse and the agriculture program has a few raised plant beds, but the large green space is mostly unused for outdoor learning experiences.				
Suitability - HS->General Classrooms-->Environment				
Acoustics and temperature regulation is a problem in classrooms across the campus. In some classes, there are unacceptable levels of noise transfer from room to room.				
Suitability - HS->General Classrooms-->Storage/Fixed Equip				
Most rooms do not have sufficient permanent casework for storage or an adequate number of adjoining storage spaces.				
Suitability - HS->Self-Contained Special Ed-->Environment				
The surfaces and furnishings in the room is aging and showing wear and tear.				
Suitability - HS->Instructional Resource Rooms-->Size				
All resource programs are in full-size regular classrooms.				
Suitability - HS->Instructional Resource Rooms-->Storage/Fixed Equip				
Rooms have little or no permanent casework in most classes.				
Suitability - HS->Science-->Storage/Fixed Equip				
Space for supplies and equipment is limited in science classrooms.				
Suitability - HS->Art-->Environment				
The room has windows, but they are undersized and do not allow in significant natural light.				
Suitability - HS->Art-->Location				
The art room is secluded in a far corner of the campus, away from other elective programs.				
Suitability - HS->Career Tech Ed-->Location				
Several of the programs are located in spaces that limit the capacity of the program. For example, the greenhouse for the agriculture program is "hemmed in" to a small space with limited accessibility.				
Suitability - HS->Computer Labs				
The school has a one-to-one laptop initiative and the school has no free-standing lab.				
Suitability - HS->P.E.-->Storage/Fixed Equip				
Storage space is very limited and not convenient for daily use.				
Suitability - HS->Performing Arts-->Environment				
The school has no auditorium space.				
Suitability - HS->Performing Arts-->Size				
The school has no auditorium space.				
Suitability - HS->Performing Arts-->Location				
The school has no auditorium space.				

Project #: 8272

County: Anson

Site #: 370018002054

Project: Assessments 2016

Region: 40

Site: ANSON HIGH SCHOOL

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS->Performing Arts-->Storage/Fixed Equip The school has no auditorium space.				
Suitability - HS->Media Center This was one of the best spaces in the school. It met all the standards and is a very inviting learning space.				
Suitability - HS->Counseling Except for the inadequate HVAC system, this is one of the best spaces in the building, and meets all the standards for the space.				
Suitability - HS->Clinic The clinic space does not meet the size standard and the space is shared with the social worker. There is no ADA compliant restroom in the space.				
Suitability - HS->Cafeteria The cafeteria does not meet the size standards and has poor acoustics. The HVAC system also does not function well enough to maintain a comfortable temperature in the space.				
Suitability - HS->Outside-->Pedestrian Traffic There is limited pedestrian traffic as the only walking students are those who live in the apartment complex across the street from the school. They have to cross a busy highway to get to the campus.				
Suitability - HS->Outside-->Athletic Courts and Fields The track is in poor condition and cannot be used for competition or practice.				
Suitability - HS->Safety and Security-->Fencing There is only fencing along the side of the school that faces a major highway.				
Suitability - HS->Safety and Security-->Ease of Supervision The school campus is comprised of six separate buildings and there are direct lines of sight down individual hallways, but many blind spots within and across the buildings on campus. These conditions are addressed with a bank of 80 security cameras on the interiors and exteriors of all buildings, with the capability to zoom in on specific locations.				
Suitability - HS->Safety and Security-->Controlled Entrances The main entrance of the school does not have a security vestibule and the doors are unsecured throughout the day. All Other spaces are also accessible as students travel from one building to another for class changes.				

Suitability Report - Full

Project #: 8272	County: Anson	Site #: 370018002973
Project: Assessments 2016	Region: 40	Site: ANSON NEW TECH HIG
Grade Config: 09-12	Site Type: High	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Fair	2.54	3.90	65.00
Size	Good	7.80	9.75	80.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Good	2.34	2.93	80.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Science				
Environment	Fair	0.54	0.83	65.00
Size	Good	1.66	2.07	80.00
Location	Good	0.50	0.62	80.00
Storage/Fixed Equip	Poor	0.31	0.62	50.00
Music				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Art				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Career Tech Ed				
Environment	Fair	1.11	1.71	65.00

Project #: 8272

County: Anson

Site #: 370018002973

Project: Assessments 2016

Region: 40

Site: ANSON NEW TECH HIG

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	3.42	4.27	80.00
Location	Good	1.03	1.28	80.00
Storage/Fixed Equip	Fair	0.83	1.28	65.00
Computer Labs				
Environment	Fair	0.20	0.30	65.00
Size	Good	0.60	0.75	80.00
Location	Good	0.18	0.23	80.00
Storage/Fixed Equip	Good	0.18	0.23	80.00
P.E.				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Restrooms (Student)	Fair	0.59	0.91	65.00
Administration	Poor	1.31	2.61	50.00
Counseling	(N/A)	0.00	0.00	0.00
Clinic	(N/A)	0.00	0.00	0.00
Staff Lounge-WkRm	Good	0.57	0.71	80.00
Cafeteria	(N/A)	0.00	0.00	0.00
Food Service and Prep	(N/A)	0.00	0.00	0.00
Custodial and Maintenance	(N/A)	0.00	0.00	0.00
Outside				
Vehicular Traffic	(N/A)	0.00	0.00	0.00
Pedestrian Traffic	Good	0.78	0.98	80.00
Parking	Good	1.69	2.11	80.00
Athletic Courts and Fields	(N/A)	0.00	0.00	0.00
Safety and Security				
Fencing	Good	0.68	0.85	80.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Good	0.40	0.50	80.00
Total For Site:		40.16	54.86	73.19

Comments

Project #: 8272

County: Anson

Site #: 370018002973

Project: Assessments 2016

Region: 40

Site: ANSON NEW TECH HIG

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Anson Tech High is a technical/advanced program housed on the Anson High School campus and serves 9th-12th grade students. Students in this program attend technical classes within an adjacent building and go to Anson High School facilities for electives, pick-up/drop-off, meals, etc. The school/program does not serve special education students. The Tech High does not have any portable classrooms associated with its program. Only Anson Tech program classrooms were assessed, not Anson High School facilities, to avoid duplication in assessment.				
Suitability - HS->Learning Environment-->Learning Style Variety Limited flexible space or room for workstations.				
Suitability - HS->Learning Environment-->Interior Environment Limited aesthetics and limited flexible space.				
Suitability - HS->Learning Environment-->Exterior Environment Limited space around the building given its location to the street.				
Suitability - HS->General Classrooms-->Environment Limited aesthetics and limited flexible space.				
Suitability - HS->General Classrooms-->Storage/Fixed Equip No closet space or permanent casework; all movable storage.				
Suitability - HS->Science-->Environment There are heating/cooling issues. Limited aesthetics.				
Suitability - HS->Science-->Storage/Fixed Equip Power strips are being used in a few rooms in which outlets are not properly located within the configuration of the room, as well as "pillar" outlets not working in the science rooms. No permanent casework; all storage is movable storage. No closet space. Sinks are present but the drain does not work in one of the classrooms.				
Suitability - HS->Career Tech Ed-->Environment There are heating/cooling issues. Limited aesthetics.				
Suitability - HS->Career Tech Ed-->Storage/Fixed Equip No permanent casework; all storage is movable storage. No closet space. Limited course related equipment.				
Suitability - HS->Computer Labs-->Environment Little aesthetics and fair acoustics.				
Suitability - HS->Restrooms (Student) Students must exit class onto a breezeway-type hallway and walk around the building to access the nearest restroom.				
Suitability - HS->Administration The Anson New Tech has an administrative office located next to general classrooms, which is designed as a classroom space. There are no directional or informational markers distinguishing this space from others. It is located centrally in the building and guests are not directed to it.				
Suitability - HS->Safety and Security-->Signage & Way Finding Lacks some directional signage.				

Suitability Report - Full

Project #: 8272	County: Bertie	Site #: 370036000104
Project: Assessments 2016	Region: 80	Site: AULANDER ELEMENTAR
Grade Config: PK-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Poor	2.50	5.00	50.00
Interior Environment	Poor	1.00	2.00	50.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Poor	2.45	4.90	50.00
Size	Good	9.80	12.25	80.00
Location	Fair	2.39	3.68	65.00
Storage/Fixed Equip	Poor	1.84	3.68	50.00
Kindergarten				
Environment	Good	0.33	0.42	80.00
Size	Good	0.83	1.04	80.00
Location	Good	0.25	0.31	80.00
Storage/Fixed Equip	Good	0.25	0.31	80.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Fair	0.47	0.72	65.00
Size	Good	1.44	1.80	80.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Poor	0.27	0.54	50.00
Science				
Environment	Poor	0.25	0.50	50.00
Size	Excel	1.25	1.25	100.00
Location	Good	0.30	0.38	80.00
Storage/Fixed Equip	Poor	0.19	0.38	50.00
Music				
Environment	(N/A)	0.00	0.00	0.00

Project #: 8272

County: Bertie

Site #: 370036000104

Project: Assessments 2016

Region: 80

Site: AULANDER ELEMENTAR

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Art				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Excel	0.85	0.85	100.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Good	1.54	1.92	80.00
Size	Excel	4.80	4.80	100.00
Location	Good	1.15	1.44	80.00
Storage/Fixed Equip	Good	1.15	1.44	80.00
Performing Arts				
Environment	Good	0.48	0.60	80.00
Size	Fair	0.98	1.51	65.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Poor	0.23	0.45	50.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Poor	1.22	2.44	50.00
Location	Fair	0.48	0.73	65.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Fair	0.58	0.89	65.00
Administration	Poor	1.28	2.56	50.00
Counseling	Poor	0.15	0.29	50.00
Clinic	Poor	0.29	0.58	50.00
Staff Lounge-WkRm	Fair	0.82	1.27	65.00
Cafeteria	Fair	3.25	5.00	65.00
Food Service and Prep	Poor	3.10	6.20	50.00
Custodial and Maintenance	Fair	0.33	0.50	65.00
Outside				
Vehicular Traffic	Fair	1.30	2.00	65.00
Pedestrian Traffic	Fair	0.63	0.97	65.00
Parking	Poor	0.41	0.81	50.00
Play Areas	Fair	1.52	2.34	65.00
Safety and Security				
Fencing	Fair	0.49	0.75	65.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Poor	1.50	3.00	50.00
Controlled Entrances	Fair	0.33	0.50	65.00

Project #: 8272

County: Bertie

Site #: 370036000104

Project: Assessments 2016

Region: 80

Site: AULANDER ELEMENTAR

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		58.97	89.06	66.22

Comments

Suitability - ES->Learning Environment-->Learning Style Variety

Other than empty classrooms Aulander has little in the way of specialized learning spaces.

Suitability - ES->Learning Environment-->Interior Environment

Aulander has had numerous additions / renovations that have made circulation difficult. Air quality and aesthetics are poor.

Suitability - ES->Learning Environment-->Exterior Environment

Aulander has an exterior play area that could be used for outdoor learning but the space is small.

Suitability - ES->General Classrooms-->Environment

Most rooms have natural light but little other amenities.

Suitability - ES->General Classrooms-->Size

General classrooms range from meeting approximately 75% to exceeding the size guidelines.

Suitability - ES->General Classrooms-->Location

The overall size of the school provides for ease of access to core areas but the circulation is convoluted.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Most general classrooms have no storage or casework.

Suitability - ES->Kindergarten-->Size

The kindergarten room meets approximately 80% of the size guideline.

Suitability - ES->Instructional Resource Rooms-->Environment

Resource rooms have little in the way of overall aesthetics. One has no natural light.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip

Resource rooms have minimal storage or casework.

Suitability - ES->Science-->Environment

Science is taught in a general classroom space.

Suitability - ES->Science-->Storage/Fixed Equip

Science is taught in a general classroom space.

Suitability - ES->Performing Arts-->Size

Aulander has a small stage adjacent to a small cafeteria.

Suitability - ES->Performing Arts-->Storage/Fixed Equip

The stage has no storage or lighting.

Suitability - ES->Media Center-->Size

The media center meets approximately 50% of the size standard.

Suitability - ES->Media Center-->Location

The media center is located in the center of the school but circulation is difficult.

Suitability - ES->Restrooms (Student)

Restroom are adequate in number but do not provide partitions or good ventilation.

Suitability - ES->Administration

Administrative spaces are small, there is no conference room and a small reception area.

Suitability - ES->Counseling

An unused classroom is being used for the counselor. There is no actual counselor office.

Project #: 8272

County: Bertie

Site #: 370036000104

Project: Assessments 2016

Region: 80

Site: AULANDER ELEMENTAR

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Clinic The clinic is small with no restroom or cot area.				
Suitability - ES->Staff Lounge-WkRm The staff workroom is located appropriately sized and located. There are few amenities.				
Suitability - ES->Cafeteria The cafeteria meets approximately 85% of the size guideline. There is no storage.				
Suitability - ES->Food Service and Prep The food service area is small with some of the equipment located outside.				
Suitability - ES->Custodial and Maintenance The convoluted configuration of the school makes serving from the custodial areas difficult.				
Suitability - ES->Outside-->Vehicular Traffic Busses and other vehicles are separated but there is some conflict.				
Suitability - ES->Outside-->Pedestrian Traffic Pedestrian traffic can cross other lanes.				
Suitability - ES->Outside-->Parking Parking is inadequate and poorly organized.				
Suitability - ES->Outside-->Play Areas There is one fenced playground area but it is small.				
Suitability - ES->Safety and Security-->Fencing There is one fenced play area. The site itself is not fenced.				
Suitability - ES->Safety and Security-->Signage & Way Finding Finding your way at Aulander can be confusing.				
Suitability - ES->Safety and Security-->Ease of Supervision The convoluted design makes supervision problematic.				
Suitability - ES->Safety and Security-->Controlled Entrances Entrances are electronically controlled. There is no entry vestibule.				

Suitability Report - Full

Project #: 8272	County: Bertie	Site #: 370036000107
Project: Assessments 2016	Region: 80	Site: COLERAIN ELEMENTAR
Grade Config: PK-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Fair	3.19	4.90	65.00
Size	Good	9.80	12.25	80.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Poor	1.84	3.68	50.00
Kindergarten				
Environment	Poor	0.21	0.42	50.00
Size	Good	0.83	1.04	80.00
Location	Good	0.25	0.31	80.00
Storage/Fixed Equip	Fair	0.20	0.31	65.00
ECE				
Environment	Poor	0.25	0.50	50.00
Size	Good	1.00	1.25	80.00
Location	Good	0.30	0.37	80.00
Storage/Fixed Equip	Fair	0.24	0.37	65.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Fair	0.47	0.72	65.00
Size	Fair	1.17	1.80	65.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Poor	0.27	0.54	50.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	(N/A)	0.00	0.00	0.00

Project #: 8272

County: Bertie

Site #: 370036000107

Project: Assessments 2016

Region: 80

Site: COLERAIN ELEMENTAR

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Art				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Computer Labs				
Environment	Fair	0.22	0.34	65.00
Size	Fair	0.55	0.85	65.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Poor	0.13	0.26	50.00
P.E.				
Environment	Good	1.54	1.92	80.00
Size	Good	3.84	4.80	80.00
Location	Good	1.15	1.44	80.00
Storage/Fixed Equip	Poor	0.72	1.44	50.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Good	1.95	2.44	80.00
Location	Good	0.58	0.73	80.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Good	0.71	0.89	80.00
Administration	Fair	1.66	2.56	65.00
Counseling	Unsat	0.00	0.29	0.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Good	4.00	5.00	80.00
Food Service and Prep	Good	4.96	6.20	80.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Good	0.65	0.81	80.00
Play Areas	Good	1.87	2.34	80.00
Safety and Security				
Fencing	Good	0.60	0.75	80.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Fair	0.33	0.50	65.00

Project #: 8272

County: Bertie

Site #: 370036000107

Project: Assessments 2016

Region: 80

Site: COLERAIN ELEMENTAR

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		63.33	86.04	73.61

Comments

Suitability - ES

Colerain Elementary school is located in a rural setting in the northern part or district. The school provides primarily core curriculum classes with very limited extra-curricular offerings for the students. The building was a previous open concept school that has been renovated but lacks a number of the necessary classroom and core space requirements of a 21st century school.

Suitability - ES->Learning Environment-->Learning Style Variety

The are limited spaces for small groups interaction or project based learning. The spaces are not flexible and do not accommodate a differentiated instructional model.

Suitability - ES->Learning Environment-->Interior Environment

The majority of the surfaces are had and create significant acoustical issues. The hallways are narrow and dark and make transition times challenging for staff and students. The environment is not inviting or stimulating and detracts from the educational objectives of the staff.

Suitability - ES->Learning Environment-->Exterior Environment

The outside of the building is not inviting. The landscaping is in poor condition. There is limited outdoor gathering spaces and there are no outdoor classrooms.

Suitability - ES->General Classrooms-->Environment

The classroom have very limited natural lighting. The floors are VCT tile and the walls are concrete block which creates significant acoustical issues for students and staff. The overall aesthetics of the classrooms are poor.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

There is a lack of storage and casework for supplies and materials in the general education classrooms.

Suitability - ES->Kindergarten-->Environment

The classroom have very limited natural lighting. The floors are VCT tile and the walls are concrete block which creates significant acoustical issues for students and staff. The overall aesthetics of the classrooms are poor. There is very limited spatial configuration options and the classrooms do not have an inviting or stimulating environment. The HVAC systems work intermittently and ventilation is poor.

Suitability - ES->Kindergarten-->Storage/Fixed Equip

There is limited storage for supplies and materials in the kindergarten classrooms.

Suitability - ES->ECE-->Environment

The classroom have very limited natural lighting. The floors are VCT tile and the walls are concrete block which creates significant acoustical issues for students and staff. The overall aesthetics of the classrooms are poor. There is very limited spatial configuration options and the classrooms do not have an inviting or stimulating environment. The HVAC systems work intermittently and ventilation is poor.

Suitability - ES->ECE-->Storage/Fixed Equip

There is limited storage in the pre-school classroom.

Suitability - ES->Instructional Resource Rooms-->Environment

The classroom have very limited natural lighting. The floors are VCT tile and the walls are concrete block which creates significant acoustical issues for students and staff. There is very limited spatial configuration options and the classrooms do not have an inviting or stimulating environment. The HVAC systems work intermittently and ventilation is poor.

Suitability - ES->Instructional Resource Rooms-->Size

The tutoring / intervention resource room is a closet with no window, ventilation or natural lighting.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip

There is a lack of storage for supplies and materials.

Project #: 8272

County: Bertie

Site #: 370036000107

Project: Assessments 2016

Region: 80

Site: COLERAIN ELEMENTAR

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
-------------	--------	-------	----------------	---------------

Suitability - ES->Computer Labs-->Environment

There lighting fixtures in the computer labs are old and lack the necessary levels of illumination for the space. The HVAC system does not cool the space properly. The floors are VCT tile and the walls are concrete block which creates significant acoustical issues for students and staff. There is very limited spatial configuration options and the classrooms do not have an inviting or stimulating environment.

Suitability - ES->Computer Labs-->Size

The computer labs meet 71% of the recommended size standard.

Suitability - ES->Computer Labs-->Storage/Fixed Equip

There is a lack of storage for supplies and materials. There is no lockable storage for equipment.

Suitability - ES->P.E.-->Storage/Fixed Equip

There is a lack of storage for P.E. equipment and supplies.

Suitability - ES->Administration

The space is small and crowded for the size of the school.

Suitability - ES->Counseling

The counseling offices are in a storage closet.

Suitability - ES->Clinic

The clinic has limited natural lighting, poor ventilation and lacks the appropriate storage for supplies and materials.

Suitability - ES->Safety and Security-->Controlled Entrances

There is no security vestibule at the school. There are limited interior cameras and no exterior cameras.

Suitability Report - Full

Project #: 8272	County: Bertie	Site #: 370036000106
Project: Assessments 2016	Region: 80	Site: WEST BERTIE ELEMENT
Grade Config: PK-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Fair	7.96	12.25	65.00
Location	Poor	1.84	3.68	50.00
Storage/Fixed Equip	Fair	2.39	3.68	65.00
Kindergarten				
Environment	Good	0.33	0.42	80.00
Size	Excel	1.04	1.04	100.00
Location	Fair	0.20	0.31	65.00
Storage/Fixed Equip	Good	0.25	0.31	80.00
ECE				
Environment	Good	0.40	0.50	80.00
Size	Excel	1.25	1.25	100.00
Location	Good	0.30	0.37	80.00
Storage/Fixed Equip	Good	0.30	0.37	80.00
Self-Contained Special Ed				
Environment	Fair	0.31	0.48	65.00
Size	Fair	0.78	1.20	65.00
Location	Good	0.29	0.36	80.00
Storage/Fixed Equip	Good	0.29	0.36	80.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Excel	1.80	1.80	100.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Poor	0.27	0.54	50.00
Science				
Environment	Fair	0.33	0.50	65.00
Size	Fair	0.81	1.25	65.00
Location	Poor	0.19	0.38	50.00
Storage/Fixed Equip	Fair	0.24	0.38	65.00
Music				
Environment	(N/A)	0.00	0.00	0.00

Project #: 8272

County: Bertie

Site #: 370036000106

Project: Assessments 2016

Region: 80

Site: WEST BERTIE ELEMENT

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Art				
Environment	Unsat	0.00	0.47	0.00
Size	Unsat	0.00	1.17	0.00
Location	Unsat	0.00	0.35	0.00
Storage/Fixed Equip	Unsat	0.00	0.35	0.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Fair	0.55	0.85	65.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Poor	0.96	1.92	50.00
Size	Excel	4.80	4.80	100.00
Location	Poor	0.72	1.44	50.00
Storage/Fixed Equip	Fair	0.94	1.44	65.00
Performing Arts				
Environment	Good	0.48	0.60	80.00
Size	Good	1.21	1.51	80.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Fair	0.29	0.45	65.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Excel	2.44	2.44	100.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Fair	0.58	0.89	65.00
Administration	Fair	1.66	2.56	65.00
Counseling	Good	0.23	0.29	80.00
Clinic	Poor	0.29	0.58	50.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Fair	3.25	5.00	65.00
Food Service and Prep	Good	4.96	6.20	80.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Poor	0.41	0.81	50.00
Play Areas	Good	1.87	2.34	80.00
Safety and Security				
Fencing	Fair	0.49	0.75	65.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Fair	0.33	0.50	65.00

Project #: 8272

County: Bertie

Site #: 370036000106

Project: Assessments 2016

Region: 80

Site: WEST BERTIE ELEMENT

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		69.38	96.30	72.04

Comments

Suitability - ES->Learning Environment-->Interior Environment

West Bertie consists of a number of separate sections constructed or renovated at different times. Classrooms in one section surround the gym, in another they are converted open concept spaces.

Suitability - ES->Learning Environment-->Exterior Environment

The facility includes some outdoor spaces that could be used for outdoor learning opportunities but much of the walkways, pavement, etc. are in disrepair.

Suitability - ES->General Classrooms-->Size

General classrooms range from 75 - 85% of the size guideline.

Suitability - ES->General Classrooms-->Location

General classrooms surround the gym.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Some general classrooms include built in storage and casework, some do not.

Suitability - ES->Kindergarten-->Location

Kindergarten rooms are located together in a converted open concept space.

Suitability - ES->Self-Contained Special Ed-->Environment

Overall the self contained room provides a reasonable learning environment. There is no natural light.

Suitability - ES->Self-Contained Special Ed-->Size

The self contained room meets approximately 75% of the size guidelines.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip

Resource rooms include minimal storage and casework.

Suitability - ES->Science-->Environment

The school includes a room with a science demonstration table that is being used as a tutoring room. The room being used for science does not have any specialized furniture or equipment.

Suitability - ES->Science-->Size

The science lab meets approximately 75% of the size guideline.

Suitability - ES->Science-->Location

The science lab is not being used as such due to the location away from other intermediate level classrooms.

Suitability - ES->Science-->Storage/Fixed Equip

The science rooms has some storage and one demonstration lab.

Suitability - ES->Art-->Environment

No art room exists. Art is being taught in a general classroom space.

Suitability - ES->Art-->Size

No art room exists. Art is being taught in a general classroom space.

Suitability - ES->Art-->Location

No art room exists. Art is being taught in a general classroom space.

Suitability - ES->Art-->Storage/Fixed Equip

No art room exists. Art is being taught in a general classroom space.

Suitability - ES->Computer Labs-->Size

The computer lab meets approximately 75% of the size guideline.

Project #: 8272

County: Bertie

Site #: 370036000106

Project: Assessments 2016

Region: 80

Site: WEST BERTIE ELEMENT

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->P.E.-->Environment The gym is a stark environment with little that makes it an inviting space.				
Suitability - ES->P.E.-->Location The gym is an interior space surrounded by general classrooms. There is no ease of outside access.				
Suitability - ES->P.E.-->Storage/Fixed Equip There is a small storage area directly outside the gym entrance.				
Suitability - ES->Performing Arts-->Location The performing arts consists of a stage located adjacent to the cafeteria.				
Suitability - ES->Performing Arts-->Storage/Fixed Equip The stage has good lighting and sound but no storage.				
Suitability - ES->Restrooms (Student) Restrooms are adequate in number. They do not all provide good ventilation or partitions.				
Suitability - ES->Administration The administrative area lacks appropriate sized spaces and conference area. The placement of the principal's office in a classroom has alleviated some of it.				
Suitability - ES->Clinic The clinic is located away from the office, has no restroom or cot separation.				
Suitability - ES->Cafeteria The cafeteria meets approximately 85% of the size guideline. There is minimal storage.				
Suitability - ES->Outside-->Parking Parking at West Bertie is inadequate and unorganized.				
Suitability - ES->Safety and Security-->Fencing The preschool playground is fenced. Other areas are not.				
Suitability - ES->Safety and Security-->Controlled Entrances Entrances are electronically monitored. There is no entry vestibule.				

Suitability Report - Full

Project #: 8272	County: Bertie	Site #: 370036002285
Project: Assessments 2016	Region: 80	Site: WINDSOR ELEMENTAR
Grade Config: PK-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Poor	0.75	1.50	50.00
General Classrooms				
Environment	Fair	3.19	4.90	65.00
Size	Good	9.80	12.25	80.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Poor	1.84	3.68	50.00
Kindergarten				
Environment	Fair	0.27	0.42	65.00
Size	Good	0.83	1.04	80.00
Location	Poor	0.16	0.31	50.00
Storage/Fixed Equip	Poor	0.16	0.31	50.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	Fair	0.31	0.48	65.00
Size	Good	0.96	1.20	80.00
Location	Good	0.29	0.36	80.00
Storage/Fixed Equip	Poor	0.18	0.36	50.00
Instructional Resource Rooms				
Environment	Fair	0.47	0.72	65.00
Size	Good	1.44	1.80	80.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Poor	0.27	0.54	50.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Fair	0.48	0.74	65.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	1.48	1.85	80.00
Location	Good	0.44	0.56	80.00
Storage/Fixed Equip	Poor	0.28	0.56	50.00
Art				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Computer Labs				
Environment	Poor	0.17	0.34	50.00
Size	Good	0.68	0.85	80.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Poor	0.13	0.26	50.00
P.E.				
Environment	Poor	0.96	1.92	50.00
Size	Fair	3.12	4.80	65.00
Location	Good	1.15	1.44	80.00
Storage/Fixed Equip	Poor	0.72	1.44	50.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Fair	1.58	2.44	65.00
Location	Good	0.58	0.73	80.00
Storage/Fixed Equip	Fair	0.48	0.73	65.00
Restrooms (Student)	Poor	0.44	0.89	50.00
Administration	Fair	1.66	2.56	65.00
Counseling	Unsat	0.00	0.29	0.00
Clinic	Poor	0.29	0.58	50.00
Staff Lounge-WkRm	Poor	0.63	1.27	50.00
Cafeteria	Poor	2.50	5.00	50.00
Food Service and Prep	Fair	4.03	6.20	65.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Poor	1.00	2.00	50.00
Pedestrian Traffic	Poor	0.49	0.97	50.00
Parking	Fair	0.53	0.81	65.00
Play Areas	Good	1.87	2.34	80.00
Safety and Security				
Fencing	Good	0.60	0.75	80.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Fair	0.33	0.50	65.00

Project #: 8272

County: Bertie

Site #: 370036002285

Project: Assessments 2016

Region: 80

Site: WINDSOR ELEMENTAR

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		59.91	89.64	66.83

Comments

Suitability - ES

Windsor elementary school has a Positive Behavior Intervention and Support (PBIS) program that helps create a school environment where there is effective achievement in both academic and social goals. The school is focused on STEM related curriculum and provides students with many opportunities to be involved in science, robotics and math.

Suitability - ES->Learning Environment-->Learning Style Variety

The school has concrete block walls and VCT tile flooring which creates in the building a very institutional environment. There are minimal small group spaces for individualized instruction as well as limited options for spatial configuration.

Suitability - ES->Learning Environment-->Interior Environment

The numerous hard surfaces (wall and floor) create a loud noisy environment which is distracting to students and difficult for teachers to maintain.

Suitability - ES->Learning Environment-->Exterior Environment

The school is not inviting, the main entrance is difficult to find. The landscaping is in poor condition. There are no outdoor classrooms or gathering areas.

Suitability - ES->General Classrooms-->Environment

The general education classroom environment is not inviting, lacks spatial configuration options, has poor acoustical properties due to hard surfaces and the overall aesthetics are poor.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

The is an overall lack of appropriate casework and storage.

Suitability - ES->Kindergarten-->Environment

The kindergarten classroom environment is not inviting, lacks spatial configuration options, has poor acoustical properties due to hard surfaces and the overall aesthetics are poor.

Suitability - ES->Kindergarten-->Location

The kindergarten classrooms are located away from the core building spaces and parent pick up areas.

Suitability - ES->Kindergarten-->Storage/Fixed Equip

Not all of the kindergarten classrooms have restrooms and there is limited casework and storage.

Suitability - ES->Self-Contained Special Ed-->Environment

The self-contained classroom environment is not inviting, lacks spatial configuration options, has poor acoustical properties due to hard surfaces and the overall aesthetics are poor.

Suitability - ES->Self-Contained Special Ed-->Storage/Fixed Equip

There is lack of casework and storage.

Suitability - ES->Instructional Resource Rooms-->Environment

The instruction resource room(s) are located in general education classrooms. The classroom environment is not inviting, lacks spatial configuration options, has poor acoustical properties due to hard surfaces and the overall aesthetics are poor.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip

There is a lack of casework and storage for supplies and materials.

Suitability - ES->Music-->Environment

The music room has no natural lighting, the HVAC does not work properly and there is no acoustical treatment on the walls.

Project #: 8272

County: Bertie

Site #: 370036002285

Project: Assessments 2016

Region: 80

Site: WINDSOR ELEMENTAR

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Music-->Storage/Fixed Equip There is a lack of storage for musical equipment, supplies and materials.				
Suitability - ES->Art Program is no longer available at the school.				
Suitability - ES->Computer Labs-->Environment The computer labs have no natural lighting,. The HVAC systems is not working and consequently the rooms are very warm. There are limited spatial configuration options and the rooms are not very inviting or stimulating.				
Suitability - ES->Computer Labs-->Storage/Fixed Equip There is a lack of storage in the computer labs for materials and equipment. There is no lockable storage.				
Suitability - ES->P.E.-->Environment The gymnasium has no natural lighting, the HVAC system does not work properly, the surfaces are hard and create a lot of noise. The court is undersized and there is no padding on the walls. The backboards are not permanently fixed to the wall creating a safety issue.				
Suitability - ES->P.E.-->Size The gymnasium meets 72% of the recommended size standard.				
Suitability - ES->P.E.-->Storage/Fixed Equip There is a lack of equipment and supply storage.				
Suitability - ES->Media Center-->Size The media center meets 78% of the recommend size standard.				
Suitability - ES->Media Center-->Storage/Fixed Equip There is limited storage in the media center.				
Suitability - ES->Restrooms (Student) The fixtures are older and in need of repair. There are partitions for the stalls but not for the urinals. There is poor ventilation and odors.				
Suitability - ES->Administration The space is undersized for the school enrollment. There is no conference room for private or confidential meetings. There is no reception area for visitors.				
Suitability - ES->Counseling The counseling office is located in a portable.				
Suitability - ES->Clinic There is no ventilation in the clinic, no windows for natural light, the space has only one cot and the storage is limited.				
Suitability - ES->Staff Lounge-WkRm The staff workroom is small for the number of staff. There is limited storage and work surfaces. There are no staff restrooms located nearby.				
Suitability - ES->Cafeteria The cafeteria has no natural lighting, the surfaces are hard creating significant noise issues, and there is limited circulation space in the service lines. The furniture is not age appropriate for the 3rd -5th graders.				
Suitability - ES->Food Service and Prep The equipment is old and some is not operational. The electrical service is not satisfactory to support operational needs. The space is small and crowded.				
Suitability - ES->Outside-->Vehicular Traffic There is a lack of separation between the bus and parent parking areas.				

Project #: 8272

County: Bertie

Site #: 370036002285

Project: Assessments 2016

Region: 80

Site: WINDSOR ELEMENTAR

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability

Rating

Score

Possible
Score

Percent
Score

Suitability - ES->Outside-->Pedestrian Traffic

There is a lack of separation between the pedestrian walking areas and vehicle traffic.

Suitability - ES->Outside-->Parking

There is not enough parking for parents during pick up and drop-off times. Traffic spills over into the adjacent public street.

Suitability - ES->Safety and Security-->Signage & Way Finding

There is a lack of signage on the exterior building to direct visitors to the main entrance. There is lack of signage on the interior of the building to direct visitors to key core spaces such as the gym, media center and offices.

Suitability - ES->Safety and Security-->Controlled Entrances

There is no security vestibule at the school.

Suitability Report - Full

Project #: 8272	County: Bertie	Site #: 370036002818
Project: Assessments 2016	Region: 80	Site: BERTIE MIDDLE
Grade Config: 06-08	Site Type: Middle	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Excel	1.50	1.50	100.00
General Classrooms				
Environment	Good	3.12	3.90	80.00
Size	Excel	9.75	9.75	100.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Good	2.34	2.93	80.00
Self-Contained Special Ed				
Environment	Good	0.44	0.55	80.00
Size	Excel	1.36	1.36	100.00
Location	Good	0.33	0.41	80.00
Storage/Fixed Equip	Good	0.33	0.41	80.00
Instructional Resource Rooms				
Environment	Good	0.66	0.82	80.00
Size	Excel	2.05	2.05	100.00
Location	Good	0.49	0.61	80.00
Storage/Fixed Equip	Good	0.49	0.61	80.00
Science				
Environment	Excel	0.95	0.95	100.00
Size	Excel	2.39	2.39	100.00
Location	Good	0.57	0.72	80.00
Storage/Fixed Equip	Excel	0.72	0.72	100.00
Music				
Environment	Good	0.59	0.74	80.00
Size	Good	1.47	1.84	80.00
Location	Good	0.44	0.55	80.00
Storage/Fixed Equip	Good	0.44	0.55	80.00
Art				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Career Tech Ed				
Environment	Good	1.08	1.35	80.00

Project #: 8272

County: Bertie

Site #: 370036002818

Project: Assessments 2016

Region: 80

Site: BERTIE MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	2.70	3.37	80.00
Location	Good	0.81	1.01	80.00
Storage/Fixed Equip	Good	0.81	1.01	80.00
Computer Labs				
Environment	Good	0.24	0.30	80.00
Size	Good	0.60	0.75	80.00
Location	Good	0.18	0.23	80.00
Storage/Fixed Equip	Good	0.18	0.23	80.00
P.E.				
Environment	Excel	2.40	2.40	100.00
Size	Excel	6.00	6.00	100.00
Location	Good	1.44	1.80	80.00
Storage/Fixed Equip	Fair	1.17	1.80	65.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.74	0.93	80.00
Size	Good	1.86	2.32	80.00
Location	Good	0.56	0.70	80.00
Storage/Fixed Equip	Excel	0.70	0.70	100.00
Restrooms (Student)	Good	0.74	0.93	80.00
Administration	Excel	2.10	2.10	100.00
Counseling	Good	0.34	0.42	80.00
Clinic	Fair	0.22	0.34	65.00
Staff Lounge-WkRm	Good	0.72	0.91	80.00
Cafeteria	Excel	4.00	4.00	100.00
Food Service and Prep	Good	4.57	5.72	80.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Excel	4.00	4.00	100.00
Pedestrian Traffic	Excel	0.43	0.43	100.00
Parking	Good	0.69	0.86	80.00
Athletic Courts and Fields	Good	0.84	1.05	80.00
Safety and Security				
Fencing	Good	0.62	0.78	80.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Excel	0.50	0.50	100.00
Total For Site:		83.19	94.68	87.87

Comments

Project #: 8272

County: Bertie

Site #: 370036002818

Project: Assessments 2016

Region: 80

Site: BERTIE MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability

Rating

Score

Possible
Score

Percent
Score

Suitability - MS

Bertie Middle School is located in rural Bertie County, North Carolina. The school serves grades 6-8 and can accommodate approximately 800 students. Currently BMS has an enrollment of 500 students. All students have daily access to technology through computer labs, media center, and classroom sets of wireless labs. The Media Center houses approximately 10,000 books, 17 desktop computers and 500 chrome books. It also promotes an exciting and involving atmosphere for reading and technology. Exploratory classes such as Spanish, Band,

Suitability - MS->P.E.-->Storage/Fixed Equip

There is a limited amount of storage for supplies and equipment in the gymnasium.

Suitability - MS->Clinic

There is only one student cot in the clinic. The space is small for the size of the student enrollment. There is no natural lighting and the ventilation is not adequate.

Suitability Report - Full

Project #: 8272

County: Bertie

Site #: 370036003149

Project: Assessments 2016

Region: 80

Site: BERTIE EARLY COLLEG

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Poor	1.00	2.00	50.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Poor	1.95	3.90	50.00
Size	Excel	9.75	9.75	100.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Poor	1.46	2.93	50.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Science				
Environment	Fair	0.54	0.83	65.00
Size	Fair	1.35	2.07	65.00
Location	Good	0.50	0.62	80.00
Storage/Fixed Equip	Good	0.50	0.62	80.00
Music				
Environment	Unsat	0.00	0.59	0.00
Size	Unsat	0.00	1.48	0.00
Location	Unsat	0.00	0.45	0.00
Storage/Fixed Equip	Unsat	0.00	0.45	0.00
Art				
Environment	Unsat	0.00	0.67	0.00
Size	Unsat	0.00	1.66	0.00
Location	Unsat	0.00	0.50	0.00
Storage/Fixed Equip	Unsat	0.00	0.50	0.00
Career Tech Ed				
Environment	Good	1.37	1.71	80.00

Project #: 8272

County: Bertie

Site #: 370036003149

Project: Assessments 2016

Region: 80

Site: BERTIE EARLY COLLEGE

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	3.42	4.27	80.00
Location	Good	1.03	1.28	80.00
Storage/Fixed Equip	Good	1.03	1.28	80.00
Computer Labs				
Environment	Good	0.24	0.30	80.00
Size	Fair	0.49	0.75	65.00
Location	Excel	0.23	0.23	100.00
Storage/Fixed Equip	Good	0.18	0.23	80.00
P.E.				
Environment	Fair	1.56	2.40	65.00
Size	Fair	3.90	6.00	65.00
Location	Good	1.44	1.80	80.00
Storage/Fixed Equip	Good	1.44	1.80	80.00
Performing Arts				
Environment	Poor	0.16	0.32	50.00
Size	Fair	0.52	0.80	65.00
Location	Good	0.19	0.24	80.00
Storage/Fixed Equip	Fair	0.16	0.24	65.00
Media Center				
Environment	Fair	0.55	0.84	65.00
Size	Fair	1.37	2.11	65.00
Location	Good	0.51	0.63	80.00
Storage/Fixed Equip	Good	0.51	0.63	80.00
Restrooms (Student)	Poor	0.46	0.91	50.00
Administration	Good	2.09	2.61	80.00
Counseling	Good	0.61	0.76	80.00
Clinic	Unsat	0.00	0.24	0.00
Staff Lounge-WkRm	Fair	0.46	0.71	65.00
Cafeteria	Good	3.20	4.00	80.00
Food Service and Prep	Fair	3.32	5.11	65.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Good	0.80	1.00	80.00
Pedestrian Traffic	Good	0.78	0.98	80.00
Parking	Excel	2.11	2.11	100.00
Athletic Courts and Fields	(N/A)	0.00	0.00	0.00
Safety and Security				
Fencing	Fair	0.55	0.85	65.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Fair	0.33	0.50	65.00
Total For Site:		61.95	90.58	68.40

Comments

Project #: 8272

County: Bertie

Site #: 370036003149

Project: Assessments 2016

Region: 80

Site: BERTIE EARLY COLLEGE

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Bertie Early College High serves students in grades 9 - 13 with a college preparatory program. Students completing the 5 year program often graduate with an AA degree. College courses are offered at the school through an on-line program.				
Suitability - HS->Learning Environment-->Learning Style Variety				
Early college high has been a number of different programs over the years that have resulted in a number of spaces that have been converted to different uses. This results in some variety of spaces though most spaces remain regular classroom space.				
Suitability - HS->Learning Environment-->Interior Environment				
The facility opened in 1964 and little has been done to improve the overall environment.				
Suitability - HS->Learning Environment-->Exterior Environment				
The outdoor space is expansive though most has not been improved. There is a central courtyard that can be used for a variety of learning opportunities.				
Suitability - HS->General Classrooms-->Environment				
General classrooms are dated with little in the way of overall aesthetics.				
Suitability - HS->General Classrooms-->Storage/Fixed Equip				
General classroom have no permanent casework or storage.				
Suitability - HS->Science-->Environment				
Science rooms have natural light and the configuration aligns with the program. They remain dated spaces with little in the way of overall aesthetics.				
Suitability - HS->Science-->Size				
Science rooms meet approximately 70% of the size guideline.				
Suitability - HS->Music-->Environment				
There is no music room.				
Suitability - HS->Music-->Size				
There is no music room.				
Suitability - HS->Music-->Location				
There is no music room.				
Suitability - HS->Music-->Storage/Fixed Equip				
There is no music room.				
Suitability - HS->Art-->Environment				
There is no art room.				
Suitability - HS->Art-->Size				
There is no art room.				
Suitability - HS->Art-->Location				
There is no art room.				
Suitability - HS->Art-->Storage/Fixed Equip				
There is no art room.				
Suitability - HS->Computer Labs-->Size				
The size of the computer labs vary but most meet approximately 75% of the size guideline.				
Suitability - HS->P.E.-->Environment				
The gym provides a reasonable environment. The locker rooms and other support spaces do not.				

Project #: 8272

County: Bertie

Site #: 370036003149

Project: Assessments 2016

Region: 80

Site: BERTIE EARLY COLLEGE

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS->P.E.-->Size The gym meets size guidelines. There is no weight room or wrestling room.				
Suitability - HS->Performing Arts-->Environment Performing arts consists of a small auditorium that is not regularly used. The lack of usage has resulted in a negative environment.				
Suitability - HS->Performing Arts-->Size The auditorium meets approximately 70% of the guideline.				
Suitability - HS->Performing Arts-->Storage/Fixed Equip There is some storage and lighting equipment. There is no seating.				
Suitability - HS->Media Center-->Environment The media center provides natural light but little else in the way of overall aesthetics.				
Suitability - HS->Media Center-->Size The library meets approximately 65% of the size guideline.				
Suitability - HS->Restrooms (Student) Student restrooms are not adequate in number, are not well ventilated, and do not provide urinal partitions.				
Suitability - HS->Counseling Counseling is located in a converted classroom space.				
Suitability - HS->Clinic There is no clinic.				
Suitability - HS->Staff Lounge-WkRm The staff lounge / workroom is adequate in size and well located. There are no staff restrooms.				
Suitability - HS->Food Service and Prep The food service area is small. Deliveries cross between the school and outside areas.				
Suitability - HS->Outside-->Athletic Courts and Fields Students who participate in athletics do so at Bertie High.				
Suitability - HS->Safety and Security-->Fencing Some areas are fenced, most is not.				
Suitability - HS->Safety and Security-->Ease of Supervision Supervision within the main building is reasonable. There are a number of outdoor hiding places.				
Suitability - HS->Safety and Security-->Controlled Entrances There are numerous entrances that are kept locked. Their is not an entry vestibule.				

Suitability Report - Full

Project #: 8272

County: Bertie

Site #: 370036000101

Project: Assessments 2016

Region: 80

Site: BERTIE HIGH SCHOOL

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Excel	5.00	5.00	100.00
Interior Environment	Excel	2.00	2.00	100.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Good	3.12	3.90	80.00
Size	Excel	9.75	9.75	100.00
Location	Excel	2.93	2.93	100.00
Storage/Fixed Equip	Poor	1.46	2.93	50.00
Self-Contained Special Ed				
Environment	Excel	0.53	0.53	100.00
Size	Excel	1.33	1.33	100.00
Location	Excel	0.40	0.40	100.00
Storage/Fixed Equip	Excel	0.40	0.40	100.00
Instructional Resource Rooms				
Environment	Good	0.64	0.80	80.00
Size	Excel	2.00	2.00	100.00
Location	Excel	0.60	0.60	100.00
Storage/Fixed Equip	Poor	0.30	0.60	50.00
Science				
Environment	Good	0.66	0.83	80.00
Size	Excel	2.07	2.07	100.00
Location	Excel	0.62	0.62	100.00
Storage/Fixed Equip	Fair	0.40	0.62	65.00
Music				
Environment	Excel	0.59	0.59	100.00
Size	Excel	1.48	1.48	100.00
Location	Excel	0.45	0.45	100.00
Storage/Fixed Equip	Excel	0.45	0.45	100.00
Art				
Environment	Excel	0.67	0.67	100.00
Size	Good	1.33	1.66	80.00
Location	Excel	0.50	0.50	100.00
Storage/Fixed Equip	Excel	0.50	0.50	100.00
Career Tech Ed				
Environment	Good	1.37	1.71	80.00

Project #: 8272

County: Bertie

Site #: 370036000101

Project: Assessments 2016

Region: 80

Site: BERTIE HIGH SCHOOL

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	4.27	4.27	100.00
Location	Poor	0.64	1.28	50.00
Storage/Fixed Equip	Good	1.03	1.28	80.00
Computer Labs				
Environment	Excel	0.30	0.30	100.00
Size	Fair	0.49	0.75	65.00
Location	Excel	0.23	0.23	100.00
Storage/Fixed Equip	Good	0.18	0.23	80.00
P.E.				
Environment	Excel	2.40	2.40	100.00
Size	Good	4.80	6.00	80.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Good	1.44	1.80	80.00
Performing Arts				
Environment	Excel	0.32	0.32	100.00
Size	Excel	0.80	0.80	100.00
Location	Excel	0.24	0.24	100.00
Storage/Fixed Equip	Excel	0.24	0.24	100.00
Media Center				
Environment	Excel	0.84	0.84	100.00
Size	Excel	2.11	2.11	100.00
Location	Excel	0.63	0.63	100.00
Storage/Fixed Equip	Excel	0.63	0.63	100.00
Restrooms (Student)	Good	0.73	0.91	80.00
Administration	Excel	2.61	2.61	100.00
Counseling	Poor	0.38	0.76	50.00
Clinic	Good	0.19	0.24	80.00
Staff Lounge-WkRm	Good	0.57	0.71	80.00
Cafeteria	Excel	4.00	4.00	100.00
Food Service and Prep	Excel	5.11	5.11	100.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Excel	1.00	1.00	100.00
Pedestrian Traffic	Good	0.78	0.98	80.00
Parking	Excel	2.11	2.11	100.00
Athletic Courts and Fields	Poor	1.38	2.77	50.00
Safety and Security				
Fencing	Good	0.68	0.85	80.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Good	0.40	0.50	80.00
Total For Site:		89.45	100.00	89.45

Comments

Project #: 8272

County: Bertie

Site #: 370036000101

Project: Assessments 2016

Region: 80

Site: BERTIE HIGH SCHOOL

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Bertie County High School is a new (2014) facility built across the street from the old high school. Some athletic and CTE facilities located at the old school remain in use. The new facility houses all other programs with one wing serving as the STEM high school.				
Suitability - HS->Learning Environment-->Exterior Environment				
The exterior space is expansive but is not developed except for parking and traffic lanes.				
Suitability - HS->General Classrooms-->Storage/Fixed Equip				
General classrooms have reasonable technology equipment but storage and casework consists of only one cabinet and minimal shelving.				
Suitability - HS->Instructional Resource Rooms-->Storage/Fixed Equip				
Resource rooms have reasonable technology equipment but storage and casework consists of only one cabinet and minimal shelving.				
Suitability - HS->Science-->Storage/Fixed Equip				
Science rooms in the regular program spaces have good equipment and storage. The science room in the STEM wing lacks equipment in the prep area.				
Suitability - HS->Art				
Bertie County High has an art room but no art program at the present time. This space is assessed as an art room but is currently used for EC resource.				
Suitability - HS->Career Tech Ed-->Environment				
The environment of the CTE spaces in the new building is excellent, the programs in the old building are in dated facilities.				
Suitability - HS->Career Tech Ed-->Location				
Four CTE programs (auto, carpentry, welding, E.M.T.) are located in the old high school building across the street. Students are bussed.				
Suitability - HS->Computer Labs-->Size				
Computer labs meet approximately 70% of the size guideline.				
Suitability - HS->P.E.-->Size				
The physical education space includes an appropriately sized gym and weight room. There is no wrestling room.				
Suitability - HS->Counseling				
The counseling space at Bertie High consists only of two offices. There is no reception or group work area.				
Suitability - HS->Clinic				
The clinic is appropriately sized and located. There is no cot separation.				
Suitability - HS->Outside-->Athletic Courts and Fields				
The new Bertie High has extensive field areas but are not developed. Facilities at the old high school are used for football and other activities. Tennis courts are in disrepair.				

Suitability Report - Full

Project #: 8272	County: Bertie	Site #: xxx2
Project: Assessments 2016	Region: 80	Site: ASKEWVILLE PRESCHO
Grade Config: PK	Site Type: Other Educational	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - Early Childhood				
Learning Environment				
Learning Style Variety	Good	3.29	4.12	80.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Good	1.20	1.50	80.00
Kindergarten				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
ECE				
Environment	Good	3.75	4.69	80.00
Size	Poor	5.86	11.72	50.00
Location	Good	2.81	3.52	80.00
Storage/Fixed Equip	Fair	2.28	3.52	65.00
Self-Contained Special Ed				
Environment	Good	0.38	0.48	80.00
Size	Fair	0.78	1.20	65.00
Location	Good	0.29	0.36	80.00
Storage/Fixed Equip	Fair	0.23	0.36	65.00
Instructional Resource Rooms				
Environment	Poor	0.36	0.72	50.00
Size	Poor	0.90	1.80	50.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Poor	0.27	0.54	50.00
P.E. - Activity				
Environment	Good	1.56	1.95	80.00
Size	Good	3.89	4.87	80.00
Location	Good	1.17	1.46	80.00
Storage/Fixed Equip	Good	1.17	1.46	80.00
Restrooms (Student)	Good	1.36	1.70	80.00
Administration	Fair	2.97	4.58	65.00
Counseling	(N/A)	0.00	0.00	0.00
Clinic	Unsat	0.00	0.78	0.00
Staff Lounge-WkRm	Good	2.40	3.00	80.00
Cafeteria	Good	2.40	3.00	80.00
Food Service and Prep	(N/A)	0.00	0.00	0.00

Project #: 8272

County: Bertie

Site #: xxx2

Project: Assessments 2016

Region: 80

Site: ASKEWVILLE PRESCHO

Grade Config: PK

Site Type: Other Educational

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Good	0.65	0.81	80.00
Play Areas	Good	1.87	2.34	80.00
Safety and Security				
Fencing	Good	0.60	0.75	80.00
Signage & Way Finding	Good	0.08	0.09	80.00
Ease of Supervision	Good	1.60	2.00	80.00
Controlled Entrances	Good	0.40	0.50	80.00
Total For Site:		49.05	69.82	70.25

Comments

Suitability - Early Childhood

Askeville Pre-school is a North Carolina certified pre-school program located in a previous Bertie County Elementary school that had been closed. The program serves 3 and 4-year regular education and special education students encompassing the Windsor and Aulander district areas. The building has 6 classrooms, a cafeteria area with a stage, and a gymnasium. The pre-school curriculum is based on the North Carolina Department of Instruction pre-school program requirements.

Suitability - Early Childhood->Learning Environment-->Interior Environment

The interior walls are primarily concrete block and the floors are VCT tile which makes for poor acoustical qualities throughout the building. There is limited natural lighting in the core spaces and administration areas.

Suitability - Early Childhood->ECE-->Size

The pre-school classrooms meet 56% of the recommended size standard.

Suitability - Early Childhood->ECE-->Storage/Fixed Equip

There is limited casework and storage in the pre-school classrooms. There is a restroom in two of the six pre-school classrooms.

Suitability - Early Childhood->Self-Contained Special Ed-->Size

The self-contained pre-school classroom meets 62% of the recommended size standard.

Suitability - Early Childhood->Self-Contained Special Ed-->Storage/Fixed Equip

There is no restroom in the self-contained pre-school classroom.

Suitability - Early Childhood->Instructional Resource Rooms-->Environment

The instruction resource room is used for physical therapy and academic intervention. The room has no natural lighting, there is not adequate ventilation and the overall aesthetics are poor. There is limited opportunity for spatial configuration to support the instructional program.

Suitability - Early Childhood->Instructional Resource Rooms-->Size

The instructional resource room meets 51% of the recommend size standard.

Suitability - Early Childhood->Instructional Resource Rooms-->Storage/Fixed Equip

The instructional resource room lacks adequate program storage for supplies and equipment.

Suitability - Early Childhood->Administration

The administration areas have no designated reception areas, the office areas are small and crowded and there is no conference room.

Suitability - Early Childhood->Clinic

There is no clinic in the school.

Suitability Report - Full

Project #: 8272	County: Davie	Site #: 370117000485
Project: Assessments 2016	Region: 300	Site: COOLEEMEE ELEMENT
Grade Config: KG-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Excel	5.00	5.00	100.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Excel	1.50	1.50	100.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Excel	12.25	12.25	100.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Good	2.94	3.68	80.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Good	0.83	1.04	80.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Good	0.25	0.31	80.00
ECE				
Environment	Good	0.40	0.50	80.00
Size	Excel	1.25	1.25	100.00
Location	Good	0.30	0.37	80.00
Storage/Fixed Equip	Good	0.30	0.37	80.00
Self-Contained Special Ed				
Environment	Good	0.38	0.48	80.00
Size	Excel	1.20	1.20	100.00
Location	Good	0.29	0.36	80.00
Storage/Fixed Equip	Good	0.29	0.36	80.00
Instructional Resource Rooms				
Environment	Excel	0.72	0.72	100.00
Size	Excel	1.80	1.80	100.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Project #: 8272

County: Davie

Site #: 370117000485

Project: Assessments 2016

Region: 300

Site: COOLEEMEE ELEMENT

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	1.48	1.85	80.00
Location	Good	0.44	0.56	80.00
Storage/Fixed Equip	Good	0.44	0.56	80.00
Art				
Environment	Good	0.37	0.47	80.00
Size	Good	0.94	1.17	80.00
Location	Good	0.28	0.35	80.00
Storage/Fixed Equip	Good	0.28	0.35	80.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Good	0.68	0.85	80.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Good	1.54	1.92	80.00
Size	Excel	4.80	4.80	100.00
Location	Good	1.15	1.44	80.00
Storage/Fixed Equip	Excel	1.44	1.44	100.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Excel	2.44	2.44	100.00
Location	Fair	0.48	0.73	65.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Fair	0.58	0.89	65.00
Administration	Excel	2.56	2.56	100.00
Counseling	Good	0.23	0.29	80.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Excel	5.00	5.00	100.00
Food Service and Prep	Good	4.96	6.20	80.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Excel	0.81	0.81	100.00
Play Areas	Good	1.87	2.34	80.00
Safety and Security				
Fencing	Good	0.60	0.75	80.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Good	0.40	0.50	80.00

Project #: 8272

County: Davie

Site #: 370117000485

Project: Assessments 2016

Region: 300

Site: COOLEEMEE ELEMENT

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		83.65	94.48	88.54

Comments

Suitability - ES

Cooleemee Elementary School is a PK-5 grade facility built in 1950 and was renovated from a high school. There was a new addition built between 2008-2012. The school serves special education students. The school does not have any portable classrooms. Large classrooms allow for flexible configurations.

Suitability - ES->General Classrooms-->Environment

Inviting/stimulating environment. Flexible spaces. The majority of general classrooms are in a suite-style configuration. Walls separate suites into 2-3 rooms each. Each room is open on the end and each suite shares built-in storage space. Some noise carries to connected rooms. There is some natural light.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Built-ins and movable storage present.

Suitability - ES->Kindergarten-->Size

Met 84% of the square footage standard.

Suitability - ES->Kindergarten-->Storage/Fixed Equip

Built-ins and movable storage present.

Suitability - ES->Art-->Size

Met 88% of the standard for square footage.

Suitability - ES->Computer Labs-->Size

Met 88% of the standard for square footage.

Suitability - ES->Computer Labs-->Storage/Fixed Equip

One computer lab uses two power strips to connect one wall of computers.

Suitability - ES->Media Center-->Environment

Inviting/stimulating environment and nice aesthetics. The Media Center is an open space and boarded on three sides by hallways (potential noise issue). There are no windows and no natural lighting.

Suitability - ES->Media Center-->Size

Inviting/stimulating environment and nice aesthetics. The Media Center is an open space and boarded on three sides by hallways (potential noise issue). There are no windows and no natural lighting.

Suitability - ES->Media Center-->Location

The Media Center is an open space and boarded on three sides by hallways (potential noise issue).

Suitability - ES->Media Center-->Storage/Fixed Equip

Most of the storage space and bookcases are movable. There is adequate storage space for their needs.

Suitability - ES->Restrooms (Student)

The boys' restroom across from the computer lab lacks urinal privacy screens. One of the stall doors is fastened too tight and is wearing away at the bottom.

Suitability - ES->Clinic

No in-room restroom/shower or refrigerator. The room is small, but has space for a cot.

Suitability - ES->Safety and Security-->Fencing

No perimeter fencing.

Suitability Report - Full

Project #: 8272	County: Davie	Site #: 370117002516
Project: Assessments 2016	Region: 300	Site: CORNATZER ELEMENT
Grade Config: KG-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Excel	5.00	5.00	100.00
Interior Environment	Excel	2.00	2.00	100.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Good	9.80	12.25	80.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Fair	2.39	3.68	65.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Good	0.83	1.04	80.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Excel	0.31	0.31	100.00
ECE				
Environment	Excel	0.50	0.50	100.00
Size	Good	1.00	1.25	80.00
Location	Good	0.30	0.37	80.00
Storage/Fixed Equip	Good	0.30	0.37	80.00
Self-Contained Special Ed				
Environment	Good	0.38	0.48	80.00
Size	Excel	1.20	1.20	100.00
Location	Good	0.29	0.36	80.00
Storage/Fixed Equip	Good	0.29	0.36	80.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Good	1.44	1.80	80.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	1.48	1.85	80.00
Location	Good	0.44	0.56	80.00
Storage/Fixed Equip	Poor	0.28	0.56	50.00
Art				
Environment	Good	0.37	0.47	80.00
Size	Good	0.94	1.17	80.00
Location	Good	0.28	0.35	80.00
Storage/Fixed Equip	Poor	0.18	0.35	50.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Good	0.68	0.85	80.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Fair	0.17	0.26	65.00
P.E.				
Environment	Excel	1.92	1.92	100.00
Size	Excel	4.80	4.80	100.00
Location	Excel	1.44	1.44	100.00
Storage/Fixed Equip	Good	1.15	1.44	80.00
Performing Arts				
Environment	Unsat	0.00	0.60	0.00
Size	Unsat	0.00	1.51	0.00
Location	Unsat	0.00	0.45	0.00
Storage/Fixed Equip	Unsat	0.00	0.45	0.00
Media Center				
Environment	Excel	0.97	0.97	100.00
Size	Excel	2.44	2.44	100.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Good	0.71	0.89	80.00
Administration	Excel	2.56	2.56	100.00
Counseling	Fair	0.19	0.29	65.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Excel	1.27	1.27	100.00
Cafeteria	Good	4.00	5.00	80.00
Food Service and Prep	Excel	6.20	6.20	100.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Excel	2.00	2.00	100.00
Pedestrian Traffic	Excel	0.97	0.97	100.00
Parking	Excel	0.81	0.81	100.00
Play Areas	Good	1.87	2.34	80.00
Safety and Security				
Fencing	Good	0.60	0.75	80.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Excel	3.00	3.00	100.00
Controlled Entrances	Fair	0.33	0.50	65.00

Project #: 8272

County: Davie

Site #: 370117002516

Project: Assessments 2016

Region: 300

Site: CORNATZER ELEMENT

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		82.06	97.50	84.17

Comments

Suitability - ES

This elementary school has pre-k through 5th grade, two self-contained classrooms, with one for severe and profound needs. There is a gym with a stage and three computer labs. Art and music instruction share a regular classroom.

Suitability - ES->Learning Environment-->Exterior Environment

There was a small area with several picnic tables near playground.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

A number of classrooms have limited fixed storage/casework.

Suitability - ES->ECE-->Location

Pre-k classroom is a separate building.

Suitability - ES->Self-Contained Special Ed

There are two self-contained special education classrooms, one of which serves severe and profound needs.

Suitability - ES->Self-Contained Special Ed-->Storage/Fixed Equip

The severe and profound room has a refrigerator, sink, microwave and counter space.

Suitability - ES->Music

Music and Art instruction use the same classroom on alternating days.

Suitability - ES->Music-->Storage/Fixed Equip

This is a regular classroom, with no acoustical treatments, no special equipment, and limited storage shared with art instruction.

Suitability - ES->Art

Music and Art instruction use the same classroom on alternating days.

Suitability - ES->Art-->Storage/Fixed Equip

There are two sinks but no clay traps, no display areas, limited storage space shared with music, and a kiln in a storage room with no direct vent.

Suitability - ES->Computer Labs

There are three computer labs.

Suitability - ES->Computer Labs-->Storage/Fixed Equip

One lab has little storage space, and another has a door with a window to the exterior of school.

Suitability - ES->Performing Arts

There is a stage in the gym, but it is walled off and used for YMCA after school program.

Suitability - ES->Performing Arts-->Environment

There is a stage in the gym, but it is walled off and used for YMCA after school program.

Suitability - ES->Performing Arts-->Size

There is a stage in the gym, but it is walled off and used for YMCA after school program.

Suitability - ES->Performing Arts-->Location

There is a stage in the gym, but it is walled off and used for YMCA after school program.

Suitability - ES->Performing Arts-->Storage/Fixed Equip

There is a stage in the gym, but it is walled off and used for YMCA after school program.

Project #: 8272

County: Davie

Site #: 370117002516

Project: Assessments 2016

Region: 300

Site: CORNATZER ELEMENT

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Counseling No adjacent waiting area. Records storage is across the hall in main office suite.				
Suitability - ES->Clinic There is only one cot adjacent to nurse station desk. There is limited visual supervision from outside the room.				
Suitability - ES->Safety and Security-->Signage & Way Finding Drug and weapons free are signs are visible.				
Suitability - ES->Safety and Security-->Controlled Entrances The front entry is unlocked, and there is no secure vestibule.				

Suitability Report - Full

Project #: 8272	County: Davie	Site #: 370117000487
Project: Assessments 2016	Region: 300	Site: MOCKSVILLE ELEMENT
Grade Config: KG-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Excel	5.00	5.00	100.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Excel	1.50	1.50	100.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Good	9.80	12.25	80.00
Location	Fair	2.39	3.68	65.00
Storage/Fixed Equip	Good	2.94	3.68	80.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Excel	1.04	1.04	100.00
Location	Good	0.25	0.31	80.00
Storage/Fixed Equip	Fair	0.20	0.31	65.00
ECE				
Environment	Good	0.40	0.50	80.00
Size	Good	1.00	1.25	80.00
Location	Good	0.30	0.37	80.00
Storage/Fixed Equip	Good	0.30	0.37	80.00
Self-Contained Special Ed				
Environment	Good	0.38	0.48	80.00
Size	Excel	1.20	1.20	100.00
Location	Fair	0.23	0.36	65.00
Storage/Fixed Equip	Good	0.29	0.36	80.00
Instructional Resource Rooms				
Environment	Fair	0.47	0.72	65.00
Size	Good	1.44	1.80	80.00
Location	Excel	0.54	0.54	100.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	1.48	1.85	80.00
Location	Good	0.44	0.56	80.00
Storage/Fixed Equip	Excel	0.56	0.56	100.00
Art				
Environment	Excel	0.47	0.47	100.00
Size	Excel	1.17	1.17	100.00
Location	Excel	0.35	0.35	100.00
Storage/Fixed Equip	Excel	0.35	0.35	100.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Excel	0.85	0.85	100.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Good	1.54	1.92	80.00
Size	Excel	4.80	4.80	100.00
Location	Good	1.15	1.44	80.00
Storage/Fixed Equip	Fair	0.94	1.44	65.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Excel	2.44	2.44	100.00
Location	Fair	0.48	0.73	65.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Excel	0.89	0.89	100.00
Administration	Good	2.05	2.56	80.00
Counseling	Fair	0.19	0.29	65.00
Clinic	Good	0.47	0.58	80.00
Staff Lounge-WkRm	Excel	1.27	1.27	100.00
Cafeteria	Fair	3.25	5.00	65.00
Food Service and Prep	Good	4.96	6.20	80.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Excel	0.81	0.81	100.00
Play Areas	Good	1.87	2.34	80.00
Safety and Security				
Fencing	Good	0.60	0.75	80.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Good	0.40	0.50	80.00

Project #: 8272

County: Davie

Site #: 370117000487

Project: Assessments 2016

Region: 300

Site: MOCKSVILLE ELEMENT

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		78.53	94.48	83.12

Comments

Suitability - ES

Mocksville Elementary School is a PK-5 grade facility built in 1970 and is the largest elementary school in the county. The school has two classrooms to serve special education students. Large classrooms allow for flexible configurations. The school has three portable classrooms, one of which is used as a 3rd grade general classroom.

Suitability - ES->General Classrooms-->Environment

Inviting/stimulating environment. Flexible spaces. The majority of general classrooms are in a suite-style configuration. Walls separate suites into 2-3 rooms each. Each room is open on the end and each suite shares built-in storage space. Some noise carries to connected rooms. There is a limited amount of natural light in some of the exterior classrooms (small windows). There are 3 rooms without any windows or natural light (two 2nd grade rooms and one 3rd grade room).

Suitability - ES->General Classrooms-->Size

One 3rd grade classroom is located in a portable.

Suitability - ES->General Classrooms-->Location

One 3rd grade class is located in a portable classroom.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Built-ins and movable storage present.

Suitability - ES->Kindergarten-->Storage/Fixed Equip

Built-ins and movable storage present. Some storage is kept in the in-class bathrooms.

Suitability - ES->Self-Contained Special Ed-->Location

One class is located near the general classrooms, and the second one is located across from the gym.

Suitability - ES->Instructional Resource Rooms-->Environment

There is no/limited natural light.

Suitability - ES->Instructional Resource Rooms-->Size

All resource spaces met the square footage standard except for one, which met 77% of the square footage standard.

Suitability - ES->Music-->Size

Occupational therapist uses the space in the Music room.

Suitability - ES->Art-->Environment

Some natural light is present.

Suitability - ES->P.E.-->Location

The gym is isolated from general classrooms. It is located next to the Guidance room and across from a SPED room.

Suitability - ES->P.E.-->Storage/Fixed Equip

Several different types of fixed equipment are present. The sound system is broken. There is some natural light.

Suitability - ES->Media Center-->Environment

Inviting/stimulating environment and nice aesthetics. The Media Center is an open space and boarded on two sides by hallways (potential noise issue). There are no windows and no natural lighting.

Suitability - ES->Media Center-->Location

The Media Center is an open space and boarded on two sides by hallways (potential noise issue).

Suitability - ES->Media Center-->Storage/Fixed Equip

Most of the storage space and bookcases are movable. There is adequate storage space for their needs.

Project #: 8272

County: Davie

Site #: 370117000487

Project: Assessments 2016

Region: 300

Site: MOCKSVILLE ELEMENT

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Administration				
The conference room is located next to the cafeteria and can be noisy. The social worker has an open space within the reception area.				
Suitability - ES->Counseling				
The behavioral specialist is located in a portable. Guidance room is located away from administration and next to the gym (inviting space and enough room to house student records). Occupational therapist uses the space in the Music room.				
Suitability - ES->Clinic				
Does not have a shower or refrigerator. Clinic is a small space but fits a cot.				
Suitability - ES->Cafeteria				
Met 74% of the sq. footage standard. The space is at capacity during lunch times.				
Suitability - ES->Food Service and Prep				
Kitchen has one broken warmer oven. Kitchen delivery area is across from the bus parking lot.				
Suitability - ES->Outside-->Vehicular Traffic				
Kitchen delivery area is across from the bus parking lot.				
Suitability - ES->Outside-->Play Areas				
PK/K play area met the play area standard and had a variety of equipment in a fenced area. The 1-5 play area has limited playground equipment, however, the school utilizes the public playground for special events/occasions.				
Suitability - ES->Safety and Security-->Ease of Supervision				
A few blind spots within the interior of the building and hallways.				

Suitability Report - Full

Project #: 8272	County: Davie	Site #: 370117000489
Project: Assessments 2016	Region: 300	Site: PINEBROOK ELEMENTA
Grade Config: KG-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Excel	5.00	5.00	100.00
Interior Environment	Excel	2.00	2.00	100.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Excel	12.25	12.25	100.00
Location	Excel	3.68	3.68	100.00
Storage/Fixed Equip	Good	2.94	3.68	80.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Excel	1.04	1.04	100.00
Location	Good	0.25	0.31	80.00
Storage/Fixed Equip	Good	0.25	0.31	80.00
ECE				
Environment	Good	0.40	0.50	80.00
Size	Good	1.00	1.25	80.00
Location	Good	0.30	0.37	80.00
Storage/Fixed Equip	Good	0.30	0.37	80.00
Self-Contained Special Ed				
Environment	Good	0.38	0.48	80.00
Size	Excel	1.20	1.20	100.00
Location	Good	0.29	0.36	80.00
Storage/Fixed Equip	Good	0.29	0.36	80.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Excel	1.80	1.80	100.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Project #: 8272

County: Davie

Site #: 370117000489

Project: Assessments 2016

Region: 300

Site: PINEBROOK ELEMENTA

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	1.85	1.85	100.00
Location	Good	0.44	0.56	80.00
Storage/Fixed Equip	Good	0.44	0.56	80.00
Art				
Environment	Good	0.37	0.47	80.00
Size	Excel	1.17	1.17	100.00
Location	Good	0.28	0.35	80.00
Storage/Fixed Equip	Fair	0.23	0.35	65.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Excel	0.85	0.85	100.00
Location	Excel	0.26	0.26	100.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Good	1.54	1.92	80.00
Size	Excel	4.80	4.80	100.00
Location	Fair	0.94	1.44	65.00
Storage/Fixed Equip	Fair	0.94	1.44	65.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Excel	2.44	2.44	100.00
Location	Fair	0.48	0.73	65.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Good	0.71	0.89	80.00
Administration	Fair	1.66	2.56	65.00
Counseling	Good	0.23	0.29	80.00
Clinic	Good	0.47	0.58	80.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Excel	5.00	5.00	100.00
Food Service and Prep	Fair	4.03	6.20	65.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Excel	0.97	0.97	100.00
Parking	Good	0.65	0.81	80.00
Play Areas	Good	1.87	2.34	80.00
Safety and Security				
Fencing	Unsat	0.00	0.75	0.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Excel	0.50	0.50	100.00

Project #: 8272

County: Davie

Site #: 370117000489

Project: Assessments 2016

Region: 300

Site: PINEBROOK ELEMENTA

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		82.12	94.48	86.92

Comments

Suitability - ES

Pinebrook Elementary School is a PK-5 grade facility built in 1969. The school has one classroom to serve special education students. The school does not have any portable classrooms. Large classrooms allow for flexible configurations.

Suitability - ES->Learning Environment-->Interior Environment

Limited natural light in the suite style general classroom spaces. Open layout may pose issues with noise from other classrooms (none observed; noted under General Classrooms). Water leak in ceiling in the hallway near the lunch room.

Suitability - ES->General Classrooms-->Environment

Inviting/stimulating environment. Flexible spaces. The majority of general classrooms are in a suite-style configuration. Walls were built to separate suites into three rooms each. Each room is open on the end and each suite shares built-in storage space. Some noise carries to other classrooms, but no major noise or distractions observed. There is a limited amount of natural light in the suite style rooms (most have a small window in the fire exit door).

Suitability - ES->General Classrooms-->Storage/Fixed Equip

The middle suite style rooms have only movable storage space and share built-in storage. Built-in storage throughout.

Suitability - ES->Kindergarten-->Environment

Inviting/stimulating environment. Flexible spaces.

Suitability - ES->Kindergarten-->Storage/Fixed Equip

Built-ins and movable storage. Some supplies stored in bathrooms on movable carts.

Suitability - ES->Music-->Environment

No windows/natural light, but lighting in classroom is good. Inviting and stimulating environment.

Suitability - ES->Music-->Location

Located next to 3rd and 4th grade classrooms and across from media center.

Suitability - ES->Music-->Storage/Fixed Equip

Built-ins and removable storage.

Suitability - ES->Art-->Environment

Inviting and stimulating environment. Good aesthetics.

Suitability - ES->Art-->Storage/Fixed Equip

Built-ins and removable storage. Lacks built-in storage space for supplies (use of carts). 1 of 3 sinks has a clay trap.

Suitability - ES->Computer Labs-->Environment

No windows/natural lighting but adequate indoor lighting. Inviting environment.

Suitability - ES->Computer Labs-->Storage/Fixed Equip

The bigger lab (across from the office) houses storage space for additional folding chairs and equipment in the back of the classroom.

Suitability - ES->P.E.-->Location

Noise from the gym carries to nearby classrooms.

Suitability - ES->P.E.-->Storage/Fixed Equip

Inadequate bleacher space for seating during events (students sit on the floor).

Project #: 8272

County: Davie

Site #: 370117000489

Project: Assessments 2016

Region: 300

Site: PINEBROOK ELEMENTA

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Media Center-->Environment Limited natural light due to its central location. Sounds travels in the large space. The Media Center is an open space and is bordered by hallways on two sides. Inviting and stimulating environment.				
Suitability - ES->Media Center-->Location Sounds travels in the large space. The Media Center is an open space and is bordered by hallways on two sides. The Music class is located across the hall near the 5th grade wing.				
Suitability - ES->Media Center-->Storage/Fixed Equip Majority of bookcases are movable and not permanent. Plenty of storage space in Media Center office area.				
Suitability - ES->Restrooms (Student) Limited/no handicap access.				
Suitability - ES->Administration Needs more student records storage space. Secondary shelving in records room is inadequate/hazardous.				
Suitability - ES->Clinic Meets all standards except for a shower space.				
Suitability - ES->Cafeteria Large space. Cracked/Broken tiles on the floor (trip hazard).				
Suitability - ES->Food Service and Prep Ice machine does not work (no ice; reoccurring issue). Cooling system insufficient in the summer (hot).				
Suitability - ES->Safety and Security-->Fencing No fencing.				
Suitability - ES->Safety and Security-->Ease of Supervision Reported there are a few minor blind spots (end of tables in cafeteria).				

Suitability Report - Full

Project #: 8272	County: Davie	Site #: 370117000490
Project: Assessments 2016	Region: 300	Site: SHADY GROVE ELEMEN
Grade Config: KG-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Fair	7.96	12.25	65.00
Location	Excel	3.68	3.68	100.00
Storage/Fixed Equip	Fair	2.39	3.68	65.00
Kindergarten				
Environment	Good	0.33	0.42	80.00
Size	Good	0.83	1.04	80.00
Location	Good	0.25	0.31	80.00
Storage/Fixed Equip	Good	0.25	0.31	80.00
ECE				
Environment	Good	0.40	0.50	80.00
Size	Fair	0.81	1.25	65.00
Location	Fair	0.24	0.37	65.00
Storage/Fixed Equip	Good	0.30	0.37	80.00
Self-Contained Special Ed				
Environment	Good	0.38	0.48	80.00
Size	Good	0.96	1.20	80.00
Location	Good	0.29	0.36	80.00
Storage/Fixed Equip	Good	0.29	0.36	80.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Good	1.44	1.80	80.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Poor	0.37	0.74	50.00

Project #: 8272

County: Davie

Site #: 370117000490

Project: Assessments 2016

Region: 300

Site: SHADY GROVE ELEMEN

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	1.48	1.85	80.00
Location	Excel	0.56	0.56	100.00
Storage/Fixed Equip	Fair	0.36	0.56	65.00
Art				
Environment	Fair	0.30	0.47	65.00
Size	Good	0.94	1.17	80.00
Location	Good	0.28	0.35	80.00
Storage/Fixed Equip	Fair	0.23	0.35	65.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Fair	0.55	0.85	65.00
Location	Excel	0.26	0.26	100.00
Storage/Fixed Equip	Fair	0.17	0.26	65.00
P.E.				
Environment	Fair	1.25	1.92	65.00
Size	Excel	4.80	4.80	100.00
Location	Excel	1.44	1.44	100.00
Storage/Fixed Equip	Fair	0.94	1.44	65.00
Performing Arts				
Environment	Unsat	0.00	0.60	0.00
Size	Unsat	0.00	1.51	0.00
Location	Unsat	0.00	0.45	0.00
Storage/Fixed Equip	Unsat	0.00	0.45	0.00
Media Center				
Environment	Excel	0.97	0.97	100.00
Size	Good	1.95	2.44	80.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Excel	0.73	0.73	100.00
Restrooms (Student)	Good	0.71	0.89	80.00
Administration	Good	2.05	2.56	80.00
Counseling	Fair	0.19	0.29	65.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Good	4.00	5.00	80.00
Food Service and Prep	Good	4.96	6.20	80.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Good	0.65	0.81	80.00
Play Areas	Good	1.87	2.34	80.00
Safety and Security				
Fencing	Good	0.60	0.75	80.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Fair	0.33	0.50	65.00

Project #: 8272

County: Davie

Site #: 370117000490

Project: Assessments 2016

Region: 300

Site: SHADY GROVE ELEMEN

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		74.13	97.50	76.03

Comments

Suitability - ES

This is a Pre-K through 5th grade school, with one self-contained classroom. The older portion of the school was designed as open classroom concept, now with permanent partitions. It has a gym, cafeteria, 2 portables, tennis courts, a sports field, and three playgrounds (age-specific).

Suitability - ES->Learning Environment-->Learning Style Variety

Older sections classrooms were designed for an open-space instructional model, and are now in suites of three classrooms. Restrooms are located in the two outside classrooms, therefore, students from middle rooms must enter outside rooms to access restrooms.

Suitability - ES->General Classrooms-->Size

Grades 1, 2, 4 and 5 meet size standards, while 3rd grade rooms are slightly under sized.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Some classrooms in triple suites have inadequate storage space.

Suitability - ES->Kindergarten-->Size

Two kindergarten rooms are slightly undersized.

Suitability - ES->ECE-->Size

The pre-k classroom suite is below the size standard.

Suitability - ES->ECE-->Location

Pre-k classroom suite is in a separate building adjacent to the main school building.

Suitability - ES->Music-->Environment

Music is held in a shared regular classroom (taught 3 days a week).

Suitability - ES->Music-->Storage/Fixed Equip

There is limited storage space, no acoustical treatments, and low ceilings.

Suitability - ES->Art-->Environment

Art instruction is held in a regular classroom.

Suitability - ES->Art-->Storage/Fixed Equip

A kiln is located in the front corner of the room, with no ventilation. There is only one sink with no clay traps.

Suitability - ES->Computer Labs-->Size

The two computer labs are below the size guideline.

Suitability - ES->Computer Labs-->Storage/Fixed Equip

Grade 3-5 computer lab has no storage space, and k-2 lab is housed in an "open space" room.

Suitability - ES->P.E.-->Environment

Old wood squares flooring is buckling in places.

Suitability - ES->P.E.-->Storage/Fixed Equip

Not enough storage space for existing equipment. Coaches office & their bathroom/shower are used for equipment storage.

Suitability - ES->Performing Arts

There is no performing arts space in the school.

Suitability - ES->Performing Arts-->Environment

There is no performing arts space in the school.

Project #: 8272

County: Davie

Site #: 370117000490

Project: Assessments 2016

Region: 300

Site: SHADY GROVE ELEMEN

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Performing Arts-->Size There is no performing arts space in the school.				
Suitability - ES->Performing Arts-->Location There is no performing arts space in the school.				
Suitability - ES->Performing Arts-->Storage/Fixed Equip There is no performing arts space in the school.				
Suitability - ES->Counseling There is no waiting or reception area for the Counseling office as it is located in a general classroom, School Psychologist uses a small office in another area of the school. Both are away from secure records storage.				
Suitability - ES->Clinic Only one cot with no separation from nurse desk.				
Suitability - ES->Cafeteria There is no storage space for tables and chairs. When not in use, they are moved to the perimeter of the cafeteria.				
Suitability - ES->Safety and Security-->Signage & Way Finding Although all signs were noted by the principal, only two were observed by assessor (Weapons free & Drug free area).				
Suitability - ES->Safety and Security-->Controlled Entrances All visitors must enter into the main office and are visible to the front desk. However, front entry door and secondary door to the school proper were not locked.				

Suitability Report - Full

Project #: 8272	County: Davie	Site #: 370117000491
Project: Assessments 2016	Region: 300	Site: WILLIAM R DAVIE ELEME
Grade Config: KG-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Excel	5.00	5.00	100.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Excel	1.50	1.50	100.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Fair	7.96	12.25	65.00
Location	Excel	3.68	3.68	100.00
Storage/Fixed Equip	Fair	2.39	3.68	65.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Good	0.83	1.04	80.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Good	0.25	0.31	80.00
ECE				
Environment	Excel	0.50	0.50	100.00
Size	Excel	1.25	1.25	100.00
Location	Good	0.30	0.37	80.00
Storage/Fixed Equip	Good	0.30	0.37	80.00
Self-Contained Special Ed				
Environment	Good	0.38	0.48	80.00
Size	Good	0.96	1.20	80.00
Location	Excel	0.36	0.36	100.00
Storage/Fixed Equip	Good	0.29	0.36	80.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Excel	1.80	1.80	100.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Fair	0.48	0.74	65.00

Project #: 8272

County: Davie

Site #: 370117000491

Project: Assessments 2016

Region: 300

Site: WILLIAM R DAVIE ELEME

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	1.48	1.85	80.00
Location	Good	0.44	0.56	80.00
Storage/Fixed Equip	Fair	0.36	0.56	65.00
Art				
Environment	Poor	0.23	0.47	50.00
Size	Fair	0.76	1.17	65.00
Location	Good	0.28	0.35	80.00
Storage/Fixed Equip	Fair	0.23	0.35	65.00
Computer Labs				
Environment	Excel	0.34	0.34	100.00
Size	Good	0.68	0.85	80.00
Location	Fair	0.17	0.26	65.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Fair	1.25	1.92	65.00
Size	Excel	4.80	4.80	100.00
Location	Excel	1.44	1.44	100.00
Storage/Fixed Equip	Good	1.15	1.44	80.00
Performing Arts				
Environment	Unsat	0.00	0.60	0.00
Size	Unsat	0.00	1.51	0.00
Location	Unsat	0.00	0.45	0.00
Storage/Fixed Equip	Unsat	0.00	0.45	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Excel	2.44	2.44	100.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Good	0.71	0.89	80.00
Administration	Excel	2.56	2.56	100.00
Counseling	Fair	0.19	0.29	65.00
Clinic	Poor	0.29	0.58	50.00
Staff Lounge-WkRm	Excel	1.27	1.27	100.00
Cafeteria	Good	4.00	5.00	80.00
Food Service and Prep	Good	4.96	6.20	80.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Excel	0.81	0.81	100.00
Play Areas	Good	1.87	2.34	80.00
Safety and Security				
Fencing	Fair	0.49	0.75	65.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Good	0.40	0.50	80.00

Project #: 8272

County: Davie

Site #: 370117000491

Project: Assessments 2016

Region: 300

Site: WILLIAM R DAVIE ELEME

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		77.36	97.50	79.35

Comments

Suitability - ES

This school serves students Pre-k through 5th grade, with two self-contained special education classrooms. It has a gym, cafeteria, two playgrounds and a sports field.

Suitability - ES->Learning Environment-->Interior Environment

Several older classrooms are in 3-room suites originally designed as part of an "open room" concept. Middle rooms have potential distractions from noise, and outside rooms have bathroom traffic.

Suitability - ES->General Classrooms-->Size

A number of classrooms do not meet the size guideline.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Some classrooms need additional storage, and all classrooms have only two student computer stations.

Suitability - ES->ECE-->Storage/Fixed Equip

There is no access to a washer & dryer.

Suitability - ES->Self-Contained Special Ed-->Storage/Fixed Equip

Restrooms do not have a shower.

Suitability - ES->Music

Music meets is in a regular classroom 2 days per week, and shares the space with AIG instruction.

Suitability - ES->Music-->Environment

There is a wall partition between the music room and the art room that may allow noise transfer.

Suitability - ES->Music-->Storage/Fixed Equip

There is limited storage space for musical equipment and materials, low ceilings, and no acoustical treatments. There is access to water fountain in adjacent hallway.

Suitability - ES->Art

Art meets in a regular classroom 2 days a week and shares the space with Guidance office needs.

Suitability - ES->Art-->Environment

There is a wall partition between the art room and the music room that may allow noise.

Suitability - ES->Art-->Size

The art room is undersized given the guideline.

Suitability - ES->Art-->Storage/Fixed Equip

There is a kiln in the room with no vent and no separation from other activities.

Suitability - ES->Computer Labs-->Location

One lab is on an exterior wall with a door (with window) to outside.

Suitability - ES->P.E.-->Environment

Floor is linoleum tile, adding to the noise factor.

Suitability - ES->P.E.-->Storage/Fixed Equip

There are no wall safety pads,.

Suitability - ES->Performing Arts

There is no performing arts space in the school.

Suitability - ES->Performing Arts-->Environment

There is no performing arts space in the school.

Project #: 8272

County: Davie

Site #: 370117000491

Project: Assessments 2016

Region: 300

Site: WILLIAM R DAVIE ELEME

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Performing Arts-->Size There is no performing arts space in the school.				
Suitability - ES->Performing Arts-->Location There is no performing arts space in the school.				
Suitability - ES->Performing Arts-->Storage/Fixed Equip There is no performing arts space in the school.				
Suitability - ES->Counseling There is no waiting area adjacent to the counselor office.				
Suitability - ES->Clinic There is one cot next to nurse desk, and no line of sight supervision.				
Suitability - ES->Cafeteria No storage area for tables and chairs.				
Suitability - ES->Safety and Security-->Fencing Safety fencing around AC units in outside learning areas is incomplete. Lacks fencing around back perimeter of sports field.				
Suitability - ES->Safety and Security-->Signage & Way Finding Only tobacco free and drug free signs are visible.				
Suitability - ES->Safety and Security-->Controlled Entrances There is interior controlled access, but front entry door is kept unlocked.				

Suitability Report - Full

Project #: 8272	County: Davie	Site #: 370117002065
Project: Assessments 2016	Region: 300	Site: NORTH DAVIE MIDDLE
Grade Config: 06-08	Site Type: Middle	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Fair	2.54	3.90	65.00
Size	Fair	6.34	9.75	65.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Good	2.34	2.93	80.00
Self-Contained Special Ed				
Environment	Good	0.44	0.55	80.00
Size	Good	1.09	1.36	80.00
Location	Good	0.33	0.41	80.00
Storage/Fixed Equip	Good	0.33	0.41	80.00
Instructional Resource Rooms				
Environment	Good	0.66	0.82	80.00
Size	Good	1.64	2.05	80.00
Location	Good	0.49	0.61	80.00
Storage/Fixed Equip	Good	0.49	0.61	80.00
Science				
Environment	Good	0.76	0.95	80.00
Size	Good	1.91	2.39	80.00
Location	Excel	0.72	0.72	100.00
Storage/Fixed Equip	Fair	0.47	0.72	65.00
Music				
Environment	Good	0.59	0.74	80.00
Size	Good	1.47	1.84	80.00
Location	Excel	0.55	0.55	100.00
Storage/Fixed Equip	Fair	0.36	0.55	65.00
Art				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Career Tech Ed				
Environment	Fair	0.88	1.35	65.00

Project #: 8272

County: Davie

Site #: 370117002065

Project: Assessments 2016

Region: 300

Site: NORTH DAVIE MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	2.70	3.37	80.00
Location	Excel	1.01	1.01	100.00
Storage/Fixed Equip	Excel	1.01	1.01	100.00
Computer Labs				
Environment	Good	0.24	0.30	80.00
Size	Fair	0.49	0.75	65.00
Location	Excel	0.23	0.23	100.00
Storage/Fixed Equip	Excel	0.23	0.23	100.00
P.E.				
Environment	Good	1.92	2.40	80.00
Size	Good	4.80	6.00	80.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Excel	1.80	1.80	100.00
Performing Arts				
Environment	Good	0.33	0.42	80.00
Size	Good	0.84	1.05	80.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Fair	0.20	0.31	65.00
Media Center				
Environment	Excel	0.93	0.93	100.00
Size	Good	1.86	2.32	80.00
Location	Excel	0.70	0.70	100.00
Storage/Fixed Equip	Excel	0.70	0.70	100.00
Restrooms (Student)	Good	0.74	0.93	80.00
Administration	Excel	2.10	2.10	100.00
Counseling	Excel	0.42	0.42	100.00
Clinic	Excel	0.34	0.34	100.00
Staff Lounge-WkRm	Good	0.72	0.91	80.00
Cafeteria	Excel	4.00	4.00	100.00
Food Service and Prep	Excel	5.72	5.72	100.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Fair	2.60	4.00	65.00
Pedestrian Traffic	Good	0.35	0.43	80.00
Parking	Excel	0.86	0.86	100.00
Athletic Courts and Fields	Good	0.84	1.05	80.00
Safety and Security				
Fencing	Excel	0.78	0.78	100.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Good	0.40	0.50	80.00
Total For Site:		78.86	96.78	81.49

Comments

Project #: 8272

County: Davie

Site #: 370117002065

Project: Assessments 2016

Region: 300

Site: NORTH DAVIE MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
North Davie Middle School is a 6-8 grade facility built in 1980. The school has one classroom to serve special education students. The school does not have any portables.				
Suitability - MS->Learning Environment-->Interior Environment				
Limited aesthetics and flexibility in some classrooms (far interior locations due to smaller size). Limited/no natural light to interior rooms as well. Cracks in floor tile in the hallway are present. There is a water leak by the corridor addition by the gym. Sound tends to carry within the narrow side corridors.				
Suitability - MS->General Classrooms-->Environment				
Several general classrooms are located on the interior of the building and lack windows/natural lighting. Sound can carry in the narrow side corridors. Flexible classroom space and good aesthetics.				
Suitability - MS->General Classrooms-->Size				
Several of the interior general classrooms that lack windows/natural lighting are smaller than the connected classrooms. These rooms average meeting 76% of the square footage standard.				
Suitability - MS->Science-->Storage/Fixed Equip				
The 6th grade science room sink does not drain properly. Limited fixed equipment and no visible safety equipment.				
Suitability - MS->Music-->Storage/Fixed Equip				
Lacks adequate storage for band equipment. There is a water leak by the exit door that has damaged the carpeting.				
Suitability - MS->Art				
There is an Art class facility, but it is not currently in use (intended to be used again in the near future). The room is equipped with a kiln/ventilation, a sink (no clay trap), good natural lighting, and meets the standard for square footage.				
Suitability - MS->Career Tech Ed-->Environment				
Limited natural light but good lighting. Limited aesthetics. Sounds tends to echo within the room.				
Suitability - MS->Computer Labs-->Size				
Each grade has its own computer lab. The 7th and 8th grade labs met 88% of the square footage standard. The 6th grade lab is smaller, located in a constructed part of the media center, and met 54% of the square footage standard.				
Suitability - MS->P.E.-->Environment				
Water leak by the double doors in the extended corridor.				
Suitability - MS->Performing Arts-->Storage/Fixed Equip				
Lacks adequate storage for theater backgrounds/props.				
Suitability - MS->Restrooms (Student)				
The 7th grade boys bathrooms lacks a urinal privacy divider.				
Suitability - MS->Clinic				
Lacks a shower in the restroom, but all other criteria met.				
Suitability - MS->Outside-->Vehicular Traffic				
Good separation between car riders and buses. Delivery area can block bus routing at times when deliveries arrive during pick-up and drop-off times.				
Suitability - MS->Outside-->Pedestrian Traffic				
Reported that class changes inside the building can be congested due to narrow hallways (enrollment is down from recent years, but congestion remains).				
Suitability - MS->Safety and Security-->Ease of Supervision				
A few blind spots in the gym (camera system).				

Suitability Report - Full

Project #: 8272	County: Davie	Site #: 370117002066
Project: Assessments 2016	Region: 300	Site: SOUTH DAVIE MIDDLE
Grade Config: 06-08	Site Type: Middle	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Fair	2.54	3.90	65.00
Size	Fair	6.34	9.75	65.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Good	2.34	2.93	80.00
Self-Contained Special Ed				
Environment	Fair	0.35	0.55	65.00
Size	Good	1.09	1.36	80.00
Location	Good	0.33	0.41	80.00
Storage/Fixed Equip	Good	0.33	0.41	80.00
Instructional Resource Rooms				
Environment	Unsat	0.00	0.82	0.00
Size	Good	1.64	2.05	80.00
Location	Fair	0.40	0.61	65.00
Storage/Fixed Equip	Good	0.49	0.61	80.00
Science				
Environment	Good	0.76	0.95	80.00
Size	Good	1.91	2.39	80.00
Location	Good	0.57	0.72	80.00
Storage/Fixed Equip	Fair	0.47	0.72	65.00
Music				
Environment	Good	0.59	0.74	80.00
Size	Good	1.47	1.84	80.00
Location	Excel	0.55	0.55	100.00
Storage/Fixed Equip	Good	0.44	0.55	80.00
Art				
Environment	Excel	0.65	0.65	100.00
Size	Good	1.29	1.61	80.00
Location	Excel	0.48	0.48	100.00
Storage/Fixed Equip	Good	0.39	0.48	80.00
Career Tech Ed				
Environment	Good	1.08	1.35	80.00

Project #: 8272

County: Davie

Site #: 370117002066

Project: Assessments 2016

Region: 300

Site: SOUTH DAVIE MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	3.37	3.37	100.00
Location	Excel	1.01	1.01	100.00
Storage/Fixed Equip	Good	0.81	1.01	80.00
Computer Labs				
Environment	Good	0.24	0.30	80.00
Size	Fair	0.49	0.75	65.00
Location	Excel	0.23	0.23	100.00
Storage/Fixed Equip	Excel	0.23	0.23	100.00
P.E.				
Environment	Good	1.92	2.40	80.00
Size	Good	4.80	6.00	80.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Excel	1.80	1.80	100.00
Performing Arts				
Environment	Good	0.33	0.42	80.00
Size	Good	0.84	1.05	80.00
Location	Good	0.25	0.31	80.00
Storage/Fixed Equip	Fair	0.20	0.31	65.00
Media Center				
Environment	Good	0.74	0.93	80.00
Size	Good	1.86	2.32	80.00
Location	Excel	0.70	0.70	100.00
Storage/Fixed Equip	Good	0.56	0.70	80.00
Restrooms (Student)	Fair	0.60	0.93	65.00
Administration	Good	1.68	2.10	80.00
Counseling	Good	0.34	0.42	80.00
Clinic	Good	0.27	0.34	80.00
Staff Lounge-WkRm	Good	0.72	0.91	80.00
Cafeteria	Excel	4.00	4.00	100.00
Food Service and Prep	Good	4.57	5.72	80.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Good	3.20	4.00	80.00
Pedestrian Traffic	Good	0.35	0.43	80.00
Parking	Good	0.69	0.86	80.00
Athletic Courts and Fields	Good	0.84	1.05	80.00
Safety and Security				
Fencing	Fair	0.50	0.78	65.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Good	0.40	0.50	80.00
Total For Site:		79.36	100.00	79.36

Comments

Project #: 8272

County: Davie

Site #: 370117002066

Project: Assessments 2016

Region: 300

Site: SOUTH DAVIE MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
South Davie Middle School is a 6-8 grade facility built during the 1970s. The school has three classrooms to serve special education students. The school has nine portable classrooms used for storage, two Exceptional Children (EC) classes, one Academically and Intellectually Gifted (AIG) class, and one remedial reading class.				
Suitability - MS->Learning Environment				
A few leaks from the roof during heavy rains (roof is 4 years old).				
Suitability - MS->Learning Environment-->Interior Environment				
Limited aesthetics in some classrooms. 12 classrooms (general and elective) do not have windows to allow for natural light. Most rooms have flexible space. Sound tends to carry within the narrow side corridors.				
Suitability - MS->General Classrooms-->Environment				
Three 6th grade, two 7th grade, and two 8th grade rooms lack adequate natural lighting. Some water damage on ceiling tiles.				
Suitability - MS->General Classrooms-->Size				
Two 6th grade, one 7th grade, and 5 8th grade rooms did not meet the minimum for square footage standard. All of these rooms with the exception of one 8th grade room, were 4% below the minimum square footage standard. The remaining 8th grade rooms was 8% below the square footage standard.				
Suitability - MS->General Classrooms-->Storage/Fixed Equip				
Most rooms have removable added storage, but also have closet and permanent storage space.				
Suitability - MS->Self-Contained Special Ed-->Environment				
Inadequate natural lighting in 2 of the 3 rooms.				
Suitability - MS->Instructional Resource Rooms-->Environment				
Inadequate natural lighting. Two EC classes, 1 REM class, and 1 AIG class are located in portables. Has built-in storage.				
Suitability - MS->Instructional Resource Rooms-->Location				
Two EC classes, 1 REM class, and 1 AIG class are located in portables. The remaining four classes that are located in the main building meet the standard for square footage.				
Suitability - MS->Science-->Storage/Fixed Equip				
Rooms have built-in and removable storage. Lacks safety equipment and has limited science fixed equipment.				
Suitability - MS->Music-->Storage/Fixed Equip				
Inadequate sound-proofing; sound of instruments can be heard down the hall.				
Suitability - MS->Art-->Size				
Met 86% of the square footage standard.				
Suitability - MS->Art-->Storage/Fixed Equip				
The two sinks are missing clay traps. Storage space inadequate for amount of materials used (materials and added storage crowd the room).				
Suitability - MS->Career Tech Ed-->Environment				
Business lab has some noise from vent in classroom.				
Suitability - MS->Computer Labs-->Size				
One computer lab met 84% of the standard for square footage. The remaining two computer labs met 65% of the standard for square footage.				
Suitability - MS->Computer Labs-->Location				
Each grade has its own computer lab.				
Suitability - MS->P.E.-->Environment				
Double doors have a gap (located in extended hall section near back entrance/bus lot).				

Project #: 8272

County: Davie

Site #: 370117002066

Project: Assessments 2016

Region: 300

Site: SOUTH DAVIE MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS->Performing Arts-->Storage/Fixed Equip Lacks adequate storage for theater backgrounds/props.				
Suitability - MS->Restrooms (Student) Boys' restrooms in main halls lack urinal privacy partitions.				
Suitability - MS->Administration Lacks adequate records storage space.				
Suitability - MS->Counseling Lacks adequate records storage space.				
Suitability - MS->Outside-->Pedestrian Traffic Some congestion in the hallways within the building.				
Suitability - MS->Safety and Security-->Fencing Lacks perimeter fencing and near back entrances/sides.				
Suitability - MS->Safety and Security-->Signage & Way Finding Parking lots missing some directional/informational signage. Interior way finding and signage is good.				
Suitability - MS->Safety and Security-->Ease of Supervision Lacks exterior security cameras behind 6th/7th grade hall.				

Suitability Report - Full

Project #: 8272	County: Davie	Site #: 370117002816
Project: Assessments 2016	Region: 300	Site: WILLIAM ELLIS MIDDLE
Grade Config: 06-08	Site Type: Middle	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Learning Environment				
Learning Style Variety	Excel	5.00	5.00	100.00
Interior Environment	Excel	2.00	2.00	100.00
Exterior Environment	Excel	1.50	1.50	100.00
General Classrooms				
Environment	Excel	3.90	3.90	100.00
Size	Excel	9.75	9.75	100.00
Location	Excel	2.93	2.93	100.00
Storage/Fixed Equip	Good	2.34	2.93	80.00
Self-Contained Special Ed				
Environment	Good	0.44	0.55	80.00
Size	Excel	1.36	1.36	100.00
Location	Good	0.33	0.41	80.00
Storage/Fixed Equip	Good	0.33	0.41	80.00
Instructional Resource Rooms				
Environment	Good	0.66	0.82	80.00
Size	Good	1.64	2.05	80.00
Location	Good	0.49	0.61	80.00
Storage/Fixed Equip	Fair	0.40	0.61	65.00
Science				
Environment	Good	0.76	0.95	80.00
Size	Excel	2.39	2.39	100.00
Location	Good	0.57	0.72	80.00
Storage/Fixed Equip	Good	0.57	0.72	80.00
Music				
Environment	Fair	0.48	0.74	65.00
Size	Fair	1.20	1.84	65.00
Location	Excel	0.55	0.55	100.00
Storage/Fixed Equip	Good	0.44	0.55	80.00
Art				
Environment	Excel	0.65	0.65	100.00
Size	Excel	1.61	1.61	100.00
Location	Excel	0.48	0.48	100.00
Storage/Fixed Equip	Good	0.39	0.48	80.00
Career Tech Ed				
Environment	Good	1.08	1.35	80.00

Project #: 8272

County: Davie

Site #: 370117002816

Project: Assessments 2016

Region: 300

Site: WILLIAM ELLIS MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Fair	2.19	3.37	65.00
Location	Excel	1.01	1.01	100.00
Storage/Fixed Equip	Good	0.81	1.01	80.00
Computer Labs				
Environment	Good	0.24	0.30	80.00
Size	Fair	0.49	0.75	65.00
Location	Good	0.18	0.23	80.00
Storage/Fixed Equip	Fair	0.15	0.23	65.00
P.E.				
Environment	Excel	2.40	2.40	100.00
Size	Excel	6.00	6.00	100.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Good	1.44	1.80	80.00
Performing Arts				
Environment	Good	0.33	0.42	80.00
Size	Good	0.84	1.05	80.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Good	0.25	0.31	80.00
Media Center				
Environment	Good	0.74	0.93	80.00
Size	Excel	2.32	2.32	100.00
Location	Excel	0.70	0.70	100.00
Storage/Fixed Equip	Excel	0.70	0.70	100.00
Restrooms (Student)	Excel	0.93	0.93	100.00
Administration	Excel	2.10	2.10	100.00
Counseling	Fair	0.28	0.42	65.00
Clinic	Fair	0.22	0.34	65.00
Staff Lounge-WkRm	Excel	0.91	0.91	100.00
Cafeteria	Good	3.20	4.00	80.00
Food Service and Prep	Good	4.57	5.72	80.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Excel	4.00	4.00	100.00
Pedestrian Traffic	Excel	0.43	0.43	100.00
Parking	Excel	0.86	0.86	100.00
Athletic Courts and Fields	Good	0.84	1.05	80.00
Safety and Security				
Fencing	Good	0.62	0.78	80.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Excel	3.00	3.00	100.00
Controlled Entrances	Fair	0.33	0.50	65.00
Total For Site:		90.60	100.00	90.60

Comments

Project #: 8272

County: Davie

Site #: 370117002816

Project: Assessments 2016

Region: 300

Site: WILLIAM ELLIS MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability

Rating

Score

Possible
Score

Percent
Score

Suitability - MS

This school serves 6th through 8th grades, has two self-contained classrooms, and three CTE rooms. The campus includes athletic fields for softball, baseball, football and soccer, a gym, wrestling room, and a stage visible from the gym and the cafeteria.

Suitability - MS->General Classrooms-->Size

Nearly all general classrooms are approximately 90% of the size guideline.

Suitability - MS->Instructional Resource Rooms-->Storage/Fixed Equip

Some resource pullout rooms lack adequate storage space.

Suitability - MS->Music-->Environment

Vocal room is in a general classroom with no acoustical treatments and low ceilings.

Suitability - MS->Music-->Size

Instrument/band room meets size guideline, but vocal room is in a general classroom which is slightly smaller than guideline.

Suitability - MS->Career Tech Ed-->Size

CTE classrooms are below state size guidelines.

Suitability - MS->Computer Labs-->Size

Computer labs are undersized based on guideline.

Suitability - MS->Computer Labs-->Storage/Fixed Equip

Computer labs do not have storage space.

Suitability - MS->Performing Arts-->Environment

The stage is accessible and visible by both the gym and the cafeteria.

Suitability - MS->Media Center-->Environment

There is no natural light in the media center.

Suitability - MS->Counseling

There is no reception/waiting area for the counselor office.

Suitability - MS->Clinic

There is only one cot next to nurse desk. Window in door into administration front desk lobby.

Suitability - MS->Cafeteria

No water fountains in room, and no storage room for tables and chairs.

Suitability - MS->Food Service and Prep

No delivery door buzzer, but door window.

Suitability - MS->Safety and Security-->Fencing

Fencing is around the athletic fields behind the school.

Suitability - MS->Safety and Security-->Signage & Way Finding

Tobacco, drug, weapons free and surveillance warning signs are visible.

Suitability - MS->Safety and Security-->Controlled Entrances

One front door is unlocked at main entry, and there is no secure vestibule.

Project #: 8272

County: Davie

Site #: 370117002827

Project: Assessments 2016

Region: 300

Site: DAVIE COUNTY EARLY C

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Computer Labs				
Environment	Excel	0.30	0.30	100.00
Size	Good	0.60	0.75	80.00
Location	Excel	0.23	0.23	100.00
Storage/Fixed Equip	Fair	0.15	0.23	65.00
P.E.				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Restrooms (Student)	Excel	0.91	0.91	100.00
Administration	Excel	2.61	2.61	100.00
Counseling	Fair	0.49	0.76	65.00
Clinic	(N/A)	0.00	0.00	0.00
Staff Lounge-WkRm	Excel	0.71	0.71	100.00
Cafeteria	Unsat	0.00	4.00	0.00
Food Service and Prep	Good	4.08	5.11	80.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Good	0.80	1.00	80.00
Pedestrian Traffic	Good	0.78	0.98	80.00
Parking	Fair	1.37	2.11	65.00
Athletic Courts and Fields	(N/A)	0.00	0.00	0.00
Safety and Security				
Fencing	(N/A)	0.00	0.00	0.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Fair	0.33	0.50	65.00
Total For Site:		46.90	56.84	82.52

Comments

Project #: 8272

County: Davie

Site #: 370117002827

Project: Assessments 2016

Region: 300

Site: DAVIE COUNTY EARLY C

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability

Rating

Score

Possible
Score

Percent
Score

Suitability - HS

This is a single building on the site of Davidson County Community College in Mocksville, NC. It provides early college instruction and basic general education college level credits for selected high school students resulting in HS completion and eventual award of an Associate degree simultaneously. There are only 8 instructional rooms in the building. It receives support services from both DCCC and the Davie County School District. Many of the typical instructional or support space found in traditional high schools is not present or needed programmatically. e.g., PE,

Suitability - HS->Science-->Size

The Science labs are only about 50-55% of the size guideline for biology/earth science labs (excluding prep/storage space).

Suitability - HS->Science-->Storage/Fixed Equip

Classroom, storage & prep room have the expected equipment and hazardous materials storage, but shares the prep/storage space with the adjacent math classroom which was designed as science classroom.

Suitability - HS->Computer Labs-->Size

There is only one computer lab, and it is roughly 80% of the size guideline.

Suitability - HS->Computer Labs-->Storage/Fixed Equip

Room lacks storage space or casework.

Suitability - HS->Counseling

There is a guidance office in the administrative suite, but no waiting /reception area.

Suitability - HS->Cafeteria

The facility has a small food prep room for breakfast and lunch, but has no cafeteria or designated eating space.

Suitability - HS->Outside-->Parking

Student/staff parking is shared with adjacent Davidson County Community College.

Suitability - HS->Safety and Security-->Signage & Way Finding

Tobacco free and surveillance signs are displayed.

Suitability - HS->Safety and Security-->Controlled Entrances

Main entrance to building is open during school hours and there is no secure vestibule.

Suitability Report - Full

Project #: 8272	County: Davie	Site #: 370117000486
Project: Assessments 2016	Region: 300	Site: DAVIE COUNTY HIGH
Grade Config: 09-12	Site Type: High	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Excel	5.00	5.00	100.00
Interior Environment	Excel	2.00	2.00	100.00
Exterior Environment	Excel	1.50	1.50	100.00
General Classrooms				
Environment	Excel	3.90	3.90	100.00
Size	Excel	9.75	9.75	100.00
Location	Excel	2.93	2.93	100.00
Storage/Fixed Equip	Excel	2.93	2.93	100.00
Self-Contained Special Ed				
Environment	Excel	0.53	0.53	100.00
Size	Excel	1.33	1.33	100.00
Location	Excel	0.40	0.40	100.00
Storage/Fixed Equip	Excel	0.40	0.40	100.00
Instructional Resource Rooms				
Environment	Excel	0.80	0.80	100.00
Size	Excel	2.00	2.00	100.00
Location	Excel	0.60	0.60	100.00
Storage/Fixed Equip	Excel	0.60	0.60	100.00
Science				
Environment	Excel	0.83	0.83	100.00
Size	Excel	2.07	2.07	100.00
Location	Excel	0.62	0.62	100.00
Storage/Fixed Equip	Excel	0.62	0.62	100.00
Music				
Environment	Excel	0.59	0.59	100.00
Size	Excel	1.48	1.48	100.00
Location	Excel	0.45	0.45	100.00
Storage/Fixed Equip	Excel	0.45	0.45	100.00
Art				
Environment	Excel	0.67	0.67	100.00
Size	Excel	1.66	1.66	100.00
Location	Excel	0.50	0.50	100.00
Storage/Fixed Equip	Excel	0.50	0.50	100.00
Career Tech Ed				
Environment	Excel	1.71	1.71	100.00

Project #: 8272

County: Davie

Site #: 370117000486

Project: Assessments 2016

Region: 300

Site: DAVIE COUNTY HIGH

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	4.27	4.27	100.00
Location	Excel	1.28	1.28	100.00
Storage/Fixed Equip	Excel	1.28	1.28	100.00
Computer Labs				
Environment	Excel	0.30	0.30	100.00
Size	Excel	0.75	0.75	100.00
Location	Excel	0.23	0.23	100.00
Storage/Fixed Equip	Excel	0.23	0.23	100.00
P.E.				
Environment	Excel	2.40	2.40	100.00
Size	Excel	6.00	6.00	100.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Excel	1.80	1.80	100.00
Performing Arts				
Environment	Excel	0.32	0.32	100.00
Size	Excel	0.80	0.80	100.00
Location	Excel	0.24	0.24	100.00
Storage/Fixed Equip	Excel	0.24	0.24	100.00
Media Center				
Environment	Excel	0.84	0.84	100.00
Size	Excel	2.11	2.11	100.00
Location	Excel	0.63	0.63	100.00
Storage/Fixed Equip	Excel	0.63	0.63	100.00
Restrooms (Student)	Excel	0.91	0.91	100.00
Administration	Excel	2.61	2.61	100.00
Counseling	Excel	0.76	0.76	100.00
Clinic	Excel	0.24	0.24	100.00
Staff Lounge-WkRm	Excel	0.71	0.71	100.00
Cafeteria	Excel	4.00	4.00	100.00
Food Service and Prep	Excel	5.11	5.11	100.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Excel	1.00	1.00	100.00
Pedestrian Traffic	Excel	0.98	0.98	100.00
Parking	Excel	2.11	2.11	100.00
Athletic Courts and Fields	Excel	2.77	2.77	100.00
Safety and Security				
Fencing	Excel	0.85	0.85	100.00
Signage & Way Finding	Excel	1.00	1.00	100.00
Ease of Supervision	Excel	3.00	3.00	100.00
Controlled Entrances	Excel	0.50	0.50	100.00
Total For Site:		100.00	100.00	100.00

Comments

Project #: 8272

County: Davie

Site #: 370117000486

Project: Assessments 2016

Region: 300

Site: DAVIE COUNTY HIGH

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability

Rating

Score

**Possible
Score**

**Percent
Score**

Suitability - HS

New School Under Construction - Scored at 100%.

Suitability Report - Full

Project #: 8272	County: Davie	Site #: 370117002853
Project: Assessments 2016	Region: 300	Site: CENTRAL DAVIE ACADE
Grade Config: 06-12	Site Type: High	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Poor	0.75	1.50	50.00
General Classrooms				
Environment	Good	3.12	3.90	80.00
Size	Good	7.80	9.75	80.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Fair	1.90	2.93	65.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Good	0.64	0.80	80.00
Size	Excel	2.00	2.00	100.00
Location	Good	0.48	0.60	80.00
Storage/Fixed Equip	Good	0.48	0.60	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Art				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Career Tech Ed				
Environment	(N/A)	0.00	0.00	0.00

Project #: 8272

County: Davie

Site #: 370117002853

Project: Assessments 2016

Region: 300

Site: CENTRAL DAVIE ACADE

Grade Config: 06-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Computer Labs				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
P.E.				
Environment	Fair	1.56	2.40	65.00
Size	Good	4.80	6.00	80.00
Location	Good	1.44	1.80	80.00
Storage/Fixed Equip	Good	1.44	1.80	80.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Restrooms (Student)	Excel	0.91	0.91	100.00
Administration	Good	2.09	2.61	80.00
Counseling	Fair	0.49	0.76	65.00
Clinic	Poor	0.12	0.24	50.00
Staff Lounge-WkRm	Fair	0.46	0.71	65.00
Cafeteria	Excel	4.00	4.00	100.00
Food Service and Prep	Good	4.08	5.11	80.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Good	0.80	1.00	80.00
Pedestrian Traffic	Good	0.78	0.98	80.00
Parking	Good	1.69	2.11	80.00
Athletic Courts and Fields	(N/A)	0.00	0.00	0.00
Safety and Security				
Fencing	Unsat	0.00	0.85	0.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Excel	3.00	3.00	100.00
Controlled Entrances	Excel	0.50	0.50	100.00
Total For Site:		53.68	68.26	78.63

Comments

Project #: 8272

County: Davie

Site #: 370117002853

Project: Assessments 2016

Region: 300

Site: CENTRAL DAVIE ACADE

Grade Config: 06-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS Central Davie Academy is an alternative school facility built in 1949 that serves middle and high school grades 6-12. The school does not serve special education students. The school focuses on students struggling in academics and/or with behavioral challenges. The Academy does not have any portable classrooms.				
Suitability - HS->Learning Environment-->Learning Style Variety Some flexibility in the space, but limited variability.				
Suitability - HS->Learning Environment-->Exterior Environment Table seating area outside the cafeteria is available. Very limited outdoor space for learning labs and gathering spaces.				
Suitability - HS->General Classrooms-->Storage/Fixed Equip Closets and movable storage spaces.				
Suitability - HS->Instructional Resource Rooms-->Storage/Fixed Equip Closet and movable storage spaces.				
Suitability - HS->Computer Labs Computers are located in the general and resource classrooms (no separate lab).				
Suitability - HS->P.E.-->Environment The gym floor is tile.				
Suitability - HS->P.E.-->Size Large gym space that is shared between the Academy and the PK/daycare program.				
Suitability - HS->Media Center Books are shelved in hallway on removable carts.				
Suitability - HS->Counseling Noted that the Academy is in need of additional office space for counseling/therapist needs.				
Suitability - HS->Clinic No separate clinic area. First Aid, medicine, and emergency medical supplies are kept in the main office. No cot, separate restroom, separate refrigerator, or shower. The Academy has a visiting nurse once a week.				
Suitability - HS->Staff Lounge-WkRm Copier is located in the hallway. Space is limited.				
Suitability - HS->Safety and Security-->Fencing No fencing.				
Suitability - HS->Safety and Security-->Signage & Way Finding Limited directional/informational internal signage.				
Suitability - HS->Safety and Security-->Ease of Supervision Small blind spot within doorways.				

Suitability Report - Full

Project #: 8272	County: Greene	Site #: 370183003244
Project: Assessments 2016	Region: 400	Site: GREENE COUNTY INTE
Grade Config: 04-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Poor	0.75	1.50	50.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Excel	12.25	12.25	100.00
Location	Excel	3.68	3.68	100.00
Storage/Fixed Equip	Excel	3.68	3.68	100.00
Kindergarten				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	Good	0.38	0.48	80.00
Size	Good	0.96	1.20	80.00
Location	Good	0.29	0.36	80.00
Storage/Fixed Equip	Good	0.29	0.36	80.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Good	1.44	1.80	80.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Excel	0.54	0.54	100.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	1.85	1.85	100.00
Location	Excel	0.56	0.56	100.00
Storage/Fixed Equip	Good	0.44	0.56	80.00
Art				
Environment	Good	0.37	0.47	80.00
Size	Excel	1.17	1.17	100.00
Location	Excel	0.35	0.35	100.00
Storage/Fixed Equip	Excel	0.35	0.35	100.00
Computer Labs				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
P.E.				
Environment	Good	1.54	1.92	80.00
Size	Excel	4.80	4.80	100.00
Location	Excel	1.44	1.44	100.00
Storage/Fixed Equip	Good	1.15	1.44	80.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Excel	0.97	0.97	100.00
Size	Excel	2.44	2.44	100.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Excel	0.73	0.73	100.00
Restrooms (Student)	Good	0.71	0.89	80.00
Administration	Excel	2.56	2.56	100.00
Counseling	Excel	0.29	0.29	100.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Excel	1.27	1.27	100.00
Cafeteria	Fair	3.25	5.00	65.00
Food Service and Prep	Good	4.96	6.20	80.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Fair	0.53	0.81	65.00
Play Areas	Poor	1.17	2.34	50.00
Safety and Security				
Fencing	Fair	0.49	0.75	65.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Good	0.40	0.50	80.00

Project #: 8272

County: Greene

Site #: 370183003244

Project: Assessments 2016

Region: 400

Site: GREENE COUNTY INTE

Grade Config: 04-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		75.91	88.19	86.07

Comments

Suitability - ES

Greene County Intermediate School is a 4th-5th grade facility built in 2012. The school has two classrooms to serve special education students. The school does not have any portable classrooms. Large classrooms allow for flexible configurations with plenty of permanent casework for storage space. The school has many closet storage areas, and workrooms and custodial closets on each hall.

Suitability - ES->Learning Environment-->Exterior Environment

Picnic tables are used for the Art room's learning space. The only other area is the playground area. There is plenty of space outside the school to develop learning lab areas.

Suitability - ES->General Classrooms-->Size

Met 96% of the standard.

Suitability - ES->Computer Labs

Utilizes tech carts.

Suitability - ES->Restrooms (Student)

Auto faucets tend to get stuck in the on position.

Suitability - ES->Clinic

No cot or room for cot.

Suitability - ES->Cafeteria

Met 77% of the square footage standard.

Suitability - ES->Food Service and Prep

Ice machine does not work (reoccurring issue).

Suitability - ES->Outside-->Parking

Visitors park on the grass during large events.

Suitability - ES->Outside-->Play Areas

Play area includes one equipment set. No hard surfaces. The area is large. No fencing to enclose area near large fields, woods, and the bus parking lot.

Suitability - ES->Safety and Security-->Fencing

No fencing to enclose play area that is located near large fields, woods, and the bus parking lot.

Suitability - ES->Safety and Security-->Ease of Supervision

The camera system covers internal spaces and entranceways only (no outside cameras). Good sight lines within school.

Suitability Report - Full

Project #: 8272	County: Greene	Site #: 370183000754
Project: Assessments 2016	Region: 400	Site: SNOW HILL PRIMARY
Grade Config: PK-01	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Excel	5.00	5.00	100.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Excel	1.50	1.50	100.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Good	9.80	12.25	80.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Good	2.94	3.68	80.00
Kindergarten				
Environment	Fair	0.27	0.42	65.00
Size	Good	0.83	1.04	80.00
Location	Good	0.25	0.31	80.00
Storage/Fixed Equip	Good	0.25	0.31	80.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	Good	0.38	0.48	80.00
Size	Excel	1.20	1.20	100.00
Location	Excel	0.36	0.36	100.00
Storage/Fixed Equip	Excel	0.36	0.36	100.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Excel	1.80	1.80	100.00
Location	Fair	0.35	0.54	65.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	1.85	1.85	100.00
Location	Good	0.44	0.56	80.00
Storage/Fixed Equip	Excel	0.56	0.56	100.00
Art				
Environment	Good	0.37	0.47	80.00
Size	Good	0.94	1.17	80.00
Location	Good	0.28	0.35	80.00
Storage/Fixed Equip	Poor	0.18	0.35	50.00
Computer Labs				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
P.E.				
Environment	Poor	0.96	1.92	50.00
Size	Excel	4.80	4.80	100.00
Location	Good	1.15	1.44	80.00
Storage/Fixed Equip	Poor	0.72	1.44	50.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Excel	2.44	2.44	100.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Good	0.71	0.89	80.00
Administration	Excel	2.56	2.56	100.00
Counseling	Excel	0.29	0.29	100.00
Clinic	Good	0.47	0.58	80.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Good	4.00	5.00	80.00
Food Service and Prep	Poor	3.10	6.20	50.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Poor	1.00	2.00	50.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Fair	0.53	0.81	65.00
Play Areas	Fair	1.52	2.34	65.00
Safety and Security				
Fencing	Fair	0.49	0.75	65.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Good	0.40	0.50	80.00

Project #: 8272

County: Greene

Site #: 370183000754

Project: Assessments 2016

Region: 400

Site: SNOW HILL PRIMARY

Grade Config: PK-01

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		71.70	90.27	79.43

Comments

Suitability - ES

Snow Hill Primary School is a PK-1st grade facility built in 1952. The school has two classrooms to serve special education students. Large, inviting classrooms in the main building allow for flexible configurations and are equipped with sinks and permanent casework for storage space. The school has 9 portable spaces; these rooms contain four PK classes (not managed by the School), storage, and Family Literacy.

Suitability - ES->Learning Environment-->Interior Environment

There are reoccurring water leaks throughout the building. Some of the classrooms have poor acoustics due to connecting doors and open joint-room floor plans in the first hall. Paint is peeling off the walls by the windows (unsure if due to moisture).

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Outdated Promethium boards.

Suitability - ES->Kindergarten-->Environment

Four of the K-classes are located in joined open-air rooms, and noise can be a distraction.

Suitability - ES->ECE

There are 4 PK classes that are present in campus in a quad portable unit, but these classes are run separately from the Primary school.

Suitability - ES->Instructional Resource Rooms-->Location

Located at the end of the 1st grade hall and near administration.

Suitability - ES->Art-->Size

Met 84% of the square footage standard.

Suitability - ES->Art-->Storage/Fixed Equip

The room has adequate permanent casework. The room does not have easy access to outside, the three sinks do not have clay traps, there is limited display space aside from the hallways, there is no kiln, and there are not enough power outlets.

Suitability - ES->P.E.-->Environment

Carpeted multipurpose room with some fixed equipment. Lighting creates a buzzing noise and there is no natural light. No safety padding by stage storage area. The space is used for events but is over capacity (events split into two sessions to accommodate attendees).

Suitability - ES->P.E.-->Storage/Fixed Equip

Fixed equipment includes a small rock climbing area. There are mobile basketball goals, and there is ample storage. The room lacks safety padding by the stage. The water fountains are located in the hallway.

Suitability - ES->Media Center-->Storage/Fixed Equip

There is a mini computer lab in an attached room to the media center.

Suitability - ES->Restrooms (Student)

There are some gaps in the stalls.

Suitability - ES->Cafeteria

HVAC venting area is dusty and noisy.

Suitability - ES->Food Service and Prep

Equipment is old and must be repaired often. They have had a lot of plumbing issues. The dry storage area is too small for the full stock received. The kitchen area tends to be hot/stuffy during preparations. 2 of 4 cooler/freezers are kept outside. The kitchen space area is small.

Project #: 8272

County: Greene

Site #: 370183000754

Project: Assessments 2016

Region: 400

Site: SNOW HILL PRIMARY

Grade Config: PK-01

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
<p>Suitability - ES->Outside-->Vehicular Traffic Traffic tends to back up on the street. The bus lot is not separated from the visitor parking area.</p>				
<p>Suitability - ES->Outside-->Parking Dim lighting for at night. There is no separation between visitor parking and the bus lot. For large crowds, there is not enough parking.</p>				
<p>Suitability - ES->Outside-->Play Areas One play area present for all students; no fenced, separate area for PK and K classes. The present play area is large with a variety of playground equipment of varying age, old and new. The fencing present is not 100% enclosed but does surround most of the playground area.</p>				
<p>Suitability - ES->Safety and Security-->Fencing There is no fenced, separate play area for PK and K classes. The fencing present is not 100% enclosed but does surround most of the playground area.</p>				
<p>Suitability - ES->Safety and Security-->Signage & Way Finding Lacking some directional and informational signage externally and internally, specifically directing traffic flow for visitors in the parking lot.</p>				
<p>Suitability - ES->Safety and Security-->Ease of Supervision The camera system is antiquated and covers entrances, the bus lot, and the interior of the facility. Limited supervision around the exterior of the facility. Good sight lines present inside.</p>				

Suitability Report - Full

Project #: 8272	County: Greene	Site #: 370183000755
Project: Assessments 2016	Region: 400	Site: WEST GREENE ELEMEN
Grade Config: 02-03	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Fair	3.19	4.90	65.00
Size	Good	9.80	12.25	80.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Poor	1.84	3.68	50.00
Kindergarten				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	Good	0.38	0.48	80.00
Size	Good	0.96	1.20	80.00
Location	Good	0.29	0.36	80.00
Storage/Fixed Equip	Fair	0.23	0.36	65.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Good	1.44	1.80	80.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	1.85	1.85	100.00
Location	Fair	0.36	0.56	65.00
Storage/Fixed Equip	Good	0.44	0.56	80.00
Art				
Environment	Good	0.37	0.47	80.00
Size	Excel	1.17	1.17	100.00
Location	Good	0.28	0.35	80.00
Storage/Fixed Equip	Fair	0.23	0.35	65.00
Computer Labs				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
P.E.				
Environment	Fair	1.25	1.92	65.00
Size	Excel	4.80	4.80	100.00
Location	Excel	1.44	1.44	100.00
Storage/Fixed Equip	Fair	0.94	1.44	65.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Good	1.95	2.44	80.00
Location	Good	0.58	0.73	80.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Fair	0.58	0.89	65.00
Administration	Good	2.05	2.56	80.00
Counseling	Good	0.23	0.29	80.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Fair	3.25	5.00	65.00
Food Service and Prep	Excel	6.20	6.20	100.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Fair	1.30	2.00	65.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Fair	0.53	0.81	65.00
Play Areas	Fair	1.52	2.34	65.00
Safety and Security				
Fencing	Fair	0.49	0.75	65.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Poor	1.50	3.00	50.00
Controlled Entrances	Excel	0.50	0.50	100.00

Project #: 8272

County: Greene

Site #: 370183000755

Project: Assessments 2016

Region: 400

Site: WEST GREENE ELEMEN

Grade Config: 02-03

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		68.23	88.19	77.37

Comments

Suitability - ES

West Greene Elementary School is a 2nd-3rd grade facility. The school serves special education students. The school has 7 portable classrooms.

Suitability - ES->Learning Environment-->Exterior Environment

There is a picnic table for outdoor learning, but the table is old/too small.

Suitability - ES->General Classrooms-->Environment

Flooding reported on the 2nd grade hallway; the school uses sandbags by the doors. Reported that occasion water leaks from ceiling occur. The ceiling tiles are old and warped.

Suitability - ES->General Classrooms-->Size

Met 84% of the square footage standard.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Built-ins in some of the classrooms. Many mobile storage units are being used. Classroom chairs are old. Some of the Smartboard projectors are too dim to see.

Suitability - ES->Self-Contained Special Ed-->Storage/Fixed Equip

Limited special equipment.

Suitability - ES->Music-->Location

One part of the music playground is housed in a portable.

Suitability - ES->Art-->Storage/Fixed Equip

No clay traps in the two sinks that are present. Teacher notes needing another sink and an art drying rack. Limited storage space; currently has built-ins and mobile storage.

Suitability - ES->Computer Labs

Utilizes tech carts.

Suitability - ES->P.E.-->Environment

Multipurpose room aesthetics and limited gym/P.E. aesthetics.

Suitability - ES->P.E.-->Storage/Fixed Equip

Storage space is sufficient. Limited fixed equipment and no safety padding. A water fountain is present. The room's floor is carpeted, and has various gym equipment, including movable basketball goals. Capacity is an issue when this room is used for events.

Suitability - ES->Media Center-->Size

Met 82% of the square footage standard.

Suitability - ES->Restrooms (Student)

No hot water. Older fixtures are in place.

Suitability - ES->Administration

Records space needs another filing cabinet (adequate space).

Suitability - ES->Clinic

No connected restroom or cot/space for a cot.

Suitability - ES->Cafeteria

Met 77% of the square footage standard. Cafeteria tends to be cooler/cold than the rest of the building.

Suitability - ES->Outside-->Vehicular Traffic

Car rider traffic tends to back up on the road.

Project #: 8272

County: Greene

Site #: 370183000755

Project: Assessments 2016

Region: 400

Site: WEST GREENE ELEMEN

Grade Config: 02-03

Site Type: Elementary

Site Size: 0.00

Suitability

Rating

Score

**Possible
Score**

**Percent
Score**

Suitability - ES->Outside-->Parking

Visitor parking can overflow onto the grass, especially for events.

Suitability - ES->Outside-->Play Areas

Some of the play structures are old/outdated. No fencing by the woods.

Suitability - ES->Safety and Security-->Fencing

No fencing by the woods by the play area.

Suitability - ES->Safety and Security-->Ease of Supervision

The camera system is old and internal only (no outside cameras). Blind spots present in a few areas internally.

Suitability Report - Full

Project #: 8272	County: Greene	Site #: 370183002294
Project: Assessments 2016	Region: 400	Site: GREENE COUNTY MIDD
Grade Config: 06-08	Site Type: Middle	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Poor	0.75	1.50	50.00
General Classrooms				
Environment	Good	3.12	3.90	80.00
Size	Excel	9.75	9.75	100.00
Location	Fair	1.90	2.93	65.00
Storage/Fixed Equip	Excel	2.93	2.93	100.00
Self-Contained Special Ed				
Environment	Good	0.44	0.55	80.00
Size	Good	1.09	1.36	80.00
Location	Fair	0.27	0.41	65.00
Storage/Fixed Equip	Good	0.33	0.41	80.00
Instructional Resource Rooms				
Environment	Good	0.66	0.82	80.00
Size	Good	1.64	2.05	80.00
Location	Fair	0.40	0.61	65.00
Storage/Fixed Equip	Good	0.49	0.61	80.00
Science				
Environment	Good	0.76	0.95	80.00
Size	Excel	2.39	2.39	100.00
Location	Fair	0.47	0.72	65.00
Storage/Fixed Equip	Excel	0.72	0.72	100.00
Music				
Environment	Good	0.59	0.74	80.00
Size	Excel	1.84	1.84	100.00
Location	Excel	0.55	0.55	100.00
Storage/Fixed Equip	Excel	0.55	0.55	100.00
Art				
Environment	Good	0.52	0.65	80.00
Size	Excel	1.61	1.61	100.00
Location	Excel	0.48	0.48	100.00
Storage/Fixed Equip	Good	0.39	0.48	80.00
Career Tech Ed				
Environment	Good	1.08	1.35	80.00

Project #: 8272

County: Greene

Site #: 370183002294

Project: Assessments 2016

Region: 400

Site: GREENE COUNTY MIDD

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	2.70	3.37	80.00
Location	Fair	0.66	1.01	65.00
Storage/Fixed Equip	Fair	0.66	1.01	65.00
Computer Labs				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
P.E.				
Environment	Good	1.92	2.40	80.00
Size	Good	4.80	6.00	80.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Good	1.44	1.80	80.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Excel	0.93	0.93	100.00
Size	Excel	2.32	2.32	100.00
Location	Excel	0.70	0.70	100.00
Storage/Fixed Equip	Good	0.56	0.70	80.00
Restrooms (Student)	Good	0.74	0.93	80.00
Administration	Good	1.68	2.10	80.00
Counseling	Good	0.34	0.42	80.00
Clinic	Fair	0.22	0.34	65.00
Staff Lounge-WkRm	Good	0.72	0.91	80.00
Cafeteria	Good	3.20	4.00	80.00
Food Service and Prep	Good	4.57	5.72	80.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Good	3.20	4.00	80.00
Pedestrian Traffic	Good	0.35	0.43	80.00
Parking	Good	0.69	0.86	80.00
Athletic Courts and Fields	Good	0.84	1.05	80.00
Safety and Security				
Fencing	Unsat	0.00	0.78	0.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Good	0.40	0.50	80.00
Total For Site:		79.96	96.41	82.94

Comments

Project #: 8272

County: Greene

Site #: 370183002294

Project: Assessments 2016

Region: 400

Site: GREENE COUNTY MIDD

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability

Rating

Score

Possible
Score

Percent
Score

Suitability - MS

Greene County Middle School is a 6th-8th grade facility built in 2013. The school has one classroom to serve special education students. Large classrooms in the main building allow for some flexible configurations and are equipped with sinks and permanent casework for storage space. The school has two large portable units that collectively house 14 classrooms; these rooms contain three 8th grade classes, resource rooms, ISS, tutoring/testing space, and storage, among other uses.

Suitability - MS->Learning Environment-->Exterior Environment

There is one outdoor space outside the cafeteria that includes picnic tables, and this space is only used as a rewards lunch space and not for outdoor learning. There is ample space around the building to create additional learning lab areas.

Suitability - MS->General Classrooms-->Location

Each grade level is located within its own wing. Three 8th grade classrooms are located in portables.

Suitability - MS->General Classrooms-->Storage/Fixed Equip

All classrooms have built-in storage and sinks.

Suitability - MS->Self-Contained Special Ed-->Environment

There are a few water stained/missing ceiling tiles from a past water leak that has been fixed.

Suitability - MS->Self-Contained Special Ed-->Size

Met 80% of the square footage standard.

Suitability - MS->Self-Contained Special Ed-->Location

The room is not acoustically isolated.

Suitability - MS->Instructional Resource Rooms-->Location

Two reading resource rooms are located in portables.

Suitability - MS->Instructional Resource Rooms-->Storage/Fixed Equip

Built-ins and mobile storage present and adequate for current needs, but the smaller space reduces the amount of expanding storage space.

Suitability - MS->Science-->Location

The agriscience class is located in a portable.

Suitability - MS->Science-->Storage/Fixed Equip

The school has a shared science lab space located in a central location between the three primary hallways.

Suitability - MS->Art-->Storage/Fixed Equip

No kiln present.

Suitability - MS->Career Tech Ed-->Environment

During heavy rains, the door to the STEM room must have sandbags to prevent water leaks.

Suitability - MS->Career Tech Ed-->Location

Most career tech classes take place in a single wing within the school, but agricultural science is located in the portable annex with 8th grade classes.

Suitability - MS->Career Tech Ed-->Storage/Fixed Equip

The STEM rooms do not have enough outlets for their technology needs.

Suitability - MS->Computer Labs

No computer lab as classes use tablets.

Suitability - MS->P.E.-->Size

The gym exceeds capacity for large events or rivalry games.

Project #: 8272

County: Greene

Site #: 370183002294

Project: Assessments 2016

Region: 400

Site: GREENE COUNTY MIDD

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS->Media Center-->Storage/Fixed Equip The media center needs floor outlets to connect technology equipment and for special events (extension cords and power strips are used for events). Most of the outlets are presently located in the bookcases.				
Suitability - MS->Restrooms (Student) One boys' restroom is missing a urinal privacy divider.				
Suitability - MS->Clinic No internal restroom or shower, but is located next to the restrooms. No cot, but there is plenty of space to fit one.				
Suitability - MS->Food Service and Prep Ice machine has to be fixed often.				
Suitability - MS->Custodial and Maintenance Large custodial closet space located in each wing of the facility.				
Suitability - MS->Safety and Security-->Fencing No fencing.				
Suitability - MS->Safety and Security-->Ease of Supervision A few blind pots present internally and externally. The curved hallway and setback doorways limits sight lines.				

Suitability Report - Full

Project #: 8272	County: Greene	Site #: 370183000750
Project: Assessments 2016	Region: 400	Site: GREENE CENTRAL HIG
Grade Config: 09-12	Site Type: High	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Fair	2.54	3.90	65.00
Size	Good	7.80	9.75	80.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Fair	1.90	2.93	65.00
Self-Contained Special Ed				
Environment	Good	0.43	0.53	80.00
Size	Excel	1.33	1.33	100.00
Location	Fair	0.26	0.40	65.00
Storage/Fixed Equip	Fair	0.26	0.40	65.00
Instructional Resource Rooms				
Environment	Good	0.64	0.80	80.00
Size	Excel	2.00	2.00	100.00
Location	Good	0.48	0.60	80.00
Storage/Fixed Equip	Good	0.48	0.60	80.00
Science				
Environment	Good	0.66	0.83	80.00
Size	Good	1.66	2.07	80.00
Location	Excel	0.62	0.62	100.00
Storage/Fixed Equip	Good	0.50	0.62	80.00
Music				
Environment	Good	0.48	0.59	80.00
Size	Excel	1.48	1.48	100.00
Location	Excel	0.45	0.45	100.00
Storage/Fixed Equip	Excel	0.45	0.45	100.00
Art				
Environment	Excel	0.67	0.67	100.00
Size	Good	1.33	1.66	80.00
Location	Good	0.40	0.50	80.00
Storage/Fixed Equip	Good	0.40	0.50	80.00
Career Tech Ed				
Environment	Fair	1.11	1.71	65.00

Project #: 8272

County: Greene

Site #: 370183000750

Project: Assessments 2016

Region: 400

Site: GREENE CENTRAL HIG

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	4.27	4.27	100.00
Location	Good	1.03	1.28	80.00
Storage/Fixed Equip	Excel	1.28	1.28	100.00
Computer Labs				
Environment	Good	0.24	0.30	80.00
Size	Excel	0.75	0.75	100.00
Location	Fair	0.15	0.23	65.00
Storage/Fixed Equip	Excel	0.23	0.23	100.00
P.E.				
Environment	Excel	2.40	2.40	100.00
Size	Excel	6.00	6.00	100.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Fair	1.17	1.80	65.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.67	0.84	80.00
Size	Fair	1.37	2.11	65.00
Location	Good	0.51	0.63	80.00
Storage/Fixed Equip	Excel	0.63	0.63	100.00
Restrooms (Student)	Poor	0.46	0.91	50.00
Administration	Fair	1.70	2.61	65.00
Counseling	Good	0.61	0.76	80.00
Clinic	Excel	0.24	0.24	100.00
Staff Lounge-WkRm	Fair	0.46	0.71	65.00
Cafeteria	Good	3.20	4.00	80.00
Food Service and Prep	Fair	3.32	5.11	65.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Good	0.80	1.00	80.00
Pedestrian Traffic	Poor	0.49	0.98	50.00
Parking	Poor	1.05	2.11	50.00
Athletic Courts and Fields	Good	2.21	2.77	80.00
Safety and Security				
Fencing	Good	0.68	0.85	80.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Poor	1.50	3.00	50.00
Controlled Entrances	Fair	0.33	0.50	65.00
Total For Site:		76.75	98.40	78.00

Comments

Project #: 8272

County: Greene

Site #: 370183000750

Project: Assessments 2016

Region: 400

Site: GREENE CENTRAL HIG

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Greene Central High School is a 9th-12th grade facility built in 1961. The school has two classrooms to serve special education students. The school has two portables that are joined and used as the clinic, which is managed by the County Family Health Services. Most classrooms have adequate storage space and some flexible space.				
Suitability - HS->Learning Environment-->Learning Style Variety				
Several general classrooms lack flexible space for groupings and workstations. The mobile storage in a few rooms reduce the available space. Environment is inviting.				
Suitability - HS->Learning Environment-->Interior Environment				
The lighting in the facility is old/dim/damaged in places. There are two partitioned walls in the general classrooms, and this leads to noise issues occasionally. There are reoccurring water leaks throughout, particularly near the media center and Room 36 (general classroom). Environment is inviting.				
Suitability - HS->Learning Environment-->Exterior Environment				
There are a few outdoor spaces.				
Suitability - HS->General Classrooms-->Environment				
Limited aesthetics and flexibility in some of the classrooms. Lighting is insufficient in half of the vocational classrooms. Acoustics are overall good except in the classrooms with partitioned walls (4 total). Environment is inviting.				
Suitability - HS->General Classrooms-->Storage/Fixed Equip				
Half of the classrooms lack a sufficient number of electrical outlets/power. Some of the classrooms have permanent casework, but most are using mobile storage. About half of the Smartboard are old, dim, and need to be replaced.				
Suitability - HS->Self-Contained Special Ed-->Location				
Located among general classrooms and not acoustically isolated.				
Suitability - HS->Self-Contained Special Ed-->Storage/Fixed Equip				
No internal restroom area.				
Suitability - HS->Science-->Storage/Fixed Equip				
One sink is reported to not work properly. There is plenty of storage space from built-ins and closets.				
Suitability - HS->Art-->Size				
Met 84% of the square footage standard.				
Suitability - HS->Art-->Storage/Fixed Equip				
2 of the 3 sinks lack clay traps.				
Suitability - HS->Career Tech Ed-->Environment				
Lighting is very dim and the rooms are dusty/air quality. The auto shop needs proper ventilation.				
Suitability - HS->Computer Labs-->Size				
Met 93% of the square footage standard.				
Suitability - HS->Computer Labs-->Location				
Located away from general classrooms and by the gym.				
Suitability - HS->P.E.-->Storage/Fixed Equip				
Limited storage space for equipment.				
Suitability - HS->Media Center-->Size				
Met 79% of the square footage standard.				
Suitability - HS->Restrooms (Student)				
One of the boys' restrooms is missing urinal privacy dividers. The girls' restroom in the separate building that houses the auto shop, woodworking, and ROTC does not have stall doors and uses curtains instead. Reported that there is sometimes sewer odor problems in the restrooms and outside the building by the cafeteria.				

Project #: 8272

County: Greene

Site #: 370183000750

Project: Assessments 2016

Region: 400

Site: GREENE CENTRAL HIG

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS->Administration				
Lack of adequate meeting space for large groups (10-100+); administration currently uses the gym. There is no room for records storage in the administration area.				
Suitability - HS->Clinic				
The clinic is in a portable unit and is managed by the County Family Health Services.				
Suitability - HS->Staff Lounge-WkRm				
Facility would benefit from 1-2 more workroom spaces. Workrooms present are small with limited equipment.				
Suitability - HS->Food Service and Prep				
Some of the appliances are old, and the warmer and hood do not work appropriately. The cooler/freezer space is insufficient for the number of students served.				
Suitability - HS->Outside-->Pedestrian Traffic				
Students must use a campus crosswalk to access the separate building that houses the auto shop, woodworking, and ROTC classes. The crosswalk crosses the street that is used by staff and buses to reach drop-off/parking.				
Suitability - HS->Outside-->Parking				
Some staff park in the grass. There is very little space for visitor parking and most of the available space is in the grass. This is a big problem when they hold events/games. There is sufficient student and bus parking. The bus, visitor, and staff parking areas are not well lit.				
Suitability - HS->Safety and Security-->Signage & Way Finding				
Lacking directional/informational signage for visitors parking.				
Suitability - HS->Safety and Security-->Ease of Supervision				
Cameras cover the interior of the building and the student parking lot and outside the ISS room. There are many blind spots outside the school, especially around the music building, which is in a separate building and must be monitored on foot often. The Science, History, and English hallway and the gym locker area lack camera coverage.				
Suitability - HS->Safety and Security-->Controlled Entrances				
No double doors for the main entrance by the office. Limited supervision of other entrances.				

Suitability Report - Full

Project #: 8272	County: Greene	Site #: xxx3
Project: Assessments 2016	Region: 400	Site: GREENE COUNTY ALTE
Grade Config: 09-12	Site Type: High	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Poor	2.50	5.00	50.00
Interior Environment	Unsat	0.00	2.00	0.00
Exterior Environment	Poor	0.75	1.50	50.00
General Classrooms				
Environment	Poor	1.95	3.90	50.00
Size	(N/A)	0.00	0.00	0.00
Location	Unsat	0.00	2.93	0.00
Storage/Fixed Equip	Poor	1.46	2.93	50.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Poor	0.40	0.80	50.00
Size	(N/A)	0.00	0.00	0.00
Location	Unsat	0.00	0.60	0.00
Storage/Fixed Equip	Poor	0.30	0.60	50.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Art				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Career Tech Ed				
Environment	(N/A)	0.00	0.00	0.00

Project #: 8272

County: Greene

Site #: xxx3

Project: Assessments 2016

Region: 400

Site: GREENE COUNTY ALTE

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Computer Labs				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
P.E.				
Environment	Poor	1.20	2.40	50.00
Size	Unsat	0.00	6.00	0.00
Location	Unsat	0.00	1.80	0.00
Storage/Fixed Equip	Fair	1.17	1.80	65.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Restrooms (Student)	Good	0.73	0.91	80.00
Administration	Good	2.09	2.61	80.00
Counseling	(N/A)	0.00	0.00	0.00
Clinic	Fair	0.15	0.24	65.00
Staff Lounge-WkRm	Fair	0.46	0.71	65.00
Cafeteria	Fair	2.60	4.00	65.00
Food Service and Prep	Poor	2.55	5.11	50.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Fair	0.65	1.00	65.00
Pedestrian Traffic	Good	0.78	0.98	80.00
Parking	Good	1.69	2.11	80.00
Athletic Courts and Fields	Poor	1.38	2.77	50.00
Safety and Security				
Fencing	Good	0.68	0.85	80.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Good	0.40	0.50	80.00
Total For Site:		27.35	58.53	46.73

Comments

Project #: 8272

County: Greene

Site #: xxx3

Project: Assessments 2016

Region: 400

Site: GREENE COUNTY ALTE

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Greene Alternative Education Center is a 6th-12th grade portable, multi-room facility built in 2006. The school does not serve special education students.				
Suitability - HS->Learning Environment-->Learning Style Variety				
The classrooms are located within a portable. Limited aesthetics and poor acoustics. There is adequate space, but the rooms lack furniture and fixed equipment to accommodate different working groups.				
Suitability - HS->Learning Environment-->Interior Environment				
The resource room is located within a portable. Limited aesthetics and poor acoustics.				
Suitability - HS->Learning Environment-->Exterior Environment				
The facility uses one of its mobile classrooms as an indoor recreation center (board games, foosball) when the weather is not appropriate for outside play. Next to the mobile facility, there is a mobile basketball goal with a partially paved area and two picnic tables. The area surrounding the mobile facility is partially fenced.				
Suitability - HS->General Classrooms-->Environment				
The general classrooms are located within a portable. Limited aesthetics and poor acoustics. There is adequate space, but the rooms lack furniture and fixed equipment to accommodate different working groups.				
Suitability - HS->General Classrooms-->Size				
The general classrooms are located within a portable unit.				
Suitability - HS->General Classrooms-->Location				
The general classrooms are located within a portable unit.				
Suitability - HS->General Classrooms-->Storage/Fixed Equip				
Adequate storage space. Limited fixed equipment. The resource room is located within a portable.				
Suitability - HS->Instructional Resource Rooms-->Environment				
The resource room is located within a portable. Limited aesthetics and poor acoustics. There is adequate space, but the room lacks furniture and fixed equipment to accommodate different working groups.				
Suitability - HS->Instructional Resource Rooms-->Size				
The resource room is located within a portable.				
Suitability - HS->Instructional Resource Rooms-->Location				
The resource room is located within a portable.				
Suitability - HS->Instructional Resource Rooms-->Storage/Fixed Equip				
Adequate storage space. Limited fixed equipment. The resource room is located within a portable.				
Suitability - HS->P.E.-->Environment				
The facility uses one of its mobile classrooms as an indoor recreation center (board games, foosball) when the weather is not appropriate for outside play. Next to the mobile facility, there is a mobile basketball goal with a partially paved area and two picnic tables. The area surrounding the mobile facility is partially fenced.				
Suitability - HS->P.E.-->Size				
Indoor recreation is located within a mobile unit. There is limited play space outside the mobile unit.				
Suitability - HS->P.E.-->Location				
The inside recreation area is located between two general education classrooms. Sounds easily carries between the mobile unit's rooms. The facility uses one of its mobile classrooms as an indoor recreation center (board games, foosball) when the weather is not appropriate for outside play. Next to the mobile facility, there is a mobile basketball goal with a partially paved area and two picnic tables. The area surrounding the mobile facility is partially fenced.				
Suitability - HS->P.E.-->Storage/Fixed Equip				
The facility uses one of its mobile classrooms as an indoor recreation center (board games, foosball) when the weather is not appropriate for outside play. Next to the mobile facility, there is a mobile basketball goal with a partially paved area and two picnic tables. The area surrounding the mobile facility is partially fenced.				

Project #: 8272

County: Greene

Site #: xxx3

Project: Assessments 2016

Region: 400

Site: GREENE COUNTY ALTE

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS->Clinic The facility has a First Aid supply box. Reported to meet the program's needs.				
Suitability - HS->Staff Lounge-WkRm Minimal office equipment present (copier).				
Suitability - HS->Cafeteria The facility utilizes its vocational/career tech classroom as the cafeteria. The facility does not prepare meals onsite. Meals are prepared at neighboring schools and are transported, kept warm, and served to students onsite.				
Suitability - HS->Food Service and Prep The facility does not prepare meals onsite. Meals are prepared at neighboring schools and are transported, kept warm, and served to students onsite. The delivery area is located by the bus parking lot area and the front entrance.				
Suitability - HS->Custodial and Maintenance The custodial closet has sufficient space. The ceiling is missing a tile from an earlier leak, which has been fixed.				
Suitability - HS->Outside-->Vehicular Traffic No separation between the bus and visitor/staff lot.				
Suitability - HS->Outside-->Pedestrian Traffic No separation between the bus and visitor/staff lot.				
Suitability - HS->Outside-->Athletic Courts and Fields The facility uses one of its mobile classrooms as an indoor recreation center (board games, foosball) when the weather is not appropriate for outside play. Next to the mobile facility, there is a mobile basketball goal with a partially paved area and two picnic tables. The area surrounding the mobile facility is partially fenced.				
Suitability - HS->Safety and Security-->Signage & Way Finding Lacking some informational signage.				

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201000874
Project: Assessments 2016	Region: 430	Site: ANDERSON CREEK PRI
Grade Config: KG-02	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Excel	5.00	5.00	100.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Excel	1.50	1.50	100.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Excel	12.25	12.25	100.00
Location	Excel	3.68	3.68	100.00
Storage/Fixed Equip	Excel	3.68	3.68	100.00
Kindergarten				
Environment	Good	0.33	0.42	80.00
Size	Excel	1.04	1.04	100.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Good	0.25	0.31	80.00
ECE				
Environment	Excel	0.50	0.50	100.00
Size	Excel	1.25	1.25	100.00
Location	Good	0.30	0.37	80.00
Storage/Fixed Equip	Excel	0.37	0.37	100.00
Self-Contained Special Ed				
Environment	Excel	0.48	0.48	100.00
Size	Excel	1.20	1.20	100.00
Location	Good	0.29	0.36	80.00
Storage/Fixed Equip	Good	0.29	0.36	80.00
Instructional Resource Rooms				
Environment	Fair	0.47	0.72	65.00
Size	Good	1.44	1.80	80.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Fair	0.35	0.54	65.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Unsat	0.00	0.74	0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Unsat	0.00	1.85	0.00
Location	Unsat	0.00	0.56	0.00
Storage/Fixed Equip	Unsat	0.00	0.56	0.00
Art				
Environment	Excel	0.47	0.47	100.00
Size	Excel	1.17	1.17	100.00
Location	Excel	0.35	0.35	100.00
Storage/Fixed Equip	Excel	0.35	0.35	100.00
Computer Labs				
Environment	Excel	0.34	0.34	100.00
Size	Excel	0.85	0.85	100.00
Location	Excel	0.26	0.26	100.00
Storage/Fixed Equip	Excel	0.26	0.26	100.00
P.E.				
Environment	Excel	1.92	1.92	100.00
Size	Excel	4.80	4.80	100.00
Location	Excel	1.44	1.44	100.00
Storage/Fixed Equip	Good	1.15	1.44	80.00
Performing Arts				
Environment	Good	0.48	0.60	80.00
Size	Good	1.21	1.51	80.00
Location	Excel	0.45	0.45	100.00
Storage/Fixed Equip	Fair	0.29	0.45	65.00
Media Center				
Environment	Excel	0.97	0.97	100.00
Size	Excel	2.44	2.44	100.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Excel	0.73	0.73	100.00
Restrooms (Student)	Good	0.71	0.89	80.00
Administration	Good	2.05	2.56	80.00
Counseling	Excel	0.29	0.29	100.00
Clinic	Unsat	0.00	0.58	0.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Fair	3.25	5.00	65.00
Food Service and Prep	Good	4.96	6.20	80.00
Custodial and Maintenance	Fair	0.33	0.50	65.00
Outside				
Vehicular Traffic	Poor	1.00	2.00	50.00
Pedestrian Traffic	Excel	0.97	0.97	100.00
Parking	Fair	0.53	0.81	65.00
Play Areas	Poor	1.17	2.34	50.00
Safety and Security				
Fencing	Unsat	0.00	0.75	0.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Excel	3.00	3.00	100.00
Controlled Entrances	Poor	0.25	0.50	50.00

Project #: 8272

County: Harnett

Site #: 370201000874

Project: Assessments 2016

Region: 430

Site: ANDERSON CREEK PRI

Grade Config: KG-02

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		81.62	97.50	83.72

Comments

Suitability - ES

Anderson Creek primary school is a pre-K through second grade facility. The school has two portables. One portable is used for music and the other portable is used for staff development.

Suitability - ES->Learning Environment-->Interior Environment

The HVAC system is inconsistent throughout the building.

Suitability - ES->General Classrooms-->Environment

The HVAC system is inconsistent throughout the building.

Suitability - ES->Kindergarten-->Environment

The HVAC system is inconsistent throughout the building.

Suitability - ES->Kindergarten-->Storage/Fixed Equip

The kindergarten classrooms do not have adequate storage for large items.

Suitability - ES->ECE-->Location

The pre-k classrooms are located at the opposite end of the building from the administrative staff and parent drop off area. They are in close proximity to the gymnasium and cafeteria.

Suitability - ES->Self-Contained Special Ed-->Location

The self-contained pre-K is located at the opposite end of the building from the parent drop off area. It is in close proximity to the gymnasium and cafeteria.

Suitability - ES->Self-Contained Special Ed-->Storage/Fixed Equip

The self-contained pre-K classroom does not have storage for mobility devices.

Suitability - ES->Instructional Resource Rooms-->Environment

One of the reading recovery rooms is a former storage room that is been converted to a small group instructional area. To reading recovery classrooms were originally resource rooms that have been divided into two smaller spaces. The storage room does not have natural lighting and is not a conducive educational environment.

Suitability - ES->Instructional Resource Rooms-->Size

Occupational Therapy is done in a small room that is also used to store records. A storage room has been converted to a small group instructional area.

Suitability - ES->Instructional Resource Rooms-->Location

In the classrooms that have been divided you can only access the back classroom by walking through the front classroom which can be extremely disruptive.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip

The Occupational Therapy and small group instructional area located in a storeroom do not have adequate built in cabinetry for storage.

Suitability - ES->Music-->Environment

Music is taught in a portable classroom.

Suitability - ES->Music-->Size

Music is taught in a portable classroom.

Suitability - ES->Music-->Location

Music is taught in a portable classroom.

Suitability - ES->Music-->Storage/Fixed Equip

Music is taught in a portable classroom.

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->P.E.-->Storage/Fixed Equip A portion of the physical education storage is being used to store tables and chairs which causes the physical education storage to be inadequate.				
Suitability - ES->Performing Arts-->Environment The school utilizes the gymnasium for school performances. It cannot seat the entire student body on the bleachers. The gym does not have any acoustical treatments.				
Suitability - ES->Performing Arts-->Size The gym is not large enough to accommodate all of the parents who want to attend school programs.				
Suitability - ES->Performing Arts-->Storage/Fixed Equip The gymnasium has an excellent sound system. It does not have a stage or additional lighting for performances.				
Suitability - ES->Media Center The media center is also a branch of the public library.				
Suitability - ES->Media Center-->Size The media center is the appropriate size for a primary school. Because it is also a branch of the public library additional shelving is required which limits the size of some of the instructional spaces.				
Suitability - ES->Restrooms (Student) The restrooms lack adequate ventilation and the lighting is dim.				
Suitability - ES->Administration The mailboxes are located in a secondary hallway through the administrative office area. Noise can be disruptive while individuals are meeting in the conference room or administrative offices.				
Suitability - ES->Clinic The school does not have a nurse's clinic.				
Suitability - ES->Staff Lounge-WkRm The school has an adequate workroom but does not have a staff lounge.				
Suitability - ES->Cafeteria The cafeteria is approximately 65% of the standard size for the student population.				
Suitability - ES->Food Service and Prep The food preparation area is small for the number of staff and the number of meals prepared. The delivery door does not have a buzzer for access.				
Suitability - ES->Custodial and Maintenance All of the custodial closets are equipped with wall-mounted sinks.				
Suitability - ES->Outside-->Vehicular Traffic The parent drop off lane and access to the main parking lot are located by the same driveway. Due to the length of the drop off lane cars back up on the road in front of the school. Both lanes are often backed up bringing all traffic to a complete halt.				
Suitability - ES->Outside-->Parking Because of the congestion in accessing and exiting the staff parking lot some staff park behind the school on grassy areas.				
Suitability - ES->Outside-->Play Areas The school has two fenced playgrounds. The playgrounds do not have an open green space and are small for the number of students served.				
Suitability - ES->Safety and Security-->Fencing The school does not have any additional perimeter fencing other than the fencing around the small playgrounds.				

Project #: 8272

County: Harnett

Site #: 370201000874

Project: Assessments 2016

Region: 430

Site: ANDERSON CREEK PRI

Grade Config: KG-02

Site Type: Elementary

Site Size: 0.00

Suitability

Rating

Score

**Possible
Score**

**Percent
Score**

Suitability - ES->Safety and Security-->Signage & Way Finding

The school does not have any external or internal directional signage.

Suitability - ES->Safety and Security-->Controlled Entrances

The front door to the main building remains open during the school day. There is direct line of sight supervision from the main office to the front door. The school does not have a buzzer system or security vestibule.

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201000875
Project: Assessments 2016	Region: 430	Site: ANGIER ELEMENTARY
Grade Config: 03-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Excel	5.00	5.00	100.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Excel	1.50	1.50	100.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Excel	12.25	12.25	100.00
Location	Excel	3.68	3.68	100.00
Storage/Fixed Equip	Excel	3.68	3.68	100.00
Kindergarten				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	Excel	0.48	0.48	100.00
Size	Excel	1.20	1.20	100.00
Location	Excel	0.36	0.36	100.00
Storage/Fixed Equip	Excel	0.36	0.36	100.00
Instructional Resource Rooms				
Environment	Fair	0.47	0.72	65.00
Size	Excel	1.80	1.80	100.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Excel	0.54	0.54	100.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Excel	0.74	0.74	100.00

Project #: 8272

County: Harnett

Site #: 370201000875

Project: Assessments 2016

Region: 430

Site: ANGIER ELEMENTARY

Grade Config: 03-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	1.85	1.85	100.00
Location	Excel	0.56	0.56	100.00
Storage/Fixed Equip	Excel	0.56	0.56	100.00
Art				
Environment	Excel	0.47	0.47	100.00
Size	Excel	1.17	1.17	100.00
Location	Excel	0.35	0.35	100.00
Storage/Fixed Equip	Excel	0.35	0.35	100.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Good	0.68	0.85	80.00
Location	Excel	0.26	0.26	100.00
Storage/Fixed Equip	Excel	0.26	0.26	100.00
P.E.				
Environment	Excel	1.92	1.92	100.00
Size	Excel	4.80	4.80	100.00
Location	Excel	1.44	1.44	100.00
Storage/Fixed Equip	Excel	1.44	1.44	100.00
Performing Arts				
Environment	Excel	0.60	0.60	100.00
Size	Excel	1.51	1.51	100.00
Location	Excel	0.45	0.45	100.00
Storage/Fixed Equip	Excel	0.45	0.45	100.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Excel	2.44	2.44	100.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Excel	0.73	0.73	100.00
Restrooms (Student)	Excel	0.89	0.89	100.00
Administration	Excel	2.56	2.56	100.00
Counseling	Fair	0.19	0.29	65.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Excel	5.00	5.00	100.00
Food Service and Prep	Excel	6.20	6.20	100.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Excel	2.00	2.00	100.00
Pedestrian Traffic	Excel	0.97	0.97	100.00
Parking	Excel	0.81	0.81	100.00
Play Areas	Good	1.87	2.34	80.00
Safety and Security				
Fencing	Poor	0.38	0.75	50.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Excel	0.50	0.50	100.00

Project #: 8272

County: Harnett

Site #: 370201000875

Project: Assessments 2016

Region: 430

Site: ANGIER ELEMENTARY

Grade Config: 03-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		87.79	92.92	94.48

Comments

Suitability - ES

Angier Elementary School is a third through fifth grade neighborhood school. The school was constructed in 2009.

Suitability - ES->Learning Environment-->Interior Environment

The interior classrooms do not have any natural light.

Suitability - ES->General Classrooms-->Environment

The interior classrooms do not have natural lighting.

Suitability - ES->Instructional Resource Rooms-->Environment

Many of the resource rooms or in small classrooms are office areas that do not have natural lighting.

Suitability - ES->Instructional Resource Rooms-->Location

The resource rooms adjacent to the cafeteria have significant noise infiltration from the cafeteria.

Suitability - ES->Computer Labs-->Environment

The computer lab does not have any natural lighting.

Suitability - ES->Computer Labs-->Size

The computer lab is approximately 85% of the size standard.

Suitability - ES->Media Center-->Environment

The media center is on the interior of the building and does not have any natural lighting.

Suitability - ES->Counseling

The guidance counselor is assigned a classroom because the counselor does large and small group instruction. The classroom also serves as the office area. It is a significant distance from the school records and does not have a reception area.

Suitability - ES->Clinic

The school has a nurse's clinic but it is not equipped with any cots.

Suitability - ES->Staff Lounge-WkRm

The school does not have a staff lounge. There is a small lounge area for custodial staff.

Suitability - ES->Outside-->Play Areas

The fenced in playground area has an open grassy area for soccer and other activities. It's extremely small in size.

Suitability - ES->Safety and Security-->Fencing

The school does not have any perimeter fencing.

Suitability - ES->Safety and Security-->Signage & Way Finding

The school does not have any external or internal directional signage.

Suitability - ES->Safety and Security-->Ease of Supervision

Due to the configuration of the hallways line of sight supervision is difficult.

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201000876
Project: Assessments 2016	Region: 430	Site: BENHAVEN ELEMENTAR
Grade Config: KG-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Poor	2.50	5.00	50.00
Interior Environment	Poor	1.00	2.00	50.00
Exterior Environment	Poor	0.75	1.50	50.00
General Classrooms				
Environment	Poor	2.45	4.90	50.00
Size	Poor	6.13	12.25	50.00
Location	Poor	1.84	3.68	50.00
Storage/Fixed Equip	Poor	1.84	3.68	50.00
Kindergarten				
Environment	Poor	0.21	0.42	50.00
Size	Poor	0.52	1.04	50.00
Location	Fair	0.20	0.31	65.00
Storage/Fixed Equip	Poor	0.16	0.31	50.00
ECE				
Environment	Fair	0.32	0.50	65.00
Size	Poor	0.62	1.25	50.00
Location	Good	0.30	0.37	80.00
Storage/Fixed Equip	Fair	0.24	0.37	65.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Poor	0.36	0.72	50.00
Size	Excel	1.80	1.80	100.00
Location	Fair	0.35	0.54	65.00
Storage/Fixed Equip	Fair	0.35	0.54	65.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Poor	0.37	0.74	50.00

Project #: 8272

County: Harnett

Site #: 370201000876

Project: Assessments 2016

Region: 430

Site: BENHAVEN ELEMENTAR

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Fair	1.20	1.85	65.00
Location	Poor	0.28	0.56	50.00
Storage/Fixed Equip	Unsat	0.00	0.56	0.00
Art				
Environment	Poor	0.23	0.47	50.00
Size	Poor	0.58	1.17	50.00
Location	Poor	0.18	0.35	50.00
Storage/Fixed Equip	Unsat	0.00	0.35	0.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Fair	0.55	0.85	65.00
Location	Fair	0.17	0.26	65.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Poor	0.96	1.92	50.00
Size	Excel	4.80	4.80	100.00
Location	Fair	0.94	1.44	65.00
Storage/Fixed Equip	Poor	0.72	1.44	50.00
Performing Arts				
Environment	Fair	0.39	0.60	65.00
Size	Excel	1.51	1.51	100.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Fair	0.29	0.45	65.00
Media Center				
Environment	Fair	0.63	0.97	65.00
Size	Fair	1.58	2.44	65.00
Location	Poor	0.37	0.73	50.00
Storage/Fixed Equip	Fair	0.48	0.73	65.00
Restrooms (Student)	Fair	0.58	0.89	65.00
Administration	Fair	1.66	2.56	65.00
Counseling	Fair	0.19	0.29	65.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Fair	3.25	5.00	65.00
Food Service and Prep	Fair	4.03	6.20	65.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Poor	1.00	2.00	50.00
Pedestrian Traffic	Poor	0.49	0.97	50.00
Parking	Poor	0.41	0.81	50.00
Play Areas	Fair	1.52	2.34	65.00
Safety and Security				
Fencing	Poor	0.38	0.75	50.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Poor	1.50	3.00	50.00
Controlled Entrances	Poor	0.25	0.50	50.00

Project #: 8272

County: Harnett

Site #: 370201000876

Project: Assessments 2016

Region: 430

Site: BENAHAVEN ELEMENTAR

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		56.57	95.10	59.48

Comments

Suitability - ES->Learning Environment-->Learning Style Variety

Benhaven Elementary has a wide variety of teaching spaces due to the number of different buildings with different configurations. Most instructional spaces, however, do not provide any degree of flexibility.

Suitability - ES->Learning Environment-->Interior Environment

The age, configuration, unaligned corridors, etc. do not provide for a positive learning environment.

Suitability - ES->Learning Environment-->Exterior Environment

Benhaven has a large amount of outside space but much of it is unimproved.

Suitability - ES->General Classrooms-->Environment

General classroom spaces are dated. 4 are located in portables.

Suitability - ES->General Classrooms-->Size

General Classrooms range from 60-90% of the guidelines. 4 are in portables, 4 are in a modular building.

Suitability - ES->General Classrooms-->Location

General classrooms are spread throughout the campus. Most require outdoor access to core areas.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Classrooms in the building have minimal storage. 4 are in portables.

Suitability - ES->Kindergarten-->Environment

The age and condition of the school does not provide for a stimulating environment.

Suitability - ES->Kindergarten-->Size

Kindergarten rooms range from 55-65% of the guidelines.

Suitability - ES->Kindergarten-->Location

Kindergarten rooms are located together in the gym building. They are not convenient to other core functions.

Suitability - ES->Kindergarten-->Storage/Fixed Equip

Kindergarten rooms have minimal storage. They do not have restrooms.

Suitability - ES->ECE-->Environment

Pre-school is located in the former teacherage. The spaces have been renovated to provide a reasonable environment for the program.

Suitability - ES->ECE-->Size

Pre-school rooms meet approximately 60% of the guideline.

Suitability - ES->ECE-->Storage/Fixed Equip

Pre-school equipment and storage is dated.

Suitability - ES->Instructional Resource Rooms-->Environment

The age and condition of the building does not lend itself to a stimulating environment.

Suitability - ES->Instructional Resource Rooms-->Location

Some resource rooms are near noisy areas.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip

Resource rooms include appropriate technology equipment but minimal storage.

Suitability - ES->Music-->Environment

Music is located in a regular classroom space.

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Music-->Size the music room meets approximately 75% of the guidelines.				
Suitability - ES->Music-->Location The music room is located near the cafeteria in a regular classroom space.				
Suitability - ES->Music-->Storage/Fixed Equip There is no storage or equipment associated with music space.				
Suitability - ES->Art-->Environment The age and condition of the building do not lend itself to a stimulating learning environment.				
Suitability - ES->Art-->Size The music room meets approximately 50% of the guidelines.				
Suitability - ES->Art-->Location the art room is a converted locker room.				
Suitability - ES->Art-->Storage/Fixed Equip There is minimal storage or equipment normally associated with art space. There is no kiln room.				
Suitability - ES->Computer Labs-->Size The computer lab meets approximately 70% of the guidelines.				
Suitability - ES->Computer Labs-->Location The computer lab is located next to the media center but not convenient to most instructional spaces.				
Suitability - ES->P.E.-->Environment Physical Education is held in an old high school gymnasium. While large, it does not provide a stimulating environment.				
Suitability - ES->P.E.-->Location The gym is located in a separate building that also houses Kindergarten. It is not located are ease of access.				
Suitability - ES->P.E.-->Storage/Fixed Equip Their is minimal PE storage. The old locker rooms have been converted to other uses.				
Suitability - ES->Performing Arts-->Environment Benhaven Elementary has an old high school auditorium that provides a unique elementary space.				
Suitability - ES->Performing Arts-->Storage/Fixed Equip The auditorium has fixed seating and a stage but little else regarding storage and equipment.				
Suitability - ES->Media Center-->Environment the media center provides little in the way of overall aesthetics.				
Suitability - ES->Media Center-->Size The media center meets approximately 75% of the guidelines.				
Suitability - ES->Media Center-->Location The media center is not located centrally.				
Suitability - ES->Media Center-->Storage/Fixed Equip Storage and fixed equipment is not up to date.				
Suitability - ES->Restrooms (Student) Student restrooms are located in each of the buildings but are dated and not well ventilated.				
Suitability - ES->Administration Administrative spaces are small.				

Project #: 8272

County: Harnett

Site #: 370201000876

Project: Assessments 2016

Region: 430

Site: BENHAVEN ELEMENTAR

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Counseling Counseling is in a general classroom space.				
Suitability - ES->Clinic The nurses office meets the space guideline but there is no cot or restroom.				
Suitability - ES->Cafeteria The cafeteria meets the size guidelines but is an older dated space.				
Suitability - ES->Food Service and Prep The kitchen area has small and the delivery area is in a difficult position.				
Suitability - ES->Outside-->Vehicular Traffic traffic lanes cross one another.				
Suitability - ES->Outside-->Pedestrian Traffic Pedestrian traffic crosses other traffic lanes.				
Suitability - ES->Outside-->Parking Parking at Benhaven is on a where it can be found basis. Parking spaces are created between and around the different buildings.				
Suitability - ES->Outside-->Play Areas The school has a large playground area but much is unimproved.				
Suitability - ES->Safety and Security-->Fencing There is some fencing but most of the campus is open.				
Suitability - ES->Safety and Security-->Signage & Way Finding There is little in the way of signage and wayfinding.				
Suitability - ES->Safety and Security-->Ease of Supervision The multiple buildings and access throughout make supervision difficult.				
Suitability - ES->Safety and Security-->Controlled Entrances Many areas are accessible. There is no entry vestibule.				

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201000877
Project: Assessments 2016	Region: 430	Site: BOONE TRAIL ELEMENT
Grade Config: KG-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Excel	5.00	5.00	100.00
Interior Environment	Excel	2.00	2.00	100.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Excel	4.90	4.90	100.00
Size	Good	9.80	12.25	80.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Good	2.94	3.68	80.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Excel	1.04	1.04	100.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Excel	0.31	0.31	100.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	Good	0.38	0.48	80.00
Size	Good	0.96	1.20	80.00
Location	Excel	0.36	0.36	100.00
Storage/Fixed Equip	Good	0.29	0.36	80.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Good	1.44	1.80	80.00
Location	Fair	0.35	0.54	65.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	1.85	1.85	100.00
Location	Excel	0.56	0.56	100.00
Storage/Fixed Equip	Good	0.44	0.56	80.00
Art				
Environment	Fair	0.30	0.47	65.00
Size	Fair	0.76	1.17	65.00
Location	Fair	0.23	0.35	65.00
Storage/Fixed Equip	Poor	0.18	0.35	50.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Poor	0.43	0.85	50.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Excel	1.92	1.92	100.00
Size	Excel	4.80	4.80	100.00
Location	Excel	1.44	1.44	100.00
Storage/Fixed Equip	Excel	1.44	1.44	100.00
Performing Arts				
Environment	Good	0.48	0.60	80.00
Size	Excel	1.51	1.51	100.00
Location	Excel	0.45	0.45	100.00
Storage/Fixed Equip	Good	0.36	0.45	80.00
Media Center				
Environment	Excel	0.97	0.97	100.00
Size	Excel	2.44	2.44	100.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Excel	0.89	0.89	100.00
Administration	Good	2.05	2.56	80.00
Counseling	Excel	0.29	0.29	100.00
Clinic	Good	0.47	0.58	80.00
Staff Lounge-WkRm	Excel	1.27	1.27	100.00
Cafeteria	Good	4.00	5.00	80.00
Food Service and Prep	Good	4.96	6.20	80.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Excel	2.00	2.00	100.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Excel	0.81	0.81	100.00
Play Areas	Good	1.87	2.34	80.00
Safety and Security				
Fencing	Good	0.60	0.75	80.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Excel	0.50	0.50	100.00

Project #: 8272

County: Harnett

Site #: 370201000877

Project: Assessments 2016

Region: 430

Site: BOONE TRAIL ELEMENT

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		82.75	95.00	87.11

Comments

Suitability - ES->General Classrooms-->Size

Classrooms in the building meet standards. 2 regular classrooms are in portables.

Suitability - ES->General Classrooms-->Location

Two classrooms are in portables. Others are located appropriately.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Storage is excellent in classrooms located in the building. 2 classrooms are in portables.

Suitability - ES->Instructional Resource Rooms-->Location

Most resource rooms are located appropriately. The ESL rooms are located next to the cafeteria and noise can be a problem.

Suitability - ES->Music-->Environment

Music is currently held in a portable. There is a music room in the main building that due to the number of general classrooms needed for the enrollment is being used as a regular classroom.

Suitability - ES->Music-->Size

Music is currently held in a portable. There is a music room in the main building that due to the number of general classrooms needed for the enrollment is being used as a regular classroom.

Suitability - ES->Music-->Location

Music is currently held in a portable. There is a music room in the main building that due to the number of general classrooms needed for the enrollment is being used as a regular classroom.

Suitability - ES->Music-->Storage/Fixed Equip

Music is currently held in a portable. There is a music room in the main building that due to the number of general classrooms needed for the enrollment is being used as a regular classroom.

Suitability - ES->Art

Currently Art is held in two portable classrooms. There is one Art room located in the building that is being used as a general classroom due to the school enrollment.

Suitability - ES->Art-->Environment

Currently Art is held in two portable classrooms. There is one Art room located in the building that is being used as a general classroom due to the school enrollment.

Suitability - ES->Art-->Size

Currently Art is held in two portable classrooms. There is one Art room located in the building that is being used as a general classroom due to the school enrollment.

Suitability - ES->Art-->Location

Currently Art is held in two portable classrooms. There is one Art room located in the building that is being used as a general classroom due to the school enrollment.

Suitability - ES->Art-->Storage/Fixed Equip

Currently Art is held in two portable classrooms. There is one Art room located in the building that is being used as a general classroom due to the school enrollment. The art room in the building includes some but not all of the storage and equipment normally associated with art classrooms.

Suitability - ES->Computer Labs-->Size

Computer labs meet approximately 60% of the standard.

Suitability - ES->Performing Arts-->Environment

Performing arts at Boone Trail is on a stage located off the gym.

Project #: 8272

County: Harnett

Site #: 370201000877

Project: Assessments 2016

Region: 430

Site: BOONE TRAIL ELEMENT

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability

Rating

Score

**Possible
Score**

**Percent
Score**

Suitability - ES->Safety and Security-->Signage & Way Finding
as rooms have changed function signage has not kept up.

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201000878
Project: Assessments 2016	Region: 430	Site: BUIES CREEK ELEMENTA
Grade Config: KG-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Fair	3.19	4.90	65.00
Size	Good	9.80	12.25	80.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Good	2.94	3.68	80.00
Kindergarten				
Environment	Good	0.33	0.42	80.00
Size	Good	0.83	1.04	80.00
Location	Good	0.25	0.31	80.00
Storage/Fixed Equip	Good	0.25	0.31	80.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Poor	0.36	0.72	50.00
Size	Fair	1.17	1.80	65.00
Location	Poor	0.27	0.54	50.00
Storage/Fixed Equip	Poor	0.27	0.54	50.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Unsat	0.00	0.74	0.00

Project #: 8272

County: Harnett

Site #: 370201000878

Project: Assessments 2016

Region: 430

Site: BUIES CREEK ELEMENTA

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Unsat	0.00	1.85	0.00
Location	Unsat	0.00	0.56	0.00
Storage/Fixed Equip	Unsat	0.00	0.56	0.00
Art				
Environment	Unsat	0.00	0.47	0.00
Size	Unsat	0.00	1.17	0.00
Location	Unsat	0.00	0.35	0.00
Storage/Fixed Equip	Unsat	0.00	0.35	0.00
Computer Labs				
Environment	Unsat	0.00	0.34	0.00
Size	Unsat	0.00	0.85	0.00
Location	Unsat	0.00	0.26	0.00
Storage/Fixed Equip	Unsat	0.00	0.26	0.00
P.E.				
Environment	Good	1.54	1.92	80.00
Size	Fair	3.12	4.80	65.00
Location	Good	1.15	1.44	80.00
Storage/Fixed Equip	Fair	0.94	1.44	65.00
Performing Arts				
Environment	Good	0.48	0.60	80.00
Size	Good	1.21	1.51	80.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Fair	0.29	0.45	65.00
Media Center				
Environment	Poor	0.49	0.97	50.00
Size	Poor	1.22	2.44	50.00
Location	Good	0.58	0.73	80.00
Storage/Fixed Equip	Poor	0.37	0.73	50.00
Restrooms (Student)	Good	0.71	0.89	80.00
Administration	Fair	1.66	2.56	65.00
Counseling	Poor	0.15	0.29	50.00
Clinic	Unsat	0.00	0.58	0.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Fair	3.25	5.00	65.00
Food Service and Prep	Fair	4.03	6.20	65.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Fair	0.53	0.81	65.00
Play Areas	Fair	1.52	2.34	65.00
Safety and Security				
Fencing	Good	0.60	0.75	80.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Fair	0.33	0.50	65.00

Project #: 8272

County: Harnett

Site #: 370201000878

Project: Assessments 2016

Region: 430

Site: BUIES CREEK ELEMENTA

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		60.40	92.60	65.22

Comments

Suitability - ES->Learning Environment-->Interior Environment

The school is older and the finishes are worn. There is limited natural light, the majority of the surfaces are hard surfaces, it has poor acoustics, and lacks the attributes of a 21st century building.

Suitability - ES->Learning Environment-->Exterior Environment

Exterior of the building has limited landscaping, and lacks inviting entrance, materials are dated and worn.

Suitability - ES->General Classrooms-->Environment

There is limited natural light, the majority of the surfaces are hard surfaces, it has poor acoustics, and lacks the attributes of a 21st century building.

Suitability - ES->Instructional Resource Rooms-->Environment

The instructional resource rooms have limited natural light, limited or no ventilation, hard surfaces and poor lighting.

Suitability - ES->Instructional Resource Rooms-->Size

The rooms meet 75% of the size standard.

Suitability - ES->Instructional Resource Rooms-->Location

One of the resource rooms is located in a portable.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip

There is a lack of adequate storage for supplies and materials.

Suitability - ES->Music-->Environment

Music is located in a portable.

Suitability - ES->Music-->Size

Music is located in a portable.

Suitability - ES->Music-->Location

Music is located in a portable.

Suitability - ES->Music-->Storage/Fixed Equip

Music is located in a portable.

Suitability - ES->Art-->Environment

Art is located in a portable.

Suitability - ES->Art-->Size

Art is located in a portable.

Suitability - ES->Art-->Location

Art is located in a portable.

Suitability - ES->Art-->Storage/Fixed Equip

Art is located in a portable.

Suitability - ES->Computer Labs-->Environment

There are no computer labs in the building due to lack of space.

Suitability - ES->Computer Labs-->Size

There are no computer labs in the building due to lack of space.

Suitability - ES->Computer Labs-->Location

There are no computer labs in the building due to lack of space.

Project #: 8272

County: Harnett

Site #: 370201000878

Project: Assessments 2016

Region: 430

Site: BUIES CREEK ELEMENTA

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Computer Labs-->Storage/Fixed Equip There are no computer labs in the building due to lack of space.				
Suitability - ES->P.E.-->Size The is only one basketball court with limited spacing before the walls limiting the number of students which can participate at one time.				
Suitability - ES->P.E.-->Storage/Fixed Equip There is limited storage for equipment and supplies.				
Suitability - ES->Performing Arts-->Storage/Fixed Equip The auditorium has older stage fixtures and lighting and limited storage for equipment and supplies.				
Suitability - ES->Media Center-->Environment The media center lacks an engaging atmosphere, natural lighting and the majority of the surfaces are old and worn.				
Suitability - ES->Media Center-->Size The media center meets 50% of the recommended size standard.				
Suitability - ES->Media Center-->Storage/Fixed Equip There is not adequate storage for supplies and equipment.				
Suitability - ES->Administration Administration is small for the number of staff. No conference room and privacy is limited.				
Suitability - ES->Counseling There is no natural light, the office has poor ventilation and does not meet the size standard.				
Suitability - ES->Clinic There is no clinic in the building, The staff uses admin spaces to treat students.				
Suitability - ES->Cafeteria The cafeteria does not meet the recommended size standard.				
Suitability - ES->Food Service and Prep The food prep area is does not meet the recommended size standard and lacks adequate storage for supplies and food products.				
Suitability - ES->Outside-->Parking Some event parking is located across the street at the college.				
Suitability - ES->Outside-->Play Areas K-2 playground equipment is older and lacks age appropriate features.				
Suitability - ES->Safety and Security-->Controlled Entrances Front entrance is not controlled by a locked system with a buzzer for visitors.				

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	1.85	1.85	100.00
Location	Excel	0.56	0.56	100.00
Storage/Fixed Equip	Good	0.44	0.56	80.00
Art				
Environment	Excel	0.47	0.47	100.00
Size	Excel	1.17	1.17	100.00
Location	Excel	0.35	0.35	100.00
Storage/Fixed Equip	Good	0.28	0.35	80.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Fair	0.55	0.85	65.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Excel	1.92	1.92	100.00
Size	Excel	4.80	4.80	100.00
Location	Excel	1.44	1.44	100.00
Storage/Fixed Equip	Excel	1.44	1.44	100.00
Performing Arts				
Environment	Excel	0.60	0.60	100.00
Size	Excel	1.51	1.51	100.00
Location	Excel	0.45	0.45	100.00
Storage/Fixed Equip	Excel	0.45	0.45	100.00
Media Center				
Environment	Excel	0.97	0.97	100.00
Size	Excel	2.44	2.44	100.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Excel	0.73	0.73	100.00
Restrooms (Student)	Good	0.71	0.89	80.00
Administration	Good	2.05	2.56	80.00
Counseling	Good	0.23	0.29	80.00
Clinic	Good	0.47	0.58	80.00
Staff Lounge-WkRm	Poor	0.63	1.27	50.00
Cafeteria	Excel	5.00	5.00	100.00
Food Service and Prep	Excel	6.20	6.20	100.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Excel	0.81	0.81	100.00
Play Areas	Excel	2.34	2.34	100.00
Safety and Security				
Fencing	Excel	0.75	0.75	100.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Good	0.40	0.50	80.00

Project #: 8272

County: Harnett

Site #: 370201000879

Project: Assessments 2016

Region: 430

Site: COATS ELEMENTARY

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		85.39	95.00	89.89

Comments

Suitability - ES->General Classrooms-->Environment

Classrooms in the building are excellent. 4 classrooms are in portables.

Suitability - ES->General Classrooms-->Size

Classrooms in the building meet or are within 10% of meeting the standard. 4 classrooms are in portables.

Suitability - ES->General Classrooms-->Location

Location of the classrooms in the building is excellent. 4 are in portables.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Storage and equipment in classrooms in the building is excellent. 4 classrooms are in portables.

Suitability - ES->Self-Contained Special Ed-->Size

One of the self contained rooms meets the size guideline, the other meets approximately 80% of the guideline.

Suitability - ES->Computer Labs-->Size

The computer lab meets approximately 65% of the size guideline.

Suitability - ES->Staff Lounge-WkRm

The only available staff lounge / workroom is very small and seldom used. Spaces intended as staff work areas have been converted to other uses.

Suitability - ES->Outside-->Vehicular Traffic

Traffic separation is excellent. The parent drop off lane often backs up onto the street.

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201000881
Project: Assessments 2016	Region: 430	Site: ERWIN ELEMENTARY
Grade Config: 03-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Poor	2.50	5.00	50.00
Interior Environment	Poor	1.00	2.00	50.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Poor	2.45	4.90	50.00
Size	Unsat	0.00	12.25	0.00
Location	Poor	1.84	3.68	50.00
Storage/Fixed Equip	Fair	2.39	3.68	65.00
Kindergarten				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Fair	0.47	0.72	65.00
Size	Good	1.44	1.80	80.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	Fair	0.33	0.50	65.00
Size	Excel	1.25	1.25	100.00
Location	Good	0.30	0.38	80.00
Storage/Fixed Equip	Good	0.30	0.38	80.00
Music				
Environment	Good	0.59	0.74	80.00

Project #: 8272

County: Harnett

Site #: 370201000881

Project: Assessments 2016

Region: 430

Site: ERWIN ELEMENTARY

Grade Config: 03-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Fair	1.20	1.85	65.00
Location	Poor	0.28	0.56	50.00
Storage/Fixed Equip	Excel	0.56	0.56	100.00
Art				
Environment	Fair	0.30	0.47	65.00
Size	Unsat	0.00	1.17	0.00
Location	Fair	0.23	0.35	65.00
Storage/Fixed Equip	Unsat	0.00	0.35	0.00
Computer Labs				
Environment	Unsat	0.00	0.34	0.00
Size	Fair	0.55	0.85	65.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Good	1.54	1.92	80.00
Size	Good	3.84	4.80	80.00
Location	Good	1.15	1.44	80.00
Storage/Fixed Equip	Good	1.15	1.44	80.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Excel	2.44	2.44	100.00
Location	Good	0.58	0.73	80.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Poor	0.44	0.89	50.00
Administration	Fair	1.66	2.56	65.00
Counseling	Fair	0.19	0.29	65.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Fair	0.82	1.27	65.00
Cafeteria	Poor	2.50	5.00	50.00
Food Service and Prep	Good	4.96	6.20	80.00
Custodial and Maintenance	Fair	0.33	0.50	65.00
Outside				
Vehicular Traffic	Unsat	0.00	2.00	0.00
Pedestrian Traffic	Fair	0.63	0.97	65.00
Parking	Unsat	0.00	0.81	0.00
Play Areas	Poor	1.17	2.34	50.00
Safety and Security				
Fencing	Good	0.60	0.75	80.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Poor	1.50	3.00	50.00
Controlled Entrances	Unsat	0.00	0.50	0.00

Project #: 8272

County: Harnett

Site #: 370201000881

Project: Assessments 2016

Region: 430

Site: ERWIN ELEMENTARY

Grade Config: 03-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		48.13	89.99	53.48

Comments

Suitability - ES->Learning Environment-->Learning Style Variety

Very limited functionality/flexibility; limited to no group space overall; available rooms are closed due to structural damage.

Suitability - ES->Learning Environment-->Interior Environment

Limited space/flexibility; overall adequate natural light; dim halls; noisy HVAC/mechanical systems; Some classes moved due to recent hurricane damage (leaks/mold/deteriorating walls); old aesthetics; hall floor very worn; areas of building restricted due to hazards/structural dangers; water fountains and sinks unusable due to lead (replaced with water cooler and hand sanitizer).

Suitability - ES->Learning Environment-->Exterior Environment

Limited space around school except for playground area which share bus lot/loading area; outdoor classroom feature; several covered walkways.

Suitability - ES->General Classrooms-->Environment

Good natural light; proper temp control except noisy; some mold in rooms vacated due to recent hurricane; old aesthetics.

Suitability - ES->General Classrooms-->Size

0% met standards for sq. footage; built-in storage and cabinets limit room space.

Suitability - ES->General Classrooms-->Location

4th grade levels current located in separate buildings due to recent hurricane damage; majority of grade levels are located in the same building and are grouped by grade.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

built-in storage; sufficient storage space, a few closets but not for every room; in tech transition - still have many old computers, some still in use.

Suitability - ES->Self-Contained Special Ed

No handicap access.

Suitability - ES->Instructional Resource Rooms-->Environment

adequate functionality/flexibility; good natural light; old aesthetics; varying temp.

Suitability - ES->Instructional Resource Rooms-->Size

Room meets standard; speech therapist / psychologist share room.

Suitability - ES->Instructional Resource Rooms-->Location

Speech therapist / psychologist share room and are upstairs; counseling is downstairs in admin.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip

Built-in storage; adequate storage space.

Suitability - ES->Science-->Environment

Limited power outlets; sinks are covered/unused.

Suitability - ES->Science-->Size

Largest class room.

Suitability - ES->Science-->Storage/Fixed Equip

Some original cabinets; built-in storage.

Suitability - ES->Music-->Environment

adequate aesthetics; limited natural lighting.

Project #: 8272

County: Harnett

Site #: 370201000881

Project: Assessments 2016

Region: 430

Site: ERWIN ELEMENTARY

Grade Config: 03-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Music-->Size Met 67% of standard.				
Suitability - ES->Music-->Location Music is isolated from gen. ed.; no visibility or camera security for entrance; uncovered entrance; no restroom for students.				
Suitability - ES->Art-->Environment Limited art work space; limited light.				
Suitability - ES->Art-->Size Met 48% of standard.				
Suitability - ES->Art-->Location Access via covered walkway; no restroom for students.				
Suitability - ES->Art-->Storage/Fixed Equip No clay traps; built in storage; 1 sink; kiln but is outside in lobby area on heat mat (no ventilation in area; supplies stored outside room in lobby near kiln; storage/kiln area does not meet standards.				
Suitability - ES->Computer Labs-->Environment Current lab limited to no use; old technology (late 90s/early 2000s); room not cool/ventilated; loud humming.				
Suitability - ES->Computer Labs-->Size Met approx. 70% of standard; lab limited/unused.				
Suitability - ES->Computer Labs-->Location Next to library; covered walkway to library from classrooms.				
Suitability - ES->Computer Labs-->Storage/Fixed Equip Good storage; currently in transition from old technology to tablets (need installation).				
Suitability - ES->P.E.-->Location Limited entrance to street parking area.				
Suitability - ES->P.E.-->Storage/Fixed Equip Old storage areas (unused locker rooms/offices).				
Suitability - ES->Performing Arts School has auditorium for ceremonies; school is an older model high school.				
Suitability - ES->Media Center-->Environment Adequate acoustics (HVAC).				
Suitability - ES->Restrooms (Student) Male/female restrooms are at opposite end of hall in main building; Music/art building has one restroom single user that is not usable by students; gaps in stall doors/walls; no handicap access; restrooms have proper ventilation.				
Suitability - ES->Administration Additional work rooms located in other buildings outside main; main office is located centrally and does not allow easy sight of visitors.				
Suitability - ES->Counseling 1 counselor located in admin w/ good secure storage; 1 psychologist is sharing room with speech therapist in 2nd floor class room.				
Suitability - ES->Clinic No fridge/restroom; no cot or room for cot; good file storage located in next room.				
Suitability - ES->Staff Lounge-WkRm Additional work rooms located in other buildings outside main; mail in main building; office equipment bare bones.				

Project #: 8272

County: Harnett

Site #: 370201000881

Project: Assessments 2016

Region: 430

Site: ERWIN ELEMENTARY

Grade Config: 03-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Cafeteria Covered walkway to entrance; noise isolated; good storage; 1 working restroom 2nd restroom under repair for leaks); 7SF per student does not meet standard.				
Suitability - ES->Food Service and Prep Limited capacity for serving breakfast for number of students.				
Suitability - ES->Custodial and Maintenance Primary storage in main building.				
Suitability - ES->Outside-->Vehicular Traffic Adequate bus parking; safety issue with car riders and loading buses; on-street pick-up at front; gravel bus loading zone by playground.				
Suitability - ES->Outside-->Pedestrian Traffic Routing to office leads visitors through middle of campus; good signage; 1 stairway non-student access; limited railing for outside walkway/stair area; majority of area fenced.				
Suitability - ES->Outside-->Parking On-street parking; limited spaces; additional parking near playground within fencing (unpaved/grass).				
Suitability - ES->Outside-->Play Areas All soft area; large space; limited/old playground equipment; one playground is mostly fenced; secondary is partially fenced by primary outer fencing but next to bus loading zone.				
Suitability - ES->Safety and Security-->Fencing Many fenced areas; lacking enclosure around secondary playground near bus loading zone.				
Suitability - ES->Safety and Security-->Signage & Way Finding Some directional signage.				
Suitability - ES->Safety and Security-->Ease of Supervision Limited sight lines in outdoor spaces between buildings; no visibility or camera for music entrance; Many hiding areas and blind spots.				
Suitability - ES->Safety and Security-->Controlled Entrances The interior is controlled to guide visitors to reception when entering office; however, visitors must enter and walk to the middle of the school campus among other buildings before reaching the main office; some signage; many blind spots; alternate entrance near music room blind spot (can only enter room on one side).				

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201000882
Project: Assessments 2016	Region: 430	Site: GENTRY PRIMARY
Grade Config: KG-02	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Unsat	0.00	2.00	0.00
Exterior Environment	Poor	0.75	1.50	50.00
General Classrooms				
Environment	Fair	3.19	4.90	65.00
Size	Fair	7.96	12.25	65.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Fair	2.39	3.68	65.00
Kindergarten				
Environment	Fair	0.27	0.42	65.00
Size	Fair	0.68	1.04	65.00
Location	Good	0.25	0.31	80.00
Storage/Fixed Equip	Poor	0.16	0.31	50.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Unsat	0.00	0.72	0.00
Size	Unsat	0.00	1.80	0.00
Location	Unsat	0.00	0.54	0.00
Storage/Fixed Equip	Unsat	0.00	0.54	0.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Project #: 8272

County: Harnett

Site #: 370201000882

Project: Assessments 2016

Region: 430

Site: GENTRY PRIMARY

Grade Config: KG-02

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	1.85	1.85	100.00
Location	Unsat	0.00	0.56	0.00
Storage/Fixed Equip	Good	0.44	0.56	80.00
Art				
Environment	Unsat	0.00	0.47	0.00
Size	Unsat	0.00	1.17	0.00
Location	Unsat	0.00	0.35	0.00
Storage/Fixed Equip	Unsat	0.00	0.35	0.00
Computer Labs				
Environment	Fair	0.22	0.34	65.00
Size	Poor	0.43	0.85	50.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Poor	0.13	0.26	50.00
P.E.				
Environment	Good	1.54	1.92	80.00
Size	Excel	4.80	4.80	100.00
Location	Good	1.15	1.44	80.00
Storage/Fixed Equip	Fair	0.94	1.44	65.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Fair	1.58	2.44	65.00
Location	Fair	0.48	0.73	65.00
Storage/Fixed Equip	Fair	0.48	0.73	65.00
Restrooms (Student)	Unsat	0.00	0.89	0.00
Administration	Poor	1.28	2.56	50.00
Counseling	Poor	0.15	0.29	50.00
Clinic	Poor	0.29	0.58	50.00
Staff Lounge-WkRm	Fair	0.82	1.27	65.00
Cafeteria	Poor	2.50	5.00	50.00
Food Service and Prep	Good	4.96	6.20	80.00
Custodial and Maintenance	Fair	0.33	0.50	65.00
Outside				
Vehicular Traffic	Fair	1.30	2.00	65.00
Pedestrian Traffic	Fair	0.63	0.97	65.00
Parking	Fair	0.53	0.81	65.00
Play Areas	Unsat	0.00	2.34	0.00
Safety and Security				
Fencing	Unsat	0.00	0.75	0.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Poor	1.50	3.00	50.00
Controlled Entrances	Poor	0.25	0.50	50.00

Project #: 8272

County: Harnett

Site #: 370201000882

Project: Assessments 2016

Region: 430

Site: GENTRY PRIMARY

Grade Config: KG-02

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		52.63	89.58	58.75

Comments

Suitability - ES->Learning Environment-->Learning Style Variety
Flexibility for groups; built-ins take up space.

Suitability - ES->Learning Environment-->Interior Environment
Noise disruption common; possible mold/mushrooms growing in classrooms; piping with water causes disruption; good natural light; several configurations; temperature varies (hot/cold); aesthetics limited; windows leak; HVAC insufficient/unreliable/leaks; pest issues (mice); asbestos.

Suitability - ES->Learning Environment-->Exterior Environment
Some outside spaces, picnic area, garden; uncovered walkways; wooden walks cause splinters and can ice over; no concrete walkway in front and students track mud inside / wet shoes; no gutters - water runs through pipes through classroom; possible lead paint.

Suitability - ES->General Classrooms-->Environment
Good natural light; some mold; piping for rain runs through classrooms and causes noise; room for groups/flexibility.

Suitability - ES->General Classrooms-->Size
Met 66% of standard. Built-ins take up space.

Suitability - ES->General Classrooms-->Storage/Fixed Equip
Built-ins; some supplies stacked.

Suitability - ES->Kindergarten-->Environment
Good natural light; some mold; piping for rain runs through classrooms and causes noise; room for groups/flexibility.

Suitability - ES->Kindergarten-->Size
Met 79% of standard; Built-ins take up space.

Suitability - ES->Kindergarten-->Storage/Fixed Equip
One K-class does not have a bathroom in-room. 2 rooms have exit doors (push open; safety hazard); built-ins; some supplies stacked.

Suitability - ES->Instructional Resource Rooms-->Environment
In portables.

Suitability - ES->Instructional Resource Rooms-->Size
In portables.

Suitability - ES->Instructional Resource Rooms-->Location
In portables; some tutoring conducted on stage located in cafeteria.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip
In portables.

Suitability - ES->Music-->Environment
Older aesthetics.

Suitability - ES->Music-->Size
Met 90% of standard.

Suitability - ES->Music-->Location
Located near library and the nurse is located in an office inside the music room; also located near K-classrooms.

Suitability - ES->Music-->Storage/Fixed Equip
A variety of instruments; sound proofing on walls, but some are falling down.

Project #: 8272

County: Harnett

Site #: 370201000882

Project: Assessments 2016

Region: 430

Site: GENTRY PRIMARY

Grade Config: KG-02

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Art-->Environment Located in portable.				
Suitability - ES->Art-->Size Located in portable.				
Suitability - ES->Art-->Location Located in portable.				
Suitability - ES->Art-->Storage/Fixed Equip Located in portable.				
Suitability - ES->Computer Labs-->Environment Limited natural light; temp fluctuates.				
Suitability - ES->Computer Labs-->Size Met 52% of standard.				
Suitability - ES->Computer Labs-->Storage/Fixed Equip Some fixed equipment; many computers are old/broken.				
Suitability - ES->P.E.-->Storage/Fixed Equip Free-standing basketball goal; has rock climbing area; bleachers are old but work; sound and AC issues.				
Suitability - ES->Media Center-->Size Met 78% of standard.				
Suitability - ES->Media Center-->Location Located away from classrooms, near to music class.				
Suitability - ES->Media Center-->Storage/Fixed Equip Old/broken computers.				
Suitability - ES->Restrooms (Student) In student bathrooms, several stall doors are installed backwards and have resulted in student injury and hospital visits; occasional sewage odors, no hot water; sufficient number and in location; water occasionally discolored; one staff bathroom missing a door.				
Suitability - ES->Administration Some admin offices located together; AP has office in classroom; guidance is in classroom; records room is located in staff workroom and is too small (can't open multiple drawers on both sides).				
Suitability - ES->Counseling Located in classroom; records are stored in another area (small records room).				
Suitability - ES->Clinic Located next/in music room. Only entrance to nurse is through music room; bathroom and sink unused/do not work; no cot but has room for one; locked med cabinet is located in office (nurse does not distribute medication; distributed by principal/secretary).				
Suitability - ES->Staff Lounge-WkRm Staff fridge is located next to the stage in cafeteria where tutoring is; sufficient office equipment.				
Suitability - ES->Cafeteria Cafeteria does not have doors and noise enters hallway; delivery area is located by the bus lot and where students enter the school; AC units in cafeteria leak from ceiling and drip on tables (tables staggered to avoid drips).				
Suitability - ES->Food Service and Prep Breakfast line can be crowded.				

Project #: 8272

County: Harnett

Site #: 370201000882

Project: Assessments 2016

Region: 430

Site: GENTRY PRIMARY

Grade Config: KG-02

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Custodial and Maintenance Some supplies housed in staff bathroom.				
Suitability - ES->Outside-->Vehicular Traffic Cones used to guide traffic away from pedestrians; unclear signage on where visitors park/enter.				
Suitability - ES->Outside-->Pedestrian Traffic Bus riders pass by kitchen delivery area when entering building; carpool lot has conflicts between traffic/pedestrians (cones in use).				
Suitability - ES->Outside-->Parking Some areas marked; some staff parking on grass; bus parking good.				
Suitability - ES->Outside-->Play Areas Only soft surface; area not fully enclosed (used by all students, including K) and have had deer enter; one play set is taped off and unusable; basketball goal on gravel/grass; large playground space; no shade.				
Suitability - ES->Safety and Security-->Fencing Part of fence damaged/down from tree; playground (used by all students including K) is not fully enclosed. Fencing old/rusted/disfigured.				
Suitability - ES->Safety and Security-->Signage & Way Finding Inside signage is good; outside signage is missing/confusing; no visitor signage; no distinct signage to indicate the front of the building or the location of the office; the front of the building (office area) is located at the back of the school.				
Suitability - ES->Safety and Security-->Ease of Supervision Very few hiding areas/good line of sight inside; cameras missing in places inside/outside; cameras due for upgrade; no keyless entry.				
Suitability - ES->Safety and Security-->Controlled Entrances Two K-rooms have exit doors (push open; safety hazard); One exit you can only exit - cannot reenter; the front of the school is located at the back; confusing as to where visitors should enter.				

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201000883
Project: Assessments 2016	Region: 430	Site: HARNETT PRIMARY
Grade Config: KG-03	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Excel	5.00	5.00	100.00
Interior Environment	Excel	2.00	2.00	100.00
Exterior Environment	Excel	1.50	1.50	100.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Excel	12.25	12.25	100.00
Location	Excel	3.68	3.68	100.00
Storage/Fixed Equip	Excel	3.68	3.68	100.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Excel	1.04	1.04	100.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Excel	0.31	0.31	100.00
ECE				
Environment	Good	0.40	0.50	80.00
Size	Fair	0.81	1.25	65.00
Location	Good	0.30	0.37	80.00
Storage/Fixed Equip	Excel	0.37	0.37	100.00
Self-Contained Special Ed				
Environment	Good	0.38	0.48	80.00
Size	Excel	1.20	1.20	100.00
Location	Good	0.29	0.36	80.00
Storage/Fixed Equip	Good	0.29	0.36	80.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Excel	1.80	1.80	100.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	Good	0.40	0.50	80.00
Size	Excel	1.25	1.25	100.00
Location	Good	0.30	0.38	80.00
Storage/Fixed Equip	Fair	0.24	0.38	65.00
Music				
Environment	Good	0.59	0.74	80.00

Project #: 8272

County: Harnett

Site #: 370201000883

Project: Assessments 2016

Region: 430

Site: HARNETT PRIMARY

Grade Config: KG-03

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	1.48	1.85	80.00
Location	Good	0.44	0.56	80.00
Storage/Fixed Equip	Good	0.44	0.56	80.00
Art				
Environment	Excel	0.47	0.47	100.00
Size	Excel	1.17	1.17	100.00
Location	Good	0.28	0.35	80.00
Storage/Fixed Equip	Excel	0.35	0.35	100.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Excel	0.85	0.85	100.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Excel	0.26	0.26	100.00
P.E.				
Environment	Fair	1.25	1.92	65.00
Size	Excel	4.80	4.80	100.00
Location	Good	1.15	1.44	80.00
Storage/Fixed Equip	Fair	0.94	1.44	65.00
Performing Arts				
Environment	Fair	0.39	0.60	65.00
Size	Good	1.21	1.51	80.00
Location	Excel	0.45	0.45	100.00
Storage/Fixed Equip	Excel	0.45	0.45	100.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Good	1.95	2.44	80.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Excel	0.73	0.73	100.00
Restrooms (Student)	Good	0.71	0.89	80.00
Administration	Excel	2.56	2.56	100.00
Counseling	Excel	0.29	0.29	100.00
Clinic	Unsat	0.00	0.58	0.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Good	4.00	5.00	80.00
Food Service and Prep	Excel	6.20	6.20	100.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Good	0.65	0.81	80.00
Play Areas	Good	1.87	2.34	80.00
Safety and Security				
Fencing	Fair	0.49	0.75	65.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Fair	0.33	0.50	65.00

Project #: 8272

County: Harnett

Site #: 370201000883

Project: Assessments 2016

Region: 430

Site: HARNETT PRIMARY

Grade Config: KG-03

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		89.43	100.00	89.43

Comments

Suitability - ES

Harnett PS is K-3 PBIS (Positive Behavior Intervention Support) school that uses a variety of instructional models throughout the building to help all students learn. The staff use all available space to deliver a wide variety of educational programs.

Suitability - ES->ECE-->Size

ECE classrooms size requirement is 1,400 square feet. Harnett PS ECE classrooms meet 68% of standard.

Suitability - ES->Science-->Storage/Fixed Equip

Science is located in a general education classroom lacking the appropriate furniture, equipment and storage.

Suitability - ES->P.E.-->Environment

Spatial configuration of the gymnasium is too small to align with instructional program and lighting in the space is limited.

Suitability - ES->P.E.-->Storage/Fixed Equip

Gymnasium lacks secure closet space.

Suitability - ES->Performing Arts-->Environment

Stage is small, and seating is limited based on cafeteria tables.

Suitability - ES->Restrooms (Student)

The restrooms are appropriately located, but lacking adequate number of restrooms. Fixtures are older.

Suitability - ES->Clinic

No clinic located on the property.

Suitability - ES->Cafeteria

The cafeteria space is an average size, but lacks table storage.

Suitability - ES->Safety and Security-->Fencing

Lack of perimeter fencing on the property. There is one fence located along the rear perimeter of the property.

Suitability - ES->Safety and Security-->Controlled Entrances

Front entrance not controlled. All other exterior entrances controlled.

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201002630
Project: Assessments 2016	Region: 430	Site: HIGHLAND ELEMENTAR
Grade Config: KG-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Fair	3.19	4.90	65.00
Size	Fair	7.96	12.25	65.00
Location	Fair	2.39	3.68	65.00
Storage/Fixed Equip	Fair	2.39	3.68	65.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Excel	1.04	1.04	100.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Excel	0.31	0.31	100.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	Excel	0.48	0.48	100.00
Size	Poor	0.60	1.20	50.00
Location	Excel	0.36	0.36	100.00
Storage/Fixed Equip	Fair	0.23	0.36	65.00
Instructional Resource Rooms				
Environment	Fair	0.47	0.72	65.00
Size	Fair	1.17	1.80	65.00
Location	Fair	0.35	0.54	65.00
Storage/Fixed Equip	Fair	0.35	0.54	65.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Unsat	0.00	0.74	0.00

Project #: 8272

County: Harnett

Site #: 370201002630

Project: Assessments 2016

Region: 430

Site: HIGHLAND ELEMENTAR

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Unsat	0.00	1.85	0.00
Location	Unsat	0.00	0.56	0.00
Storage/Fixed Equip	Unsat	0.00	0.56	0.00
Art				
Environment	Unsat	0.00	0.47	0.00
Size	Unsat	0.00	1.17	0.00
Location	Unsat	0.00	0.35	0.00
Storage/Fixed Equip	Unsat	0.00	0.35	0.00
Computer Labs				
Environment	Unsat	0.00	0.34	0.00
Size	Unsat	0.00	0.85	0.00
Location	Unsat	0.00	0.26	0.00
Storage/Fixed Equip	Unsat	0.00	0.26	0.00
P.E.				
Environment	Excel	1.92	1.92	100.00
Size	Excel	4.80	4.80	100.00
Location	Excel	1.44	1.44	100.00
Storage/Fixed Equip	Excel	1.44	1.44	100.00
Performing Arts				
Environment	Excel	0.60	0.60	100.00
Size	Fair	0.98	1.51	65.00
Location	Excel	0.45	0.45	100.00
Storage/Fixed Equip	Excel	0.45	0.45	100.00
Media Center				
Environment	Excel	0.97	0.97	100.00
Size	Fair	1.58	2.44	65.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Fair	0.48	0.73	65.00
Restrooms (Student)	Fair	0.58	0.89	65.00
Administration	Good	2.05	2.56	80.00
Counseling	Fair	0.19	0.29	65.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Fair	3.25	5.00	65.00
Food Service and Prep	Fair	4.03	6.20	65.00
Custodial and Maintenance	Fair	0.33	0.50	65.00
Outside				
Vehicular Traffic	Fair	1.30	2.00	65.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Good	0.65	0.81	80.00
Play Areas	Fair	1.52	2.34	65.00
Safety and Security				
Fencing	Good	0.60	0.75	80.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Poor	1.50	3.00	50.00
Controlled Entrances	Fair	0.33	0.50	65.00

Project #: 8272

County: Harnett

Site #: 370201002630

Project: Assessments 2016

Region: 430

Site: HIGHLAND ELEMENTAR

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		62.62	95.00	65.92

Comments

Suitability - ES

Highlands Elementary School is a kindergarten through fifth grade facility. It is located in a rural setting. The school serves students with autism. The building was built in 2002. The school currently utilizes 16 portable classrooms.

Suitability - ES->Learning Environment-->Learning Style Variety

The school was not designed with small group or individualized instructional spaces. The interior general classrooms are large enough to be configured into small group areas. However, the school also utilizes 13 portables as general classrooms.

Suitability - ES->Learning Environment-->Interior Environment

The interior environment of the school is very conducive to student learning. The school utilizes 13 portable classrooms.

Suitability - ES->Learning Environment-->Exterior Environment

The school has two covered areas with picnic tables on the playground for student socialization. The grounds have numerous places where the soil is exposed and grass does not grow.

Suitability - ES->General Classrooms-->Environment

The general classrooms in the main building have a very positive educational environment. The school in addition utilizes 13 general education classrooms. All fifth grade students and fourth grade students are housed in portable classrooms.

Suitability - ES->General Classrooms-->Size

The internal classrooms meet the size standard, however the school utilizes 13 portable classrooms.

Suitability - ES->General Classrooms-->Location

The school utilizes 13 portable classrooms which are located a significant distance from many of the internal instructional support spaces, parent drop off zone, and administrative offices. Many of the portable classrooms do not have restrooms.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

The internal general classrooms are well-equipped with storage cabinetry, sinks and technology equipment. The school utilizes 13 portable general classrooms.

Suitability - ES->Self-Contained Special Ed-->Size

The school has two instructional spaces for autistic children. One of the spaces is approximately 375 ft.?. It is very small. The small classroom does not have a restroom.

Suitability - ES->Self-Contained Special Ed-->Storage/Fixed Equip

The small autistic classroom has some built in cabinetry but it is not sufficient for the needed supplies and materials.

Suitability - ES->Instructional Resource Rooms-->Environment

Resource teachers are located in numerous environments such as the multipurpose room, book room, and records room. The spaces are not a stimulating educational environment.

Suitability - ES->Instructional Resource Rooms-->Size

The resource rooms that were designed for that purpose are adequate in size and meet the standards. Due to the student population, reading recovery and other tutorial programs are being taught in a multipurpose room, book room, records room which are not adequate in size.

Suitability - ES->Instructional Resource Rooms-->Location

Some of the resource rooms are located in spaces designed for other purposes such as a storage of records or multipurpose room.

Project #: 8272

County: Harnett

Site #: 370201002630

Project: Assessments 2016

Region: 430

Site: HIGHLAND ELEMENTAR

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip The resource rooms that were designed for that purpose do have adequate storage. The other spaces that are being used such as the records room do not have any built in cabinetry for storage.				
Suitability - ES->Music The school has a room that was designed for music instruction. It is currently being used as a third grade classroom.				
Suitability - ES->Music-->Environment Music is taught in a portable classroom.				
Suitability - ES->Music-->Size Music is taught in a portable classroom.				
Suitability - ES->Music-->Location Music is taught in a portable classroom.				
Suitability - ES->Music-->Storage/Fixed Equip Music is taught in a portable classroom.				
Suitability - ES->Art The school does have a room that was originally designed as an art room. It is currently being used for third grade.				
Suitability - ES->Art-->Environment Art is being taught in a portable classroom.				
Suitability - ES->Art-->Size Art is being taught in a portable classroom.				
Suitability - ES->Art-->Location Art is being taught in a portable classroom.				
Suitability - ES->Art-->Storage/Fixed Equip Art is being taught in a portable classroom.				
Suitability - ES->Computer Labs-->Environment The school does not have a computer lab.				
Suitability - ES->Computer Labs-->Size The school does not have a computer lab.				
Suitability - ES->Computer Labs-->Location The school does not have a computer lab.				
Suitability - ES->Computer Labs-->Storage/Fixed Equip The school does not have a computer lab.				
Suitability - ES->P.E.-->Location Two days a week physical education is also taught in the multipurpose room. The multipurpose room was originally designed as a physical education space.				
Suitability - ES->Performing Arts The stage is located at one end of the multipurpose room.				
Suitability - ES->Performing Arts-->Size The multipurpose room cannot seat the entire student body. For student school programs the largest group that is can be seated is one grade level.				
Suitability - ES->Media Center-->Size The media center is a proximally 75% of the size standard.				

Project #: 8272

County: Harnett

Site #: 370201002630

Project: Assessments 2016

Region: 430

Site: HIGHLAND ELEMENTAR

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
<p>Suitability - ES->Media Center-->Storage/Fixed Equip Many of the originally designed support spaces for the media center are now being used for other purposes. One wing of the media center has been blocked off for a military liaison office.</p>				
<p>Suitability - ES->Restrooms (Student) Students located in the portables do not have access to restrooms unless they come into the main building. Some of the boys restrooms do not have urinal partitions.</p>				
<p>Suitability - ES->Administration The conference room is used as a testing room. The hallway that accesses the administrative offices is extremely narrow.</p>				
<p>Suitability - ES->Counseling Student records are stored in a media center storage room. The space also houses a reading recovery teacher.</p>				
<p>Suitability - ES->Clinic The school has a nurse's office that is not equipped with any cots.</p>				
<p>Suitability - ES->Staff Lounge-WkRm The school has numerous workrooms. The workrooms do not have counter space which is adequate for the assembly of materials. The school does not have a staff lounge.</p>				
<p>Suitability - ES->Cafeteria The cafeteria is approximately 65% of the size standard for the student population.</p>				
<p>Suitability - ES->Food Service and Prep The food preparation area is small for the number of meals being prepared and the number of staff.</p>				
<p>Suitability - ES->Custodial and Maintenance The portables are not equipped with custodial closets. Custodial supplies and equipment must be carried to each of the portables for cleaning.</p>				
<p>Suitability - ES->Outside-->Vehicular Traffic The parent drop off lane runs directly through the main parking lot. Due to the number of parents dropping off individuals cannot access the parking lot. Instead staff are parking on the grassy areas on the perimeter of the playground. There are adequate parking spots in the parking lot.</p>				
<p>Suitability - ES->Outside-->Pedestrian Traffic The school does not have covered walkways to the portable classrooms.</p>				
<p>Suitability - ES->Outside-->Parking The number of parking spots are adequate, however due to the congestion associated with parents dropping off and picking up students individuals cannot access the parking lot and are parking on grassy areas.</p>				
<p>Suitability - ES->Outside-->Play Areas The school does not have a separately fenced play area for the children with autism.</p>				
<p>Suitability - ES->Safety and Security-->Fencing The school does not have adequate fencing on the perimeter in front of the building.</p>				
<p>Suitability - ES->Safety and Security-->Signage & Way Finding The school does not have adequate internal and external directional signage.</p>				
<p>Suitability - ES->Safety and Security-->Ease of Supervision Due to the utilization of 16 portables and the configuration of the hallways, line of sight supervision of the building is extremely difficult.</p>				
<p>Suitability - ES->Safety and Security-->Controlled Entrances Due to the use of portables, a gym building that is separate from the main building, many doors remain unlocked throughout the school day. The school is equipped with a security vestibule at the main entrance.</p>				

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201000885
Project: Assessments 2016	Region: 430	Site: JOHNSONVILLE ELEME
Grade Config: KG-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Poor	0.75	1.50	50.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Unsat	0.00	12.25	0.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Fair	2.39	3.68	65.00
Kindergarten				
Environment	Good	0.33	0.42	80.00
Size	Excel	1.04	1.04	100.00
Location	Good	0.25	0.31	80.00
Storage/Fixed Equip	Good	0.25	0.31	80.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	Good	0.38	0.48	80.00
Size	Excel	1.20	1.20	100.00
Location	Good	0.29	0.36	80.00
Storage/Fixed Equip	Fair	0.23	0.36	65.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Excel	1.80	1.80	100.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	Good	0.40	0.50	80.00
Size	Good	1.00	1.25	80.00
Location	Good	0.30	0.38	80.00
Storage/Fixed Equip	Fair	0.24	0.38	65.00
Music				
Environment	Unsat	0.00	0.74	0.00

Project #: 8272

County: Harnett

Site #: 370201000885

Project: Assessments 2016

Region: 430

Site: JOHNSONVILLE ELEME

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Unsat	0.00	1.85	0.00
Location	Unsat	0.00	0.56	0.00
Storage/Fixed Equip	Unsat	0.00	0.56	0.00
Art				
Environment	Good	0.37	0.47	80.00
Size	Excel	1.17	1.17	100.00
Location	Fair	0.23	0.35	65.00
Storage/Fixed Equip	Fair	0.23	0.35	65.00
Computer Labs				
Environment	Poor	0.17	0.34	50.00
Size	Fair	0.55	0.85	65.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Fair	1.25	1.92	65.00
Size	Good	3.84	4.80	80.00
Location	Excel	1.44	1.44	100.00
Storage/Fixed Equip	Fair	0.94	1.44	65.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Excel	0.97	0.97	100.00
Size	Excel	2.44	2.44	100.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Fair	0.48	0.73	65.00
Restrooms (Student)	Fair	0.58	0.89	65.00
Administration	Good	2.05	2.56	80.00
Counseling	Poor	0.15	0.29	50.00
Clinic	Good	0.47	0.58	80.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Fair	3.25	5.00	65.00
Food Service and Prep	Good	4.96	6.20	80.00
Custodial and Maintenance	Fair	0.33	0.50	65.00
Outside				
Vehicular Traffic	Poor	1.00	2.00	50.00
Pedestrian Traffic	Fair	0.63	0.97	65.00
Parking	Unsat	0.00	0.81	0.00
Play Areas	Good	1.87	2.34	80.00
Safety and Security				
Fencing	Good	0.60	0.75	80.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Good	0.40	0.50	80.00

Project #: 8272

County: Harnett

Site #: 370201000885

Project: Assessments 2016

Region: 430

Site: JOHNSONVILLE ELEME

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		59.88	94.48	63.38

Comments

Suitability - ES->Learning Environment-->Exterior Environment
Limited to playground area/field.

Suitability - ES->General Classrooms-->Environment
All have natural light, varying in amount; noise a problem in some areas from other classes.

Suitability - ES->General Classrooms-->Size
All K met standard; all other grades failed to meet standard.

Suitability - ES->General Classrooms-->Location
Good locations and grouped by levels; located away from gym/cafeteria, but can hear noise from other classes and halls.

Suitability - ES->General Classrooms-->Storage/Fixed Equip
Some closet space (limited) and built-ins in all; some fixed equipment not used and taking up space (extra sinks/counters).

Suitability - ES->Self-Contained Special Ed-->Storage/Fixed Equip
Limited equip; built-in storage; limited closet space.

Suitability - ES->Science-->Storage/Fixed Equip
Built-in storage; 1 sink (low water pressure); limited equipment; limited storage/built-ins.

Suitability - ES->Music-->Environment
Located in portable.

Suitability - ES->Music-->Size
Located in portable.

Suitability - ES->Music-->Location
Located in portable.

Suitability - ES->Music-->Storage/Fixed Equip
Located in portable.

Suitability - ES->Art-->Environment
Met 91% of standard sq. footage; limited natural light; limited flexibility in configuration.

Suitability - ES->Art-->Size
Met 91% of standard sq. footage.

Suitability - ES->Art-->Location
Limited natural light; not in central location.

Suitability - ES->Art-->Storage/Fixed Equip
Built-ins; lack of storage space; 1 sink w/ clay trap; no kiln.

Suitability - ES->Computer Labs-->Environment
Room very warm and has no/little ventilation; fixed equipment; limited natural light.

Suitability - ES->Computer Labs-->Size
Met 70% of standard.

Suitability - ES->Computer Labs-->Location
Joined to media center; central location.

Project #: 8272

County: Harnett

Site #: 370201000885

Project: Assessments 2016

Region: 430

Site: JOHNSONVILLE ELEME

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->P.E.-->Environment Old bleachers (not in use); uses chairs for assemblies; lack of storage for chairs/tables and are stored on gym floor.				
Suitability - ES->P.E.-->Storage/Fixed Equip Lack of storage for chairs/tables and are stored on gym floor.				
Suitability - ES->Media Center-->Storage/Fixed Equip Limited storage; rearranged cases to make area in media space for storage.				
Suitability - ES->Restrooms (Student) 1 single use restroom (non-student) located near Art / EC; have to go outside to access student restrooms in other areas; 1 set of urinals lack privacy screens.				
Suitability - ES->Counseling 80% in portables.				
Suitability - ES->Clinic Has record area, locked med cabinet; lack cot/room for cot.				
Suitability - ES->Staff Lounge-WkRm Several workrooms located throughout; limited office technology in some.				
Suitability - ES->Cafeteria Met 61% of standard; crowded at breakfast.				
Suitability - ES->Food Service and Prep Delivery is located near the playground and lacks divider.				
Suitability - ES->Custodial and Maintenance Cramped storage space; located near admin; only 1 closet.				
Suitability - ES->Outside-->Vehicular Traffic access to buses safety issue; crowded morning drop-off traffic (3 lanes); poor bus parking.				
Suitability - ES->Outside-->Pedestrian Traffic Interior good; exterior lacks covered walkway in one high traffic area; access to buses safety issue.				
Suitability - ES->Outside-->Parking Very little paved parking for staff, visitors and buses. Staff and several buses park in grass/gravel/unmarked areas; Buses are located in front of the building (not separate lot); faded paint lines; limited signage; parking is off-street except for front where visitor and admin staff use parking in drop off lanes.				
Suitability - ES->Safety and Security-->Fencing Lacking some fence near property line / woods.				
Suitability - ES->Safety and Security-->Signage & Way Finding Lacking some exterior/interior signage.				
Suitability - ES->Safety and Security-->Ease of Supervision Limited sight in older section (EC / Art area); good sight in others; 22 security cameras; lacking camera at front exterior.				
Suitability - ES->Safety and Security-->Controlled Entrances Double-door access and front enters at office, however, lacks security camera for front of building.				

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201000886
Project: Assessments 2016	Region: 430	Site: LAFAYETTE ELEMENTA
Grade Config: KG-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Poor	1.00	2.00	50.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Fair	3.19	4.90	65.00
Size	Good	9.80	12.25	80.00
Location	Fair	2.39	3.68	65.00
Storage/Fixed Equip	Fair	2.39	3.68	65.00
Kindergarten				
Environment	Good	0.33	0.42	80.00
Size	Good	0.83	1.04	80.00
Location	Good	0.25	0.31	80.00
Storage/Fixed Equip	Excel	0.31	0.31	100.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	Fair	0.31	0.48	65.00
Size	Fair	0.78	1.20	65.00
Location	Fair	0.23	0.36	65.00
Storage/Fixed Equip	Poor	0.18	0.36	50.00
Instructional Resource Rooms				
Environment	Poor	0.36	0.72	50.00
Size	Poor	0.90	1.80	50.00
Location	Poor	0.27	0.54	50.00
Storage/Fixed Equip	Poor	0.27	0.54	50.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Unsat	0.00	0.74	0.00

Project #: 8272

County: Harnett

Site #: 370201000886

Project: Assessments 2016

Region: 430

Site: LAFAYETTE ELEMENTA

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Unsat	0.00	1.85	0.00
Location	Unsat	0.00	0.56	0.00
Storage/Fixed Equip	Unsat	0.00	0.56	0.00
Art				
Environment	Unsat	0.00	0.47	0.00
Size	Unsat	0.00	1.17	0.00
Location	Unsat	0.00	0.35	0.00
Storage/Fixed Equip	Unsat	0.00	0.35	0.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Good	0.68	0.85	80.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Fair	1.25	1.92	65.00
Size	Excel	4.80	4.80	100.00
Location	Fair	0.94	1.44	65.00
Storage/Fixed Equip	Fair	0.94	1.44	65.00
Performing Arts				
Environment	Unsat	0.00	0.60	0.00
Size	Unsat	0.00	1.51	0.00
Location	Unsat	0.00	0.45	0.00
Storage/Fixed Equip	Unsat	0.00	0.45	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Fair	1.58	2.44	65.00
Location	Good	0.58	0.73	80.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Fair	0.58	0.89	65.00
Administration	Good	2.05	2.56	80.00
Counseling	Fair	0.19	0.29	65.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Poor	0.63	1.27	50.00
Cafeteria	Unsat	0.00	5.00	0.00
Food Service and Prep	Good	4.96	6.20	80.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Excel	0.81	0.81	100.00
Play Areas	Fair	1.52	2.34	65.00
Safety and Security				
Fencing	Fair	0.49	0.75	65.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Poor	1.50	3.00	50.00
Controlled Entrances	Poor	0.25	0.50	50.00

Project #: 8272

County: Harnett

Site #: 370201000886

Project: Assessments 2016

Region: 430

Site: LAFAYETTE ELEMENTA

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		57.63	95.00	60.67

Comments

Suitability - ES->Learning Environment-->Learning Style Variety

Lafayette Elementary consists of a variety of spaces/buildings that have been added to and revised over the years. Some flexible spaces exist but not throughout.

Suitability - ES->Learning Environment-->Interior Environment

The newer sections of the school provide a good environment while the older spaces are dated. Circulation is difficult due to the number of unaligned corridors.

Suitability - ES->Learning Environment-->Exterior Environment

There are spaces between the buildings that could be used as outdoor learning space but none are developed.

Suitability - ES->General Classrooms-->Environment

Lafayette Elementary School has a wide variety of general classroom spaces. Those in the newer sections provide an excellent environment while others are located in old shop spaces.

Suitability - ES->General Classrooms-->Size

General classrooms range from meeting the size requirement to meeting 75% of the requirement.

Suitability - ES->General Classrooms-->Location

General classrooms are located throughout different buildings and additions.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

General classrooms range from excellent storage and equipment to minimal storage.

Suitability - ES->Self-Contained Special Ed-->Environment

One self contained early childhood room is located in the building and provides a good environment. One is located in a portable.

Suitability - ES->Self-Contained Special Ed-->Size

One self contained early childhood room is located in the building and meets the size standard. One is located in a portable.

Suitability - ES->Self-Contained Special Ed-->Location

One self contained early childhood room is located appropriately in the building. One is located in a portable.

Suitability - ES->Self-Contained Special Ed-->Storage/Fixed Equip

The self contained early childhood room located in the building includes good storage and a restroom but lacks other built in equipment normally associated with this space. One room is located in a portable.

Suitability - ES->Instructional Resource Rooms-->Environment

Approximately 1/2 of resource rooms are in portables.

Suitability - ES->Instructional Resource Rooms-->Size

Approximately 1/2 of resource rooms are in portables.

Suitability - ES->Instructional Resource Rooms-->Location

Approximately 1/2 of resource rooms are in portables.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip

Approximately 1/2 of resource rooms are in portables.

Suitability - ES->Music-->Environment

Music is located in a portable.

Suitability - ES->Music-->Size

Music is located in a portable.

Project #: 8272

County: Harnett

Site #: 370201000886

Project: Assessments 2016

Region: 430

Site: LAFAYETTE ELEMENTA

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Music-->Location Music is located in a portable.				
Suitability - ES->Music-->Storage/Fixed Equip Music is located in a portable.				
Suitability - ES->Art-->Environment Art is located in a portable.				
Suitability - ES->Art-->Size Art is located in a portable.				
Suitability - ES->Art-->Location Art is located in a portable.				
Suitability - ES->Art-->Storage/Fixed Equip Art is located in a portable.				
Suitability - ES->Computer Labs-->Size The computer lab meets approximately 80% of the size standard.				
Suitability - ES->P.E.-->Environment The gym is an old building that, while providing good PE space is environmentally dated.				
Suitability - ES->P.E.-->Location The gym is located in the center of the campus providing good access from many of the instructional areas but does not have good outside access.				
Suitability - ES->P.E.-->Storage/Fixed Equip PE equipment is dated. Storage is in old locker room spaces.				
Suitability - ES->Performing Arts-->Environment Lafayette Elementary has no performing arts space.				
Suitability - ES->Performing Arts-->Size Lafayette Elementary has no performing arts space.				
Suitability - ES->Performing Arts-->Location Lafayette Elementary has no performing arts space.				
Suitability - ES->Performing Arts-->Storage/Fixed Equip Lafayette Elementary has no performing arts space.				
Suitability - ES->Media Center-->Size The media center meets approximately 70% of the size guideline.				
Suitability - ES->Restrooms (Student) The number of student restrooms is minimal for the enrollment.				
Suitability - ES->Counseling The counseling office is located in a classroom wing and consists of one room with visual access to the hallway.				
Suitability - ES->Clinic The clinic meets size guidelines but does not have a cot.				
Suitability - ES->Staff Lounge-WkRm The staff lounge / workroom is small and poorly located.				
Suitability - ES->Cafeteria The cafeteria space meets less than 50% of the guideline.				

Project #: 8272

County: Harnett

Site #: 370201000886

Project: Assessments 2016

Region: 430

Site: LAFAYETTE ELEMENTA

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability

Rating

Score

**Possible
Score**

**Percent
Score**

Suitability - ES->Outside-->Play Areas

Playgrounds are located in different areas around the school and some do not have good access.

Suitability - ES->Safety and Security-->Fencing

While the school site is fenced, there are numerous entrances. The fencing for the K-1 playground is inadequate.

Suitability - ES->Safety and Security-->Signage & Way Finding

Most areas are signed. The configuration of the building makes wayfinding difficult.

Suitability - ES->Safety and Security-->Ease of Supervision

The multiple buildings, unaligned hallways, and portables make supervision difficult.

Suitability - ES->Safety and Security-->Controlled Entrances

There is no vestibule entry. Multiple entrances are unsupervised.

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201002670
Project: Assessments 2016	Region: 430	Site: LILLINGTON-SHAWTOW
Grade Config: KG-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Excel	5.00	5.00	100.00
Interior Environment	Excel	2.00	2.00	100.00
Exterior Environment	Excel	1.50	1.50	100.00
General Classrooms				
Environment	Excel	4.90	4.90	100.00
Size	Good	9.80	12.25	80.00
Location	Excel	3.68	3.68	100.00
Storage/Fixed Equip	Excel	3.68	3.68	100.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Fair	0.68	1.04	65.00
Location	Good	0.25	0.31	80.00
Storage/Fixed Equip	Excel	0.31	0.31	100.00
ECE				
Environment	Excel	0.50	0.50	100.00
Size	Poor	0.62	1.25	50.00
Location	Excel	0.37	0.37	100.00
Storage/Fixed Equip	Good	0.30	0.37	80.00
Self-Contained Special Ed				
Environment	Fair	0.31	0.48	65.00
Size	Poor	0.60	1.20	50.00
Location	Fair	0.23	0.36	65.00
Storage/Fixed Equip	Fair	0.23	0.36	65.00
Instructional Resource Rooms				
Environment	Excel	0.72	0.72	100.00
Size	Fair	1.17	1.80	65.00
Location	Excel	0.54	0.54	100.00
Storage/Fixed Equip	Excel	0.54	0.54	100.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	1.85	1.85	100.00
Location	Excel	0.56	0.56	100.00
Storage/Fixed Equip	Excel	0.56	0.56	100.00
Art				
Environment	Excel	0.47	0.47	100.00
Size	Excel	1.17	1.17	100.00
Location	Excel	0.35	0.35	100.00
Storage/Fixed Equip	Excel	0.35	0.35	100.00
Computer Labs				
Environment	Excel	0.34	0.34	100.00
Size	Poor	0.43	0.85	50.00
Location	Excel	0.26	0.26	100.00
Storage/Fixed Equip	Excel	0.26	0.26	100.00
P.E.				
Environment	Good	1.54	1.92	80.00
Size	Fair	3.12	4.80	65.00
Location	Excel	1.44	1.44	100.00
Storage/Fixed Equip	Fair	0.94	1.44	65.00
Performing Arts				
Environment	Excel	0.60	0.60	100.00
Size	Poor	0.76	1.51	50.00
Location	Excel	0.45	0.45	100.00
Storage/Fixed Equip	Unsat	0.00	0.45	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Good	1.95	2.44	80.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Fair	0.58	0.89	65.00
Administration	Excel	2.56	2.56	100.00
Counseling	Unsat	0.00	0.29	0.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Excel	5.00	5.00	100.00
Food Service and Prep	Excel	6.20	6.20	100.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Excel	2.00	2.00	100.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Excel	0.81	0.81	100.00
Play Areas	Excel	2.34	2.34	100.00
Safety and Security				
Fencing	Good	0.60	0.75	80.00
Signage & Way Finding	Excel	1.00	1.00	100.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Excel	0.50	0.50	100.00

Project #: 8272

County: Harnett

Site #: 370201002670

Project: Assessments 2016

Region: 430

Site: LILLINGTON-SHAWTOW

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		84.99	97.50	87.17

Comments

Suitability - ES

Lillington-Shawtown Elementary School is a kindergarten through fifth grade facility. The school was built in 2003. The school currently uses five portables. The school serves special education students.

Suitability - ES->General Classrooms-->Size

Rooms meet approx. 80% of standards.

Suitability - ES->Kindergarten-->Size

K rooms meet approx. 75% of the standard.

Suitability - ES->Kindergarten-->Location

K rooms are located together, but not conv. to playground and bus drop-off.

Suitability - ES->ECE-->Size

Meet 65% of the standard; do not have kitchenettes.

Suitability - ES->ECE-->Storage/Fixed Equip

Does not have kitchenette; no access to W/D or changing area.

Suitability - ES->Self-Contained Special Ed-->Environment

SPED rooms located in blue hall meet standards. One SPED room is located in a general classroom, and three are in portables.

Suitability - ES->Self-Contained Special Ed-->Size

SPED rooms in building meet approx. 75% of standard. 3 SPED rooms are in portables.

Suitability - ES->Self-Contained Special Ed-->Location

SPED rooms in building meet approx. 75% of standard. 3 SPED rooms are in portables.

Suitability - ES->Self-Contained Special Ed-->Storage/Fixed Equip

SPED rooms in building meet approx. 75% of standard. 3 SPED rooms are in portables.

Suitability - ES->Instructional Resource Rooms-->Size

Approx. 75% meet the standard.

Suitability - ES->Music-->Environment

Overall environment excellent; ceiling height is similar to a regular classroom.

Suitability - ES->Computer Labs-->Size

Met approx. 60% of the standard.

Suitability - ES->Computer Labs-->Location

Lab is located adjacent to the media center.

Suitability - ES->P.E.-->Environment

Associated w/ multi-purpose room; lighting levels acceptable.

Suitability - ES->P.E.-->Size

Approx. 75% of standard.

Suitability - ES->P.E.-->Storage/Fixed Equip

Has some storage; minimal fixed equipment.

Suitability - ES->Performing Arts-->Size

Meets approx. 50% of standard.

Project #: 8272

County: Harnett

Site #: 370201002670

Project: Assessments 2016

Region: 430

Site: LILLINGTON-SHAWTOW

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Performing Arts-->Storage/Fixed Equip No storage.				
Suitability - ES->Media Center-->Size Meets approx. 88% of standard.				
Suitability - ES->Restrooms (Student) Not conv. to the activity and cafeteria spaces; boys don't have urinal separation.				
Suitability - ES->Counseling Located in portable.				
Suitability - ES->Clinic Met 78% of standard; no cot area.				

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201000890
Project: Assessments 2016	Region: 430	Site: NORTH HARNETT PRIM
Grade Config: KG-02	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Fair	3.19	4.90	65.00
Size	Poor	6.13	12.25	50.00
Location	Fair	2.39	3.68	65.00
Storage/Fixed Equip	Good	2.94	3.68	80.00
Kindergarten				
Environment	Good	0.33	0.42	80.00
Size	Excel	1.04	1.04	100.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Good	0.25	0.31	80.00
ECE				
Environment	Good	0.40	0.50	80.00
Size	Unsat	0.00	1.25	0.00
Location	Good	0.30	0.37	80.00
Storage/Fixed Equip	Good	0.30	0.37	80.00
Self-Contained Special Ed				
Environment	Fair	0.31	0.48	65.00
Size	Good	0.96	1.20	80.00
Location	Good	0.29	0.36	80.00
Storage/Fixed Equip	Good	0.29	0.36	80.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Good	1.44	1.80	80.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Project #: 8272

County: Harnett

Site #: 370201000890

Project: Assessments 2016

Region: 430

Site: NORTH HARNETT PRIM

Grade Config: KG-02

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	1.85	1.85	100.00
Location	Fair	0.36	0.56	65.00
Storage/Fixed Equip	Good	0.44	0.56	80.00
Art				
Environment	Fair	0.30	0.47	65.00
Size	Excel	1.17	1.17	100.00
Location	Excel	0.35	0.35	100.00
Storage/Fixed Equip	Excel	0.35	0.35	100.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Excel	0.85	0.85	100.00
Location	Excel	0.26	0.26	100.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Excel	1.92	1.92	100.00
Size	Poor	2.40	4.80	50.00
Location	Fair	0.94	1.44	65.00
Storage/Fixed Equip	Good	1.15	1.44	80.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Excel	2.44	2.44	100.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Fair	0.58	0.89	65.00
Administration	Good	2.05	2.56	80.00
Counseling	Good	0.23	0.29	80.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Excel	1.27	1.27	100.00
Cafeteria	Good	4.00	5.00	80.00
Food Service and Prep	Excel	6.20	6.20	100.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Excel	0.81	0.81	100.00
Play Areas	Fair	1.52	2.34	65.00
Safety and Security				
Fencing	Poor	0.38	0.75	50.00
Signage & Way Finding	Excel	1.00	1.00	100.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Good	0.40	0.50	80.00

Project #: 8272

County: Harnett

Site #: 370201000890

Project: Assessments 2016

Region: 430

Site: NORTH HARNETT PRIM

Grade Config: KG-02

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		71.15	94.48	75.31

Comments

Suitability - ES->General Classrooms-->Environment

All class rooms have windows (3-6 large); HVAC cooling issues throughout (varies by room); acoustics cause echoes.

Suitability - ES->General Classrooms-->Size

Met 62% of the standard. 5 rooms under footage standards.

Suitability - ES->General Classrooms-->Location

Five 1st grade classes are in separate building on opposite side of school away from 2 other 1st grade rooms.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Sufficient storage; no closet space; majority of storage are add-ins (many cabinets).

Suitability - ES->Kindergarten-->Storage/Fixed Equip

Sufficient storage; no closet space; majority of storage are add-ins (many cabinets).

Suitability - ES->ECE-->Size

One ECE room did not meet standard sq. footage.

Suitability - ES->ECE-->Storage/Fixed Equip

Sufficient storage; no closet space; majority of storage are add-ins (many cabinets).

Suitability - ES->Self-Contained Special Ed-->Environment

No fixed equipment.

Suitability - ES->Self-Contained Special Ed-->Storage/Fixed Equip

Sufficient storage; no closet space; majority of storage are add-ins (many cabinets).

Suitability - ES->Instructional Resource Rooms-->Size

Met 85% of the standard.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip

Sufficient storage; no closet space; majority of storage are add-ins (many cabinets).

Suitability - ES->Music-->Size

Met 90% of standard.

Suitability - ES->Music-->Location

Music located on main hall across from PK/PK self-contained and next to conference room; noise carries into hall and nearby rooms.

Suitability - ES->Music-->Storage/Fixed Equip

Sufficient storage; no closet space; majority of storage are add-ins (many cabinets).

Suitability - ES->Art-->Environment

Rooms are uninviting.

Suitability - ES->Art-->Storage/Fixed Equip

Sufficient storage; has closet space; some storage are add-ins.

Suitability - ES->Computer Labs-->Environment

HVAC cooling issues throughout (varies by room); computer lab has adequate cooling.

Suitability - ES->Computer Labs-->Storage/Fixed Equip

Sufficient storage; no closet space.

Project #: 8272

County: Harnett

Site #: 370201000890

Project: Assessments 2016

Region: 430

Site: NORTH HARNETT PRIM

Grade Config: KG-02

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->P.E.-->Size Met 61% of standard. Multi purpose room; Noted capacity issues.				
Suitability - ES->P.E.-->Location Outside access via bus lot; long walk for classes on other side of school and in portables/secondary building (covered outdoor walkways for those groups).				
Suitability - ES->P.E.-->Storage/Fixed Equip Converted multipurpose room.				
Suitability - ES->Media Center-->Environment No/limited natural light; some natural light from hallway windows.				
Suitability - ES->Restrooms (Student) Located throughout; have to exit building for access to boy's restroom.				
Suitability - ES->Clinic Small; no space for cot; limited visual.				
Suitability - ES->Outside-->Vehicular Traffic Noted issue w/ parents parking in fire lane (many cones out front to deter).				
Suitability - ES->Outside-->Play Areas Large outdoor area adequate, not fully fenced and by portables (reported accidents); fenced PK play area has some mechanical hazards (grate - fenced; AC units in windows stick out into play area).				
Suitability - ES->Safety and Security-->Fencing Pre-K and Kindergarten properly fenced, however, area is not built for play (extra outside area w/ hazards, such as fenced grate, window units from building sticking into area); outside storage unit for equipment next to covered walkway; main playground is mostly fenced with openings near hazard areas.				
Suitability - ES->Safety and Security-->Ease of Supervision Some limited sight in administrative areas; outside walks.				
Suitability - ES->Safety and Security-->Controlled Entrances Limitations in camera surveillance.				

Suitability Report - Full

Project #: 8272

County: Harnett

Site #: 370201002995

Project: Assessments 2016

Region: 430

Site: OVERHILLS ELEMENTAR

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Excel	5.00	5.00	100.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Good	9.80	12.25	80.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Good	2.94	3.68	80.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Excel	1.04	1.04	100.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Excel	0.31	0.31	100.00
ECE				
Environment	Excel	0.50	0.50	100.00
Size	Excel	1.25	1.25	100.00
Location	Excel	0.37	0.37	100.00
Storage/Fixed Equip	Excel	0.37	0.37	100.00
Self-Contained Special Ed				
Environment	Excel	0.48	0.48	100.00
Size	Excel	1.20	1.20	100.00
Location	Excel	0.36	0.36	100.00
Storage/Fixed Equip	Excel	0.36	0.36	100.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Excel	1.80	1.80	100.00
Location	Excel	0.54	0.54	100.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Poor	0.37	0.74	50.00

Project #: 8272

County: Harnett

Site #: 370201002995

Project: Assessments 2016

Region: 430

Site: OVERHILLS ELEMENTAR

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Poor	0.93	1.85	50.00
Location	Poor	0.28	0.56	50.00
Storage/Fixed Equip	Poor	0.28	0.56	50.00
Art				
Environment	Poor	0.23	0.47	50.00
Size	Poor	0.58	1.17	50.00
Location	Poor	0.18	0.35	50.00
Storage/Fixed Equip	Poor	0.18	0.35	50.00
Computer Labs				
Environment	Excel	0.34	0.34	100.00
Size	Fair	0.55	0.85	65.00
Location	Excel	0.26	0.26	100.00
Storage/Fixed Equip	Excel	0.26	0.26	100.00
P.E.				
Environment	Excel	1.92	1.92	100.00
Size	Excel	4.80	4.80	100.00
Location	Excel	1.44	1.44	100.00
Storage/Fixed Equip	Fair	0.94	1.44	65.00
Performing Arts				
Environment	Excel	0.60	0.60	100.00
Size	Excel	1.51	1.51	100.00
Location	Excel	0.45	0.45	100.00
Storage/Fixed Equip	Excel	0.45	0.45	100.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Fair	1.58	2.44	65.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Fair	0.48	0.73	65.00
Restrooms (Student)	Excel	0.89	0.89	100.00
Administration	Good	2.05	2.56	80.00
Counseling	Good	0.23	0.29	80.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Excel	5.00	5.00	100.00
Food Service and Prep	Excel	6.20	6.20	100.00
Custodial and Maintenance	Unsat	0.00	0.50	0.00
Outside				
Vehicular Traffic	Fair	1.30	2.00	65.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Fair	0.53	0.81	65.00
Play Areas	Fair	1.52	2.34	65.00
Safety and Security				
Fencing	Fair	0.49	0.75	65.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Poor	1.50	3.00	50.00
Controlled Entrances	Fair	0.33	0.50	65.00

Project #: 8272

County: Harnett

Site #: 370201002995

Project: Assessments 2016

Region: 430

Site: OVERHILLS ELEMENTAR

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		80.33	97.50	82.39

Comments

Suitability - ES

The Overhills Elementary School is a pre-K special education to fifth grade school. It utilizes 12 portable classrooms. The school was built in 2008.

Suitability - ES->Learning Environment-->Interior Environment

The school utilizes 12 portable classrooms. The entire fifth grade and two 3rd grade classes are housed in portable classrooms.

Suitability - ES->Learning Environment-->Exterior Environment

The exterior of the building is not attractive and well-maintained. Instead of grass much of the grounds are bare soil. The school does not have any external learning spaces or social gathering areas.

Suitability - ES->General Classrooms-->Environment

The school utilizes many portables classrooms.

Suitability - ES->General Classrooms-->Size

The classrooms housed in the building are excellent in size and meet the standards. The entire fifth grade and two sections of third grade are located in portables.

Suitability - ES->General Classrooms-->Location

The fifth grade and two sections of the third grade are located in portables and are not in close proximity to the media center, gymnasium, and other educational programs.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

The classrooms housed in the building have excellent storage. The classrooms housed in the portables do not have adequate built in storage nor do they have access to restrooms.

Suitability - ES->Kindergarten-->Storage/Fixed Equip

The kindergarten classrooms are equipped with a sink but no water fountain.

Suitability - ES->ECE

The early childhood education program is for students with special needs.

Suitability - ES->ECE-->Storage/Fixed Equip

The restrooms are not equipped with a shower.

Suitability - ES->Self-Contained Special Ed-->Storage/Fixed Equip

The restroom does not have a shower.

Suitability - ES->Instructional Resource Rooms-->Environment

Many of the resource rooms do not have natural lighting. One resource room is located in a portable.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip

The reading recovery rooms do not have ceiling mounted projectors.

Suitability - ES->Music-->Environment

One of the music classrooms is located in a portable. The other music classroom does not have any acoustical treatments.

Suitability - ES->Music-->Size

One music classroom is located in a portable.

Suitability - ES->Music-->Location

One musical classroom is located in a portable.

Project #: 8272

County: Harnett

Site #: 370201002995

Project: Assessments 2016

Region: 430

Site: OVERHILLS ELEMENTAR

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Music-->Storage/Fixed Equip One of the two musical classrooms are located in a is located in a portable.				
Suitability - ES->Art-->Environment The school has two art rooms. One of them is located in a portable.				
Suitability - ES->Art-->Size One of the art classrooms is located in a portable.				
Suitability - ES->Art-->Location One of the art classrooms is located in a portable area.				
Suitability - ES->Art-->Storage/Fixed Equip One of the art classrooms is located in a portable.				
Suitability - ES->Computer Labs-->Size The school has two small computer labs. They average approximately 70% of the size standard.				
Suitability - ES->P.E.-->Storage/Fixed Equip Physical education equipment is stored on the stage in the gymnasium. Chair storage is in a corner of the gymnasium. There is not adequate storage space for all the physical education equipment.				
Suitability - ES->Media Center-->Environment The media center does not have any natural lighting.				
Suitability - ES->Media Center-->Size The media center is approximately 75% of the size standard for the student population.				
Suitability - ES->Media Center-->Storage/Fixed Equip The media center does not have a workroom. The support spaces are small in size.				
Suitability - ES->Administration The conference room is small and only seats eight individuals.				
Suitability - ES->Counseling The counseling area does not have a conference room.				
Suitability - ES->Clinic The school has a clinic which has a office for a nurse. It is not equipped with cots.				
Suitability - ES->Staff Lounge-WkRm Their copiers are located in workrooms on each of the classroom wings. The school does not have a staff lounge.				
Suitability - ES->Food Service and Prep The delivery door does not have a buzzer.				
Suitability - ES->Custodial and Maintenance The school is only a equipped with one floor mounted sink that has hot water. Custodians must carry all cleaning supplies including mop buckets to the portables.				
Suitability - ES->Outside-->Vehicular Traffic The school does utilize a separate bus lane and parent drop off lane. The parent drop off lane, in order to keep traffic from stopping in the middle of a major road, has the cars meander through the entire parking lot prior to dropping off children. The student drop off area does not have a covered walkway.				
Suitability - ES->Outside-->Pedestrian Traffic The location of the school on a major roadway pedestrians traffic is limited. The sidewalks to the portables are not covered. Students often get wet walking to the portable classrooms.				
Suitability - ES->Outside-->Parking Staff parking is in back of the school on a grassy area.				

Project #: 8272

County: Harnett

Site #: 370201002995

Project: Assessments 2016

Region: 430

Site: OVERHILLS ELEMENTAR

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability

Rating

Score

Possible
Score

Percent
Score

Suitability - ES->Outside-->Play Areas

The school does not have adequate playground equipment for the population. The playground does not have a grassy area, instead the play area is bare soil.

Suitability - ES->Safety and Security-->Fencing

The school does not have adequate perimeter fencing in the front of the building.

Suitability - ES->Safety and Security-->Signage & Way Finding

The school does not have adequate traffic directional signage or internal directional signage.

Suitability - ES->Safety and Security-->Ease of Supervision

Due to the school having three wings and portable classrooms line of sight supervision is extremely difficult.

Suitability - ES->Safety and Security-->Controlled Entrances

The main entrance of the school does have a security vestibule. Because the school utilizes portable classrooms without restrooms some doors remain unlocked during the entire school day.

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201000892
Project: Assessments 2016	Region: 430	Site: SOUTH HARNETT ELEM
Grade Config: 03-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Poor	2.45	4.90	50.00
Size	Fair	7.96	12.25	65.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Fair	2.39	3.68	65.00
Kindergarten				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	Fair	0.31	0.48	65.00
Size	Excel	1.20	1.20	100.00
Location	Good	0.29	0.36	80.00
Storage/Fixed Equip	Poor	0.18	0.36	50.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Fair	1.17	1.80	65.00
Location	Fair	0.35	0.54	65.00
Storage/Fixed Equip	Fair	0.35	0.54	65.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Project #: 8272

County: Harnett

Site #: 370201000892

Project: Assessments 2016

Region: 430

Site: SOUTH HARNETT ELEM

Grade Config: 03-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	1.48	1.85	80.00
Location	Fair	0.36	0.56	65.00
Storage/Fixed Equip	Good	0.44	0.56	80.00
Art				
Environment	Good	0.37	0.47	80.00
Size	Excel	1.17	1.17	100.00
Location	Excel	0.35	0.35	100.00
Storage/Fixed Equip	Good	0.28	0.35	80.00
Computer Labs				
Environment	Fair	0.22	0.34	65.00
Size	Excel	0.85	0.85	100.00
Location	Fair	0.17	0.26	65.00
Storage/Fixed Equip	Poor	0.13	0.26	50.00
P.E.				
Environment	Fair	1.25	1.92	65.00
Size	Fair	3.12	4.80	65.00
Location	Good	1.15	1.44	80.00
Storage/Fixed Equip	Poor	0.72	1.44	50.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Excel	0.97	0.97	100.00
Size	Excel	2.44	2.44	100.00
Location	Good	0.58	0.73	80.00
Storage/Fixed Equip	Excel	0.73	0.73	100.00
Restrooms (Student)	Poor	0.44	0.89	50.00
Administration	Fair	1.66	2.56	65.00
Counseling	Good	0.23	0.29	80.00
Clinic	Good	0.47	0.58	80.00
Staff Lounge-WkRm	Fair	0.82	1.27	65.00
Cafeteria	Unsat	0.00	5.00	0.00
Food Service and Prep	Good	4.96	6.20	80.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Fair	1.30	2.00	65.00
Pedestrian Traffic	Fair	0.63	0.97	65.00
Parking	Fair	0.53	0.81	65.00
Play Areas	Good	1.87	2.34	80.00
Safety and Security				
Fencing	Fair	0.49	0.75	65.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Poor	0.25	0.50	50.00

Project #: 8272

County: Harnett

Site #: 370201000892

Project: Assessments 2016

Region: 430

Site: SOUTH HARNETT ELEM

Grade Config: 03-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		60.98	89.89	67.83

Comments

Suitability - ES->Learning Environment-->Learning Style Variety

3rd grade wing has less flexibility, more room-to-room traffic (no hall); flexible room space.

Suitability - ES->Learning Environment-->Interior Environment

Lots of natural lighting; less spatial configuration options in 3rd grade wing; HVAC issues (some rooms hotter/colder/humidity/mold) good aesthetics aside from water damage in some areas; hall near media center and computer lab floods.

Suitability - ES->General Classrooms-->Environment

Spacious rooms, good aesthetics except for water damage areas, inviting atmosphere; issues with temp control, possible mold, humidity; some bulletin boards peeling from wall, foundation cracks; condensation; several rooms lack noise control from mechanical spaces or other classes.

Suitability - ES->General Classrooms-->Size

4th grade rooms met 79% of the standard; 3rd and 5th grade met standard.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Many built-ins; storage issues due to flooding/water leaks from ceiling.

Suitability - ES->Self-Contained Special Ed-->Environment

Shared bath room between rooms accessible from the room; temp issues.

Suitability - ES->Self-Contained Special Ed-->Storage/Fixed Equip

Chained closet door so kids don't get locked in; bulletin board peeling and may have mold; limited fixed equipment.

Suitability - ES->Instructional Resource Rooms-->Size

One room requires groups to be run in class and in hall simultaneously due to lack of space.

Suitability - ES->Instructional Resource Rooms-->Location

In 3rd grade wing where there is no hall and only room-to-room access.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip

Built-ins; limited storage space and room sharing.

Suitability - ES->Music-->Size

Met 84% of standard for sq. footage.

Suitability - ES->Music-->Location

Located next to workroom and reading room/3rd grade room.

Suitability - ES->Art-->Storage/Fixed Equip

Sufficient storage (built-ins); kiln stored in office with ventilation system; sinks (2) have clay traps.

Suitability - ES->Computer Labs-->Environment

Plenty of space, good lighting; HVAC an issue (balmy, humid, ceiling leaks).

Suitability - ES->Computer Labs-->Location

In main building - 3rd/4th grade in separate buildings.

Suitability - ES->Computer Labs-->Storage/Fixed Equip

Good storage; Old Mac desktops (not enough working for all students in class); Have outlets but bad drops; 3 not hard wired and have to use Wi-Fi.

Suitability - ES->P.E.-->Environment

Small space; flooding in PE office space.

Project #: 8272

County: Harnett

Site #: 370201000892

Project: Assessments 2016

Region: 430

Site: SOUTH HARNETT ELEM

Grade Config: 03-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->P.E.-->Size Met 66% of standard for sq. footage.				
Suitability - ES->P.E.-->Storage/Fixed Equip Bleachers auto function does not work; can't retract ball goals (tears apart wall); limited/no safety padding; converted multi-purpose space.				
Suitability - ES->Media Center-->Size Meets 6SF min + sq. footage standard.				
Suitability - ES->Media Center-->Location 3rd and 4th grades have to go outside to access.				
Suitability - ES->Restrooms (Student) Some wear on signs; missing privacy screens for urinals; difficult/limited bathroom access for 3rd wing (no hall and rooms are connected - share single user bathroom).				
Suitability - ES->Administration Some pest issues near conference room (mice/ants); some water leaks; Need larger records room.				
Suitability - ES->Counseling Located away from main admin.				
Suitability - ES->Clinic Connected restroom, locked cabinet; has pads for laying on but no cot and limited space.				
Suitability - ES->Staff Lounge-WkRm Ventilation/ceiling leaks.				
Suitability - ES->Cafeteria Met 38% of standard; have extended lunch periods; water fountains out of service; long lines; students must go outside to reach cafeteria.				
Suitability - ES->Food Service and Prep Short lunch line area (have extended lunch times).				
Suitability - ES->Outside-->Vehicular Traffic Crowded.				
Suitability - ES->Outside-->Pedestrian Traffic Policy in place for staff parking lot to avoid interfering with bus traffic; missing covered walkway; blind spots.				
Suitability - ES->Outside-->Parking Lack of space for visitors and staff; bus parking is good.				
Suitability - ES->Outside-->Play Areas Some modern equipment; very spacious and fenced; issues with students near tree line (hunting nearby); septic area within area but fenced.				
Suitability - ES->Safety and Security-->Fencing Good fencing but gap exists due to sharing of ball field with local Rec center (open to public); fencing close to tree line on playground a hazard due to local hunting.				
Suitability - ES->Safety and Security-->Signage & Way Finding Good directional signage; some wear on interior signs (restroom signs missing letters).				
Suitability - ES->Safety and Security-->Ease of Supervision Sight lines in admin and 4th grade buildings are good but separate; 3rd grade wing has 0% sight lines (no hall way, no public restroom, and only room-to-room access); several exterior blind spots re: cameras near front entrance and back wall facing playground. Have 15 cameras but no front door camera or one facing playground.				

Project #: 8272

County: Harnett

Site #: 370201000892

Project: Assessments 2016

Region: 430

Site: SOUTH HARNETT ELEM

Grade Config: 03-05

Site Type: Elementary

Site Size: 0.00

Suitability

Rating

Score

**Possible
Score**

**Percent
Score**

Suitability - ES->Safety and Security-->Controlled Entrances

Good use of locks and directing visitor traffic; separate building design makes security difficult, esp. with 3rd grade wing (room-to-room access only).

Project #: 8272

County: Harnett

Site #: 370201000893

Project: Assessments 2016

Region: 430

Site: WAYNE AVENUE ELEM

Grade Config: 04-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Unsat	0.00	1.85	0.00
Location	Unsat	0.00	0.56	0.00
Storage/Fixed Equip	Unsat	0.00	0.56	0.00
Art				
Environment	Unsat	0.00	0.47	0.00
Size	Unsat	0.00	1.17	0.00
Location	Unsat	0.00	0.35	0.00
Storage/Fixed Equip	Unsat	0.00	0.35	0.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Fair	0.55	0.85	65.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Poor	0.13	0.26	50.00
P.E.				
Environment	Good	1.54	1.92	80.00
Size	Good	3.84	4.80	80.00
Location	Fair	0.94	1.44	65.00
Storage/Fixed Equip	Excel	1.44	1.44	100.00
Performing Arts				
Environment	Good	0.48	0.60	80.00
Size	Good	1.21	1.51	80.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Good	0.36	0.45	80.00
Media Center				
Environment	Excel	0.97	0.97	100.00
Size	Excel	2.44	2.44	100.00
Location	Poor	0.37	0.73	50.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Good	0.71	0.89	80.00
Administration	Poor	1.28	2.56	50.00
Counseling	Unsat	0.00	0.29	0.00
Clinic	Unsat	0.00	0.58	0.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Good	4.00	5.00	80.00
Food Service and Prep	Good	4.96	6.20	80.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Good	0.65	0.81	80.00
Play Areas	Poor	1.17	2.34	50.00
Safety and Security				
Fencing	Fair	0.49	0.75	65.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Poor	0.25	0.50	50.00

Project #: 8272

County: Harnett

Site #: 370201000893

Project: Assessments 2016

Region: 430

Site: WAYNE AVENUE ELEM

Grade Config: 04-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		61.47	92.92	66.15

Comments

Suitability - ES

Wayne Avenue ES was built in 1956 and is one of the oldest schools in Harnett County. The building has a positive atmosphere which provide students the opportunity to be engaged in a variety of activities.

Suitability - ES->Learning Environment-->Learning Style Variety

The building has narrow hallways, hard surfaces, older construction, and smaller classrooms. It is a challenging environment for implementation of various instructional models.

Suitability - ES->Learning Environment-->Interior Environment

The building has a lot of natural light, circulation, and air quality. The overall aesthetics of the building are older and lacks the characteristics of an inviting and stimulating environment.

Suitability - ES->Learning Environment-->Exterior Environment

The exterior is an older environment. The materials are worn, paint is discolored, masonry work needs repointing.

Suitability - ES->General Classrooms-->Size

General Education classrooms are 680 square feet, meeting 79% of the standard.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Classrooms lack appropriate casework cabinetry and storage.

Suitability - ES->Self-Contained Special Ed-->Environment

Self-Contained Classroom is located in a portable hut outside the building. Bathrooms are present inside the hut, but lacks appropriate storage.

Suitability - ES->Self-Contained Special Ed-->Size

Self-Contained Classroom is located in a portable hut outside the building. Bathrooms are present inside the hut, but lacks appropriate storage.

Suitability - ES->Self-Contained Special Ed-->Location

Self-Contained Classroom is located in a portable hut outside the building. Bathrooms are present inside the hut, but lacks appropriate storage.

Suitability - ES->Self-Contained Special Ed-->Storage/Fixed Equip

Self-Contained Classroom is located in a portable hut outside the building. Bathrooms are present inside the hut, but lacks appropriate storage.

Suitability - ES->Instructional Resource Rooms-->Environment

50% of resource rooms are located in portable huts.

Suitability - ES->Instructional Resource Rooms-->Size

50% of resource rooms are located in portable huts.

Suitability - ES->Instructional Resource Rooms-->Location

50% of resource rooms are located in portable huts.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip

50% of resource rooms are located in portable huts.

Suitability - ES->Music-->Environment

The music room is located in a portable hut outside of the building.

Suitability - ES->Music-->Size

The music room is located in a portable hut outside of the building.

Project #: 8272

County: Harnett

Site #: 370201000893

Project: Assessments 2016

Region: 430

Site: WAYNE AVENUE ELEM

Grade Config: 04-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Music-->Location The music room is located in a portable hut outside of the building.				
Suitability - ES->Music-->Storage/Fixed Equip The music room is located in a portable hut outside of the building.				
Suitability - ES->Art-->Environment The Art room is located in an outside portable hut.				
Suitability - ES->Art-->Size The Art room is located in an outside portable hut.				
Suitability - ES->Art-->Location The Art room is located in an outside portable hut.				
Suitability - ES->Art-->Storage/Fixed Equip The Art room is located in an outside portable hut.				
Suitability - ES->Computer Labs-->Size The size of the computer lab meets 68% of the standard.				
Suitability - ES->Computer Labs-->Storage/Fixed Equip The computer lab has little to no storage space.				
Suitability - ES->P.E.-->Environment The gymnasium has a rubber floor.				
Suitability - ES->P.E.-->Size The gymnasium has a rubber floor.				
Suitability - ES->P.E.-->Location The gymnasium is isolated in a wing of the building.				
Suitability - ES->Media Center-->Location The media center is isolated near the gymnasium and not located near academic programs.				
Suitability - ES->Restrooms (Student) The size and location of bathrooms is excellent, but the bathroom has older fixtures.				
Suitability - ES->Administration The administration office lacks a conference room, a workroom, and a large reception area. The space is small and easily overcrowded.				
Suitability - ES->Counseling The counseling office is located in an outside portable hut.				
Suitability - ES->Clinic There is no clinic located on this campus.				
Suitability - ES->Outside-->Play Areas The equipment in the play area is not age or developmentally appropriate.				
Suitability - ES->Safety and Security-->Fencing Lack of perimeter fencing on the property. There is one fence located along the rear perimeter of the property.				
Suitability - ES->Safety and Security-->Controlled Entrances Front entrance is not access controlled; remaining exterior doors are locked with access control.				

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201002456
Project: Assessments 2016	Region: 430	Site: COATS-ERWIN MIDDLE
Grade Config: 06-08	Site Type: Middle	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Good	3.12	3.90	80.00
Size	Good	7.80	9.75	80.00
Location	Excel	2.93	2.93	100.00
Storage/Fixed Equip	Fair	1.90	2.93	65.00
Self-Contained Special Ed				
Environment	Good	0.44	0.55	80.00
Size	Excel	1.36	1.36	100.00
Location	Excel	0.41	0.41	100.00
Storage/Fixed Equip	Good	0.33	0.41	80.00
Instructional Resource Rooms				
Environment	Good	0.66	0.82	80.00
Size	Excel	2.05	2.05	100.00
Location	Good	0.49	0.61	80.00
Storage/Fixed Equip	Good	0.49	0.61	80.00
Science				
Environment	Good	0.76	0.95	80.00
Size	Good	1.91	2.39	80.00
Location	Good	0.57	0.72	80.00
Storage/Fixed Equip	Fair	0.47	0.72	65.00
Music				
Environment	Good	0.59	0.74	80.00
Size	Good	1.47	1.84	80.00
Location	Excel	0.55	0.55	100.00
Storage/Fixed Equip	Good	0.44	0.55	80.00
Art				
Environment	Fair	0.42	0.65	65.00
Size	Excel	1.61	1.61	100.00
Location	Good	0.39	0.48	80.00
Storage/Fixed Equip	Good	0.39	0.48	80.00
Career Tech Ed				
Environment	(N/A)	0.00	0.00	0.00

Project #: 8272

County: Harnett

Site #: 370201002456

Project: Assessments 2016

Region: 430

Site: COATS-ERWIN MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Computer Labs				
Environment	Good	0.24	0.30	80.00
Size	Excel	0.75	0.75	100.00
Location	Good	0.18	0.23	80.00
Storage/Fixed Equip	Good	0.18	0.23	80.00
P.E.				
Environment	Good	1.92	2.40	80.00
Size	Good	4.80	6.00	80.00
Location	Good	1.44	1.80	80.00
Storage/Fixed Equip	Fair	1.17	1.80	65.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.74	0.93	80.00
Size	Excel	2.32	2.32	100.00
Location	Excel	0.70	0.70	100.00
Storage/Fixed Equip	Excel	0.70	0.70	100.00
Restrooms (Student)	Excel	0.93	0.93	100.00
Administration	Fair	1.36	2.10	65.00
Counseling	Good	0.34	0.42	80.00
Clinic	Fair	0.22	0.34	65.00
Staff Lounge-WkRm	Good	0.72	0.91	80.00
Cafeteria	Excel	4.00	4.00	100.00
Food Service and Prep	Excel	5.72	5.72	100.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Good	3.20	4.00	80.00
Pedestrian Traffic	Good	0.35	0.43	80.00
Parking	Excel	0.86	0.86	100.00
Athletic Courts and Fields	Poor	0.52	1.05	50.00
Safety and Security				
Fencing	Good	0.62	0.78	80.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Fair	0.33	0.50	65.00
Total For Site:		75.94	91.16	83.30

Comments

Project #: 8272

County: Harnett

Site #: 370201002456

Project: Assessments 2016

Region: 430

Site: COATS-ERWIN MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS->Learning Environment-->Interior Environment HVAC issues; very little spatial variation but have unused spaces to use. Adequate aesthetics; bubbles/cracks in hallway tiles; some side tile missing.				
Suitability - MS->General Classrooms-->Environment Little variation in configurations but have space to do so. Adequate aesthetics.				
Suitability - MS->General Classrooms-->Storage/Fixed Equip Built-ins and file cabinets in class rooms; cabinets/closets present; Health room has fixed tables that will be removed (old comp. lab).				
Suitability - MS->Instructional Resource Rooms-->Storage/Fixed Equip Some built-ins.				
Suitability - MS->Science-->Size Good class size; Lack prep space.				
Suitability - MS->Science-->Storage/Fixed Equip Shelving in storage for 7th grade fallen; counters not heat resistant; some faucets do not work.				
Suitability - MS->Art-->Environment Limited aesthetics; 3 sinks/1 trap; kiln room but no kiln - used for storage.				
Suitability - MS->P.E.-->Storage/Fixed Equip Football storage odors/limited venting; Bleachers have issue coming all the way out (manually pull).				
Suitability - MS->Performing Arts Auditorium outdated; curtains missing/old; seats broken; sound/tech box inadequate/old.				
Suitability - MS->Administration Records room too small; stacked/boxed files.				
Suitability - MS->Clinic No cot/padding; no room for cot.				
Suitability - MS->Custodial and Maintenance Some custodial equipment stored in unused class space.				
Suitability - MS->Outside-->Pedestrian Traffic Barrier used for directing carpool to avoid pedestrian/traffic issue.				
Suitability - MS->Outside-->Athletic Courts and Fields Football field lack enough bleachers/some bleachers damaged; football scoreboard doesn't work properly; Baseball field has a hill visitors walk down to get to field and needs appropriate walkway; no irrigation for football field.				
Suitability - MS->Safety and Security-->Signage & Way Finding Good signage; some missing lettering inside building.				
Suitability - MS->Safety and Security-->Ease of Supervision Very few hiding areas; few blind spots; in process of upgrading system.				
Suitability - MS->Safety and Security-->Controlled Entrances No double doors at main entrance, but traffic is directed through door directly to reception/office. No double doors at main entrance, but traffic directed to door to main office; Work order in for weather stripping - pest issues; have had snakes enter building/classes; some mice/insects.				

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201000880
Project: Assessments 2016	Region: 430	Site: DUNN MIDDLE
Grade Config: 06-08	Site Type: Middle	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Good	3.12	3.90	80.00
Size	Excel	9.75	9.75	100.00
Location	Excel	2.93	2.93	100.00
Storage/Fixed Equip	Fair	1.90	2.93	65.00
Self-Contained Special Ed				
Environment	Good	0.44	0.55	80.00
Size	Excel	1.36	1.36	100.00
Location	Excel	0.41	0.41	100.00
Storage/Fixed Equip	Good	0.33	0.41	80.00
Instructional Resource Rooms				
Environment	Good	0.66	0.82	80.00
Size	Excel	2.05	2.05	100.00
Location	Good	0.49	0.61	80.00
Storage/Fixed Equip	Fair	0.40	0.61	65.00
Science				
Environment	Good	0.76	0.95	80.00
Size	Excel	2.39	2.39	100.00
Location	Excel	0.72	0.72	100.00
Storage/Fixed Equip	Good	0.57	0.72	80.00
Music				
Environment	Good	0.59	0.74	80.00
Size	Good	1.47	1.84	80.00
Location	Excel	0.55	0.55	100.00
Storage/Fixed Equip	Fair	0.36	0.55	65.00
Art				
Environment	Good	0.52	0.65	80.00
Size	Excel	1.61	1.61	100.00
Location	Excel	0.48	0.48	100.00
Storage/Fixed Equip	Good	0.39	0.48	80.00
Career Tech Ed				
Environment	Good	1.08	1.35	80.00

Project #: 8272

County: Harnett

Site #: 370201000880

Project: Assessments 2016

Region: 430

Site: DUNN MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	2.70	3.37	80.00
Location	Excel	1.01	1.01	100.00
Storage/Fixed Equip	Excel	1.01	1.01	100.00
Computer Labs				
Environment	Good	0.24	0.30	80.00
Size	Fair	0.49	0.75	65.00
Location	Excel	0.23	0.23	100.00
Storage/Fixed Equip	Good	0.18	0.23	80.00
P.E.				
Environment	Excel	2.40	2.40	100.00
Size	Excel	6.00	6.00	100.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Good	1.44	1.80	80.00
Performing Arts				
Environment	Good	0.33	0.42	80.00
Size	Excel	1.05	1.05	100.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Fair	0.20	0.31	65.00
Media Center				
Environment	Excel	0.93	0.93	100.00
Size	Excel	2.32	2.32	100.00
Location	Excel	0.70	0.70	100.00
Storage/Fixed Equip	Good	0.56	0.70	80.00
Restrooms (Student)	Good	0.74	0.93	80.00
Administration	Good	1.68	2.10	80.00
Counseling	Good	0.34	0.42	80.00
Clinic	Fair	0.22	0.34	65.00
Staff Lounge-WkRm	Excel	0.91	0.91	100.00
Cafeteria	Excel	4.00	4.00	100.00
Food Service and Prep	Good	4.57	5.72	80.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Excel	4.00	4.00	100.00
Pedestrian Traffic	Excel	0.43	0.43	100.00
Parking	Excel	0.86	0.86	100.00
Athletic Courts and Fields	Excel	1.05	1.05	100.00
Safety and Security				
Fencing	Good	0.62	0.78	80.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Good	0.40	0.50	80.00
Total For Site:		89.42	100.00	89.42

Comments

Project #: 8272

County: Harnett

Site #: 370201000880

Project: Assessments 2016

Region: 430

Site: DUNN MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS->General Classrooms-->Storage/Fixed Equip Technology equipment meets standards. Built in cabinetry/ storage is minimal.				
Suitability - MS->Instructional Resource Rooms-->Storage/Fixed Equip Built in storage/cabinetry is minimal.				
Suitability - MS->Music-->Size The instrumental room meets the standard, the vocal room meets approximately 75% of the standard.				
Suitability - MS->Music-->Storage/Fixed Equip Music suite has an adequate storage room but nearly none in the classroom spaces.				
Suitability - MS->Career Tech Ed-->Size Dunn Middle School has a number of traditional CTE spaces (FACS, Shop) that are not being used for that purpose. CTE now consists of one classroom space utilized for the Success Maker Program.				
Suitability - MS->Computer Labs-->Size The computer labs meet approximately 75% of the standard.				
Suitability - MS->Computer Labs-->Storage/Fixed Equip Computer labs have good built in student stations but lack some the cabinetry normally associated with this type of space.				
Suitability - MS->Performing Arts-->Size Dunn Middle School includes a full size auditorium.				
Suitability - MS->Performing Arts-->Storage/Fixed Equip While the overall space exceeds the middle school standard, storage was minimal.				
Suitability - MS->Clinic The clinic meets the square footage standard but has no space for a cot.				

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201000578
Project: Assessments 2016	Region: 430	Site: HARNETT CENTRAL MI
Grade Config: 06-08	Site Type: Middle	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Fair	2.54	3.90	65.00
Size	Fair	6.34	9.75	65.00
Location	Poor	1.46	2.93	50.00
Storage/Fixed Equip	Fair	1.90	2.93	65.00
Self-Contained Special Ed				
Environment	Poor	0.27	0.55	50.00
Size	Excel	1.36	1.36	100.00
Location	Excel	0.41	0.41	100.00
Storage/Fixed Equip	Poor	0.20	0.41	50.00
Instructional Resource Rooms				
Environment	Good	0.66	0.82	80.00
Size	Good	1.64	2.05	80.00
Location	Good	0.49	0.61	80.00
Storage/Fixed Equip	Poor	0.31	0.61	50.00
Science				
Environment	Fair	0.62	0.95	65.00
Size	Fair	1.55	2.39	65.00
Location	Good	0.57	0.72	80.00
Storage/Fixed Equip	Fair	0.47	0.72	65.00
Music				
Environment	Fair	0.48	0.74	65.00
Size	Good	1.47	1.84	80.00
Location	Excel	0.55	0.55	100.00
Storage/Fixed Equip	Poor	0.28	0.55	50.00
Art				
Environment	Fair	0.42	0.65	65.00
Size	Fair	1.05	1.61	65.00
Location	Fair	0.31	0.48	65.00
Storage/Fixed Equip	Good	0.39	0.48	80.00
Career Tech Ed				
Environment	Good	1.08	1.35	80.00

Project #: 8272

County: Harnett

Site #: 370201000578

Project: Assessments 2016

Region: 430

Site: HARNETT CENTRAL MI

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	2.70	3.37	80.00
Location	Excel	1.01	1.01	100.00
Storage/Fixed Equip	Good	0.81	1.01	80.00
Computer Labs				
Environment	Excel	0.30	0.30	100.00
Size	Excel	0.75	0.75	100.00
Location	Excel	0.23	0.23	100.00
Storage/Fixed Equip	Excel	0.23	0.23	100.00
P.E.				
Environment	Fair	1.56	2.40	65.00
Size	Poor	3.00	6.00	50.00
Location	Fair	1.17	1.80	65.00
Storage/Fixed Equip	Poor	0.90	1.80	50.00
Performing Arts				
Environment	Excel	0.42	0.42	100.00
Size	Poor	0.52	1.05	50.00
Location	Fair	0.20	0.31	65.00
Storage/Fixed Equip	Fair	0.20	0.31	65.00
Media Center				
Environment	Excel	0.93	0.93	100.00
Size	Fair	1.51	2.32	65.00
Location	Excel	0.70	0.70	100.00
Storage/Fixed Equip	Excel	0.70	0.70	100.00
Restrooms (Student)	Poor	0.46	0.93	50.00
Administration	Excel	2.10	2.10	100.00
Counseling	Poor	0.21	0.42	50.00
Clinic	Unsat	0.00	0.34	0.00
Staff Lounge-WkRm	Fair	0.59	0.91	65.00
Cafeteria	Fair	2.60	4.00	65.00
Food Service and Prep	Excel	5.72	5.72	100.00
Custodial and Maintenance	Fair	0.33	0.50	65.00
Outside				
Vehicular Traffic	Good	3.20	4.00	80.00
Pedestrian Traffic	Excel	0.43	0.43	100.00
Parking	Excel	0.86	0.86	100.00
Athletic Courts and Fields	Fair	0.68	1.05	65.00
Safety and Security				
Fencing	Fair	0.50	0.78	65.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Unsat	0.00	3.00	0.00
Controlled Entrances	Unsat	0.00	0.50	0.00
Total For Site:		68.57	100.00	68.57

Comments

Project #: 8272

County: Harnett

Site #: 370201000578

Project: Assessments 2016

Region: 430

Site: HARNETT CENTRAL MI

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Harnett Central Middle School is a sixth through eighth grade facility. The school houses a large population of students with special needs. The entire sixth grade is located in portable classrooms.				
Suitability - MS->Learning Environment-->Learning Style Variety				
The portable classrooms do not have adequate space for small group and project-based instruction. The school does not have any spaces that were designed for small group or individualized instruction.				
Suitability - MS->Learning Environment-->Interior Environment				
The portable classrooms do not provide a stimulating educational environment. Classrooms in the center of the pods do not have any natural lighting.				
Suitability - MS->Learning Environment-->Exterior Environment				
There is an outdoor area adjacent to the portable classrooms with numerous picnic tables that can be used as a social gathering and instructional space. In addition, the school has a courtyard that is utilized by various groups.				
Suitability - MS->General Classrooms-->Environment				
The school utilizes numerous portable classrooms for all sixth grade general instruction.				
Suitability - MS->General Classrooms-->Size				
The school utilizes portable classrooms for all sixth grade general instruction. The classrooms inside the building are adequate in size.				
Suitability - MS->General Classrooms-->Location				
The sixth grade classrooms are located in portable buildings and are not adjacent to many of the student support and elective instructional areas.				
Suitability - MS->General Classrooms-->Storage/Fixed Equip				
The portable general classrooms do not have adequate storage and fixed equipment. The general classrooms have limited storage cabinetry.				
Suitability - MS->Self-Contained Special Ed-->Environment				
The self-contained special education students are housed in general classrooms. These rooms were not designed for special education students and do not provide a stimulating educational environment.				
Suitability - MS->Self-Contained Special Ed-->Size				
Special education classrooms are general education classrooms and are adequate in size.				
Suitability - MS->Self-Contained Special Ed-->Storage/Fixed Equip				
The special education classrooms are general classrooms and are not equipped with storage for specialized equipment and mobility devices. The rooms are equipped with a sink. Two of the of self-contained classrooms do have a shared bathroom. The changing table is located in a curtained off area in the classroom itself.				
Suitability - MS->Instructional Resource Rooms-->Environment				
The resource rooms that are located on the internal portion of the pods do not have any natural lighting. The sixth grade resource rooms are located in portable classrooms.				
Suitability - MS->Instructional Resource Rooms-->Size				
The six grade resource rooms are located in portable classrooms.				
Suitability - MS->Instructional Resource Rooms-->Location				
The six grade resource rooms are located in portable classrooms.				
Suitability - MS->Instructional Resource Rooms-->Storage/Fixed Equip				
The resource rooms do not have any additional cabinetry other than what is normally found in a general classroom. It is not adequate for instructional supplies and materials.				

Project #: 8272

County: Harnett

Site #: 370201000578

Project: Assessments 2016

Region: 430

Site: HARNETT CENTRAL MI

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability

Rating

Score

Possible
Score

Percent
Score

Suitability - MS->Science-->Environment

The sixth grade science classrooms are located in portables. The seventh and eighth grade science classrooms are lecture lab combination's. In addition, the school has science taught in general classrooms. The portable classrooms and the general classrooms that are used for science instruction do not provide an inviting and stimulating educational environment.

Suitability - MS->Science-->Size

Sixth grade science is taught in portable classrooms. Two other general classrooms are utilized for science instruction. Those general classrooms are approximately 850 ft.?.

Suitability - MS->Science-->Location

Six grade science is taught in portable classrooms.

Suitability - MS->Science-->Storage/Fixed Equip

Science is taught in portables for sixth grade. The general classrooms that are utilized to teach science do not have any additional cabinetry, sinks, safety equipment, or other fixed equipment directly related to science instruction. Rooms designed as science labs do not have a safety shower or chemical hood.

Suitability - MS->Music-->Environment

The vocal room was originally designed as an additional art classroom and does not have any acoustical treatments. It has low ceilings.

Suitability - MS->Music-->Storage/Fixed Equip

The vocal room does not have a sink, practice rooms, or adequate storage for instructional materials. The instrumental room does not have practice rooms, a sink, or adequate storage for musical instruments.

Suitability - MS->Art-->Environment

Sixth grade art is taught in a portable classroom.

Suitability - MS->Art-->Size

Six grade art is taught in a portable classroom.

Suitability - MS->Art-->Location

Six grade art is taught in a portable classroom.

Suitability - MS->Art-->Storage/Fixed Equip

The art room is equipped with adequate sinks. The sinks do not have clay traps.

Suitability - MS->Career Tech Ed-->Environment

The broadcasting room was previously a computer lab. The room has not been reconfigured into a broadcasting lab. The school has a family consumer science foods lab that is currently being used for storage.

Suitability - MS->Career Tech Ed-->Size

The STEM lab is not adequate in size.

Suitability - MS->Career Tech Ed-->Storage/Fixed Equip

The STEM lab does not have adequate built in cabinetry for the storing of equipment and materials.

Suitability - MS->P.E.-->Environment

The locker rooms are showing significant wear and tear. The conditioning program is located in portable classrooms.

Suitability - MS->P.E.-->Size

In order to accommodate the number of physical education classes that are needed to be taught, the students rotate between health instruction, physical education activities outdoors, physical education activities in the gym, or conditioning activities in portable classrooms. the school does not have an auxiliary gym.

Suitability - MS->P.E.-->Location

Conditioning activities are located in portable classrooms.

Project #: 8272

County: Harnett

Site #: 370201000578

Project: Assessments 2016

Region: 430

Site: HARNETT CENTRAL MI

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS->P.E.-->Storage/Fixed Equip Physical education does not have enough storage for all of the equipment and supplies including athletic equipment.				
Suitability - MS->Performing Arts-->Size The auditorium seats 460 people. It cannot accommodate one grade level. Due to the limited seating, school programs are often presented on a grade level instead of a combined schoolwide program.				
Suitability - MS->Performing Arts-->Location Individuals attending activities in the auditorium cannot be restricted from the rest of the building. The restrooms adjacent o the auditorium are small and lack an adequate number of fixtures.				
Suitability - MS->Performing Arts-->Storage/Fixed Equip The auditorium does not have restrooms in the dressing rooms, adequate storage for costumes, general storage for props and sets.				
Suitability - MS->Media Center-->Size The media center is small for the number of students served. It is approximately 75% of the size standard.				
Suitability - MS->Restrooms (Student) The school utilizes a portable building for restrooms for students in the sixth grade that are housed in the mobile classrooms. The restrooms in the main building do not have adequate numbers of fixtures and are not well ventilated.				
Suitability - MS->Counseling The sixth grade counselor is located in a portable classroom. Additional counselors are located in spaces that were originally designed as a resource rooms. The counselors do not have a reception area or conference room. In some cases student records are stored a significant distance from the counselor's office. Parents accessing the counselor's office wait in the main office.				
Suitability - MS->Clinic The school has an office area that houses the nurse and the storage of medications. There is an area which house a restroom but does not have any cots and can not be supervised by the school nurse.				
Suitability - MS->Staff Lounge-WkRm The school does not have a staff lounge. The primary workroom for faculty is located adjacent to the media center. In addition there is a workroom in the main administrative area. The sixth grade teachers do not have a workroom in close proximity to the portable classrooms.				
Suitability - MS->Cafeteria In order to accommodate the number of students the school utilizes a six lunch periods. The cafeteria is small in size for the student population.				
Suitability - MS->Custodial and Maintenance Custodians must carry all of their cleaning supplies between each of the portable classrooms.				
Suitability - MS->Outside-->Vehicular Traffic The parent drop off zone is located in the visitor parking area. Vehicle access to the school can backup due to left hand turns.				
Suitability - MS->Outside-->Athletic Courts and Fields The athletic fields do not have adequate restroom facilities adjacent to the baseball, soccer, and softball fields. The school does not have a track or tennis courts.				
Suitability - MS->Safety and Security-->Fencing The school has some fencing around the athletic areas. Fencing in front of the school adjacent to the main road does not exist and there are other areas of open access that are not well fenced.				
Suitability - MS->Safety and Security-->Signage & Way Finding The school does not have any internal or external directional signage.				

Project #: 8272

County: Harnett

Site #: 370201000578

Project: Assessments 2016

Region: 430

Site: HARNETT CENTRAL MI

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability

Rating

Score

Possible
Score

Percent
Score

Suitability - MS->Safety and Security-->Ease of Supervision

Due to the number of portable classrooms, the building being a multi-story building, and the classrooms being configured in a pod arrangement the building is extremely difficult to visually supervise.

Suitability - MS->Safety and Security-->Controlled Entrances

The main office does not have direct visual supervision of the main door. Due to the sixth-graders being housed in portables doors adjacent to the portables remain open all day. None of the classroom doors can be locked from the inside. Sixth grade students during a lockdown shelter in place.

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201003309
Project: Assessments 2016	Region: 430	Site: HIGHLAND MIDDLE
Grade Config: 06-08	Site Type: Middle	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Learning Environment				
Learning Style Variety	Excel	5.00	5.00	100.00
Interior Environment	Excel	2.00	2.00	100.00
Exterior Environment	Excel	1.50	1.50	100.00
General Classrooms				
Environment	Excel	3.90	3.90	100.00
Size	Excel	9.75	9.75	100.00
Location	Excel	2.93	2.93	100.00
Storage/Fixed Equip	Fair	1.90	2.93	65.00
Self-Contained Special Ed				
Environment	Excel	0.55	0.55	100.00
Size	Excel	1.36	1.36	100.00
Location	Excel	0.41	0.41	100.00
Storage/Fixed Equip	Excel	0.41	0.41	100.00
Instructional Resource Rooms				
Environment	Excel	0.82	0.82	100.00
Size	Excel	2.05	2.05	100.00
Location	Excel	0.61	0.61	100.00
Storage/Fixed Equip	Excel	0.61	0.61	100.00
Science				
Environment	Excel	0.95	0.95	100.00
Size	Excel	2.39	2.39	100.00
Location	Excel	0.72	0.72	100.00
Storage/Fixed Equip	Excel	0.72	0.72	100.00
Music				
Environment	Excel	0.74	0.74	100.00
Size	Excel	1.84	1.84	100.00
Location	Excel	0.55	0.55	100.00
Storage/Fixed Equip	Excel	0.55	0.55	100.00
Art				
Environment	Excel	0.65	0.65	100.00
Size	Excel	1.61	1.61	100.00
Location	Excel	0.48	0.48	100.00
Storage/Fixed Equip	Excel	0.48	0.48	100.00
Career Tech Ed				
Environment	Excel	1.35	1.35	100.00

Project #: 8272

County: Harnett

Site #: 370201003309

Project: Assessments 2016

Region: 430

Site: HIGHLAND MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	3.37	3.37	100.00
Location	Excel	1.01	1.01	100.00
Storage/Fixed Equip	Excel	1.01	1.01	100.00
Computer Labs				
Environment	Excel	0.30	0.30	100.00
Size	Excel	0.75	0.75	100.00
Location	Excel	0.23	0.23	100.00
Storage/Fixed Equip	Excel	0.23	0.23	100.00
P.E.				
Environment	Excel	2.40	2.40	100.00
Size	Excel	6.00	6.00	100.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Excel	1.80	1.80	100.00
Performing Arts				
Environment	Excel	0.42	0.42	100.00
Size	Excel	1.05	1.05	100.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Excel	0.31	0.31	100.00
Media Center				
Environment	Excel	0.93	0.93	100.00
Size	Excel	2.32	2.32	100.00
Location	Excel	0.70	0.70	100.00
Storage/Fixed Equip	Excel	0.70	0.70	100.00
Restrooms (Student)	Excel	0.93	0.93	100.00
Administration	Excel	2.10	2.10	100.00
Counseling	Excel	0.42	0.42	100.00
Clinic	Excel	0.34	0.34	100.00
Staff Lounge-WkRm	Excel	0.91	0.91	100.00
Cafeteria	Excel	4.00	4.00	100.00
Food Service and Prep	Excel	5.72	5.72	100.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Excel	4.00	4.00	100.00
Pedestrian Traffic	Excel	0.43	0.43	100.00
Parking	Excel	0.86	0.86	100.00
Athletic Courts and Fields	Excel	1.05	1.05	100.00
Safety and Security				
Fencing	Excel	0.78	0.78	100.00
Signage & Way Finding	Excel	1.00	1.00	100.00
Ease of Supervision	Excel	3.00	3.00	100.00
Controlled Entrances	Excel	0.50	0.50	100.00
Total For Site:		98.98	100.00	98.98

Comments

Project #: 8272

County: Harnett

Site #: 370201003309

Project: Assessments 2016

Region: 430

Site: HIGHLAND MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability

Rating

Score

**Possible
Score**

**Percent
Score**

Suitability - MS->General Classrooms-->Storage/Fixed Equip
Classrooms lack adequate storage for materials and supplies.

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201002525
Project: Assessments 2016	Region: 430	Site: OVERHILLS MIDDLE
Grade Config: 06-08	Site Type: Middle	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Learning Environment				
Learning Style Variety	Excel	5.00	5.00	100.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Good	3.12	3.90	80.00
Size	Good	7.80	9.75	80.00
Location	Excel	2.93	2.93	100.00
Storage/Fixed Equip	Good	2.34	2.93	80.00
Self-Contained Special Ed				
Environment	Good	0.44	0.55	80.00
Size	Excel	1.36	1.36	100.00
Location	Excel	0.41	0.41	100.00
Storage/Fixed Equip	Fair	0.27	0.41	65.00
Instructional Resource Rooms				
Environment	Good	0.66	0.82	80.00
Size	Excel	2.05	2.05	100.00
Location	Good	0.49	0.61	80.00
Storage/Fixed Equip	Excel	0.61	0.61	100.00
Science				
Environment	Good	0.76	0.95	80.00
Size	Poor	1.19	2.39	50.00
Location	Excel	0.72	0.72	100.00
Storage/Fixed Equip	Fair	0.47	0.72	65.00
Music				
Environment	Good	0.59	0.74	80.00
Size	Excel	1.84	1.84	100.00
Location	Excel	0.55	0.55	100.00
Storage/Fixed Equip	Fair	0.36	0.55	65.00
Art				
Environment	Fair	0.42	0.65	65.00
Size	Poor	0.81	1.61	50.00
Location	Good	0.39	0.48	80.00
Storage/Fixed Equip	Fair	0.31	0.48	65.00
Career Tech Ed				
Environment	(N/A)	0.00	0.00	0.00

Project #: 8272

County: Harnett

Site #: 370201002525

Project: Assessments 2016

Region: 430

Site: OVERHILLS MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Computer Labs				
Environment	Good	0.24	0.30	80.00
Size	Excel	0.75	0.75	100.00
Location	Excel	0.23	0.23	100.00
Storage/Fixed Equip	Good	0.18	0.23	80.00
P.E.				
Environment	Good	1.92	2.40	80.00
Size	Good	4.80	6.00	80.00
Location	Fair	1.17	1.80	65.00
Storage/Fixed Equip	Fair	1.17	1.80	65.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.74	0.93	80.00
Size	Excel	2.32	2.32	100.00
Location	Excel	0.70	0.70	100.00
Storage/Fixed Equip	Excel	0.70	0.70	100.00
Restrooms (Student)	Excel	0.93	0.93	100.00
Administration	Excel	2.10	2.10	100.00
Counseling	Good	0.34	0.42	80.00
Clinic	Good	0.27	0.34	80.00
Staff Lounge-WkRm	Excel	0.91	0.91	100.00
Cafeteria	Excel	4.00	4.00	100.00
Food Service and Prep	Excel	5.72	5.72	100.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Good	3.20	4.00	80.00
Pedestrian Traffic	Fair	0.28	0.43	65.00
Parking	Excel	0.86	0.86	100.00
Athletic Courts and Fields	Good	0.84	1.05	80.00
Safety and Security				
Fencing	Good	0.62	0.78	80.00
Signage & Way Finding	Excel	1.00	1.00	100.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Good	0.40	0.50	80.00
Total For Site:		77.49	91.16	85.00

Comments

Project #: 8272

County: Harnett

Site #: 370201002525

Project: Assessments 2016

Region: 430

Site: OVERHILLS MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS->Learning Environment-->Interior Environment Hallways are dimly lit.				
Suitability - MS->General Classrooms-->Environment Some space for flexibility.				
Suitability - MS->General Classrooms-->Size Met 98% of standard.				
Suitability - MS->General Classrooms-->Storage/Fixed Equip Primarily built-ins.				
Suitability - MS->Self-Contained Special Ed-->Storage/Fixed Equip Some equipment; one piece deteriorating; use more padding in therapy room.				
Suitability - MS->Science-->Size Met 60% of standard.				
Suitability - MS->Science-->Storage/Fixed Equip Pest issue w/ mice in storage area (worse in 6th grade wing).				
Suitability - MS->Music-->Environment Flooding/separating tiles in hallway outside Band room.				
Suitability - MS->Music-->Size Both chorus/band rooms meet standard.				
Suitability - MS->Music-->Storage/Fixed Equip Students share locker space to store instruments; instrument lockers are located in another room.				
Suitability - MS->Art-->Environment Primarily focused on drawing/illustrations; limited variety of art.				
Suitability - MS->Art-->Size Met 54% of standard.				
Suitability - MS->Art-->Storage/Fixed Equip Kiln but not in use; no clay traps on sinks.				
Suitability - MS->P.E.-->Size Classrooms and gym good space; outside area spacious but issue is w/ use of portables when it rains.				
Suitability - MS->P.E.-->Location When it rains, the outside PE classes use portables (2 of 6); school has 6 classes - 2 gym, 2 classroom, 2 outside.				
Suitability - MS->P.E.-->Storage/Fixed Equip Use of portables during poor weather for outside PE classes.				
Suitability - MS->Performing Arts Auditorium is used for awards/events; lighting makes a loud humming sound; a few chairs are broken.				
Suitability - MS->Counseling Need more room for records.				
Suitability - MS->Clinic No cot but have pads; a little space for a cot if table moved/removed.				
Suitability - MS->Outside-->Vehicular Traffic Overall good; some issues with road traffic and construction and line for drop off.				

Project #: 8272

County: Harnett

Site #: 370201002525

Project: Assessments 2016

Region: 430

Site: OVERHILLS MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability

Rating

Score

**Possible
Score**

**Percent
Score**

Suitability - MS->Outside-->Pedestrian Traffic

Issue with nearby subdivision and students walking to school (crossing street, through grass, across vehicle drop-off area); all other areas well-routed; need sidewalks.

Suitability - MS->Safety and Security-->Ease of Supervision

Clear sight lines in hallway; limited by portables; need camera outside in front of admin area and back near portables; need interior cameras in the middle of each grade wing (no coverage; students know and plan fights in the middle because of lack of camera coverage); Very few hiding areas; 12 working cameras outside, 26 inside; a few need to be adjusted or wired.

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201002296
Project: Assessments 2016	Region: 430	Site: WESTERN HARNETT M
Grade Config: 06-08	Site Type: Middle	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Excel	1.50	1.50	100.00
General Classrooms				
Environment	Good	3.12	3.90	80.00
Size	Excel	9.75	9.75	100.00
Location	Excel	2.93	2.93	100.00
Storage/Fixed Equip	Good	2.34	2.93	80.00
Self-Contained Special Ed				
Environment	Good	0.44	0.55	80.00
Size	Excel	1.36	1.36	100.00
Location	Excel	0.41	0.41	100.00
Storage/Fixed Equip	Fair	0.27	0.41	65.00
Instructional Resource Rooms				
Environment	Good	0.66	0.82	80.00
Size	Excel	2.05	2.05	100.00
Location	Excel	0.61	0.61	100.00
Storage/Fixed Equip	Excel	0.61	0.61	100.00
Science				
Environment	Good	0.76	0.95	80.00
Size	Good	1.91	2.39	80.00
Location	Excel	0.72	0.72	100.00
Storage/Fixed Equip	Good	0.57	0.72	80.00
Music				
Environment	Fair	0.48	0.74	65.00
Size	Excel	1.84	1.84	100.00
Location	Excel	0.55	0.55	100.00
Storage/Fixed Equip	Fair	0.36	0.55	65.00
Art				
Environment	Excel	0.65	0.65	100.00
Size	Excel	1.61	1.61	100.00
Location	Excel	0.48	0.48	100.00
Storage/Fixed Equip	Good	0.39	0.48	80.00
Career Tech Ed				
Environment	Good	1.08	1.35	80.00

Project #: 8272

County: Harnett

Site #: 370201002296

Project: Assessments 2016

Region: 430

Site: WESTERN HARNETT M

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	3.37	3.37	100.00
Location	Excel	1.01	1.01	100.00
Storage/Fixed Equip	Good	0.81	1.01	80.00
Computer Labs				
Environment	Good	0.24	0.30	80.00
Size	Excel	0.75	0.75	100.00
Location	Excel	0.23	0.23	100.00
Storage/Fixed Equip	Excel	0.23	0.23	100.00
P.E.				
Environment	Fair	1.56	2.40	65.00
Size	Fair	3.90	6.00	65.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Fair	1.17	1.80	65.00
Performing Arts				
Environment	Excel	0.42	0.42	100.00
Size	Excel	1.05	1.05	100.00
Location	Good	0.25	0.31	80.00
Storage/Fixed Equip	Fair	0.20	0.31	65.00
Media Center				
Environment	Excel	0.93	0.93	100.00
Size	Excel	2.32	2.32	100.00
Location	Excel	0.70	0.70	100.00
Storage/Fixed Equip	Excel	0.70	0.70	100.00
Restrooms (Student)	Good	0.74	0.93	80.00
Administration	Excel	2.10	2.10	100.00
Counseling	Excel	0.42	0.42	100.00
Clinic	Fair	0.22	0.34	65.00
Staff Lounge-WkRm	Fair	0.59	0.91	65.00
Cafeteria	Excel	4.00	4.00	100.00
Food Service and Prep	Excel	5.72	5.72	100.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Excel	4.00	4.00	100.00
Pedestrian Traffic	Excel	0.43	0.43	100.00
Parking	Excel	0.86	0.86	100.00
Athletic Courts and Fields	Fair	0.68	1.05	65.00
Safety and Security				
Fencing	Poor	0.39	0.78	50.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Unsat	0.00	0.50	0.00
Total For Site:		87.76	100.00	87.76

Comments

Project #: 8272

County: Harnett

Site #: 370201002296

Project: Assessments 2016

Region: 430

Site: WESTERN HARNETT M

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Western Harnett Middle School is a sixth through eighth grade facility. It and Harnett Central Middle School have the exact same floorplan. The school serves a limited population of self-contained special education students. The school provides English as a second language instruction.				
Suitability - MS->Learning Environment-->Learning Style Variety				
The school does not have spaces designed for small group and individualized instruction. Teachers are able to configure their classrooms to meet this need.				
Suitability - MS->Learning Environment-->Interior Environment				
The HVAC system is not consistent.				
Suitability - MS->Learning Environment-->Exterior Environment				
The school does have a covered gazebo that is equipped with picnic tables for outdoor learning. It also has a courtyard area.				
Suitability - MS->General Classrooms-->Environment				
Where whiteboards of been removed and technology has been installed there is still glue on the walls and areas that have not been painted.				
Suitability - MS->General Classrooms-->Storage/Fixed Equip				
The classrooms have limited built in storage. They do not have a wall of storage cabinets.				
Suitability - MS->Self-Contained Special Ed-->Environment				
The self contained special education classrooms are not equipped with any specialized storage cabinetry or other fixed equipment to assist in meeting students physical and educational needs.				
Suitability - MS->Self-Contained Special Ed-->Storage/Fixed Equip				
The self-contained special education classrooms do not have a changing table. They do not have adequate built in storage for supplies, materials, and mobility devices. The two rooms share a restroom.				
Suitability - MS->Instructional Resource Rooms-->Environment				
Some of the resource rooms are located in the interior portion of the pods do not have natural lighting.				
Suitability - MS->Science-->Environment				
The sixth grade science rooms are general classrooms.				
Suitability - MS->Science-->Size				
The sixth grade science rooms are general classrooms and do not meet the size standard for Middle School science rooms.				
Suitability - MS->Science-->Storage/Fixed Equip				
The science classrooms are not equipped with an emergency shower. The rooms do have sinks but there is not a work area adjacent to the sinks. The chemical storage area is not adequately ventilated.				
Suitability - MS->Music-->Environment				
The choral classroom was originally designed as the art room. It contains an island with four sinks located in the back of the room. It has low ceilings. The choral room does not have any acoustical treatments.				
Suitability - MS->Music-->Storage/Fixed Equip				
The choral room does not have an office or storage area. The band room does not have a sink. The music areas lack practice and small ensemble rooms.				
Suitability - MS->Art-->Storage/Fixed Equip				
Art is being taught in a room that is equipped with only one sink. The sink does not have a clay trap.				
Suitability - MS->Career Tech Ed-->Environment				
The HVAC system does not keep the labs cool in all situations.				

Project #: 8272

County: Harnett

Site #: 370201002296

Project: Assessments 2016

Region: 430

Site: WESTERN HARNETT M

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS->Career Tech Ed-->Storage/Fixed Equip The Computers Labs do not have adequate built in cabinetry for the storage of materials and supplies.				
Suitability - MS->Computer Labs-->Environment The HVAC system does not keep the labs consistently cool.				
Suitability - MS->P.E.-->Environment The locker rooms are showing significant wear and tear.				
Suitability - MS->P.E.-->Size The school does not have an auxiliary gym. The boys locker rooms is small.				
Suitability - MS->P.E.-->Storage/Fixed Equip Half of the girls locker room is being used for storage for equipment. The school does not have adequate storage for physical education and athletic equipment. The lockers can not accommodate the football gear.				
Suitability - MS->Performing Arts-->Location The auditorium cannot be separated from the rest of the building during performances. The adjacent restrooms are very small and lack adequate fixtures.				
Suitability - MS->Performing Arts-->Storage/Fixed Equip The performing arts area does not have custom storage, storage for sets, and props.				
Suitability - MS->Restrooms (Student) The restrooms are worn and are not adequately ventilated.				
Suitability - MS->Clinic The nurse's clinic does not have any cots.				
Suitability - MS->Staff Lounge-WkRm The school does not have a staff lounge. Staff restrooms and workrooms are located in each grade level pod.				
Suitability - MS->Outside-->Athletic Courts and Fields The school does not have track or tennis courts.				
Suitability - MS->Safety and Security-->Fencing The school sits off of the road significant distance. There is not any fencing separating the school building from the main road. A portion of the athletic fields are fenced.				
Suitability - MS->Safety and Security-->Signage & Way Finding The school does not have adequate internal and external directional signage.				
Suitability - MS->Safety and Security-->Ease of Supervision Due to the configuration of the classrooms in pods and the building having multiple stories visual supervision is difficult.				
Suitability - MS->Safety and Security-->Controlled Entrances The main office does not have direct visual supervision of any of the buildings entrances. The school does not utilize a buzzer system or security vestibule.				

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201000884
Project: Assessments 2016	Region: 430	Site: HARNETT CENTRAL HI
Grade Config: 09-12	Site Type: High	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Poor	1.00	2.00	50.00
Exterior Environment	Poor	0.75	1.50	50.00
General Classrooms				
Environment	Poor	1.95	3.90	50.00
Size	Fair	6.34	9.75	65.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Poor	1.46	2.93	50.00
Self-Contained Special Ed				
Environment	Good	0.43	0.53	80.00
Size	Excel	1.33	1.33	100.00
Location	Fair	0.26	0.40	65.00
Storage/Fixed Equip	Good	0.32	0.40	80.00
Instructional Resource Rooms				
Environment	Good	0.64	0.80	80.00
Size	Good	1.60	2.00	80.00
Location	Good	0.48	0.60	80.00
Storage/Fixed Equip	Fair	0.39	0.60	65.00
Science				
Environment	Fair	0.54	0.83	65.00
Size	Good	1.66	2.07	80.00
Location	Good	0.50	0.62	80.00
Storage/Fixed Equip	Unsat	0.00	0.62	0.00
Music				
Environment	Good	0.48	0.59	80.00
Size	Excel	1.48	1.48	100.00
Location	Excel	0.45	0.45	100.00
Storage/Fixed Equip	Good	0.36	0.45	80.00
Art				
Environment	Good	0.53	0.67	80.00
Size	Good	1.33	1.66	80.00
Location	Good	0.40	0.50	80.00
Storage/Fixed Equip	Unsat	0.00	0.50	0.00
Career Tech Ed				
Environment	Good	1.37	1.71	80.00

Project #: 8272

County: Harnett

Site #: 370201000884

Project: Assessments 2016

Region: 430

Site: HARNETT CENTRAL HI

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Fair	2.78	4.27	65.00
Location	Poor	0.64	1.28	50.00
Storage/Fixed Equip	Fair	0.83	1.28	65.00
Computer Labs				
Environment	Poor	0.15	0.30	50.00
Size	Good	0.60	0.75	80.00
Location	Excel	0.23	0.23	100.00
Storage/Fixed Equip	Excel	0.23	0.23	100.00
P.E.				
Environment	Fair	1.56	2.40	65.00
Size	Fair	3.90	6.00	65.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Good	1.44	1.80	80.00
Performing Arts				
Environment	Poor	0.16	0.32	50.00
Size	Unsat	0.00	0.80	0.00
Location	Good	0.19	0.24	80.00
Storage/Fixed Equip	Unsat	0.00	0.24	0.00
Media Center				
Environment	Good	0.67	0.84	80.00
Size	Good	1.69	2.11	80.00
Location	Good	0.51	0.63	80.00
Storage/Fixed Equip	Excel	0.63	0.63	100.00
Restrooms (Student)	Good	0.73	0.91	80.00
Administration	Good	2.09	2.61	80.00
Counseling	Good	0.61	0.76	80.00
Clinic	Fair	0.15	0.24	65.00
Staff Lounge-WkRm	Good	0.57	0.71	80.00
Cafeteria	Fair	2.60	4.00	65.00
Food Service and Prep	Excel	5.11	5.11	100.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Good	0.80	1.00	80.00
Pedestrian Traffic	Fair	0.64	0.98	65.00
Parking	Poor	1.05	2.11	50.00
Athletic Courts and Fields	Good	2.21	2.77	80.00
Safety and Security				
Fencing	Good	0.68	0.85	80.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Poor	1.50	3.00	50.00
Controlled Entrances	Good	0.40	0.50	80.00
Total For Site:		69.81	100.00	69.81

Comments

Project #: 8272

County: Harnett

Site #: 370201000884

Project: Assessments 2016

Region: 430

Site: HARNETT CENTRAL HI

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS->Learning Environment-->Learning Style Variety Some flexibility overall but limited in other spaces.				
Suitability - HS->Learning Environment-->Interior Environment Aesthetics and level of stimulating environment vary; very little flexibility or room for configurations; variable temp, 62% w/ some degree of natural light; 6 portables.				
Suitability - HS->Learning Environment-->Exterior Environment Very few outside spaces; primarily near shops via garage doors.				
Suitability - HS->General Classrooms-->Environment acoustics vary; temp varies; 9 rooms do not have natural light, 6 classes in portables; some structural damage (leaks, cracks in walls); broken window seals.				
Suitability - HS->General Classrooms-->Size Additions offer a few bigger room; overall classes are small relative to the number of students.				
Suitability - HS->General Classrooms-->Storage/Fixed Equip Overall lack of storage; most built-ins or sharing storage.				
Suitability - HS->Self-Contained Special Ed-->Location Two classes separate from each other; one has better access to restroom, specialized equipment, kitchenette; lacking padding.				
Suitability - HS->Instructional Resource Rooms-->Storage/Fixed Equip Built-in storage is limited.				
Suitability - HS->Science-->Environment Good natural light; limited flexibility; small work stations.				
Suitability - HS->Science-->Storage/Fixed Equip Some fixed equipment; not enough power outlets; 1 room has table tops that are not heat resistant (chemistry lab); work stations are too small; no drain under eye wash stations / eyewash on hose; one floor drain is higher than floor and causes flooding; Room 835 has acid cabinet that corroded (made of metal and not polyurethane) and fumes have degraded cabinet and it can no longer be opened / no ventilation for fumes.				
Suitability - HS->Music-->Environment Some aesthetics; minimal natural light; can hear chorus in hall but is appropriately located away from general ed.				
Suitability - HS->Music-->Storage/Fixed Equip Only a few built-ins; good large storage space.				
Suitability - HS->Art-->Environment Cluttered room; kiln room blocked from stacked items in room.				
Suitability - HS->Art-->Size Met standard but capacity is too small for number of students.				
Suitability - HS->Art-->Storage/Fixed Equip In need of storage solutions; items stored in available storage/built-ins, stacked in class, and found in other class storage areas; small art hall with minimal room for display; crowded room; some fixed equipment; 2 sink but no clay traps.				
Suitability - HS->Career Tech Ed-->Environment Equipment appropriate to instruction; limited light for shop areas (garage doors only); limited flexibility.				
Suitability - HS->Career Tech Ed-->Size Masonry/Carpentry/Horticulture housed in portables; shops separate.				
Suitability - HS->Career Tech Ed-->Location 25% have class in room separate from shop area (not connected); 5 classes are located in portables.				

Project #: 8272

County: Harnett

Site #: 370201000884

Project: Assessments 2016

Region: 430

Site: HARNETT CENTRAL HI

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS->Career Tech Ed-->Storage/Fixed Equip Lack outlets. Culinary has direct wire and not disconnect to stove; has some fixed equipment.				
Suitability - HS->Computer Labs-->Environment Minimal light; cooling unit added to one class (takes up floor space); fixed tables; temp varies.				
Suitability - HS->Computer Labs-->Size Met 80% of standard.				
Suitability - HS->P.E.-->Environment Poor ventilation and no natural light in weight room (but appropriate size); temp varies.				
Suitability - HS->P.E.-->Size Main gym lacks capacity for events (use of chairs).				
Suitability - HS->P.E.-->Storage/Fixed Equip Chairs/tables for evens are stored on the gym floor.				
Suitability - HS->Performing Arts-->Environment Minimal natural light; equipment stored in several areas; primary area is auditorium which is badly outdated (broken/missing chairs) and small for student population; bad sound equipment; dim inside lighting.				
Suitability - HS->Performing Arts-->Size Does not meet standard (small, bad sound system, dim lighting).				
Suitability - HS->Performing Arts-->Storage/Fixed Equip Equipment stored in several areas; primary area is auditorium which is badly outdated (broken/missing chairs) and small for student population; bad sound equipment; dim inside lighting.				
Suitability - HS->Media Center-->Environment Limited natural light (only from hall).				
Suitability - HS->Restrooms (Student) Distance to each from classes esp. on 1st floor.				
Suitability - HS->Counseling Counseling (4) grouped by media center across from admin.				
Suitability - HS->Clinic Meds in locked cabinet in nearby workroom; folded cot present but no space.				
Suitability - HS->Staff Lounge-WkRm Equipment varies; 1 temp space.				
Suitability - HS->Cafeteria 67% of the standard.				
Suitability - HS->Outside-->Pedestrian Traffic 1 common outdoor walkway w/o covering.				
Suitability - HS->Outside-->Parking Some signage; not enough parking for visitors/staff (staff park on grass); student parking off-street by buses (student lot and bus lot have divider); lane paint faded.				
Suitability - HS->Outside-->Athletic Courts and Fields Chairs added to gym for events.				
Suitability - HS->Safety and Security-->Signage & Way Finding Some directional signage; crowded class change in cross-section of old and new addition; students use outside stairs to avoid.				

Project #: 8272

County: Harnett

Site #: 370201000884

Project: Assessments 2016

Region: 430

Site: HARNETT CENTRAL HI

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability

Rating

Score

**Possible
Score**

**Percent
Score**

Suitability - HS->Safety and Security-->Ease of Supervision

Poor sight lines in additions areas, office areas, and some walkways; many blind spots.

Suitability - HS->Safety and Security-->Controlled Entrances

Main entrance met criteria; side entrances lack some visibility/control.

Suitability Report - Full

Project #: 8272

County: Harnett

Site #: 370201002733

Project: Assessments 2016

Region: 430

Site: OVERHILLS HIGH

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Poor	1.95	3.90	50.00
Size	Fair	6.34	9.75	65.00
Location	Unsat	0.00	2.93	0.00
Storage/Fixed Equip	Unsat	0.00	2.93	0.00
Self-Contained Special Ed				
Environment	Excel	0.53	0.53	100.00
Size	Excel	1.33	1.33	100.00
Location	Excel	0.40	0.40	100.00
Storage/Fixed Equip	Excel	0.40	0.40	100.00
Instructional Resource Rooms				
Environment	Good	0.64	0.80	80.00
Size	Good	1.60	2.00	80.00
Location	Good	0.48	0.60	80.00
Storage/Fixed Equip	Poor	0.30	0.60	50.00
Science				
Environment	Fair	0.54	0.83	65.00
Size	Fair	1.35	2.07	65.00
Location	Good	0.50	0.62	80.00
Storage/Fixed Equip	Good	0.50	0.62	80.00
Music				
Environment	Good	0.48	0.59	80.00
Size	Excel	1.48	1.48	100.00
Location	Excel	0.45	0.45	100.00
Storage/Fixed Equip	Fair	0.29	0.45	65.00
Art				
Environment	Good	0.53	0.67	80.00
Size	Excel	1.66	1.66	100.00
Location	Excel	0.50	0.50	100.00
Storage/Fixed Equip	Poor	0.25	0.50	50.00
Career Tech Ed				
Environment	Good	1.37	1.71	80.00

Project #: 8272

County: Harnett

Site #: 370201002733

Project: Assessments 2016

Region: 430

Site: OVERHILLS HIGH

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Fair	2.78	4.27	65.00
Location	Excel	1.28	1.28	100.00
Storage/Fixed Equip	Good	1.03	1.28	80.00
Computer Labs				
Environment	Good	0.24	0.30	80.00
Size	Fair	0.49	0.75	65.00
Location	Good	0.18	0.23	80.00
Storage/Fixed Equip	Good	0.18	0.23	80.00
P.E.				
Environment	Fair	1.56	2.40	65.00
Size	Poor	3.00	6.00	50.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Poor	0.90	1.80	50.00
Performing Arts				
Environment	Good	0.26	0.32	80.00
Size	Fair	0.52	0.80	65.00
Location	Excel	0.24	0.24	100.00
Storage/Fixed Equip	Poor	0.12	0.24	50.00
Media Center				
Environment	Excel	0.84	0.84	100.00
Size	Fair	1.37	2.11	65.00
Location	Excel	0.63	0.63	100.00
Storage/Fixed Equip	Good	0.51	0.63	80.00
Restrooms (Student)	Fair	0.59	0.91	65.00
Administration	Fair	1.70	2.61	65.00
Counseling	Excel	0.76	0.76	100.00
Clinic	Good	0.19	0.24	80.00
Staff Lounge-WkRm	Excel	0.71	0.71	100.00
Cafeteria	Fair	2.60	4.00	65.00
Food Service and Prep	Good	4.08	5.11	80.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Good	0.80	1.00	80.00
Pedestrian Traffic	Excel	0.98	0.98	100.00
Parking	Good	1.69	2.11	80.00
Athletic Courts and Fields	Good	2.21	2.77	80.00
Safety and Security				
Fencing	Good	0.68	0.85	80.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Fair	0.33	0.50	65.00
Total For Site:		68.24	100.00	68.24

Comments

Project #: 8272

County: Harnett

Site #: 370201002733

Project: Assessments 2016

Region: 430

Site: OVERHILLS HIGH

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS Overhills High School is a ninth through twelfth grade facility. The school was built in 2003. The school currently uses twelve portables (including foreign language and social studies classes). The school serves special education students.				
Suitability - HS->Learning Environment-->Learning Style Variety School does have some large and small group meeting spaces, but classrooms lack flexibility for different style of learning.				
Suitability - HS->General Classrooms-->Environment Limited lighting/aesthetics in some rooms.				
Suitability - HS->General Classrooms-->Size Classrooms in building meet sq. ft. standard, however, 11 (over 20%) of classrooms are in portables.				
Suitability - HS->General Classrooms-->Location Over 20% of class rooms are in portables.				
Suitability - HS->General Classrooms-->Storage/Fixed Equip Class rooms in building have minimal storage; over 20% of class rooms are in portables.				
Suitability - HS->Instructional Resource Rooms-->Size Most meet standard.				
Suitability - HS->Instructional Resource Rooms-->Storage/Fixed Equip Minimal storage space; most resource rooms had little fixed equipment/storage.				
Suitability - HS->Science-->Environment 2 of 9 (approx. 22%) are in general class room spaces.				
Suitability - HS->Science-->Size Science rooms are good; 2 of the rooms are in general classrooms.				
Suitability - HS->Science-->Location 2 of the rooms are general education rooms.				
Suitability - HS->Science-->Storage/Fixed Equip Excellent in science rooms; 2 of the rooms were in general education rooms.				
Suitability - HS->Music-->Storage/Fixed Equip Limited storage; did not have adequate storage for all needs.				
Suitability - HS->Art-->Environment Overall environment good; space included a gallery.				
Suitability - HS->Art-->Storage/Fixed Equip No equipment/storage normally associated with art rooms; no kiln room; 1 sink; minimal storage space.				
Suitability - HS->Career Tech Ed-->Size While overall size of most CTE spaces was good, the organization of the space creates some spaces that exceed standards while others (primarily class room space - non-shop) were below standards.				
Suitability - HS->Computer Labs-->Size Approx. 65% met the standard.				
Suitability - HS->Computer Labs-->Location Two rooms together; away from library.				
Suitability - HS->P.E.-->Environment Weight room had fair ventilation.				

Project #: 8272

County: Harnett

Site #: 370201002733

Project: Assessments 2016

Region: 430

Site: OVERHILLS HIGH

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS->P.E.-->Size Main gym not large enough to fully utilize bleachers / student populations; weight room meets 50% of the standard.				
Suitability - HS->P.E.-->Storage/Fixed Equip Some storage; inadequate for the programs housed.				
Suitability - HS->Performing Arts-->Size Meets requirement for fixed seating; no additional performing arts spaces.				
Suitability - HS->Performing Arts-->Storage/Fixed Equip Minimal storage associated with performing arts.				
Suitability - HS->Media Center-->Size Meets 65% of standard.				
Suitability - HS->Restrooms (Student) Only one restroom for each hallway.				
Suitability - HS->Administration Some of the administrators are assigned to remote locations per available space, not based on locale where most needed; sharing of space.				
Suitability - HS->Clinic No place or space for a cot.				
Suitability - HS->Cafeteria Meets 75% of the standard.				
Suitability - HS->Outside-->Parking Amount of parking excellent; no parking for baseball/softball fields.				
Suitability - HS->Safety and Security-->Signage & Way Finding Some signs missing; some signs not accurate.				
Suitability - HS->Safety and Security-->Ease of Supervision Lots of spaces that have multiple entrances/exits/extensions; portables block line of sight.				
Suitability - HS->Safety and Security-->Controlled Entrances Could be unseen access to school.				

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201002158
Project: Assessments 2016	Region: 430	Site: TRITON HIGH
Grade Config: 09-12	Site Type: High	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Fair	2.54	3.90	65.00
Size	Good	7.80	9.75	80.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Unsat	0.00	2.93	0.00
Self-Contained Special Ed				
Environment	Good	0.43	0.53	80.00
Size	Good	1.07	1.33	80.00
Location	Good	0.32	0.40	80.00
Storage/Fixed Equip	Good	0.32	0.40	80.00
Instructional Resource Rooms				
Environment	Fair	0.52	0.80	65.00
Size	Good	1.60	2.00	80.00
Location	Good	0.48	0.60	80.00
Storage/Fixed Equip	Fair	0.39	0.60	65.00
Science				
Environment	Good	0.66	0.83	80.00
Size	Good	1.66	2.07	80.00
Location	Good	0.50	0.62	80.00
Storage/Fixed Equip	Good	0.50	0.62	80.00
Music				
Environment	Fair	0.39	0.59	65.00
Size	Good	1.19	1.48	80.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Fair	0.29	0.45	65.00
Art				
Environment	Good	0.53	0.67	80.00
Size	Good	1.33	1.66	80.00
Location	Good	0.40	0.50	80.00
Storage/Fixed Equip	Good	0.40	0.50	80.00
Career Tech Ed				
Environment	Excel	1.71	1.71	100.00

Project #: 8272

County: Harnett

Site #: 370201002158

Project: Assessments 2016

Region: 430

Site: TRITON HIGH

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	4.27	4.27	100.00
Location	Good	1.03	1.28	80.00
Storage/Fixed Equip	Excel	1.28	1.28	100.00
Computer Labs				
Environment	Good	0.24	0.30	80.00
Size	Good	0.60	0.75	80.00
Location	Good	0.18	0.23	80.00
Storage/Fixed Equip	Fair	0.15	0.23	65.00
P.E.				
Environment	Good	1.92	2.40	80.00
Size	Good	4.80	6.00	80.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Good	1.44	1.80	80.00
Performing Arts				
Environment	Good	0.26	0.32	80.00
Size	Excel	0.80	0.80	100.00
Location	Excel	0.24	0.24	100.00
Storage/Fixed Equip	Excel	0.24	0.24	100.00
Media Center				
Environment	Good	0.67	0.84	80.00
Size	Good	1.69	2.11	80.00
Location	Good	0.51	0.63	80.00
Storage/Fixed Equip	Excel	0.63	0.63	100.00
Restrooms (Student)	Good	0.73	0.91	80.00
Administration	Good	2.09	2.61	80.00
Counseling	Good	0.61	0.76	80.00
Clinic	Unsat	0.00	0.24	0.00
Staff Lounge-WkRm	Good	0.57	0.71	80.00
Cafeteria	Good	3.20	4.00	80.00
Food Service and Prep	Good	4.08	5.11	80.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Good	0.80	1.00	80.00
Pedestrian Traffic	Good	0.78	0.98	80.00
Parking	Good	1.69	2.11	80.00
Athletic Courts and Fields	Good	2.21	2.77	80.00
Safety and Security				
Fencing	Good	0.68	0.85	80.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Poor	1.50	3.00	50.00
Controlled Entrances	Poor	0.25	0.50	50.00
Total For Site:		76.36	100.00	76.36

Comments

Project #: 8272

County: Harnett

Site #: 370201002158

Project: Assessments 2016

Region: 430

Site: TRITON HIGH

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Triton High School is a traditional public high school built in 1985. The school serves students in 9th-12th grade. There are 8 portable classrooms.				
Suitability - HS->Learning Environment-->Learning Style Variety				
The overall flow and design of the high school do not exemplify the 21st century standards and attributes of modern high school design.				
Suitability - HS->Learning Environment-->Interior Environment				
There is limited natural lighting making the school less inviting and engaging for students. The acoustics within the building are poor which creates excessive noise and distractions.				
Suitability - HS->Learning Environment-->Exterior Environment				
There is limited architectural variance in the roof lines, the entrances or the exterior walls of the building. The exterior of the building does not have a lot of landscaping, common areas, outdoor classrooms or student meeting areas.				
Suitability - HS->General Classrooms-->Environment				
The general education classrooms have limited natural lighting, poor acoustics due to mostly hard surfaces throughout and in some cases poor ventilation, heating and cooling.				
Suitability - HS->General Classrooms-->Storage/Fixed Equip				
Storage was removed in order to add more desks.				
Suitability - HS->Instructional Resource Rooms-->Environment				
Lacked natural light and acoustical treatment.				
Suitability - HS->Instructional Resource Rooms-->Storage/Fixed Equip				
Lack of adequate storage and equipment.				
Suitability - HS->Music-->Environment				
The music room has older, worn surfaces and the finishes are deteriorating.				
Suitability - HS->Music-->Storage/Fixed Equip				
The music room lacked large instrument, lockable storage space.				
Suitability - HS->Computer Labs-->Storage/Fixed Equip				
Computer labs lacked lockable laptop and small device storage.				
Suitability - HS->Restrooms (Student)				
Restrooms meet most criteria, but older fixtures are in place.				
Suitability - HS->Clinic				
No clinic on site.				
Suitability - HS->Safety and Security-->Ease of Supervision				
Triton HS has unobservable stairways and multiple hallways with blind spots, making supervision difficult.				
Suitability - HS->Safety and Security-->Controlled Entrances				
Triton HS does not have controlled access at the front entrance. There are limited security cameras and unsupervised access to exterior doors.				

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201000894
Project: Assessments 2016	Region: 430	Site: WESTERN HARNETT H
Grade Config: 09-12	Site Type: High	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Poor	2.50	5.00	50.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Poor	0.75	1.50	50.00
General Classrooms				
Environment	Fair	2.54	3.90	65.00
Size	Poor	4.88	9.75	50.00
Location	Excel	2.93	2.93	100.00
Storage/Fixed Equip	Poor	1.46	2.93	50.00
Self-Contained Special Ed				
Environment	Excel	0.53	0.53	100.00
Size	Excel	1.33	1.33	100.00
Location	Fair	0.26	0.40	65.00
Storage/Fixed Equip	Good	0.32	0.40	80.00
Instructional Resource Rooms				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Science				
Environment	Good	0.66	0.83	80.00
Size	Good	1.66	2.07	80.00
Location	Excel	0.62	0.62	100.00
Storage/Fixed Equip	Good	0.50	0.62	80.00
Music				
Environment	Excel	0.59	0.59	100.00
Size	Fair	0.96	1.48	65.00
Location	Excel	0.45	0.45	100.00
Storage/Fixed Equip	Good	0.36	0.45	80.00
Art				
Environment	Excel	0.67	0.67	100.00
Size	Excel	1.66	1.66	100.00
Location	Good	0.40	0.50	80.00
Storage/Fixed Equip	Excel	0.50	0.50	100.00
Career Tech Ed				
Environment	Poor	0.85	1.71	50.00

Project #: 8272

County: Harnett

Site #: 370201000894

Project: Assessments 2016

Region: 430

Site: WESTERN HARNETT H

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Poor	2.14	4.27	50.00
Location	Poor	0.64	1.28	50.00
Storage/Fixed Equip	Unsat	0.00	1.28	0.00
Computer Labs				
Environment	Excel	0.30	0.30	100.00
Size	Excel	0.75	0.75	100.00
Location	Excel	0.23	0.23	100.00
Storage/Fixed Equip	Excel	0.23	0.23	100.00
P.E.				
Environment	Fair	1.56	2.40	65.00
Size	Fair	3.90	6.00	65.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Fair	1.17	1.80	65.00
Performing Arts				
Environment	Excel	0.32	0.32	100.00
Size	Poor	0.40	0.80	50.00
Location	Excel	0.24	0.24	100.00
Storage/Fixed Equip	Unsat	0.00	0.24	0.00
Media Center				
Environment	Good	0.67	0.84	80.00
Size	Fair	1.37	2.11	65.00
Location	Excel	0.63	0.63	100.00
Storage/Fixed Equip	Fair	0.41	0.63	65.00
Restrooms (Student)	Poor	0.46	0.91	50.00
Administration	Fair	1.70	2.61	65.00
Counseling	Fair	0.49	0.76	65.00
Clinic	Poor	0.12	0.24	50.00
Staff Lounge-WkRm	Fair	0.46	0.71	65.00
Cafeteria	Excel	4.00	4.00	100.00
Food Service and Prep	Fair	3.32	5.11	65.00
Custodial and Maintenance	Fair	0.33	0.50	65.00
Outside				
Vehicular Traffic	Fair	0.65	1.00	65.00
Pedestrian Traffic	Excel	0.98	0.98	100.00
Parking	Fair	1.37	2.11	65.00
Athletic Courts and Fields	Excel	2.77	2.77	100.00
Safety and Security				
Fencing	Fair	0.55	0.85	65.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Poor	1.50	3.00	50.00
Controlled Entrances	Poor	0.25	0.50	50.00
Total For Site:		64.87	96.01	67.57

Comments

Project #: 8272

County: Harnett

Site #: 370201000894

Project: Assessments 2016

Region: 430

Site: WESTERN HARNETT H

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Western Harnett High School is a 9th through 12th grade facility. It provides limited programming in special education. The building was built in 1977 and has had one significant addition. The school utilizes nine portable classrooms.				
Suitability - HS->Learning Environment-->Learning Style Variety				
The building was not designed with any small group or individualized instructional spaces.				
Suitability - HS->Learning Environment-->Interior Environment				
The building is showing some wear and tear. Many of the hallways are narrow. Most offices and many classrooms do not have any windows or natural lighting.				
Suitability - HS->Learning Environment-->Exterior Environment				
The school does not have any outdoor learning labs or social gathering spaces.				
Suitability - HS->General Classrooms-->Environment				
Many of the classrooms do not have any natural lighting or windows. The classrooms are not configured for small group or individualized instruction.				
Suitability - HS->General Classrooms-->Size				
The majority of the classrooms are 760 ft.?. Class sizes often are 35 students. The rooms are too small for the number of students served.				
Suitability - HS->General Classrooms-->Storage/Fixed Equip				
Most of the classrooms do not have any built in storage cabinetry.				
Suitability - HS->Self-Contained Special Ed-->Location				
The self-contained special education classrooms are located in the back of the school. They are a significant distance from the cafeteria, administrative offices, and main entrance.				
Suitability - HS->Self-Contained Special Ed-->Storage/Fixed Equip				
The special education classrooms do not have adequate storage for large mobility equipment.				
Suitability - HS->Science-->Environment				
Some of the science rooms do not have adequate lab stations.				
Suitability - HS->Science-->Size				
The chemistry lab is approximately 80% of the size standard.				
Suitability - HS->Science-->Storage/Fixed Equip				
One of the science rooms has freestanding sinks with no built in lab work areas. Many of the science labs do not have an emergency shower.				
Suitability - HS->Music-->Size				
The music rooms do not have practice rooms, or small ensemble rooms.				
Suitability - HS->Music-->Storage/Fixed Equip				
The band room does not have a sink or adequate uniform storage.				
Suitability - HS->Art-->Location				
The hallway that accesses the art room is extremely narrow.				
Suitability - HS->Career Tech Ed-->Environment				
The shop areas are showing significant wear and tear. They're not well lit. And they do not provide a stimulating educational environment. The school uses numerous portables for CTE instruction.				
Suitability - HS->Career Tech Ed-->Size				
The horticulture program, masonry program, carpentry classroom, metals classroom, and ROTC are all housed in portables. The metal shop, carpentry shops, agricultural shop, and automotive mechanics shops are less than 50% of the size standard. One of the business computer labs is very small.				

Project #: 8272

County: Harnett

Site #: 370201000894

Project: Assessments 2016

Region: 430

Site: WESTERN HARNETT H

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS->Career Tech Ed-->Location The some of the classrooms are located in portables are not adjacent to the shop areas.				
Suitability - HS->Career Tech Ed-->Storage/Fixed Equip The shops do not have adequate storage for supplies materials. The carpentry program does not have a finish room, the culinary arts program does not have adequate storage for all of the equipment.				
Suitability - HS->P.E.-->Environment The weight rooms are former general classrooms that are not well ventilated and are not a stimulating educational environment. The locker rooms are showing significant wear and tear.				
Suitability - HS->P.E.-->Size The school does not have a wrestling room. Wrestling practice is in the auxiliary gym which requires the mats to be rolled out and rolled up after each practice. The weight rooms are extremely small. The physical education locker rooms are small.				
Suitability - HS->P.E.-->Storage/Fixed Equip The school does not have adequate storage for physical education equipment, and mats. The showers are being used for storage.				
Suitability - HS->Performing Arts-->Size The auditorium seats approximately 300 students. It is not large enough to seat the sophomore class. The stage has an extremely low ceiling and is small in size. The performing arts area does not have a small auditorium or a black box theater.				
Suitability - HS->Performing Arts-->Storage/Fixed Equip The performing arts area does not have dressing rooms, a scene shop, adequate storage for props, and costumes.				
Suitability - HS->Media Center-->Environment The media center does not have any natural lighting.				
Suitability - HS->Media Center-->Size The media center is approximately 65% of the size standard. This includes the second floor space.				
Suitability - HS->Media Center-->Storage/Fixed Equip The media center does not have adequate support space. The workroom, AV storage area, and resource materials storage areas are small for the student population.				
Suitability - HS->Restrooms (Student) The school does not have an adequate number of restrooms and bathroom fixtures. The restrooms are showing their age.				
Suitability - HS->Administration Many of the administrative offices are small in size and do not have any natural lighting. The conference room can only seat six individuals. The main conference room has a door that separates it from the nurse's office. Noise infiltration into the nurse's office is a concern. There is a copier in the main administrative hallway.				
Suitability - HS->Counseling Student records are stored in a small room that also serves as the conference room for the counseling staff. The counselor's offices are small and do not have natural lighting.				
Suitability - HS->Clinic The clinic area does not have a restroom or cots. In addition there is a nurse's office located down the hall.				
Suitability - HS->Staff Lounge-WkRm The school has small workrooms that house a copier in various locations. The school does not have a large workroom for the assembly materials, and storage of teaching supplies and materials. The school does not have a staff lounge.				

Project #: 8272

County: Harnett

Site #: 370201000894

Project: Assessments 2016

Region: 430

Site: WESTERN HARNETT H

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
<p>Suitability - HS->Food Service and Prep The food preparation area is extremely small. The office area in the kitchen is small. Due to the configuration of the driveway delivery of food into the kitchen is difficult.</p>				
<p>Suitability - HS->Custodial and Maintenance Many of the custodial areas are not adequately ventilated. The portables are not equipped with custodial rooms requiring the custodians to carry their equipment to the portables.</p>				
<p>Suitability - HS->Outside-->Vehicular Traffic The school is located on a busy highway. Cars turning into and out of the school, due to inadequate turning lanes, cause significant congestion. The parent pick up zone after school is a gravel lot. The gravel lot is used so that the cars do not backup on the highway.</p>				
<p>Suitability - HS->Outside-->Pedestrian Traffic The school is located in a rural setting and there are not walkers.</p>				
<p>Suitability - HS->Outside-->Parking There is not adequate student parking. Overflow parking is in a gravel lot.</p>				
<p>Suitability - HS->Safety and Security-->Fencing The school does not have any perimeter fencing other than the fencing that surrounds the athletic areas.</p>				
<p>Suitability - HS->Safety and Security-->Signage & Way Finding The school does not have adequate external and internal directional signage.</p>				
<p>Suitability - HS->Safety and Security-->Ease of Supervision Due to the configuration of the hallways and the school being two stories, line of sight supervision is extremely difficult.</p>				
<p>Suitability - HS->Safety and Security-->Controlled Entrances The entrance that leads into the main administrative offices does have a security vestibule. The main entrance for students remains open and does not have direct line of sight supervision.</p>				

Suitability Report - Full

Project #: 8272	County: Harnett	Site #: 370201002117
Project: Assessments 2016	Region: 430	Site: STAR ACADEMY
Grade Config: 06-12	Site Type: Other Educational	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Fair	2.54	3.90	65.00
Size	Fair	6.34	9.75	65.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Poor	1.46	2.93	50.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Science				
Environment	Poor	0.41	0.83	50.00
Size	Poor	1.04	2.07	50.00
Location	Poor	0.31	0.62	50.00
Storage/Fixed Equip	Poor	0.31	0.62	50.00
Music				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Art				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Career Tech Ed				
Environment	Poor	0.85	1.71	50.00

Project #: 8272

County: Harnett

Site #: 370201002117

Project: Assessments 2016

Region: 430

Site: STAR ACADEMY

Grade Config: 06-12

Site Type: Other Educational

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Poor	2.14	4.27	50.00
Location	Poor	0.64	1.28	50.00
Storage/Fixed Equip	Poor	0.64	1.28	50.00
Computer Labs				
Environment	Good	0.24	0.30	80.00
Size	Good	0.60	0.75	80.00
Location	Good	0.18	0.23	80.00
Storage/Fixed Equip	Good	0.18	0.23	80.00
P.E.				
Environment	Fair	1.56	2.40	65.00
Size	Good	4.80	6.00	80.00
Location	Fair	1.17	1.80	65.00
Storage/Fixed Equip	Good	1.44	1.80	80.00
Performing Arts				
Environment	Fair	0.21	0.32	65.00
Size	Good	0.64	0.80	80.00
Location	Good	0.19	0.24	80.00
Storage/Fixed Equip	Fair	0.16	0.24	65.00
Media Center				
Environment	Unsat	0.00	0.84	0.00
Size	Unsat	0.00	2.11	0.00
Location	Unsat	0.00	0.63	0.00
Storage/Fixed Equip	Unsat	0.00	0.63	0.00
Restrooms (Student)	Fair	0.59	0.91	65.00
Administration	Fair	1.70	2.61	65.00
Counseling	Good	0.61	0.76	80.00
Clinic	Unsat	0.00	0.24	0.00
Staff Lounge-WkRm	Unsat	0.00	0.71	0.00
Cafeteria	Poor	2.00	4.00	50.00
Food Service and Prep	Fair	3.32	5.11	65.00
Custodial and Maintenance	Fair	0.33	0.50	65.00
Outside				
Vehicular Traffic	Good	0.80	1.00	80.00
Pedestrian Traffic	Good	0.78	0.98	80.00
Parking	Good	1.69	2.11	80.00
Athletic Courts and Fields	(N/A)	0.00	0.00	0.00
Safety and Security				
Fencing	Fair	0.55	0.85	65.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Poor	0.25	0.50	50.00
Total For Site:		51.95	84.28	61.64

Comments

Project #: 8272

County: Harnett

Site #: 370201002117

Project: Assessments 2016

Region: 430

Site: STAR ACADEMY

Grade Config: 06-12

Site Type: Other Educational

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS->Learning Environment-->Learning Style Variety Older historical building serving as an alternative school for high risk youth that lacks a number of 21st century attributes.				
Suitability - HS->Learning Environment-->Interior Environment Most of the surfaces are older and worn with poor acoustical properties.				
Suitability - HS->General Classrooms-->Environment The majority of the classrooms contain hard and worn surface. There is limited natural lighting and poor heating and ventilation.				
Suitability - HS->General Classrooms-->Size The classrooms meet 75% of the recommended size standard.				
Suitability - HS->General Classrooms-->Storage/Fixed Equip There is no storage in the classrooms.				
Suitability - HS->Science-->Environment Science is located in a regular education classroom.				
Suitability - HS->Science-->Size Science is located in a regular education classroom.				
Suitability - HS->Science-->Location Science is located in a regular education classroom.				
Suitability - HS->Science-->Storage/Fixed Equip Science is located in a regular education classroom.				
Suitability - HS->Career Tech Ed-->Environment Career and Technical Education classes is located in a regular education classroom.				
Suitability - HS->Career Tech Ed-->Size Career and Technical Education classes is located in a regular education classroom.				
Suitability - HS->Career Tech Ed-->Location Career and Technical Education classes is located in a regular education classroom.				
Suitability - HS->Career Tech Ed-->Storage/Fixed Equip Career and Technical Education classes is located in a regular education classroom.				
Suitability - HS->P.E.-->Environment Gym floor is lifting, the ceiling is to low for a number of activities, there is limited natural lighting and the HVAC systems work intermittently.				
Suitability - HS->P.E.-->Location The gym is detached from the main building.				
Suitability - HS->Performing Arts-->Environment The auditorium has older seats, lighting equipment and stage curtains. The carpet is worn and the paint is peeling in a number of places.				
Suitability - HS->Performing Arts-->Storage/Fixed Equip The auditorium has older seats, lighting equipment and stage curtains.				
Suitability - HS->Media Center-->Environment There is no media center in the building.				
Suitability - HS->Media Center-->Size There is no media center in the building.				

Project #: 8272

County: Harnett

Site #: 370201002117

Project: Assessments 2016

Region: 430

Site: STAR ACADEMY

Grade Config: 06-12

Site Type: Other Educational

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS->Media Center-->Location There is no media center in the building.				
Suitability - HS->Media Center-->Storage/Fixed Equip There is no media center in the building.				
Suitability - HS->Restrooms (Student) The restrooms have older fixtures, lack storage and poor ventilation.				
Suitability - HS->Administration The administrative offices are small and the principal's office is located in another area of the building.				
Suitability - HS->Clinic There is not a clinic in the building.				
Suitability - HS->Staff Lounge-WkRm There is no staff lounge in the building.				
Suitability - HS->Cafeteria Older tables and chairs. The ceiling is low with stained tiles. There is limited natural lighting and it has poor ventilation.				
Suitability - HS->Food Service and Prep Small with older worn equipment.				
Suitability - HS->Custodial and Maintenance There are a limited number of custodial closets in the building. None on the second floor.				
Suitability - HS->Safety and Security-->Fencing There is a lack of perimeter fencing around the school grounds.				
Suitability - HS->Safety and Security-->Controlled Entrances Lacks controlled entrances at the front of building.				

Suitability Report - Full

Project #: 8272	County: Clay	Site #: 370087000332
Project: Assessments 2016	Region: 220	Site: HAYESVILLE ELEMENTA
Grade Config: PK-04	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Fair	3.19	4.90	65.00
Size	Good	9.80	12.25	80.00
Location	Poor	1.84	3.68	50.00
Storage/Fixed Equip	Fair	2.39	3.68	65.00
Kindergarten				
Environment	Poor	0.21	0.42	50.00
Size	Fair	0.68	1.04	65.00
Location	Poor	0.16	0.31	50.00
Storage/Fixed Equip	Fair	0.20	0.31	65.00
ECE				
Environment	Poor	0.25	0.50	50.00
Size	Poor	0.62	1.25	50.00
Location	Poor	0.19	0.37	50.00
Storage/Fixed Equip	Unsat	0.00	0.37	0.00
Self-Contained Special Ed				
Environment	Unsat	0.00	0.48	0.00
Size	Unsat	0.00	1.20	0.00
Location	Unsat	0.00	0.36	0.00
Storage/Fixed Equip	Unsat	0.00	0.36	0.00
Instructional Resource Rooms				
Environment	Fair	0.47	0.72	65.00
Size	Good	1.44	1.80	80.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Poor	0.27	0.54	50.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Project #: 8272

County: Clay

Site #: 370087000332

Project: Assessments 2016

Region: 220

Site: HAYESVILLE ELEMENTA

Grade Config: PK-04

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	1.48	1.85	80.00
Location	Fair	0.36	0.56	65.00
Storage/Fixed Equip	Good	0.44	0.56	80.00
Art				
Environment	Poor	0.23	0.47	50.00
Size	Fair	0.76	1.17	65.00
Location	Good	0.28	0.35	80.00
Storage/Fixed Equip	Poor	0.18	0.35	50.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Good	0.68	0.85	80.00
Location	Fair	0.17	0.26	65.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Good	1.54	1.92	80.00
Size	Good	3.84	4.80	80.00
Location	Fair	0.94	1.44	65.00
Storage/Fixed Equip	Good	1.15	1.44	80.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Good	1.95	2.44	80.00
Location	Good	0.58	0.73	80.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Fair	0.58	0.89	65.00
Administration	Good	2.05	2.56	80.00
Counseling	Poor	0.15	0.29	50.00
Clinic	Unsat	0.00	0.58	0.00
Staff Lounge-WkRm	Poor	0.63	1.27	50.00
Cafeteria	(N/A)	0.00	0.00	0.00
Food Service and Prep	(N/A)	0.00	0.00	0.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Poor	1.00	2.00	50.00
Pedestrian Traffic	Poor	0.49	0.97	50.00
Parking	Fair	0.53	0.81	65.00
Play Areas	Poor	1.17	2.34	50.00
Safety and Security				
Fencing	Unsat	0.00	0.75	0.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Poor	1.50	3.00	50.00
Controlled Entrances	Unsat	0.00	0.50	0.00

Project #: 8272

County: Clay

Site #: 370087000332

Project: Assessments 2016

Region: 220

Site: HAYESVILLE ELEMENTA

Grade Config: PK-04

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		53.96	83.27	64.80

Comments

Suitability - ES

Hayesville Elementary School consists of grades Kindergarten through fourth grade. The four primary buildings these grades are housed in are the main elementary building, Kindergarten/1st grade building, Rock gym and the old elementary building . Four mobile units are also used for additional classroom space. Hayesville Elementary school offers art, Computers and Chorus to supplement the required curriculum of the State Board of Education.

Suitability - ES->Learning Environment-->Learning Style Variety

The building has limited pull out spaces for small groups. The multiple buildings make for long transition times between classes and pull out programs. There are minimal spatial configuration options for differentiated instructional practices.

Suitability - ES->Learning Environment-->Interior Environment

The surfaces materials are hard (concrete block and VCT tile) which creates acoustical issues and excessive noise in the main circulation areas of the building. There are long transition times between classed due the multiple buildings housing k-4.

Suitability - ES->Learning Environment-->Exterior Environment

The exterior of the building has few architectural features. The grassy areas are worn and / or missing exposing mud which creates cleaning and safety problems on the walkways and building entrances. There is little or no landscaping.

Suitability - ES->General Classrooms-->Environment

The general education classrooms lack an inviting and stimulating environment. There are limited spatial configuration options to support program instruction. Hard material surfaces create significant noise and acoustical problems.

Suitability - ES->General Classrooms-->Location

Classrooms are spread-out across three different buildings making for long transition times.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

There is a lack of casework and cabinetry in the classrooms which limits storage for equipment and supplies.

Suitability - ES->Kindergarten-->Environment

The building housing the kindergarten class rooms is an open concept design. This design creates a significant amount of noise between classrooms which is a distraction for students and makes teaching more challenging.

Suitability - ES->Kindergarten-->Size

The kindergarten classrooms meet 70% of the recommend size standard.

Suitability - ES->Kindergarten-->Location

The kindergarten classrooms are located away from the core educational spaces (media center, office / admin and gym). The parent and bus pick up and drop-off areas are not adjacent to the kindergarten classrooms.

Suitability - ES->Kindergarten-->Storage/Fixed Equip

There is limited storage for kindergarten equipment and supplies. Only on of four kindergarten rooms has a restroom.

Suitability - ES->ECE-->Environment

The pre-school program is located in the old elementary school which does not provide for an inviting and stimulating educational environment. There are limited spatial configuration options and the overall aesthetics are very poor.

Suitability - ES->ECE-->Size

The pre-school program classrooms meet 60% of the recommended size standard.

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->ECE-->Location The pre-school program is located away from the parent and bus pick-up and drop-off areas. The core building spaces are a considerable distance from the pre-school classrooms.				
Suitability - ES->ECE-->Storage/Fixed Equip There is a lack of appropriate storage in the pre-school classrooms. There are not restrooms are changing areas in the regular education or special education pre-school classrooms.				
Suitability - ES->Self-Contained Special Ed-->Environment The self contained special education program is located in a portable classroom building.				
Suitability - ES->Self-Contained Special Ed-->Size The self contained special education program is located in a portable classroom building.				
Suitability - ES->Self-Contained Special Ed-->Location The self contained special education program is located in a portable classroom building.				
Suitability - ES->Self-Contained Special Ed-->Storage/Fixed Equip The self contained special education program is located in a portable classroom building.				
Suitability - ES->Instructional Resource Rooms-->Environment There is limited natural lighting in the instructional resource spaces. The classrooms have hard surfaces (concrete block and VCT tile) creating significant noise and acoustical issues.				
Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip There is limited casework for storage of supplies and equipment. There are no lockable storage cabinets.				
Suitability - ES->Music-->Location The elementary music program is in the Rock building which is a considerable distance from the general education classrooms.				
Suitability - ES->Art-->Environment The art classroom is a converted general education classroom. The art room lacks the standard configuration options for this program. There is limited natural lighting and the environment is not very stimulating. Overall the aesthetics are poor.				
Suitability - ES->Art-->Size The art room meets 65% of the recommended size standard.				
Suitability - ES->Art-->Storage/Fixed Equip There are no sinks, the kiln is not working and there is limited storage for supplies.				
Suitability - ES->Computer Labs-->Location The elementary computer lab is in the Rock building which is a considerable distance from the general education classrooms.				
Suitability - ES->P.E.-->Location The elementary gymnasium is in the Rock building which is a considerable distance from the general education classrooms.				
Suitability - ES->Performing Arts The performing arts building is shared between all three schools (ES, MS and HS) the space has been scored as a component of the high school.				
Suitability - ES->Restrooms (Student) The number of restrooms is not sufficient for the size of the school enrollment.				
Suitability - ES->Counseling There is not a counseling office in the elementary school. The counselor comes 3 times a week and sets up in a conference room. The are issues with privacy and confidentiality.				

Project #: 8272

County: Clay

Site #: 370087000332

Project: Assessments 2016

Region: 220

Site: HAYESVILLE ELEMENTA

Grade Config: PK-04

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Clinic				
The clinic is located in a space that was previously a closet. There are no windows or ventilation in the space. There is no waiting area for students. The clinic and the nurses are shared by all three schools (ES, MS, HS).				
Suitability - ES->Staff Lounge-WkRm				
The staff workroom is a shared space within the administration areas.				
Suitability - ES->Cafeteria				
The cafeteria is shared between all three schools (ES, MS and HS) the space has been scored as a component of the high school.				
Suitability - ES->Food Service and Prep				
The food service is a shared space between all three schools (ES, MS and HS) the space has been scored as a component of the high school.				
Suitability - ES->Outside-->Vehicular Traffic				
There is not adequate traffic separation between vehicles, buses, and pedestrian traffic.				
Suitability - ES->Outside-->Pedestrian Traffic				
There is a lack of vehicle and pedestrian separation. There are not adequate sidewalks or pedestrian pathways.				
Suitability - ES->Outside-->Parking				
There is limited staff and visitor parking.				
Suitability - ES->Outside-->Play Areas				
There is not a designated area for elementary school playfields on the school campus. The current areas being used lack adequate size, equipment and grass fields.				
Suitability - ES->Safety and Security-->Fencing				
There is not adequate fencing to secure the campus appropriately.				
Suitability - ES->Safety and Security-->Ease of Supervision				
There are a number of blind spots behind buildings and structures across the campus. There are a limited number of security cameras. Supervision is difficult during morning and afternoon pick-up and drop-off times.				
Suitability - ES->Safety and Security-->Controlled Entrances				
The entrance to the school is not controlled by means of an electronic access device or card. Multiple doors throughout the building are unlocked during school hours.				

Suitability Report - Full

Project #: 8272	County: Clay	Site #: 370087002226
Project: Assessments 2016	Region: 220	Site: HAYESVILLE MIDDLE
Grade Config: 05-08	Site Type: Middle	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Poor	0.75	1.50	50.00
General Classrooms				
Environment	Fair	2.54	3.90	65.00
Size	Good	7.80	9.75	80.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Poor	1.46	2.93	50.00
Self-Contained Special Ed				
Environment	Fair	0.35	0.55	65.00
Size	Poor	0.68	1.36	50.00
Location	Good	0.33	0.41	80.00
Storage/Fixed Equip	Poor	0.20	0.41	50.00
Instructional Resource Rooms				
Environment	Fair	0.53	0.82	65.00
Size	Fair	1.33	2.05	65.00
Location	Good	0.49	0.61	80.00
Storage/Fixed Equip	Poor	0.31	0.61	50.00
Science				
Environment	Poor	0.48	0.95	50.00
Size	Fair	1.55	2.39	65.00
Location	Good	0.57	0.72	80.00
Storage/Fixed Equip	Unsat	0.00	0.72	0.00
Music				
Environment	Unsat	0.00	0.74	0.00
Size	Unsat	0.00	1.84	0.00
Location	Unsat	0.00	0.55	0.00
Storage/Fixed Equip	Unsat	0.00	0.55	0.00
Art				
Environment	Unsat	0.00	0.65	0.00
Size	Unsat	0.00	1.61	0.00
Location	Unsat	0.00	0.48	0.00
Storage/Fixed Equip	Unsat	0.00	0.48	0.00
Career Tech Ed				
Environment	(N/A)	0.00	0.00	0.00

Project #: 8272

County: Clay

Site #: 370087002226

Project: Assessments 2016

Region: 220

Site: HAYESVILLE MIDDLE

Grade Config: 05-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Computer Labs				
Environment	Good	0.24	0.30	80.00
Size	Good	0.60	0.75	80.00
Location	Good	0.18	0.23	80.00
Storage/Fixed Equip	Good	0.18	0.23	80.00
P.E.				
Environment	Good	1.92	2.40	80.00
Size	Good	4.80	6.00	80.00
Location	Good	1.44	1.80	80.00
Storage/Fixed Equip	Poor	0.90	1.80	50.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.74	0.93	80.00
Size	Good	1.86	2.32	80.00
Location	Good	0.56	0.70	80.00
Storage/Fixed Equip	Good	0.56	0.70	80.00
Restrooms (Student)	Good	0.74	0.93	80.00
Administration	Good	1.68	2.10	80.00
Counseling	Good	0.34	0.42	80.00
Clinic	Unsat	0.00	0.34	0.00
Staff Lounge-WkRm	Good	0.72	0.91	80.00
Cafeteria	(N/A)	0.00	0.00	0.00
Food Service and Prep	(N/A)	0.00	0.00	0.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Poor	2.00	4.00	50.00
Pedestrian Traffic	Poor	0.22	0.43	50.00
Parking	Fair	0.56	0.86	65.00
Athletic Courts and Fields	Poor	0.52	1.05	50.00
Safety and Security				
Fencing	Unsat	0.00	0.78	0.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Poor	1.50	3.00	50.00
Controlled Entrances	Unsat	0.00	0.50	0.00
Total For Site:		50.47	81.45	61.97

Comments

Project #: 8272

County: Clay

Site #: 370087002226

Project: Assessments 2016

Region: 220

Site: HAYESVILLE MIDDLE

Grade Config: 05-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Hayesville Middle School consists of fifth through eighth grades. The students are primarily housed in the middle school building and the middle school gymnasium. The middle school shares two mobile units with high school for alternative learning programs and English as a Second Language Program. Hayesville Middle School offers Art, Chorus, Academically Gifted, Music, Computers, Agriculture and STEAM (Science, Technology, Engineering, Arts and Math) as a supplement to the required state curriculum. The middle school also has an alternative education				
Suitability - MS->Learning Environment-->Interior Environment				
The facility lacks an inviting and stimulating environment. There are limited spatial configuration options. Minimal small break out spaces for students and overall aesthetics are poor. The building has an institutional feel which does not enhance and support the educational objectives of the staff.				
Suitability - MS->Learning Environment-->Exterior Environment				
The exterior of the building provides little or no educational spaces for students to extend their learning opportunities. There are no outdoor classrooms, no art patios and limited social gathering spaces. The grounds are not conducive to the educational programs of the middle school.				
Suitability - MS->General Classrooms-->Environment				
The general education classrooms do not provide an inviting and stimulating environment. There is limited spatial configuration options to enhance the instructional program. Overall the spaces are very institutional in appearance and aesthetics are very poor.				
Suitability - MS->General Classrooms-->Storage/Fixed Equip				
The general classrooms have limited appropriate casework and supply storage. Classrooms are lacking lockable storage for expensive technology equipment.				
Suitability - MS->Self-Contained Special Ed-->Environment				
The self contained classrooms do not provide an inviting or stimulating environment. There are limited spatial configuration options to enhance the instructional program.				
Suitability - MS->Self-Contained Special Ed-->Size				
The self-contained resource room meets 64% of the recommended size standard.				
Suitability - MS->Self-Contained Special Ed-->Storage/Fixed Equip				
There is limited storage for special education equipment, occupational and therapy equipment and program supplies. Most self contained rooms do not have washer / dryer spaces and many lack restrooms, changing areas and showers.				
Suitability - MS->Instructional Resource Rooms-->Environment				
The instructional resource classrooms do not provide an inviting and stimulating environment. There is limited spatial configuration options to enhance the instructional program. Overall the spaces are very institutional in appearance and aesthetics are very poor.				
Suitability - MS->Instructional Resource Rooms-->Size				
50% of the instructional resource classrooms do not meet the recommended size standard.				
Suitability - MS->Instructional Resource Rooms-->Storage/Fixed Equip				
There is limited casework and supply storage. Classrooms are lacking lockable storage for expensive technology equipment.				
Suitability - MS->Science-->Environment				
Science classrooms are located in general education classrooms which lack the environmental standards for standard middle school science classrooms.				
Suitability - MS->Science-->Size				
Science classrooms meet 71% of the recommended size standard.				
Suitability - MS->Science-->Storage/Fixed Equip				
The science classrooms do not have the minimum level of science and safety equipment as required.				

Project #: 8272

County: Clay

Site #: 370087002226

Project: Assessments 2016

Region: 220

Site: HAYESVILLE MIDDLE

Grade Config: 05-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS->Music-->Environment				
The middle school does not have music classrooms. The North Carolina facility guidelines suggests music (chorus and band) at all middle schools. The lack of music classrooms at the middle school results in an unsatisfactory rating.				
Suitability - MS->Music-->Size				
The middle school does not have music classrooms. The North Carolina facility guidelines suggests music (chorus and band) at all middle schools. The lack of music classrooms at the middle school results in an unsatisfactory rating.				
Suitability - MS->Music-->Location				
The middle school does not have music classrooms. The North Carolina facility guidelines suggests music (chorus and band) at all middle schools. The lack of music classrooms at the middle school results in an unsatisfactory rating..				
Suitability - MS->Music-->Storage/Fixed Equip				
The middle school does not have music classrooms. The North Carolina facility guidelines suggests music (chorus and band) at all middle schools. The lack of music classrooms at the middle school results in an unsatisfactory rating.				
Suitability - MS->Art-->Environment				
The middle school does not have art classrooms. The North Carolina facility guidelines suggest art classrooms at all middle schools. The lack of art classrooms at the middle school results in an unsatisfactory rating.				
Suitability - MS->Art-->Size				
The middle school does not have art classrooms. The North Carolina facility guidelines suggest art classrooms at all middle schools. The lack of art classrooms at the middle school results in an unsatisfactory rating.				
Suitability - MS->Art-->Location				
The middle school does not have art classrooms. The North Carolina facility guidelines suggest art classrooms at all middle schools. The lack of art classrooms at the middle school results in an unsatisfactory rating.				
Suitability - MS->Art-->Storage/Fixed Equip				
The middle school does not have art classrooms. The North Carolina facility guidelines suggest art classrooms at all middle schools. The lack of art classrooms at the middle school results in an unsatisfactory rating.				
Suitability - MS->P.E.-->Storage/Fixed Equip				
Both the boys and girls locker rooms lack the appropriate number of bathroom stalls / urinals, lockers, equipment storage and shower facilities.				
Suitability - MS->Clinic				
There is no clinic in the middle school.				
Suitability - MS->Outside-->Vehicular Traffic				
There is not adequate traffic separation between vehicles, buses, and pedestrian traffic.				
Suitability - MS->Outside-->Pedestrian Traffic				
There is a lack of vehicle and pedestrian separation. There are not adequate sidewalks or pedestrian pathways.				
Suitability - MS->Outside-->Parking				
There is limited staff and visitor parking.				
Suitability - MS->Outside-->Athletic Courts and Fields				
There is not a designated area for middle school playfields on the school campus. The current areas being used lack adequate size, equipment and grass fields.				
Suitability - MS->Safety and Security-->Fencing				
There is not adequate fencing to secure the campus appropriately.				

Project #: 8272

County: Clay

Site #: 370087002226

Project: Assessments 2016

Region: 220

Site: HAYESVILLE MIDDLE

Grade Config: 05-08

Site Type: Middle

Site Size: 0.00

Suitability

Rating

Score

**Possible
Score**

**Percent
Score**

Suitability - MS->Safety and Security-->Ease of Supervision

There are a number of blind spots behind buildings and structures across the campus. There are a limited number of security cameras. Supervision is difficult during morning and afternoon pick-up and drop-off times.

Suitability - MS->Safety and Security-->Controlled Entrances

The entrance to the school is not controlled by means of an electronic access device or card. Multiple doors throughout the building are unlocked during school hours.

Suitability Report - Full

Project #: 8272	County: Clay	Site #: 370087000333
Project: Assessments 2016	Region: 220	Site: HAYESVILLE HIGH
Grade Config: 09-12	Site Type: High	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Poor	0.75	1.50	50.00
General Classrooms				
Environment	Fair	2.54	3.90	65.00
Size	Good	7.80	9.75	80.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Poor	1.46	2.93	50.00
Self-Contained Special Ed				
Environment	Fair	0.35	0.53	65.00
Size	Good	1.07	1.33	80.00
Location	Good	0.32	0.40	80.00
Storage/Fixed Equip	Poor	0.20	0.40	50.00
Instructional Resource Rooms				
Environment	Fair	0.52	0.80	65.00
Size	Good	1.60	2.00	80.00
Location	Good	0.48	0.60	80.00
Storage/Fixed Equip	Fair	0.39	0.60	65.00
Science				
Environment	Good	0.66	0.83	80.00
Size	Good	1.66	2.07	80.00
Location	Good	0.50	0.62	80.00
Storage/Fixed Equip	Good	0.50	0.62	80.00
Music				
Environment	Good	0.48	0.59	80.00
Size	Fair	0.96	1.48	65.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Fair	0.29	0.45	65.00
Art				
Environment	Good	0.53	0.67	80.00
Size	Good	1.33	1.66	80.00
Location	Good	0.40	0.50	80.00
Storage/Fixed Equip	Fair	0.32	0.50	65.00
Career Tech Ed				
Environment	Good	1.37	1.71	80.00

Project #: 8272

County: Clay

Site #: 370087000333

Project: Assessments 2016

Region: 220

Site: HAYESVILLE HIGH

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	3.42	4.27	80.00
Location	Good	1.03	1.28	80.00
Storage/Fixed Equip	Good	1.03	1.28	80.00
Computer Labs				
Environment	Good	0.24	0.30	80.00
Size	Good	0.60	0.75	80.00
Location	Good	0.18	0.23	80.00
Storage/Fixed Equip	Good	0.18	0.23	80.00
P.E.				
Environment	Excel	2.40	2.40	100.00
Size	Excel	6.00	6.00	100.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Good	1.44	1.80	80.00
Performing Arts				
Environment	Poor	0.16	0.32	50.00
Size	Good	0.64	0.80	80.00
Location	Good	0.19	0.24	80.00
Storage/Fixed Equip	Poor	0.12	0.24	50.00
Media Center				
Environment	Good	0.67	0.84	80.00
Size	Good	1.69	2.11	80.00
Location	Good	0.51	0.63	80.00
Storage/Fixed Equip	Good	0.51	0.63	80.00
Restrooms (Student)	Fair	0.59	0.91	65.00
Administration	Good	2.09	2.61	80.00
Counseling	Good	0.61	0.76	80.00
Clinic	Unsat	0.00	0.24	0.00
Staff Lounge-WkRm	Good	0.57	0.71	80.00
Cafeteria	Fair	2.60	4.00	65.00
Food Service and Prep	Fair	3.32	5.11	65.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Unsat	0.00	1.00	0.00
Pedestrian Traffic	Poor	0.49	0.98	50.00
Parking	Fair	1.37	2.11	65.00
Athletic Courts and Fields	Good	2.21	2.77	80.00
Safety and Security				
Fencing	Poor	0.42	0.85	50.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Poor	1.50	3.00	50.00
Controlled Entrances	Unsat	0.00	0.50	0.00
Total For Site:		74.23	100.00	74.23

Comments

Project #: 8272

County: Clay

Site #: 370087000333

Project: Assessments 2016

Region: 220

Site: HAYESVILLE HIGH

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Hayesville High School is comprised of night through twelfth grade. The students are primarily housed in the high school building and the bottom of the central office building. Hayesville High School offers the Standard Course of Study required by the State Board of Education.				
Suitability - HS->Learning Environment-->Interior Environment				
The high school building has limited spatial configuration. The concrete block walls and VCT tile floors give the building and institutional feeling which not very inviting or stimulating.				
Suitability - HS->Learning Environment-->Exterior Environment				
The exterior of the building provides little or no educational spaces for students to extend their learning opportunities. There are no outdoor classrooms, no art patios and limited social gathering spaces.				
Suitability - HS->General Classrooms-->Environment				
The general education classrooms do not provide an inviting and stimulating environment. There is limited spatial configuration options to enhance the instructional program. Overall the spaces are very institutional in appearance and aesthetics are very poor.				
Suitability - HS->General Classrooms-->Storage/Fixed Equip				
The general classrooms have limited appropriate casework and supply storage. Classrooms are lacking lockable storage for expensive technology equipment.				
Suitability - HS->Self-Contained Special Ed-->Environment				
There are limited spatial configuration options to enhance the instructional program.				
Suitability - HS->Self-Contained Special Ed-->Storage/Fixed Equip				
There is limited storage for special education equipment, occupational and therapy equipment and program supplies. The self contained rooms do not have washer / dryer spaces and many lack restrooms, changing areas and showers.				
Suitability - HS->Instructional Resource Rooms-->Environment				
The instructional resource classrooms do not provide an inviting and stimulating environment. There is limited spatial configuration options to enhance the instructional program. Overall the spaces are very institutional in appearance and aesthetics are very poor.				
Suitability - HS->Instructional Resource Rooms-->Storage/Fixed Equip				
There is limited casework and supply storage.				
Suitability - HS->Music-->Size				
Chorus room is a general education classroom and does not meet the size standard guidelines.				
Suitability - HS->Music-->Storage/Fixed Equip				
The chorus room does not have adequate storage for equipment and supplies.				
Suitability - HS->Art-->Storage/Fixed Equip				
There are no clay traps on the sinks and the kiln is not working properly.				
Suitability - HS->Performing Arts-->Environment				
The performing arts center is a stand alone older building lacking a number of contemporary attributes. The stage is small, lacks the appropriate lighting and sound systems. The seating is old and not very flexible. The tile floor is asbestos.				
Suitability - HS->Performing Arts-->Storage/Fixed Equip				
The stage is small, lacks the appropriate lighting and sound systems. There are no dressing rooms. Storage for costumes and sets is lacking.				
Suitability - HS->Restrooms (Student)				
The restrooms are not the appropriate size or do they have adequate numbers of stall / urinals for the student population.				

Project #: 8272

County: Clay

Site #: 370087000333

Project: Assessments 2016

Region: 220

Site: HAYESVILLE HIGH

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS->Clinic There is no clinic at the High School.				
Suitability - HS->Cafeteria The cafeteria is a stand alone building shared by all three schools (ES, MS, and HS). The size of the building and seating capacity is not adequate to support the student population of all three schools. The serving lines are long and serving areas are crowded.				
Suitability - HS->Food Service and Prep The food service area is lacking adequate preparation spaces and service areas. The equipment is older and in some cases is not working properly. There is limited cold and dry storage.				
Suitability - HS->Outside-->Vehicular Traffic There is not adequate traffic separation between vehicles, buses, and pedestrian traffic.				
Suitability - HS->Outside-->Pedestrian Traffic There is a lack of vehicle and pedestrian separation. There are not adequate sidewalks or pedestrian pathways.				
Suitability - HS->Outside-->Parking There is limited staff and visitor parking.				
Suitability - HS->Safety and Security-->Fencing There is not adequate fencing to secure the campus appropriately.				
Suitability - HS->Safety and Security-->Ease of Supervision There are a number of blind spots behind buildings and structures across the campus. There are a limited number of security cameras. Supervision is difficult during morning and afternoon pick-up and drop-off times.				
Suitability - HS->Safety and Security-->Controlled Entrances The entrance to the school is not controlled by means of an electronic access device or card. Multiple doors throughout the building are unlocked during school hours.				

Suitability Report - Full

Project #: 8272	County: Jones	Site #: 370240001033
Project: Assessments 2016	Region: 520	Site: COMFORT ELEMENTAR
Grade Config: PK-06	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Excel	2.00	2.00	100.00
Exterior Environment	Poor	0.75	1.50	50.00
General Classrooms				
Environment	Excel	4.90	4.90	100.00
Size	Excel	12.25	12.25	100.00
Location	Excel	3.68	3.68	100.00
Storage/Fixed Equip	Excel	3.68	3.68	100.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Excel	1.04	1.04	100.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Excel	0.31	0.31	100.00
ECE				
Environment	Excel	0.50	0.50	100.00
Size	Excel	1.25	1.25	100.00
Location	Excel	0.37	0.37	100.00
Storage/Fixed Equip	Excel	0.37	0.37	100.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Excel	0.72	0.72	100.00
Size	Excel	1.80	1.80	100.00
Location	Excel	0.54	0.54	100.00
Storage/Fixed Equip	Excel	0.54	0.54	100.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Project #: 8272

County: Jones

Site #: 370240001033

Project: Assessments 2016

Region: 520

Site: COMFORT ELEMENTAR

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Poor	0.93	1.85	50.00
Location	Good	0.44	0.56	80.00
Storage/Fixed Equip	Poor	0.28	0.56	50.00
Art				
Environment	Good	0.37	0.47	80.00
Size	Poor	0.58	1.17	50.00
Location	Good	0.28	0.35	80.00
Storage/Fixed Equip	Poor	0.18	0.35	50.00
Computer Labs				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
P.E.				
Environment	Good	1.54	1.92	80.00
Size	Fair	3.12	4.80	65.00
Location	Excel	1.44	1.44	100.00
Storage/Fixed Equip	Fair	0.94	1.44	65.00
Performing Arts				
Environment	Good	0.48	0.60	80.00
Size	Poor	0.76	1.51	50.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Poor	0.23	0.45	50.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Good	1.95	2.44	80.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Excel	0.73	0.73	100.00
Restrooms (Student)	Excel	0.89	0.89	100.00
Administration	Excel	2.56	2.56	100.00
Counseling	Good	0.23	0.29	80.00
Clinic	Good	0.47	0.58	80.00
Staff Lounge-WkRm	Excel	1.27	1.27	100.00
Cafeteria	Good	4.00	5.00	80.00
Food Service and Prep	Excel	6.20	6.20	100.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Excel	2.00	2.00	100.00
Pedestrian Traffic	Excel	0.97	0.97	100.00
Parking	Excel	0.81	0.81	100.00
Play Areas	Excel	2.34	2.34	100.00
Safety and Security				
Fencing	Poor	0.38	0.75	50.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Good	0.40	0.50	80.00

Project #: 8272

County: Jones

Site #: 370240001033

Project: Assessments 2016

Region: 520

Site: COMFORT ELEMENTAR

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		81.61	93.39	87.38

Comments

Suitability - ES

Comfort Elementary School is located in Trenton, NC and serves students in grades PK through 6. It is one of the newer schools in the county, having been built in 1999. The school has a patio courtyard area that facilitates outside learning.

Suitability - ES->Learning Environment-->Learning Style Variety

The school does not have flexible use spaces to accommodate differentiated instruction and multiple teaching styles.

Suitability - ES->Learning Environment-->Exterior Environment

There are no outdoor learning spaces.

Suitability - ES->Self-Contained Special Ed

There is no program or program space at the school.

Suitability - ES->Science

There is no science space at the school.

Suitability - ES->Music

The school has no music room. This subject is in a regular classroom and the space is shared with the art program.

Suitability - ES->Music-->Size

The program is in a regular classroom that shares space with the art program.

Suitability - ES->Music-->Storage/Fixed Equip

The music program shares a room with the art program and does not have sufficient storage space.

Suitability - ES->Art

The school has no art room. This subject is in a regular classroom and the space is shared with the music program.

Suitability - ES->Art-->Size

The program is in a regular classroom with space shared with the music program.

Suitability - ES->Art-->Storage/Fixed Equip

The room does not meet the size standards for an art space.

Suitability - ES->P.E.-->Size

The space is a multipurpose room that is below the size standard for an elementary school gym.

Suitability - ES->P.E.-->Storage/Fixed Equip

The space has good storage, but there are no safety pads on the walls behind the basketball hoops on both ends of the room.

Suitability - ES->Performing Arts-->Size

The stage is well below the size standard and limits its utility for performances.

Suitability - ES->Performing Arts-->Storage/Fixed Equip

There is no storage space and the stage has no curtains.

Suitability - ES->Safety and Security-->Fencing

The only fencing is around the pre-kindergarten playground. There is no other fencing on the campus.

Suitability Report - Full

Project #: 8272	County: Jones	Site #: 370240001036
Project: Assessments 2016	Region: 520	Site: MAYSVILLE ELEMENTAR
Grade Config: PK-06	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Poor	2.50	5.00	50.00
Interior Environment	Excel	2.00	2.00	100.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Excel	4.90	4.90	100.00
Size	Excel	12.25	12.25	100.00
Location	Excel	3.68	3.68	100.00
Storage/Fixed Equip	Excel	3.68	3.68	100.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Excel	1.04	1.04	100.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Excel	0.31	0.31	100.00
ECE				
Environment	Excel	0.50	0.50	100.00
Size	Excel	1.25	1.25	100.00
Location	Excel	0.37	0.37	100.00
Storage/Fixed Equip	Excel	0.37	0.37	100.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Good	1.44	1.80	80.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Unsat	0.00	0.74	0.00

Project #: 8272

County: Jones

Site #: 370240001036

Project: Assessments 2016

Region: 520

Site: MAYSVILLE ELEMENTAR

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Unsat	0.00	1.85	0.00
Location	Unsat	0.00	0.56	0.00
Storage/Fixed Equip	Unsat	0.00	0.56	0.00
Art				
Environment	Unsat	0.00	0.47	0.00
Size	Unsat	0.00	1.17	0.00
Location	Unsat	0.00	0.35	0.00
Storage/Fixed Equip	Unsat	0.00	0.35	0.00
Computer Labs				
Environment	Unsat	0.00	0.34	0.00
Size	Unsat	0.00	0.85	0.00
Location	Unsat	0.00	0.26	0.00
Storage/Fixed Equip	Unsat	0.00	0.26	0.00
P.E.				
Environment	Good	1.54	1.92	80.00
Size	Good	3.84	4.80	80.00
Location	Good	1.15	1.44	80.00
Storage/Fixed Equip	Good	1.15	1.44	80.00
Performing Arts				
Environment	Good	0.48	0.60	80.00
Size	Good	1.21	1.51	80.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Good	0.36	0.45	80.00
Media Center				
Environment	Excel	0.97	0.97	100.00
Size	Poor	1.22	2.44	50.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Excel	0.89	0.89	100.00
Administration	Excel	2.56	2.56	100.00
Counseling	Poor	0.15	0.29	50.00
Clinic	Poor	0.29	0.58	50.00
Staff Lounge-WkRm	Excel	1.27	1.27	100.00
Cafeteria	Fair	3.25	5.00	65.00
Food Service and Prep	Fair	4.03	6.20	65.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Excel	2.00	2.00	100.00
Pedestrian Traffic	Excel	0.97	0.97	100.00
Parking	Excel	0.81	0.81	100.00
Play Areas	Excel	2.34	2.34	100.00
Safety and Security				
Fencing	Excel	0.75	0.75	100.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Excel	0.50	0.50	100.00

Project #: 8272

County: Jones

Site #: 370240001036

Project: Assessments 2016

Region: 520

Site: MAYSVILLE ELEMENTAR

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		74.48	95.10	78.32

Comments

Suitability - ES

Mayville Elementary School is located in Mayville, NC, and is surrounded by communities that have experienced high population growth due to nearby military bases. The school serves students in grades PK through 6. The main school building was constructed in 1981, with an additional wing completed in the early 1990's.

Suitability - ES->Learning Environment-->Learning Style Variety

The school does not have flexible-use spaces that facilitate various group sizes or differentiated instruction.

Suitability - ES->Self-Contained Special Ed

There is no program or space for Self-Contained Special Education at this school.

Suitability - ES->Science

This is not a required space at the elementary level.

Suitability - ES->Music-->Environment

There is no music space in the school. Music shares the space with music in a regular classroom.

Suitability - ES->Music-->Size

There is no music space in the school. Music shares the space with music in a regular classroom.

Suitability - ES->Music-->Location

There is no music space in the school. Music shares the space with music in a regular classroom.

Suitability - ES->Music-->Storage/Fixed Equip

There is no music space in the school. Music shares the space with music in a regular classroom.

Suitability - ES->Art-->Environment

There is no art space in the school. Art shares the space with music in a regular classroom.

Suitability - ES->Art-->Size

There is no art space in the school. Art shares the space with music in a regular classroom.

Suitability - ES->Art-->Location

There is no art space in the school. Art shares the space with music in a regular classroom.

Suitability - ES->Art-->Storage/Fixed Equip

There is no art space in the school. Art shares the space with music in a regular classroom.

Suitability - ES->Computer Labs-->Environment

There is no computer lab in the school.

Suitability - ES->Computer Labs-->Size

There is no computer lab in the school.

Suitability - ES->Computer Labs-->Location

There is no computer lab in the school.

Suitability - ES->Computer Labs-->Storage/Fixed Equip

There is no computer lab in the school.

Suitability - ES->Media Center-->Size

The space is well below the size standard.

Suitability - ES->Counseling

The space is well below the size standard.

Project #: 8272

County: Jones

Site #: 370240001036

Project: Assessments 2016

Region: 520

Site: MAYSVILLE ELEMENTAR

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability

Rating

Score

**Possible
Score**

**Percent
Score**

Suitability - ES->Clinic

There is not a dedicated clinic in the school, and the space does not meet the standards for a clinic. There is no nurse at the school full time.

Suitability - ES->Cafeteria

Space is slightly below the size standard.

Suitability - ES->Food Service and Prep

Space is slightly below the size standard.

Suitability - ES->Safety and Security-->Signage & Way Finding

The main entrance and main office are clearly designated, but there is no way-finding signage to the other major spaces in the school.

Suitability Report - Full

Project #: 8272

County: Jones

Site #: 370240001037

Project: Assessments 2016

Region: 520

Site: POLLOCKSVILLE ELEM

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Poor	2.50	5.00	50.00
Interior Environment	Excel	2.00	2.00	100.00
Exterior Environment	Poor	0.75	1.50	50.00
General Classrooms				
Environment	Excel	4.90	4.90	100.00
Size	Excel	12.25	12.25	100.00
Location	Excel	3.68	3.68	100.00
Storage/Fixed Equip	Excel	3.68	3.68	100.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Excel	1.04	1.04	100.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Excel	0.31	0.31	100.00
ECE				
Environment	Excel	0.50	0.50	100.00
Size	Excel	1.25	1.25	100.00
Location	Excel	0.37	0.37	100.00
Storage/Fixed Equip	Excel	0.37	0.37	100.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Excel	0.72	0.72	100.00
Size	Good	1.44	1.80	80.00
Location	Excel	0.54	0.54	100.00
Storage/Fixed Equip	Excel	0.54	0.54	100.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Unsat	0.00	0.74	0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Unsat	0.00	1.85	0.00
Location	Unsat	0.00	0.56	0.00
Storage/Fixed Equip	Unsat	0.00	0.56	0.00
Art				
Environment	Unsat	0.00	0.47	0.00
Size	Unsat	0.00	1.17	0.00
Location	Unsat	0.00	0.35	0.00
Storage/Fixed Equip	Unsat	0.00	0.35	0.00
Computer Labs				
Environment	Excel	0.34	0.34	100.00
Size	Excel	0.85	0.85	100.00
Location	Excel	0.26	0.26	100.00
Storage/Fixed Equip	Excel	0.26	0.26	100.00
P.E.				
Environment	Poor	0.96	1.92	50.00
Size	Poor	2.40	4.80	50.00
Location	Excel	1.44	1.44	100.00
Storage/Fixed Equip	Poor	0.72	1.44	50.00
Performing Arts				
Environment	Good	0.48	0.60	80.00
Size	Poor	0.76	1.51	50.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Fair	0.29	0.45	65.00
Media Center				
Environment	Excel	0.97	0.97	100.00
Size	Poor	1.22	2.44	50.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Excel	0.89	0.89	100.00
Administration	Excel	2.56	2.56	100.00
Counseling	Fair	0.19	0.29	65.00
Clinic	Good	0.47	0.58	80.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Fair	3.25	5.00	65.00
Food Service and Prep	Good	4.96	6.20	80.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Excel	2.00	2.00	100.00
Pedestrian Traffic	Excel	0.97	0.97	100.00
Parking	Excel	0.81	0.81	100.00
Play Areas	Excel	2.34	2.34	100.00
Safety and Security				
Fencing	Excel	0.75	0.75	100.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Excel	0.50	0.50	100.00

Project #: 8272

County: Jones

Site #: 370240001037

Project: Assessments 2016

Region: 520

Site: POLLOCKSVILLE ELEM

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		74.31	95.10	78.14

Comments

Suitability - ES

Pollocksville Elementary School is located in the town of Pollocksville, NC in the northeast corner of Jones County, and serves students in grades PK through 6. It is one of the newer schools in the county, having been built in 1990.

Suitability - ES->Learning Environment-->Learning Style Variety

The school does not have flexible-use spaces that facilitate various group sizes or differentiated instruction.

Suitability - ES->Learning Environment-->Exterior Environment

The school has no exterior learning spaces.

Suitability - ES->Self-Contained Special Ed

This program does not exist at this school.

Suitability - ES->Science

This is not a required space at the elementary level and there is no science space at this school.

Suitability - ES->Music-->Environment

There is no music space in the school. Music shares the space with art in a regular PK/K classroom.

Suitability - ES->Music-->Size

There is no music space in the school. Music shares the space with art in a regular PK/K classroom.

Suitability - ES->Music-->Location

There is no music space in the school. Music shares the space with art in a regular PK/K classroom.

Suitability - ES->Music-->Storage/Fixed Equip

There is no music space in the school. Music shares the space with art in a regular PK/K classroom.

Suitability - ES->Art-->Environment

There is no art space in the school. Art shares the space with music in a regular PK/K classroom.

Suitability - ES->Art-->Size

There is no art space in the school. Art shares the space with music in a regular PK/K classroom.

Suitability - ES->Art-->Location

There is no art space in the school. Art shares the space with music in a regular PK/K classroom.

Suitability - ES->Art-->Storage/Fixed Equip

There is no art space in the school. Art shares the space with music in a regular PK/K classroom.

Suitability - ES->Computer Labs

Computer lab is not currently in full use.

Suitability - ES->P.E.-->Environment

The space is a small multi-purpose room and does contains the required components of a gym.

Suitability - ES->P.E.-->Size

The space is a small multi-purpose room and does not meet the size standard.

Suitability - ES->P.E.-->Storage/Fixed Equip

There is very limited storage space.

Suitability - ES->Performing Arts-->Size

Space is well below the size standard.

Suitability - ES->Performing Arts-->Storage/Fixed Equip

There is a small amount of space behind the stage but materials and equipment have exceeded the available space.

Project #: 8272

County: Jones

Site #: 370240001037

Project: Assessments 2016

Region: 520

Site: POLLOCKSVILLE ELEM

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Media Center-->Size Space does not meet the size standard.				
Suitability - ES->Counseling Guidance office is below the size standard.				
Suitability - ES->Clinic The school does not have a full-time nurse so the space provided falls below the standard for space/size.				
Suitability - ES->Cafeteria The cafeteria does not meet the size standard.				
Suitability - ES->Safety and Security-->Signage & Way Finding Other than the main entrance and office areas, there is no way-finding signage in the building.				

Suitability Report - Full

Project #: 8272	County: Jones	Site #: 370240001038
Project: Assessments 2016	Region: 520	Site: TRENTON ELEMENTAR
Grade Config: PK-06	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Poor	2.50	5.00	50.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Poor	0.75	1.50	50.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Good	9.80	12.25	80.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Poor	1.84	3.68	50.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Good	0.83	1.04	80.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Poor	0.16	0.31	50.00
ECE				
Environment	Excel	0.50	0.50	100.00
Size	Excel	1.25	1.25	100.00
Location	Excel	0.37	0.37	100.00
Storage/Fixed Equip	Good	0.30	0.37	80.00
Self-Contained Special Ed				
Environment	Fair	0.31	0.48	65.00
Size	Good	0.96	1.20	80.00
Location	Good	0.29	0.36	80.00
Storage/Fixed Equip	Good	0.29	0.36	80.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Good	1.44	1.80	80.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Poor	0.27	0.54	50.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Project #: 8272

County: Jones

Site #: 370240001038

Project: Assessments 2016

Region: 520

Site: TRENTON ELEMENTAR

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Poor	0.93	1.85	50.00
Location	Good	0.44	0.56	80.00
Storage/Fixed Equip	Poor	0.28	0.56	50.00
Art				
Environment	Good	0.37	0.47	80.00
Size	Poor	0.58	1.17	50.00
Location	Good	0.28	0.35	80.00
Storage/Fixed Equip	Poor	0.18	0.35	50.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Good	0.68	0.85	80.00
Location	Excel	0.26	0.26	100.00
Storage/Fixed Equip	Excel	0.26	0.26	100.00
P.E.				
Environment	Unsat	0.00	1.92	0.00
Size	Unsat	0.00	4.80	0.00
Location	Unsat	0.00	1.44	0.00
Storage/Fixed Equip	Unsat	0.00	1.44	0.00
Performing Arts				
Environment	Unsat	0.00	0.60	0.00
Size	Unsat	0.00	1.51	0.00
Location	Unsat	0.00	0.45	0.00
Storage/Fixed Equip	Unsat	0.00	0.45	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Poor	1.22	2.44	50.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Fair	0.48	0.73	65.00
Restrooms (Student)	Good	0.71	0.89	80.00
Administration	Good	2.05	2.56	80.00
Counseling	Good	0.23	0.29	80.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Excel	1.27	1.27	100.00
Cafeteria	Fair	3.25	5.00	65.00
Food Service and Prep	Fair	4.03	6.20	65.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Excel	2.00	2.00	100.00
Pedestrian Traffic	Poor	0.49	0.97	50.00
Parking	Good	0.65	0.81	80.00
Play Areas	Excel	2.34	2.34	100.00
Safety and Security				
Fencing	Excel	0.75	0.75	100.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Excel	0.50	0.50	100.00

Project #: 8272

County: Jones

Site #: 370240001038

Project: Assessments 2016

Region: 520

Site: TRENTON ELEMENTAR

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		62.73	97.50	64.34

Comments

Suitability - ES

Trenton Elementary School is located in Trenton, NC, and was founded in 1958. It is the largest of four elementary schools in Jones County serving students in grades PK through 6. In addition to the main school building, there is one relocatable building that houses the PE program.

Suitability - ES->Learning Environment-->Learning Style Variety

There are no flexible use spaces to facilitated differentiated instruction.

Suitability - ES->Learning Environment-->Exterior Environment

The school does not have exterior learning spaces.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

There is insufficient storage/permanent casework in most classrooms.

Suitability - ES->Kindergarten-->Storage/Fixed Equip

The rooms do not have adequate storage.

Suitability - ES->Self-Contained Special Ed-->Environment

The class has an open floor plan that works well for the exceptional student population; however, the space is not inviting or intellectually stimulating.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip

There is not adequate permanent casework in this space for storage.

Suitability - ES->Science

This space does not exist at the school.

Suitability - ES->Music

The school has no music room. This subject is in a regular classroom and the space is shared with the art program.

Suitability - ES->Music-->Size

The school has no music room. This subject is in a regular classroom and the space is shared with the art program.

Suitability - ES->Music-->Storage/Fixed Equip

The music space does not meet the size standards.

Suitability - ES->Art

There is no art space in the school and this program shares space with music.

Suitability - ES->Art-->Size

The program is in a regular classroom with space shared with the music program.

Suitability - ES->Art-->Storage/Fixed Equip

The room does not meet the size standards for an art space.

Suitability - ES->P.E.

The school has no gym and PE is taught in a portable classroom.

Suitability - ES->P.E.-->Environment

The school has no gym and PE is taught in a portable classroom.

Suitability - ES->P.E.-->Size

The school has no gym and PE is taught in a portable classroom.

Suitability - ES->P.E.-->Location

The school has no gym and PE is taught in a portable classroom.

Project #: 8272

County: Jones

Site #: 370240001038

Project: Assessments 2016

Region: 520

Site: TRENTON ELEMENTAR

Grade Config: PK-06

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->P.E.-->Storage/Fixed Equip The school has no gym and PE is taught in a portable classroom.				
Suitability - ES->Performing Arts There is no performing arts space in the school.				
Suitability - ES->Performing Arts-->Environment The school has no performance spaces in the school.				
Suitability - ES->Performing Arts-->Size The school has no performance spaces in the school.				
Suitability - ES->Performing Arts-->Location The school has no performance spaces in the school.				
Suitability - ES->Performing Arts-->Storage/Fixed Equip The school has no performance spaces in the school.				
Suitability - ES->Media Center-->Size The media center does not meet the size standards.				
Suitability - ES->Media Center-->Storage/Fixed Equip There is not sufficient storage space to accommodate all media materials and equipment.				
Suitability - ES->Restrooms (Student) Most student restrooms are not ADA compliant.				
Suitability - ES->Clinic The clinic does not meet the size standards.				
Suitability - ES->Cafeteria The cafeteria does not meet the size standards but has all other suitability components.				
Suitability - ES->Food Service and Prep The kitchen and food prep areas have all required suitability components; however, the space is undersized.				
Suitability - ES->Outside-->Pedestrian Traffic There are no paved sidewalks at the school.				
Suitability - ES->Safety and Security-->Fencing The school is next to a DOT dump soil site, so it is important that this fence barrier is present.				

Project #: 8272

County: Jones

Site #: 370240001034

Project: Assessments 2016

Region: 520

Site: JONES MIDDLE

Grade Config: 07-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	2.70	3.37	80.00
Location	Good	0.81	1.01	80.00
Storage/Fixed Equip	Good	0.81	1.01	80.00
Computer Labs				
Environment	Fair	0.20	0.30	65.00
Size	Good	0.60	0.75	80.00
Location	Good	0.18	0.23	80.00
Storage/Fixed Equip	Fair	0.15	0.23	65.00
P.E.				
Environment	Fair	1.56	2.40	65.00
Size	Good	4.80	6.00	80.00
Location	Good	1.44	1.80	80.00
Storage/Fixed Equip	Poor	0.90	1.80	50.00
Performing Arts				
Environment	Unsat	0.00	0.42	0.00
Size	Unsat	0.00	1.05	0.00
Location	Unsat	0.00	0.31	0.00
Storage/Fixed Equip	Unsat	0.00	0.31	0.00
Media Center				
Environment	Fair	0.60	0.93	65.00
Size	Fair	1.51	2.32	65.00
Location	Good	0.56	0.70	80.00
Storage/Fixed Equip	Good	0.56	0.70	80.00
Restrooms (Student)	Fair	0.60	0.93	65.00
Administration	Good	1.68	2.10	80.00
Counseling	Good	0.34	0.42	80.00
Clinic	Good	0.27	0.34	80.00
Staff Lounge-WkRm	Good	0.72	0.91	80.00
Cafeteria	Fair	2.60	4.00	65.00
Food Service and Prep	Fair	3.72	5.72	65.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Excel	4.00	4.00	100.00
Pedestrian Traffic	Excel	0.43	0.43	100.00
Parking	Excel	0.86	0.86	100.00
Athletic Courts and Fields	Unsat	0.00	1.05	0.00
Safety and Security				
Fencing	Unsat	0.00	0.78	0.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Excel	0.50	0.50	100.00
Total For Site:		68.02	100.00	68.02

Comments

Project #: 8272

County: Jones

Site #: 370240001034

Project: Assessments 2016

Region: 520

Site: JONES MIDDLE

Grade Config: 07-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Jones Middle School is located in Trenton, NC and was built in 1950 and was formerly a high school. The school currently serves students in grades 7 and 8. In addition to spaces for core academic courses, the school provides CTE classes in agriculture and has a STEM lab.				
Suitability - MS->Learning Environment-->Learning Style Variety				
The rooms in the building do not facilitate flexible use or differentiated instruction.				
Suitability - MS->Learning Environment-->Interior Environment				
Most spaces in the building are not visually stimulating or inviting. Electrical power is not sufficient in many rooms and the overall aesthetics of the rooms are poor.				
Suitability - MS->Learning Environment-->Exterior Environment				
Several of the CTE programs use outdoor spaces to extend the learning environment.				
Suitability - MS->General Classrooms-->Environment				
Most classrooms are not visually stimulating or inviting. The aesthetics in most spaces are not inviting as rooms have peeling paint on walls, and stained and damaged ceiling tiles.				
Suitability - MS->General Classrooms-->Storage/Fixed Equip				
Most rooms have limited permanent casework and much of the storage is provided by containers or movable bookcases.				
Suitability - MS->Self-Contained Special Ed-->Environment				
The overall aesthetics of the space are less than ideal. There are worn fixtures and surfaces of the wall are peeling.				
Suitability - MS->Instructional Resource Rooms-->Storage/Fixed Equip				
There is insufficient performance casework for storage in the instructional resource rooms.				
Suitability - MS->Science-->Environment				
The science lab space does not provide an inviting or stimulating environment. Fixtures are worn and the overall aesthetics in the lab are less than ideal.				
Suitability - MS->Music-->Environment				
The air quality, acoustics, and lighting levels in the space do not meet the suitability standards for a music space.				
Suitability - MS->Music-->Size				
The music room does not meet the size standards.				
Suitability - MS->Music-->Storage/Fixed Equip				
The small overall size of the room limits the storage space in the room.				
Suitability - MS->Art-->Environment				
The art class is located in a regular classroom and that does not meet the suitability standards for this program.				
Suitability - MS->Art-->Size				
Art is in a regular classroom and does not meet the size standards for an art room.				
Suitability - MS->Art-->Storage/Fixed Equip				
Due to art being located in a regular classroom, there is insufficient storage space.				
Suitability - MS->Career Tech Ed-->Environment				
The overall aesthetics in the CTE rooms are not ideal. Most rooms have peeling paint, worn fixtures, and ceiling tiles show signs of previous water damage.				
Suitability - MS->Computer Labs-->Environment				
The overall aesthetics of the gym are less than ideal due to the advanced age of the facility.				
Suitability - MS->Computer Labs-->Storage/Fixed Equip				
Storage space in the computer labs is limited.				

Project #: 8272

County: Jones

Site #: 370240001034

Project: Assessments 2016

Region: 520

Site: JONES MIDDLE

Grade Config: 07-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS->P.E.-->Environment There is not a great deal of natural light, and the acoustics in the gym are not conducive the maintaining appropriate sound levels.				
Suitability - MS->P.E.-->Storage/Fixed Equip There is very limited storage space in the gym. Showers and restrooms have been taken for storage, and the much of the gym equipment is worn and showing signs of age.				
Suitability - MS->Performing Arts There is no performing arts space in the school.				
Suitability - MS->Performing Arts-->Environment There is no performing arts space in the school.				
Suitability - MS->Performing Arts-->Size There is no performing arts space in the school.				
Suitability - MS->Performing Arts-->Location There is no performing arts space in the school.				
Suitability - MS->Performing Arts-->Storage/Fixed Equip There is no performing arts space in the school.				
Suitability - MS->Media Center-->Environment The media center environment is not inviting or stimulating. The space does not have adequate natural lighting.				
Suitability - MS->Media Center-->Size The library space is below the size standard.				
Suitability - MS->Restrooms (Student) The students restrooms are poorly ventilated and several were in disrepair at the time of the visit. Not all spaces are ADA compliant.				
Suitability - MS->Cafeteria The space does not meet the standard.				
Suitability - MS->Food Service and Prep There is not sufficient pick-up and delivery space at the loading area of the cafeteria. The access to the door is blocked by the dumpster.				
Suitability - MS->Outside-->Athletic Courts and Fields The school has no fields. Students use the football field at the high school and adjacent fields that belong to the local community rec department.				
Suitability - MS->Safety and Security-->Fencing There is no exterior fencing at the school.				
Suitability - MS->Safety and Security-->Signage & Way Finding Other than signage indicating the location of the main office, wayfinding signage is not present throughout the school.				
Suitability - MS->Safety and Security-->Ease of Supervision Supervision of all spaces in the school is aided by the presence of security cameras.				

Suitability Report - Full

Project #: 8272

County: Jones

Site #: 370240001035

Project: Assessments 2016

Region: 520

Site: JONES SENIOR HIGH

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Poor	2.50	5.00	50.00
Interior Environment	Poor	1.00	2.00	50.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Poor	1.95	3.90	50.00
Size	Fair	6.34	9.75	65.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Poor	1.46	2.93	50.00
Self-Contained Special Ed				
Environment	Good	0.43	0.53	80.00
Size	Excel	1.33	1.33	100.00
Location	Good	0.32	0.40	80.00
Storage/Fixed Equip	Good	0.32	0.40	80.00
Instructional Resource Rooms				
Environment	Fair	0.52	0.80	65.00
Size	Good	1.60	2.00	80.00
Location	Good	0.48	0.60	80.00
Storage/Fixed Equip	Fair	0.39	0.60	65.00
Science				
Environment	Fair	0.54	0.83	65.00
Size	Good	1.66	2.07	80.00
Location	Good	0.50	0.62	80.00
Storage/Fixed Equip	Good	0.50	0.62	80.00
Music				
Environment	Poor	0.30	0.59	50.00
Size	Poor	0.74	1.48	50.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Fair	0.29	0.45	65.00
Art				
Environment	Fair	0.43	0.67	65.00
Size	Good	1.33	1.66	80.00
Location	Good	0.40	0.50	80.00
Storage/Fixed Equip	Poor	0.25	0.50	50.00
Career Tech Ed				
Environment	Fair	1.11	1.71	65.00

Project #: 8272

County: Jones

Site #: 370240001035

Project: Assessments 2016

Region: 520

Site: JONES SENIOR HIGH

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	3.42	4.27	80.00
Location	Good	1.03	1.28	80.00
Storage/Fixed Equip	Good	1.03	1.28	80.00
Computer Labs				
Environment	Poor	0.15	0.30	50.00
Size	Good	0.60	0.75	80.00
Location	Good	0.18	0.23	80.00
Storage/Fixed Equip	Good	0.18	0.23	80.00
P.E.				
Environment	Excel	2.40	2.40	100.00
Size	Excel	6.00	6.00	100.00
Location	Good	1.44	1.80	80.00
Storage/Fixed Equip	Excel	1.80	1.80	100.00
Performing Arts				
Environment	Unsat	0.00	0.32	0.00
Size	Unsat	0.00	0.80	0.00
Location	Unsat	0.00	0.24	0.00
Storage/Fixed Equip	Unsat	0.00	0.24	0.00
Media Center				
Environment	Fair	0.55	0.84	65.00
Size	Fair	1.37	2.11	65.00
Location	Good	0.51	0.63	80.00
Storage/Fixed Equip	Good	0.51	0.63	80.00
Restrooms (Student)	Fair	0.59	0.91	65.00
Administration	Good	2.09	2.61	80.00
Counseling	Good	0.61	0.76	80.00
Clinic	Poor	0.12	0.24	50.00
Staff Lounge-WkRm	Good	0.57	0.71	80.00
Cafeteria	Fair	2.60	4.00	65.00
Food Service and Prep	Fair	3.32	5.11	65.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Excel	1.00	1.00	100.00
Pedestrian Traffic	Excel	0.98	0.98	100.00
Parking	Excel	2.11	2.11	100.00
Athletic Courts and Fields	Excel	2.77	2.77	100.00
Safety and Security				
Fencing	Unsat	0.00	0.85	0.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Excel	0.50	0.50	100.00
Total For Site:		71.70	100.00	71.70

Comments

Project #: 8272

County: Jones

Site #: 370240001035

Project: Assessments 2016

Region: 520

Site: JONES SENIOR HIGH

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Jones High School is located in Trenton, NC and was built in 1951. The school serves students in grades 9-12. The high school campus has five separate buildings that house classes for core academic and a variety of CTE courses including health sciences, masonry, and auto mechanics.				
Suitability - HS->Learning Environment-->Learning Style Variety				
The layout and design of the building severely limits flexibility in the use of the learning spaces and does not facilitate differentiated instruction.				
Suitability - HS->Learning Environment-->Interior Environment				
Most systems in the school are below suitability standards. The temperature varies greatly across the campus with limited ability to regulate it effectively. Surfaces and fixtures are worn, and many areas of the school have peeling paint, sagging ceiling tiles and water stains.				
Suitability - HS->Learning Environment-->Exterior Environment				
Outdoor learning spaces were developed and utilized by CTE program and one of the special education classes.				
Suitability - HS->General Classrooms-->Environment				
The overall aesthetics in classrooms are below suitability standards. Many rooms have worn fixtures, ceiling tiles that are stained and/or sagging, and peeling paint.				
Suitability - HS->General Classrooms-->Size				
The rooms are slightly below the size standards.				
Suitability - HS->General Classrooms-->Storage/Fixed Equip				
The majority of rooms have very limited permanent casework.				
Suitability - HS->Instructional Resource Rooms-->Environment				
This space has no windows and poor air circulation.				
Suitability - HS->Instructional Resource Rooms-->Storage/Fixed Equip				
Room has limited storage space.				
Suitability - HS->Science-->Environment				
Science rooms are aged and many fixtures are worn. Some of the equipment is not functional (e.g., none of the rooms are connected to gas).				
Suitability - HS->Music-->Environment				
The music room is not an inviting or stimulating environment. There is limited natural light and acoustics are not ideal.				
Suitability - HS->Music-->Size				
The space is well below the size standards.				
Suitability - HS->Music-->Storage/Fixed Equip				
There is a wall of instrument storage in the classroom, but it takes up space and limits overall size of the room.				
Suitability - HS->Art-->Environment				
There is a kiln but it is stored in the main classroom and is not properly vented. The sinks do not have clay traps.				
Suitability - HS->Art-->Storage/Fixed Equip				
Space has been provided for storage, but the rooms do not have sufficient permanent casework appropriate for the program. Many materials are stored in boxes or portable containers.				
Suitability - HS->Career Tech Ed-->Environment				
Rooms for most CTE programs have poor aesthetics and have limited natural light.				
Suitability - HS->Computer Labs-->Environment				
Most labs are not being used for that purpose and rooms have worn and aging finishes.				

Project #: 8272

County: Jones

Site #: 370240001035

Project: Assessments 2016

Region: 520

Site: JONES SENIOR HIGH

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS->P.E.-->Environment The gym is the newest structure at the school, having been built in 2011.				
Suitability - HS->P.E.-->Location The new gym is across campus from the main building.				
Suitability - HS->Performing Arts There is no performing arts space in the school.				
Suitability - HS->Performing Arts-->Environment There is no performing arts space in the school.				
Suitability - HS->Performing Arts-->Size There is no performing arts space in the school.				
Suitability - HS->Performing Arts-->Location There is no performing arts space in the school.				
Suitability - HS->Performing Arts-->Storage/Fixed Equip There is no performing arts space in the school.				
Suitability - HS->Media Center-->Environment The environment is not inviting or visually stimulating. Furnishings are worn and showing signs of age.				
Suitability - HS->Media Center-->Size The space was slightly below the size standards.				
Suitability - HS->Restrooms (Student) Most restrooms are located on hallways that open to the outdoors, and there is not sufficient HVAC systems to maintain comfortable climates (the rooms were very cold). Most spaces do not have ADA accessible stalls.				
Suitability - HS->Clinic A space has been provided for a clinic but is not equipped properly due to the fact that the nurse is not onsite full time. medicines are kept in the main office.				
Suitability - HS->Cafeteria Cafeteria does not meet the size standard and does not have sufficient storage.				
Suitability - HS->Food Service and Prep Space does not meet the size standards.				
Suitability - HS->Safety and Security-->Fencing There is no fencing at the school.				
Suitability - HS->Safety and Security-->Signage & Way Finding Way-finding signage is minimal at the school. The main entrance of the school is not clearly indicated and other main sections of the building have no signage.				
Suitability - HS->Safety and Security-->Ease of Supervision There are clear lines of sight through most of the campus; however, there are blind spots on the campus that are not covered by security cameras.				
Suitability - HS->Safety and Security-->Controlled Entrances The school has a buzzer system at the main entrance and other access points in the school are locked during the day.				

Suitability Report - Full

Project #: 8272	County: Scotland	Site #: 370420001686
Project: Assessments 2016	Region: 830	Site: COVINGTON STREET E
Grade Config: KG-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Unsat	0.00	1.50	0.00
General Classrooms				
Environment	Fair	3.19	4.90	65.00
Size	Excel	12.25	12.25	100.00
Location	Excel	3.68	3.68	100.00
Storage/Fixed Equip	Good	2.94	3.68	80.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Excel	1.04	1.04	100.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Excel	0.31	0.31	100.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Poor	0.36	0.72	50.00
Size	Poor	0.90	1.80	50.00
Location	Poor	0.27	0.54	50.00
Storage/Fixed Equip	Poor	0.27	0.54	50.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Unsat	0.00	0.74	0.00

Project #: 8272

County: Scotland

Site #: 370420001686

Project: Assessments 2016

Region: 830

Site: COVINGTON STREET E

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Unsat	0.00	1.85	0.00
Location	Unsat	0.00	0.56	0.00
Storage/Fixed Equip	Unsat	0.00	0.56	0.00
Art				
Environment	Poor	0.23	0.47	50.00
Size	Good	0.94	1.17	80.00
Location	Poor	0.18	0.35	50.00
Storage/Fixed Equip	Fair	0.23	0.35	65.00
Computer Labs				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
P.E.				
Environment	Unsat	0.00	1.92	0.00
Size	Unsat	0.00	4.80	0.00
Location	Unsat	0.00	1.44	0.00
Storage/Fixed Equip	Unsat	0.00	1.44	0.00
Performing Arts				
Environment	Fair	0.39	0.60	65.00
Size	Poor	0.76	1.51	50.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Poor	0.23	0.45	50.00
Media Center				
Environment	Excel	0.97	0.97	100.00
Size	Fair	1.58	2.44	65.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Poor	0.37	0.73	50.00
Restrooms (Student)	Good	0.71	0.89	80.00
Administration	Good	2.05	2.56	80.00
Counseling	Excel	0.29	0.29	100.00
Clinic	Good	0.47	0.58	80.00
Staff Lounge-WkRm	Excel	1.27	1.27	100.00
Cafeteria	Fair	3.25	5.00	65.00
Food Service and Prep	Fair	4.03	6.20	65.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Excel	2.00	2.00	100.00
Pedestrian Traffic	Excel	0.97	0.97	100.00
Parking	Excel	0.81	0.81	100.00
Play Areas	Excel	2.34	2.34	100.00
Safety and Security				
Fencing	Good	0.60	0.75	80.00
Signage & Way Finding	Excel	1.00	1.00	100.00
Ease of Supervision	Excel	3.00	3.00	100.00
Controlled Entrances	Excel	0.50	0.50	100.00

Project #: 8272

County: Scotland

Site #: 370420001686

Project: Assessments 2016

Region: 830

Site: COVINGTON STREET E

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		61.99	90.90	68.20

Comments

Suitability - ES

Covington Street Elementary serves students in grades K through 5 and is located in Laurinburg, North Carolina. All grades are housed in the school building, but music, physical education, and gifted education classes are housed in portables. It is one of the oldest schools in the district and was built in 1952.

Suitability - ES->Learning Environment-->Interior Environment

Room temperatures vary greatly throughout the building. Some rooms are very warm and others are chilly.

Suitability - ES->Learning Environment-->Exterior Environment

There are no such places at the school.

Suitability - ES->General Classrooms-->Environment

The temperature varied considerably from room to room.

Suitability - ES->General Classrooms-->Size

Nearly all classes met the size standards.

Suitability - ES->General Classrooms-->Location

Space has been allocated in the main building for all academic classes. None are located in portables and all grade levels are in adjacent classrooms.

Suitability - ES->ECE

The school does not have a pre-kindergarten program.

Suitability - ES->Self-Contained Special Ed

The school does not have self-contained classes.

Suitability - ES->Instructional Resource Rooms-->Environment

The school has no spaces that meet the standard. Resource personnel fill into make do spaces, e.g., the school social worker works with students in the media specialist's office.

Suitability - ES->Instructional Resource Rooms-->Size

The majority of the spaces for instructional resource personnel do not meet the size requirement. The principal has opted for smaller spaces as opposed to moving these services into portables.

Suitability - ES->Instructional Resource Rooms-->Location

No true dedicated space for instructional resource personnel.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip

Storage space is shared with other areas.

Suitability - ES->Science

There is no dedicated science space in the school. Not required in elementary school standards.

Suitability - ES->Music-->Environment

Music is located in portable classroom.

Suitability - ES->Music-->Size

Music is located in portable classroom.

Suitability - ES->Music-->Location

Music is located in portable classroom.

Suitability - ES->Music-->Storage/Fixed Equip

Music is located in portable classroom.

Project #: 8272

County: Scotland

Site #: 370420001686

Project: Assessments 2016

Region: 830

Site: COVINGTON STREET E

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Art-->Environment Art is housed in an empty classroom and is not visually pleasing. The room does have windows, but does not have good acoustics or temperature controls.				
Suitability - ES->Art-->Location Art room is relatively isolated from the main part of the school on the kindergarten hallway.				
Suitability - ES->Art-->Storage/Fixed Equip There is little permanent casework, mainly portable cabinets.				
Suitability - ES->Computer Labs Computers are distributed throughout the school and there is no stand alone lab.				
Suitability - ES->P.E.-->Environment Music is located in portable classroom.				
Suitability - ES->P.E.-->Size Music is located in portable classroom.				
Suitability - ES->P.E.-->Location Music is located in portable classroom.				
Suitability - ES->P.E.-->Storage/Fixed Equip Music is located in portable classroom.				
Suitability - ES->Performing Arts-->Environment School has a small cafetorium with stage lights and sound equipment, but poor acoustics for a performance.				
Suitability - ES->Performing Arts-->Size Cafetorium does not meet the size standard.				
Suitability - ES->Performing Arts-->Storage/Fixed Equip There is very little storage backstage.				
Suitability - ES->Media Center-->Size Space is slightly below the size standard.				
Suitability - ES->Media Center-->Storage/Fixed Equip Storage space is being used as a resource room.				
Suitability - ES->Clinic Clinic only has space for one cot and there is no shower.				
Suitability - ES->Cafeteria Cafeteria is undersized for the school population.				
Suitability - ES->Food Service and Prep Kitchen and food prep areas are undersized.				
Suitability - ES->Outside-->Vehicular Traffic The school has four separate zones for car riders, walkers, school bus riders, and daycare/afterschool program buses.				
Suitability - ES->Safety and Security-->Fencing There is no separate playground for kindergarten.				
Suitability - ES->Safety and Security-->Controlled Entrances All visitors must be buzzed in and the school entrance comes directly into the main office.				

Suitability Report - Full

Project #: 8272	County: Scotland	Site #: 370420002544
Project: Assessments 2016	Region: 830	Site: I E JOHNSON ELEMENTAR
Grade Config: PK-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Excel	5.00	5.00	100.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Fair	7.96	12.25	65.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Good	2.94	3.68	80.00
Kindergarten				
Environment	Good	0.33	0.42	80.00
Size	Good	0.83	1.04	80.00
Location	Good	0.25	0.31	80.00
Storage/Fixed Equip	Good	0.25	0.31	80.00
ECE				
Environment	Good	0.40	0.50	80.00
Size	Fair	0.81	1.25	65.00
Location	Good	0.30	0.37	80.00
Storage/Fixed Equip	Good	0.30	0.37	80.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Good	1.44	1.80	80.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Project #: 8272

County: Scotland

Site #: 370420002544

Project: Assessments 2016

Region: 830

Site: I E JOHNSON ELEMENTAR

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	1.85	1.85	100.00
Location	Good	0.44	0.56	80.00
Storage/Fixed Equip	Good	0.44	0.56	80.00
Art				
Environment	Good	0.37	0.47	80.00
Size	Fair	0.76	1.17	65.00
Location	Good	0.28	0.35	80.00
Storage/Fixed Equip	Poor	0.18	0.35	50.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Poor	0.43	0.85	50.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Fair	1.25	1.92	65.00
Size	Good	3.84	4.80	80.00
Location	Good	1.15	1.44	80.00
Storage/Fixed Equip	Fair	0.94	1.44	65.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Excel	0.97	0.97	100.00
Size	Excel	2.44	2.44	100.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Good	0.71	0.89	80.00
Administration	Good	2.05	2.56	80.00
Counseling	Good	0.23	0.29	80.00
Clinic	Excel	0.58	0.58	100.00
Staff Lounge-WkRm	Excel	1.27	1.27	100.00
Cafeteria	Good	4.00	5.00	80.00
Food Service and Prep	Fair	4.03	6.20	65.00
Custodial and Maintenance	Fair	0.33	0.50	65.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Fair	0.53	0.81	65.00
Play Areas	Fair	1.52	2.34	65.00
Safety and Security				
Fencing	Good	0.60	0.75	80.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Good	0.40	0.50	80.00

Project #: 8272

County: Scotland

Site #: 370420002544

Project: Assessments 2016

Region: 830

Site: I E JOHNSON ELEMENTAR

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		71.24	92.08	77.37

Comments

Suitability - ES

I. E. Johnson Elementary School is a PK-5 grade facility. The school does not serve special education students and does not have any portable classrooms.

Suitability - ES->Learning Environment-->Interior Environment

Built-in storage.

Suitability - ES->General Classrooms-->Environment

4th grade, 5th grade, and 1st grade rooms all had flexible space; space flexibility more limited in 2nd and 3rd grade rooms.

Suitability - ES->General Classrooms-->Size

4th grade rooms met 84% of the standard (3 total rooms). Both 2nd grade (3 total rooms) and 3rd grade (4 total rooms) met 64% of the standard. Built-ins limited class space. 1st grade (3 total rooms) and 5th grade (3 total rooms) met/exceeded the standard.

Suitability - ES->Kindergarten-->Size

Met 84% of the standard.

Suitability - ES->ECE-->Size

Met 72% of the standard.

Suitability - ES->Art-->Size

Met 72% of the standard.

Suitability - ES->Art-->Storage/Fixed Equip

Sinks lack clay traps and no kiln (kiln ventilation equipment present). Limited display space.

Suitability - ES->Computer Labs-->Size

Meets 64% of the standard.

Suitability - ES->P.E.-->Environment

Fair lighting and limited aesthetics.

Suitability - ES->P.E.-->Storage/Fixed Equip

Bleachers and goals are old, but function. Gym lacks safety padding.

Suitability - ES->Food Service and Prep

Kitchen lacks proper HVAC system and tends to get hot; staff open the delivery door and use fans to keep cool. One lunch line available and inadequate for number of students.

Suitability - ES->Custodial and Maintenance

Lacks adequate custodial storage spaces, and some of the custodial equipment is stored in other supply areas (teacher supplies and gym equipment).

Suitability - ES->Outside-->Parking

Bus parking is limited.

Suitability - ES->Outside-->Play Areas

Playground equipment for non-PK-K grades in back of school is old and lacks variety.

Suitability - ES->Safety and Security-->Ease of Supervision

Good visibility overall except for a few blind spot areas outside between buildings.

Suitability Report - Full

Project #: 8272	County: Scotland	Site #: 370420001689
Project: Assessments 2016	Region: 830	Site: LAUREL HILL ELEMENTA
Grade Config: PK-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Good	9.80	12.25	80.00
Location	Excel	3.68	3.68	100.00
Storage/Fixed Equip	Fair	2.39	3.68	65.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Good	0.83	1.04	80.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Good	0.25	0.31	80.00
ECE				
Environment	Excel	0.50	0.50	100.00
Size	Good	1.00	1.25	80.00
Location	Excel	0.37	0.37	100.00
Storage/Fixed Equip	Good	0.30	0.37	80.00
Self-Contained Special Ed				
Environment	Excel	0.48	0.48	100.00
Size	Excel	1.20	1.20	100.00
Location	Excel	0.36	0.36	100.00
Storage/Fixed Equip	Good	0.29	0.36	80.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Good	1.44	1.80	80.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Fair	0.35	0.54	65.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Fair	0.48	0.74	65.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Fair	1.20	1.85	65.00
Location	Good	0.44	0.56	80.00
Storage/Fixed Equip	Poor	0.28	0.56	50.00
Art				
Environment	Excel	0.47	0.47	100.00
Size	Excel	1.17	1.17	100.00
Location	Excel	0.35	0.35	100.00
Storage/Fixed Equip	Excel	0.35	0.35	100.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Good	0.68	0.85	80.00
Location	Excel	0.26	0.26	100.00
Storage/Fixed Equip	Poor	0.13	0.26	50.00
P.E.				
Environment	Good	1.54	1.92	80.00
Size	Poor	2.40	4.80	50.00
Location	Poor	0.72	1.44	50.00
Storage/Fixed Equip	Good	1.15	1.44	80.00
Performing Arts				
Environment	Good	0.48	0.60	80.00
Size	Good	1.21	1.51	80.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Good	0.36	0.45	80.00
Media Center				
Environment	Excel	0.97	0.97	100.00
Size	Excel	2.44	2.44	100.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Excel	0.73	0.73	100.00
Restrooms (Student)	Excel	0.89	0.89	100.00
Administration	Excel	2.56	2.56	100.00
Counseling	Excel	0.29	0.29	100.00
Clinic	Good	0.47	0.58	80.00
Staff Lounge-WkRm	Excel	1.27	1.27	100.00
Cafeteria	Excel	5.00	5.00	100.00
Food Service and Prep	Excel	6.20	6.20	100.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Excel	0.81	0.81	100.00
Play Areas	Excel	2.34	2.34	100.00
Safety and Security				
Fencing	Poor	0.38	0.75	50.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Excel	0.50	0.50	100.00

Project #: 8272

County: Scotland

Site #: 370420001689

Project: Assessments 2016

Region: 830

Site: LAUREL HILL ELEMENTA

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		81.52	97.50	83.61

Comments

Suitability - ES

Laurel Hill Elementary is located in Laurel Hill, North Carolina and serves students in grades PK-5.. All grades are housed in the school building and there are no portable classrooms. It is one of the newest facilities in the school district and was built in 1999.

Suitability - ES->Learning Environment-->Exterior Environment

There is an outdoor learning space but it is not frequently utilized.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

The amount of permanent casework for storage was slightly below the facilities standards.

Suitability - ES->Self-Contained Special Ed

SPED Self-Contained spaces have been well designed and are bright and stimulating learning spaces.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip

Spaces have little permanent casework for storage.

Suitability - ES->Science

There are no dedicated science lab spaces in the school. (Not required in the standards).

Suitability - ES->Music-->Environment

Music classes are held in a regular classroom, not designed for that purpose. So acoustics and overall aesthetics fall short of the standards.

Suitability - ES->Music-->Size

Space is undersized based on the standards.

Suitability - ES->Music-->Storage/Fixed Equip

Room does not have adequate storage to meet the needs of the music program.

Suitability - ES->Art

The art room is in a space that is actually designed for that purpose with a kiln room, appropriate natural light and adjacent outdoor patio, and ample storage space.

Suitability - ES->Computer Labs-->Storage/Fixed Equip

Storage space is limited in the lab but ample storage is available in neighboring spaces on the same hall.

Suitability - ES->P.E.-->Size

The school has gym but it is well below the size standard for elementary PE.

Suitability - ES->P.E.-->Location

The gym is next to the cafeteria with an accordion wall separating the spaces. Sound from both spaces travels to each room.

Suitability - ES->Performing Arts

The school has the accepted stage/gym/cafeteria combo, as the stage is located in the gym, and there is an accordion wall between the cafeteria and gym that can be opened for public performances.. The stage has curtains, lighting, but no built in sound system, so a microphone has to be brought in for performances. there is adequate storage for chairs.

Suitability - ES->Media Center-->Storage/Fixed Equip

The library is at the heart of the school near the main entrance. It is visually stimulating and the layout encourages multiple learning activities to take place simultaneously.

Project #: 8272

County: Scotland

Site #: 370420001689

Project: Assessments 2016

Region: 830

Site: LAUREL HILL ELEMENTA

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Restrooms (Student)				
There were a sufficient number of group bathrooms in addition to most of the early childhood and primary classes having bathrooms in the classrooms. All facilities were clean and in good working condition and all had ADA compliant stalls.				
Suitability - ES->Clinic				
The clinic meets all the standards except for size and having a shower.				
Suitability - ES->Staff Lounge-WkRm				
Teachers have a formal lounge area that meets all facilities standards as well as designated areas in the main cafeteria.				
Suitability - ES->Outside-->Pedestrian Traffic				
There are paved walkways that are out of the path of traffic and parents often walk their children up to the school from the parking lot because of the long line of traffic at the parent pick-up area.				
Suitability - ES->Outside-->Parking				
There is clearly designated parking sufficient for the school staff and daily visitors.				
Suitability - ES->Outside-->Play Areas				
The school has multiple play zones/designated playgrounds to keep older children separated from younger ones, and the PK/K classes have their own enclosed play area.				
Suitability - ES->Safety and Security-->Fencing				
There is no fencing at the school. There is a shared campus with the adjacent middle school (Carver) and is entirely open. There is a fenced playground enclosure for the PK/K grades.				
Suitability - ES->Safety and Security-->Signage & Way Finding				
The school's signage and way finding clearly directs the public to the main entrance of the school and main office, but not as clearly to other major spaces in the building.				
Suitability - ES->Safety and Security-->Ease of Supervision				
The design of the building has created many "hiding areas" however, there is adequate coverage of the building with the installation of securing cameras internally, and at strategic locations around the exterior of the building.				

Suitability Report - Full

Project #: 8272	County: Scotland	Site #: 370420001690
Project: Assessments 2016	Region: 830	Site: NORTH LAURINBURG E
Grade Config: PK-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Poor	0.75	1.50	50.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Good	9.80	12.25	80.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Fair	2.39	3.68	65.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Excel	1.04	1.04	100.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Fair	0.20	0.31	65.00
ECE				
Environment	Good	0.40	0.50	80.00
Size	Excel	1.25	1.25	100.00
Location	Excel	0.37	0.37	100.00
Storage/Fixed Equip	Fair	0.24	0.37	65.00
Self-Contained Special Ed				
Environment	Good	0.38	0.48	80.00
Size	Good	0.96	1.20	80.00
Location	Good	0.29	0.36	80.00
Storage/Fixed Equip	Fair	0.23	0.36	65.00
Instructional Resource Rooms				
Environment	Excel	0.72	0.72	100.00
Size	Excel	1.80	1.80	100.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	Good	0.40	0.50	80.00
Size	Good	1.00	1.25	80.00
Location	Good	0.30	0.38	80.00
Storage/Fixed Equip	Poor	0.19	0.38	50.00
Music				
Environment	Fair	0.48	0.74	65.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Fair	1.20	1.85	65.00
Location	Poor	0.28	0.56	50.00
Storage/Fixed Equip	Poor	0.28	0.56	50.00
Art				
Environment	Fair	0.30	0.47	65.00
Size	Good	0.94	1.17	80.00
Location	Good	0.28	0.35	80.00
Storage/Fixed Equip	Good	0.28	0.35	80.00
Computer Labs				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
P.E.				
Environment	Poor	0.96	1.92	50.00
Size	Poor	2.40	4.80	50.00
Location	Poor	0.72	1.44	50.00
Storage/Fixed Equip	Poor	0.72	1.44	50.00
Performing Arts				
Environment	Good	0.48	0.60	80.00
Size	Good	1.21	1.51	80.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Good	0.36	0.45	80.00
Media Center				
Environment	Excel	0.97	0.97	100.00
Size	Good	1.95	2.44	80.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Excel	0.73	0.73	100.00
Restrooms (Student)	Fair	0.58	0.89	65.00
Administration	Good	2.05	2.56	80.00
Counseling	Excel	0.29	0.29	100.00
Clinic	Good	0.47	0.58	80.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Good	4.00	5.00	80.00
Food Service and Prep	Good	4.96	6.20	80.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Excel	2.00	2.00	100.00
Pedestrian Traffic	Excel	0.97	0.97	100.00
Parking	Excel	0.81	0.81	100.00
Play Areas	Excel	2.34	2.34	100.00
Safety and Security				
Fencing	Excel	0.75	0.75	100.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Excel	0.50	0.50	100.00

Project #: 8272

County: Scotland

Site #: 370420001690

Project: Assessments 2016

Region: 830

Site: NORTH LAURINBURG E

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		76.01	98.29	77.33

Comments

Suitability - ES

North Laurinburg Elementary serves students in grades PK through 5 and is located in Laurinburg, North Carolina. All grades are housed in the school building, and the school has no portable classrooms. The school provides special education programs, including autism, to a significant population of special education students. It is one of the oldest schools in the district and was built in 1958.

Suitability - ES->Learning Environment-->Exterior Environment

The school does not have these kind of spaces.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Rooms have little in the way of permanent casework.

Suitability - ES->Kindergarten-->Storage/Fixed Equip

Rooms have little in the way of permanent casework.

Suitability - ES->ECE-->Storage/Fixed Equip

Rooms have little in the way of permanent casework.

Suitability - ES->Self-Contained Special Ed-->Storage/Fixed Equip

Room has little in the way of permanent casework.

Suitability - ES->Instructional Resource Rooms-->Location

Rooms are located in a part of the building that provides shelter from noisy areas.

Suitability - ES->Science-->Storage/Fixed Equip

A classroom on 5th grade is a dedicated science space and is equipped accordingly, but permanent casework is at a minimum.

Suitability - ES->Music-->Environment

Music is located in a regular classroom which does not have the aesthetics that would be in a true music room.

Suitability - ES->Music-->Size

Music is held in a regular classroom and does not meet the size standard.

Suitability - ES->Music-->Location

The music room is poorly located in the middle of a hallway surrounded by 1st grade and academic intervention classes.

Suitability - ES->Music-->Storage/Fixed Equip

The room has little permanent casework for storage and instruments and other materials are sored in portable cabinets.

Suitability - ES->Art-->Environment

The classroom space meets the standards except it lacks a kiln and clay trap for the sink.

Suitability - ES->Computer Labs

Computers are distributed to classrooms throughout the building and there is no free standing computer lab.

Suitability - ES->P.E.-->Environment

The school has no gym and is using a regular classroom for gym.

Suitability - ES->P.E.-->Size

Classroom space does not meet the PE size requirements.

Suitability - ES->P.E.-->Location

The room is surrounded by pre-school academic classrooms.

Project #: 8272

County: Scotland

Site #: 370420001690

Project: Assessments 2016

Region: 830

Site: NORTH LAURINBURG E

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->P.E.-->Storage/Fixed Equip There is very little permanent casework storage in the room.				
Suitability - ES->Performing Arts The school has a cafetorium which is acceptable for an elementary school and though small is adequate for the size of the school.				
Suitability - ES->Media Center-->Environment The librarian has created a learning environment that is very visually stimulating and attractive. There are distinct learning zones throughout the space for multiple activities to be conducted simultaneously.				
Suitability - ES->Restrooms (Student) None of the classrooms are ADA compliant.				
Suitability - ES->Administration Administrative offices were slightly below the size standards.				
Suitability - ES->Clinic Clinic met all the standards except for the lack of shower, and is slightly below the size standard.				
Suitability - ES->Food Service and Prep The kitchen/food prep area is small, but sufficient for the student population of less than 300.				
Suitability - ES->Outside-->Pedestrian Traffic The school has paved walking surfaces around the building.				
Suitability - ES->Outside-->Play Areas The PK/K and 1st grade classes have separated, enclosed play areas.				
Suitability - ES->Safety and Security-->Fencing Most of the classrooms open to the outdoors and the school district has constructed a security wall that encloses the open walkways and allows those areas to be secured. The school also has security cameras throughout the interior building and at key exterior access points.				
Suitability - ES->Safety and Security-->Signage & Way Finding The wayfinding signage is insufficient at the school. When entering the building there are similar doors to the right and left of the entrance and for those visiting for the first time, it is not immediately apparent which is the main office. The same with most spaces throughout both school buildings.				
Suitability - ES->Safety and Security-->Ease of Supervision The school has many "hiding areas" and supervision is reliant on the availability of security cameras throughout the building.				

Suitability Report - Full

Project #: 8272

County: Scotland

Site #: 370420001694

Project: Assessments 2016

Region: 830

Site: SOUTH SCOTLAND ELE

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Excel	1.50	1.50	100.00
General Classrooms				
Environment	Fair	3.19	4.90	65.00
Size	Good	9.80	12.25	80.00
Location	Excel	3.68	3.68	100.00
Storage/Fixed Equip	Poor	1.84	3.68	50.00
Kindergarten				
Environment	Good	0.33	0.42	80.00
Size	Good	0.83	1.04	80.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Good	0.25	0.31	80.00
ECE				
Environment	Good	0.40	0.50	80.00
Size	Good	1.00	1.25	80.00
Location	Excel	0.37	0.37	100.00
Storage/Fixed Equip	Good	0.30	0.37	80.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Fair	0.47	0.72	65.00
Size	Poor	0.90	1.80	50.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Poor	0.27	0.54	50.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Poor	0.37	0.74	50.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Poor	0.93	1.85	50.00
Location	Poor	0.28	0.56	50.00
Storage/Fixed Equip	Poor	0.28	0.56	50.00
Art				
Environment	Fair	0.30	0.47	65.00
Size	Good	0.94	1.17	80.00
Location	Good	0.28	0.35	80.00
Storage/Fixed Equip	Fair	0.23	0.35	65.00
Computer Labs				
Environment	Excel	0.34	0.34	100.00
Size	Excel	0.85	0.85	100.00
Location	Excel	0.26	0.26	100.00
Storage/Fixed Equip	Excel	0.26	0.26	100.00
P.E.				
Environment	Unsat	0.00	1.92	0.00
Size	Unsat	0.00	4.80	0.00
Location	Unsat	0.00	1.44	0.00
Storage/Fixed Equip	Unsat	0.00	1.44	0.00
Performing Arts				
Environment	Fair	0.39	0.60	65.00
Size	Poor	0.76	1.51	50.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Good	0.36	0.45	80.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Fair	1.58	2.44	65.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Good	0.71	0.89	80.00
Administration	Good	2.05	2.56	80.00
Counseling	Excel	0.29	0.29	100.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Excel	1.27	1.27	100.00
Cafeteria	Poor	2.50	5.00	50.00
Food Service and Prep	Poor	3.10	6.20	50.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Excel	2.00	2.00	100.00
Pedestrian Traffic	Excel	0.97	0.97	100.00
Parking	Excel	0.81	0.81	100.00
Play Areas	Excel	2.34	2.34	100.00
Safety and Security				
Fencing	Excel	0.75	0.75	100.00
Signage & Way Finding	Excel	1.00	1.00	100.00
Ease of Supervision	Excel	3.00	3.00	100.00
Controlled Entrances	Excel	0.50	0.50	100.00

Project #: 8272

County: Scotland

Site #: 370420001694

Project: Assessments 2016

Region: 830

Site: SOUTH SCOTLAND ELE

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		64.21	95.10	67.52

Comments

Suitability - ES

South Scotland Elementary serves students in grades PK through 5 and is located in Laurinburg, North Carolina. All grades are housed in the school building and the school has no portable classrooms. There is no gymnasium or other designated PE space in the building. It is one of the oldest schools in the district and was built in 1960.

Suitability - ES->Learning Environment-->Interior Environment

Temperatures in rooms across the school vary greatly and the noise separation in one of the building wing additions is not ideal.

Suitability - ES->Learning Environment-->Exterior Environment

School has a large outdoor classroom multi-use space.

Suitability - ES->General Classrooms-->Environment

Room temperatures varied greatly (cold to hot) from room to room throughout the building. Several classrooms have no windows.

Suitability - ES->General Classrooms-->Location

Classroom assignments are such that grade levels are grouped together. No "orphan" classes isolated from the rest of the grade level.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Many classrooms do not have permanent casework. Storage consists primarily of movable storage cabinets and rolling shelves.

Suitability - ES->Self-Contained Special Ed

The school does not have any special education self-contained classes.

Suitability - ES->Instructional Resource Rooms-->Environment

Temperatures vary greatly (hot to cold) from room to room, and most spaces lack natural light (windows).

Suitability - ES->Instructional Resource Rooms-->Size

Most spaces do not meet the size standards.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip

Rooms are undersized and do not have adequate storage space.

Suitability - ES->Science

There is no designated science space in the school. Not required in the standards.

Suitability - ES->Music-->Environment

Music is in a regular classroom with no acoustic tiles or other equipment to improve the quality of acoustics in the room.

Suitability - ES->Music-->Size

The room did not meet the size guidelines for an elementary music class.

Suitability - ES->Music-->Location

The music room is located on a hall with other academic classes (5th grade). Sound carries into other classrooms and limits the activities that can be done with the room without disturbing other classes.

Suitability - ES->Music-->Storage/Fixed Equip

The room has no storage appropriate to a music program.

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Art-->Environment				
Although the art class is located in a regular classroom, the room has good natural light and there is limited noise transfer from room to room. There is little in the way of display space, and the room is mostly bare space not representative of an art room.				
Suitability - ES->Art-->Storage/Fixed Equip				
Most of the storage is not permanent casework. There are a small number of drying racks but not sufficient for the size of the school.				
Suitability - ES->P.E.-->Environment				
There is no gym/PE space in the building. This space is located in a portable.				
Suitability - ES->P.E.-->Size				
There is no gym/PE space in the building. This space is located in a portable.				
Suitability - ES->P.E.-->Location				
There is no gym/PE space in the building. This space is located in a portable.				
Suitability - ES->P.E.-->Storage/Fixed Equip				
There is no gym/PE space in the building. This space is located in a portable.				
Suitability - ES->Performing Arts-->Environment				
The school has a cafetorium with less than ideal acoustics for performances.				
Suitability - ES->Performing Arts-->Size				
The space does not meet the size standards.				
Suitability - ES->Performing Arts-->Storage/Fixed Equip				
Stage has curtain, lighting, and sound system, lacks sufficient storage and technology equipment.				
Suitability - ES->Media Center-->Size				
The media center square footage was below the facilities standard for the space.				
Suitability - ES->Restrooms (Student)				
Most classrooms have restrooms shared between two classes and there is only one boys and girls group bathroom in the school. Neither has an ADA-compliant stall. Disabled students use adult restroom.				
Suitability - ES->Clinic				
The clinic is undersized. There is room for only one cot and there is no shower.				
Suitability - ES->Cafeteria				
The cafeteria was undersized for the total student population at the school.				
Suitability - ES->Food Service and Prep				
Kitchen/food prep areas were undersized for the size of the school.				
Suitability - ES->Outside-->Vehicular Traffic				
The bus loading zone and parent drop-off/pick-up zones are on different sides of the building.				
Suitability - ES->Outside-->Play Areas				
Both the pre-kindergarten and kindergarten classes have their own separate, enclosed play areas that are used exclusively by these students.				

Suitability Report - Full

Project #: 8272

County: Scotland

Site #: 370420002111

Project: Assessments 2016

Region: 830

Site: SYCAMORE LANE ELEM

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Fair	3.19	4.90	65.00
Size	Fair	7.96	12.25	65.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Good	2.94	3.68	80.00
Kindergarten				
Environment	Poor	0.21	0.42	50.00
Size	Fair	0.68	1.04	65.00
Location	Poor	0.16	0.31	50.00
Storage/Fixed Equip	Good	0.25	0.31	80.00
ECE				
Environment	Good	0.40	0.50	80.00
Size	Fair	0.81	1.25	65.00
Location	Good	0.30	0.37	80.00
Storage/Fixed Equip	Good	0.30	0.37	80.00
Self-Contained Special Ed				
Environment	Good	0.38	0.48	80.00
Size	Good	0.96	1.20	80.00
Location	Poor	0.18	0.36	50.00
Storage/Fixed Equip	Fair	0.23	0.36	65.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Good	1.44	1.80	80.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Project #: 8272

County: Scotland

Site #: 370420002111

Project: Assessments 2016

Region: 830

Site: SYCAMORE LANE ELEM

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Fair	1.20	1.85	65.00
Location	Good	0.44	0.56	80.00
Storage/Fixed Equip	Good	0.44	0.56	80.00
Art				
Environment	Good	0.37	0.47	80.00
Size	Excel	1.17	1.17	100.00
Location	Good	0.28	0.35	80.00
Storage/Fixed Equip	Good	0.28	0.35	80.00
Computer Labs				
Environment	Fair	0.22	0.34	65.00
Size	Excel	0.85	0.85	100.00
Location	Poor	0.13	0.26	50.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Good	1.54	1.92	80.00
Size	Excel	4.80	4.80	100.00
Location	Good	1.15	1.44	80.00
Storage/Fixed Equip	Good	1.15	1.44	80.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Excel	2.44	2.44	100.00
Location	Excel	0.73	0.73	100.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Good	0.71	0.89	80.00
Administration	Good	2.05	2.56	80.00
Counseling	Good	0.23	0.29	80.00
Clinic	Excel	0.58	0.58	100.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Fair	3.25	5.00	65.00
Food Service and Prep	Fair	4.03	6.20	65.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Good	0.65	0.81	80.00
Play Areas	Poor	1.17	2.34	50.00
Safety and Security				
Fencing	Poor	0.38	0.75	50.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Good	0.40	0.50	80.00

Project #: 8272

County: Scotland

Site #: 370420002111

Project: Assessments 2016

Region: 830

Site: SYCAMORE LANE ELEM

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		70.66	94.48	74.79

Comments

Suitability - ES

Sycamore Lane Elementary School is a PK-5 grade facility. The school has one classroom to serve special education students. The school has 9 portable classrooms, but all portables are not in use and are slotted for removal.

Suitability - ES->Learning Environment-->Exterior Environment

Some gathering spaces, but limited in use/flexibility.

Suitability - ES->General Classrooms-->Environment

Some of the classrooms have eye wash stations, as these used to be middle school science rooms.

Suitability - ES->General Classrooms-->Size

All 4th grade rooms met the square footage standard. Half of the 1st grade rooms met 86% of the square footage standard; one of the five 2nd grade rooms met 77% of the standard; four of the five 3rd grade rooms met 86% of the standard; and two of the five 5th grade rooms met 84% of the standard.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Built-in storage.

Suitability - ES->Kindergarten-->Environment

This room used to be a Home Economics classroom, and a considerable space is unused and contains misc. storage and the old Home Economic appliances and cabinets/counters. Power strips used for computers. Other Kindergarten rooms do not have this constraint. All use additional built-ins/storage, but are reported to meet their needs. Some of the classrooms have eye wash stations, as these used to be middle school science rooms.

Suitability - ES->Kindergarten-->Size

Met 79% of the square footage standard.

Suitability - ES->Kindergarten-->Location

One of the classrooms is located on the other end of the school. Bathroom located down the hall for the room on the other end of the school.

Suitability - ES->ECE-->Size

Met 72% of square footage standard.

Suitability - ES->Self-Contained Special Ed-->Location

Located away from main office and next to the music room and computer lab.

Suitability - ES->Self-Contained Special Ed-->Storage/Fixed Equip

Limited fixed equipment present. Built-in storage.

Suitability - ES->Music-->Size

Met 65% of square footage standard.

Suitability - ES->Computer Labs-->Environment

Glue is leaking between the tiles and causing large black streaks across the floor.

Suitability - ES->Computer Labs-->Location

Located away from general classrooms and next to gym and music classroom.

Suitability - ES->Cafeteria

Shorter lunch times due to congestion and limited table space.

Suitability - ES->Food Service and Prep

One wall of outlets does not work (currently under work order). The dishwasher causes leaks (fall hazard) and the water does not get very hot. The freezer and cooler leak.

Project #: 8272

County: Scotland

Site #: 370420002111

Project: Assessments 2016

Region: 830

Site: SYCAMORE LANE ELEM

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability

Rating

Score

Possible
Score

Percent
Score

Suitability - ES->Outside-->Play Areas

There is no separate fenced play area for Kindergarten students. Very little variation in playground equipment and most fixtures are old.

Suitability - ES->Safety and Security-->Fencing

Most of the playground area is fenced. There is no separate fenced play area for Kindergarten students.

Suitability - ES->Safety and Security-->Signage & Way Finding

Lacks some directional and visitor parking signage. Lacks grade level signage inside the building.

Suitability - ES->Safety and Security-->Ease of Supervision

A few blind spots present in narrower hallways and connecting rooms. Camera blind spot is present in the back of the cafeteria outside. Good internal line of sight.

Suitability Report - Full

Project #: 8272	County: Scotland	Site #: 370420001695
Project: Assessments 2016	Region: 830	Site: WAGRAM ELEMENTARY
Grade Config: PK-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Good	9.80	12.25	80.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Fair	2.39	3.68	65.00
Kindergarten				
Environment	Fair	0.27	0.42	65.00
Size	Good	0.83	1.04	80.00
Location	Fair	0.20	0.31	65.00
Storage/Fixed Equip	Poor	0.16	0.31	50.00
ECE				
Environment	Good	0.40	0.50	80.00
Size	Fair	0.81	1.25	65.00
Location	Good	0.30	0.37	80.00
Storage/Fixed Equip	Excel	0.37	0.37	100.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Excel	1.80	1.80	100.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Good	0.59	0.74	80.00

Project #: 8272

County: Scotland

Site #: 370420001695

Project: Assessments 2016

Region: 830

Site: WAGRAM ELEMENTARY

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	1.85	1.85	100.00
Location	Good	0.44	0.56	80.00
Storage/Fixed Equip	Good	0.44	0.56	80.00
Art				
Environment	Good	0.37	0.47	80.00
Size	Excel	1.17	1.17	100.00
Location	Good	0.28	0.35	80.00
Storage/Fixed Equip	Fair	0.23	0.35	65.00
Computer Labs				
Environment	Fair	0.22	0.34	65.00
Size	Fair	0.55	0.85	65.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Fair	1.25	1.92	65.00
Size	Fair	3.12	4.80	65.00
Location	Good	1.15	1.44	80.00
Storage/Fixed Equip	Fair	0.94	1.44	65.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Excel	2.44	2.44	100.00
Location	Good	0.58	0.73	80.00
Storage/Fixed Equip	Fair	0.48	0.73	65.00
Restrooms (Student)	Good	0.71	0.89	80.00
Administration	Fair	1.66	2.56	65.00
Counseling	Good	0.23	0.29	80.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Good	4.00	5.00	80.00
Food Service and Prep	Fair	4.03	6.20	65.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Good	1.60	2.00	80.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Good	0.65	0.81	80.00
Play Areas	Good	1.87	2.34	80.00
Safety and Security				
Fencing	Fair	0.49	0.75	65.00
Signage & Way Finding	Excel	1.00	1.00	100.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Good	0.40	0.50	80.00

Project #: 8272

County: Scotland

Site #: 370420001695

Project: Assessments 2016

Region: 830

Site: WAGRAM ELEMENTARY

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		70.92	92.08	77.02

Comments

Suitability - ES

Wagram Elementary School is a PK-5 grade facility. The school does not serve special education students and does not have any portable classrooms.

Suitability - ES->General Classrooms-->Size

1st grade rooms fall slightly below standard (96% of standard). All other classrooms meet square footage standard.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Built-ins and rollaway carts used for storage.

Suitability - ES->Kindergarten-->Environment

One of the rooms has limited natural light.

Suitability - ES->Kindergarten-->Size

Lots of built-in storage. Met 84% of the square footage standard.

Suitability - ES->Kindergarten-->Location

Kindergarten classrooms are located on different halls (2 on one hall, and 2 on the other).

Suitability - ES->Kindergarten-->Storage/Fixed Equip

Two of the Kindergarten rooms lack an attached bathroom. Lots of built-in storage.

Suitability - ES->ECE-->Size

Met 72% of square footage standard.

Suitability - ES->Art-->Storage/Fixed Equip

Room has a sink but no clay trap. No kiln.

Suitability - ES->Computer Labs-->Environment

Limited aesthetics and no natural light.

Suitability - ES->Computer Labs-->Size

Met 72% of the square footage standard.

Suitability - ES->P.E.-->Environment

Limited natural. There is a gap present underneath the double doors, and there is a dip in the gym floor where students have tripped.

Suitability - ES->P.E.-->Size

Multipurpose room type area and limited gym space for activities.

Suitability - ES->P.E.-->Storage/Fixed Equip

Limited fixed equipment (2 basketball goals).

Suitability - ES->Media Center-->Storage/Fixed Equip

Projector for smartboard is on a mobile cart and the cord is plugged into the floor (the cord is taped to the floor and the outlet is covered by a milk crate for safety).

Suitability - ES->Administration

Guidance office is located next to Music classroom.

Suitability - ES->Clinic

No bathroom inside nurse's room but restrooms located nearby.

Suitability - ES->Food Service and Prep

No HVAC in kitchen area. Delivery area is across from main playground and does not have fencing in between.

Project #: 8272

County: Scotland

Site #: 370420001695

Project: Assessments 2016

Region: 830

Site: WAGRAM ELEMENTARY

Grade Config: PK-05

Site Type: Elementary

Site Size: 0.00

Suitability

Rating

Score

**Possible
Score**

**Percent
Score**

Suitability - ES->Safety and Security-->Fencing

Delivery area is across from main playground and does not have fencing in between.

Suitability - ES->Safety and Security-->Ease of Supervision

Few hiding areas present. Camera blind spot exists in back of school on far sides of playground.

Suitability Report - Full

Project #: 8272	County: Scotland	Site #: 370420001684
Project: Assessments 2016	Region: 830	Site: CARVER MIDDLE
Grade Config: 06-08	Site Type: Middle	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Excel	2.00	2.00	100.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Good	3.12	3.90	80.00
Size	Good	7.80	9.75	80.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Poor	1.46	2.93	50.00
Self-Contained Special Ed				
Environment	Good	0.44	0.55	80.00
Size	Excel	1.36	1.36	100.00
Location	Excel	0.41	0.41	100.00
Storage/Fixed Equip	Poor	0.20	0.41	50.00
Instructional Resource Rooms				
Environment	Excel	0.82	0.82	100.00
Size	Excel	2.05	2.05	100.00
Location	Excel	0.61	0.61	100.00
Storage/Fixed Equip	Excel	0.61	0.61	100.00
Science				
Environment	Excel	0.95	0.95	100.00
Size	Excel	2.39	2.39	100.00
Location	Excel	0.72	0.72	100.00
Storage/Fixed Equip	Excel	0.72	0.72	100.00
Music				
Environment	Excel	0.74	0.74	100.00
Size	Excel	1.84	1.84	100.00
Location	Excel	0.55	0.55	100.00
Storage/Fixed Equip	Excel	0.55	0.55	100.00
Art				
Environment	Poor	0.32	0.65	50.00
Size	Poor	0.81	1.61	50.00
Location	Poor	0.24	0.48	50.00
Storage/Fixed Equip	Poor	0.24	0.48	50.00
Career Tech Ed				
Environment	Excel	1.35	1.35	100.00

Project #: 8272

County: Scotland

Site #: 370420001684

Project: Assessments 2016

Region: 830

Site: CARVER MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	3.37	3.37	100.00
Location	Excel	1.01	1.01	100.00
Storage/Fixed Equip	Good	0.81	1.01	80.00
Computer Labs				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
P.E.				
Environment	Good	1.92	2.40	80.00
Size	Good	4.80	6.00	80.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Good	1.44	1.80	80.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Excel	0.93	0.93	100.00
Size	Excel	2.32	2.32	100.00
Location	Excel	0.70	0.70	100.00
Storage/Fixed Equip	Excel	0.70	0.70	100.00
Restrooms (Student)	Excel	0.93	0.93	100.00
Administration	Excel	2.10	2.10	100.00
Counseling	Excel	0.42	0.42	100.00
Clinic	Good	0.27	0.34	80.00
Staff Lounge-WkRm	Excel	0.91	0.91	100.00
Cafeteria	Good	3.20	4.00	80.00
Food Service and Prep	Good	4.57	5.72	80.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Excel	4.00	4.00	100.00
Pedestrian Traffic	Good	0.35	0.43	80.00
Parking	Excel	0.86	0.86	100.00
Athletic Courts and Fields	Good	0.84	1.05	80.00
Safety and Security				
Fencing	Poor	0.39	0.78	50.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Excel	0.50	0.50	100.00
Total For Site:		82.44	96.41	85.51

Comments

Project #: 8272

County: Scotland

Site #: 370420001684

Project: Assessments 2016

Region: 830

Site: CARVER MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Carver Middle School is located in Laurel Hill, North Carolina and serves students in grades 6- 8. It is one of three middle schools in Scotland County. There are no portable classrooms. It is one of the newest facilities in the school district and was built in 2000.				
Suitability - MS->Learning Environment-->Exterior Environment				
The school has space that could be converted to outdoor learning labs but are not currently used as such except for a gardening project that the SPED Self-Contained classes have developed.				
Suitability - MS->General Classrooms-->Storage/Fixed Equip				
Most rooms had no permanent casework sufficient to meet the standard.				
Suitability - MS->Self-Contained Special Ed-->Environment				
One of the rooms for this program has no windows.				
Suitability - MS->Self-Contained Special Ed-->Storage/Fixed Equip				
Storage is limited.				
Suitability - MS->Instructional Resource Rooms				
The school has ample appropriate space for housing instruction resource classes for small groups, and so that itinerant staff have suitable spaces during their time at the school.				
Suitability - MS->Science				
The science labs are designed as large open spaces that have the lab and all required equipment and furnishings on one side of the room and traditional classroom on the other.				
Suitability - MS->Art-->Environment				
The art class has been moved out of the room that was designed for art, and is housed in a regular classroom with no kiln room or clay trap in the sink.				
Suitability - MS->Art-->Size				
Art is located in a regular classroom and does not meet the space standards.				
Suitability - MS->Art-->Location				
The art room is on a hallway with regular academic classrooms and in a regular classroom, not a space designed for art..				
Suitability - MS->Art-->Storage/Fixed Equip				
The art room is in a regular classroom and does not meet the standards for storage.				
Suitability - MS->Computer Labs				
School does not have any computer labs that are not CTE classrooms. Computers are distributed in classrooms and other spaces (e.g., school library) rather than true computer labs.				
Suitability - MS->Performing Arts				
The school has no performing arts spaces. there is no auditorium and the cafeteria does not have a stage.				
Suitability - MS->Media Center				
The media center is well-situated at the front of the building and meets all standards for size, lighting, storage and condition.				
Suitability - MS->Restrooms (Student)				
There are a sufficient number of student bathrooms located throughout the campus and all are ADA compliant.				
Suitability - MS->Clinic				
Clinic has all requirement equipment and materials except for a shower, and is slightly undersized based on the standard.				
Suitability - MS->Staff Lounge-WkRm				
There are several of these spaces located throughout the building with at least one per grade level hallway.				

Project #: 8272

County: Scotland

Site #: 370420001684

Project: Assessments 2016

Region: 830

Site: CARVER MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
<p>Suitability - MS->Outside-->Vehicular Traffic There is complete separation of the bus loading and parent pick-up/drop-off zones; and both are "off street".</p>				
<p>Suitability - MS->Outside-->Pedestrian Traffic Students are not permitted to walk to school and are dropped off in the front of the building. There are sidewalks around the main entrance to the school to the street for any pedestrians who come to the school.</p>				
<p>Suitability - MS->Outside-->Parking The school has well-designated and sufficient parking for all staff members and a designated number of visitors spots.</p>				
<p>Suitability - MS->Outside-->Athletic Courts and Fields The school has a gym that is slightly below the size standard and outdoor playing fields for football, baseball, softball, and a basketball court.</p>				
<p>Suitability - MS->Safety and Security-->Fencing There is little fencing around the school property and persons can walk onto the campus unimpeded.</p>				
<p>Suitability - MS->Safety and Security-->Signage & Way Finding Way finding signage at the entrance to the school and once inside on the main hallway signage directing visitors to the main office is also highly visible. Artistic murals that include the grade levels located on the hallways are also prominent; however, signs adjacent to classroom doors have the room number only (no teacher name/subject).</p>				
<p>Suitability - MS->Safety and Security-->Ease of Supervision The architectural design of the building has produced a myriad of "hiding areas" however, the interior of the building can be monitored through security cameras, which are also mounted at main entrances and strategic locations around the exterior of the building.</p>				
<p>Suitability - MS->Safety and Security-->Controlled Entrances All exterior doors are locked throughout the day and the main entrance must be accessed through a buzzer system. The school can be locked off during public events held in the gym so that visitors cannot access the rest of the building.</p>				

Suitability Report - Full

Project #: 8272	County: Scotland	Site #: 370420002546
Project: Assessments 2016	Region: 830	Site: SPRING HILL MIDDLE
Grade Config: 06-08	Site Type: Middle	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Good	3.12	3.90	80.00
Size	Good	7.80	9.75	80.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Fair	1.90	2.93	65.00
Self-Contained Special Ed				
Environment	Fair	0.35	0.55	65.00
Size	Good	1.09	1.36	80.00
Location	Poor	0.20	0.41	50.00
Storage/Fixed Equip	Poor	0.20	0.41	50.00
Instructional Resource Rooms				
Environment	Fair	0.53	0.82	65.00
Size	Good	1.64	2.05	80.00
Location	Excel	0.61	0.61	100.00
Storage/Fixed Equip	Good	0.49	0.61	80.00
Science				
Environment	Good	0.76	0.95	80.00
Size	Good	1.91	2.39	80.00
Location	Excel	0.72	0.72	100.00
Storage/Fixed Equip	Fair	0.47	0.72	65.00
Music				
Environment	Good	0.59	0.74	80.00
Size	Excel	1.84	1.84	100.00
Location	Good	0.44	0.55	80.00
Storage/Fixed Equip	Good	0.44	0.55	80.00
Art				
Environment	Good	0.52	0.65	80.00
Size	Excel	1.61	1.61	100.00
Location	Excel	0.48	0.48	100.00
Storage/Fixed Equip	Good	0.39	0.48	80.00
Career Tech Ed				
Environment	(N/A)	0.00	0.00	0.00

Project #: 8272

County: Scotland

Site #: 370420002546

Project: Assessments 2016

Region: 830

Site: SPRING HILL MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Computer Labs				
Environment	Fair	0.20	0.30	65.00
Size	Good	0.60	0.75	80.00
Location	Fair	0.15	0.23	65.00
Storage/Fixed Equip	Excel	0.23	0.23	100.00
P.E.				
Environment	Fair	1.56	2.40	65.00
Size	Good	4.80	6.00	80.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Fair	1.17	1.80	65.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.74	0.93	80.00
Size	Good	1.86	2.32	80.00
Location	Excel	0.70	0.70	100.00
Storage/Fixed Equip	Good	0.56	0.70	80.00
Restrooms (Student)	Good	0.74	0.93	80.00
Administration	Good	1.68	2.10	80.00
Counseling	Good	0.34	0.42	80.00
Clinic	Excel	0.34	0.34	100.00
Staff Lounge-WkRm	Good	0.72	0.91	80.00
Cafeteria	Good	3.20	4.00	80.00
Food Service and Prep	Good	4.57	5.72	80.00
Custodial and Maintenance	Fair	0.33	0.50	65.00
Outside				
Vehicular Traffic	Excel	4.00	4.00	100.00
Pedestrian Traffic	Good	0.35	0.43	80.00
Parking	Good	0.69	0.86	80.00
Athletic Courts and Fields	Good	0.84	1.05	80.00
Safety and Security				
Fencing	Good	0.62	0.78	80.00
Signage & Way Finding	Fair	0.65	1.00	65.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Good	0.40	0.50	80.00
Total For Site:		71.96	91.16	78.94

Comments

Project #: 8272

County: Scotland

Site #: 370420002546

Project: Assessments 2016

Region: 830

Site: SPRING HILL MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS Spring Hill Middle School is a 6-8 grade facility. The school has one classroom to serve special education students. The school does not have any portable classrooms.				
Suitability - MS->Learning Environment-->Learning Style Variety Limited configurations and flexibility in half of the rooms. Limited aesthetics.				
Suitability - MS->Learning Environment-->Interior Environment Water damage to ceiling tiles present throughout; was reported that roof maintenance was performed on leaks and leaks are no longer present (aesthetics issue remains). Limited aesthetics and lack of flexibility in some rooms. No natural light in some of the classrooms. Temperature fluctuates.				
Suitability - MS->General Classrooms-->Size Majority of rooms met or exceeded the standard for square footage. The Spanish/FLA room met 77% of the standard.				
Suitability - MS->General Classrooms-->Storage/Fixed Equip Built-in storage and lacking storage in some rooms.				
Suitability - MS->Self-Contained Special Ed-->Environment Rooms used to be a Home Economics classroom, and has cabinets, counters, stoves, etc. The room tends to be cold; students and staff often wear jackets in the classroom.				
Suitability - MS->Self-Contained Special Ed-->Location Located next to Music/Band room and away from administration/clinic. Room is isolated from all other general classrooms.				
Suitability - MS->Self-Contained Special Ed-->Storage/Fixed Equip No attached restroom or SPED fixed equipment. The room used to be a Home Economic rooms, so there are sinks and a refrigerator present (as well as unused stoves, counters, and cabinets).				
Suitability - MS->Instructional Resource Rooms-->Environment Most of the resource rooms were located in spaces without windows/natural light. Rooms also tended to be warm/humid and have limited aesthetics.				
Suitability - MS->Science-->Size 5 of 6 science rooms met 90% of the square footage standard. One science room met 79% of the square footage standard.				
Suitability - MS->Science-->Storage/Fixed Equip Each science room had sinks and an eye wash station. Limited prep tables and other science-related fixed equipment.				
Suitability - MS->Computer Labs-->Environment Limited aesthetics. Labs tend to be warm/hot and humid.				
Suitability - MS->Computer Labs-->Location Computer labs are located away from general classrooms and on the same hall as Art, Vocal, and Music/Band rooms.				
Suitability - MS->P.E.-->Environment Floor outlets in gym break often and they avoid using them. HVAC System does not work properly in gym and tends to go out; also causes condensation on the ceiling which causes drops of water to fall (fall hazard and electrical hazard given there are floor outlets).				
Suitability - MS->P.E.-->Storage/Fixed Equip Has a roll-in bleacher addition. Floor outlets in gym break often and they avoid using them.				
Suitability - MS->Food Service and Prep There is a reoccurring water leak outside in the delivery area that has eroded the pavement.				

Project #: 8272

County: Scotland

Site #: 370420002546

Project: Assessments 2016

Region: 830

Site: SPRING HILL MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability

Rating

Score

**Possible
Score**

**Percent
Score**

Suitability - MS->Custodial and Maintenance

Some custodial supplies are kept outside in the kitchen delivery area.

Suitability - MS->Safety and Security-->Signage & Way Finding

Overall, exterior signage is good. Interior signage is lacking in a few areas. Sign for records room and supply room in administration area are incorrect.

Suitability - MS->Safety and Security-->Ease of Supervision

A few blind spots present inside. Several camera blind spots outside the building.

Suitability Report - Full

Project #: 8272	County: Scotland	Site #: 370420003231
Project: Assessments 2016	Region: 830	Site: SCOTLAND HIGH SCHO
Grade Config: 09-12	Site Type: High	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Excel	1.50	1.50	100.00
General Classrooms				
Environment	Good	3.12	3.90	80.00
Size	Good	7.80	9.75	80.00
Location	Excel	2.93	2.93	100.00
Storage/Fixed Equip	Fair	1.90	2.93	65.00
Self-Contained Special Ed				
Environment	Good	0.43	0.53	80.00
Size	Good	1.07	1.33	80.00
Location	Good	0.32	0.40	80.00
Storage/Fixed Equip	Fair	0.26	0.40	65.00
Instructional Resource Rooms				
Environment	Excel	0.80	0.80	100.00
Size	Excel	2.00	2.00	100.00
Location	Excel	0.60	0.60	100.00
Storage/Fixed Equip	Excel	0.60	0.60	100.00
Science				
Environment	Good	0.66	0.83	80.00
Size	Excel	2.07	2.07	100.00
Location	Excel	0.62	0.62	100.00
Storage/Fixed Equip	Excel	0.62	0.62	100.00
Music				
Environment	Excel	0.59	0.59	100.00
Size	Good	1.19	1.48	80.00
Location	Excel	0.45	0.45	100.00
Storage/Fixed Equip	Excel	0.45	0.45	100.00
Art				
Environment	Excel	0.67	0.67	100.00
Size	Excel	1.66	1.66	100.00
Location	Excel	0.50	0.50	100.00
Storage/Fixed Equip	Excel	0.50	0.50	100.00
Career Tech Ed				
Environment	Excel	1.71	1.71	100.00

Project #: 8272

County: Scotland

Site #: 370420003231

Project: Assessments 2016

Region: 830

Site: SCOTLAND HIGH SCHO

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	4.27	4.27	100.00
Location	Excel	1.28	1.28	100.00
Storage/Fixed Equip	Excel	1.28	1.28	100.00
Computer Labs				
Environment	Excel	0.30	0.30	100.00
Size	Excel	0.75	0.75	100.00
Location	Excel	0.23	0.23	100.00
Storage/Fixed Equip	Fair	0.15	0.23	65.00
P.E.				
Environment	Excel	2.40	2.40	100.00
Size	Excel	6.00	6.00	100.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Excel	1.80	1.80	100.00
Performing Arts				
Environment	Good	0.26	0.32	80.00
Size	Excel	0.80	0.80	100.00
Location	Excel	0.24	0.24	100.00
Storage/Fixed Equip	Excel	0.24	0.24	100.00
Media Center				
Environment	Excel	0.84	0.84	100.00
Size	Excel	2.11	2.11	100.00
Location	Excel	0.63	0.63	100.00
Storage/Fixed Equip	Excel	0.63	0.63	100.00
Restrooms (Student)	Excel	0.91	0.91	100.00
Administration	Excel	2.61	2.61	100.00
Counseling	Excel	0.76	0.76	100.00
Clinic	Good	0.19	0.24	80.00
Staff Lounge-WkRm	Excel	0.71	0.71	100.00
Cafeteria	Excel	4.00	4.00	100.00
Food Service and Prep	Excel	5.11	5.11	100.00
Custodial and Maintenance	Excel	0.50	0.50	100.00
Outside				
Vehicular Traffic	Excel	1.00	1.00	100.00
Pedestrian Traffic	Excel	0.98	0.98	100.00
Parking	Excel	2.11	2.11	100.00
Athletic Courts and Fields	Excel	2.77	2.77	100.00
Safety and Security				
Fencing	Excel	0.85	0.85	100.00
Signage & Way Finding	Excel	1.00	1.00	100.00
Ease of Supervision	Excel	3.00	3.00	100.00
Controlled Entrances	Excel	0.50	0.50	100.00
Total For Site:		93.60	100.00	93.60

Comments

Project #: 8272

County: Scotland

Site #: 370420003231

Project: Assessments 2016

Region: 830

Site: SCOTLAND HIGH SCHO

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Scotland High School serves students in grades 9-12 and is located in Laurinburg, North Carolina. It is one of two comprehensive high schools in Scotland County. The school has an extensive CTE program with a large variety of course offerings that include carpentry, culinary arts, electronics, and welding. It is one of the older schools in the district and was built in 1967.				
Suitability - HS->General Classrooms-->Location				
The school has planned classroom arrangements to minimize student movement across the campus, especially the 9th graders.				
Suitability - HS->General Classrooms-->Storage/Fixed Equip				
Most classrooms do not have permanent storage space; however, there are numerous storage spaces in rooms on each floor throughout the school buildings.				
Suitability - HS->Self-Contained Special Ed-->Storage/Fixed Equip				
There is limited permanent storage space in the classroom.				
Suitability - HS->Science-->Location				
Science labs are clustered in a second-floor wing.				
Suitability - HS->Music-->Size				
Chorus room is slightly below the size standard.				
Suitability - HS->Music-->Location				
The band and chorus rooms are located in spaces that are removed from academic classes.				
Suitability - HS->Art				
The visual arts rooms are located in a suite of rooms that are spacious and have adequate natural lighting. The space includes a separated kiln room, and space for drying racks.				
Suitability - HS->Career Tech Ed-->Environment				
The school has CTE classes in both the main building and in a separate building dedicated to these courses. In addition, there are external learning spaces, e.g., a greenhouse, exterior car detailing bays, and laundry that serves as a vocational training space for both general and special education students.				
Suitability - HS->Computer Labs-->Location				
Labs are distributed across the campus.				
Suitability - HS->Computer Labs-->Storage/Fixed Equip				
There is limited permanent casework in the computer labs.				
Suitability - HS->P.E.				
The school has a main gym that was an addition to the original construction. The old gym is well-maintained and used for in-coming freshmen to reduce student movement across the campus.				
Suitability - HS->Media Center-->Location				
The school's library is well-situated in the center of the main building.				
Suitability - HS->Restrooms (Student)				
There are a sufficient number of male and female bathrooms throughout the campus, with ADA compliant facilities.				
Suitability - HS->Administration				
The main administrative suite is located at the main entrance to the school, with satellite offices for assistant principals in other locations throughout the building.				
Suitability - HS->Counseling				
The guidance suite has ample size for offices and conference rooms. There is a separate space also dedicated for college and career counseling.				

Project #: 8272

County: Scotland

Site #: 370420003231

Project: Assessments 2016

Region: 830

Site: SCOTLAND HIGH SCHO

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
<p>Suitability - HS->Clinic Clinic space is slightly undersized.</p>				
<p>Suitability - HS->Staff Lounge-WkRm Staff lounges are in multiple locations throughout the campus.</p>				
<p>Suitability - HS->Cafeteria The cafeteria has ample space for the size of the student population, with seating available both in the building and in an adjacent outdoor patio.</p>				
<p>Suitability - HS->Custodial and Maintenance The school has a dozen storage closets distributed on both floors of the main building and throughout the outer buildings on campus.</p>				
<p>Suitability - HS->Outside-->Vehicular Traffic The school has complete separation between the bus loading and car rider zones.</p>				
<p>Suitability - HS->Safety and Security-->Fencing The entire campus is well-secured with locked gates and fences.</p>				
<p>Suitability - HS->Safety and Security-->Ease of Supervision The school recently had an upgrade to the security system, with full color cameras throughout both the interior and exterior of the school.</p>				
<p>Suitability - HS->Safety and Security-->Controlled Entrances In addition to secured fences and gates, the school has security personnel that monitor movement throughout the building during the day.</p>				

Suitability Report - Full

Project #: 8272	County: Scotland	Site #: 370420001687
Project: Assessments 2016	Region: 830	Site: SHAW ACADEMY
Grade Config: 06-12	Site Type: High	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Fair	2.54	3.90	65.00
Size	Fair	6.34	9.75	65.00
Location	Fair	1.90	2.93	65.00
Storage/Fixed Equip	Fair	1.90	2.93	65.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Fair	0.52	0.80	65.00
Size	Good	1.60	2.00	80.00
Location	Good	0.48	0.60	80.00
Storage/Fixed Equip	Good	0.48	0.60	80.00
Science				
Environment	Fair	0.54	0.83	65.00
Size	Fair	1.35	2.07	65.00
Location	Good	0.50	0.62	80.00
Storage/Fixed Equip	Poor	0.31	0.62	50.00
Music				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Art				
Environment	Fair	0.43	0.67	65.00
Size	Poor	0.83	1.66	50.00
Location	Good	0.40	0.50	80.00
Storage/Fixed Equip	Poor	0.25	0.50	50.00
Career Tech Ed				
Environment	(N/A)	0.00	0.00	0.00

Project #: 8272

County: Scotland

Site #: 370420001687

Project: Assessments 2016

Region: 830

Site: SHAW ACADEMY

Grade Config: 06-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Computer Labs				
Environment	Fair	0.20	0.30	65.00
Size	Poor	0.38	0.75	50.00
Location	Good	0.18	0.23	80.00
Storage/Fixed Equip	Fair	0.15	0.23	65.00
P.E.				
Environment	Fair	1.56	2.40	65.00
Size	Good	4.80	6.00	80.00
Location	Good	1.44	1.80	80.00
Storage/Fixed Equip	Fair	1.17	1.80	65.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Poor	0.42	0.84	50.00
Size	Fair	1.37	2.11	65.00
Location	Fair	0.41	0.63	65.00
Storage/Fixed Equip	Poor	0.32	0.63	50.00
Restrooms (Student)	Good	0.73	0.91	80.00
Administration	Good	2.09	2.61	80.00
Counseling	Fair	0.49	0.76	65.00
Clinic	Good	0.19	0.24	80.00
Staff Lounge-WkRm	Good	0.57	0.71	80.00
Cafeteria	Fair	2.60	4.00	65.00
Food Service and Prep	Poor	2.55	5.11	50.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Good	0.80	1.00	80.00
Pedestrian Traffic	Good	0.78	0.98	80.00
Parking	Fair	1.37	2.11	65.00
Athletic Courts and Fields	Fair	1.80	2.77	65.00
Safety and Security				
Fencing	Poor	0.42	0.85	50.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Fair	0.33	0.50	65.00
Total For Site:		55.84	84.22	66.31

Comments

Project #: 8272

County: Scotland

Site #: 370420001687

Project: Assessments 2016

Region: 830

Site: SHAW ACADEMY

Grade Config: 06-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS Shaw Academy is a 7-12 grade facility built in the early 1950s. The school does not serve special education students. The school does not have any portable classrooms. The facility has many rooms that are unused. The school was originally built as an elementary school.				
Suitability - HS->Learning Environment-->Learning Style Variety Flexible space available, but largely unused. Limited equipment/opportunity for different configurations/groups/stations.				
Suitability - HS->Learning Environment-->Interior Environment Space available for configurations. Limited natural light and aesthetics. Temperature varies room to room. HVAC system can be noisy. Old piping exposed in classrooms and hallway. Occasional problem with snakes in the walls of the building.				
Suitability - HS->Learning Environment-->Exterior Environment Limited areas except for athletic fields.				
Suitability - HS->General Classrooms-->Environment Limited aesthetics and lighting levels.				
Suitability - HS->General Classrooms-->Size Two of the rooms used for middle school classes fell below the square footage standard (65% and 70% of the square footage standard).				
Suitability - HS->General Classrooms-->Location Some rooms are used for various grades and subjects. The A hall is separate from the main building and is rarely used; one room of the six available is used daily. The rooms used for middle school subjects and high school subjects are indiscernible.				
Suitability - HS->General Classrooms-->Storage/Fixed Equip Built-in storage in most rooms.				
Suitability - HS->Instructional Resource Rooms-->Environment Limited aesthetics and lighting levels.				
Suitability - HS->Instructional Resource Rooms-->Storage/Fixed Equip Built-in storage.				
Suitability - HS->Science-->Environment Limited aesthetics and lighting levels.				
Suitability - HS->Science-->Size Met 70% of the square footage standard.				
Suitability - HS->Science-->Storage/Fixed Equip 1 of 2 science rooms have a sink present. No other fixed equipment present. No safety equipment present. Built-in storage. Lacking enough electrical outlets.				
Suitability - HS->Art-->Environment Limited flexible space.				
Suitability - HS->Art-->Size Met 50% of the square footage standard.				
Suitability - HS->Art-->Storage/Fixed Equip Built-in storage and lacking storage. No sink/kiln.				
Suitability - HS->Computer Labs-->Environment Limited aesthetics. Lack sufficient outlets; using power strips to connect. Room can be warm and humid. Computers are located near heating vents.				

Project #: 8272

County: Scotland

Site #: 370420001687

Project: Assessments 2016

Region: 830

Site: SHAW ACADEMY

Grade Config: 06-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS->Computer Labs-->Size Met 53% of the square footage standard.				
Suitability - HS->Computer Labs-->Storage/Fixed Equip Limited technology equipment outside of desktop computers. Built-in storage.				
Suitability - HS->P.E.-->Environment Limited aesthetics. Broken/removed goals.				
Suitability - HS->P.E.-->Storage/Fixed Equip Older and limited fixed equipment. Gym floor is warped and coming apart in places.				
Suitability - HS->Media Center-->Environment Limited/poor aesthetics. Plenty of space, but most unused. Some natural light.				
Suitability - HS->Media Center-->Size Per middle school standard, the space met 85% of the square footage standard. Per high school standard, the space met 77% of the square footage standard.				
Suitability - HS->Media Center-->Location Media center is located in an independent building accessed via an outdoor covered walkway.				
Suitability - HS->Media Center-->Storage/Fixed Equip Very few bookcases with books. Very little technology equipment. Plenty of space, but mostly unused. Unused tables are lined near one of the bookcases.				
Suitability - HS->Restrooms (Student) Water fountains are low for the age group instructed. The school was originally built as an elementary school.				
Suitability - HS->Counseling Located away from main office. Limited secure file space.				
Suitability - HS->Cafeteria Cafeteria is located in an independent building accessed via outdoor covered walkway.				
Suitability - HS->Food Service and Prep Meals are only served, not prepared or cooked in the kitchen. Some breakfast food is stored and served. Lunches are prepared, cooked, and delivered from the Middle School. One cooler and freezer are in use; others are not. Dishwasher present, but not used (use disposable plates, etc. only). No stoves present. No prep or cooking fixed equipment. Delivery area is across from the gym and is in front of entrance to athletic fields. (Van delivery only - no trucks.) Kitchen has adequate counter space and storage for needs.				
Suitability - HS->Outside-->Parking Staff parking in dirt/lawn area created into another parking lot (unpaved).				
Suitability - HS->Outside-->Athletic Courts and Fields No chain-link fencing around area (open to woods). Insufficient outdoor seating. Old fixed equipment.				
Suitability - HS->Safety and Security-->Fencing Some wooden fencing in the front. No chain-link fencing on the property.				
Suitability - HS->Safety and Security-->Signage & Way Finding Internal signage lacking or incorrect. External signage adequate except for detailing independent building usage.				
Suitability - HS->Safety and Security-->Ease of Supervision Good interior camera use and sight lines. Outdoor cameras limited and there are a few blind spots around the independent buildings.				
Suitability - HS->Safety and Security-->Controlled Entrances Main office entrance is controlled. Entrances to separate buildings are not as well-controlled (Mostly unused classroom section A, Cafeteria, Media Center, and Gym).				

Suitability Report - Full

Project #: 8272

County: Yancey

Site #: 370507002025

Project: Assessments 2016

Region: 995

Site: BURNSVILLE ELEMENTA

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Excel	5.00	5.00	100.00
Interior Environment	Good	1.60	2.00	80.00
Exterior Environment	Excel	1.50	1.50	100.00
General Classrooms				
Environment	Good	3.92	4.90	80.00
Size	Excel	12.25	12.25	100.00
Location	Fair	2.39	3.68	65.00
Storage/Fixed Equip	Fair	2.39	3.68	65.00
Kindergarten				
Environment	Excel	0.42	0.42	100.00
Size	Good	0.83	1.04	80.00
Location	Good	0.25	0.31	80.00
Storage/Fixed Equip	Fair	0.20	0.31	65.00
ECE				
Environment	Good	0.40	0.50	80.00
Size	Excel	1.25	1.25	100.00
Location	Excel	0.37	0.37	100.00
Storage/Fixed Equip	Good	0.30	0.37	80.00
Self-Contained Special Ed				
Environment	Fair	0.31	0.48	65.00
Size	Good	0.96	1.20	80.00
Location	Good	0.29	0.36	80.00
Storage/Fixed Equip	Good	0.29	0.36	80.00
Instructional Resource Rooms				
Environment	Good	0.58	0.72	80.00
Size	Excel	1.80	1.80	100.00
Location	Excel	0.54	0.54	100.00
Storage/Fixed Equip	Good	0.43	0.54	80.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Poor	0.37	0.74	50.00

Project #: 8272

County: Yancey

Site #: 370507002025

Project: Assessments 2016

Region: 995

Site: BURNSVILLE ELEMENTA

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Excel	1.85	1.85	100.00
Location	Poor	0.28	0.56	50.00
Storage/Fixed Equip	Unsat	0.00	0.56	0.00
Art				
Environment	Poor	0.23	0.47	50.00
Size	Fair	0.76	1.17	65.00
Location	Fair	0.23	0.35	65.00
Storage/Fixed Equip	Poor	0.18	0.35	50.00
Computer Labs				
Environment	Good	0.27	0.34	80.00
Size	Excel	0.85	0.85	100.00
Location	Excel	0.26	0.26	100.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Fair	1.25	1.92	65.00
Size	Good	3.84	4.80	80.00
Location	Fair	0.94	1.44	65.00
Storage/Fixed Equip	Fair	0.94	1.44	65.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Excel	2.44	2.44	100.00
Location	Good	0.58	0.73	80.00
Storage/Fixed Equip	Good	0.58	0.73	80.00
Restrooms (Student)	Fair	0.58	0.89	65.00
Administration	Good	2.05	2.56	80.00
Counseling	Good	0.23	0.29	80.00
Clinic	Good	0.47	0.58	80.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Good	4.00	5.00	80.00
Food Service and Prep	Fair	4.03	6.20	65.00
Custodial and Maintenance	Fair	0.33	0.50	65.00
Outside				
Vehicular Traffic	Fair	1.30	2.00	65.00
Pedestrian Traffic	Good	0.78	0.97	80.00
Parking	Fair	0.53	0.81	65.00
Play Areas	Excel	2.34	2.34	100.00
Safety and Security				
Fencing	Excel	0.75	0.75	100.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Good	0.40	0.50	80.00

Project #: 8272

County: Yancey

Site #: 370507002025

Project: Assessments 2016

Region: 995

Site: BURNSVILLE ELEMENTA

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		76.65	94.48	81.13

Comments

Suitability - ES

Burnsville Elementary School is a PK-5 grade facility built in 1993. The school has one classroom to serve special education students. The school does not have any portable classrooms. Large classrooms allow for flexible configurations and the school has inviting spaces.

Suitability - ES->Learning Environment-->Interior Environment

There are heating and cooling issues throughout the building. There are also several areas where there are reoccurring water leaks (in self-contained room, room #213, room #403, and the kitchen).

Suitability - ES->General Classrooms-->Size

Met 90% of the square footage standard.

Suitability - ES->General Classrooms-->Location

One 2nd grade classroom is located at the far end of the school next to the cafeteria, away from the other general classrooms. Similarly, there are two classrooms, another 2nd grade and a Kindergarten class, that are located across from the office and away from the other general classrooms.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

The 4th and 5th grade classrooms lack enough storage space (bookbags are kept in a corner in the hallway).

Suitability - ES->Kindergarten-->Size

Overall, the 3 Kindergarten classrooms met 86% of the square footage standard. One room exceeded the standard, another room met 84% of the standard, and the final room met 75% of the standard.

Suitability - ES->Kindergarten-->Storage/Fixed Equip

Two of the three Kindergarten classrooms do not have a restroom inside the classroom. The one room that does have an attached restroom currently uses the restroom as a storage space (not used as restroom).

Suitability - ES->ECE-->Size

Met 91% of the square footage standard.

Suitability - ES->Self-Contained Special Ed-->Environment

There is a large water leak in the room that has stained the ceiling and the floor. The ceiling leak is leaking into the light fixture.

Suitability - ES->Self-Contained Special Ed-->Storage/Fixed Equip

Students have access to therapy room with a variety of equipment located down the hall.

Suitability - ES->Instructional Resource Rooms-->Location

Rooms are located throughout the school.

Suitability - ES->Music

The same room is used for Music and Art.

Suitability - ES->Music-->Environment

Poor aesthetics and not conducive to music space.

Suitability - ES->Music-->Size

Met 90% of the square footage standard for a music room.

Suitability - ES->Music-->Location

The room is located next to general classrooms and is across from the main office.

Suitability - ES->Music-->Storage/Fixed Equip

Storage space is used for art supplies; music equipment is stored in a neighboring Kindergarten class closet.

Project #: 8272

County: Yancey

Site #: 370507002025

Project: Assessments 2016

Region: 995

Site: BURNSVILLE ELEMENTA

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Art The same room is used for Music and Art.				
Suitability - ES->Art-->Environment Poor aesthetics and not conducive to art space.				
Suitability - ES->Art-->Size Met 77% of the square footage standard for an Art space.				
Suitability - ES->Art-->Location No direct access to outside space; nearest exit leads to visitor parking lot.				
Suitability - ES->Art-->Storage/Fixed Equip The space has some built-ins and mobile storage. There is no sink or art equipment present.				
Suitability - ES->Computer Labs-->Environment The lab tends to be warm.				
Suitability - ES->Computer Labs-->Size Met 90% of the square footage standard.				
Suitability - ES->P.E.-->Environment Gym is dimly lit and the floor is aging with a few damaged spots in the floor where the wood is chipping/buckling.				
Suitability - ES->P.E.-->Size Exceeded the square footage standard, however, the gym has only one side with bleachers and exceeds capacity during events. Visitors tend to be on the floor or leaning by the walls/doors.				
Suitability - ES->P.E.-->Location To access the gym, students have to enter by walking through the cafeteria.				
Suitability - ES->P.E.-->Storage/Fixed Equip Some custodial equipment is stored in the gym storage areas, and all gym equipment is currently kept in the coach's office. The gym has backboards, padding, and water fountains. The gym also has a rock climbing wall area.				
Suitability - ES->Media Center-->Environment Inviting media center space with a book nook, however, the carpet is old, tearing, and rippling in areas and could be a trip hazard. The media center tends to be very warm.				
Suitability - ES->Media Center-->Storage/Fixed Equip Reported to need floor outlets for the projector and events to connect equipment.				
Suitability - ES->Restrooms (Student) Boys' restrooms are missing urinal privacy dividers. Some of the restrooms lack hot water.				
Suitability - ES->Administration Records room space is nearing capacity.				
Suitability - ES->Clinic Clinic met all criteria except for the shower area. The clinic has a shower, but the space is currently being used as storage for the locked medicine cabinet.				
Suitability - ES->Cafeteria Cafeteria is nearing capacity. One air unit in the cafeteria is only blowing out cold air.				
Suitability - ES->Food Service and Prep There are several large appliances that are not in use or broken that need to be removed. There is a water leak above the serving line.				
Suitability - ES->Custodial and Maintenance Some custodial equipment is stored in the gym storage areas and in outside sheds.				

Project #: 8272

County: Yancey

Site #: 370507002025

Project: Assessments 2016

Region: 995

Site: BURNSVILLE ELEMENTA

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability

Rating

Score

Possible
Score

Percent
Score

Suitability - ES->Outside-->Vehicular Traffic

Sometimes traffic overflows into the street. Reported needing an additional lane for car pick-up and drop-off. Good separation of cars and bus lot.

Suitability - ES->Outside-->Pedestrian Traffic

Good routing throughout. The sidewalk is aged and chipping in places.

Suitability - ES->Outside-->Parking

Parking is inadequate for events and at the start of the school year. Visitors during events park on the side of the street and on the grass.

Suitability - ES->Safety and Security-->Ease of Supervision

Blind spots exist inside the building in a few places and the hallway zig-zag pattern limits sight lines. There is only one outside camera, facing the bus lot. Front entrance is controlled and monitored by front office.

Suitability Report - Full

Project #: 8272	County: Yancey	Site #: 370507002029
Project: Assessments 2016	Region: 995	Site: MICAVILLE ELEMENTAR
Grade Config: KG-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Poor	1.00	2.00	50.00
Exterior Environment	Good	1.20	1.50	80.00
General Classrooms				
Environment	Fair	3.19	4.90	65.00
Size	Good	9.80	12.25	80.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Poor	1.84	3.68	50.00
Kindergarten				
Environment	Poor	0.21	0.42	50.00
Size	Fair	0.68	1.04	65.00
Location	Fair	0.20	0.31	65.00
Storage/Fixed Equip	Poor	0.16	0.31	50.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Fair	0.47	0.72	65.00
Size	Good	1.44	1.80	80.00
Location	Fair	0.35	0.54	65.00
Storage/Fixed Equip	Poor	0.27	0.54	50.00
Science				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Music				
Environment	Poor	0.37	0.74	50.00

Project #: 8272

County: Yancey

Site #: 370507002029

Project: Assessments 2016

Region: 995

Site: MICAVILLE ELEMENTAR

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Poor	0.93	1.85	50.00
Location	Poor	0.28	0.56	50.00
Storage/Fixed Equip	Poor	0.28	0.56	50.00
Art				
Environment	Poor	0.23	0.47	50.00
Size	Unsat	0.00	1.17	0.00
Location	Fair	0.23	0.35	65.00
Storage/Fixed Equip	Poor	0.18	0.35	50.00
Computer Labs				
Environment	Fair	0.22	0.34	65.00
Size	Poor	0.43	0.85	50.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Unsat	0.00	0.26	0.00
P.E.				
Environment	Poor	0.96	1.92	50.00
Size	Good	3.84	4.80	80.00
Location	Fair	0.94	1.44	65.00
Storage/Fixed Equip	Unsat	0.00	1.44	0.00
Performing Arts				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Media Center				
Environment	Good	0.78	0.97	80.00
Size	Good	1.95	2.44	80.00
Location	Good	0.58	0.73	80.00
Storage/Fixed Equip	Fair	0.48	0.73	65.00
Restrooms (Student)	Fair	0.58	0.89	65.00
Administration	Good	2.05	2.56	80.00
Counseling	Poor	0.15	0.29	50.00
Clinic	Fair	0.38	0.58	65.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Fair	3.25	5.00	65.00
Food Service and Prep	Poor	3.10	6.20	50.00
Custodial and Maintenance	Fair	0.33	0.50	65.00
Outside				
Vehicular Traffic	Poor	1.00	2.00	50.00
Pedestrian Traffic	Fair	0.63	0.97	65.00
Parking	Poor	0.41	0.81	50.00
Play Areas	Fair	1.52	2.34	65.00
Safety and Security				
Fencing	Good	0.60	0.75	80.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Good	0.40	0.50	80.00

Project #: 8272

County: Yancey

Site #: 370507002029

Project: Assessments 2016

Region: 995

Site: MICAVILLE ELEMENTAR

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		58.01	89.58	64.75

Comments

Suitability - ES

Micaville Elementary School is a K-5 grade facility built in 1936. The school does not serve special education students. The school has one mobile unit with two portable classrooms, used for ESL and Exceptional Children classes as well as office space for the ESL and Speech/Occupational/Physical Therapy staff. The facility has an aging electrical, plumbing, and HVAC infrastructures.

Suitability - ES->Learning Environment-->Learning Style Variety

Many spaces are limited in flexibility due to a lack of adequate permanent storage space.

Suitability - ES->Learning Environment-->Interior Environment

Both the heating and cooling systems are loud; the heating system makes a loud and continuous clanking noise when it comes on, and the AC window units are loud and students have trouble hearing. Many spaces are limited in flexibility due to a lack of adequate permanent storage space. There is a metal barb protruding out of the carpet in the 1st-2nd grade hallway that presents a tripping hazard.

Suitability - ES->General Classrooms-->Environment

Both the heating and cooling systems are loud; the heating system makes a loud and continuous clanking noise when it comes on, and the AC window units are loud and students have trouble hearing. There is some flexible space in the general classrooms.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

There is no permanent casework in the general classrooms. One classroom uses an old restroom in the room as a closet. All storage is mobile, and more storage space is needed. The 4th and 5th grade levels lack enough power outlets.

Suitability - ES->Kindergarten-->Environment

The classroom space is cramped from lack of adequate permanent storage space. Temperature can be hard to regulate. There is a raised part of tile floor and carpet that present trip hazards. The entrance to the room is a cubby area on an incline near the stage and has steep stairs and a steep ramp, posing considerable trip and fall hazards.

Suitability - ES->Kindergarten-->Size

Met 78% of the square footage standard.

Suitability - ES->Kindergarten-->Location

The room is located away from other general classrooms and is next to the stage and gym area.

Suitability - ES->Kindergarten-->Storage/Fixed Equip

There is space for storage, but all storage present are mobile storage units and take up considerable classroom space. The restroom has only cold water.

Suitability - ES->Instructional Resource Rooms-->Environment

Two of the rooms are located in a mobile unit. The HVAC system is difficult to regulate and noisy.

Suitability - ES->Instructional Resource Rooms-->Size

Met 96% of the square footage standard.

Suitability - ES->Instructional Resource Rooms-->Location

Two resource rooms are located within a mobile unit.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip

There is enough storage for their needs, however, all available storage spaces are mobile storage and not any permanent casework.

Suitability - ES->Music

Music and Art classes occur within the same classroom space.

Project #: 8272

County: Yancey

Site #: 370507002029

Project: Assessments 2016

Region: 995

Site: MICAVILLE ELEMENTAR

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Music-->Environment The room has poor lighting, acoustics, improper temperature regulation, and poor aesthetics.				
Suitability - ES->Music-->Size Met 51% of the square footage standard.				
Suitability - ES->Music-->Location The room can only be accessed by leaving the main building. The Music room is located next to a room that houses counseling, and noise easily travels through the connecting door.				
Suitability - ES->Music-->Storage/Fixed Equip The room does not have any permanent storage space. There is limited equipment.				
Suitability - ES->Art Music and Art classes occur within the same classroom space.				
Suitability - ES->Art-->Environment The room has poor lighting, acoustics, improper temperature regulation, and poor aesthetics.				
Suitability - ES->Art-->Size Met 43% of the square footage standard.				
Suitability - ES->Art-->Location The room can only be accessed by leaving the main building. The Art room is located next to a room that houses counseling, and noise easily travels through the connecting door.				
Suitability - ES->Art-->Storage/Fixed Equip The room does not have any permanent storage space. There is limited equipment. There is a sink, but it does not have a clay trap.				
Suitability - ES->Computer Labs-->Environment The computer lab tends to be warm and not well-ventilated.				
Suitability - ES->Computer Labs-->Size Met 56% of the square footage standard.				
Suitability - ES->Computer Labs-->Storage/Fixed Equip There are no storage areas in the computer lab.				
Suitability - ES->P.E.-->Environment The gym is dimly lit, has a tile floor, and has poor acoustics (easily echoes all sound). Part of the tile floor is damaged, and much of the gym space on the perimeter is occupied by equipment due to a lack of storage space.				
Suitability - ES->P.E.-->Size While the gym met the square footage standard, much of the gym space is occupied by equipment due to a lack of storage space.				
Suitability - ES->P.E.-->Location The gym is located in the middle of the school near the front entrance, and the space is bordered by the clinic, a Kindergarten, and 2nd grade classrooms.				
Suitability - ES->P.E.-->Storage/Fixed Equip All equipment, including folding chairs, are stored on the sides of the gym floor. There are backboards and some fixed equipment, but there is no safety padding and water fountains are located in the hallway.				
Suitability - ES->Media Center-->Size Met 87% of the square footage standard.				
Suitability - ES->Media Center-->Storage/Fixed Equip The media center is in need of more storage space. There are not enough power outlets to connect technology, and power strips and extension cords are currently being used.				

Project #: 8272

County: Yancey

Site #: 370507002029

Project: Assessments 2016

Region: 995

Site: MICAVILLE ELEMENTAR

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Restrooms (Student) There is no hot water in the restrooms. Reported that their septic tank is in failure and has backed up before, however, they have been approved for a replacement. Reported that the building also has low water pressure and sometimes the water stops flowing momentarily before working.				
Suitability - ES->Administration Records are stored in the conference room in locked filing cabinets.				
Suitability - ES->Counseling Counseling is located away from the main office and is accessed only by leaving the building. It is also located next to the Music/Art room, and noise carries through the wall between the two rooms. The room is cramped and lacks adequate storage space.				
Suitability - ES->Clinic The clinic met all criteria except for having an attached restroom with shower. The room does have a sink, locked cabinet, cot, space for a cot, and fridge.				
Suitability - ES->Cafeteria The HVAC system in the cafeteria is loud. Routing is good within the space. The cafeteria space is smaller due to the kitchen housing its fridge, freezer, office area, and other equipment within the cafeteria space. Large custodial equipment is also stored on the sides of the cafeteria.				
Suitability - ES->Food Service and Prep The kitchen does not have floor drains. Dry storage tends to warm and is not ventilated, and the area has wooden racks instead of metal racks. The kitchen is in need of more electrical outlets, and staff are currently using extension cords. The fridge and freezer are located in the cafeteria space, the freezers are not walk-in, and the fridge tends to leak water. The ice machine tends to freeze and won't produce ice. The kitchen lacks adequate storage space. The cafeteria manager's office is located within the cafeteria space. The kitchen is an open floor plan without separation				
Suitability - ES->Custodial and Maintenance Custodial and maintenance spaces are located throughout the building, but are using space for other rooms (such as the gym and cafeteria).				
Suitability - ES->Outside-->Vehicular Traffic There is no separation between the car drop-off area, the bus lot, and staff parking. Traffic tends to overflow into the street.				
Suitability - ES->Outside-->Pedestrian Traffic Routing is good overall except for a few areas. When students/staff need to access the mobile unit containing ESL and EC. They must walk through part of the parking lot behind bus parking to access, and the walkway is uncovered. Also, students/staff have to exit the building to access the Music/Art room and the Counselor's room. The walkway is through the courtyard and is uncovered.				
Suitability - ES->Outside-->Parking There is not enough parking for visitors during events. Staff parking and bus parking are not separated.				
Suitability - ES->Outside-->Play Areas The Kindergarten does not have a separate and enclosed playground area. There are several playground areas around the school. There are also several outdoor gathering and learning areas around the school.				
Suitability - ES->Safety and Security-->Fencing The Kindergarten does not have a separate and enclosed playground area. The Kindergarten shares with 1st grade on a playground designated for those two grade levels, and the area is mostly fenced.				
Suitability - ES->Safety and Security-->Ease of Supervision There are few hiding areas within the building. There are security cameras inside and one outside facing the bus lot. There are blind spots outside and around the building, and within the garden and courtyard areas.				

Suitability Report - Full

Project #: 8272	County: Yancey	Site #: 370507002032
Project: Assessments 2016	Region: 995	Site: SOUTH TOE ELEMENTA
Grade Config: KG-05	Site Type: Elementary	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Fair	3.19	4.90	65.00
Size	Fair	7.96	12.25	65.00
Location	Good	2.94	3.68	80.00
Storage/Fixed Equip	Fair	2.39	3.68	65.00
Kindergarten				
Environment	Fair	0.27	0.42	65.00
Size	Fair	0.68	1.04	65.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Fair	0.20	0.31	65.00
ECE				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Fair	0.47	0.72	65.00
Size	Excel	1.80	1.80	100.00
Location	Good	0.43	0.54	80.00
Storage/Fixed Equip	Poor	0.27	0.54	50.00
Science				
Environment	Poor	0.25	0.50	50.00
Size	Good	1.00	1.25	80.00
Location	Good	0.30	0.38	80.00
Storage/Fixed Equip	Unsat	0.00	0.38	0.00
Music				
Environment	Poor	0.37	0.74	50.00

Project #: 8272

County: Yancey

Site #: 370507002032

Project: Assessments 2016

Region: 995

Site: SOUTH TOE ELEMENTA

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Fair	1.20	1.85	65.00
Location	Good	0.44	0.56	80.00
Storage/Fixed Equip	Poor	0.28	0.56	50.00
Art				
Environment	Poor	0.23	0.47	50.00
Size	Poor	0.58	1.17	50.00
Location	Good	0.28	0.35	80.00
Storage/Fixed Equip	Poor	0.18	0.35	50.00
Computer Labs				
Environment	Fair	0.22	0.34	65.00
Size	Fair	0.55	0.85	65.00
Location	Good	0.20	0.26	80.00
Storage/Fixed Equip	Good	0.20	0.26	80.00
P.E.				
Environment	Fair	1.25	1.92	65.00
Size	Fair	3.12	4.80	65.00
Location	Excel	1.44	1.44	100.00
Storage/Fixed Equip	Poor	0.72	1.44	50.00
Performing Arts				
Environment	Poor	0.30	0.60	50.00
Size	Good	1.21	1.51	80.00
Location	Excel	0.45	0.45	100.00
Storage/Fixed Equip	Poor	0.23	0.45	50.00
Media Center				
Environment	Fair	0.63	0.97	65.00
Size	Unsat	0.00	2.44	0.00
Location	Good	0.58	0.73	80.00
Storage/Fixed Equip	Poor	0.37	0.73	50.00
Restrooms (Student)	Fair	0.58	0.89	65.00
Administration	Poor	1.28	2.56	50.00
Counseling	Fair	0.19	0.29	65.00
Clinic	Unsat	0.00	0.58	0.00
Staff Lounge-WkRm	Good	1.01	1.27	80.00
Cafeteria	Fair	3.25	5.00	65.00
Food Service and Prep	Good	4.96	6.20	80.00
Custodial and Maintenance	Fair	0.33	0.50	65.00
Outside				
Vehicular Traffic	Fair	1.30	2.00	65.00
Pedestrian Traffic	Fair	0.63	0.97	65.00
Parking	Good	0.65	0.81	80.00
Play Areas	Good	1.87	2.34	80.00
Safety and Security				
Fencing	Fair	0.49	0.75	65.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Good	2.40	3.00	80.00
Controlled Entrances	Good	0.40	0.50	80.00

Project #: 8272

County: Yancey

Site #: 370507002032

Project: Assessments 2016

Region: 995

Site: SOUTH TOE ELEMENTA

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Total For Site:		63.19	95.10	66.44

Comments

Suitability - ES->Learning Environment-->Learning Style Variety

South Toe Elementary consists primarily of regular classroom spaces along with some specialized rooms. There is not a great deal of opportunity for a variety of instructional spaces.

Suitability - ES->Learning Environment-->Interior Environment

Most spaces have natural light and the size of the school allows for ease of circulation. The age of the facility limits the overall aesthetics.

Suitability - ES->Learning Environment-->Exterior Environment

The exterior space at South Toe provides enough play space but has little developed outdoor learning areas.

Suitability - ES->General Classrooms-->Environment

General classrooms provide natural light and reasonable acoustics but the age of the facility limits the overall aesthetics.

Suitability - ES->General Classrooms-->Size

Grade 1-3 classrooms meet approximately 70% of the guideline, grade 4-5 meet approximately 70%.

Suitability - ES->General Classrooms-->Storage/Fixed Equip

Classrooms include minimal storage. Some have "cloak rooms". Most include appropriate technology equipment.

Suitability - ES->Kindergarten-->Environment

The kindergarten classroom provides natural light and reasonable acoustics but the age of the facility limits the overall aesthetics.

Suitability - ES->Kindergarten-->Size

The Kindergarten room meets approximately 75% of the guideline.

Suitability - ES->Kindergarten-->Storage/Fixed Equip

The kindergarten room includes a bathroom and a wet area. Storage is limited.

Suitability - ES->Instructional Resource Rooms-->Environment

Resource rooms provide natural light and reasonable acoustics but the age of the facility limits the overall aesthetics.

Suitability - ES->Instructional Resource Rooms-->Storage/Fixed Equip

Storage and equipment in resource rooms is minimal.

Suitability - ES->Science-->Environment

South Toe utilizes one general classroom type space for all specialized instruction (music / art / science) and as the nurses office. It contains little in the way of a stimulating environment for science instruction.

Suitability - ES->Science-->Storage/Fixed Equip

There is no storage or equipment associated with science instruction.

Suitability - ES->Music-->Environment

South Toe utilizes one general classroom type space for all specialized instruction (music / art / science) and as the nurses office. It contains little in the way of a stimulating environment for music instruction.

Suitability - ES->Music-->Size

The room meets approximately 70% of the guideline.

Suitability - ES->Music-->Storage/Fixed Equip

There is minimal storage or equipment associated with music instruction.

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Art-->Environment South Toe utilizes one general classroom type space for all specialized instruction (music / art / science) and as the nurses office. It contains little in the way of a stimulating environment for art instruction.				
Suitability - ES->Art-->Size The room meets approximately 50% of the guideline.				
Suitability - ES->Art-->Storage/Fixed Equip There is minimal storage or equipment associated with art instruction.				
Suitability - ES->Computer Labs-->Environment The computer lab provides natural light and reasonable acoustics but the age of the facility limits the overall aesthetics.				
Suitability - ES->Computer Labs-->Size The computer lab meets approximately 75% of the guideline.				
Suitability - ES->P.E.-->Environment The PE space at South Toe is a very basic gym space. There is no natural light and little else in the way of overall aesthetics.				
Suitability - ES->P.E.-->Size The PE space meets approximately 65% of the guideline.				
Suitability - ES->P.E.-->Storage/Fixed Equip The PE space lacks storage and equipment.				
Suitability - ES->Performing Arts-->Environment Performing arts consists of a small stage area off the cafeteria that is used for a variety of other purposes.				
Suitability - ES->Performing Arts-->Storage/Fixed Equip There is minimal storage / equipment associated with performing arts.				
Suitability - ES->Media Center-->Environment The media center consists of an oversize general classroom type space. There is natural light and some improvements to the environment have been made.				
Suitability - ES->Media Center-->Size The media center meets less than 50% of the guideline.				
Suitability - ES->Media Center-->Storage/Fixed Equip The media center lacks appropriate storage and equipment.				
Suitability - ES->Restrooms (Student) There is one set of student restrooms. The facilities are dated.				
Suitability - ES->Administration The administrative area is appropriately located but consists of only a principals and administrative assistant office. There is no work space, conference room, reception area.				
Suitability - ES->Counseling Guidance consists of one small office area.				
Suitability - ES->Clinic South Toe essentially has no clinic. A makeshift nurses office has been established in the multi-purpose room but does not include a restroom, separate cot area or other amenities normally associated with a clinic.				
Suitability - ES->Cafeteria The cafeteria meets approximately 80% of the size guideline. There is minimal storage.				

Project #: 8272

County: Yancey

Site #: 370507002032

Project: Assessments 2016

Region: 995

Site: SOUTH TOE ELEMENTA

Grade Config: KG-05

Site Type: Elementary

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - ES->Custodial and Maintenance Custodial area consists of one small area at one end of the building.				
Suitability - ES->Outside-->Vehicular Traffic There is separation of bus and other traffic but the entrances to both are very small causing some conflict.				
Suitability - ES->Outside-->Pedestrian Traffic While pedestrian traffic is minimal, it crosses other traffic lanes.				
Suitability - ES->Safety and Security-->Fencing There are some fenced areas but it does not secure the site.				
Suitability - ES->Safety and Security-->Controlled Entrances Entrances are secure with appropriate supervision. There is no entry vestibule.				

Suitability Report - Full

Project #: 8272	County: Yancey	Site #: 370507002026
Project: Assessments 2016	Region: 995	Site: CANE RIVER MIDDLE
Grade Config: 06-08	Site Type: Middle	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Fair	2.54	3.90	65.00
Size	Good	7.80	9.75	80.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Poor	1.46	2.93	50.00
Self-Contained Special Ed				
Environment	Poor	0.27	0.55	50.00
Size	Poor	0.68	1.36	50.00
Location	Fair	0.27	0.41	65.00
Storage/Fixed Equip	Fair	0.27	0.41	65.00
Instructional Resource Rooms				
Environment	Fair	0.53	0.82	65.00
Size	Good	1.64	2.05	80.00
Location	Good	0.49	0.61	80.00
Storage/Fixed Equip	Good	0.49	0.61	80.00
Science				
Environment	Good	0.76	0.95	80.00
Size	Good	1.91	2.39	80.00
Location	Good	0.57	0.72	80.00
Storage/Fixed Equip	Fair	0.47	0.72	65.00
Music				
Environment	Poor	0.37	0.74	50.00
Size	Poor	0.92	1.84	50.00
Location	Good	0.44	0.55	80.00
Storage/Fixed Equip	Fair	0.36	0.55	65.00
Art				
Environment	Good	0.52	0.65	80.00
Size	Good	1.29	1.61	80.00
Location	Good	0.39	0.48	80.00
Storage/Fixed Equip	Fair	0.31	0.48	65.00
Career Tech Ed				
Environment	(N/A)	0.00	0.00	0.00

Project #: 8272

County: Yancey

Site #: 370507002026

Project: Assessments 2016

Region: 995

Site: CANE RIVER MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Computer Labs				
Environment	Fair	0.20	0.30	65.00
Size	Good	0.60	0.75	80.00
Location	Good	0.18	0.23	80.00
Storage/Fixed Equip	Fair	0.15	0.23	65.00
P.E.				
Environment	Fair	1.56	2.40	65.00
Size	Good	4.80	6.00	80.00
Location	Good	1.44	1.80	80.00
Storage/Fixed Equip	Fair	1.17	1.80	65.00
Performing Arts				
Environment	Poor	0.21	0.42	50.00
Size	Fair	0.68	1.05	65.00
Location	Fair	0.20	0.31	65.00
Storage/Fixed Equip	Fair	0.20	0.31	65.00
Media Center				
Environment	Good	0.74	0.93	80.00
Size	Excel	2.32	2.32	100.00
Location	Good	0.56	0.70	80.00
Storage/Fixed Equip	Fair	0.45	0.70	65.00
Restrooms (Student)	Poor	0.46	0.93	50.00
Administration	Good	1.68	2.10	80.00
Counseling	Poor	0.21	0.42	50.00
Clinic	Excel	0.34	0.34	100.00
Staff Lounge-WkRm	Good	0.72	0.91	80.00
Cafeteria	Good	3.20	4.00	80.00
Food Service and Prep	Poor	2.86	5.72	50.00
Custodial and Maintenance	Fair	0.33	0.50	65.00
Outside				
Vehicular Traffic	Poor	2.00	4.00	50.00
Pedestrian Traffic	Fair	0.28	0.43	65.00
Parking	Unsat	0.00	0.86	0.00
Athletic Courts and Fields	Good	0.84	1.05	80.00
Safety and Security				
Fencing	Good	0.62	0.78	80.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Good	0.40	0.50	80.00
Total For Site:		64.76	93.26	69.44

Comments

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Cane River Middle School is a 6-8 grade facility built in the 1950s, with an additional wing added in 1999. The school has one classroom to serve special education students. The school does not have any portables. The school's infrastructure is antiquated and inadequate for the needs of the school, including the electrical, plumbing, and HVAC systems.				
Suitability - MS->Learning Environment-->Learning Style Variety				
There are several general classrooms, the self-contained EC, band, chorus, and performing arts spaces that are limited in flexible space for different configurations.				
Suitability - MS->Learning Environment-->Interior Environment				
The HVAC system is loud and varies to the extremes. The HVAC system also tends to emit odors from outside and dust into the classrooms. Good aesthetics and inviting in most of the rooms. Flexible space is limited in some of the classrooms. There are many water leaks throughout the building (through ceilings and under doorways), including some that leak directly into light fixtures.				
Suitability - MS->Learning Environment-->Exterior Environment				
There is an outdoor patio space used for events/dances.				
Suitability - MS->General Classrooms-->Environment				
The HVAC system is loud and varies to the extremes. The HVAC system also tends to emit odors from outside and dust into the classrooms. There is some flexible space in some of the classrooms; others are limited by the mobile storage space. Good aesthetics and inviting in most of the rooms.				
Suitability - MS->General Classrooms-->Storage/Fixed Equip				
There is adequate built-in and mobile storage in most of the general classrooms. All rooms lack interactive technology, such as a Smartboard. Also, many of the rooms do not have mounted projectors.				
Suitability - MS->Self-Contained Special Ed-->Environment				
The classroom is not acoustically isolated from the computer lab and counseling office. The space is small and cramped.				
Suitability - MS->Self-Contained Special Ed-->Size				
Met 62% of the square footage standard.				
Suitability - MS->Self-Contained Special Ed-->Location				
Located next to the computer lab and counselor's office. The room is located on the side of the school where the gym and band rooms are located.				
Suitability - MS->Self-Contained Special Ed-->Storage/Fixed Equip				
Limited storage space available. Little fixed equipment within the classroom space. The self-contained space does have an excellent bathroom attached to the space that includes plenty of space for movement, handicap access, shower, and changing area.				
Suitability - MS->Instructional Resource Rooms-->Environment				
The space is contains some storage space and old fixtures. The room is used more often for storage or an extension for the EC self-contained class.				
Suitability - MS->Science-->Storage/Fixed Equip				
2 of the 3 science rooms have built-in casework, sinks, and other fixed equipment. The 6th grade science room is located in a general classroom and does not have built-in casework, sinks, or other fixtures outside of science work tables. The 7th and 8th grade science rooms have adequate storage and related science equipment.				
Suitability - MS->Music-->Environment				
There is fair lighting and fair acoustics in the band and chorus rooms. Both rooms have heating and cooling issues. The band room's HVAC system is loud. Some aesthetics in both rooms present. Limited space for different configurations.				

Project #: 8272

County: Yancey

Site #: 370507002026

Project: Assessments 2016

Region: 995

Site: CANE RIVER MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS->Music-->Size The band room met 71% of the square footage standard. The chorus room met 48% of the square footage space.				
Suitability - MS->Music-->Storage/Fixed Equip There is mobile casework in the hallway to accommodate instrument storage. Storage within the band classroom is full and takes up considerable classroom space. There is limited storage space in the chorus classroom.				
Suitability - MS->Art-->Size Met 86% of the square footage standard.				
Suitability - MS->Art-->Storage/Fixed Equip No kiln. There is one sink without a clay trap; the sink is old and tends to emit odors. There is limited display space.				
Suitability - MS->Computer Labs-->Environment Computer lab in the older part of the building is very warm and not adequately cooled.				
Suitability - MS->Computer Labs-->Size The computer lab in the older hall met 82% of the square footage standard. The computer lab in the newer hall met 90% of the square footage standard.				
Suitability - MS->Computer Labs-->Storage/Fixed Equip Limited storage space, but adequate for needs.				
Suitability - MS->P.E.-->Environment Flooding and humidity are issues, and have been damaging the new gym floor.				
Suitability - MS->P.E.-->Size Gym size is excellent; the office and locker room space is good.				
Suitability - MS->P.E.-->Storage/Fixed Equip There are a few small storage spaces. Some of the gym equipment is stored in other closet areas of the school. Equipment is also stored in a built-in area on the stage area that has been deemed not up to code for use and poses a safety hazard. The PA system in the gym is very poor. The sound system is poor. The side basketball goals are hard to retract.				
Suitability - MS->Performing Arts-->Environment Poor acoustics and temperature control in the classroom space, and the space is small with limited flexibility.				
Suitability - MS->Performing Arts-->Size The classroom space is small and acoustics are poor. The stage is located within the gym.				
Suitability - MS->Performing Arts-->Location The performing arts classroom is located next to the chorus room.				
Suitability - MS->Performing Arts-->Storage/Fixed Equip Limited storage space present and no permanent casework.				
Suitability - MS->Media Center-->Storage/Fixed Equip Carpet is old/damaged and in need of replacement. There is permanent casework and mobile bookcases present.				
Suitability - MS->Restrooms (Student) All restrooms lack access to hot water. There is broken tile and fixtures in some of the restroom spaces. The boys' locker room restrooms lack stalls around the toilets (privacy partitions only).				
Suitability - MS->Counseling The space lacks a reception area, adequate storage, or space for group work. The area is not soundproof and is located next to the EC self-contained classroom. Noise and smells carry into the small space. There is limited storage space for records.				
Suitability - MS->Cafeteria The freezer is located in the dining space. The space met the square footage standard.				

Project #: 8272

County: Yancey

Site #: 370507002026

Project: Assessments 2016

Region: 995

Site: CANE RIVER MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
<p>Suitability - MS->Food Service and Prep The freezer is spacious but is located within the cafeteria dining area. An old oven and fryer are outside and need to be disposed of. The kitchen tends to be hot to the point staff open the back door. There is a water leak outside by the delivery area.</p>				
<p>Suitability - MS->Custodial and Maintenance Some of the larger custodial equipment are being housed in the cafeteria.</p>				
<p>Suitability - MS->Outside-->Vehicular Traffic Traffic can extend into the street and down the road. Congestion has resulted in rerouting through the available parking spaces around the school. Needs a "bus only" sign for one of the school's entrances.</p>				
<p>Suitability - MS->Outside-->Pedestrian Traffic More separation and routing are needed for pedestrian walkways.</p>				
<p>Suitability - MS->Outside-->Parking Reported that lack of parking is the biggest complaint from visitors. Limited parking for visitors and staff; they often park in the grass or gravel areas. Lots are not well-lit or marked. Vehicular traffic consumes parking spaces to ease congestion. Pavement is fractured and there are many potholes. There is a lack of lighting in the parking lots.</p>				
<p>Suitability - MS->Safety and Security-->Ease of Supervision Good sight lines within the building. One hallway is not covered by a camera. A few blind spots exist in the gym, and there are a few hiding spaces in the smaller hallways connecting rooms. One camera is old and provides a blurred picture. There is inadequate camera coverage of the parking lots.</p>				

Suitability Report - Full

Project #: 8272	County: Yancey	Site #: 370507002028
Project: Assessments 2016	Region: 995	Site: EAST YANCEY MIDDLE
Grade Config: 06-08	Site Type: Middle	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS				
Learning Environment				
Learning Style Variety	Fair	3.25	5.00	65.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Poor	0.75	1.50	50.00
General Classrooms				
Environment	Poor	1.95	3.90	50.00
Size	Fair	6.34	9.75	65.00
Location	Good	2.34	2.93	80.00
Storage/Fixed Equip	Poor	1.46	2.93	50.00
Self-Contained Special Ed				
Environment	(N/A)	0.00	0.00	0.00
Size	(N/A)	0.00	0.00	0.00
Location	(N/A)	0.00	0.00	0.00
Storage/Fixed Equip	(N/A)	0.00	0.00	0.00
Instructional Resource Rooms				
Environment	Fair	0.53	0.82	65.00
Size	Good	1.64	2.05	80.00
Location	Good	0.49	0.61	80.00
Storage/Fixed Equip	Poor	0.31	0.61	50.00
Science				
Environment	Poor	0.48	0.95	50.00
Size	Fair	1.55	2.39	65.00
Location	Fair	0.47	0.72	65.00
Storage/Fixed Equip	Fair	0.47	0.72	65.00
Music				
Environment	Poor	0.37	0.74	50.00
Size	Poor	0.92	1.84	50.00
Location	Poor	0.28	0.55	50.00
Storage/Fixed Equip	Poor	0.28	0.55	50.00
Art				
Environment	Good	0.52	0.65	80.00
Size	Excel	1.61	1.61	100.00
Location	Good	0.39	0.48	80.00
Storage/Fixed Equip	Fair	0.31	0.48	65.00
Career Tech Ed				
Environment	Fair	0.88	1.35	65.00

Project #: 8272

County: Yancey

Site #: 370507002028

Project: Assessments 2016

Region: 995

Site: EAST YANCEY MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Poor	1.69	3.37	50.00
Location	Good	0.81	1.01	80.00
Storage/Fixed Equip	Fair	0.66	1.01	65.00
Computer Labs				
Environment	Good	0.24	0.30	80.00
Size	Good	0.60	0.75	80.00
Location	Good	0.18	0.23	80.00
Storage/Fixed Equip	Good	0.18	0.23	80.00
P.E.				
Environment	Good	1.92	2.40	80.00
Size	Good	4.80	6.00	80.00
Location	Excel	1.80	1.80	100.00
Storage/Fixed Equip	Good	1.44	1.80	80.00
Performing Arts				
Environment	Good	0.33	0.42	80.00
Size	Fair	0.68	1.05	65.00
Location	Excel	0.31	0.31	100.00
Storage/Fixed Equip	Poor	0.16	0.31	50.00
Media Center				
Environment	Excel	0.93	0.93	100.00
Size	Fair	1.51	2.32	65.00
Location	Excel	0.70	0.70	100.00
Storage/Fixed Equip	Excel	0.70	0.70	100.00
Restrooms (Student)	Fair	0.60	0.93	65.00
Administration	Fair	1.36	2.10	65.00
Counseling	Poor	0.21	0.42	50.00
Clinic	Excel	0.34	0.34	100.00
Staff Lounge-WkRm	Good	0.72	0.91	80.00
Cafeteria	Good	3.20	4.00	80.00
Food Service and Prep	Good	4.57	5.72	80.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Poor	2.00	4.00	50.00
Pedestrian Traffic	Poor	0.22	0.43	50.00
Parking	Poor	0.43	0.86	50.00
Athletic Courts and Fields	Good	0.84	1.05	80.00
Safety and Security				
Fencing	Good	0.62	0.78	80.00
Signage & Way Finding	Good	0.80	1.00	80.00
Ease of Supervision	Fair	1.95	3.00	65.00
Controlled Entrances	Fair	0.33	0.50	65.00
Total For Site:		67.08	97.27	68.97

Comments

Project #: 8272

County: Yancey

Site #: 370507002028

Project: Assessments 2016

Region: 995

Site: EAST YANCEY MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS->Learning Environment-->Learning Style Variety Most instructional spaces do not include the flexibility to provide a good deal of differentiated instruction. However the media center and multiple small learning spaces provides some degree of flexibility.				
Suitability - MS->Learning Environment-->Interior Environment The original section of the building consists primarily of a hallway with dated classrooms so little in the way of a stimulating environment. The media center provides a very inviting environment.				
Suitability - MS->Learning Environment-->Exterior Environment Outdoor spaces at East Yancey are limited with some access problems.				
Suitability - MS->General Classrooms-->Environment General classrooms are dated and provide little in the way of overall aesthetics.				
Suitability - MS->General Classrooms-->Size General classrooms meet approximately 75% of the guideline.				
Suitability - MS->General Classrooms-->Storage/Fixed Equip General classrooms have minimal equipment and storage.				
Suitability - MS->Instructional Resource Rooms-->Environment A variety of spaces are used as resource rooms. Most have minimal amenities.				
Suitability - MS->Instructional Resource Rooms-->Storage/Fixed Equip Resource rooms have minimal storage and equipment.				
Suitability - MS->Science-->Environment 3 rooms are used for science, 1 of which could be considered a science room with appropriate equipment and service. All three provide little in the way of a stimulating environment.				
Suitability - MS->Science-->Size Of the three rooms used for science, 1 meets the guideline, 1 meets approximately 85% and the other 75%. None have associated prep rooms.				
Suitability - MS->Science-->Location Science rooms are in the academic hallway but are not located together.				
Suitability - MS->Science-->Storage/Fixed Equip 1 science room has appropriate equipment, the other 2 do not.				
Suitability - MS->Music-->Environment Both the band and choir rooms provide minimal amenities.				
Suitability - MS->Music-->Size The band room meets approximately 75 % of the guideline, the choir room 50%. Neither have storage or other support spaces.				
Suitability - MS->Music-->Location The music rooms are not located together. To access the choir room students must enter through the art room.				
Suitability - MS->Music-->Storage/Fixed Equip Neither music room provides adequate casework, storage, sink, or other equipment.				
Suitability - MS->Art-->Size The art room meets the size guideline.				
Suitability - MS->Art-->Storage/Fixed Equip The art room includes some storage but minimal display space and only one small sink.				

Project #: 8272

County: Yancey

Site #: 370507002028

Project: Assessments 2016

Region: 995

Site: EAST YANCEY MIDDLE

Grade Config: 06-08

Site Type: Middle

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - MS->Career Tech Ed-->Environment The CTE space at East Yancey consists of one technology classroom. It has natural light but little else in the way of overall aesthetics.				
Suitability - MS->Career Tech Ed-->Size The CTE space meets approximately 60% of the size guideline.				
Suitability - MS->Career Tech Ed-->Storage/Fixed Equip Computer stations are good but there is no other storage or equipment.				
Suitability - MS->Computer Labs-->Environment The environment in one computer lab is excellent, the other is fair.				
Suitability - MS->Computer Labs-->Size One computer lab meets the size guideline, the other meets approximately 70%.				
Suitability - MS->Computer Labs-->Storage/Fixed Equip One computer lab has appropriate equipment and storage, the other lacks appropriate storage.				
Suitability - MS->P.E.-->Size The gymnasium meets the size guidelines. The locker rooms and other support areas do not.				
Suitability - MS->Performing Arts-->Size Performing arts at East Yancey consists of a stage off the gym. The gym space is ample but the stage is small and has effectively been turned into a weight room.				
Suitability - MS->Performing Arts-->Storage/Fixed Equip There is minimal storage or equipment associated with performing arts.				
Suitability - MS->Media Center-->Size The media center meets approximately 70% of the guideline.				
Suitability - MS->Restrooms (Student) Restrooms are adequate in number but the facilities are dated.				
Suitability - MS->Administration Offices and reception are adequate. There is no conference or workroom.				
Suitability - MS->Counseling Counseling consists of only one office. There is no group area.				
Suitability - MS->Clinic East Yancey includes an extensive health center.				
Suitability - MS->Outside-->Vehicular Traffic Bus and other traffic merge and backups occur.				
Suitability - MS->Outside-->Pedestrian Traffic Pedestrian traffic crosses other traffic lanes.				
Suitability - MS->Outside-->Parking Parking at East Yancey is inadequate and for the most part unorganized.				
Suitability - MS->Safety and Security-->Ease of Supervision In school supervision is good, the outside areas have multiple hidden areas.				
Suitability - MS->Safety and Security-->Controlled Entrances Entrances are controlled but is not easily seen from the office and there is no entry vestibule.				

Suitability Report - Full

Project #: 8272	County: Yancey	Site #: 370507002030
Project: Assessments 2016	Region: 995	Site: MOUNTAIN HERITAGE H
Grade Config: 09-12	Site Type: High	Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS				
Learning Environment				
Learning Style Variety	Good	4.00	5.00	80.00
Interior Environment	Fair	1.30	2.00	65.00
Exterior Environment	Fair	0.98	1.50	65.00
General Classrooms				
Environment	Poor	1.95	3.90	50.00
Size	Poor	4.88	9.75	50.00
Location	Fair	1.90	2.93	65.00
Storage/Fixed Equip	Poor	1.46	2.93	50.00
Self-Contained Special Ed				
Environment	Good	0.43	0.53	80.00
Size	Excel	1.33	1.33	100.00
Location	Good	0.32	0.40	80.00
Storage/Fixed Equip	Good	0.32	0.40	80.00
Instructional Resource Rooms				
Environment	Fair	0.52	0.80	65.00
Size	Good	1.60	2.00	80.00
Location	Good	0.48	0.60	80.00
Storage/Fixed Equip	Poor	0.30	0.60	50.00
Science				
Environment	Excel	0.83	0.83	100.00
Size	Excel	2.07	2.07	100.00
Location	Good	0.50	0.62	80.00
Storage/Fixed Equip	Excel	0.62	0.62	100.00
Music				
Environment	Poor	0.30	0.59	50.00
Size	Poor	0.74	1.48	50.00
Location	Good	0.36	0.45	80.00
Storage/Fixed Equip	Good	0.36	0.45	80.00
Art				
Environment	Fair	0.43	0.67	65.00
Size	Poor	0.83	1.66	50.00
Location	Good	0.40	0.50	80.00
Storage/Fixed Equip	Fair	0.32	0.50	65.00
Career Tech Ed				
Environment	Good	1.37	1.71	80.00

Project #: 8272

County: Yancey

Site #: 370507002030

Project: Assessments 2016

Region: 995

Site: MOUNTAIN HERITAGE H

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Size	Good	3.42	4.27	80.00
Location	Good	1.03	1.28	80.00
Storage/Fixed Equip	Good	1.03	1.28	80.00
Computer Labs				
Environment	Good	0.24	0.30	80.00
Size	Excel	0.75	0.75	100.00
Location	Good	0.18	0.23	80.00
Storage/Fixed Equip	Good	0.18	0.23	80.00
P.E.				
Environment	Poor	1.20	2.40	50.00
Size	Fair	3.90	6.00	65.00
Location	Poor	0.90	1.80	50.00
Storage/Fixed Equip	Poor	0.90	1.80	50.00
Performing Arts				
Environment	Good	0.26	0.32	80.00
Size	Excel	0.80	0.80	100.00
Location	Good	0.19	0.24	80.00
Storage/Fixed Equip	Good	0.19	0.24	80.00
Media Center				
Environment	Excel	0.84	0.84	100.00
Size	Good	1.69	2.11	80.00
Location	Excel	0.63	0.63	100.00
Storage/Fixed Equip	Good	0.51	0.63	80.00
Restrooms (Student)	Fair	0.59	0.91	65.00
Administration	Poor	1.31	2.61	50.00
Counseling	Poor	0.38	0.76	50.00
Clinic	Fair	0.15	0.24	65.00
Staff Lounge-WkRm	Good	0.57	0.71	80.00
Cafeteria	Poor	2.00	4.00	50.00
Food Service and Prep	Good	4.08	5.11	80.00
Custodial and Maintenance	Good	0.40	0.50	80.00
Outside				
Vehicular Traffic	Fair	0.65	1.00	65.00
Pedestrian Traffic	Poor	0.49	0.98	50.00
Parking	Poor	1.05	2.11	50.00
Athletic Courts and Fields	Good	2.21	2.77	80.00
Safety and Security				
Fencing	Good	0.68	0.85	80.00
Signage & Way Finding	Poor	0.50	1.00	50.00
Ease of Supervision	Unsat	0.00	3.00	0.00
Controlled Entrances	Unsat	0.00	0.50	0.00
Total For Site:		64.79	100.00	64.79

Comments

Project #: 8272

County: Yancey

Site #: 370507002030

Project: Assessments 2016

Region: 995

Site: MOUNTAIN HERITAGE H

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS->Learning Environment-->Learning Style Variety Mountain Heritage High includes a wide variety of teaching and learning spaces. There is opportunity to offer a wide variety of instruction.				
Suitability - HS->Learning Environment-->Interior Environment In many ways, the interior configuration is very inviting. The facility contains many sections across a hillside with pleasant views and aesthetics. However, the convoluted arrangement of many spaces and the inclusion of interior spaces lower the score for this category.				
Suitability - HS->Learning Environment-->Exterior Environment There are a variety of outside spaces available, some are difficult to utilize due to the configuration of the site.				
Suitability - HS->General Classrooms-->Environment Most general classrooms have little on the way of appropriate aesthetics. Some have no natural light.				
Suitability - HS->General Classrooms-->Size Most general classroom meet approximately 75% of the guideline. None meet the guideline.				
Suitability - HS->General Classrooms-->Location Most but not all general classrooms are located appropriately however the configuration of the building makes movement from the general classrooms to other sections of the school a problem.				
Suitability - HS->General Classrooms-->Storage/Fixed Equip Most general classrooms have little or no storage or fixed equipment.				
Suitability - HS->Instructional Resource Rooms-->Environment Most resource rooms lack appropriate acoustics, lighting levels and overall aesthetics.				
Suitability - HS->Instructional Resource Rooms-->Storage/Fixed Equip Resource rooms have minimal storage or equipment.				
Suitability - HS->Music-->Environment Music rooms provide little in the way of a stimulating environments and overall aesthetics.				
Suitability - HS->Music-->Size Music rooms meet approximately 60-70% of the guideline. None meet the guideline.				
Suitability - HS->Art-->Environment The art room lacks appropriate aesthetics.				
Suitability - HS->Art-->Size The art room meets approximately 55% of the guideline.				
Suitability - HS->Art-->Storage/Fixed Equip The art room lacks adequate casework and storage.				
Suitability - HS->Career Tech Ed-->Size Most CTE spaces meet the guideline. Some FACS rooms do not.				
Suitability - HS->P.E.-->Environment The gymnasium provides a good environment, other spaces including locker rooms, weight room, wrestling building, health classroom do not.				
Suitability - HS->P.E.-->Size The gymnasium and outdoor PE spaces are good, other spaces do not meet size guidelines.				
Suitability - HS->P.E.-->Location The gymnasium has good outside access but cannot be separated from other areas of the building. The wrestling building is located off site.				

Project #: 8272

County: Yancey

Site #: 370507002030

Project: Assessments 2016

Region: 995

Site: MOUNTAIN HERITAGE H

Grade Config: 09-12

Site Type: High

Site Size: 0.00

Suitability	Rating	Score	Possible Score	Percent Score
Suitability - HS->P.E.-->Storage/Fixed Equip PE storage is problematic. Mats are stored in a space that makes it difficult to access.				
Suitability - HS->Performing Arts-->Location The auditorium is located appropriately but cannot be separated from other parts of the building.				
Suitability - HS->Media Center-->Size The media center meets over 90% of the guideline but there is no video studio, production room, or associated storage.				
Suitability - HS->Restrooms (Student) Student restrooms are adequate in number and location but are dated.				
Suitability - HS->Administration Overall offices are small, there is no conference room and the administrative space does not have visual access to the entrances.				
Suitability - HS->Counseling counselor offices are small, there is no reception or group work area.				
Suitability - HS->Clinic The clinic is located appropriately but does not have a restroom or cot separation.				
Suitability - HS->Staff Lounge-WkRm Staff workrooms are located at different places throughout the school.				
Suitability - HS->Cafeteria The cafeteria space meets approximately 75% of the guideline. There is no table or chair storage.				
Suitability - HS->Outside-->Vehicular Traffic There is some separation of busses with student and parent traffic but some conflict exists with general traffic. Bus parking is adequate.				
Suitability - HS->Outside-->Pedestrian Traffic Pedestrian traffic conflicts with other traffic lanes.				
Suitability - HS->Outside-->Parking Parking is not adequate for staff, students and visitors. Event parking backs up to the highway.				
Suitability - HS->Safety and Security-->Signage & Way Finding Many areas of the school are difficult to locate.				
Suitability - HS->Safety and Security-->Ease of Supervision The numerous entrances, hallways, and stairways make supervision difficult.				
Suitability - HS->Safety and Security-->Controlled Entrances Mountain Heritage High has numerous uncontrolled entrances.				